# **Table of Contents**

I.	Introduction	1
II.	The Bronx	12
	THE DIVIX	13
	Grand Concourse	14
	Pedestrian Safety Demonstration Project	
	High Pedestrian Accident Locations Improvements	
	Grand Concourse / East 170 <sup>th</sup> Street	
	Grand Concourse / East 183 <sup>rd</sup> Street	25
	South Bronx Churches	27
	East Fordham Road / East Kingsbridge Road / Bainbridge Avenue	31
	University Avenue / West 181st Street / Hall of Fame Terrace	
III.	Brooklyn	37
		0.0
	Grand Army Plaza	38
	Improvements in the Vicinity of Eastern Parkway / Utica Avenue & Kings Highway /	40
	Linden Boulevard / Remsen Avenue	
	<ul><li>Eastern Parkway</li><li>Kings Highway / Linden Boulevard / Remsen Avenue</li></ul>	
	Ocean ParkwayBushwick Avenue / East New York Avenue / Jackie Robinson Parkway	
	Bushwick Avenue / Last New Tork Avenue / Jackie Robinson Farkway	
IV.	Manhattan	59
	Park Avenue / East 33 <sup>rd</sup> Street	60
	Edgecombe Avenue	
	Upper Park Avenue	
	West 30th Street / 9th Avenue	
	Triangle at Canal, Varick and Laight Streets	
	Henry Hudson Parkway Interchange / Riverside Drive /	
	West 95th and 96th Street Corridors	78
	Henry Hudson Parkway Interchange	
	West 95 <sup>th</sup> Street / Riverside Drive	
	West 96th Street / Broadway	
	West 95 <sup>th</sup> Street Between Riverside Drive and Amsterdam Avenue	

V.	Queens	92
	Queens Boulevard	93
	Pedestrian Safety Study	
	NYCDOT Initiated Improvements	
	Queens Boulevard Pedestrian Safety Study (Phase II)	
	High Accident Location Improvements	
	Queens Boulevard / Woodhaven Boulevard / 59th Avenue	
	Queens Boulevard / Van Dam Street / Thomson Avenue	
	Rockaway Freeway	
	Linden Boulevard / South Conduit Avenue	
	Main Street	
	Southbound Main Street Service Road at 68 <sup>th</sup> Drive	
	Southbound Main Street Service Road at 73rd Avenue	
	Cooper Avenue Underpass / 74th Street	
	Van Wyck Expressway / North Conduit Avenue	
	Northern Boulevard Corridor	
	Northern Boulevard / Clearview Expressway	
	Francis Lewis Boulevard Between 120th Avenue / 220th Street and	
	125 <sup>th</sup> Avenue / 232 <sup>nd</sup> Street	131
	69th Street / Grand Avenue / Long Island Expressway	
	Parsons Boulevard / Kissena Boulevard	
VI.	Staten Island	
	Hylan Boulevard	
	Hylan Boulevard / Reynolds Street	
	Father Capodanno Boulevard	
	Page Avenue, PS 6	
	Borough Wide Daylighting Initiative	
	Forest Avenue / Morningstar Road / Richmond Avenue	
	Narrows Road South / Richmond Road	156
VII.	Brooklyn/Queens	158
	Atlantic Avenue Safety Improvements	
	Queens Improvements	
	Brooklyn Improvements	163
VIII.	Citywide Initiatives	165
	Citywide Oversized Street Name Signs	166
	Improving Safety at Intermodal Transit Stations / Bus Stops Under the El	
	Jerome Avenue / Burnside Avenue	
	Bay Parkway / 86 <sup>th</sup> Street	178




## Park Avenue/East 33rd Street

#### **Description**

The intersection of Park Avenue and East 33<sup>rd</sup> Street had consistently been ranked number one in the number of pedestrian crashes in the City, holding this position from 1996 through 1998, and again in 2001. This trend is directly attributed to the unusual configuration of the intersection and its location at the terminus or "mouth" of the Park Avenue Tunnel, which runs under Park Avenue between East 33<sup>rd</sup> and East 40<sup>th</sup> Streets. The tunnel serves two-way traffic with one lane in each direction. There is a posted height clearance of 8'–11" and trucks are prohibited in the tunnel. At the north leg of the intersection, the Park Avenue Tunnel emerges, severely limiting visibility for southbound Park Avenue traffic exiting the tunnel. Additionally, the merging of southbound Park Avenue surface traffic and southbound tunnel traffic exiting at East 33<sup>rd</sup> Street created unsafe pedestrian and vehicular conditions. Overall, pedestrians crossing on the north leg of the intersection were at the most risk due to the limited visibility.

Based upon these known factors, DOT has been actively working at this location to improve overall safety, especially for pedestrians. A central component of this initiative was the prohibition of pedestrians from using the north leg to cross Park Avenue directly at the mouth of the tunnel. This was accomplished through the use of signs and an iron fence at the northeast and northwest corners. Nevertheless, non-compliance of these regulations remains high.

Pedestrian Accident Experience 1996 - 2001



In terms of the accident history at this location, this intersection has consistently ranked first in the City with the highest number of pedestrian accidents (18 in 1996, 20 in 1997, 16 in 1998 and 15 in 2001.) Pedestrian accidents peaked in 1997 with 20, and continued to decline with 16 accidents in 1998 and 12 accidents in 1999, the year the Department implemented its improvements. In 2000, the first full year for which post-implementation

information is available, accidents declined to 9, which is 55% less than the accident experience in 1997. The Department believes the decline since 1999 can be attributed to the improvements and changes to pedestrian movements through this intersection. However, in 2001, pedestrian accidents increased substantially by 67% to 15. Given the decline in accidents at this location between 1997 and 2000 and the unusual increase that took place in 2001, the Department took a closer look at the contributing factors for accidents that took place at this intersection. A detailed analysis of each of the 15 accidents indicated that most of these accidents were attributed to pedestrians crossing against the signal and occurred in the southbound direction where vehicles exit the tunnel.


Although accident information for 2002 and 2003 is not available from the NYSDOT database at this time, the Department utilized the New York City Police Department Accident Database, which is not generally used in this report, to supplement this investigation with available information for the 2002 and 2003 accident experience. According to this database, pedestrian accidents decreased by 56% to only six in 2002. In 2003, pedestrian accidents increased slightly to eight. There were no fatalities in 2001 or 2002 and one fatality in 2003.

Based upon the additional information, the Department believes the accident experience in 2001 was an anomaly. Overall, pedestrian accidents have declined significantly at this location since the safety improvements were implemented in October 1999 and have made this intersection significantly safer for pedestrians and motorists alike.

#### Improvements Implemented in October 1999


As part of the 1999 Mayor's Holiday Traffic Program, the Department implemented several measures to separate Park Avenue Tunnel traffic from pedestrians. This was accomplished by the installation of barriers extending from the mouth of the tunnel at the north leg of the intersection to near the south leg. Now pedestrians are physically able to cross Park Avenue only at the south leg (in conformance with the existing regulation). Furthermore, westbound traffic on East 33<sup>rd</sup> Street is no longer allowed to continue across Park Avenue, but is required to turn right (northbound) at Park Avenue. Green right arrow signals have been installed for westbound East 33<sup>rd</sup> Street. The improvements resulted in an overall reduction in conflicts between pedestrians and turning vehicles at all crosswalks in the intersection. Wayfinding





Above: Signage and physical treatments on the north leg of the intersection

Below: High Visibility Crosswallks and distinct signage advises pedestrians to cross with care



signs were installed throughout the area to direct truckers to appropriate truck routes (e.g., East 31st Street) and avoid unnecessary travel on East 33rd Street or Park Avenue. Specifically, the following improvements were implemented:

- A Jersey barrier separating the southbound tunnel exit from southbound Park Avenue surface traffic.
- Qwick Kurb along the centerline of Park Avenue between the mouth of the tunnel and the south leg crosswalk.
- Signs prohibiting through traffic on westbound East 33<sup>rd</sup> Street and requiring

all traffic to turn right to proceed northbound on Park Avenue surface road or into the tunnel (except trucks, which are prohibited in the tunnel).

- Wayfinding signs to direct motorists primarily to East 31<sup>st</sup> Street to access East 33<sup>rd</sup> Street west of Park Avenue and points west.
- Signal face with right green arrow for traffic on westbound East 33<sup>rd</sup> Street approach to Park Avenue.
- Daylighting of the south curb of East 33<sup>rd</sup> Street at the approach to Park Avenue to facilitate turning movements for trucks.
- Remove alternate side "No Standing" regulations on East 33rd Street between Lexington and Park Avenues since the additional capacity created by making the curb lane a travel lane is no longer needed (East 33rd Street experiences reduced volume as a result of the improvements).
- Provide continuous "WALK" signal for pedestrians crossing west leg of intersection across East 33<sup>rd</sup> Street, including the signal phase when Park Avenue traffic is stopped since no conflicts can occur from westbound traffic.

Maintenance of all special items is continuing. In June 2000, several damaged sections of the iron fencing were repaired and re-installed. In March 2003, 18 linear feet of fencing was repaired and re-installed. Pavement markings were refurbished in June 2003.


## **Edgecombe Avenue**

#### **Description**

Along the section of Edgecombe Avenue between West 155<sup>th</sup> Street and Amsterdam Avenue there are three schools (IS 90/PS 79, IS 164, and PS 8), a new police precinct (33<sup>rd</sup> Precinct) and a playground. The community raised concerns regarding the traffic safety of the school children in the area, limited parking and congestion. The Department, in coordination with Community Board 12 convened a task force to address these concerns. Members included the Department of Parks and Recreation, the Department of Sanitation, the Fire Department, the Community League and the Board of Education. As a result, the Department identified specific problems and in July 2002 implemented a series of improvements to ensure that the needs of the community were met.

As part of the review of the corridor, the Department examined the accident history for Edgecombe Avenue between West 155<sup>th</sup> Street and Amsterdam Avenue. In 1998,

there were a total of 61 accidents, of which one involved a pedestrian. In 1999, total accidents decreased 20% to 49 with one pedestrian accident. In 2000, total accidents increased 33% to 65 with three pedestrian accidents. In 2001, total accidents declined significantly by 33% to 43 with one pedestrian accident. This decline follows the trend citywide of decreasing accidents and the Department anticipates an additional decline in accidents as a result of the improvements implemented in July 2002.




#### Improvements Implemented In July 2002

 Converted Edgecombe Avenue to one-way southbound (from two-way operation) from Jumel Place to West 167<sup>th</sup> Street.

- Converted Jumel Place to one-way northbound (from two-way operation) from West 167<sup>th</sup> Street to Edgecombe Avenue.
- Converted West 168<sup>th</sup> Street to one-way eastbound (from two-way operation) from Amsterdam Avenue to Jumel Place.
- Installed angle parking on West 168<sup>th</sup> Street between Amsterdam Avenue and Jumel Place.
- Narrowed Edgecombe Avenue with pavement markings between West 167<sup>th</sup> Street and West 164<sup>th</sup> Street.
- Installed additional school crosswalks and appropriate signage around PS 8 and IS 90.
- Installed curve warning signs on Edgecombe Avenue.

The implemented improvements are shown on the following page.






## **Upper Park Avenue**

#### **Description**

Beginning at East 96<sup>th</sup> Street, the Park Avenue roadway is divided by the Metro-North Viaduct which runs above the roadway from East 96<sup>th</sup> Street to East 132<sup>nd</sup> Street. The viaduct splits the Park Avenue roadway into separate northbound and southbound corridors with a typical width of 24 to 26 feet and vehicles often use it as a two-lane roadway. Along the entire corridor, a stone fascia is closely aligned to the curb line, and along a ten-block portion between East 101<sup>st</sup> Street and East 111<sup>th</sup> Street, the fascia of the viaduct is aligned approximately one foot from the curb line. This contributes to limited sight distances as motorists are not able to clearly view or react to a pedestrians presence as they emerge from behind the stone fascia. Motorists also have a difficult time seeing other vehicles emerging from underneath the viaduct. The impacts in pedestrian and traffic flow on the roadway from these characteristics is most evident between East 101<sup>st</sup> and East 111<sup>th</sup> Street and in the vicinity of the Metro-North station at East 125<sup>th</sup> Street.

The Metro-North station at East 125<sup>th</sup> Street is a highly congested area with both high volumes of pedestrians and passengers discharging and loading. Additionally,



the roadway narrows at this intersection to 19 feet due to the elevated columns supporting the rail station and tracks above. Much of the street below the station is leased from the City for vehicle parking by private entities.

The accident experience for this corridor indicates a rising trend in accidents along the length of the corridor between 1998 and 2001. In 1998, total accidents on Park Avenue between East 96<sup>th</sup> and East 132<sup>nd</sup> Streets

were 230 including 11 involving pedestrians and 11 involving bicycles. In 1999, total accidents increased 17% to 270 of which 13 involved pedestrians and nine


involved bicycles. In 2000, total accidents remained relatively unchanged at 267 with 13 involving pedestrians and 11 involving bicycles. In 2001, total accidents increased an additional 22% to 326 with 17 involving pedestrians and 15 involving bicycles. The rising accident trends predate the improvements that were implemented in September 2002. The treatments that were implemented reflect the Department's concern for the rising accident trend at this location.

#### Improvements Implemented in September 2002


In conjunction with a DDC Engineering Resurfacing project between East 96<sup>th</sup> and East 132<sup>nd</sup> Streets, the following improvements were implemented in September 2002:

- Installed a three-foot wide thermoplastic 'buffer' (flush channelization) using pavement markings between East 101<sup>st</sup> and East 132<sup>nd</sup> Streets. The buffer is intended to realign the single travel lane away from the pedestrian refuge area in the center of Park Avenue's north and south roadways. The buffer markings improve the line of sight between motorist and pedestrian as well as cause motorists to reduce speed by creating the appearance of a narrowed roadway.
- Installed edge line between East 97<sup>th</sup> and East 100<sup>th</sup> Streets south of the new bus terminal currently under construction.
- Installed "WAIT FOR WALK SIGNAL" pavement messages to advise pedestrians to wait for a fresh walk signal. Messages are recommended between East 101<sup>st</sup> and East 111<sup>th</sup> Streets where the stone walls of the viaduct severely limit visibility for both pedestrians and motorists.
- Installed two sections of 20-foot jersey barriers at the north and south ends of each block in advance of the crosswalks between East 127<sup>th</sup> and East 132<sup>nd</sup> Streets to prevent motorists from traveling beneath the elevated structure (20 sections of 20-foot jersey barrier are required).
- Installed "NO STANDING 7-10AM Mon-Fri" rush hour regulation on the west curb (southbound) from East 132<sup>nd</sup> Street to East 130<sup>th</sup> Street to provide a second travel lane during morning rush hours.
- Removed signal faces (for northbound and southbound traffic) within the area beneath the elevated structure north of East 127<sup>th</sup> Street.
- Upgraded crosswalk markings to high visibility at all signalized intersections.
- Installed advance pedestrian crossing warning signs in the section of the stone viaduct between East 101<sup>st</sup> and East 111<sup>th</sup> Streets.

The improvements are shown on the following pages.









### West 30<sup>th</sup> Street/9<sup>th</sup> Avenue

#### **Description**



Aerial view of West 30th Street and 9th Avenue

Accident Experience 1998 - 2001



The intersection 30<sup>th</sup> of West Street and 9th Avenue is a complex intersection. At this location, traffic travels southbound along 9th Avenue while Lincoln Tunnel traffic travels eastbound along West 30th Street. Midblock, between 9th and Avenues is the approach and exit ramps to and from the Lincoln Tunnel which contribute to most of the traffic on West 30th Street, Traffic on West 30th Street is separated by striping on the western end and a raised median east of the Tunnel roadway, generally known as Dyer Avenue. At certain times of the day, the Port Authority allows buses to layover on the northern portion of the roadway separated by the median. Additionally, a large number of United States Postal Service vehicles utilize this roadway, as there are postal facilities on both sides of West 30th Street.

With the high amount of vehicular traffic associated with the Lincoln Tunnel, there are pedestrian/vehicle conflicts at this location, especially during peak hours when post office employees cross West 30<sup>th</sup> Street while vehicles enter and exit the Lincoln Tunnel.


Between 1998 and 2001, the accident

experience at this location indicated a relatively high accident occurrence. In 1998, there were a total of 25 accidents, five of which involved pedestrians. In 1999, there were a total of 21 accidents, one of which was a pedestrian accident. In 2000, there were a total of 33 accidents, three of which involved pedestrians. In 2001, there were a total of 23 accidents, one of which involved a pedestrian. These accidents predate the implementation of the safety improvements in September 2002

#### Implemented Improvements

- Old pedestrian crossing signs were repositioned for improved visibility in September 2002.
- Yield to Pedestrian signs were installed on the southeast and southwest corners in September 2002.
- Lane assignment markings were installed in November 2002 to improve vehicular movements and decrease conflicts.
- All crosswalks were upgraded to high visibility to improve pedestrian safety in November 2002.
- A Leading Pedestrian Interval (LPI) was installed on the south leg of the intersection in December 2002.
- Two new pedestrian signals for the westerly crossing of West 30<sup>th</sup> Street were installed and signal timing modifications were completed in December 2002.

The improvements are shown on the following page.



# Triangle at Canal, Laight and Varick Streets


#### **Description**

The triangle formed by Canal, Laight and Varick Streets has become a key gateway into the growing neighborhood of Tribeca and Lower Manhattan. For several Its status as an ungraded cobble-stoned parking area with no usable sidewalk or curb was aesthetically unpleasant for both pedestrians and vehicles. In its original configuration, there was no separation between the cobblestoned pedestrian area and the roadway, leaving pedestrians without a defined sidewalk and unprotected from vehicles. In addition, the sidewalk on the western curb of Varick Street was substandard.

The triangle lies due east of the Holland Tunnel Exit Rotary and experiences significant traffic exiting from the Tunnel and heading onto Canal Street and into Lower Manhattan. Currently, traffic signals and street lights within the triangle are on concrete cylinders. There is no curb or graded sidewalk separating the non-roadway portion of the area with the marked street. Parking within the triangle was largely unregulated and the area was frequently used as a storage area for disabled vehicles from the Holland Tunnel.

For pedestrians, both the 8th Avenue Subway Line (A,C,E) 7<sup>th</sup> Avenue Line and the (1.9)have exits/entrances at points of the triangle. As the neighborhood around it has grown, pedestrian traffic crossing the triangle and the area around it has increased noticeably. New bars. restaurants, and shops have opened and complemented the growing residential population.

In terms of the accident



experience, the number of accidents since 1998 has been declining. In 1998, there were a total of 136 accidents, of which eight were pedestrian. In 1999, accidents declined significantly to 95, of which four were pedestrian. In 2000, total accidents continued to decline to 73, three of which were pedestrian. Two fatalities occurred in 2000. In 2001, total accidents were down 45% to 43, of which one was a pedestrian and one a bicycle accident. This dramatic decline over the time period can be attributed to changes in the flow of traffic to and from the Holland Tunnel. In 2001, the dramatic decline can also be attributed to the resulting traffic patterns in Lower Manhattan after September 11th and the restrictions placed on trucks traveling through the Holland Tunnel. The downward trend also parallels the overall decline in accidents citywide over this period.

The Department's safety improvement plan for this location involved several key partners:

- Port Authority of NY and NJ partial owners of the triangle and operators of the Holland Tunnel
- Department of Design and Construction water main project on Varick Street
- Parks Department
- Police Department First Precinct and Transit Police
- Community Board 1


Central to these efforts to improve the safety and aesthetic values of the triangle is the creation of a pedestrian-friendly park. This park, built under the Parks Department GreenStreets Program would serve several key purposes:

- Create a welcoming and safe environment for pedestrians crossing the area in and around the triangle.
- Provide the growing residential and business community with valuable green space.
- · Establish clear markings and curb lines to improve vehicle safety.
- Offer regulated parking for Police Department vehicles.
- Act as a visual gateway into Lower Manhattan for vehicles coming from New Jersey (via the Tunnel) and northern Manhattan.


#### Implemented Improvements

- March 2003
  - DOT Manhattan Street Maintenance excavated the triangle area and prepared it for construction.
- June 2003
  - Department of Design and Construction Restoration of Varick Street roadway and replacement of the sidewalk on the western side and the curb on the eastern side.
- Fall 2003
  - New York City Department of Transportation Installed new streetlights on Canal Street, Laight Street and Varrick Street.
- September 2004
  - New York City Department of Transportation Relocation and modification of street light and signal poles, and traffic and pedestrian signals to accommodate the new street alignment.
- October 2004
  - Port Authority of New York and New Jersey Construction of the sidewalk around the triangle and installation of curbs on Laight and Canal Street
- November 2004 May 2005
  - New York City Parks Department Construction of GreenStreet.

The improvements are shown on the following two pages.







## Henry Hudson Parkway Interchange/Riverside Drive/ West 95<sup>th</sup> and 96<sup>th</sup> Street Corridors

#### **Description**

For motorists and pedestrians alike, using the Henry Hudson Parkway (HHP) at the West 95<sup>th</sup>/96<sup>th</sup> Street interchange and the area roadways was a challenge, presenting numerous conflicts and safety issues, as well as traffic flow problems. Both elected officials and the Department of Transportation have actively been working on resolving these issues over the past few years. In 2003, the Manhattan Borough President's Office retained a consultant to perform a traffic study on the West 96<sup>th</sup> Street Corridor. Working with the recommendations of this report, the Department developed a plan to improve traffic and pedestrian safety throughout this corridor.

There are four primary locations that are being addressed as a result of this initiative. These include:


- the Henry Hudson Parkway Interchange at West 95<sup>th</sup> and West 96<sup>th</sup> Streets,
- the intersection of Riverside Drive and West 95th Street,
- West 95<sup>th</sup> Street between Riverside Drive and Amsterdam Avenue and
- the intersection of Broadway and West 96th Street

While the operation of the Henry Hudson Parkway interchange is the central component of this initiative, the safety improvements and changes in regulations on the interchange's supporting intersections should provide for a substantial improvement in pedestrian and vehicular safety throughout the area.

# Henry Hudson Parkway Interchange

#### **Description**

Numerous traffic issues are the direct result of the unusual design of the HHP's 95 th/96th Street interchange and the movement of vehicles entering, exiting and continuing along the mainline of the parkway. All vehicles exiting the HHP, including those traveling in the southbound direction were forced into a short single lane merge in which they had options to exit at either West 95th or West 96th Street. This merge caused excessive speed differentials and overlapping merges between exiting traffic. Additionally, the exit lane for West 96th Street also served as an acceleration lane for traffic entering the northbound roadway at West 95th Street, causing additional conflicting movements and reducing both visibility and warning time for exiting and entering drivers. Motorists were forced into sudden acceleration and deceleration in order to either merge onto or exit the parkway. These movements also created conflicts between mainline and entering/exiting traffic, frequently causing extensive queuing on the mainline roadway and ramps. These conflicts are illustrated graphically below.



#### **Improvements Implemented in November 2003**

In order the alleviate the conflict between vehicles exiting and entering the highway, the Department minimized the weaving conflicts by:


- Closing the entrance ramp from West 95<sup>th</sup> Street and Riverside Drive to all traffic.
- Eliminating the West 95<sup>th</sup> Street exit for exiting northbound HHP traffic and
- Eliminating the West 96<sup>th</sup> Street exit for southbound traffic.


In this configuration, weaving conflicts between northbound and southbound exiting vehicles are completely eliminated. Southbound vehicles are required to exit at the West 95<sup>th</sup> Street exit, while northbound vehicles are required to exit at the West 96th Street exit. Additionally, vehicles entering at the West 96<sup>th</sup> Street entrance will be provided with a longer acceleration lane and have fewer conflicts with vehicles on the mainline HHP.

These treatments were implemented through the use of new markings on the roadway, advance signage, and the use of flexible bollards and Qwick Kurb on all approaches and ramps.

The improvements and resulting changes in traffic flow are shown on the following two pages.







Operation of Henry Hudson Parkway / West 95th and 96th Street Interchange under the new configuration








Henry Hudson Parkway at Modified West 95th Street Exit, including physical treatments and signage

### West 95th Street/Riverside Drive

#### **Description**


The intersection of West 95th Street and Riverside Drive was a signalized fourway intersection with an entrance and exit ramp to the Henry Hudson Parkway along its western leg. Due to the curvature of the exit ramps from the northbound Henry Hudson Parkway, motorists had little time to react to pedestrians crossing the southwest side of the intersection. Motorists entering the northbound Henry Hudson Parkway, especially those turning from southbound Riverside Drive had limited visibility of pedestrians crossing on the northwest side of the intersection. Additionally, there was insufficient refuge area for pedestrians crossing between the exit and exit ramps.

The accident experience at this location varied between 1998 and 2001. In 1998, there was one accident. In 1998, <sup>12</sup> accidents increased to seven, of which one involved a pedestrian. In 2000, accidents decreased to four and in a 2001, accidents increased to 11. In 2002, the Department installed 6 several immediate treatments to improve safety for pedestrians and 4 motorists at this intersection. These treatments were upgraded as part of the overall improvements taking , place on the Henry Hudson Parkway and the resulting changes in traffic flow in 2003.



Original Configuration of Intersection

#### Accident Experience 1998-2001



#### Improvements implemented in 2002

In September 2002, the Department installed several improvements aimed at improving safety at the intersection of West 95<sup>th</sup> Street and Riverside Drive at the entrance and exit ramps to the HHP. These included:

- High visibility crosswalks were installed on the north and south legs of the intersection.
- The west crosswalk was widened by three feet to provide additional pedestrian space.
- The radius of the northwest corner was modified and an expanded neckdown was installed using markings.
- A temporary neckdown using roadway markings was created to provide shorter crossing distance and to prevent motorists from making wide turns from the Henry Hudson Parkway exit to southbound Riverside Drive on the southwest corner.

#### **Improvements Implemented in February 2003**

- Installed five newly designed "Turning Vehicles Yield to Pedestrians" signs.
- A neckdown was installed on the northwest corner to provide shorter crossing distance and to slow motorist making turns onto the HHP entrance from southbound Riverside Drive.




Closure of West 96<sup>th</sup> Street Entrance Ramp to Henry Hudson Parkway

# Improvements Implemented in November 2003

- As part of the overall changes in the operation of the Henry Hudson Parkway interchange, the Department closed the entrance ramp from West 96th Street and Riverside Drive to reduce conflicts on the Parkway. This closure was implemented through the use of signage and barriers. (Depicted to the left)
- Adjusted signal timing at intersection. (August 2004)



• In an effort to better channelize traffic and organize weaving movement between the main roadway and service road of Riverside Drive, the Department installed additional roadway markings between West 95<sup>th</sup> and West 97<sup>th</sup> Streets. The improvement is illustrated below.



New Roadway Markings and Channelization on Riverside Drive

#### Improvements Implemented in 2004


- A six second Leading Pedestrian Interval (LPI) was installed to cross Riverside Drive at West 95th Street. (April 2004)
- Adjusted signal timing at intersection. (August 2004)

# West 96th Street/Broadway

#### **Description**

Broadway is the major two way, north-south arterial in the area. This intersection experiences extremely high vehicular and pedestrian traffic. Contributing factors include high density residential/commercial land uses, the 96<sup>th</sup> Street Subway station (1,2,3 and 9 lines), the M96 bus, and West 96<sup>th</sup> Street serving as one of the areas main east-west corridors due to the fact that it is two way and links up with the eastbound Central Park Transverse roadway as well as the West 96<sup>th</sup> Street entrance to the Henry Hudson Parkway. The roadway is split by a center median situated between the north and south travel lanes of Broadway that serves as a pedestrian refuge.

Overall, this was a poorly performing intersection due to the turning movements of vehicles. Double parking, buses making turns, and non-dedicated signals provide numerous conflicts for motorists and pedestrians. Previously, left turns were prohibited in both directions daily between the hours of 7 AM and 7 PM. There was also some illegal turning activity that takes place during these hours. Additional left turn prohibitions were also in place for southbound 95<sup>th</sup> Street which diverts eastbound traffic to West 94<sup>th</sup> Street and other residential streets.



Accidents at this location remained fairly consistent between 1998 and 2000, rising from 40 in 1998 to 42 in 1999 and peaking at 49 in 2000. In 2001. accidents decreased by 20% to 39. Although the decline predates improvements, decline in 2001 parallels overall decline in accidents taking place citywide during this time period.

As with the other improvements implemented throughout this corridor, the treatments at this location are part of an overall plan for improving traffic and safety throughout the area.

#### Improvements Implemented in November 2003

The improvements implemented at the intersection of West 96th Street and Broadway are part of the overall plan for improving traffic related to the HHP Interchange. These improvements included:

- Installation of a left turn signal phase and left turn bays on Broadway at West 96th Street to improve the performance of the intersection and to enable left turns.
- Replacement of meters on two blockfaces with truck loading zones to prevent double parking and ensure that at least two travel lanes are available for through traffic.

## Improvements Implemented in Summer 2004


- Installed "No Standing 7AM-10AM, 4PM-7PM, Mon-Fri" regulations on the east curb of West End Avenue for 120 feet south of West 96th Street to provide peak-hour northbound curbside travel lanes and restriped northbound approach to three moving lanes. (July 2004)
- Installed "dual left turn" signs at intersection of Broadway and West 96th Street to complement lane markings on the roadway to guide left-turning vehicles. (September 2004)



Treatments at Intersection of West 96th Street and Broadway



The improvements are shown on the following page.




## West 95<sup>th</sup> Street Between Riverside Drive and Amsterdam Avenue

#### **Description**

West 95<sup>th</sup> Street is one of the two exits from the Henry Hudson Parkway. In addition, the roadway provides eastbound access to Broadway as there is no access to West 96th Street from Riverside Drive. Currently, West 95<sup>th</sup> Street runs eastbound from Riverside Drive to Amsterdam Avenue, where it then changes to westbound operation. While this corridor does not experience heavy traffic volumes, parking restrictions and a wide roadway provided for three possible travel lanes during much of the day. These factors contributed to a speeding problem along this corridor. In addition, there is a public school located on the north corner of West End Avenue which contributes to pedestrian activity along this corridor.

#### Improvements Implemented in November 2003

In order to decrease speeding, the Department amended the parking regulations along West 95th Street from Riverside Drive to Amsterdam Avenue. The new restrictions will discourage vehicles from using West 95th Street as a through street by effectively reducing the number of available travel lanes. The new parking regulations provide for additional community parking. The new regulations (depicted in green) are illustrated below. The previous regulations are depicted in red.




Parking Regulations along the West 95th Street Corridor



#### Improvements Implemented in May 2004

• Relocated teacher parking regulations from west side of West End Avenue to north side of West 95<sup>th</sup> Street, and installed "No Standing School Days 7AM-4PM" regulations on West End Avenue to accommodate school buses and drop offs/pick ups of children.





Overall Traffc Improvements in the Vicinity of the West 95 <sup>th</sup>/96<sup>th</sup> Street / Henry Hudson Parkway Interchange