irn_Unique_Id	irn_Incident_Num	irn_Incident_Date_Occured
100000826	2300221	5/5/2020 11:30
100000826	2300221	5/5/2020 11:30
100000826	2300221	5/5/2020 11:30
100000826	2300221	5/5/2020 11:30
100000826	2300221	5/5/2020 11:30
100000826	2300221	5/5/2020 11:30
100000826	2300221	5/5/2020 11:30
100000830		5/8/2020 13:20
100000830		5/8/2020 13:20
100000830		5/8/2020 13:20
100000830		5/8/2020 13:20
100000830		5/8/2020 13:20
100000830		5/8/2020 13:20
100000830		5/8/2020 13:20
100000830		5/8/2020 13:20
100000833	2300495	5/12/2020 14:10
100000833	2300495	5/12/2020 14:10
100000833	2300495	5/12/2020 14:10
100000834		5/12/2020 10:00
100000834		5/12/2020 10:00
100000834		5/12/2020 10:00
100000834		5/12/2020 10:00
100000834		5/12/2020 10:00
100000834		5/12/2020 10:00
100000835		5/13/2020 8:15
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000837	3474398239	5/13/2020 12:00
100000838		5/20/2020 13:40
100000838		5/20/2020 13:40
100000838		5/20/2020 13:40
100000838		5/20/2020 13:40
100000838		5/20/2020 13:40
100000843		5/22/2020 9:00
100000843		5/22/2020 9:00
100000843		5/22/2020 9:00
100000843		5/22/2020 9:00

5/23/2020 8:15 5/23/2020 8:15 5/23/2020 8:15 5/23/2020 8:15 5/23/2020 11:00 5/23/2020 11:00 5/23/2020 11:00 5/23/2020 11:00 5/23/2020 11:00 5/23/2020 11:00 5/23/2020 11:00 5/23/2020 11:00 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/18/2020 11:55 5/27/2020 12:30 5/27/2020 12:30 5/27/2020 12:30 5/27/2020 12:30 5/27/2020 12:30 5/27/2020 12:30 5/28/2020 12:00 5/28/2020 12:00 5/28/2020 12:00 5/28/2020 12:00 5/28/2020 12:00 5/28/2020 1:00 5/28/2020 1:00 5/28/2020 1:00 5/28/2020 1:00 5/28/2020 1:00 5/28/2020 1:00 5/28/2020 1:00 5/28/2020 1:00 5/28/2020 1:00 5/28/2020 1:00 5/28/2020 1:00

1000000851		5/28/2020 1:00
100000851		5/28/2020 1:00
100000851		5/28/2020 1:00
100000852	4812113	5/28/2020 12:00
100000852	4812113	5/28/2020 12:00
100000852	4812113	5/28/2020 12:00
100000852	4812113	5/28/2020 12:00
100000852	4812113	5/28/2020 12:00
100000852	4812113	5/28/2020 12:00
100000853		5/4/2020 9:00
100000853		5/4/2020 9:00
100000853		5/4/2020 9:00
100000853		5/4/2020 9:00
100000853		5/4/2020 9:00
100000853		5/4/2020 9:00
100000854		5/28/2020 11:00
100000854		5/28/2020 11:00
100000854		5/28/2020 11:00
100000854		5/28/2020 11:00
100000854		5/28/2020 11:00
100000854		5/28/2020 11:00
100000854		5/28/2020 11:00
100000864		5/12/2020 12:00
100000864		5/12/2020 12:00
100000864		5/12/2020 12:00
100000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
100000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
1000000864		5/12/2020 12:00
100000865		5/29/2020 14:00
1000000865		5/29/2020 14:00
1000000865		5/29/2020 14:00
1000000865		5/29/2020 14:00
1000000865		5/29/2020 14:00

irn_Incident_Location_Bin_Number

	irn_Incident_Location_House_Num	
2129044		425
2129044		425
2129044		425
2129044		425
2129044		425
2129044		425
2129044		425
1084306		124
1084306		124
1084306		124
1084306		124
1084306		124
1084306		124
1084306		124
1084306		124
2127129		600
2127129		600
2127129		600
2128766		775
2128766		775
2128766		775
2128766		775
2128766		775
2128766		775
1012831		341
3323538		263
3323538		263
3323538		263
3323538		263
3323538 3323538		263
3323538		263 263
3323538		263
3323538		263
3323538		263
3323538		263
3323538		263
3071356		203 111
3071356		111
3071356		111
3071356		111
3071356		111
1084093		L295
100-000	-	

4622929	Oct-47
4622929	Oct-47
4622929	Oct-47
4622929	Oct-47
2129154	600
2129154	600
2129154	600
2129154	600
2129154	600
2129154	600
2129154	600
2129154	600
2025407	1230
2025407	1230
2025407	1230
2025407	1230
2025407	1230
2025407	1230
2025407	1230
2025407	1230
2025407	1230
2025407	1230
2025407	1230
2025407	1230
2025407	1230
1054682	201
1054682	201
1054682	201
1054682	201
1054682	201
1054682	201
4619735 108-75	
4619735 108-75	
4619735 108-75	
4619735 108-75	
4619735 108-75	
2129250	211
2129250	211
2129250	211
2129250	211
2129250	211
2129250	211
2129250	211
2129250	211
2129250	211
2129250	211
2129250	211

2129250	211
2129250	211
2129250	211
4458300 20-12	
4458300 20-12	
4458300 20-12	
4458300 20-12	
4458300 20-12	
4458300 20-12	
1036152	122
1036152	122
1036152	122
1036152	122
1036152	122
1036152	122
4619735 108-75	
4619735 108-75	
4619735 108-75	
4619735 108-75	
4619735 108-75	
4619735 108-75	
4619735 108-75	
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
3062216	186
4619735 108-75	
4619735 108-75	
4619735 108-75	
4619735 108-75	
4619735 108-75	

irn Incident Location Street Name Grand Concourse E14 Street Bergen Avenue **Bergen Avenue Bergen Avenue Crotona Park North** Crotona Park North Crotona Park North **Crotona Park North** Crotona Park North Crotona Park North 9th Avenue South 5th Street Humboldt Street Humboldt Street Humboldt Street Humboldt Street Humboldt Street AMSTERDAM AVENUE AMSTERDAM AVENUE AMSTERDAM AVENUE AMSTERDAM AVENUE

irn Incident Location Borough Bronx Bronx Bronx Bronx Bronx Bronx Bronx Manhattan Manhattan Manhattan Manhattan Manhattan Manhattan Manhattan Manhattan Bronx Bronx Bronx Bronx Bronx Bronx Bronx Bronx Bronx Manhattan Brooklyn Manhattan Manhattan Manhattan Manhattan

Beach 21st Street Beach 21st Street Beach 21st Street Beach 21st Street E 156th Street Metcalf Ave. E 125th St 62nd Drive 62nd Drive 62nd Drive 62nd Drive 62nd Drive East 203rd Street East 203rd Street

Queens Queens Queens Queens Bronx Manhattan Manhattan Manhattan Manhattan Manhattan Manhattan Queens Queens Queens Queens Queens Bronx Bronx

East 203rd Street East 203rd Street East 203rd Street MOTT AVE MOTT AVE MOTT AVE MOTT AVE MOTT AVE MOTT AVE East 42nd Street 62nd Drive N6th Street 62nd Drive 62nd Drive 62nd Drive 62nd Drive 62nd Drive

Bronx Bronx Bronx Queens Queens Queens Queens Queens Queens Manhattan Manhattan Manhattan Manhattan Manhattan Manhattan Queens Queens Queens Queens Queens Queens Queens Brooklyn Queens Queens Queens Queens Queens

irn Incident Person Reporting By 10451 General Contractor 10003 General Contractor 10455 General Contractor 10455 General Contractor 10455 General Contractor 10460 Person in Control of Site 10199 General Contractor 11211 Person in Control of Site 7728 General Contractor 10027 General Contractor 10027 General Contractor 10027 General Contractor 10027 General Contractor

11691 General Contractor 11691 General Contractor 11691 General Contractor 11691 General Contractor 10455 General Contractor 10472 General Contractor 10035 General Contractor 11375 Person in Control of Site 10458 General Contractor 10458 General Contractor

10458 General Contractor 10458 General Contractor 10458 General Contractor 11691 General Contractor 10168 Subcontractor 10168 Subcontractor 10168 Subcontractor 10168 Subcontractor 10168 Subcontractor 10168 Subcontractor 11375 General Contractor 11211 General Contractor 11375 General Contractor

irn_Incident_Person_Reporting_Phone

irn_Incident_Person_Reporting_By_Type

7184891716	Business
7184891716	Business
7184891716	Business
7184891716	Business
7184891716	
	Business
7188758160	Individual
7188758160	Individual
7188758160	Business
7188758160	Business
7188758160	
7188758160	
7188758160	
7188758160	
7188758160	
7182997000	Business
7182997000	Business
7182997000	Business
	Business
7182997000	2 40 11 200
7182997000	Business

7182997000	Business
7182997000	Business
7182997000	Business
2129966640	Business
9736189545	Business
7188758160	Business
2129243100	Individual
7188758160	Individual

irn_Incident_Person_Reporting_Org_Name Monadnock Construction Suffolk Construction Mountco Construction & Development Mountco Construction & Development Mountco Construction & Development

Urban Atelier Group

Armstrong Roofing Corp. NEELAM CONSTRUCTION CORP. NEELAM CONSTRUCTION CORP. NEELAM CONSTRUCTION CORP. NEELAM CONSTRUCTION CORP. Mega Contracting Group, LLC Mega Contracting Group, LLC

Monadnock Construction Monadnock Construction Monadnock Construction Monadnock Construction Monadnock Construction

Procida Construction Corp **Procida Construction Corp** Procida Construction Corp Procida Construction Corp Lettire Construction Lettire Construction Lettire Construction Lettire Construction Lettire Construction Lettire Construction Mobility Elevator & Lift Co Inc Monadnock Construction Inc. Monadnock Construction Inc.

Construction Superintendent Construction Superintendent Construction Superintendent Construction Superintendent Construction Superintendent

Site Safety Manager Site Safety Manager

Site Safety Manager Site Safety Manager Site Safety Manager Site Safety Manager

irn Incident Contractor Org Name **RNC** Industries Long Island Concrete MTB AMG Inc MTB AMG Inc MTB AMG Inc BYN Custom Design, LLC DBA BYN Iron Works Northeast Interiors Specialists (Nordest Services, LLC Spectrum Precision Painting, LLC Armstrong Roofing Corp. NEELAM CONSTRUCTION CORP. NEELAM CONSTRUCTION CORP. NEELAM CONSTRUCTION CORP. NEELAM CONSTRUCTION CORP.

United Industries Construction United Industries Construction United Industries Construction United Industries Construction Cosan Construction HDK Construction Monadnock Construction Monadnock Construction Monadnock Construction Monadnock Construction Monadnock Construction Monadnock Construction New Leaf Development **Concrete Structures Concrete Structures**

Concrete Structures Concrete Structures Concrete Structures RC Structures RC Structures RC Structures RC Structures RC Structures RC Structures Mobility Elevator & Lift Co Inc New Leaf Development Tomek New Leaf Development New Leaf Development New Leaf Development New Leaf Development New Leaf Development

irn	Incident	Person	_Reporting_	Org	License	Num

GC-611358 GC-611358 GC-611358 GC-611358 GC-611358 GC-611358 GC-611358 GC-611358

GC-15095 GC-15095 GC-15095 GC-15095

603805
603805
603805
603805
603805
603805
603805
603805
603805
603805
603805
603805

GC3427 gc-3427 gc-3427 gc-3427 gc-3427 gc-3427 gc-3427

M002479 M002479

22-2869761

22-2869761

22-2869761

22-2869761

22-2869761

22-2869761

irn Incident Location Owner Name Trinity Mid Bronx Residential L.P. NYCEDC NYCEDC NYCEDC NYCEDC NYCEDC NYCEDC NYCEDC NYCEDC LA Central Owners LLC LA Central Owners LLC LA Central Owners LLC H.E.L.P Development Corp. USPS Havemeyer Holdings, LLC NYCHA NYCHA NYCHA NYCHA NYCHA NYCHA NYCHA NYCHA NYCHA

irn_Incident_Active_Permits_Issued_Count

8

NYC Economic Development Corporation	4
NYC Economic Development Corporation	4
NYC Economic Development Corporation	4
NYC Economic Development Corporation	4
Phipps Houses	8
JV Associates LLC	13
Richman Group Development	6
Apex Place	5
Housing and Services Inc.	14

Housing and Services Inc.	14
Housing and Services Inc.	14
Housing and Services Inc.	14
FRV Housing Development	6
Chanin Building	6
Apex Place Associates LP	7
186 N6 Owner, LLC	16
Apex Place LLP	5

irn_Incident_Location_Union_Site_Desc Non-Union Non-Union Non-Union Non-Union Non-Union Non-Union Non-Union Union Union Union Union Union Union Union Union Non-Union Non-Union Non-Union **Open Shop Open Shop Open Shop Open Shop Open Shop Open Shop Open Shop** Non-Union Union Union Union Union Union Union Union Union Union

irn_Incident_Constr_Worker_Involved_Flag

Υ

Y Y

Y Y

Y Y

Y

Y

Y

Y

Y Y

Y

Y Y

Υ

Y

Y Y

Y Y

Y

Y

Y

Y Y

Y

Y Y

Y

Y

Y

Y

Y Y

Y Y

Y

Y

Υ

Y

Y Y

Υ

Y

Open Shop	Y
Open Shop	Y
Open Shop	Y
Open Shop	Y
Open Shop	Y
Non-Union	
	Ŷ
Non-Union	Y
Non-Union	Y
Non-Union	Y
Non-Union	Y
Open Shop	Ŷ
Open Shop	Y
Open Shop	Ŷ
• •	
Open Shop	Y
Non-Union	Ŷ
Non-Union	Y
Non-Union	Ŷ
Non-Union	Y

Non-Union		
Non-Union		
Open Shop		
Non-Union		
Open Shop		

Y Y

Y Y Y Y Y

Y Y

Y Y Y

Y Y

Y Y Y

Y Y Y

Y

Y Y Y

Y

Y Y Y

Y Y Y

Y Y

Y Y

Y Y Y

Y Y

Y Y

irn_Incident_Description

A worker was installed horizontal rebar in the elevator pit when vertical rebar fell over hitting the horizontal reba A worker was installed horizontal rebar in the elevator pit when vertical rebar fell over hitting the horizontal rebar A worker was installed horizontal rebar in the elevator pit when vertical rebar fell over hitting the horizontal reba A worker was installed horizontal rebar in the elevator pit when vertical rebar fell over hitting the horizontal rebar A worker was installed horizontal rebar in the elevator pit when vertical rebar fell over hitting the horizontal reba A worker was installed horizontal rebar in the elevator pit when vertical rebar fell over hitting the horizontal reba A worker was installed horizontal rebar in the elevator pit when vertical rebar fell over hitting the horizontal reba As per the statement made by the witness, Peter Byrne, the injured worker was assisting in re-positioning of the L As per the statement made by the witness, Peter Byrne, the injured worker was assisting in re-positioning of the I As per the statement made by the witness, Peter Byrne, the injured worker was assisting in re-positioning of the L As per the statement made by the witness, Peter Byrne, the injured worker was assisting in re-positioning of the L As per the statement made by the witness, Peter Byrne, the injured worker was assisting in re-positioning of the [As per the statement made by the witness, Peter Byrne, the injured worker was assisting in re-positioning of the L As per the statement made by the witness, Peter Byrne, the injured worker was assisting in re-positioning of the L As per the statement made by the witness, Peter Byrne, the injured worker was assisting in re-positioning of the [Worker was attempting to move materials in an apartment on the 12th floor. He was walking backwards and trip Worker was attempting to move materials in an apartment on the 12th floor. He was walking backwards and trip Worker was attempting to move materials in an apartment on the 12th floor. He was walking backwards and trip An iron worker was working on a scaffold on the East side of the 7th Fl Roof preparing to finish installing the roof An iron worker was working on a scaffold on the East side of the 7th Fl Roof preparing to finish installing the roof An iron worker was working on a scaffold on the East side of the 7th Fl Roof preparing to finish installing the roof An iron worker was working on a scaffold on the East side of the 7th Fl Roof preparing to finish installing the roof An iron worker was working on a scaffold on the East side of the 7th Fl Roof preparing to finish installing the roof An iron worker was working on a scaffold on the East side of the 7th Fl Roof preparing to finish installing the roof Prior to commencement of work 2 Nordest Interiors LLC workers were charging a water extinguisher on the 4th f Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Worker set up a Baker Scaffold at 6 feet in height. While the worker was using/standing on the platform of the sca Two Workers were moving Hanging Scaffold Equipment, one of the gentlemen picked up a piece of the scaffold a Two Workers were moving Hanging Scaffold Equipment, one of the gentlemen picked up a piece of the scaffold a Two Workers were moving Hanging Scaffold Equipment, one of the gentlemen picked up a piece of the scaffold a Two Workers were moving Hanging Scaffold Equipment, one of the gentlemen picked up a piece of the scaffold a Two Workers were moving Hanging Scaffold Equipment, one of the gentlemen picked up a piece of the scaffold a While unloading the steel plates with other labor(Rene P Sinchi). Luis's finger got pinched between the truck body While unloading the steel plates with other labor(Rene P Sinchi). Luis's finger got pinched between the truck body While unloading the steel plates with other labor(Rene P Sinchi). Luis's finger got pinched between the truck body While unloading the steel plates with other labor(Rene P Sinchi). Luis's finger got pinched between the truck body

Worker was struck by a beam. Worker was struck by a beam. Worker was struck by a beam. Worker was struck by a beam.

Worker was mixing cement when particles of the cement got into his eye. Worker was mixing cement when particles of the cement got into his eye. Worker was mixing cement when particles of the cement got into his eye. Worker was mixing cement when particles of the cement got into his eye. Worker was mixing cement when particles of the cement got into his eye. Worker was mixing cement when particles of the cement got into his eye. Worker was mixing cement when particles of the cement got into his eye. Worker was mixing cement when particles of the cement got into his eye. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. The worker slipped on the job ramp while walking down and fractured her left ankle. Worker stated that he suffers from seizures and takes medication for them. He had a seizure and fell down in the Worker stated that he suffers from seizures and takes medication for them. He had a seizure and fell down in the Worker stated that he suffers from seizures and takes medication for them. He had a seizure and fell down in the Worker stated that he suffers from seizures and takes medication for them. He had a seizure and fell down in the Worker stated that he suffers from seizures and takes medication for them. He had a seizure and fell down in the Worker stated that he suffers from seizures and takes medication for them. He had a seizure and fell down in the as per injured worker, he twisted his left ankle while installing rebars for grade beam around 11:00 am as per injured worker, he twisted his left ankle while installing rebars for grade beam around 11:00 am as per injured worker, he twisted his left ankle while installing rebars for grade beam around 11:00 am as per injured worker, he twisted his left ankle while installing rebars for grade beam around 11:00 am as per injured worker, he twisted his left ankle while installing rebars for grade beam around 11:00 am Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Concrete Worker, RHadames Tiburcio Mato, was assisting Concrete foreman, Nelson Catarino, strapping down Ma Worker was installing Shoe block for Horizontal Netting. Worker slipped when he stepoped on Shovel causing his Worker was installing Shoe block for Horizontal Netting. Worker slipped when he stepoped on Shovel causing his Worker was installing Shoe block for Horizontal Netting. Worker slipped when he stepoped on Shovel causing his Worker was installing Shoe block for Horizontal Netting. Worker slipped when he stepoped on Shovel causing his Worker was installing Shoe block for Horizontal Netting. Worker slipped when he stepoped on Shovel causing his Worker was installing Shoe block for Horizontal Netting. Worker slipped when he stepoped on Shovel causing his Worker was installing Shoe block for Horizontal Netting. Worker slipped when he stepoped on Shovel causing his Worker was installing Shoe block for Horizontal Netting. Worker slipped when he stepoped on Shovel causing his Worker was installing Shoe block for Horizontal Netting. Worker slipped when he stepoped on Shovel causing his Part of Delivery Team unloading multi-lift and was cut on his upper left arm

Part of Delivery Team unloading multi-lift and was cut on his upper left arm Part of Delivery Team unloading multi-lift and was cut on his upper left arm

Part of Delivery Team unloading multi-lift and was cut on his upper left arm

Part of Delivery Team unloading multi-lift and was cut on his upper left arm

Part of Delivery Team unloading multi-lift and was cut on his upper left arm

Foundation/excavation subcontractor worker tripped over rebar and sprained his ankle. Accident reported to SSN Foundation/excavation subcontractor worker tripped over rebar and sprained his ankle. Accident reported to SSN Foundation/excavation subcontractor worker tripped over rebar and sprained his ankle. Accident reported to SSN Foundation/excavation subcontractor worker tripped over rebar and sprained his ankle. Accident reported to SSN Foundation/excavation subcontractor worker tripped over rebar and sprained his ankle. Accident reported to SSN Foundation/excavation subcontractor worker tripped over rebar and sprained his ankle. Accident reported to SSN Foundation/excavation subcontractor worker tripped over rebar and sprained his ankle. Accident reported to SSN Foundation/excavation subcontractor worker tripped over rebar and sprained his ankle. Accident reported to SSN Foundation/excavation subcontractor worker tripped over rebar and sprained his ankle. Accident reported to SSN

Sheetrocker fail off a ladder approximately 4' high Sheetrocker fail off a ladder approximately 4' high

As per injured worker, he was carrying formwork with co-worker and then he lost balanced and hurt back. Did not As per injured worker, he was carrying formwork with co-worker and then he lost balanced and hurt back. Did not As per injured worker, he was carrying formwork with co-worker and then he lost balanced and hurt back. Did not As per injured worker, he was carrying formwork with co-worker and then he lost balanced and hurt back. Did not As per injured worker, he was carrying formwork with co-worker and then he lost balanced and hurt back. Did not As per injured worker, he was carrying formwork with co-worker and then he lost balanced and hurt back. Did not

irn_Incident_Fatality_	Count
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	1
1	0
1	0
1	0
1 1	0 0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0

1	0
1	0
1	
	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	
	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0

1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0
1	0

irn	Incident	Violations	Issued	Count

irn_Incident_Total_Square_Footage	
3	278,555
3	278,555
3	278,555
3	278,555
3	278,555
3	278,555
3	278,555
0	250,000
0	250,000
0	250,000
0	250,000
0	250,000
0	250,000
0	250,000
0	250,000
0	386000
0	386000
0	386000
0	66,985
0	66,985
0	66,985
0	66,985
0	66,985
0	66,985
0 1.2M	
3	350,000
3	350,000
3	350,000
3	350,000
3	350,000
3	350,000
3	350,000
3	350,000
3	350,000
3	350,000
3	350,000
3	350,000
0	200
0	200
0	200
0	200
0	200
0	2000
0	2000
0	2000
0	2000

0	254000
0	254000
0	254000
0	254000
0	209853
0	209853
0	209853
0	209853
0	209853
0	209853
0	209853
0	209853
0	33718
0	33718
0	33718
0	33718
0	33718
0	33718
0	33718
0	33718
0	33718
0	33718
0	33718
0	33718
0	33718
0	470,000
0	470,000
0	470,000
0	470,000
0	470,000
0	470,000
5	34446
5	34446
5 5	34446
	34446
5	34446
0	8000
0	8000
0	8000
0	8000
0	8000
0	8000
0	8000
0	8000
0	8000
0	8000
0	8000
U	8000

0	8000
0	8000
0	8000
5	820000
5	820000
5	820000
5	820000
5	820000
5	820000
0	2600
0	2600
0	2600
0	2600
0	2600
0	2600
5	5000
5	5000
5	5000
5	5000
5	5000
5	5000
5	5000
1	100
1	100
1	100
1	100
1	100
1	100
1	100
1	100
1	100
1	100
1	100
1	100
1	100
1	100
1	100
1	100
0	31446
0	31446
0	31446
0	31446
0	31446

 $irn_Incident_Location_New_Building_Flag$ Y Ν Y Y Y Y Y Y Y Y Y Y Y Y Ν Ν Ν Ν Ν Ν Ν Ν Ν

Y Y Y Y Y Y Y Y Y Y Y N N N N N Y Y Y Y Y Y

irn_Incident_Location_Existing_Num_Stories

10 100+

7	70
7	70
7	70
7	70
7	70
0	0
0	0
0	0
0	0

54	667.6
54	667.6
54	667.6
54	667.6
54	667.6
54	667.6

5	60
5	60
5	60
5	60
5	60
5	60
5	60
5	60
5	60
5	60
5	60
5	60
5	60
5	60
5	60
5	60

irn_Incident_Location_Proposed_Num_Stories

13	
13	
13	
13	
13	
13	

irn_Incident_Location_Proposed_Height

irn Active Permits Num 270 220569999-01-FO 270 220569999-01-FO-EA 270 220569999-01-NB 270 220569999-02-PL 270 240232672-01-ew-sd 270 X00270348-11-FN 270 X00300640-11-EL 286 121189203-01-NB 286 140883355-01-EQ OT 286 140888430-01-EQ OT 286 121189203-02-PL 286 123654296-01-DM 286 123725353-01-EQ OT 286 140832115-01-EW SP 286 140874837-01-EQ OT 153 220151868-01-EQ FN 153 220151868-01-NB 153 220151868-02-PL 73 240178678-01-EW SD 73 240178678-01-EW SP 73 240180255-01-EW SD 73 240247531-01-EQ OT 73 240251008-01-EQ OT 73 240253462-01-EW OT 123784164-01-EW OT 263 321192437-01-EQ-FN 263 321192437-01-FO 263 321192437-01-NB 263 321389467-01-AL 263 340561500-01-EW-SD 263 B00010537-I1-EL 263 B00054075-I1-SH 263 B00085229-I1-EL 263 B00131175-I1-SH 263 B00166921-I1-EL 263 B00172649-I1-SF 263 B00343720-I1-EL 340666087-01-EW-OT B00172001-I1-EL B00183520-I1-FN B00183521-I1-SH B00184717-I1-SF 140831429-01-EW-OT M00126980-I1-FN M00127059-I1-EL M00234347-I1-EL

100 420666005-01-FO 100 420666005-01-FO EA 100 420666005-01-NB 100 420666005-02-PL 125 220152705-01-FO EA 125 220152705-01-NB 125 220152705-04-PL 125 240196051-01-EW SD 125 240196051-01-EW SP 125 240202320-01-EW SD 125 240246177-01-EQ OT 125 240263184-01-EW OT 145 210178001-04-PL 145 240259457-01-EQ OT 145 210178001-01-FO 145 210178001-01-FO EA 145 210178001-01-NB 145 240239407-01-EW SD 145 240239416-01-EW SD 145 240239416-01-EW SP 145 240260285-01-EQ OT 145 240262773-01-EQ OT 145 240262808-01-EQ OT 145 240263488-01-EQ OT 145 240271594-01-EW OT 254 121204464-01-nb 254 140879930-01-eq-ot 254 140888591-01-eq-ot 254 m00236719-i1-sh 254 m00267860-i1-el 254 moo287138-i1-sf 130 420663838-01-FO 130 420663838-01-FO-EA 130 420663838-01-NB 130 420663838-04-PL 130 Q00173780-I1-FN 134 210178485-01 NB 134 210178485-01-FO 134 210178485-01-FO-EA 134 210178485-01-PL 134 240251268-01-EW-SD 134 240265262-01-EQ-OT 134 X00195186-I1-FN 134 X00221855-I1-EL 134 X00229262-IL-SH 134 X00229264-I1-FN 134 X00306731-I1-EL

134	X00306731-IL-EL	
134	X00312868-IL-EL	
134	X00312982-IL-VT	
122	420663589-01 FO	
122	420663589-01 FO EA	
122	420663589-01 NB	
122	420663589-03 PL	
122	440481195-01 EW SD	
122	440593458-01 EQ OT	
		2457547
		3450431
		3575100
		3575103
		3626067
		3752383
	420663838-01-FO	
	420663838-01-FO-EA	
	420663838-01-NB	
	440486948-01-EW-OT	
	Q00173780-I1-FN	
	Q00306849-I1-EL	
	Q00307098-I1-SF	
	300636872-01-EW-BL	
	300636881-01-PL	
	300636890-01-EW-OT	
	301792781-01-PL	
	301799873-01-EW-MH	
	301799873-01-EW-OT	
	320910911-01-AL	
	320910911-02-PL	
	320910911-03-PL	
	321163986-01-EQ-SF	
	321171593-01-EQ-SH	
	32196161034-01-EW-O	
	34072040-01-EW-OT	
	3P0006506-01	
	3P0008881-01	
	3PL008454-03-EW-SP	
130	420663838-01-FO	
130	420663838-01-FO-EA	
130	420663838-01-NB	
130	420663838-04-PL	
130	Q00173780-I1-FN	

158'-6 158'-6 158'-6 158'-6 158'-6 158'-6