

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 34 ST. FERRY TERMINAL / EAST 35 ST. PIER
Address : EAST RIVER AT 34TH STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0199.010 / 14223 **Yr Built/Renovated** : 2010 /
Area Sq Ft : 3,723 **Project Type** : FERRIES
Date of Survey : 03-Mar-2023 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1
Block : 966 **Lot** : 50 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Site Pavements		\$128,700
Total		\$128,700
Importance Code C		\$128,700
Total		\$128,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$900			\$26,700
Interior Architecture	\$400	\$300		
Electrical	\$600	\$700	\$3,100	\$4,100
Mechanical			\$100	
Site Enclosure	\$5,300			
Site Pavements	\$18,600	\$8,000	\$500	\$1,900
Total	\$25,800	\$9,000	\$3,700	\$32,800
Importance Code A	\$900			\$26,800
Importance Code B	\$600	\$1,000	\$3,100	\$4,100
Importance Code C	\$24,300	\$8,000	\$500	\$1,900
Total	\$25,800	\$9,000	\$3,700	\$32,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

**DEPARTMENT OF TRANSPORTATION - 841
EAST 34 ST. FERRY TERMINAL / EAST 35 ST. PIER**

Asset # : 14223

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Metal/Glass Curt Wall	5%			LIFE	**	5	\$800	
Metal Panel	85%			2054	**	5-10	\$48,400	
Wood	10%	2-4	\$900	2047	**	5	\$2,100	
<i>Deteriorated Finish, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Ticket Booth Facade</i>								
Windows								
Aluminum	100%			2050	**	5	\$100	
Roof								
Single Ply Membrane	92%			2039	**	10	\$13,500	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Light Weight Fabric Structure</i>								
Not Accessible	8%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : Rooftop Ticket Booth. Inaccessible Assume Concrete Deck</i>								
Soffits								
Exposed Struc: Steel	100%			LIFE	**	5	\$44,500	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Canopy</i>								
<i>Explanation : Steel Structure Covered By Fabric Material</i>								
Interior								
Floors								
Cast in Place Concrete	50%			LIFE	**	5	\$6,100	
Vinyl Tile	50%			2039	**	3	\$1,000	
Interior Walls								
Concrete Masonry Unit	50%			LIFE	**	5	\$500	
Gypsum Board	50%	Now	\$400	LIFE	**	5	\$800	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Toilet</i>								
Ceilings								
Exposed Struc: Steel	50%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Mechanical Room</i>								
<i>Explanation : Metal Decking</i>								
Gypsum Board	50%			LIFE	**	5	\$800	
Site Enclosure								
Fence/Gates								
Chain Link	100%	2-4	\$5,300	2054	**			
<i>Corrosion/Rusting, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout Deck</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chian Link Is Stainless Steel Wire Mesh</i>								
Site Pavements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
EAST 34 ST. FERRY TERMINAL / EAST 35 ST. PIER**

Asset # : 14223

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Site Pavements

Public Sidewalk

Pavers/Stone

100%

2043

**

On-Site Walkways

Metal

15%

2054

**

1-3

\$25,500

Pavers/Stone

75%

2-4

\$16,700

2043

**

Other Observation, Extent : Moderate, Area Affected : 5%

Location : At Ferry Gates

Explanation : Erosion Caused By Gate Swing

Wood

10%

2032

\$128,700

1-3

\$7,600

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Service Equipment

Molded Case Bkrs

100%

2054

**

5

\$100

Other Observation, Extent : Light, Area Affected : 100%

Location : Electrical Room

Explanation : One 400 Ampere Main Disconnect

Switchgear / Switchboard

Molded Case Bkrs

100%

2054

**

5

\$100

Raceway

Conduit

100%

2054

**

1

Panelboards

Fused Disc Sw

1%

2050

**

5

Molded Case Bkrs

99%

2050

**

5

\$100

Wiring

Thermoplastic

100%

2054

**

1

Motor Controllers

Locally Mounted

100%

2047

**

5

Ground

Grounding Devices

Generic

100%

LIFE

**

5

\$100

Stand-by Power

Transfer Switches

Automatic

100%

2047

**

1

\$1,200

Generators

Diesel

100%

2043

**

1

\$1,400

Other Observation, Extent : Light, Area Affected : 100%

Location : Generator Room

Explanation : One 77 Kilowatts

Batteries

Lead/Acid

100%

2028

\$2,400

5

\$100

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 34 ST. FERRY TERMINAL / EAST 35 ST. PIER

Asset # : 14223

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Stand-by Power								
Fuel Storage								
Main Tank	100%			2062	**	5		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Generator Room</i>								
<i>Explanation : No Available Nameplate Rating Capacity.</i>								
Lighting								
Interior Lighting								
Fluorescent	100%			2039	**	10	\$3,400	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
Egress Lighting								
Emergency, Service	50%			2039	**	1		
Exit, Service	50%			2039	**	1		
Exterior Lighting								
LED	30%			2039	**			
No Component	70%							
Alarm								
Security System								
Generic	100%			2039	**	1	\$1,400	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Outside</i>								
<i>Explanation : CCTV Surveillance Cameras</i>								
Fire/Smoke Detection								
Generic, Digital	100%			2039	**	1-3	\$2,300	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : Strobe Lights, Horn, Smoke Detector, Alarm Bell, Pull Box And Fire Alarm Panel</i>								

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Conversion Equipment								
Radiant Heater	10%			2034	\$9,500	2	\$200	
No Component	90%							
Air Conditioning								
Energy Source								
Electricity	10%			2050	**	1		
No Component	90%							
Conversion Equipment								
Split Unit	10%			2034	\$8,600			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : 1st Floor</i>								
<i>Explanation : Heating And Cooling</i>								
No Component	90%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
EAST 34 ST. FERRY TERMINAL / EAST 35 ST. PIER**

Asset # : 14223

Mechanical	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Ventilation								
Distribution								
Ductwork/Diffusers	10%			LIFE	**	2-5	\$200	
No Component	90%							
Exhaust Fans								
Roof	10%			2034	\$700	2		
No Component	90%							
Plumbing								
H/C Water Piping								
Brass/Copper	10%			2044	**	1		
No Component	90%							
Sanitary Piping								
Cast Iron	10%			LIFE	**	1		
No Component	90%							
Backflow Preventer								
No Component	90%							
Generic	10%			2034	\$200	1		
Fixtures								
Generic	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ST. GEORGE STATION FERRY, BUS, TRAIN TERMINAL
Address : 1 RICHMOND TERRACE @ BAY ST.
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0109.000 / 2420 **Yr Built/Renovated** : 1950 / 2013
Area Sq Ft : 279,135 **Project Type** : FERRIES
Date of Survey : 24-Oct-2023 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,3
Block : 2 **Lot** : 1 **BIN** : 5141706

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$936,900	\$1,362,700
Interior Architecture	\$1,087,200	\$989,300
Mechanical	\$1,308,500	\$24,467,700
Total	\$3,332,600	\$26,819,800
Importance Code A	\$936,900	\$1,362,700
Importance Code B	\$2,340,700	\$25,457,000
Importance Code C	\$55,000	
Total	\$3,332,600	\$26,819,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$96,200		\$14,700	
Interior Architecture	\$146,100		\$16,700	\$3,100
Electrical	\$54,700	\$46,000	\$55,100	\$47,900
Mechanical	\$164,200	\$103,400	\$161,600	\$97,500
Elevators/Escalators	\$31,200	\$31,200	\$31,200	\$31,200
Total	\$492,500	\$180,500	\$279,300	\$179,600
Importance Code A	\$110,000	\$13,800	\$28,800	\$13,800
Importance Code B	\$351,600	\$166,700	\$233,800	\$165,800
Importance Code C	\$30,900		\$16,700	
Total	\$492,500	\$180,500	\$279,300	\$179,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE STATION FERRY, BUS, TRAIN TERMINAL

Asset # : 2420

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Glass Block	4%			LIFE	**	5	\$14,700	
Masonry: Brick	30%	2-4	\$355,300	LIFE	**	5	\$88,400	
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Metal, Corrugated	25%			2045	**	1		
Metal/Glass Curt Wall	25%			LIFE	**	5	\$276,100	
Metal Panel	10%			2045	**	5-10	\$202,500	
Metal Coiling Doors	6%			2040	**	5	\$55,200	
Windows								
Aluminum	80%			2043	**	5	\$8,800	
Metal Louvers	15%			2038	**	10	\$10,300	
Steel	5%	4+	\$40,200	2060	**	5	\$3,400	
<i>Corrosion/Rusting, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Bulkheads</i>								
<i>Thermally Inefficient, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Slips</i>								
Parapets								
Masonry: Brick	20%			LIFE	**	5-10	\$23,000	
Metal Panel	10%			2045	**	5	\$6,500	
Metal Rail	70%			2040	**	5-10	\$212,800	
Roof								
Cast in Place Concrete	10%			LIFE	**	10	\$76,300	
Metal Panel	15%			2040	**	10	\$125,900	
Paver: Asphalt	10%	Now	\$62,200	2038	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Over First Floor Corridor</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Over First Floor Corridor</i>								
Roll Roofing	10%	2-4	\$29,000	2031	\$290,100	5	\$38,100	
<i>Ponding, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Rear Roof With Mechanical Equipment</i>								
Sloped Glazing	5%			LIFE	**	5	\$610,200	
Under Construction	50%							
Soffits								
Cast in Place Concrete	100%			LIFE	**	5		

Interior

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE STATION FERRY, BUS, TRAIN TERMINAL
Asset # : 2420

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Floors								
Cast in Place Concrete	20%			LIFE	**	5	\$213,600	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout 1st Floor</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Slips</i>								
<i>Explanation : Movable Steel Ferry Boarding Bridges And Gallows Are Not Included In This Survey</i>								
Ceramic Tile	60%	0-2	\$806,400	2038	**	5	\$73,200	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Concourses</i>								
Steel Grating	5%			2055	**	1		
Terrazzo	3%			LIFE	**	5	\$11,400	
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : Main Waiting Room</i>								
<i>Explanation : Inlaid Harbor Map</i>								
Terrazzo	2%	Now	\$22,300	LIFE	**	5	\$3,800	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Train Turnstile Entrance Area</i>								
<i>Worn/Eroded, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Train Turnstile Entrance Area</i>								
Vinyl Tile	10%			2035		3	\$12,200	
Interior Walls								
Ceramic Tile	20%			2038	**	5	\$33,400	
Concrete Masonry Unit	15%			LIFE	**	5	\$20,000	
Glass: Special Gauge	10%			LIFE	**	1		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Ferry Waiting Room</i>								
<i>Explanation : Double Glazed Glass Enclosure And Sliding Boarding Doors</i>								
Gypsum Board	30%			LIFE	**	5-10	\$85,000	
SGFT/Glazed Masonry	25%			LIFE	**	10	\$20,800	
Ceilings								
AcousTileSusp.Lay-In	10%			2040	**	5	\$20,100	
Exposed Struc: Concrete	20%			LIFE	**	5-10	\$50,300	
Exposed Struc: Steel	10%			LIFE	**	10	\$40,200	
Gypsum Board	40%	Now	\$68,700	LIFE	**	5	\$100,500	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Main Concourse And Retail</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Main Concourse, Retail And 3rd Floor Rear Lobby</i>								
Metal Panel	20%			LIFE	**	5	\$100,500	
Site Enclosure								
Fence/Gates								
Metal Panel	100%			LIFE	**	10		
Site Pavements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE STATION FERRY, BUS, TRAIN TERMINAL

Asset # : 2420

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Site Pavements

Public Sidewalk

Cast in Place Concrete	100%			2048	**			
------------------------	------	--	--	------	----	--	--	--

On-Site Walkways

Cast in Place Concrete	100%			2040	**			
------------------------	------	--	--	------	----	--	--	--

Cracking/Crumbling, Extent : Moderate, Area Affected : 5%

Location : Rear Adjacent To Ferry Dock

Parking/Driveway

Asphalt	80%			2038	**			
---------	-----	--	--	------	----	--	--	--

Cast in Place Concrete	20%			2040	**			
------------------------	-----	--	--	------	----	--	--	--

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Over 600 Volts

Service Equipment

Air Circuit Breaker	100%			2055	**	3	\$1,000	
---------------------	------	--	--	------	----	---	---------	--

Transformers

Dry Type	100%			2048	**	3	\$1,500	
----------	------	--	--	------	----	---	---------	--

Other Observation, Extent : N/A, Area Affected : 100%

Location : Electrical Room

Explanation : Two 2,000 Kilovolt-ampere, 4,160 Volts Primary To 120/ 208 Volts

Secondary

Feeders

Cable	100%			2051	**	1		
-------	------	--	--	------	----	---	--	--

Raceway

Conduit	90%			2055	**	1		
---------	-----	--	--	------	----	---	--	--

Tray	10%			2048	**	1		
------	-----	--	--	------	----	---	--	--

Under 600 Volts

Service Equipment

Air Circuit Breaker	100%			2055	**	5	\$1,500	
---------------------	------	--	--	------	----	---	---------	--

Other Observation, Extent : N/A, Area Affected : 100%

Location : Electrical Room

Explanation : Six 4,000 Ampere, Four 3,200 Ampere And Two 2,000 Ampere Main Service

Disconnect Switches.

Switchgear / Switchboard

Fused Disc Sw	20%			2055	**	5	\$200	
---------------	-----	--	--	------	----	---	-------	--

Molded Case Bkrs	80%			2055	**	5	\$5,900	
------------------	-----	--	--	------	----	---	---------	--

Raceway

Conduit	90%			2055	**	1		
---------	-----	--	--	------	----	---	--	--

Tray	10%			2048	**	1		
------	-----	--	--	------	----	---	--	--

Panelboards

Fused Disc Sw	10%			2043	**	5	\$600	
---------------	-----	--	--	------	----	---	-------	--

Molded Case Bkrs	90%			2043	**	5	\$6,600	
------------------	-----	--	--	------	----	---	---------	--

Wiring

Thermoplastic	100%			2055	**	1		
---------------	------	--	--	------	----	---	--	--

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE STATION FERRY, BUS, TRAIN TERMINAL
Asset # : 2420

Electrical	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Under 600 Volts								
Motor Controllers								
Locally Mounted	50%			2048	**	5	\$900	
Variable Frequency Drive	50%			2048	**			
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$8,200	
Stand-by Power								
Transfer Switches								
Automatic	100%			2048	**	1	\$85,900	
Generators								
Diesel	75%			2044	**	1	\$81,100	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Generator Room Across Slip</i>					
			<i>Explanation : Diesel Generator Rated At 1,000 Kilowatts</i>					
Diesel	25%			2048	**	1	\$27,000	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Outside Near Boiler Room</i>					
			<i>Explanation : Diesel Generator Rated At 515 Kilowatts</i>					
Batteries								
Lead/Acid	100%			2029	\$2,400	5	\$10,300	
Fuel Storage								
Main Tank								
	20%			2063	**	5		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Outside Near Boiler Room</i>					
			<i>Explanation : 675 Gallons Rated Capacity</i>					
Main Tank	10%			2063	**	5		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Generator Room Across Slip</i>					
			<i>Explanation : 275 Gallons Rated Capacity</i>					
Main Tank	70%			2050	**	5		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Above Ground</i>					
			<i>Explanation : 10,000 Gallon Shared With Boilers</i>					
Lighting								
Interior Lighting								
LED	100%			2040	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout The Building</i>					
			<i>Explanation : LED Lighting Fixtures Observed</i>					
Egress Lighting								
Emergency, Service	50%			2040	**	1		
Exit, Service	50%			2040	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE STATION FERRY, BUS, TRAIN TERMINAL

Asset # : 2420

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Exterior Lighting HID	10%			2040	**	10	\$100	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Outside</i>						
		<i>Explanation : Operated Via Timer</i>						
LED	15%			2040	**			
No Component	75%							
Alarm								
Security System Generic	100%			2040	**	1	\$104,300	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout Public Spaces</i>						
		<i>Explanation : Surveillance Cameras</i>						
Fire/Smoke Detection Generic, Analog	100%			2040	**	1-3	\$172,000	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout The Building</i>						
		<i>Explanation : Manual Pull Station, Alarm Bells, Smoke Detectors, Strobe Lights And Horns</i>						
Mechanical								
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Heating								
Energy Source Interruptible Gas/Dual Fuel	100%			2055	**	1		
Conversion Equipment Hot Water Boiler	100%			2040	**	1	\$138,000	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Mechanical Room</i>						
		<i>Explanation : 3 Units</i>						
Distribution Hot Wtr Piping/Pump	100%			2043	**	4	\$20,600	
Terminal Devices Air Handler	60%			2035	\$3,078,200	1	\$103,600	
Convector/Radiator	25%			2040	**	1	\$22,500	
Unit Heater - Hot Water	15%			2035	\$242,500			
Controls Digital	100%			2030	\$7,829,800			
Air Conditioning								
Energy Source Electricity	100%			2051	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE STATION FERRY, BUS, TRAIN TERMINAL

Asset # : 2420

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Air Conditioning								
Conversion Equipment								
Absorption Chiller/Direct Fire	90%			2030	\$6,744,500	1	\$271,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Mechanical Room</i>								
<i>Explanation : 2 Units. Lithium Bromide Refrigerant</i>								
Split Unit	10%			2035	\$647,400			
Distribution								
CW & CHW Wtr Pipe/Pump	90%			2045	**	4	\$12,400	
No Component	10%							
Terminal Devices								
Air Handler/Cool/Ht	90%			2035	\$4,760,800	1	\$155,400	
Fan Coil - 2 Pipe	10%			2035	\$831,700	1	\$9,000	
Heat Rejection								
Air Cooled Condenser Unit	10%			2035	\$78,900	2	\$19,400	
Water Cooling Tower	80%			2029	\$1,101,600	2	\$224,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : 4 Cooling Towers Service Both Chillers</i>								
Water Cooling Tower	10%	0-2	\$13,800	2029	\$137,700	2	\$22,500	
<i>Corroded, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Supporting Beams, Roof</i>								
Ventilation								
Distribution								
Ductwork/Diffusers	100%			LIFE	**	2-5	\$246,400	
Exhaust Fans								
Interior	60%			2040	**	2	\$5,100	
Roof	40%			2040	**	2	\$3,400	
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2045	**	1		
Water Heater With Tanks								
Electric	100%			2030	\$184,800	4		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Various Locations</i>								
<i>Explanation : 5 Small Units 80 Gallons Each</i>								
Sanitary Piping								
Cast Iron	100%			LIFE	**	1		
Storm Drain Piping								
Cast Iron	100%			LIFE	**	1		
Sewage Ejector(s)								
Electric	100%			2040	**	4	\$11,100	
Backflow Preventer								
Generic	100%			2040	**	1	\$17,100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE STATION FERRY, BUS, TRAIN TERMINAL
Asset # : 2420

Mechanical		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Plumbing								
Fixtures								
Generic	100%							
Vertical Transport								
Elevators								
Hydraulic	100%			LIFE		* *		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Basement To 2nd Floor</i>						
		<i>Explanation : Two Passenger Units And One Freight Unit</i>						
Escalators								
Under 20' Rise	100%			LIFE		* *		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 1st To 2nd Floor</i>						
		<i>Explanation : One Unit</i>						
Fire Suppression								
Standpipe								
Generic	100%			2045		* *	1-5	\$140,700
Sprinkler								
Generic	100%			2045		* *	1-2	\$78,200

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : VESSEL MAINTENANCE FACILITY
Address : 1 BAY STREET @ FERRY TERMINAL
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0141.000 / 4379 **Yr Built/Renovated** : 1992 /
Area Sq Ft : 85,000 **Project Type** : FERRIES
Date of Survey : 24-Oct-2023 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2A,3
Block : 1 **Lot** : 70 **BIN** : 5132949

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$103,600	\$1,579,900
Interior Architecture	\$316,700	\$1,116,000
Electrical		\$1,169,000
Mechanical		\$4,455,600
Site Pavements	\$54,700	
Total	\$475,000	\$8,320,400
Importance Code A	\$103,600	\$1,644,500
Importance Code B	\$234,000	\$6,593,300
Importance Code C	\$137,400	\$82,700
Total	\$475,000	\$8,320,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$79,800		\$10,300	
Interior Architecture	\$121,500		\$9,200	\$3,900
Electrical	\$16,400	\$13,100	\$14,200	\$15,400
Mechanical	\$41,800	\$17,900	\$22,400	\$14,200
Site Pavements	\$6,200			
Elevators/Escalators	\$14,400	\$14,400	\$14,400	\$14,400
Total	\$280,000	\$45,400	\$70,400	\$47,900
Importance Code A	\$84,000	\$4,200	\$14,500	\$4,200
Importance Code B	\$163,100	\$41,200	\$49,900	\$43,700
Importance Code C	\$32,900		\$6,100	
Total	\$280,000	\$45,400	\$70,400	\$47,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
VESSEL MAINTENANCE FACILITY
Asset # : 4379

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Cast in Place Concrete	5%			LIFE	**	5	\$40,300	
Masonry: Brick	80%	4+	\$103,600	LIFE	**	5	\$64,400	
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Metal Panel	10%			2045	**	5-10	\$55,400	
Metal Coiling Doors	5%			2040	**	5	\$12,600	
Windows								
Aluminum	100%			2043	**	5	\$20,500	
Parapets								
Cast in Place Concrete	5%			LIFE	**	5	\$8,900	
Masonry: Brick	85%			LIFE	**	5-10	\$50,100	
Metal Panel	10%			2045	**	5	\$3,300	
Roof								
IRMA/Protected Membrane	75%			2035		10	\$62,900	
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Main Roof</i>								
<i>Explanation : Solar Panels</i>								
Metal Panel	5%			2040	**	10	\$7,700	
Single Ply Membrane	20%			2040	**	10	\$16,800	
Soffits								
Cast in Place Concrete	100%			LIFE	**	5	\$25,000	
Interior								
Floors								
Cast in Place Concrete	70%	0-2	\$145,200	LIFE	**	5	\$191,200	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Ceramic Tile	5%			2038	**	5	\$6,200	
Vinyl Tile	25%	2-4	\$42,100	2035		3	\$11,700	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Interior Walls								
Ceramic Tile	5%			2038	**	5	\$12,200	
Concrete Masonry Unit	85%			LIFE	**	5	\$165,500	
Gypsum Board	10%			LIFE	**	5-10	\$41,400	
Ceilings								
AcousTileSusp.Lay-In	25%	Now	\$25,300	2040	**	5	\$15,600	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Staining/Discoloring, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout Third Floor</i>								
Exposed Struc: Concrete	65%			LIFE	**	5-10	\$101,400	
Gypsum Board	10%			LIFE	**	5-10	\$42,900	
Site Pavements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
VESSEL MAINTENANCE FACILITY
Asset # : 4379

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2040		**		
On-Site Walkways								
Cast in Place Concrete	100%	0-2	\$6,200	2040		**		
			<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Adjacent To Main Driveway</i>					
Parking/Driveway								
Asphalt	100%	0-2	\$54,700	2038		**		
			<i>Cracking/Crumbling, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Driveway</i>					
Electrical								
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Under 600 Volts								
Service Equipment								
Air Circuit Breaker	30%			2055		**	5	\$100
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Electrical Room</i>					
			<i>Explanation : Four 400 Ampere Service Disconnect Switches Serving The Solar Panels.</i>					
Fused Disc Sw	70%			2045		**	5	\$300
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Electrical Room</i>					
			<i>Explanation : Two Main Service Disconnect Switches Rated At 1,600 Amperes</i>					
Switchgear / Switchboard								
Fused Disc Sw	100%			2045		**	5	\$400
Raceway								
Conduit	100%			2045		**	1	
Panelboards								
Fused Disc Sw	10%			2043		**	5	\$200
Molded Case Bkrs	90%			2043		**	5	\$2,000
Wiring								
Thermoplastic	100%			2045		**	1	
Motor Controllers								
Locally Mounted	70%			2040		**	5	\$400
Variable Frequency Drive	30%			2048		**		
Ground								
Grounding Devices								
Generic	100%			LIFE		**	5	\$2,500
Stand-by Power								
Transfer Switches								
Automatic	70%			2048		**	1	\$18,300
Manual	30%			2055		**	5	\$100

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
VESSEL MAINTENANCE FACILITY
Asset # : 4379

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Stand-by Power Generators								
Diesel	30%			2038	**	1	\$9,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Outside</i>								
<i>Explanation : 400 Kilowatts</i>								
Natural Gas	70%			2044	**	1	\$23,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Outside</i>								
<i>Explanation : No Available Nameplate Rating Capacity</i>								
Batteries								
Lead/Acid	30%			2029	\$700	5	\$900	
No Component	70%							
Fuel Storage								
Day Tank	100%			2051	**	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 675 Gallons</i>								
Lighting								
Interior Lighting Fluorescent	100%			2035	\$721,000	10	\$78,000	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Egress Lighting								
Emergency, Service	50%			2035	\$25,600	1		
Exit, Service	50%			2035	\$17,900	1		
Exterior Lighting								
Fluorescent	2%			2035	\$6,600	10	\$200	
<i>T-5 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Entrance</i>								
HID	8%			2035	\$31,000	10		
No Component	90%							
Alarm								
Security System								
Generic	100%			2035	\$155,800	1	\$31,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Hallways, Outside Perimeter</i>								
<i>Explanation : Surveillance Cameras</i>								
Fire/Smoke Detection								
Generic, Analog	100%			2035	\$214,100	1-3	\$54,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Hallways, Offices</i>								
<i>Explanation : Alarm Bells And Manual Pull Stations</i>								

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
VESSEL MAINTENANCE FACILITY
Asset # : 4379

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Fuel Oil No 2	25%			2035	\$47,600	5	\$6,600	
Natural Gas	75%			2055	**	1		
Conversion Equipment								
Furnace	25%			2035	\$64,600	1	\$10,500	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor</i>								
<i>Explanation : Heats The Trade Workshop</i>								
Hot Water Boiler	75%			2048	**	1	\$31,500	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor Boiler Room</i>								
<i>Explanation : 2 Gas Fired Units, 1 Oil Unit Used As Backup</i>								
Distribution								
Hot Wtr Piping/Pump	100%			2051	**	4	\$6,300	
Terminal Devices								
Air Handler	60%			2030	\$937,300	1	\$31,500	
Fan Coil Unit/Heat	40%			2030	\$823,300	1	\$11,000	
Controls								
Digital	100%			2030	\$2,384,300			
Air Conditioning								
Energy Source								
Electricity	40%			2051	**	1		
No Component	60%							
Conversion Equipment								
Exterior Pkg Unit - Cooling	20%			2040	**	2	\$1,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : Refrigerant R-410a</i>								
Split Unit	20%			2040	**			
No Component	60%							
Terminal Devices								
Fan Coil - 2 Pipe	10%			2040	**	1	\$2,800	
No Component	90%							
Heat Rejection								
Air Cooled Condenser Unit	10%			2040	**	2	\$5,900	
No Component	90%							
Ventilation								
Distribution								
Ductwork/Diffusers	100%			LIFE	**	2-5	\$75,000	
Exhaust Fans								
Interior	20%			2035	\$73,600	2	\$500	
Roof	20%			2035	\$32,200	2	\$500	
Wall Unit	60%			2040	**	2	\$1,600	
Plumbing								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
VESSEL MAINTENANCE FACILITY
Asset # : 4379

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Plumbing								
H/C Water Piping	Brass/Copper	100%			2045	**	1	
Water Heater With Tanks	Oil Fired	100%			2030	\$172,500	1	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Boiler Room</i>								
<i>Explanation : 110 Gallons</i>								
Sanitary Piping	Cast Iron	100%			LIFE	**	1	
Storm Drain Piping	Cast Iron	100%			LIFE	**	1	
Sewage Ejector(s)	Electric	100%			2040	**	4	\$3,400
Backflow Preventer	Generic	100%			2040	**	1	\$5,200
Fixtures								
	Generic	100%						
Vertical Transport								
Elevators	Hydraulic	100%			LIFE	**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : One Unit From 1st To 3rd Floor, One Unit From 1st To 2nd Floor</i>								
<i>Explanation : One Passenger Unit And One Freight Unit</i>								
Fire Suppression								
Standpipe	Generic	100%			2045	**	1-5	\$42,900
Sprinkler	Generic	100%			2045	**	1-2	\$23,800

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST MIDTOWN FERRY TERMINAL / PIER 79
Address : HUDSON RIVER AT 39 STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0214.000 / 14635 **Yr Built/Renovated** : 2005 /
Area Sq Ft : 20,200 **Project Type** : FERRIES
Date of Survey : 04-Nov-2022 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2
Block : 665 **Lot** : 14 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$115,200	\$82,400
Electrical		\$209,300
Mechanical		\$566,600
Total	\$115,200	\$858,300
Importance Code A	\$115,200	\$82,400
Importance Code B		\$775,900
Total	\$115,200	\$858,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$47,000	\$35,200		\$9,000
Interior Architecture	\$46,400	\$5,300	\$8,100	\$400
Electrical	\$11,800	\$4,000	\$6,100	\$16,200
Mechanical	\$21,100	\$1,100	\$2,800	\$1,100
Site Enclosure		\$19,800		
Site Pavements	\$45,600			
Elevators/Escalators	\$7,200	\$7,200	\$7,200	\$7,200
Total	\$179,100	\$72,700	\$24,200	\$33,900
Importance Code A	\$47,000	\$35,200		\$9,100
Importance Code B	\$67,100	\$17,600	\$23,600	\$24,900
Importance Code C	\$65,100	\$19,800	\$600	
Total	\$179,100	\$72,700	\$24,200	\$33,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST MIDTOWN FERRY TERMINAL / PIER 79
Asset # : 14635

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Metal/Glass Curt Wall	80%			LIFE	**	5	\$37,900	
		<i>Glazing Clouded, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Lobby Area</i>						
Metal Panel	10%			2054	**	5-10	\$17,400	
Metal Coiling Doors	3%			2047	**	5	\$2,400	
Pre-Cast Concrete	2%			LIFE	**	5	\$1,600	
Stucco Cement	5%			2047	**	5	\$3,200	
Windows								
Aluminum	100%	Now	\$600	2050	**	5	\$300	
		<i>Water Penetration, Extent : Severe, Area Affected : 2%</i>						
		<i>Location : 2nd Floor Taxi Area Office</i>						
Parapets								
Metal Rail	100%			2047	**	5-10	\$53,500	
Roof								
Cast in Place Concrete	10%			LIFE	**			
		<i>Water Penetration, Extent : Severe, Area Affected : 5%</i>						
		<i>Location : Boardwalk During Heavy Rain Into Lobby Area</i>						
Sloped Glazing	20%			LIFE	**	5	\$82,400	
Spray-on Foam	70%	Now	\$46,400	2039	**	5	\$14,400	
		<i>Blisters, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Throughout</i>						
		<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Throughout</i>						
		<i>Ponding, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : North Side Of Building</i>						
		<i>Water Penetration, Extent : Severe, Area Affected : 5%</i>						
		<i>Location : South Side Of Building, By Generator</i>						
Soffits								
Metal Panel	25%			2054	**	5-10	\$15,700	
Stucco Cement	75%	Now	\$115,200	2047	**	5	\$8,500	
		<i>Cracking/Crumbling, Extent : Severe, Area Affected : 15%</i>						
		<i>Location : West Side Walkway</i>						
		<i>Water Penetration, Extent : Severe, Area Affected : 20%</i>						
		<i>Location : West Side Walkway</i>						
Interior								
Floors								
Carpet	35%			2033	\$181,800	3	\$15,800	
Cast in Place Concrete	5%			LIFE	**	5	\$3,300	
Ceramic Tile	50%			2043	**	5	\$15,000	
Vinyl Tile	10%	Now	\$4,100	2039	**	3	\$1,100	
		<i>Cracking/Crumbling, Extent : Severe, Area Affected : 15%</i>						
		<i>Location : At Building Expansion Joints</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST MIDTOWN FERRY TERMINAL / PIER 79

Asset # : 14635

Architecture		Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost		
Interior									
Interior Walls									
Ceramic Tile	5%			2043	**	5	\$1,200		
Concrete Masonry Unit	5%			LIFE	**	5	\$500		
Glass: Single Pane	40%	Now	\$28,100	LIFE	**	5	\$7,100		
<i>Glazing Broken/Cracked, Extent : Severe, Area Affected : 5%</i>									
<i>Location : 1st Floor Ticket Area</i>									
Gypsum Board	10%			LIFE	**	5	\$1,400		
Metal Panel	40%			LIFE	**				
Ceilings									
AcousTileSusp.Lay-In	10%	Now	\$1,000	2047	**	5	\$1,500		
<i>Water Penetration, Extent : Moderate, Area Affected : 10%</i>									
<i>Location : 2nd Floor Offices, Water Taxi</i>									
Embossed Metal	30%	Now	\$13,300	LIFE	**	5	\$4,100		
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 10%</i>									
<i>Location : Lobby Waiting Area</i>									
Gypsum Board	60%			LIFE	**	5	\$22,600		
Site Enclosure									
Fence/Gates									
Aluminum Rail	100%			2047	**	5-10	\$32,600		
Free Standing Walls									
Cast in Place Concrete	10%			2069	**				
Cast in Place Concrete	90%			2069	**				
<i>Other Observation, Extent : Light, Area Affected : 100%</i>									
<i>Location : Throughout</i>									
<i>Explanation : Material Is Metal Panel</i>									
Site Pavements									
Public Sidewalk									
Cast in Place Concrete	100%	Now	\$8,600	2047	**				
<i>Cracking/Crumbling, Extent : Light, Area Affected : 2%</i>									
<i>Location : Along 12th Avenue</i>									
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>									
<i>Location : Along 12th Avenue</i>									
<i>Explanation : Failing Expansion Joint In Sidewalk</i>									
On-Site Walkways									
Cast in Place Concrete	100%	Now	\$3,500	2047	**				
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 10%</i>									
<i>Location : Bulkheads</i>									
<i>Other Observation, Extent : Severe, Area Affected : 20%</i>									
<i>Location : Expansion Joints Of Walkway</i>									
<i>Explanation : Joint Failure</i>									

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST MIDTOWN FERRY TERMINAL / PIER 79
Asset # : 14635

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Site Pavements								
Parking/Driveway								
Asphalt	30%	Now	\$33,400	2043	**			
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Driveway</i>								
<i>Potholes, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Driveway</i>								
Cast in Place Concrete	70%			2047	**			

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2054	**	5	\$100	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : One 4,000 Ampere Main Disconnect Switch</i>								
Transformers								
Dry Type	100%			2047	**	5	\$100	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : One 150 Kilovolt Amperes, 480 Volt 208/120 Volt</i>								
Switchgear / Switchboard								
Fused Disc Sw	100%			2054	**	5	\$100	
Raceway								
Conduit	100%			2054	**	1		
Panelboards								
Fused Disc Sw	10%			2050	**	5		
Molded Case Bkrs	90%			2042	**	5	\$500	
Wiring								
Thermoplastic	80%			2054	**	1		
Thermoplastic	20%	0-2	\$6,500	2064	**	1		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Building Exterior</i>								
<i>Explanation : Exterior Under Concrete Wiring Was Damaged By The Sandy Storm And Is Causing Exterior Lighting Problems</i>								
Motor Controllers								
Locally Mounted	100%			2047	**	5	\$100	
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$300	
Stand-by Power								
Transfer Switches								
Automatic	100%			2047	**	1	\$6,200	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST MIDTOWN FERRY TERMINAL / PIER 79
Asset # : 14635

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Stand-by Power								
Generators								
Diesel	100%			2043	**	1	\$7,800	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : One 250 Kilovolt Amperes, 200 Kilowatt</i>								
Batteries								
Lead/Acid	100%			2028	\$2,400	5	\$700	
Fuel Storage								
Main Tank	100%			2062	**	5		
Lighting								
Interior Lighting								
Fluorescent	20%			2034	\$44,100	10	\$3,700	
<i>T-5 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Lobby, Facade And Waiting Area</i>								
Fluorescent	55%			2034	\$121,100	10	\$10,200	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Fluorescent	20%			2034	\$44,100	10	\$3,700	
<i>Compact Fluorescent Light, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
Incandescent	5%			2029	\$12,800	2		
Egress Lighting								
Emergency, Service	70%			2039	**	1		
Exit, Service	30%			2039	**	1		
Exterior Lighting								
Fluorescent	5%	2-4	\$2,000	2039	**			
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Walkway Shade</i>								
HID	15%			2039	**	10		
No Component	80%							
Alarm								
Security System								
Generic	100%			2039	**	1	\$7,500	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Interior And Exterior</i>								
<i>Explanation : Cameras Security System</i>								
Fire/Smoke Detection								
Generic, Digital	100%			2039	**	1-3	\$12,500	

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2060	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
WEST MIDTOWN FERRY TERMINAL / PIER 79**

Asset # : 14635

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Vertical Transport	Elevators							
	Hydraulic	100%			LIFE		**	
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : 1st To 2nd Floor</i>					
			<i>Explanation : One Unit</i>					
Fire Suppression	Sprinkler							
	Generic	100%			2054		**	\$5,700
Fire Pump	Generic	100%			2043		**	\$3,800

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WHITEHALL FERRY TERMINAL
Address : SOUTH AND WHITEHALL STS @ PETER MINUIT PLAZA
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0106.000 / 2418 **Yr Built/Renovated** : 2005 /
Area Sq Ft : 206,998 **Project Type** : FERRIES
Date of Survey : 15-Feb-2023 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2,3,Mez,Ph
Block : 2 **Lot** : 1 **BIN** : 1085792

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$546,800	\$717,900
Interior Architecture	\$792,100	\$496,800
Electrical		\$1,404,300
Mechanical		\$14,170,500
Total	\$1,338,900	\$16,789,400
Importance Code A	\$546,800	\$717,900
Importance Code B	\$792,100	\$16,006,500
Importance Code C		\$65,000
Total	\$1,338,900	\$16,789,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$1,700			\$5,800
Interior Architecture	\$33,100	\$12,400		\$3,900
Electrical	\$47,400	\$61,900	\$37,600	\$40,200
Mechanical	\$119,500	\$73,600	\$118,200	\$96,800
Site Pavements	\$24,400			
Elevators/Escalators	\$76,800	\$76,800	\$76,800	\$76,800
Total	\$302,900	\$224,800	\$232,600	\$223,500
Importance Code A	\$11,900	\$10,200	\$10,200	\$16,500
Importance Code B	\$266,500	\$214,500	\$222,400	\$207,000
Importance Code C	\$24,400			
Total	\$302,900	\$224,800	\$232,600	\$223,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL
Asset # : 2418

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Concrete Masonry Unit	10%			LIFE	**	5	\$17,700	
Metal, Corrugated	10%			2054	**	1		
Metal/Glass Curt Wall	54%			LIFE	**	5	\$286,000	
Metal Panel	20%	Now	\$73,200	2054	**	5	\$105,900	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Terminal Roof At Overhang East Facade</i>								
<i>Punct/Tear/Impact Damage, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Above Trash Loading Area</i>								
Metal Coiling Doors	1%	Now	\$117,900	2047	**	5	\$4,400	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Trash Loading Dock</i>								
<i>Hardware Missing, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Trash Loading Dock</i>								
Pre-Cast Concrete	5%			LIFE	**	5	\$45,900	
Windows								
Metal Louvers	100%	Now	\$1,700	2043	**			
<i>Bent/Warped Elements, Extent : Severe, Area Affected : 1%</i>								
<i>Location : 3rd Floor Mechanical Room</i>								
Parapets								
Cast in Place Concrete	5%			LIFE	**	5	\$6,200	
Concrete Masonry Unit	20%			LIFE	**	5	\$2,700	
Metal Panel	25%			2054	**	5	\$11,600	
No Component	50%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Edge Of Terminal Roof At 3rd Floor</i>								
<i>Explanation : Metal Rail As Guard Railing For Site Information</i>								
Roof								
Modified Bitumen	80%	2-4	\$266,000	2039	**			
<i>Blisters, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Terminal Roof</i>								
<i>Patching Evident, Extent : Light, Area Affected : 5%</i>								
<i>Location : Terminal Roof</i>								
Plaza Roof: Stone Panels	20%			2054	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Upper Roof Level</i>								
<i>Explanation : On Pedestal System</i>								
Soffits								
Metal Panel	100%	Now	\$89,700	2054	**	5	\$325,900	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Bus Waiting Canopy And 1st Floor Vehicle Underpass</i>								
<i>Staining/Discoloring, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								

Interior

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL
Asset # : 2418

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Interior								
Floors								
Carpet	5%			2030	\$267,600	3	\$23,200	
Cast in Place Concrete	25%			LIFE	**	5	\$169,400	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : First Floor Utility Area</i>								
<i>Paint Peeling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : 3rd Floor</i>								
Ceramic Tile	15%	4+	\$51,200	2043	**	5	\$23,200	
<i>Worn/Eroded, Extent : Light, Area Affected : 10%</i>								
<i>Location : Toilets On 2nd Floor</i>								
Granite Panels	8%			LIFE	**	5	\$18,600	
Quarry Tile	2%			2047	**	5	\$9,300	
Terrazzo	35%	Now	\$495,100	LIFE	**	5	\$84,700	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : 2nd Floor Waiting Room</i>								
Vinyl Tile	10%	4+	\$16,700	2039	**	3	\$11,600	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Mezzanine Level Storage Area</i>								
<i>Punct/Tear/Impact Damage, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Elevator Lobby 2nd And 3rd Floors</i>								
<i>Worn/Eroded, Extent : Light, Area Affected : 15%</i>								
<i>Location : Elevator Lobbies</i>								
Interior Walls								
Concrete Masonry Unit	60%			LIFE	**	5	\$65,000	
Glass: Special Gauge	10%			LIFE	**	1		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Main Waiting Room</i>								
<i>Explanation : Double Glazed Wall And Sliding Boarding Doors</i>								
Gypsum Board	20%			LIFE	**	5	\$32,500	
Metal Panel	10%			LIFE	**			
Ceilings								
AcousTileSusp.Lay-In	15%			2051	**	5	\$32,800	
Exposed Struc: Steel	15%	4+	\$153,900	LIFE	**			
<i>Paint Peeling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Street Level Slip 3</i>								
Gypsum Board	5%			LIFE	**	5	\$13,700	
Metal Panel	65%	Now	\$91,900	LIFE	**	5	\$177,600	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Ferry Boarding Area</i>								
<i>Corrosion/Rusting, Extent : Light, Area Affected : 10%</i>								
<i>Location : Entrance And Main Waiting Area 2nd Floor</i>								
Site Enclosure								
Fence/Gates								
Chain Link	100%			2054	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL
Asset # : 2418

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Site Enclosure								
Free Standing Walls								
Cast in Place Concrete	100%			2069	**			
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Walkway Columns Metal, Concrete At Loading Area</i>								
<i>Explanation : Some Are Metal Panel Columns</i>								
Site Pavements								
Public Sidewalk								
Pavers/Stone	100%			2043	**			
On-Site Walkways								
Masonry: Granite	75%			LIFE	**			
Pavers/Stone	25%	0-2	\$24,400	2043	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Main Entrance</i>								
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Ferry Waiting And Boarding Area</i>								
Parking/Driveway								
Asphalt	100%			2043	**			
Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	98%			2044	**	5	\$900	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Electrical Room Ground Floor</i>								
<i>Explanation : One 6,000 Amperes For The Entire Building, Two 2,000 Amperes For Automatic Transfer Switch1 And 2, One 2,000 Amperes And 1,200 Amperes For The Concession Area</i>								
Fused Disc Sw	2%			2044	**	5		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Solar Panel Room</i>								
<i>Explanation : One 200 Amperes Main Disconnect Switch For Solar Panel</i>								
Transformers								
Dry Type	100%			2039	**	5	\$800	
Switchgear / Switchboard								
Fused Disc Sw	100%			2044	**	5	\$900	
Raceway								
Conduit	100%			2044	**	1		
Panelboards								
Fused Disc Sw	10%			2042	**	5	\$500	
Fused Disc Sw	2%	2-4	\$3,500	2059	**	5		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Ground Floor</i>								
<i>Explanation : Enclosure Corroded</i>								
Molded Case Bkrs	88%			2042	**	5	\$4,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL
Asset # : 2418

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Wiring								
Thermoplastic	100%			2044	**	1		
Motor Controllers								
Locally Mounted	20%			2047	**	5	\$300	
Motor Control Center	78%			2039	**	5	\$4,400	
Variable Frequency Drive	2%			2051	**			
Ground								
Grounding Devices								
Generic	100%	2-4	\$10,200	LIFE	**	5	\$3,000	
<i>Corroded, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Water Main Ground Floor</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Pump Room</i>								
<i>Explanation : Main Water Pipe</i>								
Stand-by Power								
Transfer Switches								
Automatic	100%			2039	**	1	\$63,700	
Generators								
Diesel	100%			2037	**	1	\$80,200	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Generator Room. Roof</i>								
<i>Explanation : One 1,000 Kilowatts</i>								
Batteries								
Nickel Cadmium	100%			2027	\$2,400	5	\$46,100	
Fuel Storage								
Day Tank								
	20%			2042	**	5		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Generator Room</i>								
<i>Explanation : One 275 Gallons</i>								
Main Tank								
	80%			2062	**	5		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Ground Floor</i>								
<i>Explanation : One 2,600 Gallons</i>								
Lighting								
Interior Lighting								
Fluorescent								
	2%			2034	\$45,100	10	\$3,800	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Elevator Lobby 2nd And 3rd Floor</i>								
Fluorescent								
	5%			2034	\$112,900	10	\$9,500	
<i>Compact Fluorescent Light, Extent : Light, Area Affected : 100%</i>								
<i>Location : Passenger Waiting Area And Some In Concession</i>								
HID								
	2%			2034	\$40,500	10	\$100	
LED								
	91%			2042	**			
Egress Lighting								
Emergency, Service								
	50%			2034	\$62,300	1		
Exit, Service								
	50%			2034	\$34,200	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL
Asset # : 2418

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Exterior Lighting								
HID	30%			2034	\$283,000	10	\$200	
No Component	70%							
Lightning Protection								
Arresters/Cabling								
Generic	100%			2049	**	5	\$6,100	
Alarm								
Security System								
Generic	100%			2034	\$379,500	1	\$77,300	
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Inside And Outside</i>						
		<i>Explanation : CCTV Surveillance Camera</i>						
Fire/Smoke Detection								
Generic, Digital	100%			2034	\$521,500	1-3	\$127,600	
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Throughout The Building</i>						
		<i>Explanation : Strobe Lights, Horns, Alarm Bell, Smoke Detectors, Pull Boxes And Fire Alarm Panel</i>						

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2054	**	1		
Conversion Equipment								
Hot Water Boiler	50%			2039	**	1	\$51,200	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 3rd Floor Mechanical Equipment Room</i>						
		<i>Explanation : 1 Unit</i>						
Hot Water Boiler	50%			2051	**	1	\$51,200	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 3rd Floor Mechanical Equipment Room</i>						
		<i>Explanation : 1 Unit</i>						
Distribution								
Hot Wtr Piping/Pump	100%			2042	**	4	\$15,300	
Terminal Devices								
Air Handler	75%			2034	\$2,853,400	1	\$96,000	
Convactor/Radiator	15%	Now	\$5,000	2039	**	1	\$9,000	
		<i>Not in Service, Extent : Moderate, Area Affected : 30%</i>						
		<i>Location : Various Spots Of 1st Floor Main Entrance.</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Part Of 3rd Floor And 1st Floor Main Entrance.</i>						
		<i>Explanation : Floor Heating Tubes</i>						
Fan Coil Unit/Heat	10%			2034	\$501,200	1	\$6,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL
Asset # : 2418

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Heating								
Controls								
	Digital	100%			2032	\$5,806,300		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Building Management System</i>								
Air Conditioning								
Energy Source								
	Natural Gas	100%			2054	**	1	
Conversion Equipment								
	Absorption Chiller/Direct Fire	80%			2039	**	1	\$179,200
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 3rd Floor Mechanical Equipment Room</i>								
<i>Explanation : 2 Units</i>								
	Split Unit	20%			2039	**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Various Locations</i>								
<i>Explanation : 16 Units</i>								
Distribution								
	CW & CHW Wtr Pipe/Pump	80%			2054	**	4	\$12,200
	No Component	20%						
Terminal Devices								
	Air Handler/Cool/Ht	80%			2034	\$3,138,200	1	\$102,400
	Fan Coil - 2 Pipe	20%			2039	**	1	\$13,400
Heat Rejection								
	Air Cooled Condenser Unit	20%			2039	**	2	\$28,800
	Water Cooling Tower	80%			2032	\$816,900	2	\$166,700
Ventilation								
Distribution								
	Ductwork/Diffusers	100%			LIFE	**	2-5	\$115,400
Exhaust Fans								
	Interior	90%			2034	\$807,000	2	\$5,700
	Roof	10%			2039	**	2	\$600
Energy Recovery Ventilator								
	Generic	100%			2032			
Plumbing								
H/C Water Piping								
	Brass/Copper	100%			2054	**	1	
Water Heater With Tanks								
	Gas Fired	100%			2032	\$33,400	2	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : 3rd Floor Mechanical Equipment Room</i>								
<i>Explanation : One 113 Gallon Unit. One Abandoned 250 Gallon Unit Remaining In Place.</i>								
Sanitary Piping								
	Cast Iron	100%			LIFE	**	1	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL
Asset # : 2418

Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Plumbing								
Storm Drain Piping Cast Iron	100%			LIFE	**	1		
Sewage Ejector(s) Electric	100%			2034	\$105,900	4	\$12,400	
Backflow Preventer Generic	100%			2034	\$90,300	1	\$12,700	
Fixtures Generic	100%							
Vertical Transport								
Elevators Hydraulic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Two Units From 1st Floor To Roof, One Unit From 1st To 3rd Floor, One Unit From 1st To 2nd Floor</i>						
		<i>Explanation : 4 Units</i>						
Escalators Over 20' Rise	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 1st Floor Main Entrance To 2nd Floor</i>						
		<i>Explanation : 5 Units</i>						
Fire Suppression								
Standpipe Generic	100%			2054	**	1-5	\$104,400	
Sprinkler Generic	100%			2044	**	1-2	\$58,000	
Fire Pump Generic	100%			2037	**	1	\$38,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ARTERIAL AND FLEET SERVICES GAS HOUSE
Address : 32-11 HARPER STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0092.020 / 564 **Yr Built/Renovated** : 1937 / 1997
Area Sq Ft : 1,967 **Project Type** : HIGHWAYS
Date of Survey : 16-Feb-2024 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1
Block : 1790 **Lot** : 1 **BIN** : 4444576

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$54,100	
Total	\$54,100	
Importance Code A	\$54,100	
Total	\$54,100	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$66,400		\$400	
Interior Architecture	\$28,600			\$100
Electrical	\$2,000	\$100	\$100	\$200
Mechanical	\$1,900	\$900	\$900	\$1,900
Total	\$98,800	\$1,000	\$1,400	\$2,100
Importance Code A	\$66,400	\$100	\$500	\$100
Importance Code B	\$29,600	\$900	\$900	\$2,000
Importance Code C	\$2,800			
Total	\$98,800	\$1,000	\$1,400	\$2,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES GAS HOUSE**

Asset # : 564

Architecture	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Glass Block	10%			LIFE	**	5	\$900	
Masonry: Brick	85%	Now	\$49,000	LIFE	**	5	\$6,100	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Corners And Openings</i>								
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout Lower Facade</i>								
<i>Recent Repair Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Cracks And Brick At Lintels</i>								
<i>Spalling, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
Masonry: Granite	3%	Now	\$8,300	LIFE	**	5	\$200	1
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Building Base</i>								
Pre-Cast Concrete	2%	Now	\$2,000	LIFE	**	5	\$500	
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : At Window Sills</i>								
Windows								
Aluminum	100%			2043	**	5	\$800	
Parapets								
Masonry: Brick	95%	Now	\$54,100	LIFE	**	5	\$2,200	1
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Exterior Parapet</i>								
<i>Recent Repair Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Parapet</i>								
<i>Staining/Discoloring, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Norht Facade Interior Parapet</i>								
Pre-Cast Concrete	5%			LIFE	**	5	\$1,400	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Coping Joints</i>								
Roof								
Modified Bitumen	100%	0-2	\$5,900	2040	**			
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Corners Of Building</i>								
Interior								
Floors								
Cast in Place Concrete	65%			LIFE	**	5	\$8,400	
Vinyl Tile	35%			2035		3	\$500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES GAS HOUSE

Asset # : 564

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Interior

Interior Walls

Concrete Masonry Unit 25% Now \$200 LIFE * * 5

Cracking/Crumbling, Extent : Moderate, Area Affected : 10%
Location : Cracks At Brick And Ceiling Joints In Locker Area

Masonry: Brick 75% Now \$2,600 LIFE * *

Cracking/Crumbling, Extent : Severe, Area Affected : 10%
Location : At Lintels
Diagonal Cracks, Extent : Severe, Area Affected : 5%
Location : Corners
Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 25%
Location : Base And Between Beams
Paint Peeling, Extent : Moderate, Area Affected : 15%
Location : Base And Top Perimeter Walls
Water Penetration, Extent : Severe, Area Affected : 25%
Location : Throughout

Ceilings

Exposed Struc: Concrete 100% Now \$21,500 LIFE * * 5 \$500

Diagonal Cracks, Extent : Severe, Area Affected : 10%
Location : Corners Of Ceiling And Perimeter Wall Joint And Between Beams
Water Penetration, Extent : Moderate, Area Affected : 20%
Location : Throughout

Site Pavements

On-Site Walkways

Asphalt 100% 2038 * *

Parking/Driveway

Asphalt 75% 2038 * *

Cast in Place Concrete 25% 2040 * *

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Raceway

Conduit 100% 2035 \$4,300 1

Panelboards

Fused Disc Sw 5% 2034 \$500 5

Molded Case Bkrs 45% 2034 \$4,400 5

Molded Case Bkrs 50% 2043 * * 5

Wiring

Braided Cloth 70% 2034 \$6,200 1

Other Observation, Extent : N/A, Area Affected : 100%
Location : Throughout The Building
Explanation : Insulation Aged

Thermoplastic 30% 2045 * * 1

Motor Controllers

Locally Mounted 100% 2033 \$11,200 5

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

**DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES GAS HOUSE**

Asset # : 564

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Interior Lighting Fluorescent	100%			2030	\$13,600	10	\$1,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : T-12 Lamps</i>								
Exterior Lighting LED	20%			2043	**			
No Component	80%							
Alarm								
Fire/Smoke Detection Generic, Analog	100%			2030	\$5,000	1-3	\$1,200	
Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source Natural Gas	100%			2045	**	1		
Conversion Equipment Furnace	100%			2035	\$6,000	1	\$1,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Various Locations</i>								
<i>Explanation : 2 Direct Fired Unit Heaters</i>								
Air Conditioning								
Energy Source Electricity	100%			2043	**	1		
Conversion Equipment Window/Wall Unit	30%			2030	\$2,200	1		
No Component	70%							
Plumbing								
H/C Water Piping Brass/Copper	100%			2045	**	1		
Water Heater With Tanks Electric	100%			2033	\$23,100	4		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : First Floor</i>								
<i>Explanation : 10 Gallons</i>								
Sanitary Piping Cast Iron	100%			LIFE	**	1		
Storm Drain Piping Cast Iron	100%			LIFE	**	1		
Fire Suppression								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES GAS HOUSE**

Asset # : 564

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Fire Suppression Chemical System Dry	5%			2030	\$2,400	1-3	\$11,800	
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Outside</i>						
		<i>Explanation : Fuel Station Only</i>						
No Component	95%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ARTERIAL AND FLEET SERVICES GUARD HOUSE
Address : 32-11 HARPER STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0092.150 / 174 **Yr Built/Renovated** : 1997 /
Area Sq Ft : 96 **Project Type** : HIGHWAYS
Date of Survey : 16-Feb-2024 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1
Block : 1790 **Lot** : 1 **BIN** : 4444576

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$93,300	
Total	\$93,300	
Importance Code A	\$93,300	
Total	\$93,300	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$400			
Interior Architecture	\$3,100			
Electrical	\$100			
Mechanical				
Site Pavements	\$400			\$200
Total	\$4,000			\$200
Importance Code A	\$400			
Importance Code B	\$3,100			
Importance Code C	\$400			\$200
Total	\$4,000			\$200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES GUARD HOUSE
Asset # : 174

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Window Wall	100%	Now	\$93,300	2065	**	5	\$5,900	
<i>Glazing Broken/Cracked, Extent : Severe, Area Affected : 5%</i>								
<i>Location : East Facade</i>								
<i>Glazing Clouded, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : South And West Facades</i>								
<i>On Extended Life, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Roof								
Roll Roofing	100%	0-2	\$400	2031	\$8,600	5	\$1,100	
<i>Seams Open/Split, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Roof</i>								
Soffits								
Metal Panel	100%			2035		5-10		
Interior								
Floors								
Ceramic Tile	100%	Now	\$2,000	2038	**	5	\$400	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Main Area</i>								
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Main Area</i>								
Ceilings								
Fiber Board	100%	2-4	\$1,100	2035	\$10,500			
<i>Worn/Eroded, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Site Enclosure								
Fence/Gates								
Chain Link	100%			2045	**			
Site Pavements								
On-Site Walkways								
Cast in Place Concrete	75%	0-2	\$100	2040	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Perimeter At Corner Guard Joint</i>								
Metal	25%	0-2	\$300	2045	**	1-3	\$500	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Walkway Perimeter</i>								
<i>Explanation : Rusted Corner Guards</i>								
Parking/Driveway								
Asphalt	100%			2038	**			
<i>Potholes, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : At Driveway Checkpoint, Quantity Assigned To Main Building, Asset 2412</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES GUARD HOUSE
Asset # : 174

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Under 600 Volts								
Raceway								
Conduit	100%			2035	\$4,300	1		
Panelboards								
Molded Case Bkrs	100%			2034	\$9,700	5		
Wiring								
Thermoplastic	100%			2035	\$8,800	1		
Lighting								
Interior Lighting								
Fluorescent	100%			2030	\$700	10	\$100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : T-12 Lamps</i>								
Alarm								
Security System								
Generic	100%			2035	\$200	1		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Outside</i>								
<i>Explanation : CCTV Surveillance Cameras</i>								

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Heating								
Energy Source								
Electricity	100%			2045	**	1		
Conversion Equipment								
Radiant Heater	100%			2035	\$2,400	2		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Office</i>								
<i>Explanation : 2 Units</i>								
Air Conditioning								
Energy Source								
Electricity	100%			2043	**	1		
Conversion Equipment								
Window/Wall Unit	100%			2033	\$400	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ARTERIAL AND FLEET SERVICES MAIN GARAGE
Address : 32-11 HARPER STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0092.000 / 2412 **Yr Built/Renovated** : 1937 / 1997
Area Sq Ft : 64,562 **Project Type** : HIGHWAYS
Date of Survey : 16-Feb-2024 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1
Block : 1790 **Lot** : 1 **BIN** : 4444576

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$2,356,900	\$53,500
Interior Architecture	\$658,400	
Electrical		\$301,900
Mechanical	\$117,700	\$1,453,200
Site Pavements	\$749,400	
Total	\$3,882,500	\$1,808,600
Importance Code A	\$2,474,600	\$256,800
Importance Code B	\$377,100	\$1,551,800
Importance Code C	\$1,030,800	
Total	\$3,882,500	\$1,808,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$74,000		\$17,600	
Interior Architecture	\$154,400		\$1,900	
Electrical	\$3,400	\$2,400	\$3,000	\$2,900
Mechanical	\$4,100	\$5,100	\$4,800	\$6,300
Site Pavements	\$5,400			
Total	\$241,200	\$7,500	\$27,300	\$9,200
Importance Code A	\$74,900	\$3,500	\$20,500	\$3,500
Importance Code B	\$111,600	\$4,000	\$6,800	\$5,700
Importance Code C	\$54,700			
Total	\$241,200	\$7,500	\$27,300	\$9,200



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES MAIN GARAGE

Asset # : 2412

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Glass Block	10%			LIFE	**	5	\$8,600	
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Garage Portion</i>								
<i>Explanation : Got Burned Last September 2023</i>								
Masonry: Brick	70%	Now	\$1,547,300	LIFE	**	5	\$48,100	1
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Various Locations</i>								
<i>Diagonal Cracks, Extent : Severe, Area Affected : 15%</i>								
<i>Location : All Facades</i>								
<i>Horizontal Cracks, Extent : Severe, Area Affected : 15%</i>								
<i>Location : North Facade, South Facade</i>								
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 10%</i>								
<i>Location : South Facade</i>								
<i>Rusting Masonry Supt, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Above Overhead Doors</i>								
<i>Vertical Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : North Facade</i>								
Masonry: Granite	3%	Now	\$47,600	LIFE	**	5	\$1,500	1
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Building Base</i>								
Metal, Corrugated	5%	0-2	\$3,300	2045	**	1		
<i>Corrosion/Rusting, Extent : Severe, Area Affected : 10%</i>								
<i>Location : At Window Openings In Blacksmith Shop</i>								
Metal Coiling Doors	10%			2040	**	5	\$21,500	
Pre-Cast Concrete	2%	Now	\$9,700	LIFE	**	5	\$4,500	
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Window Sills</i>								
Windows								
Aluminum	90%			2043	**	5	\$14,800	
Metal Louvers	10%			2038	**	10	\$10,300	
Parapets								
Masonry: Brick	95%	Now	\$678,000	LIFE	**	5	\$27,400	
<i>Diagonal Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : East Facade</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : North Facade, South Facade</i>								
<i>Spalling, Extent : Severe, Area Affected : 25%</i>								
<i>Location : All Facades</i>								
Pre-Cast Concrete	5%			LIFE	**	5	\$18,200	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES MAIN GARAGE

Asset # : 2412

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Roof								
Asphalt Shingle	70%	Now	\$131,600	2038	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : At Ridge</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Garage Area</i>								
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Garage Area</i>								
<i>Explanation : Holes On Roof Due To Burning Last September 2023.</i>								
Modified Bitumen	30%			2040	**	10	\$53,500	
Interior								
Floors								
Asphalt Macadam	90%	0-2	\$41,400	2048	**	5	\$21,200	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Ceramic Tile	2%			2038	**	5	\$1,900	
Vinyl Tile	8%			2040	**	3	\$2,800	
Interior Walls								
Cast in Place Concrete	5%	Now	\$17,300	LIFE	**			
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Columns</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Columns</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Garage</i>								
<i>Explanation : Various Expressway Columns Run Through The Garage Area</i>								
Concrete Masonry Unit	30%	Now	\$32,100	LIFE	**	5	\$2,800	
<i>Diagonal Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Walls Dividing Garage Areas</i>								
<i>Horizontal Cracks, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Walls Dividing Garage Areas</i>								
Masonry: Brick	65%	Now	\$281,400	LIFE	**			
<i>Diagonal Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Rusting Masonry Supt, Extent : Severe, Area Affected : 40%</i>								
<i>Location : Lintels Throughout</i>								
<i>Vertical Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Throughout Perimeter Walls And At Interior Walls Of Blacksmith Shop</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES MAIN GARAGE
Asset # : 2412

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Ceilings								
AcousTileSusp.Lay-In	5%	Now	\$1,500	2048	**	5	\$2,400	
<i>Water Penetration, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Offices Throughout</i>								
Exposed Struc: Steel	20%			LIFE	**	10	\$37,700	
Exposed Struc: Wood	60%	Now	\$377,100	LIFE	**			
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Garage Area</i>								
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Garage Area</i>								
<i>Explanation : Burned Wood Structural Ceiling Members</i>								
Exposed Struc: Wood	10%			LIFE	**	10	\$14,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Shop</i>								
<i>Explanation : Painted Exposed Wood Members</i>								
Gypsum Board	5%			LIFE	**	5-10	\$16,200	
Site Enclosure								
Fence/Gates								
Chain Link	100%			2045	**			
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2040	**			
On-Site Walkways								
Asphalt	75%	Now	\$3,500	2038	**			
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Perimeter Of Building</i>								
Cast in Place Concrete	25%	0-2	\$1,900	2040	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Entries And West Facade Area</i>								
Parking/Driveway								
Asphalt	100%	Now	\$749,400	2038	**			
<i>Ponding, Extent : Severe, Area Affected : 20%</i>								
<i>Location : North Facade Towards Center Of Building</i>								

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2045	**	5	\$300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : Main Service Disconnect Switch Rated At 2,000 Amperes.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES MAIN GARAGE**

Asset # : 2412

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Transformers								
Dry Type	100%			2040	**	5	\$200	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Electrical Room</i>						
		<i>Explanation : 150 Kilovolt Amperes, 480 Volts Primary, 277 Volts Secondary</i>						
Switchgear / Switchboard								
Fused Disc Sw	100%			2045	**	5	\$300	
Raceway								
Conduit	20%			2045	**	1		
Conduit	80%			2035	\$8,600	1		
Panelboards								
Fused Disc Sw	5%			2034	\$1,900	5	\$100	
Molded Case Bkrs	45%			2043	**	5	\$800	
Molded Case Bkrs	50%			2034	\$19,500	5	\$900	
Wiring								
Braided Cloth	30%			2034	\$6,600	1		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout The Building</i>						
		<i>Explanation : Insulation Aged</i>						
Thermoplastic	45%			2045	**	1		
Thermoplastic	25%			2035	\$5,500	1		
Motor Controllers								
Locally Mounted	100%			2033	\$78,500	5	\$400	
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$1,900	
Lighting								
Interior Lighting								
Fluorescent	50%			2035	\$223,300	10	\$29,600	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Offices</i>						
		<i>Explanation : T-8 Lamps</i>						
LED	50%			2043	**			
Egress Lighting								
Emergency, Battery	50%			2040	**	10	\$7,600	
Exit, Service	50%			2040	**	1		
Exterior Lighting								
HID	20%			2040	**	10		
No Component	80%							
Alarm								
Security System								
Generic	100%			2043	**	1	\$24,100	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Outside Perimeter</i>						
		<i>Explanation : CCTV Surveillance Cameras</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES MAIN GARAGE

Asset # : 2412

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Electricity	10%			2045	**	1		
Natural Gas	90%			2045	**	1		
Conversion Equipment								
Furnace	10%			2040	**	1	\$3,200	
Furnace	60%	0-2	\$117,700	2045	**	1	\$17,200	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 40 Direct Fired Unit Heaters Are Not In Service, Either Broken Or Damaged.</i>								
Furnace	20%			2030	\$39,200	1	\$6,400	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Various Locations</i>								
<i>Explanation : Direct Fired Unit Heaters</i>								
Radiant Heater	10%			2035	\$164,100	2	\$3,000	
Air Conditioning								
Energy Source								
Electricity	100%			2043	**	1		
Conversion Equipment								
Split Unit	10%			2035	\$149,700			
Window/Wall Unit	10%			2030	\$23,900	1		
No Component	80%							
Ventilation								
Exhaust Fans								
Wall Unit	80%			2030	\$21,800	2	\$1,600	
No Component	20%							
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2035	\$809,800	1		
Water Heater With Tanks								
Electric	100%			2033	\$23,100	4		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : First Floor</i>								
<i>Explanation : 40 Gallons</i>								
Sanitary Piping								
Cast Iron	100%			LIFE	**	1		
Storm Drain Piping								
Cast Iron	100%			LIFE	**	1		
Backflow Preventer								
Generic	100%			2043	**	1	\$4,000	
Fixtures								
Generic	100%							
Fire Suppression								
Standpipe								
Generic	100%			2035	\$290,300	1-5	\$33,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ARTERIAL AND FLEET SERVICES OFFICE AND STOREHOUSE
Address : 32-11 HARPER STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0092.010 / 2406 **Yr Built/Renovated** : 1937 / 2005
Area Sq Ft : 11,436 **Project Type** : HIGHWAYS
Date of Survey : 16-Feb-2024 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2
Block : 1790 **Lot** : 1 **BIN** : 4444576

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$993,600	\$361,800
Interior Architecture	\$251,600	
Electrical		\$317,600
Total	\$1,245,100	\$679,400
Importance Code A	\$993,600	\$361,800
Importance Code B	\$162,500	\$317,600
Importance Code C	\$89,100	
Total	\$1,245,100	\$679,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$54,100		\$900	
Interior Architecture	\$67,600		\$800	\$800
Electrical	\$1,500	\$400	\$500	\$500
Mechanical	\$8,000	\$800	\$900	\$700
Site Pavements	\$27,000			
Total	\$158,200	\$1,200	\$3,100	\$2,000
Importance Code A	\$54,600	\$600	\$1,400	\$600
Importance Code B	\$72,300	\$600	\$1,600	\$1,500
Importance Code C	\$31,200			
Total	\$158,200	\$1,200	\$3,100	\$2,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES OFFICE AND STOREHOUSE

Asset # : 2406

Architecture	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Glass Block	10%	Now	\$4,300	LIFE	**	5	\$1,300	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Office 1, Office 8 At East And West Facades</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Entire Building Office And Storehouse</i>								
<i>Explanation : Scheduled To Be Demolished Within A Year.</i>								
Masonry: Brick	65%	Now	\$451,000	LIFE	**	5	\$14,000	1
<i>Diagonal Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Various Locations</i>								
<i>Horizontal Cracks, Extent : Severe, Area Affected : 25%</i>								
<i>Location : West Facade, East Facade</i>								
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 50%</i>								
<i>Location : West Facade, East Facade</i>								
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 20%</i>								
<i>Location : North Facade</i>								
<i>Punct/Tear/Impact Damage, Extent : Severe, Area Affected : 10%</i>								
<i>Location : West Facade</i>								
<i>Rusting Masonry Supt, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Vertical Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Various Locations</i>								
Masonry: Granite	5%	Now	\$24,900	LIFE	**	5	\$800	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Bases Of Piers Along South And West Facade</i>								
Metal Coiling Doors	5%			2040	**	5	\$3,400	
Pre-Cast Concrete	5%	Now	\$3,800	LIFE	**	5	\$3,500	
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 50%</i>								
<i>Location : North Facade, Window Sills</i>								
Stucco Cement	10%	0-2	\$6,000	2040	**	5	\$2,700	
<i>Horizontal Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : East Facade At Second Floor</i>								
Windows								
Aluminum	95%	Now	\$248,900	2060	**	5	\$2,700	
<i>Air Infiltration, Extent : Severe, Area Affected : 50%</i>								
<i>Location : All Facades</i>								
<i>Unit Inoperable, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Metal Clad	5%			2043	**	5	\$1,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES OFFICE AND STOREHOUSE

Asset # : 2406

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Parapets								
Masonry: Brick	95%	Now	\$15,100	LIFE	**	5	\$2,400	1
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout Exterior Facade</i>								
Metal Panel	5%			2045	**	5	\$500	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Metal Coping</i>								
Roof								
Modified Bitumen	95%			2035	\$361,800	10	\$33,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : All Roof</i>								
<i>Explanation : Snow Covered Surfaces</i>								
Skylight, Metal/Glass	5%	Now	\$293,700	2065	**			
<i>Corrosion/Rusting, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Over Mens Locker Room</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Over Mens And Womens Locker Room, Storage Area Skylights</i>								
Interior								
Floors								
Carpet	5%			2031	\$18,600	3	\$2,100	
Cast in Place Concrete	40%	Now	\$14,300	LIFE	**	5	\$18,800	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Storage Areas</i>								
<i>Loose/Delam Surface, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Storage Areas And Mechanical Areas</i>								
<i>Paint Peeling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Storage And Mechanical Areas</i>								
Mosaic Tile	5%	Now	\$4,900	2040	**	5	\$1,300	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Bathrooms</i>								
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Bathrooms</i>								
Sheet Vinyl/Rubber	8%	Now	\$54,900	2045	**	5	\$1,300	
<i>Worn/Eroded, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Locker Rooms</i>								
Vinyl Tile	30%			2040	**	3	\$2,400	
Vinyl Tile	5%	Now	\$5,800	2045	**	3	\$400	
<i>Water Penetration, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Mechanical Areas</i>								
Vinyl Tile 9" X 9"	5%	Now	\$4,200	2040	**	3	\$400	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Office 1</i>								
<i>Worn/Eroded, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Office 1</i>								
Wood	2%			2050	**	5	\$800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES OFFICE AND STOREHOUSE

Asset # : 2406

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Interior Walls								
Gypsum Board	15%	Now	\$1,100	LIFE	**	5	\$1,000	
<i>Water Penetration, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Offices At Perimeter Walls</i>								
Masonry: Brick	45%	Now	\$89,100	LIFE	**			
<i>Diagonal Cracks, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Storage Space</i>								
<i>Horizontal Cracks, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Storage Area At Lintels</i>								
<i>Vertical Cracks, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Storage Space</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Perimeter Walls</i>								
Plaster	20%	Now	\$2,500	LIFE	**	5	\$600	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Throughout Perimeter Walls And Locker Rooms</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout Perimeter Walls</i>								
Plywood/Hardboard	10%			LIFE	**	10	\$100	
SGFT/Glazed Masonry	10%			LIFE	**	10	\$500	
Ceilings								
AcousTileSusp.Lay-In	30%	4+	\$2,100	2040	**	5	\$3,200	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Mechanical Areas And Lounge On First Floor</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Office 8, 13 And Lounge</i>								
Exposed Struc: Concrete	20%			LIFE	**	5-10	\$5,400	
Exposed Struc: Wood	25%	Now	\$107,500	LIFE	**			
<i>Split/Cracked, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Storage Area</i>								
<i>Staining/Discoloring, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Over Storage Area</i>								
Gypsum Board	10%	Now	\$22,000	LIFE	**	5	\$2,700	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Storage Area At First Floor And Second Floor Offices</i>								
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Storage Area At First Floor</i>								
Plaster	15%	Now	\$4,800	LIFE	**	5	\$2,000	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Mens And Womens Locker Room</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Mens And Womens Locker Room</i>								

Site Pavements

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES OFFICE AND STOREHOUSE

Asset # : 2406

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Site Pavements

On-Site Walkways

Cast in Place Concrete	100%	0-2	\$600	2040		**		
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : South Facade Walkway</i>								

Parking/Driveway

Asphalt	100%	Now	\$26,400	2038		**		
<i>Ponding, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Northwest Corner Of Parking Area</i>								

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Switchgear / Switchboard

Molded Case Bkrs	100%			2035	\$127,000	5	\$300	
------------------	------	--	--	------	-----------	---	-------	--

Raceway

Conduit	60%			2035	\$19,000	1		
Conduit	40%			2055	**	1		

Panelboards

Fused Disc Sw	5%			2034	\$1,900	5		
Molded Case Bkrs	55%			2034	\$21,400	5	\$200	
Molded Case Bkrs	40%			2051	**	5	\$100	

Wiring

Braided Cloth	20%			2034	\$10,500	1		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : Insulation Aged</i>								
Thermoplastic	40%			2035	\$21,000	1		
Thermoplastic	40%			2055	**	1		

Motor Controllers

Locally Mounted	100%			2033	\$45,800	5	\$100	
-----------------	------	--	--	------	----------	---	-------	--

Lighting

Interior Lighting

Fluorescent	10%			2030	\$19,100	10	\$1,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor</i>								
<i>Explanation : T-12 Lamps</i>								
Fluorescent	80%			2035	\$152,500	10	\$8,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : T-8 Lamps</i>								
Fluorescent	10%			2035	\$19,100	10	\$1,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Storage</i>								
<i>Explanation : T-5 Lamps</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES OFFICE AND STOREHOUSE

Asset # : 2406

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Lighting

Egress Lighting								
Emergency, Battery	50%			2035	\$9,400	10	\$1,400	
Exit, Service	50%			2035	\$2,400	1		
Exterior Lighting								
LED	20%			2043	**			
No Component	80%							

Alarm

Security System								
Generic	100%			2043	**	1	\$4,300	

Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Heating

Energy Source								
Natural Gas	100%			2045	**	1		
Conversion Equipment								
Furnace	80%			2035	\$27,800	1	\$4,500	
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Various Locations</i>					
			<i>Explanation : 15 Direct Fired Unit Heaters</i>					
Hot Water Boiler	20%			2055	**	1	\$1,100	
			<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : 2 Units. Boiler Room</i>					
Distribution								
Hot Wtr Piping/Pump	20%			2043	**	4	\$200	
No Component	80%							
Terminal Devices								
Convactor/Radiator	20%			2040	**	1	\$700	
No Component	80%							

Air Conditioning

Energy Source								
Electricity	100%			2043	**	1		
Conversion Equipment								
Split Unit	15%			2040	**			
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Various Locations</i>					
			<i>Explanation : 3 Units. R-410a</i>					
Window/Wall Unit	60%			2030	\$25,400	1		
No Component	25%							
Terminal Devices								
Fan Coil - 2 Pipe	15%			2040	**	1	\$600	
No Component	85%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES OFFICE AND STOREHOUSE

Asset # : 2406

Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Air Conditioning								
Heat Rejection								
Air Cooled Condenser Unit	15%			2040	**	2	\$1,200	
No Component	85%							
Ventilation								
Exhaust Fans								
Interior	10%			2035	\$5,000	2		
Roof	10%			2035	\$2,200	2		
Wall Unit	10%			2045	**	2		
Wall Unit	10%			2030	\$500	2		
No Component	60%							
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2045	**	1		
Water Heater With Tanks								
Electric	50%			2030	\$11,500	4		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : First Floor</i>								
<i>Explanation : 40 Gallons</i>								
Electric	50%			2035	\$11,500	4		
Sanitary Piping								
Cast Iron	100%	0-2	\$7,000	LIFE	**	1		
<i>Blockage /Clogged, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Outside Under Harper Street</i>								
Storm Drain Piping								
Cast Iron	100%			LIFE	**	1		
Fixtures								
Generic	100%							
<i>Obsolete Fixtures, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : First Floor Mens Bathroom</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ARTERIAL AND FLEET SERVICES STORAGE 1
Address : 32-11 HARPER STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0092.040 / 2407 **Yr Built/Renovated** : 1937 / 1997
Area Sq Ft : 1,758 **Project Type** : HIGHWAYS
Date of Survey : 16-Feb-2024 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1
Block : 1790 **Lot** : 1 **BIN** : 4444576

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$73,000	\$197,500
Interior Architecture		\$69,000
Total	\$73,000	\$266,500
Importance Code A	\$73,000	\$197,500
Importance Code B		\$69,000
Total	\$73,000	\$266,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$64,000		\$2,100	
Interior Architecture	\$18,300			\$100
Electrical	\$1,500			
Mechanical	\$100	\$100	\$1,400	\$100
Site Pavements	\$13,600			
Total	\$97,500	\$100	\$3,500	\$200
Importance Code A	\$64,100	\$100	\$2,200	\$100
Importance Code B	\$16,000		\$1,300	\$100
Importance Code C	\$17,400			
Total	\$97,500	\$100	\$3,500	\$200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES STORAGE 1
Asset # : 2407

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Glass Block	10%			LIFE	**	5	\$1,400	
Masonry: Brick	80%	Now	\$73,000	LIFE	**	5	\$9,100	1
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Corners</i>								
<i>Diagonal Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Horizontal Cracks, Extent : Severe, Area Affected : 20%</i>								
<i>Location : East Facade, West Facade</i>								
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 15%</i>								
<i>Location : North And East Facade</i>								
Metal Coiling Doors	5%	Now	\$5,900	2040	**	5	\$900	
<i>Deteriorated Finish, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Interior Side Of Doors</i>								
Pre-Cast Concrete	5%	Now	\$8,000	LIFE	**	5	\$1,800	1
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Window Sills And Building Base</i>								
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 50%</i>								
<i>Location : At Window Sills, Building Base</i>								
Windows								
Aluminum	100%			2043	**	5	\$4,100	
Parapets								
Masonry: Brick	95%	Now	\$38,000	LIFE	**	5	\$1,500	1
<i>Diagonal Cracks, Extent : Severe, Area Affected : 15%</i>								
<i>Location : At Corners</i>								
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Exterior Parapets</i>								
Metal Panel	5%			2045	**	5	\$300	
Roof								
Modified Bitumen	95%			2035		10	\$7,900	
Skylight, Metal/Glass	5%	Now	\$11,400	2035			\$113,600	
<i>Corrosion/Rusting, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Main Roof</i>								
<i>Glazing Broken/Cracked, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Main Roof</i>								
Interior								
Floors								
Cast in Place Concrete	80%			LIFE	**	5	\$15,400	
Vinyl Tile 9" X 9"	20%			2030		3	\$400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES STORAGE 1**

Asset # : 2407

Architecture		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Interior

Interior Walls

Masonry: Brick

100% Now \$3,800 LIFE **

Cracking/Crumbling, Extent : Moderate, Area Affected : 25%

Location : Throughout

Diagonal Cracks, Extent : Severe, Area Affected : 5%

Location : At Corners

Horizontal Cracks, Extent : Moderate, Area Affected : 10%

Location : Throughout

Paint Peeling, Extent : Moderate, Area Affected : 20%

Location : Throughout

Vertical Cracks, Extent : Severe, Area Affected : 10%

Location : Throughout

Water Penetration, Extent : Severe, Area Affected : 20%

Location : Throughout

Ceilings

Exposed Struc: Wood

100%

LIFE

**

10

\$6,600

Site Pavements

On-Site Walkways

Asphalt

100%

2038

**

Parking/Driveway

Asphalt

100% Now

\$13,600

2038

**

Cracking/Crumbling, Extent : Moderate, Area Affected : 25%

Location : At Base Of Building

Ponding, Extent : Moderate, Area Affected : 10%

Location : East Of Building

Electrical		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Under 600 Volts

Raceway

Conduit

100%

2035

\$4,300

1

Panelboards

Fused Disc Sw

20%

2034

\$1,900

5

Fused Toggle Switch

80%

2034

\$7,800

5

Wiring

Braided Cloth

50%

2034

\$4,400

1

Other Observation, Extent : N/A, Area Affected : 100%

Location : Throughout The Building

Explanation : Insulation Aged

Thermoplastic

50%

2035

\$4,400

1

Motor Controllers

Locally Mounted

100%

2033

\$11,200

5

Lighting

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
ARTERIAL AND FLEET SERVICES STORAGE 1**

Asset # : 2407

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Interior Lighting Fluorescent	95%			2030	\$11,600	10	\$1,500	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : T-12 Lamps</i>								
HID	5%			2030	\$1,000	10		
Exterior Lighting								
LED	20%			2043	**			
No Component	80%							

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source Natural Gas	100%			2045	**	1		
Conversion Equipment Furnace	100%			2043	**	1	\$900	
Air Conditioning								
Energy Source Electricity	100%			2043	**	1		
Conversion Equipment Window/Wall Unit	20%			2028	\$1,300	1		
No Component	80%							
Plumbing								
Storm Drain Piping Cast Iron	100%			LIFE	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BAYRIDGE GARAGE
Address : 8501 FIFTH AVENUE @ 85TH ST.
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0203.000 / 14316 **Yr Built/Renovated** : 1972 /
Area Sq Ft : 88,950 **Project Type** : HIGHWAYS
Date of Survey : 10-Nov-2021 **Landmark Status** : NONE
Areas Surveyed : Basement, Roof, Floors 1,2,3,4
Block : 6036 **Lot** : 1 **BIN** : 3153196

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$556,800	\$56,100
Interior Architecture	\$3,858,500	\$119,200
Electrical	\$224,100	\$164,500
Total	\$4,639,300	\$339,800
Importance Code A	\$556,800	\$56,100
Importance Code B	\$4,082,600	\$283,700
Total	\$4,639,300	\$339,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$148,600		\$15,000	
Interior Architecture	\$27,900	\$1,300		\$500
Electrical	\$3,600	\$9,400	\$9,700	\$10,000
Mechanical	\$6,400		\$6,100	
Site Pavements	\$68,400			
Elevators/Escalators	\$14,400	\$14,400	\$14,400	\$14,400
Total	\$269,400	\$25,200	\$45,200	\$24,800
Importance Code A	\$148,800		\$15,200	
Importance Code B	\$61,200	\$25,100	\$30,000	\$24,800
Importance Code C	\$59,400	\$100		
Total	\$269,400	\$25,200	\$45,200	\$24,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BAYRIDGE GARAGE
Asset # : 14316

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Cast in Place Concrete	35%	Now	\$65,600	LIFE	**	5	\$56,100	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Adjacent To Main Entrance To The Garage And Other Areas Throughout</i>								
Concrete Masonry Unit	10%	Now	\$33,600	LIFE	**	5	\$2,000	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : East Elevation</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : East Facade</i>								
Masonry: Brick	16%	Now	\$41,300	LIFE	**	5	\$5,100	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Masonry: Granite	2%	Now	\$1,000	LIFE	**	5	\$500	
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Metal Panel	15%			2043	**	5-10	\$33,100	
Metal Coiling Doors	2%	0-2	\$20,100	2046	**	5	\$1,000	
<i>Deformed/Dented, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Right Garage Door</i>								
Pre-Cast Concrete	10%	Now	\$45,400	LIFE	**	5	\$10,400	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Window Wall	10%			2053	**	5	\$12,000	
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : West And South Sides</i>								
<i>Explanation : Sections Of The First Floor Are Occupied By A School, Bank And Stores</i>								
Windows								
Metal Louvers	100%			2042	**	10	\$12,100	
Parapets								
Cast in Place Concrete	50%			LIFE	**	5	\$14,900	
Concrete Masonry Unit	15%			LIFE	**	5	\$500	
Metal Rail	20%			2046	**	5-10	\$10,400	
Metal: Cage/Fence	15%	4+	\$1,000	2038	**	5	\$1,400	
<i>Deteriorated Finish, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : East Facade</i>								
Roof								
Traffic Topping	95%	Now	\$491,200	2043	**			
<i>Gut/DS Non Func/Miss, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Bulkhead</i>								
<i>Worn/Eroded, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Top Parking Level</i>								
Not Accessible	5%							
Soffits								
Cast in Place Concrete	100%			LIFE	**	5		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BAYRIDGE GARAGE
Asset # : 14316

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Interior								
Floors								
Cast in Place Concrete	25%	Now	\$503,100	LIFE	**	5	\$66,200	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Near Basement Entrance, Main Drive And Entrance</i>								
Ceramic Tile	2%			2042	**	5	\$2,400	
Traffic Topping	70%	Now	\$2,371,000	2038	**	5	\$53,000	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : All Parking Levels</i>								
<i>Worn/Eroded, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : All Parking Levels</i>								
Vinyl Tile	3%	0-2	\$98,000	2043	**	3	\$1,400	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Office</i>								
<i>Worn/Eroded, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Office</i>								
Interior Walls								
Cast in Place Concrete	70%			LIFE	**			
Ceramic Tile	2%			2042	**	5	\$200	
Concrete Masonry Unit	20%	Now	\$10,600	LIFE	**	5	\$900	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Masonry: Brick	8%	Now	\$17,300	LIFE	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Ceilings								
Exposed Struc: Concrete	100%	2-4	\$886,300	LIFE	**	5	\$18,900	
<i>Loose/Delam Surface, Extent : Light, Area Affected : 5%</i>								
<i>Location : First Floor Utility</i>								
Site Enclosure								
Fence/Gates								
Chain Link	90%			2053	**			
Iron Picket	10%			2068	**			
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	98%	Now	\$35,900	2046	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 50%</i>								
<i>Location : Fifth Avenue And 85th Street</i>								
Pavers/Stone	2%	Now	\$1,000	2042	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Fifth Avenue And 85th Street</i>								
On-Site Walkways								
Cast in Place Concrete	100%	Now	\$31,400	2053	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : East Side Of Building</i>								
Parking/Driveway								
Cast in Place Concrete	100%			2046	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BAYRIDGE GARAGE
Asset # : 14316

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2033	\$7,400	5	\$400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : Main Service Disconnect Switch Rated At 800 Amperes.</i>								
Switchgear / Switchboard								
Molded Case Bkrs	100%			2033	\$63,500	5	\$2,300	
Raceway								
Conduit	100%			2033	\$10,800	1		
Panelboards								
Fused Disc Sw	20%			2032	\$7,800	5	\$400	
Molded Case Bkrs	80%			2032	\$31,200	5	\$1,900	
Wiring								
Thermoplastic	100%			2033	\$22,100	1		
Motor Controllers								
Locally Mounted	100%			2031	\$101,000	5	\$600	
Ground								
Grounding Devices								
Not Accessible	100%							
Lighting								
Interior Lighting								
LED	100%			2041	**			
Egress Lighting								
Exit, LED	100%			2068	**	1		
Exterior Lighting								
LED	30%			2041	**			
No Component	70%							
Alarm								
Security System								
Generic	100%			2041	**	1	\$33,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : CCTV Surveillance Cameras</i>								
Fire/Smoke Detection								
Generic, Analog	100%	Now	\$224,100	2043	**	1-3	\$49,800	
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Stair Cases</i>								
<i>Explanation : Not Functional</i>								
Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Heating								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BAYRIDGE GARAGE
Asset # : 14316

Mechanical		Current Repair		Future Replacement		Maintenance			
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Heating									
Energy Source									
	Electricity	2%			2043	**	1		
	No Component	98%							
Conversion Equipment									
	Radiant Heater	1%	0-2	\$200	2043	**	2		
	<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
	<i>Location : Restrooms</i>								
	<i>Explanation : Obsolete Units</i>								
	Radiant Heater	1%			2033	\$200	2		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
	<i>Location : 1st Floor Office</i>								
	<i>Explanation : Electric Unit Heater</i>								
	No Component	98%							
Air Conditioning									
Energy Source									
	Electricity	2%			2041	**	1		
	No Component	98%							
Conversion Equipment									
	Window/Wall Unit	2%			2028	\$6,000	1		
	No Component	98%							
Plumbing									
H/C Water Piping									
	Brass/Copper	2%			2033	\$20,300	1		
	No Component	98%							
Water Heater With Tanks									
	Electric	2%			2026	\$500	4		
	No Component	98%							
Sanitary Piping									
	Cast Iron	20%	0-2	\$4,000	LIFE	**	1		
	<i>Corroded, Extent : Moderate, Area Affected : 2%</i>								
	<i>Location : Basement</i>								
	Cast Iron	80%			LIFE	**	1		
Sump Pump(s)									
	Non-Submersible	10%	Now	\$1,700	2043	**	4	\$200	
	<i>Corroded, Extent : Severe, Area Affected : 100%</i>								
	<i>Location : Basement</i>								
	<i>Obsolete Equipment, Extent : Moderate, Area Affected : 100%</i>								
	<i>Location : Basement</i>								
	No Component	90%							
Vertical Transport									

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BAYRIDGE GARAGE
Asset # : 14316

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Vertical Transport	Elevators							
	Hydraulic	100%			LIFE	**		
				<i>Controller Not Working, Extent : Moderate, Area Affected : 100%</i>				
				<i>Location : Level 1 To Roof</i>				
				<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
				<i>Location : Level 1 To Roof</i>				
				<i>Explanation : 2 Units</i>				
Fire Suppression	Standpipe							
	Generic	100%			2043	**	1-5	\$400
	Sprinkler							
	No Component	98%						
	Generic	2%			2033	\$200	1-2	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BRIDGES BUILDING
Address : 17 SOUTH 6TH STREET CORNER OF KENT AVE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0348.010 / 15362 **Yr Built/Renovated** : 1960 /
Area Sq Ft : 20,272 **Project Type** : HIGHWAYS
Date of Survey : 02-Mar-2022 **Landmark Status** : NONE
Areas Surveyed : Basement, Roof, Floors 1,2
Block : 2454 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$319,400	\$55,600
Interior Architecture	\$644,200	\$51,100
Mechanical		\$58,400
Total	\$963,600	\$165,100
Importance Code A	\$319,400	\$55,600
Importance Code B	\$251,200	\$109,500
Importance Code C	\$393,000	
Total	\$963,600	\$165,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$30,300			\$1,200
Interior Architecture	\$73,400	\$900		\$800
Electrical	\$2,300	\$1,900	\$23,600	\$2,500
Mechanical	\$3,500	\$4,000	\$3,200	\$4,100
Site Pavements	\$13,800			
Elevators/Escalators	\$7,200	\$7,200	\$7,200	\$7,200
Total	\$130,600	\$13,900	\$34,000	\$15,800
Importance Code A	\$31,300	\$1,000	\$1,000	\$2,200
Importance Code B	\$60,400	\$12,500	\$32,900	\$13,600
Importance Code C	\$38,800	\$400		
Total	\$130,600	\$13,900	\$34,000	\$15,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES BUILDING
Asset # : 15362

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Glass Block	2%			LIFE	**	5	\$500	
Masonry: Brick Cavity	95%	Now	\$319,400	LIFE	**	5	\$37,500	
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Along 5th Street</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Along 5th Street</i>								
<i>Explanation : Steel Braces Installed To Stabilize Wall</i>								
Metal Coiling Doors	3%			2046	**	5	\$3,700	
Windows								
Aluminum	99%			2049	**	5	\$2,400	
Metal Louvers	1%			2042	**	10	\$200	
Parapets								
Cast Stone/Terra Cotta	15%			LIFE	**	5	\$7,900	
Masonry: Brick Cavity	85%	0-2	\$28,500	LIFE	**	5	\$5,800	
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 5%</i>								
<i>Location : Interior Parapet</i>								
<i>Miss/Damaged Flashings, Extent : Light, Area Affected : 5%</i>								
<i>Location : 2nd Floor Flashing</i>								
Roof								
Panel/Paver: Cer/Brk	100%			2043	**	10	\$55,600	
Interior								
Floors								
Cast in Place Concrete	77%			LIFE	**	5	\$51,100	
Ceramic Tile	3%			2042	**	5	\$900	
Vinyl Tile	20%	2-4	\$32,700	2038	**	3	\$2,300	
<i>Worn/Eroded, Extent : Light, Area Affected : 20%</i>								
<i>Location : Offices</i>								
Interior Walls								
Cast in Place Concrete	2%			LIFE	**			
Ceramic Tile	2%			2042	**	5	\$800	
Concrete Masonry Unit	20%	Now	\$38,800	LIFE	**	5	\$3,400	
<i>Vertical Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Adjacent Overhead Door</i>								
Glass: Single Pane	1%			LIFE	**	5	\$300	
Gypsum Board	25%			LIFE	**	5	\$6,300	
Masonry: Brick	50%	Now	\$393,000	LIFE	**			
<i>Diagonal Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Rear Garage Storage</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Rear Garage Storage</i>								
<i>Other Observation, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Rear Storage</i>								
<i>Explanation : Steel Braces Installed To Stabilize Wall</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES BUILDING
Asset # : 15362

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Interior

Ceilings

AcousTileSusp.Lay-In	20%	Now	\$1,900	2046	**	5	\$2,900
----------------------	-----	-----	---------	------	----	---	---------

Broken/Missing Elements, Extent : Light, Area Affected : 2%
Location : Offices

Exposed Struc: Concrete	60%	Now	\$251,200	LIFE	**	5	\$2,700
-------------------------	-----	-----	-----------	------	----	---	---------

Cracking/Crumbling, Extent : Moderate, Area Affected : 5%
Location : Rear Garage Storage
Exposed Reinforcement, Extent : Moderate, Area Affected : 5%
Location : Garage Storage
Other Observation, Extent : Moderate, Area Affected : 5%
Location : Rear Garage Storage
Explanation : Steel Braces Installed To Stabilize Ceiling

Exposed Struc: Steel	20%			LIFE	**		
----------------------	-----	--	--	------	----	--	--

Site Pavements

Public Sidewalk

Cast in Place Concrete	100%	0-2	\$13,800	2046	**		
------------------------	------	-----	----------	------	----	--	--

Cracking/Crumbling, Extent : Light, Area Affected : 5%
Location : Throughout

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Service Equipment

Fused Disc Sw	100%			2053	**	5	\$100
---------------	------	--	--	------	----	---	-------

Other Observation, Extent : Moderate, Area Affected : 100%
Location : Basement Electrical Room
Explanation : Main Service Switch Rating 600 Amperes

Switchgear / Switchboard

Fused Disc Sw	100%			2053	**	5	\$100
---------------	------	--	--	------	----	---	-------

Raceway

Conduit	100%			2053	**	1	
---------	------	--	--	------	----	---	--

Panelboards

Molded Case Bkrs	100%			2049	**	5	\$500
------------------	------	--	--	------	----	---	-------

Wiring

Thermoplastic	100%			2053	**	1	
---------------	------	--	--	------	----	---	--

Motor Controllers

Locally Mounted	100%			2046	**	5	\$100
-----------------	------	--	--	------	----	---	-------

Ground

Grounding Devices

Generic	100%			LIFE	**	5	\$300
---------	------	--	--	------	----	---	-------

Lighting

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES BUILDING
Asset # : 15362

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Interior Lighting Fluorescent	10%			2033	\$14,000	10	\$1,900	
<i>T-8 Lamps And Fixtures, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Basement And Some Area At 1st Floor</i>								
LED	90%			2038	**			
Egress Lighting								
Emergency, Battery	50%			2038	**	10	\$2,400	
Exit, Battery	50%			2038	**	10	\$700	
Exterior Lighting								
HID	20%			2028	\$18,500	10		
No Component	80%							
Alarm								
Security System Generic	100%			2038	**	1	\$7,600	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Interior And Exterior Of The Building</i>								
<i>Explanation : Cameras Security System</i>								
Fire/Smoke Detection								
Generic, Digital	100%			2038	**	1-3	\$12,900	
Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source Natural Gas	100%			2053	**	1		
Conversion Equipment								
Furnace	70%			2038	**	1	\$7,000	
Hot Water Boiler	30%			2046	**	1	\$3,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Basement Boiler Room</i>								
<i>Explanation : 2 Units</i>								
Distribution								
Hot Wtr Piping/Pump	30%			2049	**	4	\$300	
No Component	70%							
Terminal Devices								
Air Handler	20%			2038	**	1	\$2,500	
Convactor/Radiator	10%			2046	**	1	\$700	
No Component	70%							
Air Conditioning								
Energy Source Electricity	30%			2049	**	1		
No Component	70%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES BUILDING
Asset # : 15362

Mechanical	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Air Conditioning							
Conversion Equipment							
Interior Pkg Unit - Cooling	10%			2034	\$31,300	2	\$100
Reciprocating Compr/Chiller	20%			2033	\$58,400	1	\$1,900
No Component	70%						
Terminal Devices							
Air Handler/Cool/Ht	20%			2038	**	1	\$2,500
No Component	80%						
Heat Rejection							
Air Cooled Condenser Unit	30%			2033	\$5,200	2	\$4,200
No Component	70%						
Ventilation							
Distribution							
Ductwork/Diffusers	30%			LIFE	**	2-5	\$3,400
No Component	70%						
Exhaust Fans							
Interior	30%			2038	**	2	\$200
Roof	70%			2033	\$26,900	2	\$400
Plumbing							
H/C Water Piping							
Brass/Copper	30%			2053	**	1	
No Component	70%						
Water Heater With Tanks							
Electric	100%			2032	\$23,100	4	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : 2nd Floor</i>				
			<i>Explanation : One 80 Gallon Unit</i>				
Sanitary Piping							
Cast Iron	100%			LIFE	**	1	
Storm Drain Piping							
Cast Iron	100%			LIFE	**	1	
Sump Pump(s)							
Submersible	100%			2026	\$600	4	\$600
Backflow Preventer							
Generic	100%			2038	**	1	\$1,200
Fixtures							
Generic	100%						
Vertical Transport							
Elevators							
Hydraulic	100%			LIFE	**		
			<i>Controller Not Working, Extent : Severe, Area Affected : 100%</i>				
			<i>Location : Has Been For 2 Years. Basement</i>				
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : Basement To 2nd Floor</i>				
			<i>Explanation : 1 Unit</i>				

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES BUILDING
Asset # : 15362

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Fire Suppression	Sprinkler							
	Generic	100%			2053	* *	1-2	\$5,700
Fire Pump								
	Generic	100%			2036	* *	1	\$3,800

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BRIDGES IRON SHOP
Address : 59 ADAMS STREET UNDER MANHATTAN BRIDGE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0216.000 / 14714 **Yr Built/Renovated** : 1910 /
Area Sq Ft : 17,412 **Project Type** : HIGHWAYS
Date of Survey : 03-Mar-2022 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2
Block : 39 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$530,800	
Interior Architecture	\$64,400	\$51,300
Electrical	\$128,600	
Mechanical		\$177,000
Total	\$723,800	\$228,300
Importance Code A	\$530,800	\$177,000
Importance Code B	\$128,600	\$51,300
Importance Code C	\$64,400	
Total	\$723,800	\$228,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$27,100			
Interior Architecture	\$67,400	\$700		\$200
Electrical	\$1,700	\$2,200	\$44,500	\$1,600
Mechanical	\$2,300	\$2,300	\$21,500	\$2,300
Site Pavements	\$21,100			
Total	\$119,700	\$5,200	\$66,000	\$4,100
Importance Code A	\$28,300	\$1,200	\$600	\$1,200
Importance Code B	\$91,400	\$4,000	\$65,400	\$3,000
Importance Code C				
Total	\$119,700	\$5,200	\$66,000	\$4,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES IRON SHOP
Asset # : 14714

Architecture	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Concrete Masonry Unit	95%	Now	\$165,700	LIFE	**	5	\$19,800	
	<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Throughout</i>							
	<i>Expansion Joint Failure, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Throughout</i>							
	<i>Rusting Masonry Supt, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Above Windows</i>							
	<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Rear Of Shop</i>							
Metal Sect. OHD	5%			2046	**	5	\$5,200	
Windows								
Steel	100%	Now	\$99,800	2058	**	5	\$8,500	
	<i>Air Infiltration, Extent : Light, Area Affected : 20%</i>							
	<i>Location : Throughout</i>							
	<i>Corrosion/Rusting, Extent : Moderate, Area Affected : 30%</i>							
	<i>Location : Throughout</i>							
	<i>Glazing Broken/Cracked, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Throughout</i>							
	<i>Unit Inoperable, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Shop</i>							
Parapets								
Cast Stone/Terra Cotta	10%	Now	\$6,000	LIFE	**	5	\$2,600	1
	<i>Cracking/Crumbling, Extent : Severe, Area Affected : 20%</i>							
	<i>Location : Throughout</i>							
Concrete Masonry Unit	90%	Now	\$18,500	LIFE	**	5	\$3,400	1
	<i>Cracking/Crumbling, Extent : Severe, Area Affected : 20%</i>							
	<i>Location : Throughout</i>							
Roof								
Panel/Paver: Cer/Brk	100%	Now	\$265,300	2043	**			
	<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Throughout</i>							
	<i>Drains Clogged, Extent : Moderate, Area Affected : 10%</i>							
	<i>Location : Roof Drains</i>							
	<i>Misaligned/Bulging, Extent : Severe, Area Affected : 10%</i>							
	<i>Location : Throughout</i>							
	<i>Miss/Damaged Flashings, Extent : Moderate, Area Affected : 25%</i>							
	<i>Location : Throughout</i>							
	<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Throughout</i>							
	<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Around Roof Drains</i>							
Interior								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES IRON SHOP
Asset # : 14714

Architecture		Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost		
Interior									
Floors									
Cast in Place Concrete	90%			LIFE	**	5	\$51,300		
Ceramic Tile	5%			2042	**	5	\$1,300		
Vinyl Tile	5%	Now	\$35,200	2043	**	3	\$500		
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>									
<i>Location : Throughout</i>									
<i>Worn/Eroded, Extent : Moderate, Area Affected : 100%</i>									
<i>Location : Throughout</i>									
Interior Walls									
Concrete Masonry Unit	100%	0-2	\$64,400	LIFE	**	5	\$14,000		
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>									
<i>Location : Throughout</i>									
<i>Vertical Cracks, Extent : Light, Area Affected : 5%</i>									
<i>Location : Iron Shop</i>									
Ceilings									
AcousTileSusp.Lay-In	40%	0-2	\$32,300	2053	**	5	\$5,000		
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>									
<i>Location : Throughout</i>									
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>									
<i>Location : 2nd Floor</i>									
<i>Worn/Eroded, Extent : Severe, Area Affected : 100%</i>									
<i>Location : Throughout</i>									
Exposed Struc: Steel	60%			LIFE	**				
Site Pavements									
Public Sidewalk									
Cast in Place Concrete	100%	Now	\$21,100	2046	**				
<i>Cracking/Crumbling, Extent : Light, Area Affected : 50%</i>									
<i>Location : Throughout</i>									
On-Site Walkways									
Cast in Place Concrete	100%			2046	**				
Parking/Driveway									
Cast in Place Concrete	100%			2046	**				

Electrical		Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost		
Under 600 Volts									
Service Equipment									
Fused Disc Sw	100%			2053	**	5	\$100		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>									
<i>Location : Electrical Room</i>									
<i>Explanation : One 1,200 Ampere Main Disconnect Switch.</i>									

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES IRON SHOP
Asset # : 14714

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Transformers								
Dry Type	50%			2046	**	5		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : One 150 Kilovolt Amperes 480/208 Volt And One 112 Kilovolt Amperes 240/120 Volt</i>								
Dry Type	50%			2038	**	5		
Switchgear / Switchboard								
Fused Disc Sw	100%			2033	\$31,800	5	\$100	
Raceway								
Conduit	100%			2033	\$4,300	1		
Panelboards								
Fused Disc Sw	20%			2032	\$1,900	5	\$100	
Molded Case Bkrs	80%			2032	\$7,800	5	\$400	
Wiring								
Thermoplastic	100%			2033	\$8,800	1		
Motor Controllers								
Locally Mounted	80%			2031	\$17,900	5	\$100	
Locally Mounted	20%			2038	**	5		
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$300	
Lighting								
Interior Lighting								
Fluorescent	60%			2028	\$72,300	10	\$9,600	
<i>T-12 Lamps And Fixtures, Extent : Light, Area Affected : 60%</i>								
<i>Location : Throughout The Building</i>								
Fluorescent	5%			2028	\$6,000	10	\$800	
<i>Compact Fluorescent Light, Extent : Light, Area Affected : 5%</i>								
<i>Location : First Floor</i>								
HID	25%			2028	\$50,300	10	\$100	
LED	10%			2041	**			
Egress Lighting								
Emergency, Battery	50%			2028	\$14,300	10	\$2,100	
Exit, Battery	50%			2033	\$9,800	10	\$600	
Exterior Lighting								
HID	20%			2028	\$15,900	10		
No Component	80%							
Alarm								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES IRON SHOP
Asset # : 14714

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Alarm								
Security System								
Generic	50%			2033	\$16,000	1	\$3,300	
	<i>Other Observation, Extent : Light, Area Affected : 50%</i>							
	<i>Location : At Doors</i>							
	<i>Explanation : Intrusion Alarm System</i>							
Generic	50%			2033	\$16,000	1	\$3,300	
	<i>Other Observation, Extent : Light, Area Affected : 50%</i>							
	<i>Location : At Doors</i>							
	<i>Explanation : CCTV Cameras</i>							
Fire/Smoke Detection								
Generic, Digital	100%			2033	\$43,900	1-3	\$10,700	
	<i>Other Observation, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Throughout The Building</i>							
	<i>Explanation : Manual Pull Stations, Horns, Strobes And Smoke Detectors</i>							

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2043	**	1		
Conversion Equipment								
Furnace	20%			2041	**	1	\$1,700	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Roof</i>							
	<i>Explanation : 1 Rooftop Package Unit</i>							
Furnace	15%	0-2	\$800	2033	\$7,900	1	\$1,200	
	<i>Not in Service, Extent : Moderate, Area Affected : 100%</i>							
	<i>Location : 1st Floor Ceiling</i>							
Furnace	25%			2033	\$13,200	1	\$2,200	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : 1st Floor Ceiling</i>							
	<i>Explanation : 5 Modine Heaters</i>							
Radiant Heater	40%			2033	\$177,000	2	\$3,200	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : 1st Floor Ceiling</i>							
	<i>Explanation : 3 Units</i>							
Air Conditioning								
Energy Source								
Electricity	100%			2041	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES IRON SHOP
Asset # : 14714

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Air Conditioning								
Conversion Equipment								
	Ext Pkg Unit - Heating/Cooling	20%			2041	**	2	\$200
<i>R-410a Refrigerant, Extent : Light, Area Affected : 100%</i>								
<i>Location : 1 Unit, Roof</i>								
	Split Unit	10%			2038	**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : 3 Units</i>								
	No Component	70%						
Terminal Devices								
	Fan Coil - 2 Pipe	10%			2038	**	1	\$600
	No Component	90%						
Heat Rejection								
	Air Cooled Condenser Unit	10%			2038	**	2	\$1,200
	No Component	90%						
Ventilation								
Distribution								
	Ductwork/Diffusers	40%			LIFE	**	2-5	\$3,900
	No Component	60%						
Exhaust Fans								
	Roof	40%			2038	**	2	\$200
	Wall Unit	60%			2038	**	2	\$300
Plumbing								
H/C Water Piping								
	Brass/Copper	100%			2043	**	1	
Water Heater With Tanks								
	Gas Fired	100%			2028	\$16,700	2	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor</i>								
<i>Explanation : 1 Tankless Unit With One 200 Gallon Tank</i>								
Sanitary Piping								
	Cast Iron	100%			LIFE	**	1	
Storm Drain Piping								
	Cast Iron	100%			LIFE	**	1	
Backflow Preventer								
	Generic	100%			2033	\$7,600	1	\$1,100
Fixtures								
	Generic	100%						
Fire Suppression								
Standpipe								
	Generic	100%			2043	**	1-5	\$8,800
Sprinkler								
	Generic	100%			2043	**	1-2	\$4,900

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BRIDGES PAINT UNIT GENERAL STORAGE BUILDING
Address : 424 WYTHE AVENUE REAR OF PARKING LOT
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0348.100 / 15376 **Yr Built/Renovated** :
Area Sq Ft : 3,627 **Project Type** : HIGHWAYS
Date of Survey : 02-Mar-2022 **Landmark Status** : NONE
Areas Surveyed : Floors 1
Block : 2454 **Lot** : 1 **BIN** :

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$20,100		\$1,700	
Interior Architecture				
Electrical	\$300	\$200	\$200	\$300
Mechanical	\$200	\$200	\$200	\$200
Site Enclosure	\$300			
Total	\$20,900	\$400	\$2,100	\$500
Importance Code A	\$20,300	\$200	\$1,900	\$200
Importance Code B	\$300	\$200	\$200	\$300
Importance Code C	\$300			
Total	\$20,900	\$400	\$2,100	\$500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES PAINT UNIT GENERAL STORAGE BUILDING

Asset # : 15376

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Concrete Masonry Unit	70%			LIFE	**	5	\$8,100	
<i>Staining/Discoloring, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Metal/Glass Curt Wall	15%			LIFE	**	5	\$5,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Material Is Channel Glass</i>								
Metal Panel	5%			2053	**	5-10	\$6,300	
Metal Sect. OHD	10%			2046	**	5	\$5,800	
Windows								
Metal Louvers	100%			2042	**	10	\$23,900	
Parapets								
Metal Rail	50%			2046	**	5-10	\$28,300	
Weathering Steel	20%			LIFE	**	1		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Parapet</i>								
<i>Explanation : Material Is Structural Steel</i>								
Not Accessible	30%							
Roof								
Skylight, Plastic	10%			2046	**	1		
Not Accessible	90%							
Interior								
Floors								
Cast in Place Concrete	100%			LIFE	**	5	\$11,900	
Interior Walls								
Wood	100%			LIFE	**	5	\$43,000	
Ceilings								
Exposed Struc: Steel	100%			LIFE	**			
Site Enclosure								
Free Standing Walls								
Cast in Place Concrete	100%	Now	\$300	2068	**			
<i>Impact Damage, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Front Entry Ramp</i>								
Site Pavements								
On-Site Walkways								
Asphalt	100%			2042	**			
Parking/Driveway								
Asphalt	100%			2042	**			
Electrical								
Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES PAINT UNIT GENERAL STORAGE BUILDING
Asset # : 15376

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment Fused Disc Sw	100%			2053	**	5		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : At The Entrance Of The Building</i>								
<i>Explanation : Main Service Switch Rating 400 Amperes</i>								
Raceway Conduit	100%			2053	**	1		
Panelboards Molded Case Bkrs	100%			2049	**	5	\$100	
Wiring Thermoplastic	100%			2053	**	1		
Motor Controllers Locally Mounted	100%			2046	**	5		
Lighting								
Interior Lighting LED	100%			2038	**			
Egress Lighting Emergency, Service Exit, LED	50%			2038	**	1		
	50%			2061	**	1		
Exterior Lighting LED No Component	20%			2038	**			
	80%							
Alarm								
Fire/Smoke Detection Generic, Digital	100%			2038	**	1-3	\$2,300	

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source Electricity	100%			2059	**	1		
Conversion Equipment Furnace	100%			2041	**	1	\$1,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Ceiling</i>								
<i>Explanation : 10 Units</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BRIDGES PAINT UNIT BLDG #3 ELECTRICAL SERVICE BUILDING
Address : 424 WYTHE AVENUE REAR OF NEW BUILDING
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0348.110 / 15377 **Yr Built/Renovated** :
Area Sq Ft : 574 **Project Type** : HIGHWAYS
Date of Survey : 02-Mar-2022 **Landmark Status** : NONE
Areas Surveyed : Floors 1
Block : **Lot** : **BIN** :

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$8,700			
Interior Architecture	\$4,700			
Electrical				
Mechanical		\$100		\$100
Total	\$13,400	\$100		\$100
Importance Code A	\$8,700	\$100		\$100
Importance Code B				
Importance Code C	\$4,700			
Total	\$13,400	\$100		\$100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES PAINT UNIT BLDG #3 ELECTRICAL SERVICE BUILDING
Asset # : 15377

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Concrete Masonry Unit	95%	Now	\$3,700	LIFE	**	5	\$2,200	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Painted Surfaces, Extent : Light, Area Affected : 100%</i>								
<i>Location : Exterior Wall</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Rear Corner</i>								
Metal Coiling Doors	5%			2046	**	5	\$600	
Parapets								
Pre-Cast Concrete	50%	Now	\$4,700	LIFE	**	5	\$900	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Rear Corner</i>								
Not Accessible	50%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Interior Parapet</i>								
<i>Explanation : Roof Is Not Accessible</i>								
Roof								
Not Accessible	100%							
Interior								
Floors								
Cast in Place Concrete	100%			LIFE	**	5	\$1,900	
Interior Walls								
Concrete Masonry Unit	100%	Now	\$4,700	LIFE	**	5	\$1,000	
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Rear Corner</i>								
Ceilings								
Exposed Struc: Concrete	100%			LIFE	**	5	\$100	
Site Pavements								
On-Site Walkways								
Asphalt	100%			2042	**			
Parking/Driveway								
Asphalt	100%			2042	**			

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2043	**	5		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Electrical Service Building</i>								
<i>Explanation : 200 Ampere Main Service Switch Rating Wall Mounting</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES PAINT UNIT BLDG #3 ELECTRICAL SERVICE BUILDING
Asset # : 15377

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Transformers								
Dry Type	100%			2038	**	5		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Electrical Service Building</i>								
<i>Explanation : One 100 Kilovolt Amperes And One 75 Kilovolt Amperes 208 Volt To 480/277 Volt</i>								
Raceway								
Conduit	100%			2043	**	1		
Panelboards								
Molded Case Bkrs	100%			2041	**	5		
Wiring								
Thermoplastic	100%			2043	**	1		
Lighting								
Interior Lighting								
Fluorescent	100%			2033	\$9,700	10	\$500	
<i>T-12 Lamps And Fixtures, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
Exterior Lighting								
LED	20%			2038	**			
No Component	80%							

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Electricity	100%			2043	**	1		
Conversion Equipment								
Radiant Heater	100%			2033	\$14,600	2	\$300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Ceiling</i>								
<i>Explanation : 1 Unit</i>								
Ventilation								
Exhaust Fans								
Roof	100%			2033	\$1,100	2		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BRIDGES PAINT UNIT WAREHOUSE OLD BUILDING
Address : 424 WYTHE AVENUE CORNER OF SOUTH 6TH STREET
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0348.000 / 15361 **Yr Built/Renovated** : 1960 /
Area Sq Ft : 10,072 **Project Type** : HIGHWAYS
Date of Survey : 02-Mar-2022 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,Att
Block : 2454 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$104,300	
Interior Architecture		\$61,000
Electrical		\$59,700
Mechanical		\$243,900
Total	\$104,300	\$364,600
Importance Code A	\$104,300	
Importance Code B		\$364,600
Total	\$104,300	\$364,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$34,100			
Interior Architecture	\$105,500		\$5,700	\$300
Electrical	\$10,300	\$1,100	\$4,900	\$900
Mechanical	\$2,900	\$1,300	\$1,400	\$1,300
Total	\$152,700	\$2,500	\$12,000	\$2,500
Importance Code A	\$35,100	\$1,000	\$1,000	\$1,000
Importance Code B	\$70,000	\$1,500	\$10,900	\$1,500
Importance Code C	\$47,700			
Total	\$152,700	\$2,500	\$12,000	\$2,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES PAINT UNIT WAREHOUSE OLD BUILDING

Asset # : 15361

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Cast in Place Concrete	5%			LIFE	**	5	\$3,000	
Concrete Masonry Unit	90%	0-2	\$27,800	LIFE	**	5	\$6,600	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Corners Of Building</i>								
<i>Painted Surfaces, Extent : Light, Area Affected : 100%</i>								
<i>Location : Exterior Walls</i>								
Metal Coiling Doors	5%			2046	**	5	\$1,800	
Windows								
Wood	100%	Now	\$104,300	2058	**	5	\$13,300	1
<i>Dry Rot/Decay, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
<i>Glazing Broken/Cracked, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Thermally Inefficient, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Unit Inoperable, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Roof								
Asphalt Shingle	100%	Now	\$5,300	2042	**			
<i>Miss/Damaged Flashings, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Gutter Above Overhead Door</i>								
Interior								
Floors								
Cast in Place Concrete	30%			LIFE	**	5	\$9,900	
Vinyl Tile	15%	Now	\$18,300	2033	\$61,000	3	\$800	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Offices</i>								
<i>Worn/Eroded, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Offices</i>								
Wood	15%	Now	\$39,500	2048	**	5	\$2,100	
<i>Deteriorated Finish, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Offices</i>								
<i>Loose Units, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Offices</i>								
<i>Split/Cracked, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Offices</i>								
Wood	40%			2048	**	5	\$11,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Attic</i>								
<i>Explanation : Plywood Floor</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES PAINT UNIT WAREHOUSE OLD BUILDING

Asset # : 15361

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Interior Walls								
Concrete Masonry Unit	50%			LIFE	**	5	\$2,900	
Masonry: Brick	35%	4+	\$46,700	LIFE	**			
<i>Paint Peeling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
<i>Painted Surfaces, Extent : Light, Area Affected : 80%</i>								
<i>Location : Offices</i>								
Plaster	15%	2-4	\$1,000	LIFE	**	5	\$600	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Offices</i>								
Ceilings								
Exposed Struc: Wood	60%			LIFE	**			
Gypsum Board	10%			LIFE	**	5	\$1,700	
Wood	30%			LIFE	**	5	\$36,200	
Site Enclosure								
Fence/Gates								
Iron Picket	100%			2068	**			
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2046	**			
On-Site Walkways								
Asphalt	80%			2042	**			
Cast in Place Concrete	20%			2046	**			
Parking/Driveway								
Asphalt	80%			2042	**			
Cast in Place Concrete	20%			2046	**			

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2033	\$3,700	5		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : 1st Floor</i>								
<i>Explanation : No Name Plate</i>								
Raceway								
Conduit	100%			2043	**	1		
Panelboards								
Molded Case Bkrs	100%			2041	**	5	\$300	
Wiring								
Thermoplastic	100%			2043	**	1		

Lighting

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
BRIDGES PAINT UNIT WAREHOUSE OLD BUILDING

Asset # : 15361

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Interior Lighting Fluorescent	5%			2028	\$3,500	10	\$500	
<i>T-12 Lamps And Fixtures, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Boiler Room</i>								
LED	95%			2033	\$59,700			
Egress Lighting								
Emergency, Service	50%			2033	\$3,000	1		
Exit, Battery	50%			2033	\$5,700	10	\$300	
Exterior Lighting								
HID	20%	0-2	\$9,200	2043	**			
<i>Not in Service, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Exterior</i>								
No Component	80%							
Alarm								
Security System								
Generic	100%			2033	\$18,500	1	\$3,800	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : Intrusion System</i>								
Fire/Smoke Detection								
Generic, Digital	100%			2033	\$25,400	1-3	\$6,200	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : 1st Floor Only</i>								
<i>Explanation : Only Smoke Detectors At 1st Floor Connected To Fire Alarm Panel At Bridges Paint Unit Warehouse</i>								
Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2053	**	1		
Conversion Equipment								
Steam Boiler	100%			2046	**	1	\$10,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor Boiler Room</i>								
<i>Explanation : 1 Unit</i>								
Distribution								
Steam Piping/Pump	100%	0-2	\$1,600	2053	**			
<i>Insul. Deteriorating, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Boiler Room And Attic</i>								
Terminal Devices								
Fan Coil Unit/Heat	100%			2033	\$243,900	1	\$3,300	
Air Conditioning								
Energy Source								
Electricity	100%			2041	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

**DEPARTMENT OF TRANSPORTATION - 841
BRIDGES PAINT UNIT WAREHOUSE OLD BUILDING**

Asset # : 15361

Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Air Conditioning								
Conversion Equipment								
Window/Wall Unit	20%			2031	\$7,500	1		
No Component	80%							
Ventilation								
Distribution								
Ductwork/Diffusers	10%			LIFE	**	2-5	\$600	
No Component	90%							
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2043	**	1		
Water Heater With Tanks								
Gas Fired	100%			2031	\$16,700	2		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Boiler Room</i>					
			<i>Explanation : One 50 Gallon Unit</i>					
Sanitary Piping								
Cast Iron	100%			LIFE	**	1		
Fixtures								
Generic								
	100%		<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Aged Equipment</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BRONX COMMISSIONER OFFICE
Address : 1400 WILLIAMSBRIDGE ROAD @ ROBERTS AVE.
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0215.000 / 14713 **Yr Built/Renovated** : 1926 / 2014
Area Sq Ft : 29,626 **Project Type** : HIGHWAYS
Date of Survey : 05-May-2022 **Landmark Status** : NONE
Areas Surveyed : Basement, Roof, Floors 1,2,3
Block : 4074 **Lot** : 1 **BIN** : 2044091

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture		\$91,000
Interior Architecture	\$134,500	\$598,200
Electrical		\$314,600
Mechanical	\$407,000	\$299,900
Total	\$541,500	\$1,303,700
Importance Code A		\$91,000
Importance Code B	\$407,000	\$1,212,700
Importance Code C	\$134,500	
Total	\$541,500	\$1,303,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$48,600	\$7,700	\$2,900	
Interior Architecture	\$81,000	\$5,700		\$6,700
Electrical	\$27,400	\$300	\$71,000	\$100
Mechanical	\$15,100	\$2,400	\$71,200	\$2,400
Site Enclosure	\$3,100			
Site Pavements	\$35,000			
Total	\$210,100	\$16,100	\$145,100	\$9,200
Importance Code A	\$50,100	\$9,200	\$4,400	\$1,500
Importance Code B	\$92,100	\$5,100	\$140,800	\$7,700
Importance Code C	\$67,900	\$1,800		
Total	\$210,100	\$16,100	\$145,100	\$9,200



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
BRONX COMMISSIONER OFFICE
Asset # : 14713

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Masonry: Brick	88%			LIFE	**	5	\$40,200	
Masonry: Limestone	5%			LIFE	**	5	\$1,700	
Metal, Corrugated	2%			2043	**	1		
Granite Panels	5%			LIFE	**	5	\$1,700	
Windows								
Aluminum	70%			2058	**	5	\$5,800	
<i>Recent Installation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : 2nd And 3rd Floor</i>								
Steel	15%			2032	\$91,000	5	\$15,500	
Wood	15%	Now	\$48,600	2058	**	5	\$6,200	
<i>Air Infiltration, Extent : Severe, Area Affected : 40%</i>								
<i>Location : 1st Floor</i>								
<i>Ctrwt/Balnc Not Funct, Extent : Severe, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Parapets								
Masonry: Brick	60%			LIFE	**	5	\$5,200	
Masonry: Limestone	40%			LIFE	**	5	\$4,400	
Roof								
Modified Bitumen	100%			2041	**	10	\$25,400	
Interior								
Floors								
Carpet	30%			2032	\$229,800	3	\$26,600	
Cast in Place Concrete	5%			LIFE	**	5	\$4,900	
Ceramic Tile	5%			2042	**	5	\$2,200	
Marble Panels	5%			LIFE	**	5	\$1,700	
Terrazzo	5%			LIFE	**	5	\$1,700	
Vinyl Tile	50%			2033	\$598,200	3	\$8,300	
Interior Walls								
Ceramic Tile	5%			2042	**	5	\$3,600	
Concrete Masonry Unit	5%			LIFE	**	5	\$1,400	
Gypsum Board	60%	Now	\$11,900	LIFE	**	5	\$26,000	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Basement By Water Utility Entrance</i>								
Masonry: Brick	10%	Now	\$134,500	LIFE	**			
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Basement</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Basement</i>								
Marble Panels	5%			LIFE	**			
Plaster	15%	Now	\$25,800	LIFE	**	5	\$3,300	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Stair Bulkhead</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRONX COMMISSIONER OFFICE
Asset # : 14713

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Ceilings								
AcousTileSusp.Lay-In	80%	Now	\$27,300	2046	**	5	\$16,800	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Basement</i>								
Exposed Struc: Concrete	5%			LIFE	**	5	\$300	
Plaster	15%	Now	\$9,400	LIFE	**	5	\$3,900	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Stair Bulkhead At Roof</i>								
Site Enclosure								
Fence/Gates								
Chain Link	55%			2043	**			
Iron Picket	10%			2053	**			
Masonry: Fieldstone	35%	Now	\$3,100	2043	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Rear Parking Area</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Rear Parking Area</i>								
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%	Now	\$7,800	2038	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Sidewalk Next To Parking Entry</i>								
<i>Sinking/Subsiding, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Sidewalk Next To Parking Entry</i>								
On-Site Walkways								
Cast in Place Concrete	90%			2038	**			
Pavers/Stone	10%			2036	**			
Parking/Driveway								
Cast in Place Concrete	100%	Now	\$27,200	2038	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Parking Area</i>								
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Parking Area</i>								

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Switchgear / Switchboard								
Molded Case Bkrs	100%			2033	\$158,800	5	\$800	
Raceway								
Conduit	90%			2033	\$60,800	1		
Conduit	10%			2053	**	1		
Panelboards								
Molded Case Bkrs	75%			2032	\$58,500	5	\$600	
Molded Case Bkrs	25%			2049	**	5	\$200	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRONX COMMISSIONER OFFICE
Asset # : 14713

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Wiring								
Braided Cloth	30%	2-4	\$27,400	2058	**	1		
<i>Insulation Aged, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
Thermoplastic	40%			2033	\$36,500	1		
Thermoplastic	30%			2053	**	1		
Motor Controllers								
Under Construction	100%							
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$400	
Lighting								
Interior Lighting								
Fluorescent	50%			2043	**	10	\$13,600	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Second Floor</i>								
Under Construction	50%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : First Floor And Basement</i>								
<i>Explanation : Under Construction</i>								
Egress Lighting								
Emergency, Battery	50%			2028	\$24,300	10	\$3,600	
Exit, Battery	50%			2028	\$20,500	10	\$1,000	
Exterior Lighting								
HID	10%			2028	\$13,500	10		
Incandescent	5%			2028	\$7,800	2		
No Component	85%							
Alarm								
Fire/Smoke Detection								
Under Construction	100%							

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2053	**	1		
Conversion Equipment								
Hot Water Boiler	100%			2038	**	1	\$14,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Basement Boiler Room</i>								
<i>Explanation : 2 Units</i>								
Distribution								
Hot Wtr Piping/Pump	100%			2032	\$63,300	4	\$1,500	
Terminal Devices								
Convactor/Radiator	100%			2031	\$236,600	1	\$9,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRONX COMMISSIONER OFFICE
Asset # : 14713

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Air Conditioning								
Energy Source								
Electricity	100%			2041	**	1		
Conversion Equipment								
Interior Pkg Unit - Cooling	50%	Now	\$228,800	2038	**	2	\$700	
	<i>Broken, Extent : Severe, Area Affected : 50%</i>							
	<i>Location : 1st Floor Mechanical Room</i>							
Exterior Pkg Unit - Cooling	40%	Now	\$126,900	2043	**	2	\$600	
	<i>Broken, Extent : Severe, Area Affected : 50%</i>							
	<i>Location : Roof Above Stairs</i>							
	<i>R-22 Refrigerant, Extent : Light, Area Affected : 20%</i>							
	<i>Location : Roof Above Staircase</i>							
	<i>Other Observation, Extent : Severe, Area Affected : 20%</i>							
	<i>Location : Roof Above Staircase</i>							
	<i>Explanation : On Extended Life</i>							
Split Unit	5%			2028	\$34,400			
Window/Wall Unit	5%			2028	\$5,500	1		
Distribution								
Ductwork/Diffusers	100%			LIFE	**	2	\$38,500	
Heat Rejection								
Air Cooled Condenser Unit	15%	0-2	\$12,600	2043	**	2	\$2,500	
	<i>Abandoned in Place, Extent : Moderate, Area Affected : 30%</i>							
	<i>Location : Roof</i>							
	<i>Other Observation, Extent : Severe, Area Affected : 15%</i>							
	<i>Location : Roof Above Stairs</i>							
	<i>Explanation : Obsolete Unit</i>							
No Component	85%							
Ventilation								
Distribution								
Ductwork/Diffusers	40%			LIFE	**	2-5	\$6,600	
No Component	60%							
Exhaust Fans								
Interior	40%			2028	\$51,300	2	\$400	
No Component	60%							
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2043	**	1		
Water Heater With Tanks								
Gas Fired	100%			2028	\$16,700	2		
	<i>Other Observation, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Basement</i>							
	<i>Explanation : 75 Gallons</i>							
Sanitary Piping								
Cast Iron	100%			LIFE	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRONX COMMISSIONER OFFICE
Asset # : 14713

Mechanical		Current Repair		Future Replacement		Maintenance			
System	Component	% of	Fail Date	Estimated Cost	Year	Estimated Cost	Cycle	Estimated Cost	Priority
	Type	Total	(Years)		FY		(Yrs)		
Plumbing									
	Storm Drain Piping								
	Cast Iron	100%			LIFE	**	1		
Fixtures									
	Generic	100%							

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CASTLETON DEPOT
Address : 5 DUBOIS AVENUE @ HURST ST.
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0220.000 / 14718 **Yr Built/Renovated** : 1980 / 2013
Area Sq Ft : 32,500 **Project Type** : HIGHWAYS
Date of Survey : 29-May-2018 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2
Block : 215 **Lot** : 100 **BIN** : 5104536

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$1,243,800	
Interior Architecture	\$72,700	\$241,700
Mechanical	\$1,139,100	\$84,300
Total	\$2,455,600	\$326,100
Importance Code A	\$1,317,800	\$84,300
Importance Code B	\$1,137,800	\$241,700
Total	\$2,455,600	\$326,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$64,400			\$4,100
Interior Architecture	\$68,800	\$1,500	\$900	
Electrical	\$4,300	\$45,100	\$18,000	\$48,200
Mechanical	\$28,000	\$19,800	\$2,900	\$49,600
Site Enclosure	\$6,000			
Total	\$171,500	\$66,300	\$21,800	\$101,900
Importance Code A	\$79,700	\$1,600	\$1,600	\$9,400
Importance Code B	\$46,400	\$64,700	\$19,600	\$92,500
Importance Code C	\$45,500		\$600	
Total	\$171,500	\$66,300	\$21,800	\$101,900



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
CASTLETON DEPOT
Asset # : 14718

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Cement - Fiber Panel	76%	Now	\$41,200	2029	\$412,400			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
Cement - Fiber Panel	4%			2039	**	10	\$3,800	
Metal Sect. OHD	20%	Now	\$21,700	2042	**	5	\$9,500	
<i>Corrosion/Rusting, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Unit Inoperable, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : South West Door</i>								
Windows								
Aluminum	100%			2054	**	5	\$500	
Parapets								
Cast Stone/Terra Cotta	10%	0-2	\$1,500	LIFE	**	5	\$3,300	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Masonry: Brick	90%			LIFE	**	5	\$3,900	
Roof								
Single Ply Membrane	100%	Now	\$831,300	2039	**			
<i>Blisters, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Drains Clogged, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Gravel/Stone Ballast, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Mechanically Attached, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Miss/Damaged Flashings, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Seams Open/Split, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Lower Roof</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
Interior								
Floors								
Cast in Place Concrete	90%	0-2	\$72,700	LIFE	**	5	\$95,800	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Ceramic Tile	3%			2032	\$80,400	5	\$1,500	
Quarry Tile	2%			2042	**	5	\$1,500	
Vinyl Tile	5%			2034	\$65,600	3	\$900	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CASTLETON DEPOT
Asset # : 14718

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Interior								
Interior Walls								
Ceramic Tile	5%			2038	**	5	\$1,200	
Concrete Masonry Unit	75%	Now	\$32,400	LIFE	**	5	\$7,000	
<i>Diagonal Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Horizontal Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
Masonry: Brick	15%	Now	\$13,100	LIFE	**			
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Plaster	5%			LIFE	**	5	\$400	
Ceilings								
AcousTileSusp.Lay-In	5%	Now	\$2,000	2042	**	5	\$1,200	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Cracking/Crumbling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Exposed Struc: Concrete	15%	Now	\$21,400	LIFE	**	5	\$1,100	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout South Garage</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout South Garage</i>								
Exposed Struc: Steel	80%			LIFE	**			
Site Enclosure								
Fence/Gates								
Chain Link	100%			2049	**			
<i>Corrosion/Rusting, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Free Standing Walls								
Concrete Masonry Unit	100%			2049	**			
Retaining Walls								
Cast in Place Concrete	100%	Now	\$6,000	2049	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2042	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CASTLETON DEPOT
Asset # : 14718

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Site Pavements

Parking/Driveway

Asphalt

80%

2032

Cast in Place Concrete

20%

2042

* *

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Service Equipment

Fused Disc Sw

100%

2029

\$3,700

5

\$100

*Other Observation, Extent : Light, Area Affected : 100%**Location : Electrical Room - Shop Area**Explanation : One 800 And One 600 Ampere Main Disconnect Switch*

Switchgear / Switchboard

Fused Disc Sw

50%

2029

\$15,900

5

\$100

Molded Case Bkrs

50%

2029

\$15,900

5

\$400

Raceway

Conduit

100%

2039

* *

1

Panelboards

Fused Disc Sw

5%

2028

\$1,000

5

Molded Case Bkrs

85%

2028

\$16,600

5

\$700

Molded Case Bkrs

10%

2051

* *

5

\$100

Wiring

Thermoplastic

95%

2029

\$8,400

1

Thermoplastic

5%

2055

* *

1

Motor Controllers

Locally Mounted

100%

2027

\$44,900

5

\$200

Ground

Grounding Devices

Generic

100%

LIFE

* *

5

\$500

Lighting

Interior Lighting

LED

100%

2039

* *

Egress Lighting

Emergency, Battery

50%

2039

* *

10

\$3,900

Exit, LED

50%

2069

* *

1

Exterior Lighting

LED

100%

2039

* *

Alarm

Fire/Smoke Detection

No Component

95%

Generic, Analog

5%

2026

\$4,100

1-3

\$1,000

*Other Observation, Extent : Light, Area Affected : 100%**Location : Outside The Building**Explanation : Only In Gas Pump Station*

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CASTLETON DEPOT
Asset # : 14718

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2039	**	1		
Conversion Equipment								
Furnace	75%	0-2	\$14,800	2029	\$74,100	1	\$10,800	
			<i>Malfunctioning, Extent : Severe, Area Affected : 75%</i>					
			<i>Location : Two Out Of Twelve Units Not Working On The First Floor</i>					
Hot Water Boiler	25%			2034	\$84,300	1	\$4,000	
			<i>Other Observation, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Room 203</i>					
			<i>Explanation : 1 Unit</i>					
Distribution								
Hot Wtr Piping/Pump	25%			2037	**	4	\$400	
No Component	75%							
Terminal Devices								
Fan Coil Unit/Heat	15%			2029	\$118,000	1	\$1,600	
Unit Heater - Steam	10%			2029	\$18,000	4	\$300	
No Component	75%							
Air Conditioning								
Energy Source								
Electricity	100%			2037	**	1		
Conversion Equipment								
Interior Pkg Unit - Cooling	20%			2027	\$100,400	2	\$400	
			<i>R-22 Refrigerant, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Room 202</i>					
Window/Wall Unit	10%			2026	\$12,000	1		
No Component	70%							
Ventilation								
Distribution								
Ductwork/Diffusers	20%			LIFE	**	2-5	\$3,600	
No Component	80%							
Exhaust Fans								
Interior	20%			2029	\$28,200	2	\$200	
No Component	80%							
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2029	\$407,700	1		
Water Heater With Tanks								
Gas Fired	100%			2027	\$16,700	2		
Sanitary Piping								
Cast Iron	100%			LIFE	**	1		
Storm Drain Piping								
Cast Iron	100%			LIFE	**	1		
Fixtures								
Generic	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CASTLETON DEPOT
Asset # : 14718

Mechanical		Current Repair		Future Replacement		Maintenance			
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Fire Suppression	Sprinkler								
	Generic	100%			2029	\$439,000	1-2	\$9,100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : COURT SQUARE-GARAGE
Address : COURT SQUARE AND THOMSON AVE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0123.000 / 2422 **Yr Built/Renovated** : 1989 /
Area Sq Ft : 241,855 **Project Type** : HIGHWAYS
Date of Survey : 11-Mar-2022 **Landmark Status** : NONE
Areas Surveyed : Basement, Roof, Floors 1,2,3,4
Block : 83 **Lot** : 18 **BIN** : 4000699

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$309,900	\$441,900
Interior Architecture	\$1,806,600	\$710,600
Electrical	\$343,000	\$1,009,400
Mechanical		\$1,925,400
Total	\$2,459,500	\$4,087,300
Importance Code A	\$309,900	\$626,400
Importance Code B	\$1,873,100	\$3,461,000
Importance Code C	\$276,500	
Total	\$2,459,500	\$4,087,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$119,800		\$4,400	
Interior Architecture	\$67,300			\$800
Electrical	\$2,600	\$5,000	\$3,100	\$1,800
Mechanical	\$15,900	\$11,800	\$55,500	\$7,300
Site Enclosure	\$42,800			
Site Pavements	\$54,200			
Elevators/Escalators	\$14,400	\$14,400	\$14,400	\$14,400
Total	\$317,200	\$31,100	\$77,500	\$24,300
Importance Code A	\$119,800	\$700	\$4,900	\$700
Importance Code B	\$109,400	\$30,500	\$72,600	\$23,600
Importance Code C	\$87,900			
Total	\$317,200	\$31,100	\$77,500	\$24,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
COURT SQUARE-GARAGE
Asset # : 2422

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Cast in Place Concrete	45%	2-4	\$309,900	LIFE	**	5	\$265,200	
<i>Paint Peeling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout Horizontal Bands And Southwest, South East Towers</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southwest Facade</i>								
Cast in Place Concrete	30%			LIFE	**	5	\$176,800	
Concrete Masonry Unit	2%	Now	\$6,200	LIFE	**	5	\$1,500	
<i>Diagonal Cracks, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Stair Roof Bulkheads</i>								
Masonry: Brick	15%	Now	\$28,400	LIFE	**	5	\$17,700	
<i>Diagonal Cracks, Extent : Severe, Area Affected : 1%</i>								
<i>Location : Southeast Corner By Stair Exit Door</i>								
<i>Vertical Cracks, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Southeast Tower</i>								
Metal Sect. OHD	1%	Now	\$41,800	2053	**	5	\$1,800	
<i>Unit Inoperable, Extent : Severe, Area Affected : 90%</i>								
<i>Location : Both Garage Entrances</i>								
Metal: Cage/Fence	5%			2046	**	5	\$25,800	
Window Wall	2%			2043	**	5	\$8,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Stair Bulkhead On Roof</i>								
<i>Explanation : Glass Wall</i>								
Windows								
Aluminum	100%			2049	**	5		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof Level</i>								
<i>Explanation : Stair Tower Windows</i>								
Parapets								
Cast in Place Concrete	95%	Now	\$8,600	LIFE	**	5	\$20,300	
<i>Diagonal Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Metal Rail	5%	Now	\$4,100	2046	**	5	\$700	
<i>Corrosion/Rusting, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Rail Supports</i>								
<i>Deteriorated Finish, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Metal Cable Rails At Roof</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
COURT SQUARE-GARAGE
Asset # : 2422

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Roof								
Cast in Place Concrete	90%	Now	\$14,300	LIFE	**			
<i>Expansion Joint Failure, Extent : Severe, Area Affected : 5%</i>								
<i>Location : All Stair Locations, Building Corners</i>								
Copper/Terne	5%			2061	**	10	\$500	
Single Ply Membrane	5%	0-2	\$3,600	2033	\$3,600			1
<i>Miss/Damaged Flashings, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Step Flashing At Stair Bulkheads And Membrane</i>								
<i>Ponding, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Stair Bulkheads</i>								
Interior								
Floors								
Cast in Place Concrete	97%	0-2	\$1,349,400	LIFE	**	5	\$710,600	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : West Car Entry Area</i>								
<i>Ponding, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Southeast Corner Of Third, Second And 1st Levels</i>								
Ceramic Tile	1%			2036	**	5	\$3,400	
Vinyl Tile	2%	0-2	\$36,100	2028	\$180,700	3	\$2,500	
<i>Worn/Eroded, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Office</i>								
Interior Walls								
Cast in Place Concrete	18%			LIFE	**			
Ceramic Tile	2%	Now	\$118,500	2048	**	5	\$1,100	
<i>Adhesion Failure, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Bathrooms</i>								
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Bathrooms</i>								
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Bathrooms</i>								
Concrete Masonry Unit	78%	Now	\$158,000	LIFE	**	5	\$34,400	
<i>Water Penetration, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Southeast Stair To Basement Level.</i>								
Gypsum Board	2%			LIFE	**	5	\$1,300	
Ceilings								
AcousTileSusp.Lay-In	2%	4+	\$29,500	2038	**	5	\$3,000	
<i>Worn/Eroded, Extent : Light, Area Affected : 100%</i>								
<i>Location : Managers Office</i>								
Exposed Struc: Concrete	98%			LIFE	**	5	\$46,400	
Site Enclosure								
Fence/Gates								
Chain Link	100%			2053	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
COURT SQUARE-GARAGE
Asset # : 2422

Architecture		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Site Enclosure								
Free Standing Walls								
Cast in Place Concrete	5%	0-2	\$10,900	2053		**		
	<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Missing Deteriorated Joints At Cast Stone Copings</i>							
Masonry: Brick	83%	Now	\$32,000	2043		**		
	<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Northeast Corner</i>							
	<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 70%</i>							
	<i>Location : Throughout</i>							
	<i>Spalling, Extent : Severe, Area Affected : 40%</i>							
	<i>Location : Throughout</i>							
Masonry: Brick	12%			2063		**		
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%	Now	\$9,100	2038		**		
	<i>Cracking/Crumbling, Extent : Light, Area Affected : 2%</i>							
	<i>Location : West Side Of Building</i>							
On-Site Walkways								
Cast in Place Concrete	100%	Now	\$45,100	2046		**		
	<i>Misaligned/Bulging, Extent : Severe, Area Affected : 10%</i>							
	<i>Location : Southeast Base Landing Connecting To Sidewalk</i>							
Electrical								
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2033	\$44,200	5	\$1,000	
	<i>Other Observation, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Electrical Room</i>							
	<i>Explanation : One 1,200 Ampere Main Disconnect Switch</i>							
Switchgear / Switchboard								
Fused Disc Sw	100%			2033	\$254,000	5	\$1,000	
Raceway								
Conduit	100%			2033	\$51,900	1		
Panelboards								
Fused Disc Sw	5%			2032	\$7,800	5	\$300	
Molded Case Bkrs	95%			2032	\$148,100	5	\$6,000	
Wiring								
Thermoplastic	100%			2033	\$106,700	1		
Motor Controllers								
Locally Mounted	100%			2031	\$448,700	5	\$1,600	
Ground								
Grounding Devices								
Generic	100%			LIFE		**	5	\$3,600

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
COURT SQUARE-GARAGE
Asset # : 2422

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Interior Lighting								
HID	2%			2028	\$55,900	10	\$200	
LED	98%			2041	**			
Egress Lighting								
Exit, LED	30%			2068	**	1		
Exit, Service	70%			2041	**	1		
Exterior Lighting								
HID	18%			2028	\$198,400	10	\$100	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : At The Roof</i>								
<i>Explanation : Lighting Pools</i>								
LED	2%			2041	**			
No Component	80%							
Alarm								
Security System								
No Component	80%							
Generic	20%			2028	\$88,700	1	\$18,100	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Exterior And Interior</i>								
<i>Explanation : Cameras Security System</i>								
Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Electricity	100%			2043	**	1		
Conversion Equipment								
Radiant Heater	3%			2033	\$184,400	2	\$3,400	
<i>Other Observation, Extent : Light, Area Affected : 3%</i>								
<i>Location : 1st Level</i>								
<i>Explanation : Management Office And Sprinkler Room Only</i>								
No Component	97%							
Terminal Devices								
Fan Coil Unit/Heat	3%			2033	\$5,300	1	\$2,300	
No Component	97%							
Air Conditioning								
Energy Source								
Electricity	100%			2041	**	1		
Conversion Equipment								
Window/Wall Unit	2%			2028	\$17,900	1		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : 1st Level</i>								
<i>Explanation : Management Office Only</i>								
No Component	98%							
Ventilation								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
COURT SQUARE-GARAGE
Asset # : 2422

Mechanical System Component Type	Current Repair		Future Replacement		Maintenance		Priority
	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Ventilation							
Distribution							
Ductwork/Diffusers	2%			LIFE	**	2-5	\$2,700
No Component	98%						
Exhaust Fans							
Interior	2%			2033	\$21,000	2	\$200
No Component	98%						
Plumbing							
H/C Water Piping							
Brass/Copper	3%			2043	**	1	
No Component	97%						
Water Heater With Tanks							
Electric	2%			2026	\$500	4	
No Component	98%						
Sanitary Piping							
Cast Iron	100%			LIFE	**	1	
Storm Drain Piping							
Cast Iron	100%			LIFE	**	1	
Sump Pump(s)							
Submersible	100%			2026	\$7,300	4	\$7,700
Fixtures							
Generic	100%						
Vertical Transport							
Elevators							
Hydraulic	100%			LIFE	**		
Fire Suppression							
Standpipe							
Generic	100%			2033	\$1,087,600	1-5	\$121,900
Sprinkler							
No Component	80%						
Generic	20%			2033	\$653,300	1-2	\$13,500

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DELANCEY - ESSEX GARAGE
Address : 107 ESSEX STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0205.000 / 14318 **Yr Built/Renovated** : 1972 /
Area Sq Ft : 130,000 **Project Type** : HIGHWAYS
Date of Survey : 21-Sep-2021 **Landmark Status** : NONE
Areas Surveyed : Basement, Roof, Floors 1,2,3,4,5,6
Block : 410 **Lot** : 38 **BIN** : 1005326

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$106,900	\$53,800
Interior Architecture	\$95,500	\$490,800
Electrical	\$402,000	\$1,133,000
Mechanical	\$66,500	\$74,200
Total	\$670,900	\$1,751,800
Importance Code A	\$106,900	\$149,100
Importance Code B	\$564,000	\$1,602,800
Total	\$670,900	\$1,751,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$5,300		\$6,700	\$100
Interior Architecture	\$1,800		\$400	
Electrical	\$15,000	\$13,900	\$33,800	\$14,600
Mechanical	\$5,300		\$15,700	
Elevators/Escalators	\$15,400	\$15,400	\$15,400	\$15,400
Total	\$42,700	\$29,200	\$72,100	\$30,100
Importance Code A	\$5,300		\$8,400	\$100
Importance Code B	\$37,400	\$29,200	\$63,600	\$29,900
Importance Code C				
Total	\$42,700	\$29,200	\$72,100	\$30,100



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
DELANCEY - ESSEX GARAGE
Asset # : 14318

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Cast in Place Concrete	10%			LIFE	**	5	\$25,100	
Masonry: Brick	15%			LIFE	**	5	\$7,500	
<i>Painted Surfaces, Extent : Light, Area Affected : 100%</i>								
<i>Location : Facades</i>								
Metal Panel	3%			2053	**	5-10	\$10,400	
Metal Coiling Doors	5%			2046	**	5	\$7,800	
Metal: Cage/Fence	30%			2050	**	5	\$65,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East And West Elevations</i>								
<i>Explanation : This Is Actually A Steel Cable Screen System</i>								
Pre-Cast Concrete	33%			LIFE	**	5	\$53,800	
Window Wall	4%			2053	**	5	\$7,500	
Windows								
Aluminum	8%			2049	**	5	\$200	
Metal Louvers	2%			2042	**	10	\$400	
No Component	90%							
Parapets								
Cast in Place Concrete	20%			LIFE	**	5	\$6,200	
Masonry: Brick	5%			LIFE	**	5	\$200	
Metal Panel	2%			2053	**	5	\$200	
Metal: Cage/Fence	10%			2046	**	5-10	\$2,300	
Pre-Cast Concrete	63%			LIFE	**	5	\$11,900	
Roof								
Traffic Topping	100%			2038	**	10	\$106,900	
Soffits								
Stucco Cement	100%			2046	**	5		
Interior								
Floors								
Cast in Place Concrete	98%			LIFE	**	5	\$379,500	
<i>Other Observation, Extent : Light, Area Affected : 75%</i>								
<i>Location : Floors And Ramps</i>								
<i>Explanation : Covered With Light Epoxy Traffic Coating</i>								
Vinyl Tile	2%			2028		3	\$1,300	
Interior Walls								
Cast in Place Concrete	92%			LIFE	**			
Concrete Masonry Unit	5%			LIFE	**	5	\$300	
Masonry: Brick	3%			LIFE	**			
Ceilings								
AcousTile,Adhered	2%			2031		5	\$3,500	
Exposed Struc: Concrete	98%			LIFE	**	5	\$27,100	
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2046	**			
Parking/Driveway								
Cast in Place Concrete	100%			2046	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DELANCEY - ESSEX GARAGE
Asset # : 14318

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Molded Case Bkrs	100%			2033	\$95,300	5	\$3,400	
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Electrical Room</i>						
		<i>Explanation : One 1,000 Ampere Main Disconnect Switch</i>						
Switchgear / Switchboard								
Molded Case Bkrs	100%			2033	\$95,300	5	\$3,400	
Raceway								
Conduit	100%			2033	\$17,300	1		
Panelboards								
Molded Case Bkrs	100%			2032	\$58,500	5	\$3,400	
Wiring								
Thermoplastic	100%			2033	\$35,300	1		
Motor Controllers								
Locally Mounted	100%			2031	\$145,800	5	\$900	
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$1,900	
Lighting								
Interior Lighting								
LED	100%			2033	\$738,200			
Egress Lighting								
Emergency, Battery	50%			2028	\$96,900	10	\$14,300	
Exit, Battery	50%			2028	\$66,700	10	\$4,000	
Exterior Lighting								
LED	20%			2041	**			
No Component	80%							
Alarm								
Security System								
Generic	50%			2028	\$119,200	1	\$24,300	
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Front And Back Of The Building</i>						
		<i>Explanation : CCTV Surveillance Cameras Are Functional</i>						
Generic	50%			2028	\$119,200	1	\$24,300	
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Throughout The Building</i>						
		<i>Explanation : Intrusion System</i>						
Fire/Smoke Detection								
Generic, Digital	100%			2041	**	1-3	\$82,500	
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Throughout The Building</i>						
		<i>Explanation : Manual Pull Station, Strobe Lights And Smoke Detectors</i>						

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DELANCEY - ESSEX GARAGE
Asset # : 14318

Mechanical	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Heating							
Energy Source							
Electricity	100%			2043	**	1	
Conversion Equipment							
Radiant Heater	3%			2033	\$900	2	
		<i>Other Observation, Extent : Light, Area Affected : 3%</i>					
		<i>Location : Office On 1st Level</i>					
		<i>Explanation : 1 Unit. Only The Office Has This Heating Device</i>					
No Component	97%						
Air Conditioning							
Energy Source							
Electricity	100%			2041	**	1	
Conversion Equipment							
Window/Wall Unit	3%			2028	\$13,100	1	
		<i>Other Observation, Extent : Light, Area Affected : 3%</i>					
		<i>Location : Management Office</i>					
		<i>Explanation : 1 Unit</i>					
No Component	97%						
Ventilation							
Distribution							
No Component	5%						
No Component	95%						
Exhaust Fans							
No Component	5%						
No Component	95%						
Plumbing							
H/C Water Piping							
Brass/Copper	5%			2033	\$74,200	1	
No Component	95%						
Sanitary Piping							
Cast Iron	5%			LIFE	**	1	
No Component	95%						
Storm Drain Piping							
Cast Iron	100%			LIFE	**	1	
Sump Pump(s)							
Submersible	100%			2026	\$3,900	4	\$4,100
Sewage Ejector(s)							
Electric	100%			2028	\$66,500	4	\$5,200
Fixtures							
Generic	100%						
Vertical Transport							
Elevators							
Geared Traction	100%			LIFE	**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
		<i>Location : Parking Levels 1 Through 6</i>					
		<i>Explanation : 2 Units. 1 New, 1 Abandoned</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DOT EMERGENCY RESPONSE UNIT
Address : 5-40 44TH DRIVE @ VERNON BLVD AND EAST RIVER
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0218.000 / 14716 **Yr Built/Renovated** : 1931 / 2013
Area Sq Ft : 20,000 **Project Type** : HIGHWAYS
Date of Survey : 11-Mar-2022 **Landmark Status** : NONE
Areas Surveyed : Floors 1
Block : 24 **Lot** : 7 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$1,041,500	
Interior Architecture	\$1,830,700	\$59,200
Electrical	\$105,200	
Site Enclosure	\$405,300	
Site Pavements	\$163,900	
Total	\$3,546,500	\$59,200
Importance Code A	\$1,041,500	
Importance Code B	\$1,141,000	\$59,200
Importance Code C	\$1,364,000	
Total	\$3,546,500	\$59,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$58,600			
Interior Architecture	\$9,300			\$200
Electrical	\$200	\$300	\$19,300	\$300
Mechanical	\$300	\$1,200	\$1,000	\$400
Total	\$68,400	\$1,400	\$20,300	\$800
Importance Code A	\$58,700	\$100	\$400	\$100
Importance Code B	\$9,700	\$1,300	\$19,900	\$700
Importance Code C				
Total	\$68,400	\$1,400	\$20,300	\$800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
DOT EMERGENCY RESPONSE UNIT
Asset # : 14716

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Masonry: Brick	60%	Now	\$487,900	LIFE	**	5	\$15,200	1
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Diagonal Cracks, Extent : Severe, Area Affected : 5%</i>								
<i>Location : At Rear Walls</i>								
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Vegetation Growth, Extent : Severe, Area Affected : 5%</i>								
<i>Location : At North Garages</i>								
<i>Vertical Cracks, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Between Garage Doors</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
Metal Coiling Doors	40%	Now	\$421,800	2046	**	5	\$15,800	1
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 75%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Garage Doors</i>								
<i>Explanation : Garage Doors Completely Missing</i>								
Windows								
Steel	95%	Now	\$42,800	2058	**	5	\$3,600	1
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Vinyl	5%			2046	**	5		
Parapets								
Cast Stone/Terra Cotta	10%	Now	\$15,800	LIFE	**	5	\$2,300	1
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
Masonry: Brick	90%	Now	\$131,800	LIFE	**	5	\$2,700	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
Roof								
No Component	5%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Sand And Gravel Storage</i>								
<i>Explanation : Roof Not Replaced After It Was Removed Due To Structural Damage</i>								
Not Accessible	95%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Entire Roof</i>								
<i>Explanation : Although Not Accessible, Roof Is Assumed To Be In Poor Condition</i>								
Interior								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT EMERGENCY RESPONSE UNIT
Asset # : 14716

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Interior								
Floors								
Cast in Place Concrete	90%	Now	\$674,600	LIFE	**	5	\$59,200	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Quarry Tile	5%			2046	**	5	\$2,300	
Vinyl Tile	5%	2-4	\$2,000	2033	\$40,600	3	\$600	
<i>Uneven Substrate, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Computer Room</i>								
Interior Walls								
Gypsum Board	10%			LIFE	**	5	\$1,400	
Masonry: Brick	90%	Now	\$794,800	LIFE	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
Ceilings								
AcousTileSusp.Lay-In	5%	Now	\$1,200	2046	**	5	\$800	
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Entry To Break Room</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Breakroom Foyer</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Break Room</i>								
<i>Explanation : Break Room</i>								
AcousTileSusp.Lay-In	5%	Now	\$4,900	2046	**	5	\$800	
<i>Loose/Miss Fasteners, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Office, Office Lounge And Bathroom</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Offices And Office Lounge Area</i>								
Exposed Struc: Wood	90%	2-4	\$361,200	LIFE	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Site Enclosure								
Fence/Gates								
Chain Link	100%			2053	**			
Free Standing Walls								
Masonry: Brick	100%	Now	\$405,300	2063	**			
<i>Impact Damage, Extent : Severe, Area Affected : 100%</i>								
<i>Location : West Entrance</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2046	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT EMERGENCY RESPONSE UNIT
Asset # : 14716

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Site Pavements

Parking/Driveway
Asphalt

100% Now \$163,900 2036 * *
Cracking/Crumbling, Extent : Severe, Area Affected : 30%
Location : Throughout
Ponding, Extent : Severe, Area Affected : 15%
Location : Entire Drive

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Service Equipment
Molded Case Bkrs

100% 2053 * * 5 \$500
Other Observation, Extent : Light, Area Affected : 100%
Location : Electrical Room
Explanation : One 200 Ampere Main Disconnect Switch

Raceway

Conduit 40% 2053 * * 1
 Conduit 60% 2033 \$2,600 1

Panelboards

Fused Disc Sw 5% 2049 * * 5
 Molded Case Bkrs 50% 2049 * * 5 \$300
 Molded Case Bkrs 45% 2032 \$4,400 5 \$200

Wiring

Thermoplastic 60% 2053 * * 1
 Thermoplastic 40% 2033 \$3,500 1

Motor Controllers

Locally Mounted 100% 2046 * * 5 \$100

Ground

Grounding Devices

Generic 100% LIFE * * 5 \$300

Lighting

Interior Lighting

Fluorescent 20% 2041 * * 10 \$3,700

T-8 Lamps And Fixtures, Extent : Moderate, Area Affected : 100%
Location : Offices

Fluorescent 76% 2028 \$105,200 10 \$13,900

T-12 Lamps And Fixtures, Extent : Light, Area Affected : 78%
Location : Throughout The Building

Incandescent 2% 2028 \$2,500 2

LED 2% 2041 * *

Other Observation, Extent : N/A, Area Affected : 100%

Location : Office

Explanation : LED Light

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT EMERGENCY RESPONSE UNIT
Asset # : 14716

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Egress Lighting								
Emergency, Battery	50%			2038	**	10	\$2,400	
Exit, Service	50%			2033	\$3,300	1		
<hr/>								
Exterior Lighting								
LED	20%			2041	**			
No Component	80%							
<hr/>								
Alarm								
Security System								
No Component	80%							
Generic	20%			2038	**	1	\$1,500	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Outside</i>								
<i>Explanation : CCTV Camera</i>								
<hr/>								
Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2059	**	1		
<hr/>								
Conversion Equipment								
Furnace	15%			2038	**	1	\$1,500	
No Component	85%							
<hr/>								
Terminal Devices								
Fan Coil Unit/Heat	30%			2041	**	1	\$1,900	
<i>Recent Installation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor</i>								
<hr/>								
No Component	70%							
<hr/>								
Air Conditioning								
Energy Source								
Electricity	100%			2049	**	1		
<hr/>								
Conversion Equipment								
Window/Wall Unit	20%			2031	\$14,800	1		
No Component	80%							
<hr/>								
Ventilation								
Distribution								
Ductwork/Diffusers	15%			LIFE	**	2-5	\$1,700	
No Component	85%							
<hr/>								
Exhaust Fans								
Interior	15%			2041	**	2	\$100	
Wall Unit	5%			2028	\$400	2		
No Component	80%							
<hr/>								
Plumbing								
H/C Water Piping								
Brass/Copper	15%			2059	**	1		
No Component	85%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT EMERGENCY RESPONSE UNIT
Asset # : 14716

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Plumbing								
Water Heater With Tanks								
	Gas Fired	15%			2032	\$2,500	2	
	No Component	85%						
Sanitary Piping								
	Cast Iron	15%			LIFE	**	1	
	No Component	85%						
Storm Drain Piping								
	Cast Iron	100%			LIFE	**	1	
Sump Pump(s)								
	Submersible	100%			2027	\$600	4	\$600
Fixtures								
	Generic	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DOT SIDEWALK & INSPECTION MGMT. CITYWIDE CONCRETE PROGRAM
Address : 672 WEST 158TH STREET UNDER RIVERSIDE DRIVE WEST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0350.000 / 15364 **Yr Built/Renovated** :
Area Sq Ft : 14,700 **Project Type** : HIGHWAYS
Date of Survey : 30-Jun-2022 **Landmark Status** : NONE
Areas Surveyed : Floors 1,2
Block : **Lot** : **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$584,200	\$166,600
Interior Architecture	\$2,304,600	
Electrical	\$101,700	
Total	\$2,990,400	\$166,600
Importance Code A	\$584,200	\$166,600
Importance Code B	\$1,677,500	
Importance Code C	\$728,800	
Total	\$2,990,400	\$166,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$14,600			
Interior Architecture	\$51,700		\$1,200	\$800
Electrical	\$20,400	\$500	\$28,600	\$500
Mechanical	\$5,900		\$100	
Total	\$92,500	\$500	\$29,900	\$1,400
Importance Code A	\$16,400		\$300	
Importance Code B	\$25,100	\$500	\$29,600	\$1,400
Importance Code C	\$51,000			
Total	\$92,500	\$500	\$29,900	\$1,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT SIDEWALK & INSPECTION MGMT. CITYWIDE CONCRETE PROGRAM
Asset # : 15364

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Cast in Place Concrete	100%	Now	\$584,200	LIFE	**	5	\$166,600	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Adjacent Parking Lot</i>								
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Adjacent Parking Lot</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Adjacent Parking Lot</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Rear Of Building By Parking Lot</i>								
<i>Vertical Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Adjacent Parking Lot Near Street</i>								
<hr/>								
Windows								
Aluminum	100%	Now	\$14,600	2041	**	5	\$700	
<i>Glazing Clouded, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Second Floor Lockers, Bathrooms And Offices</i>								
<i>Caulking Deteriorated, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Windows Throughout</i>								
<hr/>								
Parapets								
Not Accessible	100%							
<hr/>								
Roof								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Roof</i>								
<i>Explanation : Riverside Drive Roadway</i>								
<hr/>								
Interior								
Floors								
Cast in Place Concrete	65%	Now	\$281,400	LIFE	**	5	\$37,100	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : 1st Floor Storage</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : 1st Floor Storage</i>								
Ceramic Tile	5%			2036	**	5	\$1,300	
Vinyl Tile	25%	Now	\$175,800	2043	**	3	\$2,400	
<i>Adhesion Failure, Extent : Severe, Area Affected : 50%</i>								
<i>Location : 2nd Floor</i>								
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 25%</i>								
<i>Location : 2nd Floor</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : 2nd Floor</i>								
Wood	5%			2048	**	5	\$2,400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT SIDEWALK & INSPECTION MGMT. CITYWIDE CONCRETE PROGRAM
Asset # : 15364

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Interior Walls								
Cast in Place Concrete	70%	Now	\$728,800	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : 1st Floor Storage</i>								
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : 1st Floor Storage</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : 1st Floor Storage</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : 1st Floor Storage</i>								
<i>Vertical Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : 1st Floor Storage</i>								
Ceramic Tile	5%	Now	\$18,800	2036		**	5	\$900
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Locker Rooms And Bathrooms</i>								
<i>Loose/Delam Surface, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Locker Rooms And Bathrooms</i>								
Concrete Masonry Unit	20%	Now	\$32,200	LIFE		**	5	\$2,800
<i>Vertical Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : 2nd Floor</i>								
Plywood/Hardboard	5%			LIFE		**		
Ceilings								
AcousTileSusp.Lay-In	20%	Now	\$80,700	2053		**	5	\$2,500
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout 2nd Floor</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout 2nd Floor</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout 2nd Floor</i>								
Exposed Struc: Concrete	55%	Now	\$600,200	LIFE		**	5	\$2,100
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : 1st Floor Storage</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : 1st Floor Storage</i>								
Exposed Struc: Steel	25%	Now	\$437,600	LIFE		**		
<i>Corrosion/Rusting, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : 1st Floor Storage And 2nd Floor</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : 2nd Floor</i>								
Site Enclosure								
Fence/Gates								
Chain Link	100%			2063		**		
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2046		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT SIDEWALK & INSPECTION MGMT. CITYWIDE CONCRETE PROGRAM
Asset # : 15364

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Site Pavements

On-Site Walkways

Asphalt

100%

2048

* *

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Service Equipment

Molded Case Bkrs

100%

2033

\$31,800

5

\$400

*Other Observation, Extent : N/A, Area Affected : 100%**Location : Electrical Room**Explanation : Main Service Disconnect Switch Rated At 800 Amperes.*

Switchgear / Switchboard

Molded Case Bkrs

100%

2033

\$31,800

5

\$400

Raceway

Conduit

100%

2033

\$4,300

1

Panelboards

Molded Case Bkrs

100%

2-4

\$9,700

2058

* *

5

\$200

*Enclosure Corroded, Extent : Moderate, Area Affected : 100%**Location : Throughout The Building*

Wiring

Thermoplastic

100%

2033

\$8,800

1

Ground

Grounding Devices

Generic

100%

0-2

\$10,200

LIFE

* *

5

\$200

*Corroded, Extent : Moderate, Area Affected : 100%**Location : Electrical Room*

Lighting

Interior Lighting

Fluorescent

80%

Now

\$81,400

2043

* *

*Malfunctioning, Extent : Severe, Area Affected : 100%**Location : Throughout The Building*

Fluorescent

20%

0-2

\$20,300

2043

* *

*Inadequate Lighting Level, Extent : Moderate, Area Affected : 100%**Location : Throughout The Building*

Egress Lighting

Emergency, Battery

100%

2028

\$24,100

10

\$3,500

Exterior Lighting

LED

20%

2033

\$15,400

No Component

80%

Alarm

Security System

Generic

100%

2033

\$27,000

1

\$5,500

*Other Observation, Extent : N/A, Area Affected : 100%**Location : Throughout The Building**Explanation : CCTV Surveillance Cameras*

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT SIDEWALK & INSPECTION MGMT. CITYWIDE CONCRETE PROGRAM
Asset # : 15364

Mechanical System Component Type	Current Repair			Future Replacement		Maintenance		Priority
	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Electricity	5%			2033		1		
No Component	95%							
<hr/>								
Conversion Equipment								
Radiant Heater	5%	0-2	\$1,900	2043	**	2	\$300	
			<i>Abandoned in Place, Extent : Severe, Area Affected : 100%</i>					
			<i>Location : 1 Unit In Storage Room</i>					
No Component	95%							
<hr/>								
Controls								
Electrical	100%			2026	\$4,000			
<hr/>								
Plumbing								
H/C Water Piping								
Not Accessible	100%							
<hr/>								
Sanitary Piping								
Cast Iron	10%			LIFE	**	1		
No Component	90%							
<hr/>								
Storm Drain Piping								
Cast Iron	100%			LIFE	**	1		
<hr/>								
Fixtures								
Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FLATLANDS AVENUE YARD MAIN BUILDING
Address : 6080 FLATLANDS AVE.
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0125.000 / 1000 **Yr Built/Renovated** : 1939 /
Area Sq Ft : 20,821 **Project Type** : HIGHWAYS
Date of Survey : 08-May-2024 **Landmark Status** : NONE
Areas Surveyed : Basement, Roof, Floors 1,Mez
Block : 8012 **Lot** : 400 **BIN** : 3325350

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$585,300	
Interior Architecture	\$573,800	\$63,100
Mechanical	\$113,000	\$621,300
Site Pavements	\$155,800	
Total	\$1,427,900	\$684,400
Importance Code A	\$585,300	\$177,200
Importance Code B	\$356,500	\$507,100
Importance Code C	\$486,200	
Total	\$1,427,900	\$684,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$68,100			
Interior Architecture	\$10,700		\$300	\$200
Electrical	\$7,500	\$800	\$800	\$1,000
Mechanical	\$15,200	\$3,100	\$4,600	\$3,100
Site Enclosure	\$2,200			
Total	\$103,700	\$3,900	\$5,700	\$4,300
Importance Code A	\$70,200	\$2,100	\$2,100	\$2,100
Importance Code B	\$32,600	\$1,800	\$3,700	\$2,200
Importance Code C	\$900			
Total	\$103,700	\$3,900	\$5,700	\$4,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATLANDS AVENUE YARD MAIN BUILDING
Asset # : 1000

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Masonry: Brick	87%	Now	\$462,500	LIFE	**	5	\$28,800	
<i>Diagonal Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : At Windows Opening</i>								
<i>Horizontal Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
<i>Rusting Masonry Supt, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : At Masonry Openings</i>								
<i>Water Penetration, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout Window Openings</i>								
Metal Coiling Doors	10%	2-4	\$17,200	2040	**	5	\$5,200	
<i>Deformed/Dented, Extent : Light, Area Affected : 5%</i>								
<i>Location : Rear Door</i>								
Stucco Cement	3%	Now	\$54,800	2055	**	5	\$1,200	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Bulkhead</i>								
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Bulkhead</i>								
<i>Worn/Eroded, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Bulkhead</i>								
Windows								
Aluminum	95%	Now	\$13,300	2043	**	5	\$2,900	
<i>Glazing Broken/Cracked, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Office And Garage</i>								
Metal Louvers	5%	Now	\$800	2038	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Basement Mechanical Room</i>								
Parapets								
Masonry: Brick	90%	Now	\$28,100	LIFE	**	5	\$2,300	
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Interior Face</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Inside Face</i>								
Masonry: Limestone	10%			LIFE	**	5-10	\$3,100	
Roof								
Built-Up (BUR)	10%	Now	\$4,900	2030	\$48,500			
<i>Gravel/Slag Surface, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Flat Section</i>								
<i>Miss/Damaged Flashings, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Throughout Flat Roof Area</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Garage</i>								
Metal Panel	87%			2048	**	10	\$67,900	
Roll Roofing	3%			2031	\$8,100	5	\$2,100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATLANDS AVENUE YARD MAIN BUILDING
Asset # : 1000

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Floors								
Cast in Place Concrete	93%	Now	\$119,800	LIFE	**	5	\$63,100	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Garage And Bulkhead Stair</i>								
Ceramic Tile	2%			2038	**	5	\$600	
Vinyl Tile	5%			2030	\$41,800	3	\$800	
Interior Walls								
Concrete Masonry Unit	5%			LIFE	**	5	\$1,100	
Glass: Single Pane	2%			LIFE	**	5	\$800	
Masonry: Brick	93%	Now	\$330,400	LIFE	**			
<i>Vertical Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Mezzanine Level</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Offices</i>								
Ceilings								
AcousTileSusp.Lay-In	5%	Now	\$500	2040	**	5	\$800	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Bathroom And Shower</i>								
Exposed Struc: Concrete	10%	Now	\$9,100	LIFE	**	5	\$500	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Exposed Struc: Steel	85%	Now	\$123,700	LIFE	**			
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Garage</i>								
Site Enclosure								
Fence/Gates								
Chain Link	100%			2045	**			
Retaining Walls								
Cast in Place Concrete	100%	0-2	\$2,200	2070	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2040	**			
On-Site Walkways								
Cast in Place Concrete	100%			2048	**			
Parking/Driveway								
Asphalt	100%	0-2	\$155,800	2038	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATLANDS AVENUE YARD MAIN BUILDING
Asset # : 1000

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment Fused Disc Sw	100%			2035	\$3,700	5	\$100	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : One Electrical Service Rated At 400 Amperes</i>								
Switchgear / Switchboard Molded Case Bkrs	100%			2035	\$31,800	5	\$500	
Raceway Conduit	100%			2035	\$4,300	1		
Panelboards								
Fused Disc Sw	5%			2034	\$1,000	5		
Molded Case Bkrs	90%			2034	\$17,500	5	\$500	
Molded Case Bkrs	5%			2057	**	5		
Wiring Thermoplastic	100%			2035	\$8,800	1		
Motor Controllers Locally Mounted	100%			2033	\$33,700	5	\$100	
Ground								
Grounding Devices Generic	100%			LIFE	**	5	\$600	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Basement</i>								
<i>Explanation : Water Main</i>								
Lighting								
Interior Lighting Fluorescent	30%			2030	\$43,200	10	\$5,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : T-8 Lamps</i>								
LED	70%			2040	**			
Egress Lighting Emergency, Battery	50%			2040	**	10	\$2,500	
Exit, Battery	50%			2030	\$11,700	10	\$700	
Exterior Lighting								
LED	20%			2043	**			
No Component	80%							
Alarm								
Security System Generic	100%			2035	\$38,200	1	\$7,800	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Outside Perimeter</i>								
<i>Explanation : Camera Monitored At 55 Water Street</i>								

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATLANDS AVENUE YARD MAIN BUILDING
Asset # : 1000

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2045	**	1		
Conversion Equipment								
Steam Boiler	100%			2033	\$177,200	1	\$20,600	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Basement</i>								
<i>Explanation : 2 Units. One Is Operational, The Other Is Under The Replacement Process.</i>								
Distribution								
Steam Piping/Pump	100%			2035	\$162,800			
Terminal Devices								
Convactor/Radiator	15%			2033	\$24,900	1	\$1,000	
Unit Heater - Steam	85%			2040	**	4	\$1,600	
Controls								
Electrical	100%			2028	\$113,000			
Air Conditioning								
Energy Source								
Electricity	100%			2043	**	1		
Conversion Equipment								
Window/Wall Unit	15%	0-2	\$6,900	2033	\$11,600	1		
<i>Not Energy Efficient, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Office Area</i>								
<i>On Extended Life, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Office Area</i>								
No Component	85%							
Ventilation								
Distribution								
Ductwork/Diffusers	20%			LIFE	**	2-5	\$3,700	
No Component	80%							
Exhaust Fans								
Roof	80%			2030	\$31,600	2	\$500	
Wall Unit	20%			2030	\$1,800	2	\$100	
Plumbing								
H/C Water Piping								
Brass/Copper	95%			2045	**	1		
Brass/Copper	5%	0-2	\$1,300	2045	**	1		
<i>Not Insulated, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Various Locations</i>								
Water Heater With Tanks								
Electric	50%			2030	\$34,600	4		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Basement Boiler Room</i>								
<i>Explanation : One 75 Gallon Unit</i>								
Gas Fired	50%			2033	\$25,000	2		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : The Rear Side Bathroom Of The Building</i>								
<i>Explanation : One 75 Gallon Unit</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
FLATLANDS AVENUE YARD MAIN BUILDING
Asset # : 1000**

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Plumbing								
Sanitary Piping Cast Iron	10%	Now	\$2,600	LIFE	**	1		
	<i>Blockage /Clogged, Extent : Moderate, Area Affected : 40%</i>							
	<i>Location : Boiler Room Entrance And Garage</i>							
Cast Iron	90%			LIFE	**	1		
Storm Drain Piping Cast Iron	100%			LIFE	**	1		
Sump Pump(s) Submersible	100%			2028	\$600	4	\$700	
Backflow Preventer Generic	100%			2043	**	1	\$1,300	
Fixtures Generic	100%							
Fire Suppression								
Sprinkler Generic	100%			2035	\$281,200	1-2	\$5,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FLATLANDS AVENUE YARD WAREHOUSE AND WELDING SHOP
Address : 6080 FLATLANDS AVE.
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0125.010 / 1036 **Yr Built/Renovated** : 1939 /
Area Sq Ft : 2,788 **Project Type** : HIGHWAYS
Date of Survey : 11-Oct-2023 **Landmark Status** : NONE
Areas Surveyed : Floors 1
Block : 8012 **Lot** : 400 **BIN** : 3325350

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture		\$85,200
Total		\$85,200
Importance Code A		\$85,200
Total		\$85,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$80,300			
Interior Architecture	\$77,800			\$300
Electrical				
Mechanical	\$100	\$100	\$100	\$100
Site Enclosure	\$1,100			
Total	\$159,300	\$100	\$100	\$400
Importance Code A	\$80,300			
Importance Code B	\$27,600	\$100	\$100	\$400
Importance Code C	\$51,400			
Total	\$159,300	\$100	\$100	\$400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATLANDS AVENUE YARD WAREHOUSE AND WELDING SHOP
Asset # : 1036

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Concrete Masonry Unit	10%			LIFE	**	5	\$900	
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Various Masonry Openings</i>								
<i>Explanation : Concrete Masonry Unit Infill Openings</i>								
Masonry: Brick	85%	Now	\$48,700	LIFE	**	5	\$6,100	1
<i>Horizontal Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Above Masonry Openings</i>								
<i>Rusting Masonry Supt, Extent : Severe, Area Affected : 50%</i>								
<i>Location : At Masonry Openings</i>								
<i>Vertical Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Corners</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Metal Coiling Doors	5%			2040	**	5	\$1,100	
Windows								
Aluminum	100%	Now	\$19,300	2051	**	5	\$400	
<i>Air Infiltration, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Glazing Broken/Cracked, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Parapets								
Masonry: Brick	95%	Now	\$3,300	LIFE	**	5	\$100	1
<i>Diagonal Cracks, Extent : Severe, Area Affected : 30%</i>								
<i>Location : At Corners</i>								
<i>Vertical Cracks, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Corners</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : Roof Inaccessible, Observations Carried Over</i>								
Masonry: Limestone	5%	Now		LIFE	**	5		
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : Roof Inaccessible, Observations Carried Over</i>								
Roof								
Built-Up (BUR)	100%	Now	\$8,500	2035	\$85,200			
<i>Water Penetration, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : Roof Inaccessible, Observations From Interior And Building Staff</i>								

Interior

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATLANDS AVENUE YARD WAREHOUSE AND WELDING SHOP
Asset # : 1036

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Floors								
Cast in Place Concrete	40%	Now	\$2,600	LIFE	**	5	\$3,400	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Vinyl Tile	60%	Now	\$6,400	2040	**	3	\$900	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Interior Walls								
Gypsum Board	20%			LIFE	**	5-10	\$5,300	
Masonry: Brick	80%	0-2	\$46,800	LIFE	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Ceilings								
AcousTileSusp.Lay-In	40%	Now	\$1,300	2040	**	5	\$800	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Exposed Struc: Concrete	60%	Now	\$17,300	LIFE	**	5	\$400	
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Site Enclosure								
Fence/Gates								
Chain Link	100%	Now	\$1,100	2055	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : East 76th Street</i>								
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2048	**			
On-Site Walkways								
Asphalt	100%			2038	**			
Parking/Driveway								
Asphalt	100%			2038	**			

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Raceway								
Conduit	100%			2035	\$4,300	1		
Panelboards								
Fused Disc Sw	50%			2034	\$4,900	5		
Molded Case Bkrs	50%			2043	**	5		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATLANDS AVENUE YARD WAREHOUSE AND WELDING SHOP

Asset # : 1036

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Wiring

Thermoplastic	50%			2045	**	1		
Thermoplastic	50%			2035	\$4,400	1		

Lighting

Interior Lighting

Fluorescent	100%			2035	\$19,300	10	\$2,600	
-------------	------	--	--	------	----------	----	---------	--

Other Observation, Extent : N/A, Area Affected : 100%

Location : Throughout The Building

Explanation : T-8 Lamps

Exterior Lighting

LED	20%			2035	\$2,900			
No Component	80%							

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Heating

Distribution

Steam Piping/Pump	100%			2045	**			
-------------------	------	--	--	------	----	--	--	--

Terminal Devices

Convactor/Radiator	100%			2040	**	1	\$900	
--------------------	------	--	--	------	----	---	-------	--

Air Conditioning

Energy Source

Electricity	100%			2043	**	1		
-------------	------	--	--	------	----	---	--	--

Conversion Equipment

Window/Wall Unit	20%			2030	\$2,100	1		
No Component	80%							

Ventilation

Exhaust Fans

Wall Unit	20%			2030	\$200	2		
No Component	80%							

Plumbing

H/C Water Piping

Brass/Copper	100%			2045	**	1		
--------------	------	--	--	------	----	---	--	--

Water Heater With Tanks

Electric	100%			2030	\$23,100	4		
----------	------	--	--	------	----------	---	--	--

Other Observation, Extent : N/A, Area Affected : 100%

Location : 2nd Floor

Explanation : One 60 Gallon Unit

Sanitary Piping

Cast Iron	100%			LIFE	**	1		
-----------	------	--	--	------	----	---	--	--

Storm Drain Piping

Cast Iron	100%			LIFE	**	1		
-----------	------	--	--	------	----	---	--	--

Fixtures

Generic	100%							
---------	------	--	--	--	--	--	--	--

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GLENDALE YARD BLDG. 7 (GARAGE AND STORAGE)
Address : 69-46 SYBILLA STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0126.020 / 2424 **Yr Built/Renovated** : 1928 / 2012
Area Sq Ft : 5,700 **Project Type** : HIGHWAYS
Date of Survey : 11-Dec-2020 **Landmark Status** : NONE
Areas Surveyed : Floors 1
Block : 3886 **Lot** : 558 **BIN** : 4095043

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$239,400	
Total	\$239,400	
Importance Code A	\$239,400	
Total	\$239,400	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$28,600	\$1,600	\$1,100	
Interior Architecture	\$46,700		\$400	
Electrical		\$5,900	\$100	
Mechanical	\$1,300	\$28,700	\$1,300	\$300
Site Pavements	\$22,900			
Total	\$99,500	\$36,300	\$2,900	\$300
Importance Code A	\$29,000	\$1,700	\$1,500	\$100
Importance Code B	\$45,700	\$34,600	\$1,400	\$300
Importance Code C	\$24,900			
Total	\$99,500	\$36,300	\$2,900	\$300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GLENDALE YARD BLDG. 7 (GARAGE AND STORAGE)

Asset # : 2424

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Alum/Vinyl Siding	10%			2052	**	10	\$400	
Cast in Place Concrete	15%	Now	\$10,200	LIFE	**	5	\$8,700	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Base Of Building</i>								
Concrete Masonry Unit	2%			LIFE	**	5	\$100	
Masonry: Brick	68%	Now	\$63,400	LIFE	**	5	\$7,900	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : East Facade</i>								
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Worn/Eroded, Extent : Severe, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
Metal Coiling Doors	5%			2037	**	5	\$1,800	
Windows								
Aluminum	100%			2048	**	5	\$2,300	
Parapets								
Masonry: Brick	95%	Now	\$175,900	LIFE	**	5	\$7,100	
<i>Horizontal Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : West Parapet Exterior</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
Metal Panel	5%			2052	**	5	\$1,500	
Roof								
Built-Up (BUR)	15%	Now	\$13,600	2037	**			
<i>Water Penetration, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Above Mens Locker Room And Staff Room</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : Roof Inaccessible, Observation As Per Visual Inspection And Building Occupant Account.</i>								
Modified Bitumen	85%	Now	\$4,800	2037	**			
<i>Water Penetration, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Roof Penetration Rear Storage Room</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : Roof Inaccessible, Observation As Per Visual Inspection And Building Occupant Account.</i>								
Interior								
Floors								
Cast in Place Concrete	75%	0-2	\$16,800	LIFE	**	5	\$22,100	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Apparatus Floor</i>								
Vinyl Tile	25%			2037	**	3	\$1,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
GLENDALE YARD BLDG. 7 (GARAGE AND STORAGE)**

Asset # : 2424

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Interior Walls								
Concrete Masonry Unit	5%			LIFE	**	5	\$500	
Gypsum Board	30%	0-2	\$2,000	LIFE	**	5	\$4,300	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Male Locker Room And Staff Room</i>								
Masonry: Brick	65%			LIFE	**			
<i>Diagonal Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Mens Locker Room</i>								
Ceilings								
AcousTileSusp.Lay-In	25%			2045	**	5	\$3,200	
Exposed Struc: Concrete	75%	Now	\$27,900	LIFE	**	5	\$1,500	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Apparatus Floor Ceiling</i>								
Site Pavements								
Parking/Driveway								
Asphalt	3%	Now	\$22,900	2041	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Overhead Door Apron</i>								
Asphalt	97%			2041	**			

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Raceway								
Conduit	100%			2052	**	1		
Panelboards								
Molded Case Bkrs	100%			2048	**	5	\$200	
Wiring								
Thermoplastic	100%			2052	**	1		
Lighting								
Interior Lighting								
Fluorescent	25%			2037	**	10	\$1,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Garage</i>								
<i>Explanation : T-5 Lamps</i>								
Fluorescent	75%			2037	**	10	\$3,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Offices</i>								
<i>Explanation : T-8 Lamps</i>								
Egress Lighting								
Emergency, Battery	50%			2037	**	10	\$700	
Exit, Service	50%			2037	**	1		
Exterior Lighting								
HID	20%			2037	**	10		
No Component	80%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
GLENDALE YARD BLDG. 7 (GARAGE AND STORAGE)**

Asset # : 2424

Mechanical System Component Type	Current Repair		Future Replacement		Maintenance		Priority
	% of Total	Fail Date (Years)	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating							
Energy Source							
Electricity	80%		2052	**	1		
Natural Gas	20%		2042	**	1		
Conversion Equipment							
Furnace	20%		2037	**	1	\$600	
Heat Pump Air Sourced	80%		2036	**	2	\$1,400	
Terminal Devices							
Fan Coil Unit/Heat	80%		2040	**	1	\$1,500	
No Component	20%						
Air Conditioning							
Energy Source							
Electricity	100%		2048	**	1		
Conversion Equipment							
Heat Pump Air Sourced	75%		2036	**	2	\$300	
Window/Wall Unit	25%		2027	\$5,300	1		
Terminal Devices							
Fan Coil - 2 Pipe	75%		2040	**	1	\$1,400	
No Component	25%						
Heat Rejection							
Dry Cooler	75%		2040	**	2	\$3,000	
No Component	25%						
Ventilation							
Exhaust Fans							
Wall Unit	40%		2032	\$1,000	2	\$100	
No Component	60%						
Plumbing							
H/C Water Piping							
Brass/Copper	100%		2052	**	1		
Water Heater With Tanks							
Electric	100%		2027	\$23,100	4		
Sanitary Piping							
Cast Iron	100%		LIFE	**	1		
Storm Drain Piping							
Cast Iron	100%		LIFE	**	1		
Fixtures							
Generic	100%						

Note: All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HARLEM RIVER BRIDGE SHOP GARAGE 1
Address : 300 W. 206TH STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0093.000 / 549 **Yr Built/Renovated** : 1958 / 2007
Area Sq Ft : 14,192 **Project Type** : HIGHWAYS
Date of Survey : 18-Nov-2021 **Landmark Status** : NONE
Areas Surveyed : Basement, Roof, Floors 1
Block : 2186 **Lot** : 9 **BIN** : 1081892

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$261,200	
Electrical		\$98,200
Total	\$261,200	\$98,200
Importance Code A	\$261,200	
Importance Code B		\$98,200
Total	\$261,200	\$98,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$57,400			\$2,800
Interior Architecture	\$1,500		\$9,300	\$400
Electrical	\$1,400	\$1,600	\$19,000	\$1,500
Mechanical	\$81,000	\$2,000	\$7,100	\$1,400
Site Enclosure	\$36,500			
Site Pavements	\$36,400			
Total	\$214,100	\$3,600	\$35,400	\$6,100
Importance Code A	\$86,500	\$700	\$700	\$3,500
Importance Code B	\$62,100	\$2,900	\$34,600	\$2,600
Importance Code C	\$65,500			
Total	\$214,100	\$3,600	\$35,400	\$6,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 1
Asset # : 549

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Masonry: Brick	82%	0-2	\$261,200	LIFE	**	5	\$32,500	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 20%</i>								
<i>Location : At Parapets Level</i>								
Metal Sect. OHD	15%			2046	**	5	\$18,600	
Pre-Cast Concrete	3%			LIFE	**	5	\$3,900	
Windows								
Aluminum	50%	Now	\$3,400	2049	**	5	\$700	
<i>Water Penetration, Extent : Light, Area Affected : 10%</i>								
<i>Location : Mechanical Locker Room</i>								
Fiberglass Panel	50%			2049	**	5	\$5,500	
Parapets								
Cast Stone/Terra Cotta	5%	Now	\$4,900	LIFE	**	5	\$2,100	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : North Facade</i>								
Masonry: Brick	95%			LIFE	**	5	\$5,200	
Roof								
Single Ply Membrane	100%	Now	\$39,900	2041	**			
<i>Water Penetration, Extent : Light, Area Affected : 10%</i>								
<i>Location : Locker Room And Corridors</i>								
Soffits								
Cement - Fiber Panel	100%			2038	**	10		
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Soffit</i>								
<i>Explanation : Paint Peeling</i>								
Interior								
Floors								
Cast in Place Concrete	10%			LIFE	**	5	\$4,600	
Terrazzo	5%			LIFE	**	5	\$800	
Traffic Topping	70%			2038	**	5	\$18,600	
Vinyl Tile	15%			2038	**	3	\$1,600	
Interior Walls								
Cast in Place Concrete	10%			LIFE	**			
Concrete Masonry Unit	75%			LIFE	**	5	\$5,700	
Glass: Single Pane	5%			LIFE	**	5	\$700	
Masonry: Brick	5%			LIFE	**			
SGFT/Glazed Masonry	5%			LIFE	**			
Ceilings								
AcousTileSusp.Lay-In	10%			2046	**	5	\$2,100	
Exposed Struc: Concrete	10%			LIFE	**	5	\$300	
Exposed Struc: Steel	70%			LIFE	**			
Gypsum Board	10%			LIFE	**	5	\$2,700	
Site Enclosure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 1
Asset # : 549

Architecture		Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost		
Site Enclosure									
Fence/Gates									
Aluminum Rail	100%	Now	\$36,500	2038	**	5	\$4,000		
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 20%</i>									
<i>Location : Loading Dock</i>									
<i>Corrosion/Rusting, Extent : Severe, Area Affected : 50%</i>									
<i>Location : Loading Dock</i>									
<i>Other Observation, Extent : Light, Area Affected : 100%</i>									
<i>Location : Loading Dock</i>									
<i>Explanation : Metal Safety Railing Along Loading Dock</i>									
Site Pavements									
Public Sidewalk									
Cast in Place Concrete	100%	Now	\$7,300	2046	**				
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 5%</i>									
<i>Location : West 200th Street</i>									
On-Site Walkways									
Cast in Place Concrete	100%	0-2	\$29,000	2053	**				
<i>Cracking/Crumbling, Extent : Light, Area Affected : 15%</i>									
<i>Location : Throughout Loading Dock, Near Steps</i>									
Parking/Driveway									
Cast in Place Concrete	100%			2046	**				
Electrical									
System Component Type		% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Under 600 Volts									
Service Equipment									
Fused Disc Sw	100%			2053	**	5	\$100		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>									
<i>Location : Electrical Room</i>									
<i>Explanation : One 2,500 Ampere Main Disconnect Switch</i>									
Switchgear / Switchboard									
Fused Disc Sw	100%			2053	**	5	\$100		
Raceway									
Conduit	100%			2053	**	1			
Panelboards									
Molded Case Bkrs	100%			2049	**	5	\$400		
Wiring									
Thermoplastic	100%			2053	**	1			
Motor Controllers									
Locally Mounted	100%			2046	**	5	\$100		
Ground									
Grounding Devices									
Generic	100%			LIFE	**	5	\$200		
Lighting									

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 1
Asset # : 549

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Interior Lighting Fluorescent	90%			2033	\$88,400	10	\$11,700	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
Fluorescent	10%			2033	\$9,800	10	\$1,300	
<i>Compact Fluorescent Light, Extent : Light, Area Affected : 100%</i>								
<i>Location : Locker Rooms</i>								
Egress Lighting								
Emergency, Battery	50%			2028	\$11,600	10	\$1,700	
Exit, LED	25%			2061	**	1		
Exit, Battery	25%			2028	\$4,000	10	\$200	
Exterior Lighting								
LED	20%			2038	**			
<i>Recent Installation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Building Perimeter</i>								
No Component	80%							
Alarm								
Security System								
Generic	100%			2033	\$26,000	1	\$5,300	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : CCTV Surveillance System</i>								
Fire/Smoke Detection								
Generic, Digital	100%			2033	\$35,800	1-3	\$8,700	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
<i>Explanation : Manual Pull Stations, Horns, Strobes And Smoke Detection</i>								

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2043	**	1		
Conversion Equipment								
Furnace	70%			2038	**	1	\$4,900	
<i>Other Observation, Extent : Light, Area Affected : 85%</i>								
<i>Location : Roof</i>								
<i>Explanation : 4 Rooftop Units</i>								
Furnace	15%	Now	\$6,500	2043	**	1	\$900	
<i>Broken, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Roof</i>								
Hot Water Boiler	15%	0-2	\$22,100	2053	**	1	\$900	
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Basement</i>								
<i>Explanation : 1 Unit. Abandoned</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 1
Asset # : 549

Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Distribution								
Hot Wtr Piping/Pump	15%			2049	**	4	\$100	
No Component	85%							
Terminal Devices								
Convactor/Radiator	15%			2046	**	1	\$700	
No Component	85%							
Air Conditioning								
Energy Source								
Electricity	100%			2049	**	1		
Conversion Equipment								
Ext Pkg Unit - Heating/Cooling	100%	Now	\$46,600	2038	**	2	\$700	
			<i>R-22 Refrigerant, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Roof</i>					
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Roof</i>					
			<i>Explanation : 2 Of 6 Units Are Broken</i>					
Distribution								
Ductwork/Diffusers	100%			LIFE	**	2	\$18,500	
Ventilation								
Distribution								
Ductwork/Diffusers	100%			LIFE	**	2-5	\$7,900	
Exhaust Fans								
Roof	100%			2038	**	2	\$400	
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2053	**	1		
Water Heater With Tanks								
Gas Fired	100%			2031	\$16,700	2		
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Basement</i>					
			<i>Explanation : 80 Gallon Unit</i>					
Sanitary Piping								
Cast Iron	100%			LIFE	**	1		
Storm Drain Piping								
Cast Iron	100%	Now	\$4,900	LIFE	**	1		
			<i>Other Observation, Extent : Severe, Area Affected : 10%</i>					
			<i>Location : Roof</i>					
			<i>Explanation : Broken And Leaking Roof Drain</i>					
Sump Pump(s)								
Submersible	100%			2027	\$400	4	\$500	
Backflow Preventer								
Generic	100%			2038	**	1	\$900	
Fixtures								
Generic	100%							
Fire Suppression								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 1
Asset # : 549

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Fire Suppression	Sprinkler							
	Generic	100%			2053	**	1-2	\$4,000

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HARLEM RIVER BRIDGE SHOP GARAGE 2
Address : 301 W. 205TH STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0093.010 / 550 **Yr Built/Renovated** : 1958 / 2007
Area Sq Ft : 20,096 **Project Type** : HIGHWAYS
Date of Survey : 18-Nov-2021 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2
Block : 2186 **Lot** : 9 **BIN** : 1081894

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$102,500	
Electrical		\$189,700
Mechanical	\$66,000	
Total	\$168,400	\$189,700
Importance Code A	\$102,500	
Importance Code B	\$66,000	\$189,700
Total	\$168,400	\$189,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$94,300		\$11,200	
Interior Architecture	\$16,000		\$900	\$3,200
Electrical	\$2,100	\$2,300	\$2,000	\$1,900
Mechanical	\$13,900	\$1,900	\$3,500	\$2,000
Elevators/Escalators	\$7,200	\$7,200	\$7,200	\$7,200
Total	\$133,500	\$11,400	\$24,800	\$14,300
Importance Code A	\$107,300	\$1,000	\$12,200	\$1,000
Importance Code B	\$26,200	\$10,400	\$12,600	\$13,300
Importance Code C				
Total	\$133,500	\$11,400	\$24,800	\$14,300



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 2
Asset # : 550

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Masonry: Brick	55%	Now	\$102,500	LIFE	**	5	\$12,700	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Metal Panel	20%			2053	**	5-10	\$31,800	
Metal Sect. OHD	20%			2046	**	5	\$14,500	
Window Wall	5%			2053	**	5	\$4,300	
Windows								
Aluminum	100%	Now	\$20,700	2049	**	5	\$4,500	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Kitchen</i>								
<i>Water Penetration, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Parapets								
Cast Stone/Terra Cotta	10%	0-2	\$2,900	LIFE	**	5	\$2,500	
<i>Open Joints, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Masonry: Brick	45%			LIFE	**	5	\$1,500	
Metal Panel	5%			2053	**	5	\$600	
Metal Rail	40%	Now	\$17,200	2046	**	5	\$9,300	
<i>Loose/Miss Fasteners, Extent : Light, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
Roof								
Plaza Roof: Stone Panels	5%			2053	**			
Single Ply Membrane	95%	Now	\$44,400	2038	**			
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Penthouse, 2nd Floor Offices And Corridor</i>								
Soffits								
Aluminum Sunshades	75%			2042	**	10	\$6,100	
Cement - Fiber Panel	25%	Now	\$1,900	2038	**			
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Over Main Entrance</i>								
Interior								
Floors								
Cast in Place Concrete	10%			LIFE	**	5	\$6,600	
Traffic Topping	5%			2038	**	5	\$1,900	
Vinyl Tile	85%			2038	**	3	\$12,800	
Interior Walls								
Concrete Masonry Unit	80%			LIFE	**	5	\$9,700	
Glass: Single Pane	5%			LIFE	**	5	\$1,100	
Gypsum Board	5%			LIFE	**	5	\$900	
SGFT/Glazed Masonry	10%			LIFE	**			
Ceilings								
AcousTileSusp.Lay-In	85%			2046	**	5	\$25,600	
Exposed Struc: Steel	15%			LIFE	**			
Site Enclosure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 2
Asset # : 550

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Site Enclosure								
Fence/Gates								
Chain Link	10%			2053	**			
Chain Link	90%			2053	**			
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2046	**			
Parking/Driveway								
Cast in Place Concrete	100%			2046	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Driveway</i>								
<i>Explanation : Shared With Asset 549</i>								
<hr/>								
Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2043	**	5	\$100	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : One 800 Ampere Main Disconnect Switch</i>								
<hr/>								
Switchgear / Switchboard								
Fused Knife Sw	100%			2043	**	5	\$100	
Raceway								
Conduit	100%			2043	**	1		
Panelboards								
Molded Case Bkrs	100%			2041	**	5	\$500	
Wiring								
Thermoplastic	100%			2043	**	1		
Motor Controllers								
Locally Mounted	100%			2038	**	5	\$100	
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$300	
Lighting								
Interior Lighting								
Fluorescent	95%			2033	\$132,100	10	\$17,500	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 95%</i>								
<i>Location : Throughout The Building</i>								
Fluorescent	5%			2033	\$7,000	10	\$900	
<i>Compact Fluorescent Light, Extent : Light, Area Affected : 5%</i>								
<i>Location : Second Floor</i>								
<hr/>								
Egress Lighting								
Emergency, Battery	50%			2033	\$16,500	10	\$2,400	
Exit, LED	25%			2061	**	1		
Exit, Battery	25%			2033	\$5,700	10	\$300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 2
Asset # : 550

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Exterior Lighting								
Fluorescent	5%			2033	\$3,900	10	\$100	
HID	15%			2033	\$13,700	10		
			<i>Outdr Lights On During Daytime, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location : Exterior</i>					
No Component	80%							
Alarm								
Security System								
Generic	100%			2033	\$36,800	1	\$7,500	
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout The Building</i>					
			<i>Explanation : CCTV Surveillance System</i>					
Fire/Smoke Detection								
Generic, Digital	100%			2033	\$50,600	1-3	\$12,400	
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout The Building</i>					
			<i>Explanation : Manual Pull Stations, Horns and Strobes And Smoke Detection</i>					
Mechanical								
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Heating								
Energy Source								
Natural Gas	100%			2053	**	1		
Conversion Equipment								
Furnace	60%			2038	**	1	\$6,000	
			<i>Other Observation, Extent : Light, Area Affected : 60%</i>					
			<i>Location : Roof</i>					
			<i>Explanation : Two Package Units</i>					
Furnace	20%	Now	\$12,200	2043	**	1	\$1,800	
			<i>Other Observation, Extent : Severe, Area Affected : 100%</i>					
			<i>Location : Roof</i>					
			<i>Explanation : 1 Unit Is Boken</i>					
Hot Water Boiler	20%			2046	**	1	\$2,000	
			<i>Other Observation, Extent : Light, Area Affected : 20%</i>					
			<i>Location : 3rd Floor Penthouse</i>					
			<i>Explanation : 1 Unit</i>					
Distribution								
Hot Wtr Piping/Pump	20%			2049	**	4	\$200	
No Component	80%							
Terminal Devices								
Convactor/Radiator	20%			2046	**	1	\$1,300	
No Component	80%							
Air Conditioning								
Energy Source								
Electricity	100%			2049	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 2
Asset # : 550

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Air Conditioning								
Conversion Equipment								
	Ext Pkg Unit - Heating/Cooling	75%			2038	**	2	\$900
<i>R-134a Refrigerant, Extent : Light, Area Affected : 100%</i>								
<i>Location : 3 Units, Roof</i>								
	Ext Pkg Unit - Heating/Cooling	20%	Now	\$66,000	2043	**	2	\$200
<i>Broken, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Roof</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>Explanation : 1 Unit</i>								
	Split Unit	5%			2038	**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Elevator Machine Room</i>								
<i>Explanation : 1 Unit</i>								
Ventilation								
Distribution								
	Ductwork/Diffusers	100%			LIFE	**	2-5	\$11,200
Exhaust Fans								
	Roof	100%			2038	**	2	\$600
Plumbing								
H/C Water Piping								
	Brass/Copper	100%			2053	**	1	
Water Heater With Tanks								
	Gas Fired	100%			2031	\$16,700	2	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : 2nd Floor</i>								
<i>Explanation : 80 Gallon Unit</i>								
Sanitary Piping								
	Cast Iron	100%			LIFE	**	1	
Storm Drain Piping								
	Cast Iron	100%			LIFE	**	1	
Backflow Preventer								
	No Component	50%						
	Generic	50%			2038	**	1	\$600
Fixtures								
	Generic	100%						
Vertical Transport								
Elevators								
	Hydraulic	100%			LIFE	**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : 1st To 3rd Floor</i>								
<i>Explanation : 1 Unit</i>								
Fire Suppression								
Sprinkler								
	Generic	100%			2053	**	1-2	\$5,600

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER BRIDGE SHOP GARAGE 2
Asset # : 550**

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HARPER ST. ASPHALT PLANT
 Address : 30-01 HARPER STREET
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0217.000 / 14715 Yr Built/Renovated : 1950 /
 Area Sq Ft : 10,800 Project Type : HIGHWAYS
 Date of Survey : 13-Apr-2015 Landmark Status : NONE
 Areas Surveyed : Basement, Roof, Floors 1,2
 Block : 1791 Lot : 52 BIN : 4045011

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture		\$151,900
Interior Architecture		\$133,400
Electrical	\$135,000	\$67,200
Mechanical	\$50,100	\$54,900
Total	\$185,100	\$407,500
Importance Code A		\$206,800
Importance Code B	\$185,100	\$200,700
Total	\$185,100	\$407,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$42,200	\$1,300		
Interior Architecture	\$3,300			\$5,100
Electrical	\$233,100	\$1,000	\$1,000	\$1,000
Mechanical	\$214,900	\$900	\$1,500	\$900
Total	\$493,500	\$3,200	\$2,500	\$7,000
Importance Code A	\$65,900	\$1,800	\$300	\$500
Importance Code B	\$427,600	\$1,400	\$2,200	\$6,500
Importance Code C				
Total	\$493,500	\$3,200	\$2,500	\$7,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARPER ST. ASPHALT PLANT
Asset # : 14715

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Alum/Vinyl Siding	20%	Now	\$5,500	2036	**			
<i>Deteriorated Finish, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Two Story Section</i>								
<i>Paint Peeling, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Two Story Section</i>								
Metal, Corrugated	65%	Now	\$9,000	2036	**	1		
<i>Deformed/Dented, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Deteriorated Finish, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Metal Sect. OHD	10%			2031	\$50,900	5	\$4,500	
<i>Other Observation, Extent : Severe, Area Affected : 25%</i>								
<i>Location : East And South Facades</i>								
<i>Explanation : Deformed Dented</i>								
Wood	5%	Now	\$4,600	2031	\$15,200	5	\$1,800	1
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Sectional Door Frames</i>								
<i>Dry Rot/Decay, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Sectional Door Frames</i>								
No Component	0%							
Windows								
Aluminum	100%			2042	**	5	\$2,600	
Roof								
Metal, Corrugated	80%			2031	\$101,000	1		
Roll Roofing	20%			2026	\$18,400	5	\$4,900	
Interior								
Floors								
Cast in Place Concrete	75%			LIFE	**	5	\$26,500	
Ceramic Tile	15%			2035	\$133,400	5	\$2,400	
Wood	10%			2054	**	5	\$3,000	
Interior Walls								
Ceramic Tile	5%			2035	\$42,700	5	\$800	
Concrete Masonry Unit	25%			LIFE	**	5	\$1,600	
Gypsum Board	15%			LIFE	**	5	\$1,400	
Gypsum Board	55%			LIFE	**	5	\$5,200	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARPER ST. ASPHALT PLANT
Asset # : 14715

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Ceilings								
AcousTileSusp.Lay-In	25%	Now	\$3,300	2039	**	5	\$2,000	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : One Story Wing</i>								
<i>Staining/Discoloring, Extent : Severe, Area Affected : 100%</i>								
<i>Location : One Story Wing</i>								
<i>Worn/Eroded, Extent : Severe, Area Affected : 50%</i>								
<i>Location : One Story Wing</i>								
AcousTileSusp.Lay-In	45%			2039	**	5	\$7,300	
Exposed Struc: Steel	15%			LIFE	**			
Gypsum Board	15%			LIFE	**	5	\$3,000	

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2026	\$3,700	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : Two 400 Ampere Main Disconnect Switches For Main Office Building</i>								
Transformers								
Dry Type	100%			2026	\$26,100	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Generator Room</i>								
<i>Explanation : One 112.5 Kilovolt-ampere, 480hv-208/120lv</i>								
Switchgear / Switchboard								
Fused Disc Sw	50%			2026	\$15,900	5		
Molded Case Bkrs	50%			2026	\$15,900	5	\$100	
Raceway								
Conduit	100%			2026	\$4,300	1		
Panelboards								
Fused Disc Sw	10%			2026	\$1,000	5		
Molded Case Bkrs	90%			2026	\$8,800	5	\$300	
Wiring								
Thermoplastic	100%			2026	\$8,800	1		
Motor Controllers								
Locally Mounted	20%			2026	\$4,500	5		
Motor Control Center	80%			2026	\$42,600	5	\$200	
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$200	
Stand-by Power								
Transfer Switches								
Automatic	100%			2026	\$10,600	1	\$3,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARPER ST. ASPHALT PLANT
Asset # : 14715

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Stand-by Power								
Generators								
Diesel	100%			2026	\$78,700	1	\$4,200	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Generator Room - Main Office Building</i>								
<i>Explanation : One 500 Kilowatt, One 800 Kilowatt And One 900 Kilowatt. The Three Generators Are For The Asphalt Plant Only</i>								
Batteries								
Lead/Acid	100%			2026	\$2,400	5	\$400	
Fuel Storage								
Day Tank	25%			2026	\$6,300	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Genrator Room</i>								
<i>Explanation : One 125 Gallon</i>								
Main Tank	75%			2029	\$56,300	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Outside</i>								
<i>Explanation : Three 25,000 Gallon</i>								
Lighting								
Interior Lighting								
Fluorescent	90%			2031	\$67,200	10	\$8,900	
<i>T-8 Lamps And Fixtures, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
HID	5%			2026	\$6,200	10		
Incandescent	5%			2026	\$3,400	2		
Egress Lighting								
Emergency, Battery	50%			2026	\$8,900	10	\$1,300	
Exit, Service	50%			2026	\$1,800	1		
Exterior Lighting								
HID	100%			2026	\$49,200	10		
Alarm								
Security System								
No Component	50%							
Generic	50%			2026	\$9,900	1	\$2,000	

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Electricity	20%			2046	**	1		
Natural Gas	80%			2036	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARPER ST. ASPHALT PLANT
Asset # : 14715

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Conversion Equipment								
Furnace	60%			2026	\$19,700	1	\$3,200	
	<i>Other Observation, Extent : N/A, Area Affected : 60%</i>							
	<i>Location : Garage</i>							
	<i>Explanation : 3 Units</i>							
Radiant Heater	20%			2031	\$54,900	2	\$1,000	
	<i>Other Observation, Extent : N/A, Area Affected : 20%</i>							
	<i>Location : 1st Floor</i>							
	<i>Explanation : 2 Units</i>							
No Component	20%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location : Office</i>							
	<i>Explanation : Heating Is Provided By A Heat Pump Listed Only Under Air Conditioning Conversion Equipment</i>							
<hr/>								
Terminal Devices								
Air Handler	20%			2026	\$31,800	1	\$1,300	
Fan Coil Unit/Heat	20%			2026	\$41,800	1	\$700	
No Component	60%							
<hr/>								
Air Conditioning								
Energy Source								
Electricity	100%			2034	\$11,600	1		
<hr/>								
Conversion Equipment								
Heat Pump Air Sourced	20%			2026	\$31,600	2	\$100	
	<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Office</i>							
	<i>Explanation : 1 Unit - Provides Both Heating And Cooling</i>							
Split Unit	20%			2026	\$50,100			
	<i>Other Observation, Extent : N/A, Area Affected : 20%</i>							
	<i>Location : Laboratory</i>							
	<i>Explanation : 1 Unit</i>							
No Component	60%							
<hr/>								
Terminal Devices								
Air Handler/Cool/Ht	20%			2026	\$16,400	1	\$1,300	
Fan Coil - 4 Pipe	20%			2026	\$32,100	1	\$700	
No Component	60%							
<hr/>								
Heat Rejection								
Dry Cooler	40%			2026	\$7,700	2	\$3,000	
No Component	60%							
<hr/>								
Ventilation								
Distribution								
Ductwork/Diffusers	20%			LIFE	**	2-5	\$1,200	
No Component	80%							
<hr/>								
Exhaust Fans								
Interior	20%			2026	\$9,400	2	\$100	
No Component	80%							
<hr/>								
Plumbing								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARPER ST. ASPHALT PLANT
Asset # : 14715

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Plumbing								
	H/C Water Piping Brass/Copper	100%			2036	* *	1	
	Water Heater With Tanks Electric	100%			2026	\$23,100	4	
	Sanitary Piping Cast Iron	100%			LIFE	* *	1	
	Fixtures Generic	100%						

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.*


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : JEROME - GUN HILL ROAD GARAGE
Address : 3510 JEROME AVENUE @ GUN HILL RD.
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0204.000 / 14317 **Yr Built/Renovated** : 1979 /
Area Sq Ft : 78,600 **Project Type** : HIGHWAYS
Date of Survey : 20-Mar-2024 **Landmark Status** : NONE
Areas Surveyed : Floors 1,2,3
Block : 3328 **Lot** : 10 **BIN** : 2017791

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$332,700	\$683,200
Interior Architecture	\$1,147,400	\$251,700
Electrical		\$1,251,800
Mechanical		\$99,900
Total	\$1,480,100	\$2,286,700
Importance Code A	\$332,700	\$846,600
Importance Code B	\$790,300	\$1,440,100
Importance Code C	\$357,100	
Total	\$1,480,100	\$2,286,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$79,300			
Interior Architecture	\$20,400			\$1,200
Electrical	\$5,500	\$2,900	\$2,900	\$4,000
Mechanical	\$400		\$16,100	
Total	\$105,500	\$2,900	\$19,000	\$5,100
Importance Code A	\$79,600		\$400	
Importance Code B	\$5,500	\$2,900	\$18,600	\$5,100
Importance Code C	\$20,400			
Total	\$105,500	\$2,900	\$19,000	\$5,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
JEROME - GUN HILL ROAD GARAGE
Asset # : 14317

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Cast in Place Concrete	80%	Now	\$126,000	LIFE	**	5	\$539,100	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Street Facade</i>								
<i>Painted Surfaces, Extent : Light, Area Affected : 100%</i>								
<i>Location : Street Facade</i>								
Metal Sect. OHD	5%	Now	\$47,800	2040	**	5	\$10,500	
<i>Deformed/Dented, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Street Facade</i>								
<i>Other Observation, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Street Facade</i>								
<i>Explanation : Broken Missing Elements</i>								
Metal: Cage/Fence	15%	Now	\$9,800	2040	**	5	\$44,200	
<i>Corrosion/Rusting, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Street Facade</i>								
<i>Deteriorated Finish, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Street Facade</i>								
<hr/>								
Windows								
Steel	5%	Now	\$84,200	2057	**	5	\$12,000	
<i>Deteriorated Finish, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Ticket Office</i>								
<i>Glazing Broken/Cracked, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Ticket Office</i>								
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Ticket Office</i>								
<i>Explanation : Welded And Screwed Closed</i>								
No Component	95%							
<hr/>								
Parapets								
Cast in Place Concrete	75%	Now	\$122,400	LIFE	**	5	\$144,100	
<i>Spalling, Extent : Light, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Vertical Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Metal: Cage/Fence	25%	Now	\$21,700	2048	**	5	\$15,000	
<i>Corrosion/Rusting, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : East Facade, South Facade</i>								
<i>Deteriorated Finish, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : East Facade, South Facade</i>								

Interior

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
JEROME - GUN HILL ROAD GARAGE
Asset # : 14317

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Floors								
Cast in Place Concrete	98%	4+	\$478,000	LIFE	**	5	\$251,700	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Uneven Surface, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Worn/Eroded, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Ceramic Tile	2%			2044	**	5	\$2,300	
Interior Walls								
Cast in Place Concrete	75%			LIFE	**	10	\$357,100	
<i>Vertical Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
Concrete Masonry Unit	23%			LIFE	**	5	\$35,000	
Glass: Single Pane	2%			LIFE	**	5	\$5,700	
Ceilings								
AcousTileSusp.Lay-In	2%			2040	**	5	\$2,200	
Exposed Struc: Concrete	98%	Now	\$312,300	LIFE	**	5	\$16,700	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Ground Floor Ceiling</i>								
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2048	**			
On-Site Walkways								
Cast in Place Concrete	100%			2040	**			

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Molded Case Bkrs	100%			2035	\$63,500	5	\$2,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : Main Service Disconnect Switch Rated At 1,200 Amperes.</i>								
Switchgear / Switchboard								
Molded Case Bkrs	100%			2035	\$63,500	5	\$2,100	
Raceway								
Conduit	100%			2035	\$10,800	1		
Panelboards								
Fused Disc Sw	2%			2034	\$800	5		
Molded Case Bkrs	98%			2034	\$38,200	5	\$2,000	
Wiring								
Thermoplastic	100%			2035	\$22,100	1		

Ground

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
JEROME - GUN HILL ROAD GARAGE
Asset # : 14317

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Ground								
Grounding Devices Not Accessible	100%							
Lighting								
Interior Lighting HID	100%			2030	\$909,100	10	\$2,600	
Exterior Lighting HID	20%			2030	\$71,600	10		
No Component	80%							
Alarm								
Security System Generic	100%			2030	\$144,100	1	\$29,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Entry And Exit</i>								
<i>Explanation : CCTV Surveillance Cameras</i>								

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source Electricity	100%			2045	**	1		
Conversion Equipment Radiant Heater	5%			2030	\$99,900	2	\$1,800	
No Component	95%							
Air Conditioning								
Energy Source Electricity	100%			2043	**	1		
Conversion Equipment Window/Wall Unit	5%			2028	\$14,500	1		
No Component	95%							
Plumbing								
H/C Water Piping Brass/Copper	5%			2045	**	1		
No Component	95%							
Water Heater With Tanks Electric	5%			2028	\$1,200	4		
<i>Corroded, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Bathroom First Floor. May Fail At Any Moment</i>								
No Component	95%							
Sanitary Piping Cast Iron	5%			LIFE	**	1		
No Component	95%							
Storm Drain Piping Cast Iron	100%			LIFE	**	1		
<i>Corroded, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : 1st Floor.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
JEROME - GUN HILL ROAD GARAGE
Asset # : 14317

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Plumbing	Fixtures							
	Generic	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : JEROME 190TH ST. GARAGE
Address : JEROME AVE. AND 190TH ST.
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0120.000 / 175 **Yr Built/Renovated** : 1961 / 2007
Area Sq Ft : 149,514 **Project Type** : HIGHWAYS
Date of Survey : 03-Dec-2020 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2,3,4
Block : 3189 **Lot** : 9 **BIN** : 2014125

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$91,600	\$132,600
Interior Architecture	\$1,193,600	\$146,900
Electrical		\$284,200
Mechanical	\$282,000	\$672,400
Site Enclosure		\$160,600
Total	\$1,567,200	\$1,396,600
Importance Code A	\$281,600	\$132,600
Importance Code B	\$1,285,600	\$1,103,500
Importance Code C		\$160,600
Total	\$1,567,200	\$1,396,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$77,600	\$12,500		
Interior Architecture	\$37,400	\$400		\$400
Electrical	\$5,400	\$11,400	\$4,500	\$3,600
Mechanical	\$16,400	\$50,700	\$3,100	\$6,300
Site Enclosure	\$1,300			
Elevators/Escalators	\$15,800	\$15,800	\$15,800	\$15,800
Total	\$154,000	\$90,800	\$23,400	\$26,200
Importance Code A	\$77,600	\$13,500		\$700
Importance Code B	\$55,700	\$77,300	\$23,400	\$25,500
Importance Code C	\$20,700			
Total	\$154,000	\$90,800	\$23,400	\$26,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
JEROME 190TH ST. GARAGE
Asset # : 175

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Cast in Place Concrete	5%	0-2	\$17,200	LIFE	**	5	\$29,500	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Masonry: Brick	17%	0-2	\$32,200	LIFE	**	5	\$20,000	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Metal Panel	60%	Now	\$91,600	2042	**	5	\$132,600	
<i>Corrosion/Rusting, Extent : Severe, Area Affected : 5%</i>								
<i>Location : 7th Floor Bulkhead. At Base Of Wall</i>								
<i>Deformed/Dented, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Front Facade Above Car Entry And Exit</i>								
Metal Sect. OHD	5%			2037	**	5	\$18,400	
Granite Panels	10%			LIFE	**	5	\$8,800	
Pre-Cast Concrete	3%			LIFE	**	5	\$11,500	
Windows								
Steel	20%	Now	\$17,600	2057	**	5	\$7,500	
<i>Deteriorated Finish, Extent : Moderate, Area Affected : 35%</i>								
<i>Location : Stairs, 1st Floor Spaces And Bulkhead</i>								
<i>Thermally Inefficient, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Stairs And Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : At Grade</i>								
<i>Explanation : Protective Metal Grilles</i>								
No Component	80%							
Parapets								
Cast in Place Concrete	40%	Now	\$7,300	LIFE	**	5	\$8,500	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : 1st Floor At Column E6, 7th Floor Roof Deck Walls</i>								
Masonry: Brick	10%			LIFE	**	5	\$200	
Metal Panel	45%			2042	**	5	\$3,600	
Metal Rail	5%			2037	**	5-10	\$1,900	
Roof								
Asphalt Macadam	95%	0-2	\$3,300	2037	**	5	\$1,200	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
<i>Drains Inad/Misposn, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Parking Spaces 401 And 403. 7th Floor Deck</i>								
<i>Water Penetration, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Metal Panel	5%			2037	**	10	\$300	

Interior

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
JEROME 190TH ST. GARAGE
Asset # : 175

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Floors								
Asphalt Macadam	88%	0-2	\$360,100	2045	**	5	\$73,700	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : Severe, Area Affected : 10%</i>								
<i>Location : At Floor Drains And Water Drain Lines. Levels 1, 2, 2.5, 3 And Grid Columns C5, D3</i>								
<i>Explanation : Ponding, Erosion, Heaving</i>								
Cast in Place Concrete	10%	0-2	\$55,600	LIFE	**	5	\$73,300	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : 1st Level</i>								
Vinyl Tile	1%	Now	\$18,100	2042	**	3	\$1,300	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Vinyl Tile	1%			2042	**	3	\$1,300	
Interior Walls								
Cast in Place Concrete	50%			LIFE	**			
Concrete Masonry Unit	25%			LIFE	**	5	\$11,000	
Masonry: Brick	15%			LIFE	**			
SGFT/Glazed Masonry	10%	0-2	\$19,400	LIFE	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout First Floor Offices</i>								
Ceilings								
Exposed Struc: Concrete	95%	Now	\$777,800	LIFE	**	5	\$33,200	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Level 1</i>								
<i>Diagonal Cracks, Extent : Severe, Area Affected : 3%</i>								
<i>Location : Grid D3 Beam</i>								
<i>Staining/Discoloring, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Various Locations Throughout</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Level 6.5 At Spots 335 Through 337 And Level 6 Spots 330, 313</i>								
Gypsum Board	5%			LIFE	**	5	\$14,000	
Site Enclosure								
Fence/Gates								
Chain Link	100%			2042	**			
Free Standing Walls								
Cast in Place Concrete	50%	Now	\$1,300	2052	**			
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 15%</i>								
<i>Location : West Wall. Rear Yard</i>								
Masonry: Fieldstone	50%			2032	\$160,600			
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2045	**			
Parking/Driveway								
Cast in Place Concrete	100%			2037	**			

Note: All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
JEROME 190TH ST. GARAGE
Asset # : 175

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2032	\$14,700	5	\$600	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Electrical Room Next To Main Office</i>								
<i>Explanation : One 600 Ampere Main Disconnect Switch</i>								
Switchgear / Switchboard								
Molded Case Bkrs	100%			2032	\$95,300	5	\$3,900	
Raceway								
Conduit	90%			2032	\$15,600	1		
Conduit	10%			2042	**	1		
Panelboards								
Molded Case Bkrs	10%			2040	**	5	\$400	
Molded Case Bkrs	90%			2031	\$52,600	5	\$3,500	
Wiring								
Thermoplastic	90%			2032	\$31,800	1		
Thermoplastic	10%			2042	**	1		
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$2,200	
Lighting								
Interior Lighting								
Fluorescent	4%			2037	**	10	\$5,500	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Offices And Bathroom</i>								
LED	96%			2042	**			
Egress Lighting								
Exit, Service	50%			2037	**	1		
No Component	50%							
Exterior Lighting								
HID	20%			2032	\$136,300	10	\$100	
No Component	80%							
Alarm								
Security System								
No Component	80%							
Generic	20%			2037	**	1	\$11,200	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Driveway Area</i>								
<i>Explanation : CCTV Surveillance Cameras</i>								
Fire/Smoke Detection								
No Component	70%							
Generic, Digital	30%			2037	**	1-3	\$27,600	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Elevator Area Throughout The Building</i>								
<i>Explanation : Smoke Detector, Strobe Lights, Alarm Bells, Manual Pull Station And Fire Alarm Panel</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
JEROME 190TH ST. GARAGE
Asset # : 175

Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Electricity	100%			2042	**	1		
Conversion Equipment								
Radiant Heater	5%			2027	\$190,000	2	\$3,500	
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Office And Restrooms</i>					
			<i>Explanation : 6 Units</i>					
No Component	95%							
Air Conditioning								
Energy Source								
Electricity	100%			2040	**	1		
Conversion Equipment								
Window/Wall Unit	5%			2027	\$27,700	1		
No Component	95%							
Ventilation								
Distribution								
Ductwork/Diffusers	2%			LIFE	**	2-5	\$1,700	
No Component	98%							
Exhaust Fans								
Interior	3%			2032	\$19,400	2	\$100	
No Component	97%							
Plumbing								
H/C Water Piping								
Brass/Copper	5%			2042	**	1		
No Component	95%							
Water Heater With Tanks								
Electric	3%			2030	\$700	4		
			<i>Other Observation, Extent : N/A, Area Affected : 3%</i>					
			<i>Location : Staff Restroom</i>					
			<i>Explanation : 1 Unit</i>					
Electric	2%			2026	\$500	4		
			<i>Other Observation, Extent : N/A, Area Affected : 2%</i>					
			<i>Location : Public Mens Room</i>					
			<i>Explanation : 1 Unit</i>					
No Component	95%							
Sanitary Piping								
Cast Iron	100%	Now	\$92,000	LIFE	**	1		
			<i>Other Observation, Extent : Severe, Area Affected : 10%</i>					
			<i>Location : D3 On Level 1, Level 2 1 To 2, Level 3 1 To 2, C5 On Level 2</i>					
			<i>Explanation : Corroded, Cracked And Clogged</i>					
Storm Drain Piping								
Cast Iron	100%	Now	\$10,300	LIFE	**	1		
			<i>Broken, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Broken Storm Drain Piping On Level 3</i>					
Fixtures								
Generic	100%							
Vertical Transport								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
JEROME 190TH ST. GARAGE
Asset # : 175

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Vertical Transport	Elevators							
	Geared Traction	100%			LIFE		**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : 1st To 6th Floor, Roof</i>					
			<i>Explanation : 2 Units</i>					
Fire Suppression	Standpipe							
	Generic	100%			2032	\$672,400	1-5	\$78,200

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : KENT AVENUE BRIDGE COMPLEX GARAGE 1 AND 1A
Address : 372 KENT AVENUE @ WILLIAMSBURG BRIDGE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0095.000 / 551 **Yr Built/Renovated** : 1930 /
Area Sq Ft : 13,889 **Project Type** : HIGHWAYS
Date of Survey : 21-Oct-2022 **Landmark Status** : NONE
Areas Surveyed : Floors 1,2,3
Block : 2453 **Lot** : 1 **BIN** : 3335960

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$271,200	
Interior Architecture	\$1,080,400	\$112,200
Electrical		\$96,100
Mechanical		\$70,600
Site Pavements	\$339,400	
Total	\$1,691,100	\$278,900
Importance Code A	\$271,200	\$70,600
Importance Code B	\$129,500	\$208,300
Importance Code C	\$1,290,300	
Total	\$1,691,100	\$278,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$97,100			\$1,200
Interior Architecture	\$14,300		\$900	\$100
Electrical	\$1,300	\$1,700	\$1,300	\$1,400
Mechanical	\$1,800	\$700	\$1,300	\$74,000
Site Enclosure	\$9,500			
Site Pavements	\$2,100			
Elevators/Escalators	\$7,200	\$7,200	\$7,200	\$7,200
Total	\$133,200	\$9,700	\$10,700	\$83,900
Importance Code A	\$97,700	\$300	\$600	\$1,600
Importance Code B	\$26,000	\$9,300	\$10,100	\$82,300
Importance Code C	\$9,500			
Total	\$133,200	\$9,700	\$10,700	\$83,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX GARAGE 1 AND 1A
Asset # : 551

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Cast in Place Concrete	20%	0-2	\$42,900	LIFE	**	5	\$36,700	
<i>Horizontal Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Various Locations Throughout</i>								
Cast Stone/Terra Cotta	10%			LIFE	**	5	\$28,700	
Exposed Struc: Steel	5%	0-2	\$93,900	LIFE	**	5	\$5,700	1
<i>Corrosion/Rusting, Extent : Severe, Area Affected : 60%</i>								
<i>Location : Throughout Metal Stairs</i>								
Masonry: Brick	60%	Now	\$177,300	LIFE	**	5	\$22,000	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : East Facade</i>								
<i>Spalling, Extent : Moderate, Area Affected : 3%</i>								
<i>Location : Southeast And East Facade</i>								
<i>Vertical Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Metal Panel	5%	Now	\$2,400	2054	**	5	\$3,400	
<i>Deformed/Dented, Extent : Severe, Area Affected : 15%</i>								
<i>Location : South Facade</i>								
Windows								
Aluminum	100%	Now	\$16,700	2042	**	5	\$1,800	
<i>Ctrwt/Balnc Not Funct, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
Roof								
Metal Panel	7%	Now	\$18,400	2051	**			
<i>Gut/DS Non Func/Miss, Extent : Severe, Area Affected : 35%</i>								
<i>Location : South And North Facades</i>								
Metal Panel	10%			2051	**	10	\$3,400	
Metal Panel	83%			2051	**	10	\$28,200	
Soffits								
Metal, Corrugated	75%	Now	\$16,600	2044	**	1		
<i>Corrosion/Rusting, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Throughout Canopies</i>								
Metal Panel	25%			2054	**	5-10	\$4,400	
Interior								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX GARAGE 1 AND 1A
Asset # : 551

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Floors								
Cast in Place Concrete	75%	0-2	\$129,500	LIFE	**	5	\$34,100	
	<i>Cracking/Crumbling, Extent : Light, Area Affected : 20%</i>							
	<i>Location : Throughout</i>							
	<i>Paint Peeling, Extent : Moderate, Area Affected : 10%</i>							
	<i>Location : Throughout</i>							
Ceramic Tile	5%			2043	**	5	\$1,000	
Vinyl Tile	4%	Now	\$2,200	2034	\$22,400	3	\$300	
	<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Throughout</i>							
	<i>Worn/Eroded, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Kitchens</i>							
Vinyl Tile	16%			2034	\$89,700	3	\$1,200	
Interior Walls								
Cast in Place Concrete	10%	0-2	\$95,700	LIFE	**			
	<i>Paint Peeling, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Throughout</i>							
	<i>Vertical Cracks, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Throughout</i>							
Concrete Masonry Unit	65%	0-2	\$256,200	LIFE	**	5	\$11,200	
	<i>Horizontal Cracks, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Stairwell</i>							
Masonry: Brick	25%	0-2	\$599,000	LIFE	**			
	<i>Horizontal Cracks, Extent : Moderate, Area Affected : 25%</i>							
	<i>Location : Various Locations</i>							
	<i>Vertical Cracks, Extent : Moderate, Area Affected : 2%</i>							
	<i>Location : East Building</i>							
Ceilings								
Exposed Struc: Concrete	10%	0-2	\$12,000	LIFE	**	5	\$300	
	<i>Paint Peeling, Extent : Moderate, Area Affected : 10%</i>							
	<i>Location : Various Locations</i>							
Exposed Struc: Steel	10%			LIFE	**			
Exposed Struc: Wood	10%			LIFE	**			
Gypsum Board	70%			LIFE	**	5	\$14,400	
Site Enclosure								
Fence/Gates								
Iron Picket	100%	Now	\$9,500	2078	**			
	<i>Corrosion/Rusting, Extent : Moderate, Area Affected : 30%</i>							
	<i>Location : Throughout</i>							
	<i>Impact Damage, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Various Locations</i>							
Site Pavements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX GARAGE 1 AND 1A
Asset # : 551

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2047	**			
		<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Front Of Building</i>						
		<i>Explanation : Minor Cracks</i>						
<hr/>								
On-Site Walkways								
Cast in Place Concrete	100%			2039	**			
<hr/>								
Parking/Driveway								
Asphalt	100%	0-2	\$339,400	2047	**			
		<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 25%</i>						
		<i>Location : Throughout</i>						
<hr/>								
Activity Yard								
Asphalt	100%	0-2	\$2,100	2043	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Interior Activity Yard</i>						
		<i>Explanation : Cracking And Crumbling</i>						

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2044	**	5	\$100	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 2nd Floor Electrical Shop</i>						
		<i>Explanation : 400 Ampere Main Switch Observed</i>						
<hr/>								
Switchgear / Switchboard								
Fused Disc Sw	100%			2044	**	5	\$100	
<hr/>								
Raceway								
Conduit	100%			2044	**	1		
<hr/>								
Panelboards								
Fused Disc Sw	5%			2042	**	5		
Molded Case Bkrs	95%			2042	**	5	\$300	
<hr/>								
Wiring								
Thermoplastic	100%			2044	**	1		
<hr/>								
Motor Controllers								
Locally Mounted	100%			2039	**	5	\$100	
<hr/>								
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$200	
<hr/>								
Lighting								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX GARAGE 1 AND 1A
Asset # : 551

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Interior Lighting Fluorescent	100%			2034	\$96,100	10	\$12,700	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>T-12 Lamps And Fixtures, Extent : Light, Area Affected : 5%</i>								
<i>Location : Boiler Room</i>								
<hr/>								
Egress Lighting								
Emergency, Battery	50%			2034	\$11,400	10	\$1,700	
Exit, Battery	50%			2034	\$7,800	10	\$500	
<hr/>								
Exterior Lighting								
HID	40%			2034	\$25,300	10		
No Component	60%							
<hr/>								
Alarm								
Security System								
Generic	100%			2034	\$25,500	1	\$5,200	
<hr/>								
Fire/Smoke Detection								
Generic, Analog	100%			2042	**	1-3	\$8,600	
<hr/>								
Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2044	**	1		
<hr/>								
Conversion Equipment								
Hot Water Boiler	50%			2039	**	1	\$3,400	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Building Closer To Water</i>								
<i>Explanation : Serves That Building Only</i>								
<hr/>								
Radiant Heater	20%			2034	\$70,600	2	\$1,300	
No Component	30%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location : Building Closer To Street</i>								
<i>Explanation : Served By Steam Boiler Located In Adjacent Building</i>								
<hr/>								
Distribution								
Hot Wtr Piping/Pump	80%			2042	**	4	\$800	
Steam Piping/Pump	20%			2044	**			
<hr/>								
Terminal Devices								
Convactor/Radiator	10%			2032	\$7,800	1	\$500	
Unit Heater - Hot Water	50%			2034	\$28,100			
Unit Heater - Steam	40%			2034	\$21,600	4	\$800	
<hr/>								
Air Conditioning								
Energy Source								
Electricity	100%			2050	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX GARAGE 1 AND 1A
Asset # : 551

Mechanical System Component Type	Current Repair		Future Replacement		Maintenance		Priority
	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Air Conditioning							
Conversion Equipment							
Window/Wall Unit	60%			2029	\$30,800	1	
No Component	40%						
Ventilation							
Exhaust Fans							
Roof	10%			2029	\$2,600	2	
Wall Unit	40%			2034	\$2,300	2	\$200
No Component	50%						
Plumbing							
H/C Water Piping							
Brass/Copper	100%			2044	**	1	
Water Heater With Tanks							
Electric	50%			2029	\$23,100	4	
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>				
			<i>Location : Building Closer To Street On 1st Floor</i>				
			<i>Explanation : 30 Gallon</i>				
Gas Fired	50%			2029	\$16,700	2	
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>				
			<i>Location : 1st Floor Of Building Closer To Water</i>				
			<i>Explanation : 100 Gallon</i>				
Sanitary Piping							
Cast Iron	100%			LIFE	**	1	
Backflow Preventer							
Generic	100%			2039	**	1	\$900
Fixtures							
Generic	100%						
Vertical Transport							
Elevators							
Hydraulic	100%			LIFE	**		
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>				
			<i>Location : 1st To 3rd Floor</i>				
			<i>Explanation : One Unit</i>				
Fire Suppression							
Sprinkler							
Generic	100%			2054	**	1-2	\$3,900

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : KENT AVENUE BRIDGE COMPLEX IRON WORKSHOP
Address : 372 KENT AVENUE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0095.010 / 552 **Yr Built/Renovated** : 1930 /
Area Sq Ft : 13,494 **Project Type** : HIGHWAYS
Date of Survey : 21-Oct-2022 **Landmark Status** : NONE
Areas Surveyed : Floors 1,2,3
Block : 2453 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$662,700	
Interior Architecture	\$99,500	
Electrical	\$93,400	
Mechanical		\$59,900
Total	\$855,600	\$59,900
Importance Code A	\$662,700	
Importance Code B	\$192,900	\$59,900
Total	\$855,600	\$59,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$38,700			\$5,600
Interior Architecture	\$14,700	\$900	\$300	
Electrical	\$800	\$900	\$1,000	\$13,200
Mechanical	\$1,300	\$400	\$800	\$10,400
Site Pavements	\$16,900			
Total	\$72,300	\$2,200	\$2,100	\$29,100
Importance Code A	\$38,700			\$5,600
Importance Code B	\$24,700	\$2,200	\$2,100	\$23,500
Importance Code C	\$9,000			
Total	\$72,300	\$2,200	\$2,100	\$29,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX IRON WORKSHOP
Asset # : 552

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Cast in Place Concrete	3%	Now	\$9,800	LIFE	**	5	\$4,200	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Various Locations</i>								
Cast Stone/Terra Cotta	10%	Now	\$87,000	LIFE	**	5	\$21,900	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 3%</i>								
<i>Location : Various Locations</i>								
Exposed Struc: Steel	3%	0-2	\$14,300	LIFE	**	5	\$2,600	
<i>Corrosion/Rusting, Extent : Moderate, Area Affected : 3%</i>								
<i>Location : Metal Stair</i>								
Masonry: Brick	74%	Now	\$499,600	LIFE	**	5	\$20,700	
<i>Diagonal Cracks, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Facade</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Vertical Cracks, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Metal Coiling Doors	10%	0-2	\$14,600	2047	**	5	\$4,400	
<i>Corrosion/Rusting, Extent : Light, Area Affected : 10%</i>								
<i>Location : Metal Doors</i>								
Windows								
Aluminum	100%			2050	**	5	\$7,100	
<i>Unit Inoperable, Extent : Light, Area Affected : 10%</i>								
<i>Location : Various Locations</i>								
Parapets								
Not Accessible	100%							
Roof								
Metal Panel	100%	0-2	\$76,000	2051	**			
<i>Gut/DS Non Func/Miss, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
Soffits								
Metal Panel	100%			2054	**	5-10	\$20,500	
Interior								
Floors								
Cast in Place Concrete	65%			LIFE	**	5	\$28,700	
Ceramic Tile	3%			2043	**	5	\$600	
Vinyl Tile	7%			2039	**	3	\$500	
Wood	25%	2-4	\$14,700	2049	**	5	\$4,700	
<i>Worn/Eroded, Extent : Light, Area Affected : 100%</i>								
<i>Location : Second Floor Woodshop</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX IRON WORKSHOP
Asset # : 552

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Interior Walls								
Cast in Place Concrete	10%			LIFE	**			
Concrete Masonry Unit	20%			LIFE	**	5	\$2,300	
Gypsum Board	5%			LIFE	**	5	\$900	
Masonry: Brick	65%			LIFE	**			
Ceilings								
AcousTileSusp.Lay-In	10%			2047	**	5	\$1,400	
Exposed Struc: Concrete	50%	0-2	\$99,500	LIFE	**	5	\$1,100	
<i>Paint Peeling, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : First Floor</i>								
Exposed Struc: Steel	30%			LIFE	**			
Exposed Struc: Wood	5%			LIFE	**			
Gypsum Board	5%			LIFE	**	5	\$900	
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%	0-2	\$2,600	2039	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northwest Sidewalk</i>								
Parking/Driveway								
Asphalt	100%	0-2	\$9,000	2037	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Activity Yard								
Asphalt	100%	0-2	\$5,300	2043	**			
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 45%</i>								
<i>Location : Interior Activity Yard</i>								

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2044	**	5	\$100	
Raceway								
Conduit	100%			2044	**	1		
Panelboards								
Molded Case Bkrs	50%			2050	**	5	\$200	
Molded Case Bkrs	50%			2042	**	5	\$200	
Wiring								
Thermoplastic	100%			2044	**	1		
Motor Controllers								
Locally Mounted	100%			2032		5	\$100	
Lighting								
Interior Lighting								
Fluorescent	100%			2029		10	\$12,400	

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX IRON WORKSHOP
Asset # : 552

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Lighting								
Exterior Lighting								
LED	40%			2039	**			
No Component	60%							
Alarm								
Fire/Smoke Detection								
Generic, Analog	100%			2034	\$34,000	1-3	\$8,300	
Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Heating								
Distribution								
Steam Piping/Pump	100%			2044	**			
Terminal Devices								
Convactor/Radiator	20%			2039	**	1	\$900	
Unit Heater - Steam	80%			2034	\$59,900	4	\$1,500	
Air Conditioning								
Energy Source								
Electricity	100%			2042	**	1		
Conversion Equipment								
Window/Wall Unit	20%			2029	\$10,000	1		
No Component	80%							
Ventilation								
Exhaust Fans								
Wall Unit	100%			2034	\$5,700	2	\$400	
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2044	**	1		
Water Heater With Tanks								
Electric	100%			2033	\$23,100	4		
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : 2nd Floor Bathroom Closet</i>					
			<i>Explanation : 40 Gallons</i>					
Sanitary Piping								
Cast Iron	100%			LIFE	**	1		
Storm Drain Piping								
Cast Iron	100%			LIFE	**	1		
Backflow Preventer								
Generic	100%			2034	\$5,900	1	\$800	
Fixtures								
Generic	100%							
Fire Suppression								
Sprinkler								
Generic	100%			2044	**	1-2	\$3,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : **KENT AVENUE BRIDGE COMPLEX STORAGE AND BOILER ROOM**
 Address : **372 KENT AVENUE**
 Borough : **BROOKLYN** Agency's Number : **N/A**
 Program / Asset # : **DOT0095.020 / 553** Yr Built/Renovated : **1930 /**
 Area Sq Ft : **2,248** Project Type : **HIGHWAYS**
 Date of Survey : **21-Oct-2022** Landmark Status : **NONE**
 Areas Surveyed : **Floors 1**
 Block : **2453** Lot : **1** BIN :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$76,500	
Interior Architecture	\$123,100	
Total	\$199,600	
Importance Code A	\$76,500	
Importance Code B	\$123,100	
Total	\$199,600	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture				
Interior Architecture	\$13,700			
Electrical				\$17,600
Mechanical	\$200	\$200	\$200	\$700
Total	\$14,000	\$200	\$200	\$18,300
Importance Code A	\$200	\$200	\$200	\$200
Importance Code B				\$18,100
Importance Code C	\$13,700			
Total	\$14,000	\$200	\$200	\$18,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX STORAGE AND BOILER ROOM
Asset # : 553

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Masonry: Brick	55%	Now	\$76,500	LIFE	**	5	\$2,400	
			<i>Diagonal Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : West Facade</i>					
			<i>Horizontal Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : West Facade</i>					
			<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 25%</i>					
			<i>Location : West Facade</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : West Facade</i>					
Masonry: Brick	45%			LIFE	**	5	\$1,900	
Parapets								
Masonry: Brick	70%			LIFE	**	5	\$700	
			<i>Efflorescence, Extent : Moderate, Area Affected : 25%</i>					
			<i>Location : East Facade</i>					
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Roof</i>					
			<i>Explanation : Not Accessible</i>					
No Component	30%							
Roof								
Not Accessible	100%							
Interior								
Floors								
Cast in Place Concrete	100%			LIFE	**	5	\$7,400	
Interior Walls								
Concrete Masonry Unit	10%	0-2	\$2,700	LIFE	**	5	\$100	
			<i>Horizontal Cracks, Extent : Moderate, Area Affected : 15%</i>					
			<i>Location : Throughout</i>					
Masonry: Brick	20%	Now	\$11,000	LIFE	**			
			<i>Loose/Delam Surface, Extent : Moderate, Area Affected : 25%</i>					
			<i>Location : Throughout</i>					
Masonry: Brick	70%			LIFE	**			
Ceilings								
Exposed Struc: Concrete	100%	Now	\$123,100	LIFE	**	5	\$500	
			<i>Cracking/Crumbling, Extent : Severe, Area Affected : 25%</i>					
			<i>Location : Throughout</i>					
			<i>Exposed Reinforcement, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : Throughout</i>					
			<i>Paint Peeling, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Throughout</i>					
			<i>Other Observation, Extent : Severe, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : There Appears To Be A Structural Issue And Beams Are Starting To Fail</i>					
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2047	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KENT AVENUE BRIDGE COMPLEX STORAGE AND BOILER ROOM
Asset # : 553

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Not Accessible	100%							
Switchgear / Switchboard								
Not Accessible	100%							
Raceway								
Conduit	100%			2044	**	1		
Panelboards								
Not Accessible	100%							
Wiring								
Rubber	100%			2042	**	1		
Lighting								
Interior Lighting								
Fluorescent	100%			2029	\$15,600	10	\$2,100	
Mechanical								
Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Natural Gas	100%			2044	**	1		
Conversion Equipment								
Radiant Heater	10%			2034	\$5,700	2	\$100	
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Boiler Room</i>						
		<i>Explanation : Electric Unit Heater</i>						
Steam Boiler	90%			2039	**	1	\$2,000	
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Boiler Room</i>						
		<i>Explanation : Serves The Iron Workshop Building And The Carpenters Workshop Building</i>						
Distribution								
Steam Piping/Pump	100%			2044	**			
Ventilation								
Exhaust Fans								
Wall Unit	10%			2034	\$100	2		
No Component	90%							
Plumbing								
Storm Drain Piping								
Cast Iron	100%			LIFE	**	1		
Sump Pump(s)								
Non-Submersible	100%			2029	\$400	4		
Backflow Preventer								
Generic	100%			2039	**	1	\$100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : MANHATTAN SIGN SHOP/BRDG OPS, PAINTERS, REPAIRER & RIVETER
Address : 345 EAST 59TH STREET UNDER QUEENSBORO BRIDGE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0349.000 / 15363 **Yr Built/Renovated** :
Area Sq Ft : 50,850 **Project Type** : HIGHWAYS
Date of Survey : 19-Jan-2022 **Landmark Status** : NONE
Areas Surveyed : Floors 1,2
Block : 1434 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$1,514,600	\$246,500
Interior Architecture	\$2,228,700	\$468,100
Electrical	\$620,100	\$528,800
Mechanical	\$3,023,200	\$774,100
Total	\$7,386,600	\$2,017,500
Importance Code A	\$1,514,600	\$246,500
Importance Code B	\$5,872,000	\$1,771,000
Total	\$7,386,600	\$2,017,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$47,900		\$23,800	
Interior Architecture	\$23,300			\$8,800
Electrical	\$5,100	\$4,700	\$8,200	\$5,700
Mechanical	\$13,600	\$17,300	\$27,600	\$8,400
Total	\$89,900	\$22,000	\$59,500	\$22,900
Importance Code A	\$53,200		\$23,900	
Importance Code B	\$34,300	\$22,000	\$35,600	\$18,100
Importance Code C	\$2,400			\$4,800
Total	\$89,900	\$22,000	\$59,500	\$22,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MANHATTAN SIGN SHOP/BRDG OPS, PAINTERS, REPAIRER & RIVETER
Asset # : 15363

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Concrete Masonry Unit	5%			LIFE	**	5	\$9,500	
Masonry: Granite	58%			LIFE	**	5	\$132,400	
Metal Coiling Doors	5%			2038	**	5	\$47,500	
Mosaic Tile	2%			2053	**	10	\$19,000	
Stucco Cement	30%	0-2	\$1,514,600	2038	**	5	\$114,100	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
<i>Worn/Eroded, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Windows								
Metal Louvers	5%			2036	**	10	\$700	
Steel	95%	Now	\$47,200	2041	**	5	\$13,400	
<i>Air Infiltration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Iron Shop And Throughout</i>								
<i>Worn/Eroded, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
Interior								
Floors								
Cast in Place Concrete	80%	4+	\$888,800	LIFE	**	5	\$468,100	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 15%</i>								
<i>Location : Trolley Garage</i>								
<i>Explanation : Brick Paving Around Train Tracks</i>								
Ceramic Tile	8%			2036	**	5	\$21,400	
Vinyl Tile	12%			2038	**	3	\$16,000	
<i>Recent Replace Evident, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Sign Shop</i>								
Interior Walls								
Ceramic Tile	5%			2036	**	5	\$4,800	
Concrete Masonry Unit	73%			LIFE	**	5	\$27,800	
Glass: Single Pane	2%			LIFE	**	5	\$1,400	
Gypsum Board	13%			LIFE	**	5	\$7,400	
Metal Coiling Doors	2%			2049	**	5	\$9,500	
Plaster	5%			LIFE	**	5	\$1,400	
<i>Worn/Eroded, Extent : Light, Area Affected : 5%</i>								
<i>Location : Entry Area</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MANHATTAN SIGN SHOP/BRDG OPS, PAINTERS, REPAIRER & RIVETER
Asset # : 15363

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Ceilings								
AcousTileSusp.Lay-In	10%	Now	\$6,200	2046	**	5	\$3,800	
<i>Recent Replace Evident, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Sign Shop</i>								
<i>Staining/Discoloring, Extent : Light, Area Affected : 2%</i>								
<i>Location : Bridge Operations Office</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Bridge Operations Office</i>								
Exposed Struc: Steel	75%	Now	\$1,339,900	LIFE	**			
<i>Water Penetration, Extent : Light, Area Affected : 10%</i>								
<i>Location : Corridor Adjacent To Iron Workers Shop</i>								
Gypsum Board	15%			LIFE	**	5	\$14,300	
<i>Loose/Delam Surface, Extent : Light, Area Affected : 2%</i>								
<i>Location : Throughout</i>								

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2043	**	5	\$200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Parking Garage Cage</i>								
<i>Explanation : One 1,200 And One 400 Ampere Main Disconnect Switches</i>								
Switchgear / Switchboard								
Fused Disc Sw	100%			2043	**	5	\$200	
Raceway								
Conduit	100%			2043	**	1		
Panelboards								
Molded Case Bkrs	100%			2041	**	5	\$1,300	
Wiring								
Thermoplastic	100%			2043	**	1		
Motor Controllers								
Locally Mounted	100%			2038	**	5	\$300	
Ground								
Grounding Devices								
Generic	100%			LIFE	**	5	\$700	

Lighting

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MANHATTAN SIGN SHOP/BRDG OPS, PAINTERS, REPAIRER & RIVETER
Asset # : 15363

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Interior Lighting								
Fluorescent	24%			2033	\$296,700	10	\$39,300	
			<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout The Building</i>					
Fluorescent	1%			2033	\$12,400	10	\$1,600	
			<i>Compact Fluorescent Light, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Iron Shop Office And Men's Locker Room</i>					
HID	50%	Now	\$620,100	2038	**			
			<i>Malfunctioning, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location : Parking Garage Area</i>					
LED	25%			2038	**			
Egress Lighting								
Emergency, Battery	75%			2033	\$219,700	10	\$32,400	
Exit, Battery	25%			2038	**	10	\$3,000	
Exterior Lighting								
HID	15%			2038	**	10		
LED	5%			2038	**			
No Component	80%							
Alarm								
Security System								
Generic	100%			2038	**	1	\$19,000	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout The Building</i>					
			<i>Explanation : CCTV Surveillance System</i>					
Fire/Smoke Detection								
Generic, Digital	100%	Now	\$2,600	2038	**	1-3	\$28,500	
			<i>Malfunctioning, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location : Breeze Way</i>					

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source								
Utility Steam	98%			2043	**	1		
Electricity	2%			2053	**	1		
Conversion Equipment								
Pres. Reducing Valve/LP Steam	100%			2036	**	5	\$10,600	
Distribution								
Steam Piping/Pump	60%			2043	**			
No Component	40%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MANHATTAN SIGN SHOP/BRDG OPS, PAINTERS, REPAIRER & RIVETER
Asset # : 15363

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Heating								
Terminal Devices								
Air Handler	10%			2028	\$328,500	1	\$11,100	
Convactor/Radiator	40%	Now	\$57,100	2046	**	1	\$20,800	
<i>Malfunctioning, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Bridge Operations Area Has No Heat At Radiators</i>								
Fan Coil Unit/Heat	10%			2038	**	1	\$5,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Bridge Operations</i>								
<i>Explanation : Electric Heaters</i>								
No Component	40%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Garage</i>								
<i>Explanation : No Heat In The Attached Garage Below The Bridge</i>								
Controls								
Electrical	100%	Now	\$5,500	2028	\$276,100			
<i>Malfunctioning, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Thermostats Not Calibrated</i>								
Air Conditioning								
Energy Source								
Electricity	100%			2041	**	1		
Conversion Equipment								
Int Pkg Unit - Heating/Cooling	40%	Now	\$1,137,500	2038	**	2	\$3,500	
<i>Broken, Extent : Severe, Area Affected : 50%</i>								
<i>Location : 2nd Floor In Breezeway, 2 Of 4 Units Broken</i>								
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : 2nd Floor Breezeway</i>								
<i>Explanation : 4 Units Total, 2 Units Broken And 2 Units Malfunction Often.</i>								
Window/Wall Unit	20%			2028	\$132,200	1		
No Component	40%							
Ventilation								
Distribution								
Ductwork/Diffusers	100%			LIFE	**	2-5	\$99,700	
Exhaust Fans								
Interior	100%	Now	\$387,100	2033	\$774,100	2	\$4,400	
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : All The Fans Are Broken Including In The Garage</i>								
Plumbing								
H/C Water Piping								
Brass/Copper	100%	Now	\$112,100	2043	**	1		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Bridge Office</i>								
<i>Explanation : Bridge Office Area Has No Hot Water</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MANHATTAN SIGN SHOP/BRDG OPS, PAINTERS, REPAIRER & RIVETER
Asset # : 15363

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Plumbing								
Water Heater With Tanks Electric	100%			2031	\$46,200	4		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor Outside Of Mechanical Room</i>								
<i>Explanation : 120 Gallons. Quantity 2</i>								
HW Heat Exchanger Steam Fired	100%			2043	* *	4	\$26,500	
Sanitary Piping Cast Iron	100%	Now	\$109,900	LIFE	* *	1		
<i>Blockage /Clogged, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Drains Back Up Often</i>								
Sump Pump(s) Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Below The Garage</i>								
<i>Explanation : Pumps Are Broken.</i>								
Backflow Preventer Generic	100%			2038	* *	1	\$10,900	
Fixtures Generic	100%							
Fire Suppression								
Sprinkler Generic	100%	Now	\$482,700	2053	* *	1-2	\$43,400	
<i>Dry System, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Garage System Doesn't Hold Pressure Needs Maintenance Often</i>								
<i>Leak Evident, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Throughout Building</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : MASPETH CENTRAL SHOP
Address : 58-50 57TH ROAD
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0096.000 / 169 **Yr Built/Renovated** : 1949 / 1999
Area Sq Ft : 109,800 **Project Type** : HIGHWAYS
Date of Survey : 12-Sep-2023 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2
Block : 2675 **Lot** : 15 **BIN** : 4059838

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$2,831,800	\$55,700
Interior Architecture	\$2,004,700	\$2,688,100
Electrical		\$1,522,800
Mechanical	\$796,100	\$5,384,100
Site Pavements	\$69,600	
Total	\$5,702,300	\$9,650,800
Importance Code A	\$2,831,800	\$850,200
Importance Code B	\$2,500,500	\$8,800,600
Importance Code C	\$369,900	
Total	\$5,702,300	\$9,650,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$8,700			
Interior Architecture	\$71,800		\$11,700	\$6,600
Electrical	\$35,400	\$10,300	\$10,600	\$13,700
Mechanical	\$54,600	\$15,200	\$33,200	\$14,800
Site Enclosure	\$39,000			
Site Pavements	\$25,700			
Total	\$235,100	\$25,400	\$55,600	\$35,100
Importance Code A	\$18,700	\$10,100	\$10,100	\$10,100
Importance Code B	\$103,300	\$15,400	\$33,800	\$25,000
Importance Code C	\$113,100		\$11,700	
Total	\$235,100	\$25,400	\$55,600	\$35,100



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
MASPETH CENTRAL SHOP
Asset # : 169

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Cast in Place Concrete	5%	2-4	\$8,700	LIFE	**	5	\$37,200	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : East Wall At Parking Area On 57th Drive And South Exit Door</i>								
Concrete Masonry Unit	60%	0-2	\$233,400	LIFE	**	5	\$55,700	
<i>Diagonal Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Various Locations Throughout</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Masonry: Brick	25%	Now	\$298,800	LIFE	**	5	\$37,200	
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Base At Perimeter Of Walls Along 57th Road</i>								
<i>Vertical Cracks, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Various Locations Throughout</i>								
Metal Coiling Doors	10%			2040	**	5	\$46,500	
Windows								
Steel	75%	Now	\$360,500	2060	**	5	\$26,700	
<i>Water Penetration, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Various Locations Throughout</i>								
<i>Window Guards, Extent : Light, Area Affected : 100%</i>								
<i>Location : West And South Facades</i>								
<i>Worn/Eroded, Extent : Severe, Area Affected : 100%</i>								
<i>Location : West And South Facades</i>								
Steel	25%	Now	\$104,500	2060	**	5	\$8,900	
<i>Water Penetration, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Various Locations Throughout</i>								
<i>Worn/Eroded, Extent : Severe, Area Affected : 100%</i>								
<i>Location : North And East Facades And Clerestories</i>								
Roof								
Modified Bitumen	100%	Now	\$1,834,600	2045	**			1
<i>Blisters, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
<i>Ponding, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
<i>Seams Open/Split, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Various Locations Throughout</i>								

Interior

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MASPETH CENTRAL SHOP
Asset # : 169

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior Floors								
Cast in Place Concrete	67%	4+	\$636,100	LIFE	**	5	\$335,000	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Throughout Garage Area</i>								
Quarry Tile	10%			2040	**	5	\$34,300	
Vinyl Tile	15%	0-2	\$92,500	2035	\$925,000	3	\$12,900	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : 2nd Floor Offices And Sign Shop</i>								
<i>Worn/Eroded, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
Vinyl Tile 9" X 9"	8%	Now	\$71,400	2030	\$1,428,200	3	\$6,900	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : 2nd Floor Offices</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 7%</i>								
<i>Location : Various 2nd Floor Offices And Corridor</i>								
<i>Worn/Eroded, Extent : Severe, Area Affected : 50%</i>								
<i>Location : 2nd Floor Offices</i>								
Interior Walls								
Ceramic Tile	5%	2-4	\$5,000	2044	**	5	\$2,300	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 2%</i>								
<i>Location : 1st Floor Bathrooms</i>								
Concrete Masonry Unit	70%	2-4	\$300,400	LIFE	**	5	\$26,200	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Wall Adjacent To Ramp At 58th Place Entrance</i>								
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Stairwell Bulkheads</i>								
<i>Diagonal Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Various Locations Throughout Garage And Shop Areas</i>								
Glass: Single Pane	5%			LIFE	**	5	\$7,000	
Gypsum Board	5%			LIFE	**	5-10	\$7,900	
Masonry: Brick	10%	2-4	\$34,800	LIFE	**			
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Mechanical Room On First Floor Below Office Area</i>								
<i>Horizontal Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Mechanical Room On First Floor Below Office Area</i>								
Metal Coiling Doors	5%			2043	**	5	\$23,400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MASPETH CENTRAL SHOP
Asset # : 169

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Ceilings								
AcousTileSusp.Lay-In	10%			2040	**	5	\$22,900	
Exposed Struc: Concrete	55%	Now	\$367,900	LIFE	**	5	\$19,600	
<i>Water Penetration, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Shops</i>								
Exposed Struc: Steel	20%	Now	\$536,500	LIFE	**			
<i>Water Penetration, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Shops</i>								
Gypsum Board	5%	Now	\$9,800	LIFE	**	5	\$14,300	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Various 2nd Floor Offices</i>								
Plaster	10%	Now	\$13,600	LIFE	**	5	\$14,300	
<i>Water Penetration, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Administration Offices On 2nd Floor</i>								
Site Enclosure								
Fence/Gates								
Aluminum Rail	40%			2040	**	5-10	\$33,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Roof Railing</i>								
<i>Explanation : Location Noted</i>								
Chain Link	60%	Now	\$39,000	2045	**			
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 10%</i>								
<i>Location : East Parking Area At 57th Road</i>								
<i>Corrosion/Rusting, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : East Parking Area At 57th Road</i>								
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2048	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Garage Entrance At 58th Avenue</i>								
On-Site Walkways								
Cast in Place Concrete	100%	0-2	\$25,700	2040	**			
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Exit Stair To Parking Area On 58th Place</i>								
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Exit Walkway At 58th Place Near 57th Drive</i>								
<i>Spalling, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Exit Walkway At 58th Place Near 57th Drive</i>								
Parking/Driveway								
Asphalt	50%	0-2	\$69,600	2038	**			
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : West Lot At 58th Place And East Lot At 57th Drive</i>								
<i>Potholes, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : West Lot At 58th Place And East Lot At 57th Drive</i>								
Cast in Place Concrete	50%			2048	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MASPETH CENTRAL SHOP
Asset # : 169

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Under 600 Volts								
	Service Equipment							
	Fused Disc Sw	100%			2035	\$7,400	5	\$500
				<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
				<i>Location : Electrical Room</i>				
				<i>Explanation : Two Main Disconnect Switches Rated At 225 And 600 Amperes</i>				
	Switchgear / Switchboard							
	Molded Case Bkrs	100%			2035	\$95,300	5	\$2,900
	Raceway							
	Conduit	100%			2035	\$17,300	1	
	Panelboards							
	Molded Case Bkrs	100%			2034	\$58,500	5	\$2,900
	Wiring							
	Braided Cloth	30%	4+	\$10,600	2060	**	1	
				<i>Insulation Aged, Extent : Moderate, Area Affected : 100%</i>				
				<i>Location : Throughout The Building</i>				
	Thermoplastic	70%			2035	\$24,700	1	
	Motor Controllers							
	Locally Mounted	100%			2033	\$145,800	5	\$700
Ground								
	Grounding Devices							
	Generic	100%			LIFE	**	5	\$3,200
Lighting								
	Interior Lighting							
	Fluorescent	75%			2035	\$569,700	10	\$75,500
				<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>				
				<i>Location : Throughout The Building</i>				
	Fluorescent	20%			2040	**	10	\$20,100
				<i>T-5 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>				
				<i>Location : First Floor Driveway And Auto Repair Shop</i>				
	LED	5%			2040	**		
				<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
				<i>Location : First Floor - Women And Mens Restrooms</i>				
				<i>Explanation : LED Lights</i>				
	Egress Lighting							
	Emergency, Battery	50%	Now	\$9,000	2045	**		
				<i>Not Functioning, Extent : Moderate, Area Affected : 100%</i>				
				<i>Location : First Floor - By Artroom Annex</i>				
	Exit, Service	50%	Now	\$1,800	2045	**	1	
				<i>Lens/Guard Missing, Extent : Moderate, Area Affected : 50%</i>				
				<i>Location : First Floor - By Artroom Annex</i>				
				<i>Not Functioning, Extent : Moderate, Area Affected : 50%</i>				
				<i>Location : First Floor - By Fire Station N. 5</i>				
	Exterior Lighting							
	HID	20%			2030	\$100,100	10	\$100
	No Component	80%						

Alarm

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MASPETH CENTRAL SHOP
Asset # : 169

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Alarm								
Security System Generic	100%			2030	\$201,300	1	\$41,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Building, Exterior Walls - Building Perimeter</i>								
<i>Explanation : CCTV System Only</i>								
Fire/Smoke Detection Generic, Digital	100%			2030	\$276,600	1-3	\$69,700	
Mechanical								
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Heating								
Energy Source Natural Gas	15%			2045	**	1		
Interruptible Gas/Dual Fuel	85%	Now	\$4,200	2035	\$209,200	1		
<i>Controller Not Working, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Auto Switch, Boiler Room</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Backyard</i>								
<i>Explanation : One Tank, 10,000 Gallons, No.2 Oil</i>								
Conversion Equipment Hot Water Boiler	15%			2040	**	1	\$8,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor - Water Service Room</i>								
<i>Explanation : One Unit</i>								
Steam Boiler	85%			2033	\$794,500	1	\$92,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor - Boiler Room</i>								
<i>Explanation : Two Units</i>								
Distribution Hot Wtr Piping/Pump	15%			2043	**	4	\$1,200	
Steam Piping/Pump	85%			2035	\$729,900			
Terminal Devices								
Air Handler	1%			2030	\$20,200	1	\$700	
<i>Abandoned in Place, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout - 12 Units</i>								
Convactor/Radiator Unit Heater - Steam	15%			2040	**	1	\$5,300	
	84%			2040	**	4	\$8,400	
Controls								
Electrical	100%			2028	\$596,200			
Air Conditioning								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MASPETH CENTRAL SHOP
Asset # : 169

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Air Conditioning								
Energy Source								
Electricity	60%			2034	\$106,100	1		
No Component	40%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Service Areas</i>								
<i>Explanation : Location Noted</i>								
Conversion Equipment								
Exterior Pkg Unit - Cooling	5%			2040	**	2	\$300	
<i>R-410a Refrigerant, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof - One Unit</i>								
Ext Pkg Unit - Heating/Cooling	12%	0-2	\$21,600	2030	\$216,200	2	\$600	
<i>Malfunctioning, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof</i>								
<i>R-22 Refrigerant, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof - One Unit</i>								
Ext Pkg Unit - Heating/Cooling	12%	Now	\$43,200	2030	\$216,200	2	\$600	
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Roof - One Unit</i>								
<i>R-22 Refrigerant, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof</i>								
Ext Pkg Unit - Heating/Cooling	6%			2030	\$108,100	2	\$400	
<i>R-22 Refrigerant, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof</i>								
Split Unit	5%			2040	**			
<i>R-410a Refrigerant, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof - Two Units</i>								
Window/Wall Unit	20%			2030	\$81,300	1		
No Component	40%							
Ventilation								
Distribution								
Ductwork/Diffusers	100%			LIFE	**	2-5	\$96,900	
Exhaust Fans								
Roof	30%			2030	\$62,400	2	\$1,000	
<i>Abandoned in Place, Extent : Light, Area Affected : 10%</i>								
<i>Location : Roof</i>								
Roof	70%			2040	**	2	\$2,400	
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2035	\$1,377,300	1		
<i>On Extended Life, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MASPETH CENTRAL SHOP
Asset # : 169

Mechanical		Current Repair		Future Replacement		Maintenance			
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Plumbing									
Water Heater With Tanks									
	Electric	20%			2030	\$4,600	4		
	Gas Fired	40%			2033	\$6,700	2		
	Gas Fired	40%			2028	\$6,700	2		
<hr/>									
Sanitary Piping									
	Cast Iron	100%	Now	\$135,100	LIFE		**	1	
<i>Blockage /Clogged, Extent : Severe, Area Affected : 100%</i>									
<i>Location : 1st Floor</i>									
<i>On Extended Life, Extent : Light, Area Affected : 100%</i>									
<i>Location : Throughout</i>									
<hr/>									
Storm Drain Piping									
	Cast Iron	100%			LIFE		**	1	
<i>On Extended Life, Extent : Light, Area Affected : 100%</i>									
<i>Location : Throughout</i>									
<hr/>									
Sump Pump(s)									
	Non-Submersible	100%			2030	\$21,500	4	\$3,500	
<hr/>									
Fixtures									
	Generic	100%							
<i>Obsolete Fixtures, Extent : Light, Area Affected : 100%</i>									
<i>Location : Toilet Rooms</i>									
<hr/>									
Fire Suppression									
	Sprinkler								
	Generic	100%			2035	\$1,483,000	1-2	\$30,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : QUEENS FAMILY COURT GARAGE
Address : 150-07 ARCHER AVENUE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0207.000 / 14320 **Yr Built/Renovated** : 1990 /
Area Sq Ft : 74,000 **Project Type** : HIGHWAYS
Date of Survey : 04-Jan-2022 **Landmark Status** : NONE
Areas Surveyed : Floors 1,2,3,6
Block : 10092 **Lot** : 6 **BIN** : 4215603

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Interior Architecture	\$476,900	\$345,700
Electrical		\$919,300
Mechanical		\$67,600
Total	\$476,900	\$1,332,500
Importance Code B	\$476,900	\$1,332,500
Total	\$476,900	\$1,332,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$25,800		\$7,200	
Interior Architecture	\$52,900	\$300		
Electrical	\$3,700	\$2,800	\$3,900	\$2,800
Mechanical	\$6,900		\$54,500	
Site Pavements	\$19,200			
Elevators/Escalators	\$7,700	\$7,700	\$7,700	\$7,700
Total	\$116,200	\$10,700	\$73,300	\$10,500
Importance Code A	\$25,800		\$8,200	
Importance Code B	\$86,800	\$10,700	\$65,100	\$10,500
Importance Code C	\$3,600			
Total	\$116,200	\$10,700	\$73,300	\$10,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS FAMILY COURT GARAGE
Asset # : 14320

Architecture		Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost		
Exterior									
Exterior Walls									
Cast in Place Concrete	20%			LIFE	**	5	\$28,600		
<i>Paint Peeling, Extent : Light, Area Affected : 10%</i>									
<i>Location : All Facades</i>									
Concrete Masonry Unit	20%			LIFE	**	5	\$3,600		
Exposed Struc: Steel	8%	4+	\$3,900	LIFE	**	5	\$7,100		
<i>Corrosion/Rusting, Extent : Light, Area Affected : 10%</i>									
<i>Location : Throughout Interior Of Garage</i>									
Masonry: Brick	15%			LIFE	**	5	\$4,300		
Metal Panel	5%			2053	**	5-10	\$9,800		
Metal Sect. OHD	2%			2046	**	5	\$1,800		
Metal: Cage/Fence	25%			2046	**	5	\$31,300		
Window Wall	5%			2053	**	5	\$5,400		
Parapets									
Cast in Place Concrete	20%			LIFE	**	5	\$3,500		
Masonry: Brick	10%			LIFE	**	5	\$200		
Metal: Cage/Fence	70%			2046	**	5-10	\$9,300		
Roof									
Cast in Place Concrete	95%			LIFE	**				
Single Ply Membrane	5%			2038	**	10	\$1,800		
Interior									
Floors									
Asphalt Poured	21%	2-4	\$38,300	2046	**	5	\$5,300		
<i>Worn/Eroded, Extent : Moderate, Area Affected : 20%</i>									
<i>Location : Throughout</i>									
Cast in Place Concrete	75%	4+	\$313,900	LIFE	**	5	\$165,300		
<i>Horizontal Cracks, Extent : Light, Area Affected : 10%</i>									
<i>Location : Throughout</i>									
<i>Water Penetration, Extent : Light, Area Affected : 5%</i>									
<i>Location : Throughout</i>									
Ceramic Tile	2%	Now	\$11,100	2036	**	5	\$1,000		
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 5%</i>									
<i>Location : Toilet Room</i>									
<i>Worn/Eroded, Extent : Moderate, Area Affected : 100%</i>									
<i>Location : Toilet Room</i>									
Vinyl Tile	2%			2033		3	\$800		
Interior Walls									
Cast in Place Concrete	25%	Now	\$3,600	LIFE	**				
<i>Horizontal Cracks, Extent : Light, Area Affected : 10%</i>									
<i>Location : Throughout</i>									
Concrete Masonry Unit	75%			LIFE	**	5	\$2,900		
Ceilings									
Metal Panel	100%	Now	\$163,000	LIFE	**	5	\$126,000		
<i>Corrosion/Rusting, Extent : Moderate, Area Affected : 10%</i>									
<i>Location : Throughout Garage Interior</i>									

Site Pavements

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS FAMILY COURT GARAGE
Asset # : 14320

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	75%	4+	\$5,700	2046		**		
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Sinking/Subsiding, Extent : Light, Area Affected : 2%</i>								
<i>Location : West Side</i>								
Pavers/Stone	25%	0-2	\$13,400	2036		**		
<i>Sinking/Subsiding, Extent : Light, Area Affected : 10%</i>								
<i>Location : North Side</i>								
Parking/Driveway								
Cast in Place Concrete	100%			2046		**		

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2043		**	5	\$300
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Electrical Room Lower Level</i>								
<i>Explanation : One 800 Ampere Main Disconnect Switch</i>								
Switchgear / Switchboard								
Molded Case Bkrs	100%			2043		**	5	\$1,900
Raceway								
Conduit	100%			2043		**	1	
Panelboards								
Molded Case Bkrs	100%			2041		**	5	\$1,900
Wiring								
Thermoplastic	100%			2043		**	1	
Lighting								
Interior Lighting								
Fluorescent	10%			2033	\$46,600		10	\$6,200
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Office, Stairwells And Electrical Room</i>								
HID	90%			2033	\$700,800		10	\$2,000
Egress Lighting								
Emergency, Battery	75%			2033	\$82,800		10	\$12,200
Exit, Battery	25%			2033	\$19,000		10	\$1,100
Exterior Lighting								
HID	10%			2033	\$33,700		10	
No Component	90%							
Alarm								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS FAMILY COURT GARAGE
Asset # : 14320

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Ventilation								
Exhaust Fans								
Interior	2%			2028	\$5,800	2		
		<i>On Extended Life, Extent : Light, Area Affected : 100%</i>						
		<i>Location : 1st Level - Garage Restroom</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 1st Level - Garage Restroom</i>						
		<i>Explanation : 1 Unit, Ceiling Mounted</i>						
Wall Unit	2%			2028	\$600	2		
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Elevator Machine Room</i>						
		<i>Explanation : 1 Unit</i>						
No Component	96%							
Plumbing								
H/C Water Piping								
Brass/Copper	8%			2033	\$67,600	1		
No Component	92%							
Water Heater With Tanks								
Electric	8%			2026	\$1,800	4		
		<i>On Extended Life, Extent : Light, Area Affected : 100%</i>						
		<i>Location : 1st Level - Garage Restroom</i>						
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : 1st Level - Garage Restroom</i>						
		<i>Explanation : 10 Gallons - 1 Unit, Quantity 1</i>						
No Component	92%							
Sanitary Piping								
Cast Iron	8%			LIFE	**	1		
No Component	92%							
Storm Drain Piping								
Cast Iron	100%			LIFE	**	1		
Fixtures								
No Component	92%							
Generic	8%							
Vertical Transport								
Elevators								
Hydraulic	100%			LIFE	**			
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : 1st To 6th Floor</i>						
		<i>Explanation : 1 Unit</i>						
Fire Suppression								
Standpipe								
Generic	100%			2043	**	1-5	\$300	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Dry Standpipe</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : STATEN ISLAND COURTHOUSE GARAGE
Address : 54 CENTRAL AVE.
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0210.000 / 14557 **Yr Built/Renovated** : 2010 /
Area Sq Ft : 223,760 **Project Type** : HIGHWAYS
Date of Survey : 23-Jun-2020 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2
Block : 6 **Lot** : 21 **BIN** : 5151736

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$106,100	\$453,700
Interior Architecture	\$534,200	\$703,300
Electrical	\$340,900	
Mechanical	\$415,200	\$3,431,600
Total	\$1,396,200	\$4,588,700
Importance Code A	\$106,100	\$453,700
Importance Code B	\$1,290,200	\$4,134,900
Total	\$1,396,200	\$4,588,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture				\$25,800
Interior Architecture		\$800		\$3,000
Electrical	\$61,700	\$7,900	\$4,200	\$4,900
Mechanical	\$50,100	\$11,200	\$38,200	\$7,100
Elevators/Escalators	\$14,900	\$14,900	\$14,900	\$14,900
Total	\$126,700	\$34,900	\$57,300	\$55,700
Importance Code A	\$12,900		\$12,500	\$25,800
Importance Code B	\$113,800	\$34,900	\$44,800	\$29,900
Importance Code C				
Total	\$126,700	\$34,900	\$57,300	\$55,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
STATEN ISLAND COURTHOUSE GARAGE
Asset # : 14557

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Cast in Place Concrete	77%	4+	\$106,100	LIFE	**	5	\$453,700	
<i>Caulking Deteriorated, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : South Elevation</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : South Elevation</i>								
Masonry: Limestone	3%			LIFE	**	5	\$2,700	
Metal/Glass Curt Wall	10%			LIFE	**	5	\$22,100	
Metal: Cage/Fence	10%			2044	**	5	\$51,600	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Installed To Promote Vegetation Growth</i>								
Windows								
Aluminum	2%			2047	**	5		
No Component	98%							
Parapets								
Cast in Place Concrete	100%			LIFE	**	5	\$21,300	
Roof								
Cast in Place Concrete	100%			LIFE	**			
Soffits								
Glass: Special Gauge	100%			LIFE	**	1		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : North Elevation</i>								
<i>Explanation : Glass And Metal Entry Awning</i>								
Interior								
Floors								
Cast in Place Concrete	96%	4+	\$534,200	LIFE	**	5	\$703,300	
<i>Water Penetration, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Mechanical Water Service Room</i>								
Ceramic Tile	2%			2040	**	5	\$6,700	
Vinyl Tile	2%			2036	**	3	\$2,500	
Interior Walls								
Cast in Place Concrete	80%			LIFE	**			
Ceramic Tile	2%			2040	**	5	\$2,200	
Concrete Masonry Unit	10%			LIFE	**	5	\$4,400	
Gypsum Board	2%			LIFE	**	5	\$1,300	
Metal: Cage/Fence	6%			LIFE	**			
Ceilings								
AcousTileSusp.Lay-In	2%			2044	**	5	\$6,100	
Exposed Struc: Concrete	98%			LIFE	**	5	\$46,400	
Site Enclosure								
Fence/Gates								
Chain Link	100%			2051	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
STATEN ISLAND COURTHOUSE GARAGE
Asset # : 14557

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Site Enclosure								
Retaining Walls								
Cast in Place Concrete	100%			2066		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : East And West Elevations</i>						
		<i>Explanation : These Are Actually Planters</i>						
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2044		**		
On-Site Walkways								
Cast in Place Concrete	100%			2044		**		
Parking/Driveway								
Asphalt	100%			2040		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : South Side Of Property</i>						
		<i>Explanation : This Is Actually An Outdoor Parking Area At Grade.</i>						
Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	100%			2051		**	5	\$1,000
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Electrical Room</i>						
		<i>Explanation : One 1,200 Ampere Main Disconnect Switch</i>						
Switchgear / Switchboard								
Fused Disc Sw	100%			2051		**	5	\$1,000
Raceway								
Conduit	100%			2051		**	1	
Panelboards								
Fused Disc Sw	10%			2047		**	5	\$500
Molded Case Bkrs	90%			2047		**	5	\$5,300
Wiring								
Thermoplastic	100%			2051		**	1	
Motor Controllers								
Locally Mounted	100%			2044		**	5	\$1,500
Ground								
Grounding Devices								
Generic	100%			LIFE		**	5	\$3,300
Lighting								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
STATEN ISLAND COURTHOUSE GARAGE
Asset # : 14557

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Interior Lighting Fluorescent	10%			2036	**	10	\$20,500	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Office, Staircase, Mechanical Room And Electrical Room</i>								
HID	50%	Now	\$258,800	2036	**			
<i>Damaged Fixtures, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
HID	40%			2036	**	10	\$2,900	
Egress Lighting								
Emergency, Battery	50%			2036	**	10	\$27,000	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Electrical Room 108</i>								
<i>Explanation : Emergency Battery Power Supplies - Lighting And Elevators</i>								
Exit, Service	50%	Now	\$3,700	2036	**	1		
<i>Damaged Fixtures, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Exterior Lighting								
HID	20%	4+	\$4,100	2036	**			
<i>Outdr Lights On During Daytime, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Roof Lighting Controls Malfunction</i>								
No Component	80%							
Alarm								
Security System								
No Component	80%							
Generic	20%	Now	\$82,000	2036	**	1	\$15,000	
<i>Cameras Damaged, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Fire/Smoke Detection								
No Component	80%							
Generic, Digital	20%			2036	**	1-3	\$27,600	

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source Electricity	100%			2051	**	1		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
STATEN ISLAND COURTHOUSE GARAGE
Asset # : 14557

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Heating								
	Conversion Equipment							
	Radiant Heater	60%			2036	**	2	\$62,300
			<i>Other Observation, Extent : Light, Area Affected : 60%</i>					
			<i>Location : Garage Office And Restrooms</i>					
			<i>Explanation : Electric Baseboard And Unit Heaters</i>					
	No Component	40%						
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location :</i>					
			<i>Explanation : Noted Under Split Unit In Air Conditioning</i>					
	Terminal Devices							
	Fan Coil Unit/Heat	40%			2031	\$1,300,400	1	\$28,900
	No Component	60%						
Air Conditioning								
	Energy Source							
	Electricity	100%			2047	**	1	
	Conversion Equipment							
	Split Unit	40%	Now	\$415,200	2031	\$2,075,800		
			<i>Malfunctioning, Extent : Severe, Area Affected : 50%</i>					
			<i>Location : Managers Office</i>					
	No Component	60%						
Ventilation								
	Distribution							
	Ductwork/Diffusers	100%			LIFE	**	2-5	\$124,800
	Exhaust Fans							
	Interior	100%			2036	**	2	\$6,900
Plumbing								
	H/C Water Piping							
	Brass/Copper	100%			2051	**	1	
	Water Heater With Tanks							
	Not Accessible	100%						
	Sanitary Piping							
	Cast Iron	100%			LIFE	**	1	
	Storm Drain Piping							
	Cast Iron	100%			LIFE	**	1	
	Fixtures							
	Generic	100%						
Vertical Transport								
	Elevators							
	Hydraulic	100%			LIFE	**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Northeast Corner Of Garage</i>					
			<i>Explanation : 2 Units</i>					
Fire Suppression								
	Standpipe							
	Generic	100%			2051	**	1-5	\$112,800

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : STATEN ISLAND SIGN SHOP
 Address : 34 WAVE STREET BTWN BAY ST. - S.I. RAILWAY
 Borough : STATEN ISLAND Agency's Number : N/A
 Program / Asset # : DOT0219.000 / 14717 Yr Built/Renovated : 1951 /
 Area Sq Ft : 12,800 Project Type : HIGHWAYS
 Date of Survey : 07-Oct-2021 Landmark Status : NONE
 Areas Surveyed : Roof, Floors 1
 Block : 489 Lot : 48 BIN : 5013187

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$303,400	
Interior Architecture	\$1,763,700	
Total	\$2,067,200	
Importance Code A	\$303,400	
Importance Code B	\$1,681,500	
Importance Code C	\$82,200	
Total	\$2,067,200	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$6,200		\$19,900	\$1,500
Interior Architecture	\$3,000			\$100
Electrical	\$500	\$600	\$14,700	\$500
Mechanical	\$19,400	\$1,800	\$2,600	\$1,800
Site Pavements	\$14,600			
Total	\$43,800	\$2,400	\$37,200	\$3,800
Importance Code A	\$7,100	\$1,000	\$20,900	\$2,400
Importance Code B	\$36,600	\$1,500	\$16,300	\$1,400
Importance Code C				
Total	\$43,800	\$2,400	\$37,200	\$3,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
STATEN ISLAND SIGN SHOP
Asset # : 14717

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Concrete Masonry Unit	40%	Now	\$83,000	LIFE	**	5	\$9,900	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Masonry: Brick	50%	Now	\$159,300	LIFE	**	5	\$19,800	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Wave Street And Sand Street Facades</i>								
<i>Joint Mortar Miss/Erod, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Front Facade On Wave Street</i>								
<i>Painted Surfaces, Extent : Light, Area Affected : 75%</i>								
<i>Location : Facades</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Wave Street</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : North Side Alley</i>								
<i>Other Observation, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Wave Street Facade</i>								
<i>Explanation : Facade Appears To Be Pulling Away</i>								
Metal Coiling Doors	10%			2046	**	5	\$12,400	
Windows								
Aluminum	100%			2049	**	5	\$2,900	
Parapets								
Cast Stone/Terra Cotta	10%			LIFE	**	5	\$4,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Coping Stones Of Parapet Wall</i>								
<i>Explanation : Covered With Metal Panning</i>								
Masonry: Brick	90%	Now	\$61,200	LIFE	**	5	\$4,900	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Front Facade</i>								
Roof								
Modified Bitumen	100%			2038	**	10	\$19,900	
Interior								
Floors								
Cast in Place Concrete	95%	0-2	\$335,300	LIFE	**	5	\$44,100	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Quarry Tile	1%			2046	**	5	\$300	
Vinyl Tile	4%	0-2	\$2,300	2038	**	3	\$300	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
STATEN ISLAND SIGN SHOP
Asset # : 14717

Architecture	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Interior

Interior Walls

Cast in Place Concrete	5%			LIFE	**			
Concrete Masonry Unit	95%	Now	\$82,200	LIFE	**	5	\$7,200	

Cracking/Crumbling, Extent : Light, Area Affected : 10%

Location : Throughout

Vertical Cracks, Extent : Moderate, Area Affected : 10%

Location : Throughout

Ceilings

AcousTileSusp.Lay-In	5%			2046	**	5	\$1,100	
Exposed Struc: Wood	95%	Now	\$1,346,300	LIFE	**			

Split/Cracked, Extent : Severe, Area Affected : 10%

Location : Ceiling

Other Observation, Extent : Light, Area Affected : 5%

Location : Interior Of Building

Explanation : Wood Truss Failing Temp Repairs Of Bow String Truss

Site Enclosure

Fence/Gates

Chain Link	100%			2053	**			
------------	------	--	--	------	----	--	--	--

Site Pavements

Public Sidewalk

Cast in Place Concrete	100%	Now	\$14,600	2046	**			
------------------------	------	-----	----------	------	----	--	--	--

Cracking/Crumbling, Extent : Severe, Area Affected : 10%

Location : Sands Street

Parking/Driveway

Cast in Place Concrete	100%			2046	**			
------------------------	------	--	--	------	----	--	--	--

Electrical

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Service Equipment

Fused Disc Sw	100%			2033	\$3,700	5	\$100	
---------------	------	--	--	------	---------	---	-------	--

Other Observation, Extent : Light, Area Affected : 100%

Location : Garage

Explanation : Two 400 Ampere Main Disconnect Switches

Raceway

Conduit	100%			2033	\$4,300	1		
---------	------	--	--	------	---------	---	--	--

Panelboards

Fused Disc Sw	5%			2032	\$500	5		
Molded Case Bkrs	95%			2032	\$9,300	5	\$300	

Wiring

Thermoplastic	100%			2033	\$8,800	1		
---------------	------	--	--	------	---------	---	--	--

Motor Controllers

Locally Mounted	100%			2031	\$22,400	5	\$100	
-----------------	------	--	--	------	----------	---	-------	--

Lighting

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
STATEN ISLAND SIGN SHOP
Asset # : 14717

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Lighting

Interior Lighting

LED	100%			2041	**			
-----	------	--	--	------	----	--	--	--

Egress Lighting

Emergency, Battery	50%			2028	\$10,500	10	\$1,500	
--------------------	-----	--	--	------	----------	----	---------	--

Exit, Service	50%			2028	\$2,100	1		
---------------	-----	--	--	------	---------	---	--	--

Exterior Lighting

LED	100%			2041	**			
-----	------	--	--	------	----	--	--	--

Alarm

Security System

Generic	100%			2041	**	1	\$4,800	
---------	------	--	--	------	----	---	---------	--

*Other Observation, Extent : Light, Area Affected : 100%**Location : Throughout The Building**Explanation : Intrusion System*

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Heating

Energy Source

Natural Gas	100%			2059	**	1		
-------------	------	--	--	------	----	---	--	--

Conversion Equipment

Furnace	50%			2038	**	1	\$3,200	
---------	-----	--	--	------	----	---	---------	--

Steam Boiler	50%			2050	**	1	\$6,300	
--------------	-----	--	--	------	----	---	---------	--

Distribution

Central Plant Steam Piping/Pmp	100%	0-2	\$17,600	2053	**	4	\$600	
--------------------------------	------	-----	----------	------	----	---	-------	--

*Leak Evident, Extent : Moderate, Area Affected : 5%**Location : Leaking Steam Piping*

Terminal Devices

Convactor/Radiator	80%			2046	**	1	\$3,300	
--------------------	-----	--	--	------	----	---	---------	--

Unit Heater - Steam	20%			2038	**	4	\$400	
---------------------	-----	--	--	------	----	---	-------	--

Air Conditioning

Energy Source

Electricity	100%			2049	**	1		
-------------	------	--	--	------	----	---	--	--

Conversion Equipment

Window/Wall Unit	5%			2031	\$2,400	1		
------------------	----	--	--	------	---------	---	--	--

No Component	95%							
--------------	-----	--	--	--	--	--	--	--

Ventilation

Distribution

Ductwork/Diffusers	100%			LIFE	**	2-5	\$7,100	
--------------------	------	--	--	------	----	-----	---------	--

Exhaust Fans

Interior	100%			2038	**	2	\$400	
----------	------	--	--	------	----	---	-------	--

Plumbing

H/C Water Piping

Brass/Copper	100%			2053	**	1		
--------------	------	--	--	------	----	---	--	--

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
STATEN ISLAND SIGN SHOP
Asset # : 14717

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Plumbing								
	Water Heater With Tanks							
	Gas Fired	100%			2031	\$16,700	2	
	Sanitary Piping							
	Cast Iron	100%			LIFE	* *	1	
	Storm Drain Piping							
	Not Accessible	100%						
	Sump Pump(s)							
	Non-Submersible	100%			2038	* *	4	\$400
	Fixtures							
	Generic	100%						
Fire Suppression								
	Sprinkler							
	Generic	100%			2053	* *	1-2	\$3,600

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SUNRISE YARD
Address : 88-26 PITKIN AVE.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0208.000 / 14436 **Yr Built/Renovated** : 2009 /
Area Sq Ft : 25,000 **Project Type** : HIGHWAYS
Date of Survey : 20-Sep-2022 **Landmark Status** : NONE
Areas Surveyed : Floors 1,2
Block : 11368 **Lot** : 20 **BIN** : 4863171

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Interior Architecture		\$55,000
Electrical		\$235,900
Mechanical	\$210,400	\$909,000
Total	\$210,400	\$1,200,000
Importance Code B	\$210,400	\$1,200,000
Total	\$210,400	\$1,200,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$45,400			
Interior Architecture	\$12,500	\$6,300	\$5,100	
Electrical	\$2,300	\$2,400	\$2,800	\$2,700
Mechanical	\$51,000	\$25,800	\$11,200	\$34,100
Elevators/Escalators	\$7,200	\$7,200	\$7,200	\$7,200
Total	\$118,500	\$41,700	\$26,400	\$44,000
Importance Code A	\$71,400	\$1,200	\$1,200	\$1,300
Importance Code B	\$47,100	\$40,400	\$21,000	\$42,700
Importance Code C			\$4,100	
Total	\$118,500	\$41,700	\$26,400	\$44,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE YARD
Asset # : 14436

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Concrete Masonry Unit	25%			LIFE	**	5		
Masonry: Brick Cavity	27%			LIFE	**	5		
Metal Panel	10%			2054	**	5-10		
Metal Coiling Doors	5%			2047	**	5		
Pre-Cast Concrete	3%			LIFE	**	5		
Window Wall	30%			2054	**	5		
Windows								
Aluminum	95%			2050	**	5		
Metal Louvers	5%			2043	**	10		
Roof								
Metal Panel	100%	Now	\$45,400	2047	**			
<i>Gut/DS Non Func/Miss, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Over Offices North Side</i>								
<i>Water Penetration, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Offices On West Facade</i>								
Soffits								
Aluminum Sunshades	5%			2043	**	10		
Metal Panel	95%			2054	**	5-10		
Interior								
Floors								
Carpet	20%			2033	\$133,700	3	\$11,600	
Cast in Place Concrete	65%			LIFE	**	5	\$55,000	
Ceramic Tile	5%			2043	**	5	\$1,900	
Vinyl Tile	10%			2039	**	3	\$1,500	
Interior Walls								
Ceramic Tile	10%			2043	**	5	\$8,300	
Concrete Masonry Unit	50%			LIFE	**	5	\$16,600	
Glass: Single Pane	15%			LIFE	**	5	\$9,300	
Gypsum Board	10%			LIFE	**	5	\$5,000	
Masonry: Brick	10%			LIFE	**			
SGFT/Glazed Masonry	5%			LIFE	**			
Ceilings								
AcousTileSusp.Lay-In	10%			2047	**	5	\$3,900	
Exposed Struc: Steel	40%			LIFE	**			
Metal Panel	50%	4+	\$12,500	LIFE	**	5	\$24,200	
<i>Water Penetration, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Offices At West Side</i>								
Site Enclosure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE YARD
Asset # : 14436

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Site Enclosure								
Fence/Gates								
Chain Link	75%			2054	**			
<i>Other Observation, Extent : N/A, Area Affected : 75%</i>								
<i>Location : Perimeter</i>								
<i>Explanation : Actually Welded Wire Mesh</i>								
Iron Picket	25%			2069	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Along Sitka Street</i>								
<i>Explanation : Actually Metal Grating Type Fence</i>								
Free Standing Walls								
Cast in Place Concrete	90%			2069	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Along Pitkin Avenue</i>								
<i>Explanation : Decorative Brick And Gravel Finish On One Side Of Wall</i>								
Masonry: Brick	10%			2054	**			
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%			2047	**			
On-Site Walkways								
Cast in Place Concrete	100%			2047	**			
Parking/Driveway								
Asphalt	50%			2043	**			
Cast in Place Concrete	50%			2047	**			

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment								
Fused Disc Sw	90%			2054	**	5	\$100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Electrical Room 116 B</i>								
<i>Explanation : Main Service Disconnect Switch Rated At 400 Amperes.</i>								
Photovoltaic Panel(s)	10%			2043	**	1		
Switchgear / Switchboard								
Molded Case Bkrs	100%			2054	**	5	\$700	
Raceway								
Conduit	100%			2054	**	1		
Panelboards								
Molded Case Bkrs	100%			2050	**	5	\$700	
Wiring								
Thermoplastic	100%			2054	**	1		
Motor Controllers								
Locally Mounted	70%			2047	**	5	\$100	
Variable Frequency Drive	30%			2047	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE YARD
Asset # : 14436

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Ground								
Grounding Devices Generic	100%			LIFE	**	5	\$400	
Lighting								
Interior Lighting Fluorescent	90%			2034	\$155,700	10	\$20,600	
<i>T-8 Lamps And Fixtures, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout The Building</i>								
Fluorescent	10%			2034	\$17,300	10	\$2,300	
<i>Compact Fluorescent Light, Extent : Light, Area Affected : 100%</i>								
<i>Location : Offices</i>								
Egress Lighting								
Emergency, Battery	50%			2034	\$20,500	10	\$3,000	
Exit, Battery	50%			2034	\$14,100	10	\$800	
Exterior Lighting								
Fluorescent	15%			2034	\$14,600	10	\$300	
<i>Compact Fluorescent Light, Extent : Light, Area Affected : 100%</i>								
<i>Location : Building Perimeter</i>								
HID	1%			2034	\$1,100	10		
LED	4%			2034	\$5,200			
No Component	80%							
Alarm								
Security System Generic	100%			2034	\$45,800	1	\$9,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Garage And Outside Perimeter</i>								
<i>Explanation : CCTV Surveillance System</i>								
Fire/Smoke Detection								
Generic, Digital	100%			2034	\$63,000	1-3	\$15,400	

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Energy Source Natural Gas	100%			2054	**	1		
Conversion Equipment Hot Water Boiler	100%	Now	\$25,900	2047	**	1	\$11,100	
<i>Unit Inoperable, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : 1st Floor - Boiler Room, 1 Unit</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 1st Floor - Boiler Room</i>								
<i>Explanation : 2 Units, Condensing Boilers</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE YARD
Asset # : 14436

Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Distribution								
Hot Wtr Piping/Pump	100%	Now	\$10,700	2050	**	4	\$1,200	
<i>Leak Evident, Extent : Severe, Area Affected : 5%</i>								
<i>Location : 1st Floor - Boiler Room - Glycol Pump</i>								
<i>Unit Inoperable, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : 1st Floor - Boiler Room - 2 Glycol Plate Heat Exchangers Bypassed / Disconnected</i>								
<hr/>								
Terminal Devices								
Air Handler	45%			2039	**	1	\$7,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 2nd Floor Mechanical Platform</i>								
<i>Explanation : Heating And Ventilating Units</i>								
Convactor/Radiator	25%			2047	**	1	\$2,000	
Unit Heater - Hot Water	5%			2034	\$7,200			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Administrative Area - Stairs, 1st Floor - Boiler Room</i>								
<i>Explanation : Cabinet / Unit Heaters</i>								
No Component	25%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Shop Area</i>								
<i>Explanation : Hydronic Radiant Flooring, Manifolds Located In Mechanical Closets</i>								
<hr/>								
Controls								
Digital	100%	Now	\$210,400	2032	\$701,300			
<i>Broken, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Mechanical Closets - Radiant Flooring Manifolds Control Valves</i>								
<i>Malfunctioning, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout - System Not Operational</i>								
<hr/>								
Air Conditioning								
Energy Source								
Electricity	30%			2050	**	1		
No Component	70%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Storage And Shop Areas</i>								
<i>Explanation : Location Noted</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE YARD
Asset # : 14436

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Air Conditioning								
Conversion Equipment								
	Heat Pump Air Sourced	4%			2039	**	2	\$100
				<i>R-410a Refrigerant, Extent : Light, Area Affected : 100%</i>				
				<i>Location : Various Locations</i>				
				<i>Recent Installation, Extent : N/A, Area Affected : 100%</i>				
				<i>Location : Outdoor Unit - Building Exterior On Grade, Indoor Units - Various Locations</i>				
				<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
				<i>Location : Building Exterior On Grade</i>				
				<i>Explanation : 6 Tons Variable Refrigerant Flow System. There Is An Additional Outdoor Unit Under Construction</i>				
	Int Pkg Unit - Heating/Cooling	25%			2032	\$99,500	2	\$400
				<i>Other Observation, Extent : Light, Area Affected : 100%</i>				
				<i>Location : Mechanical Equipment Room 108</i>				
				<i>Explanation : R-407c Refrigerant</i>				
	Split Unit	1%			2034	\$5,800		
				<i>R-410a Refrigerant, Extent : Light, Area Affected : 100%</i>				
				<i>Location : Outdoor Unit - 2nd Floor Mechanical Platform, Indoor Unit - Office 119</i>				
	No Component	70%						
Terminal Devices								
	Fan Coil - 2 Pipe	3%			2044	**	1	\$200
				<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
				<i>Location : Various Locations</i>				
				<i>Explanation : Variable Refrigerant Flow Fan Coils, Recent Installation</i>				
	No Component	97%						
Ventilation								
Distribution								
	Ductwork/Diffusers	100%			LIFE	**	2-5	\$13,900
Exhaust Fans								
	Interior	100%			2034	\$108,300	2	\$800
Plumbing								
H/C Water Piping								
	Brass/Copper	100%			2054	**	1	
Water Heater With Tanks								
	Gas Fired	100%			2027	\$16,700	2	
				<i>On Extended Life, Extent : Light, Area Affected : 100%</i>				
				<i>Location : 1st Floor - Boiler Room</i>				
				<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
				<i>Location : 1st Floor - Boiler Room</i>				
				<i>Explanation : 1 Unit, 80 Gallons</i>				
Sanitary Piping								
	Cast Iron	100%			LIFE	**	1	
Storm Drain Piping								
	Cast Iron	100%			LIFE	**	1	
Backflow Preventer								
	Generic	100%			2034	\$10,900	1	\$1,500

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE YARD
Asset # : 14436

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Plumbing								
Fixtures								
	Generic	100%						
Vertical Transport								
Elevators								
	Hydraulic	100%			LIFE	**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : 1st To 2nd Floor</i>					
			<i>Explanation : 1 Unit</i>					
Fire Suppression								
Standpipe								
	Generic	100%			2054	**	1-5	\$12,600
Sprinkler								
	Generic	100%			2054	**	1-2	\$7,000
Chemical System								
	Dry	100%			2029	\$15,900	1-3	\$78,900
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Above Gas Pump</i>					
			<i>Explanation : 20 Square Feet</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEBSTER AVENUE FLEET SERVICES MAINTENANCE AND REPAIR SHOP
Address : 2144 WEBSTER AVENUE @E. 181 STREET
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0097.000 / 2847 **Yr Built/Renovated** : 2002 /
Area Sq Ft : 46,400 **Project Type** : HIGHWAYS
Date of Survey : 29-Oct-2020 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2
Block : 3030 **Lot** : 6 **BIN** : 2011133

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$317,000	\$256,500
Interior Architecture	\$4,877,900	\$127,500
Electrical	\$542,600	\$63,500
Site Pavements	\$60,600	
Total	\$5,798,100	\$447,500
Importance Code A	\$317,000	\$256,500
Importance Code B	\$5,044,900	\$191,000
Importance Code C	\$436,200	
Total	\$5,798,100	\$447,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$82,300			
Interior Architecture	\$43,500			\$1,000
Electrical	\$1,500	\$64,300	\$900	\$900
Mechanical	\$7,300	\$29,900	\$7,800	\$6,500
Elevators/Escalators	\$7,200	\$7,200	\$7,200	\$7,200
Total	\$141,800	\$101,400	\$15,800	\$15,600
Importance Code A	\$85,800	\$2,300	\$1,100	\$2,200
Importance Code B	\$46,200	\$99,100	\$14,700	\$13,400
Importance Code C	\$9,800			
Total	\$141,800	\$101,400	\$15,800	\$15,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE FLEET SERVICES MAINTENANCE AND REPAIR SHOP
Asset # : 2847

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Exterior								
Exterior Walls								
Concrete Masonry Unit	65%			LIFE	**	5	\$27,400	
Glass Block	5%	Now	\$6,700	LIFE	**	5	\$2,100	
<i>Water Penetration, Extent : Light, Area Affected : 5%</i>								
<i>Location : Main Garage</i>								
Metal Panel	15%	Now	\$13,100	2052	**	5	\$19,000	
<i>Deformed/Dented, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Garage Entry Area</i>								
Metal Coiling Doors	10%	Now	\$35,200	2045	**	5	\$10,600	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 20%</i>								
<i>Location : Dented Near Bottom</i>								
Pre-Cast Concrete	5%			LIFE	**	5	\$11,000	
Windows								
Fiberglass Panel	90%	Now	\$10,900	2048	**	5	\$9,500	
<i>Water Penetration, Extent : Light, Area Affected : 5%</i>								
<i>Location : Over Main Shop</i>								
Metal Louvers	10%			2041	**	10	\$3,500	
Parapets								
Concrete Masonry Unit	20%			LIFE	**	5	\$2,400	
Masonry: Brick	25%	Now	\$16,400	LIFE	**	5	\$2,700	
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 10%</i>								
<i>Location : Along Flashing</i>								
Metal Security Bars	30%			2060	**			
Pre-Cast Concrete	25%			LIFE	**	5	\$16,700	
Roof								
Built-Up (BUR)	35%	Now	\$128,200	2032	\$256,500			
<i>Alligatoring, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Roof Above Second Floor</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
Metal Panel	55%	Now	\$100,500	2045	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Fascia At North Side</i>								
<i>Miss/Damaged Flashings, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
Skylight, Metal/Glass	10%	Now	\$88,200	2052	**			
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Over Stair</i>								

Interior

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE FLEET SERVICES MAINTENANCE AND REPAIR SHOP
Asset # : 2847

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Interior								
Floors								
Cast in Place Concrete	85%	Now	\$96,800	LIFE	**	5	\$127,500	
<i>Water Penetration, Extent : Light, Area Affected : 20%</i>								
<i>Location : At Truck Washing Area</i>								
Ceramic Tile	3%	2-4	\$5,700	2041	**	5	\$1,000	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : At Work Bays</i>								
Vinyl Tile	12%	Now	\$22,200	2037	**	3	\$3,100	
<i>Cracking/Crumbling, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Office Areas</i>								
Interior Walls								
Concrete Masonry Unit	60%	Now	\$311,900	LIFE	**	5	\$27,200	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Near Truck Wash Area And Entry</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Glass: Single Pane	5%	Now	\$6,700	LIFE	**	5	\$4,200	
<i>Glazing Broken/Cracked, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Conference Room</i>								
Gypsum Board	10%	Now	\$3,100	LIFE	**	5	\$6,800	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Second Floor</i>								
SGFT/Glazed Masonry	25%	Now	\$124,300	LIFE	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Garage</i>								
Ceilings								
Exposed Struc: Steel	90%	Now	\$4,344,900	LIFE	**			
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Garage</i>								
Gypsum Board	10%	Now	\$5,900	LIFE	**	5	\$8,600	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Stair</i>								
<i>Water Penetration, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Womens Locker Room</i>								
Site Pavements								
Public Sidewalk								
Cast in Place Concrete	100%	4+	\$60,600	2045	**			
<i>Cracking/Crumbling, Extent : Light, Area Affected : 25%</i>								
<i>Location : Front Sidewalk</i>								

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE FLEET SERVICES MAINTENANCE AND REPAIR SHOP
Asset # : 2847

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Under 600 Volts								
Service Equipment Fused Disc Sw	100%			2032	\$14,700	5	\$200	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : Main Service Switch Rated At 2500 Amperes.</i>								
Switchgear / Switchboard Molded Case Bkrs	100%			2032	\$63,500	5	\$1,200	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : 2 Sections Of Main Distribution Board</i>								
Raceway Conduit	100%			2032	\$36,000	1		
Panelboards Fused Disc Sw	5%			2031	\$2,400	5	\$100	
Molded Case Bkrs	95%			2031	\$46,000	5	\$1,200	
Wiring Thermoplastic	100%			2032	\$32,500	1		
Motor Controllers Locally Mounted	100%			2030	\$17,800	5	\$300	
Ground								
Grounding Devices Generic	100%			LIFE	**	5	\$700	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Water Meter Room</i>								
<i>Explanation : Connected To Main Water Pipe.</i>								
Lighting								
Interior Lighting Fluorescent	25%			2027	\$98,400	10	\$10,600	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Offices, Mechanical, Electrical Rooms</i>								
<i>Explanation : Surface Mounted Fluorescent Light Fixtures With T-8 Lamps</i>								
Fluorescent	25%			2027	\$98,400	10	\$10,600	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Conference Room, Stair Case And Part Of Repair Shop</i>								
<i>Explanation : Recessed And Pendant Mounted Compact Fluorescent Light Fixtures</i>								
HID	50%			2027	\$134,300	10	\$800	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Repair Shops</i>								
<i>Explanation : Pendant Mounted HID Lights</i>								
Egress Lighting Emergency, Battery	50%			2040	**	10	\$5,600	
Exit, LED	50%			2067	**	1		
Exterior Lighting HID	100%			2027	\$211,500	10	\$100	
Alarm								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE FLEET SERVICES MAINTENANCE AND REPAIR SHOP
Asset # : 2847

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Alarm

Security System

No Component

80%

Generic

20%

2027

\$17,000

1

\$3,500

*Other Observation, Extent : Moderate, Area Affected : 100%**Location : Shops And Outside**Explanation : CCTV Surveillance Camera Systems*

Fire/Smoke Detection

No Component

80%

Generic, Digital

20%

2027

\$23,400

1-3

\$5,700

*Other Observation, Extent : Moderate, Area Affected : 100%**Location : Throughout The Building**Explanation : Strobe Lights, Manual Pull Stations, Smoke Detectors And Horns*

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Heating

Energy Source

Electricity

25%

2052

**

1

Natural Gas

75%

2052

**

1

Conversion Equipment

Furnace

50%

0-2

\$3,500

2037

**

1

\$10,300

*Malfunctioning, Extent : Severe, Area Affected : 10%**Location : Unit No. 5 Compressor Is Not Working On The Roof.**Other Observation, Extent : Light, Area Affected : 100%**Location : Roof**Explanation : 5 Units. Included In Air Conditioning System*

Radiant Heater

25%

2037

**

2

\$5,400

*Other Observation, Extent : Light, Area Affected : 100%**Location : Offices, 1st Floor**Explanation : 15 Units*

No Component

25%

Air Conditioning

Energy Source

Electricity

100%

2048

**

1

Conversion Equipment

Ext Pkg Unit - Heating/Cooling

100%

2037

**

2

\$2,800

*R-22 Refrigerant, Extent : Light, Area Affected : 100%**Location : Air Conditioning Units On The Roof**Other Observation, Extent : Light, Area Affected : 100%**Location : Roof**Explanation : 5 Units*

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE FLEET SERVICES MAINTENANCE AND REPAIR SHOP
Asset # : 2847

Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Air Conditioning								
Terminal Devices								
Air Handler/Cool/Ht	5%	Now	\$900	2032	\$44,000	1	\$1,300	
<i>Malfunctioning, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Control System. Penthouse</i>								
No Component	95%							
Heat Rejection								
Air Cooled Condenser Unit	20%			2037	**	2	\$6,500	
No Component	80%							
Ventilation								
Distribution								
Ductwork/Diffusers	100%			LIFE	**	2-5	\$25,900	
Exhaust Fans								
Interior	90%			2037	**	2	\$1,300	
Roof	10%			2037	**	2	\$100	
Plumbing								
H/C Water Piping								
Galvanized Steel	100%			2049	**	1		
Water Heater With Tanks								
Electric	30%			2030	\$13,900	4		
Gas Fired	70%			2027	\$23,400	2		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Mechanical Room, 2nd Floor</i>								
<i>Explanation : One Unit</i>								
Sanitary Piping								
Cast Iron	100%			LIFE	**	1		
Storm Drain Piping								
Cast Iron	100%			LIFE	**	1		
Backflow Preventer								
Generic	100%			2040	**	1	\$2,800	
Fixtures								
Generic	100%							
Vertical Transport								
Elevators								
Hydraulic	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : 1st To 2nd Floor</i>								
<i>Explanation : One Unit</i>								
Fire Suppression								
Sprinkler								
Generic	100%			2052	**	1-2	\$13,000	
Fire Pump								
Generic	100%			2041	**	1	\$8,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEBSTER AVENUE YARD STAGING GARAGE AND SIGN SHOP
Address : 4409 PARK AVENUE @E. 181 STREET
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0097.010 / 13606 **Yr Built/Renovated** : 2002 /
Area Sq Ft : 36,850 **Project Type** : HIGHWAYS
Date of Survey : 29-Oct-2020 **Landmark Status** : NONE
Areas Surveyed : Roof, Floors 1,2
Block : 3030 **Lot** : 6 **BIN** : 2100288

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Exterior Architecture	\$332,100	
Interior Architecture	\$221,000	\$135,000
Electrical	\$491,400	
Mechanical		\$11,200
Total	\$1,044,600	\$146,200
Importance Code A	\$332,100	\$11,200
Importance Code B	\$593,900	\$135,000
Importance Code C	\$118,500	
Total	\$1,044,600	\$146,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Exterior Architecture	\$49,100	\$12,700		
Interior Architecture	\$3,900		\$600	
Electrical	\$1,000	\$75,600	\$600	\$600
Mechanical	\$25,900	\$37,500	\$6,200	\$4,200
Site Pavements	\$30,300			
Total	\$110,200	\$125,700	\$7,400	\$4,700
Importance Code A	\$55,000	\$14,700	\$1,600	\$2,000
Importance Code B	\$53,500	\$111,000	\$5,700	\$2,700
Importance Code C	\$1,700			
Total	\$110,200	\$125,700	\$7,400	\$4,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE YARD STAGING GARAGE AND SIGN SHOP
Asset # : 13606

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Exterior								
Exterior Walls								
Concrete Masonry Unit	60%			LIFE	**	5	\$25,300	
			<i>Water Penetration, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Front Main Office Entrance</i>					
Fiberglass Panel	7%			2041	**	5	\$17,700	
Glass Block	5%			LIFE	**	5	\$2,100	
Glazed Ceramic Panel	3%			LIFE	**	5	\$9,500	
Metal Panel	10%			2052	**	5-10	\$46,400	
Metal Coiling Doors	10%	Now	\$14,100	2045	**	5	\$10,600	
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Throughout</i>					
Pre-Cast Concrete	5%	Now	\$4,800	LIFE	**	5	\$11,000	
			<i>Expansion Joint Failure, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Throughout</i>					
Parapets								
Cast in Place Concrete	30%	Now	\$5,600	LIFE	**	5	\$32,900	
			<i>Expansion Joint Failure, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Throughout</i>					
Masonry: Brick	60%	Now	\$15,800	LIFE	**	5	\$6,400	
			<i>Efflorescence, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Interior Face</i>					
			<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Throughout</i>					
			<i>Miss/Damaged Flashings, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Throughout</i>					
Metal Security Bars	10%			2060	**			
Roof								
Built-Up (BUR)	35%	Now	\$153,900	2037	**			
			<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Throughout</i>					
			<i>Water Penetration, Extent : Moderate, Area Affected : 40%</i>					
			<i>Location : Throughout</i>					
Metal Panel	65%	Now	\$178,200	2045	**			
			<i>Punct/Tear/Impact Damage, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Throughout</i>					
			<i>Water Penetration, Extent : Light, Area Affected : 25%</i>					
			<i>Location : Throughout</i>					
Interior								
Floors								
Cast in Place Concrete	90%	Now	\$102,500	LIFE	**	5	\$135,000	
			<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Throughout</i>					
Ceramic Tile	3%			2041	**	5	\$2,100	
Vinyl Tile	7%			2037	**	3	\$1,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE YARD STAGING GARAGE AND SIGN SHOP
Asset # : 13606

Architecture		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Interior

Interior Walls

Ceramic Tile	3%			2041	**	5	\$3,400	
Concrete Masonry Unit	57%	0-2	\$118,500	LIFE	**	5	\$25,800	

Cracking/Crumbling, Extent : Light, Area Affected : 5%

Location : Throughout

Glass: Single Pane	5%			LIFE	**	5	\$4,200	
Gypsum Board	10%			LIFE	**	5	\$6,800	
SGFT/Glazed Masonry	25%			LIFE	**			

Ceilings

AcousTileSusp.Lay-In	10%			2045	**	5	\$6,900	
Exposed Struc: Steel	85%			LIFE	**			
Gypsum Board	5%	Now	\$1,200	LIFE	**	5	\$4,300	

Cracking/Crumbling, Extent : Light, Area Affected : 5%

Location : Throughout

Loose/Delam Surface, Extent : Severe, Area Affected : 5%

Location : West Stair. Leaking

Site Pavements

Public Sidewalk

Cast in Place Concrete	100%	4+	\$30,300	2045	**			
------------------------	------	----	----------	------	----	--	--	--

Cracking/Crumbling, Extent : Light, Area Affected : 10%

Location : Front Sidewalk

Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Under 600 Volts

Service Equipment

Fused Disc Sw	100%			2032	\$3,700	5	\$200	
---------------	------	--	--	------	---------	---	-------	--

Other Observation, Extent : Moderate, Area Affected : 100%

Location : Electrical Room

Explanation : 2 Main Service Switches Rated At 400 Amperes And 600 Amperes.

Switchgear / Switchboard

Molded Case Bkrs	100%			2032	\$31,800	5	\$1,000	
------------------	------	--	--	------	----------	---	---------	--

Raceway

Conduit	100%			2032	\$4,300	1		
---------	------	--	--	------	---------	---	--	--

Panelboards

Fused Disc Sw	5%			2031	\$1,000	5		
Molded Case Bkrs	95%			2031	\$18,500	5	\$900	

Wiring

Thermoplastic	100%			2032	\$8,800	1		
---------------	------	--	--	------	---------	---	--	--

Motor Controllers

Locally Mounted	100%			2030	\$44,900	5	\$200	
-----------------	------	--	--	------	----------	---	-------	--

Ground

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE YARD STAGING GARAGE AND SIGN SHOP
Asset # : 13606

Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Ground

Grounding Devices
Generic

100%
LIFE ** 5 \$500
Other Observation, Extent : Moderate, Area Affected : 100%
Location : Water Meter Room
Explanation : Connected To Metal Water Pipe

Lighting

Interior Lighting
Fluorescent

60% 2027 \$153,000 10 \$20,300
Other Observation, Extent : N/A, Area Affected : 100%
Location : Offices
Explanation : Surface Mounted And Recessed Mounted Fluorescent Light Fixtures With T-8 Lamps

HID

40% 2027 \$170,500 10 \$500

Egress Lighting

Exit, Service

50% 2027 \$6,100 1

Exit, Battery

50% 2027 \$20,800 10 \$1,200

Exterior Lighting

HID

100% 2027 \$167,900 10 \$100

Alarm

Security System

No Component

90%

Generic

10% 2027 \$6,800 1 \$1,400

Other Observation, Extent : Moderate, Area Affected : 100%
Location : Outside
Explanation : CCTV Surveillance Camera System

Fire/Smoke Detection

No Component

80%

Generic, Digital

20% 2027 \$18,600 1-3 \$4,500

Other Observation, Extent : Moderate, Area Affected : 100%
Location : Throughout The Building
Explanation : Strobe Lights, Smoke Detector, Alarm Bells And Manual Pull Stations

Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Heating

Energy Source

Electricity

30% 2058 ** 1

Natural Gas

70% 2058 ** 1

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE YARD STAGING GARAGE AND SIGN SHOP
Asset # : 13606

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Heating								
Conversion Equipment								
Furnace	80%			2037	**	1	\$14,600	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Roof. Included In Air Conditioning System</i>								
<i>Explanation : 3 Units</i>								
Furnace	10%	Now	\$4,500	2032	\$11,200	1	\$1,600	
<i>Not in Service, Extent : Severe, Area Affected : 10%</i>								
<i>Location : 2 Of 4 Units Are Not Working In The Garage Area</i>								
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : In The Garage Area</i>								
<i>Explanation : 4 Independent Units. 2 Units Out Of 4 Burn Out On The Roof. Which Are Units Hv-3 And Hv-4</i>								
Radiant Heater	10%			2037	**	2	\$1,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Offices On The First Floor</i>								
<i>Explanation : 12 Units</i>								
Air Conditioning								
Energy Source								
Electricity	100%			2054	**	1		
Conversion Equipment								
Ext Pkg Unit - Heating/Cooling	30%	Now	\$18,100	2037	**	2	\$500	
<i>Malfunctioning, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Control System</i>								
<i>R-22 Refrigerant, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Air Conditioning Units On Roof</i>								
No Component	70%							
Terminal Devices								
Air Handler/Cool/Ht	10%	Now	\$400	2037	**	1	\$2,100	
<i>Malfunctioning, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Control System, Roof</i>								
No Component	90%							
Heat Rejection								
Air Cooled Condenser Unit	20%			2037	**	2	\$5,100	
No Component	80%							
Ventilation								
Distribution								
Ductwork/Diffusers	100%			LIFE	**	2-5	\$20,500	
Exhaust Fans								
Interior	70%			2037	**	2	\$800	
Roof	30%			2037	**	2	\$300	
Plumbing								
H/C Water Piping								
Brass/Copper	100%			2058	**	1		
Water Heater With Tanks								
Gas Fired	100%			2027	\$33,400	2		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEBSTER AVENUE YARD STAGING GARAGE AND SIGN SHOP
Asset # : 13606

Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Plumbing								
	Sanitary Piping							
	Cast Iron	100%			LIFE	* *	1	
	Storm Drain Piping							
	Cast Iron	100%			LIFE	* *	1	
	Fixtures							
	Generic	100%						
Fire Suppression								
	Sprinkler							
	Generic	100%			2052	* *	1-2	\$10,300

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 102ND STREET HAWTREE BASIN
Address : 102ND ST. BETWEEN BROADWAY AND RUSSEL STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0274.000 / 15028 **Yr Built/Renovated** :
Area Sq Ft : 4,698 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2248250

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,200		\$5,300	\$9,500
Total	\$2,200		\$5,300	\$9,500
Importance Code A	\$2,200		\$100	
Importance Code C			\$5,100	\$9,500
Total	\$2,200		\$5,300	\$9,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
102ND STREET HAWTREE BASIN
Asset # : 15028

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Buried Under Pavement</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Timber	100%			2040			**	
Mat (scour & erosion)								
Riprap	100%			LIFE			**	
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$10,300
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
		<i>Rust Stains, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
102ND STREET HAWTREE BASIN
Asset # : 15028

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 11TH AVE VIADUCT (RAMP) W 34 ST/AMTRAK 30 ST. BRANCH
Address : WEST 34 STREET AMTRAK 30 ST.BRANCH
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0066.0D0 / 2935 **Yr Built/Renovated** : 1934 /
Area Sq Ft : 11,800 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 02-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224501D

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,053,100	\$233,600
Total	\$1,053,100	\$233,600
Importance Code A	\$655,600	\$116,800
Importance Code B	\$330,200	\$116,800
Importance Code C	\$67,300	
Total	\$1,053,100	\$233,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$155,500		\$26,600	
Total	\$155,500		\$26,600	
Importance Code A	\$10,400		\$12,600	
Importance Code B	\$65,700		\$13,900	
Importance Code C	\$79,400			
Total	\$155,500		\$26,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 34 ST/AMTRAK 30 ST. BRANCH
Asset # : 2935

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$3,400	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : On East Side</i>								
<i>Explanation : Bridge Abuts To Another Structure</i>								
Backwall Concrete	100%	4+	\$25,300	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$2,100	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Missing Armor On Northwest Corner</i>								
Mat (scour & erosion) Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout On West Side</i>								
<i>Explanation : Concrete Mat</i>								
Stem (breastwall) Concrete	100%	2-4	\$213,400	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Leakage, Extent : Light, Area Affected : 10%</i>								
<i>Location : Center Of Stem On West Side</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Explanation : Honeycombing</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 34 ST/AMTRAK 30 ST. BRANCH

Asset # : 2935

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Masonry	100%			LIFE		**		
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Southwest Wingwall</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout Northwest Wingwall</i>								
<i>Explanation : Limited Access</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pier Protection								
Concrete	100%	4+	\$1,400	LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Cracks</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$9,000	2044		**	4	\$6,200
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$3,600	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northwest Corner</i>								
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044		**	4	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Northwest Corner</i>								
<i>Explanation : Concrete Parapet</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Southwest Corner</i>								
<i>Explanation : Chain Link Fence</i>								
Sidewalks								
Concrete	100%	0-2	\$20,700	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On West Side</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 34 ST/AMTRAK 30 ST. BRANCH
Asset # : 2935

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns Steel	100%			LIFE	**	2-8	\$105,100	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Failure</i>								
<hr/>								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE	**			
<hr/>								
Piles Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$3,400	LIFE	**			
<i>Misaligned/Bulging, Extent : Light, Area Affected : 15%</i>								
<i>Location : North Side</i>								
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Severe, Area Affected : 1%</i>								
<i>Location : Southeast Side</i>								
<i>Explanation : Armoring Is Dislodged</i>								
<hr/>								
Railings/Parapets Concrete	100%			2044	**	4	\$1,900	
<hr/>								
Sidewalks Concrete	100%	4+	\$24,300	2040	**	5	\$4,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface Concrete	100%	4+	\$67,300	2044	**	5	\$20,700	
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : West End</i>								
<i>Explanation : Failing Asphalt Patches</i>								
<hr/>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 34 ST/AMTRAK 30 ST. BRANCH

Asset # : 2935

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure Deck, Structural Concrete	100%	2-4	\$408,000	LIFE	**	5	\$10,900	
<i>Cracks, Extent : Moderate, Area Affected : 30%</i> <i>Location : Random Locations Throughout</i> <i>Delaminations, Extent : Moderate, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Moderate, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Moderate, Area Affected : 5%</i> <i>Location : Center Bay At East Side And Random Locations</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Center Bay At East Side And Random Locations</i> <i>Other Observation, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations On Center Bay</i> <i>Explanation : Scaling</i>								
Primary Member Steel	100%	4+	\$247,600	LIFE	**	2-8	\$218,100	
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								
Secondary Member Steel	100%			LIFE	**	2-8	\$320,800	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 11TH AVE VIADUCT (RAMP) W 35 ST/AMTRAK 30 ST. BRANCH
Address : WEST 35 STREET AMTRAK 30 ST.BRANCH
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0066.0E0 / 2936 **Yr Built/Renovated** : 1934 /
Area Sq Ft : 6,500 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 02-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224501E

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$54,200	
Total	\$54,200	
Importance Code A	\$54,200	
Total	\$54,200	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$129,600		\$4,400	
Total	\$129,600		\$4,400	
Importance Code A	\$41,300		\$2,800	
Importance Code B	\$55,200		\$1,600	
Importance Code C	\$33,100			
Total	\$129,600		\$4,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 35 ST/AMTRAK 30 ST. BRANCH
Asset # : 2936

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Bridge Abuts To Another Structure On West Side. Limited Access To Abutment Components On East Side Due To Construction.</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Over On East Side</i>								
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Walls Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout East Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : On East Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 35 ST/AMTRAK 30 ST. BRANCH
Asset # : 2936

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%	4+	\$8,400	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : On East Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								
Approaches								
Pavement								
Asphalt	100%	4+	\$16,000	2036		**	4	\$2,300
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations On East Side</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On East Side, Worst Cases Near Abutment Joint</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On East Side</i>								
<i>Explanation : Limited Access To Southeast Corner Due To Construction. Raveling</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$1,400	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Corner</i>								
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations On East Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout South Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Under Construction	100%							
Sidewalks								
Asphalt	100%			2036		**	4	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout East Approach</i>								
<i>Explanation : Temporary Asphalt Sidewalk On North Side. Under Construction On South Side</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 35 ST/AMTRAK 30 ST. BRANCH
Asset # : 2936

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Scupper								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout South Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								
Piers								
Cap Beam								
Steel	100%	2-4	\$54,200	LIFE	**	2-8	\$64,100	
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Loss of Section, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Other Observation, Extent : Light, Area Affected : 65%</i>								
<i>Location : Random Locations On West Pier</i>								
<i>Explanation : Limited Access Due To Construction On East Side. Paint System Failure</i>								
Pier, Columns								
Steel	100%			LIFE	**	2-8	\$74,700	
<i>Rust Stains, Extent : Light, Area Affected : 35%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Other Observation, Extent : Light, Area Affected : 65%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Explanation : Limited Access Due To Construction On East Side. Paint System Failure</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout East Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout South Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								
Railings/Parapets								
Concrete	100%			2044	**	4		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On South Side</i>								
<i>Explanation : Temporary Concrete Barriers With Chain Link Fence On Top On North Side.</i>								
<i>Limited Access Due To Construction</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 35 ST/AMTRAK 30 ST. BRANCH
Asset # : 2936

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Under Construction	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Temporary Concrete Sidewalk On North Side. Under Construction On South Side</i>								
<hr/>								
Wearing Surface								
Concrete	100%	0-2	\$17,100	2038	**	5	\$10,500	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : South Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Joints								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : West Joint</i>								
<i>Explanation : Debris</i>								
<hr/>								
Primary Member								
Concrete Encased Steel	100%	4+	\$39,900	LIFE	**	5	\$32,800	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Bottom Flange Of Girders</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout East Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								
<hr/>								
Secondary Member								
Concrete	100%	4+	\$17,700	LIFE	**	5	\$2,700	
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout East Side</i>								
<i>Explanation : Limited Access Due To Construction</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 35 ST/AMTRAK 30 ST. BRANCH
Asset # : 2936

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 11TH AVE VIADUCT (RAMP) W 36 ST/AMTRAK 30 ST. BRANCH
Address : WEST 36 STREET AMTRAK 30 ST.BRANCH
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0066.0F0 / 2937 **Yr Built/Renovated** : 1934 /
Area Sq Ft : 16,400 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 02-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224501F

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,144,900	\$213,300
Total	\$1,144,900	\$213,300
Importance Code A	\$1,011,200	\$165,800
Importance Code B	\$47,500	\$47,500
Importance Code C	\$86,300	
Total	\$1,144,900	\$213,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$148,000		\$14,300	
Total	\$148,000		\$14,300	
Importance Code A	\$49,800		\$8,300	
Importance Code B	\$61,600		\$4,800	
Importance Code C	\$36,700		\$1,200	
Total	\$148,000		\$14,300	



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 36 ST/AMTRAK 30 ST. BRANCH
Asset # : 2937

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout On East Side</i>								
<i>Explanation : Limited Access To Abutment Components</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,900	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : West Abutment And Random Locations</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southwest Corner</i>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout On East Side</i>								
<i>Explanation : Limited Access</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 36 ST/AMTRAK 30 ST. BRANCH
Asset # : 2937

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Feature Crossed								
Pier Protection								
Concrete	100%	2-4	\$18,800	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout On East Side</i>								
<i>Explanation : Limited Access</i>								
Approaches								
Pavement								
Asphalt	100%			2036		**	4	\$2,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On East Side</i>								
Concrete	100%			2044		**	4	\$100
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On West Side</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$3,600	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : East Approach</i>								
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044		**	4	
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%	2-4	\$5,200	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 20%</i>								
<i>Location : East Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Corner</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 36 ST/AMTRAK 30 ST. BRANCH
Asset # : 2937

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southeast Corner</i>								
<i>Explanation : 1 Scupper</i>								
<hr/>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$321,600
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Limited Access To Pier Components On 50 Percent Area. Paint Peeling</i>								
<hr/>								
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$224,200
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Painted Steel Face Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2044		**	4	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Temporary Barriers On South Side</i>								
<hr/>								
Steel	100%			LIFE		**	2-8	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Corrugated Steel Panels On Top Of Concrete Parapet On North Side. Chain Link Fence On Top Of Temporary Barriers On South Side.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP) W 36 ST/AMTRAK 30 ST. BRANCH
Asset # : 2937

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%	Now	\$86,300	2040	**	5	\$6,700	
<i>Cracks, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Southeast Corner</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With More Severe Cases On South Side</i>								
<hr/>								
Wearing Surface								
Concrete	100%	2-4	\$17,600	2044	**	5	\$27,200	
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Joints								
Generic	100%	4+	\$13,800	LIFE	**			
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Along Longitudinal Staging Joints</i>								
<hr/>								
Primary Member								
Concrete Encased Steel	100%	2-4	\$928,000	LIFE	**	5	\$82,600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On Bottom Flanges</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains/ Exposed Reinforcements.</i>								
<hr/>								
Secondary Member								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Secondary Members Are Embedded In Concrete</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 11TH AVE VIADUCT (RAMP)- W.33 ST AMTRAK 30TH ST.BRANCH
Address : WEST 33 STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0066.0B0 / 2933 **Yr Built/Renovated** : 1934 /
Area Sq Ft : 16,500 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 02-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224501B

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$685,700	\$368,200
Total	\$685,700	\$368,200
Importance Code A	\$402,500	\$163,300
Importance Code B	\$283,200	\$204,900
Total	\$685,700	\$368,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$309,200		\$41,200	
Total	\$309,200		\$41,200	
Importance Code A	\$64,400		\$20,600	
Importance Code B	\$72,100		\$20,500	
Importance Code C	\$172,700			
Total	\$309,200		\$41,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP)- W.33 ST AMTRAK 30TH ST.BRANCH
Asset # : 2933

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$3,400	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 15%</i> <i>Location : Random Locations On West Side</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On West Side</i> <i>Spalling, Extent : Moderate, Area Affected : 15%</i> <i>Location : Random Locations On West Side</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : On East Side</i> <i>Explanation : Bridge Abuts To Another Structure</i>								
Backwall Concrete	100%	4+	\$39,600	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On West Side</i> <i>Efflorescence, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations On West Side</i> <i>Rust Stains, Extent : Severe, Area Affected : 30%</i> <i>Location : Random Locations On West Side</i>								
Brngs,Ancr Blts,Pads Steel	100%	4+	\$6,500	LIFE			**	
<i>Corrosion, Extent : Severe, Area Affected : 10%</i> <i>Location : Random Locations On West Side</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On West Side</i>								
Footings Not Accessible	100%							
Joint with Deck Generic	100%	2-4	\$1,200	LIFE			**	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i> <i>Location : Southwest Corner</i> <i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On West Side</i>								
Mat (scour & erosion) Earth	100%			LIFE			**	
Stem (breastwall) Concrete	100%	4+	\$119,900	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On West Side</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations On West Side</i> <i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations On West Side</i> <i>Explanation : Scaling</i>								
Wingwalls								
Footings Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP)- W.33 ST AMTRAK 30TH ST.BRANCH
Asset # : 2933

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Masonry: Schist/Gneiss	100%	4+	\$12,700	LIFE		**		
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Light Joint Mortar Missing/ Eroded On 5 Percent Area. Broken/ Missing Elements</i>					
Feature Crossed								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pier Protection								
Concrete	100%	0-2	\$8,400	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Approaches								
Pavement								
Concrete	100%	4+	\$22,600	2044		**	4	\$6,200
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations On West Side</i>					
			<i>Old Repair, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Failing Patch On West Side</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations On West Side</i>					
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Approach Only On West Side</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
Embankment								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP)- W.33 ST AMTRAK 30TH ST.BRANCH
Asset # : 2933

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets								
Concrete	100%			2044	**	4		
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Concrete Wall Is On The South Side Of The Bridge</i>							
Steel	100%			LIFE	**			
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Steel Fence Is On The North Side Of The Bridge</i>							
Sidewalks								
Concrete	100%	4+	\$5,200	LIFE	**			
	<i>Cracks, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Scupper								
Cast Iron	100%			LIFE	**			
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : On Southwest Corner</i>							
	<i>Explanation : 1 Scupper</i>							
Piers								
Pier,Columns								
Steel	100%	4+	\$32,700	LIFE	**	2-8	\$119,700	
	<i>Corrosion, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Delaminations, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
	<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Railings/Parapets								
Concrete	100%			2044	**	4	\$8,500	
Sidewalks								
Concrete	100%	4+	\$34,500	2040	**	5	\$6,700	
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVE VIADUCT (RAMP)- W.33 ST AMTRAK 30TH ST.BRANCH
Asset # : 2933

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface Concrete	100%	4+	\$44,300	2044	**	5	\$27,300	
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Old Repair, Extent : Light, Area Affected : 5%</i> <i>Location : Failing Patches On Random Locations</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural Concrete	100%	4+	\$239,200	LIFE	**	5	\$16,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Center Bay And On Random Locations</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On Center Bay</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On Center Bay</i> <i>Other Observation, Extent : N/A, Area Affected : 10%</i> <i>Location : Center Bay</i> <i>Explanation : Light Scaling On 10 Percent Area On Center Bay. Covered By Timber Shielding</i>								
Joints								
Generic	100%	4+	\$13,800	LIFE	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$522,800	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Failure</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$448,600	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 11TH AVENUE AMTRAK 30 ST BRANCH
Address : 11TH AVENUE ABOUT W58TH STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0293.000 / 15051 **Yr Built/Renovated** :
Area Sq Ft : 11,286 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245209

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$26,600		\$11,800	
Total	\$26,600		\$11,800	
Importance Code A	\$10,100			
Importance Code C	\$16,500		\$11,800	
Total	\$26,600		\$11,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE AMTRAK 30 ST BRANCH
Asset # : 15051

Bridge Structure	Current Repair		Future Replacement		Maintenance			
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : No Access To Amtrak Property Underneath</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Paved Over With Asphalt</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Walls Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Bank Protection Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE AMTRAK 30 ST BRANCH
Asset # : 15051

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%			2036	**	4	\$23,700	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Northbound Lane</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rutting</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$10,100	LIFE	**			
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE AMTRAK 30 ST BRANCH
Asset # : 15051

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	10%	4+	\$11,400	2040	**	5	\$8,800	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	90%			2040	**	5	\$17,600	
Wearing Surface								
Asphalt	100%	2-4	\$5,100	2036	**	5	\$7,600	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Rutting In Random Locations</i>								
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : Northbound Lane</i>								
<i>Explanation : Recent Repair Evident</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 11TH AVENUE LIRR & SEA BEACH
Address : 11TH AVENUE BET. 61ST & 62ND STS
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0295.000 / 15053 **Yr Built/Renovated** :
Area Sq Ft : 9,838 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243630

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$3,900		\$10,300	\$18,100
Total	\$3,900		\$10,300	\$18,100
Importance Code A	\$3,900		\$3,300	
Importance Code C			\$7,000	\$18,100
Total	\$3,900		\$10,300	\$18,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE LIRR & SEA BEACH
Asset # : 15053

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$13,900
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Southwest Approach</i>					
			<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE LIRR & SEA BEACH
Asset # : 15053

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,600	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations On North Side</i>					
Steel	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 75%</i>					
			<i>Location : Throughout Except Southwest Approach</i>					
			<i>Explanation : Chain Link Fence</i>					
Sidewalks								
Concrete	100%			LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Old Repair, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Uneven Asphalt Patch On Northeast Approach</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Scupper								
Cast Iron	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Southeast And Southwest Approach</i>					
			<i>Explanation : 2 Approach Scuppers</i>					
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE LIRR & SEA BEACH
Asset # : 15053

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Concrete	100%			2044		**	4	\$4,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$10,200
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%			2040		**	5	\$7,300
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044		**	5	\$36,200
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southeast And Southwest Corner</i>								
<i>Explanation : 2 Deck Scuppers</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 11TH AVENUE VIADUCT LIRR W. SIDE YARD
Address : 30TH-36TH ST, 10TH-11TH AVE. LIRR WEST SIDE YARD
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0066.000 / 2491 **Yr Built/Renovated** : 1934 /
Area Sq Ft : 157,500 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 17-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245010

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$758,300	\$903,900
Total	\$758,300	\$903,900
Importance Code C	\$758,300	\$903,900
Total	\$758,300	\$903,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$33,400			\$47,700
Total	\$33,400			\$47,700
Importance Code A	\$6,900			\$31,000
Importance Code B	\$7,700			
Importance Code C	\$18,900			\$16,700
Total	\$33,400			\$47,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE VIADUCT LIRR W. SIDE YARD
Asset # : 2491

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : MTA And Amtrak Access Required.</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	60%			LIFE				**
Generic	40%	4+	\$7,700	LIFE				**
<i>Broken/Missing Elements, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Near Sidewalk</i>								
<i>Explanation : Under Construction</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE VIADUCT LIRR W. SIDE YARD
Asset # : 2491

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%	2-4	\$3,500	2033	\$176,200	4	\$2,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	60%			2041	**	4	\$33,400	
Concrete	40%	2-4	\$113,700	2041	**	4	\$33,400	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Guide Railing								
Concrete	100%			2041	**	4	\$5,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Between 34th And 35th Streets</i>								
<i>Explanation : Concrete Barrier During Construction</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	88%	4+	\$6,900	2041	**	4	\$3,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	12%			2041	**	4	\$3,700	
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Between 34th And 35th Streets</i>								
<i>Explanation : Under Construction</i>								
Sidewalks								
Concrete	60%			LIFE	**			
Concrete	40%	4+	\$15,400	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE VIADUCT LIRR W. SIDE YARD
Asset # : 2491

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	88%			LIFE		**		
		<i>Rust Stains, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete w/ Steel Face	12%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Between 34th And 35th Streets</i>						
		<i>Explanation : Under Construction</i>						
Guide Railing								
Concrete	100%			2045		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Between 34th And 35th Streets</i>						
		<i>Explanation : Concrete Barrier</i>						
Railings/Parapets								
Concrete	88%			2041	**	4	\$26,300	
Concrete	12%			2041	**	4	\$26,300	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Between 34th And 35th Streets</i>						
		<i>Explanation : Under Construction</i>						
Steel	100%			LIFE	**	2-8		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Steel Railing And Chain Link Fence</i>						
Sidewalks								
Concrete	88%			2037	**	5	\$84,000	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete	12%			2037	**	5	\$84,000	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Between 34th And 35th Streets</i>						
		<i>Explanation : Under Construction</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
11TH AVENUE VIADUCT LIRR W. SIDE YARD
Asset # : 2491

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Concrete	80%			2041	**	5	\$643,700	
Concrete	20%	2-4	\$121,200	2041	**	5	\$321,900	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Scupper								
Cast Iron	88%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : 6 Scuppers Observed</i>								
Cast Iron	12%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Between 34th And 35th Streets</i>								
<i>Explanation : Under Construction</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Joints								
Generic	30%	Now	\$117,500	LIFE	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Joints Missing, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Filler Material Missing</i>								
Generic	70%			LIFE	**			
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 130TH STREET BELT SYSTEM - SOUTHERN PARKWAY
Address : 130TH ST OVER BELT PKWY BTWN N. & S. CONDUIT AVES
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0383.000 / 15403 **Yr Built/Renovated** :
Area Sq Ft : 6,643 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231590

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$301,000	
Total	\$301,000	
Importance Code A	\$217,400	
Importance Code B	\$83,600	
Total	\$301,000	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$25,600		\$2,000	
Total	\$25,600		\$2,000	
Importance Code A	\$12,300		\$100	
Importance Code B	\$600			
Importance Code C	\$12,800		\$1,800	
Total	\$25,600		\$2,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
130TH STREET BELT SYSTEM - SOUTHERN PARKWAY
Asset # : 15403

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$600	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Damaged Seal</i>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%	2-4	\$83,600	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : South Abutment</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : South Abutment</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : South Abutment</i>								
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Paving Underneath</i>								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
130TH STREET BELT SYSTEM - SOUTHERN PARKWAY
Asset # : 15403

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%	4+	\$8,800	2042	**	4	\$12,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Both Abutment Joints</i>								
Curbs								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Approach Only</i>								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%	4+	\$8,400	LIFE	**			
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Cast Iron Railing</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Vertical Cracks On Random Locations</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
130TH STREET BELT SYSTEM - SOUTHERN PARKWAY
Asset # : 15403

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<hr/>								
Railings/Parapets								
Cast Iron	100%	4+	\$3,800	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$3,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Cast Iron Railing</i>								
<hr/>								
Sidewalks								
Concrete	100%			2038	**	5	\$3,600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$4,000	2042	**	5	\$13,300	
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Concrete	100%	2-4	\$217,400	LIFE	**	5	\$49,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered With Wire Mesh On 10 Percent Of Area. Limited Access.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 147TH STREET BELT SYSTEM - CROSS ISLAND
Address : 14TH AVE OVER CROSS ISLAND PKWAY BTWN 148TH & 149TH STREETS
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0385.000 / 15405 **Yr Built/Renovated** :
Area Sq Ft : 5,960 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231980

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$139,200
Total		\$139,200
Importance Code C		\$139,200
Total		\$139,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$21,400		\$2,400	\$2,500
Total	\$21,400		\$2,400	\$2,500
Importance Code A	\$19,200		\$200	
Importance Code C	\$2,100		\$2,200	\$2,500
Total	\$21,400		\$2,400	\$2,500



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
147TH STREET BELT SYSTEM - CROSS ISLAND

Asset # : 15405

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			* *	
Stem (breastwall)								
Concrete	100%			LIFE			* *	
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			* *	
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE			* *	
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Southeast Wingwall</i>					
			<i>Vegetation Growth, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Southeast Wingwall</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			* *	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Asphalt Paving Underneath</i>					
Pier Protection								
Concrete	100%			LIFE			* *	
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Approaches								
Pavement								
Asphalt	100%			2034	\$139,200	4	\$6,400	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete	100%			LIFE			* *	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
147TH STREET BELT SYSTEM - CROSS ISLAND
Asset # : 15405

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%	2-4	\$7,500	LIFE			**	
			<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Corrosion, Extent : Moderate, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Paint Peeling</i>					
Steel	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Moderate Vegetation Growth In 20 Percent Area. Chain Link Fence Is Attached To Cast Iron Railing.</i>					
Sidewalks								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Vertical Cracks On Random Locations</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%			2053			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
147TH STREET BELT SYSTEM - CROSS ISLAND
Asset # : 15405

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Cast Iron	100%	4+	\$11,800	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 5%</i>								
<i>Location : East Side</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Steel	100%			LIFE		**	2-8	\$4,800
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Light Vegetation Growth On 10 Percent Area At Northeast And Southwest Corner, Chain Link Fence Attached To Cast Iron Railing.</i>								
Sidewalks								
Concrete	100%			2038		**	5	\$4,400
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%			2034	\$39,700		5	\$5,100
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Concrete	100%			LIFE		**	5	\$44,300
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 149TH STREET BELT SYSTEM - CROSS ISLAND
Address : 149TH ST. OVER CROSS ISLAND BLVD BTWN 14TH & 15TH AVENUES
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0387.000 / 15407 **Yr Built/Renovated** :
Area Sq Ft : 5,888 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231960

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$192,700	\$100,400
Total	\$192,700	\$100,400
Importance Code A	\$192,700	
Importance Code C		\$100,400
Total	\$192,700	\$100,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,200		\$100	
Total	\$2,200		\$100	
Importance Code A	\$600		\$100	
Importance Code C	\$1,500			
Total	\$2,200		\$100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
149TH STREET BELT SYSTEM - CROSS ISLAND
Asset # : 15407

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 70%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE			**	
			<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Asphalt Paving Underneath</i>					
Pier Protection								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 70%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Approaches								
Pavement								
Asphalt	100%			2034	\$100,400	4	\$4,600	
			<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
Curbs								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Both Sides At South Approach</i>					
Concrete w/ Steel Face	100%			LIFE			**	
			<i>Rust Stains, Extent : Moderate, Area Affected : 70%</i>					
			<i>Location : Throughout</i>					
Embankment								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
149TH STREET BELT SYSTEM - CROSS ISLAND
Asset # : 15407

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%			LIFE		**		
			<i>Corrosion, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Sidewalks								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Scupper								
Cast Iron	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : South Approach</i>					
			<i>Explanation : Total Of 2 Scuppers</i>					
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 10%</i>					
			<i>Location : At East And West Ends</i>					
			<i>Explanation : Limited Access On 70 Percent Area. Masonry Granite Fascia At Both Ends.</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	2%	2-4	\$100	2053		**		
			<i>Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	98%			2053		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
149TH STREET BELT SYSTEM - CROSS ISLAND**

Asset # : 15407

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Cast Iron	100%			LIFE		**		
	<i>Corrosion, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
Steel	100%	4+	\$500	LIFE		**	2-8	\$3,900
	<i>Rust Stains, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Northeast And Southeast Corner</i>							
	<i>Explanation : Chain Link Fence Attached To Cast Iron Railing Throughout. Vegetation Growth</i>							
Sidewalks								
Concrete	100%			2038		**	5	
Wearing Surface								
Asphalt	100%			2034	\$38,800		5	
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Concrete	100%	4+	\$192,700	LIFE		**	5	
	<i>Cracks, Extent : Moderate, Area Affected : 15%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Efflorescence, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Limited Access On 70 Percent Area. Covered With Wire Mesh.</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 14TH AVENUE BELT SYSTEM - CROSS ISLAND
Address : 14TH AVE OVER CROSS IALAND PKWAY BTWN 148TH & 149TH STREETS
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0386.000 / 15406 **Yr Built/Renovated** :
Area Sq Ft : 7,665 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231970

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$250,800	\$392,800
Total	\$250,800	\$392,800
Importance Code A	\$250,800	\$56,900
Importance Code C		\$335,900
Total	\$250,800	\$392,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$55,300			\$3,400
Total	\$55,300			\$3,400
Importance Code A	\$29,700			
Importance Code C	\$25,600			\$3,400
Total	\$55,300			\$3,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
14TH AVENUE BELT SYSTEM - CROSS ISLAND

Asset # : 15406

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 70%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE			**	
			<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Asphalt Paving Underneath</i>					
Pier Protection								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Approaches								
Pavement								
Asphalt	100%	4+	\$14,100	2034	\$282,700	4	\$8,700	
			<i>Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete	100%	4+	\$3,000	LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
14TH AVENUE BELT SYSTEM - CROSS ISLAND
Asset # : 15406

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%	4+	\$13,200	LIFE		**		
			<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Chain Link Fence Attached To Cast Iron Railing</i>					
Sidewalks								
Concrete	100%	4+	\$6,200	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Settlement, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Southwest Corner</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	13%	2-4	\$200	2053		**		
			<i>Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	87%			2053		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
14TH AVENUE BELT SYSTEM - CROSS ISLAND**

Asset # : 15406

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Cast Iron	100%	4+	\$13,200	LIFE		**		
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Pack Rust</i>								
Steel	100%			LIFE		**	2-8	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Light Vegetation Growth On 5 Percent Area. Chain Link Fence Attached To Cast Iron Railing.</i>								
Sidewalks								
Concrete	100%	4+	\$5,200	2038		**	5	\$2,200
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%			2034	\$53,200		5	\$6,800
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Concrete	100%	4+	\$250,800	LIFE		**	5	\$56,900
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Granite Fascia On East Spandrel Over Both Spans</i>								
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 150TH STREET BELT SYSTEM - CROSS ISLAND
Address : 150TH ST OVER CROSS ISLAND PKWY BTWN 14TH & 15TH ROADS
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0388.000 / 15408 **Yr Built/Renovated** :
Area Sq Ft : 5,510 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231950

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$136,500
Total		\$136,500
Importance Code C		\$136,500
Total		\$136,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$14,900		\$100	\$2,500
Total	\$14,900		\$100	\$2,500
Importance Code A	\$8,700		\$100	
Importance Code C	\$6,200			\$2,500
Total	\$14,900		\$100	\$2,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
150TH STREET BELT SYSTEM - CROSS ISLAND
Asset # : 15408

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			* *	
Stem (breastwall)								
Concrete	100%			LIFE			* *	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 90%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			* *	
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE			* *	
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Joint Mortar Missing/ Eroded</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			* *	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Asphalt Paving Underneath</i>					
Pier Protection								
Concrete	100%			LIFE			* *	
			<i>Other Observation, Extent : N/A, Area Affected : 70%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Approaches								
Pavement								
Asphalt	100%			2034	\$136,500	4	\$6,300	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations On Both Approaches</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
150TH STREET BELT SYSTEM - CROSS ISLAND
Asset # : 15408

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Curb On North Approach Only</i>								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 40%</i>								
<i>Location : Throughout South Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%	4+	\$2,500	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southwest Corner</i>								
Steel	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Is Attached To Cast Iron Railing</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At South Approach</i>								
<i>Explanation : Total Of 2 Scuppers</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : At East And West Ends</i>								
<i>Explanation : Limited Access On 80 Percent Area. Masonry Granite Fascia At Ends.</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
150TH STREET BELT SYSTEM - CROSS ISLAND**

Asset # : 15408

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%			2053		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On East Side</i>								
<hr/>								
Railings/Parapets								
Cast Iron	100%	4+	\$3,700	LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Repair Evident, Extent : N/A, Area Affected : 5%</i>								
<i>Location : East Side Near Pier</i>								
Steel	100%	4+	\$2,500	LIFE		**	2-8	\$3,700
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Cast Iron Railing</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$4,100	2038		**	5	\$1,700
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On East Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On East Side</i>								
<hr/>								
Wearing Surface								
Asphalt	100%			2034	\$40,000		5	\$5,100
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 160TH STREET BELY SYSTEM - CROSS ISLAND
Address : 160TH ST OVER CROSS ISLAND PKWY WHITESTONE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0325.000 / 15184 **Yr Built/Renovated** : 1941 /
Area Sq Ft : 5,704 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 02-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231920

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$5,000	\$1,800	\$100	\$4,100
Total	\$5,000	\$1,800	\$100	\$4,100
Importance Code A			\$100	
Importance Code B	\$1,800			
Importance Code C	\$3,200	\$1,800		\$4,100
Total	\$5,000	\$1,800	\$100	\$4,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
160TH STREET BELY SYSTEM - CROSS ISLAND

Asset # : 15184

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	25%	0-2	\$1,800	LIFE			**	
	<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 25%</i>							
	<i>Location : Random Locations Throughout</i>							
Generic	75%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Walls Are Concrete With Stone Facing. 50 Percent Not Accessible.</i>							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%			2041		**	4	\$8,200
	<i>Cracks, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
	<i>Rust Stains, Extent : Light, Area Affected : 20%</i>							
	<i>Location : Random Locations Throughout</i>							
Embankment								
Earth	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
160TH STREET BELY SYSTEM - CROSS ISLAND
Asset # : 15184

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : North And South Sides</i>						
		<i>Explanation : Chain Link Fence Behind Steel Bridge Railing</i>						
Sidewalks								
Concrete	100%			LIFE			**	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Both Approaches</i>						
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE			**	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 10%</i>						
		<i>Location : Both Ends</i>						
		<i>Explanation : Ends Are Treated With Stone Facade. Stem, Solid Pier Consists Of 25 Percent Concrete, 75 Percent Not Accessible.</i>						
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
		<i>Rust Stains, Extent : Light, Area Affected : 15%</i>						
		<i>Location : Random Locations Throughout</i>						
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$3,900
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : North And South Sides</i>						
		<i>Explanation : Chain Link Fence Behind Steel Bridge Railing</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
160TH STREET BELY SYSTEM - CROSS ISLAND

Asset # : 15184

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2037	**	5	\$3,700	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	0-2	\$3,200	2041	**	5	\$10,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 21ST STREET BRIDGE
Address : 21ST STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0170.000 / 13578 **Yr Built/Renovated** :
Area Sq Ft : 17,590 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 10-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247270

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$53,500
Total		\$53,500
Importance Code B		\$53,500
Total		\$53,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$232,400		\$5,800	
Total	\$232,400		\$5,800	
Importance Code A	\$41,300		\$400	
Importance Code B	\$1,400		\$5,400	
Importance Code C	\$189,700			
Total	\$232,400		\$5,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
21ST STREET BRIDGE
Asset # : 13578

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	50%			LIFE			**	
Generic	50%	4+	\$1,400	LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 3%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 3%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	50%	4+	\$37,200	LIFE			**	
			<i>Cracks, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Northeast</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Northeast</i>					
Concrete	50%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Not Accessible</i>					
Feature Crossed								
Bank Protection								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
21ST STREET BRIDGE
Asset # : 13578

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	88%			2042	**	4	\$29,500	
Concrete	12%	4+	\$34,700	2042	**	4	\$19,700	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Along Joint Header</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$11,200	LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4		
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%	4+	\$15,900	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South Approach</i>								
<i>Explanation : Two Scuppers</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$154,100	
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
21ST STREET BRIDGE
Asset # : 13578

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$19,400	LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 3%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Concrete	70%			2042		**	4	\$12,500
Concrete	30%	4+	\$6,600	2042		**	4	\$8,400
			<i>Cracks, Extent : Light, Area Affected : 3%</i>					
			<i>Location : Northwest Corner</i>					
Steel	100%			LIFE		**	2-8	\$11,500
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Sidewalks								
Concrete	100%	4+	\$28,600	2038		**	5	\$5,500
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Near Joints And Curbs</i>					
Wearing Surface								
Concrete	100%	4+	\$22,400	2042		**	5	\$34,600
			<i>Cracks, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Steel	100%	4+	\$41,100	LIFE		**		
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 225TH STREET BELT PARKWAY-SOUTHERN PARKWAY
Address : 225TH STREET OVER BELT PKWY BTW N & S CONDUITS
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0397.000 / 15417 **Yr Built/Renovated** :
Area Sq Ft : 6,700 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231640

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$311,200	\$99,500
Total	\$311,200	\$99,500
Importance Code A	\$260,900	\$99,500
Importance Code C	\$50,300	
Total	\$311,200	\$99,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$105,100		\$200	
Total	\$105,100		\$200	
Importance Code A	\$9,000		\$200	
Importance Code B	\$46,400			
Importance Code C	\$49,700			
Total	\$105,100		\$200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
225TH STREET BELT PARKWAY-SOUTHERN PARKWAY

Asset # : 15417

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Footings							
Not Accessible	100%						
Joint with Deck							
Generic	100%	4+	\$900	LIFE			* *
	<i>Spalling, Extent : Moderate, Area Affected : 5%</i>						
	<i>Location : Random Locations On Both Abutments</i>						
Mat (scour & erosion)							
Generic	100%			LIFE			* *
Stem (breastwall)							
Concrete	9%	0-2	\$45,500	LIFE			* *
	<i>Cracks, Extent : Moderate, Area Affected : 5%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>						
	<i>Location : South Abutment</i>						
	<i>Spalling, Extent : Moderate, Area Affected : 3%</i>						
	<i>Location : South Abutment</i>						
	<i>Other Observation, Extent : N/A, Area Affected : 60%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Limited Access</i>						
Concrete	91%			LIFE			* *
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Earth	100%			LIFE			* *
Piles							
Not Accessible	100%						
Walls							
Masonry: Granite	100%			LIFE			* *
	<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Explanation : Joint Mortar Missing/ Eroded</i>						
Feature Crossed							
Mat (scour & erosion)							
Generic	100%			LIFE			* *
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Asphalt Paving Underneath</i>						
Pier Protection							
Concrete	100%			LIFE			* *
	<i>Other Observation, Extent : N/A, Area Affected : 60%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Limited Access</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
225TH STREET BELT PARKWAY-SOUTHERN PARKWAY

Asset # : 15417

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%	4+	\$50,300	2042	**	4	\$31,000	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On Both Approaches</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On Both Approaches</i>								
<hr/>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$2,900	LIFE	**			
<i>Misaligned/Bulging, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northwest Corner</i>								
<hr/>								
Embankment								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Concrete	100%			2042	**	4	\$4,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Vegetation Growth</i>								
Steel	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
<hr/>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
225TH STREET BELT PARKWAY-SOUTHERN PARKWAY

Asset # : 15417

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Old Repair, Extent : Light, Area Affected : 15%</i> <i>Location : South Face Of Pier</i> <i>Other Observation, Extent : N/A, Area Affected : 10%</i> <i>Location : At East And West Ends</i> <i>Explanation : Limited Access On 60 Percent Area. Masonry Granite Fascia At Both Ends.</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$3,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 60%</i> <i>Location : Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 3%</i> <i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2042		**	4	\$4,600
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Vegetation Growth</i>								
Steel	100%			LIFE		**	2-8	\$4,300
<i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 15%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%	2-4	\$26,700	2038		**	5	\$1,900
<i>Cracks, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
225TH STREET BELT PARKWAY-SOUTHERN PARKWAY

Asset # : 15417

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface Concrete	100%	2-4	\$23,100	2042	**	5	\$12,800	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Near Abutment Joints On Both Sides</i>								
<i>Explanation : Asphalt Patches</i>								
<hr/>								
Superstructure								
Deck, Structural Not Accessible	100%							
<hr/>								
Primary Member Concrete	10%	Now	\$260,900	LIFE	**	5	\$49,800	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Concrete	90%			LIFE	**	5	\$49,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 252ND ST BRIDGE
Address : 252ND STREET HHP
Borough : BRONX
Program / Asset # : DOT0211.000 / 14579
Area Sq Ft : 4,500
Date of Survey : 24-Oct-2023
Areas Surveyed :
Block : Lot : BIN : 2229500
Agency's Number : N/A
Yr Built/Renovated :
Project Type : HIGHWAY BRIDGES
Landmark Status : NONE


CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,500		\$2,800	\$8,000
Total	\$2,500		\$2,800	\$8,000
Importance Code A	\$2,500		\$600	
Importance Code C			\$2,200	\$8,000
Total	\$2,500		\$2,800	\$8,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
252ND ST BRIDGE
Asset # : 14579

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE			**	
Mat (scour & erosion) Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Roadway Asphalt</i>					
Pedestals								
Not Accessible	100%							
Stem (breastwall) Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Vegetation Growth, Extent : Moderate, Area Affected : 25%</i>					
			<i>Location : Southwest Wing</i>					
Feature Crossed								
Mat (scour & erosion) Asphalt Paving	100%			LIFE			**	
Pier Protection Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Concrete Barrier</i>					
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
252ND ST BRIDGE
Asset # : 14579

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$4,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 75%</i>								
<i>Location : Throughout</i>								
Guide Railing								
Steel	100%			LIFE	**	2-8	\$700	
Timber	100%			2036	**	4	\$900	
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Granite	100%			LIFE	**			
Steel	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Sidewalks								
Concrete	100%			LIFE	**			
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 2 Scuppers</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Granite	100%			LIFE	**			
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Roadway</i>								
Pedestals								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
252ND ST BRIDGE
Asset # : 14579

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 75%</i>					
			<i>Location : Random Locations Throughout</i>					
Guide Railing								
Steel	100%			LIFE	**			
Timber	100%			2055	**			
Railings/Parapets								
Granite	100%			LIFE	**			
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Efflorescence</i>					
Steel	100%			LIFE	**	2-8	\$5,900	
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Paint Peeling</i>					
Sidewalks								
Concrete	100%			2040	**	5	\$3,300	
			<i>Cracks, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	100%			2044	**	5	\$15,900	
			<i>Cracks, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%			LIFE	**			
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 278 I EASTBOUND - BQE CADMAN PLZA / 278I WESTBOUND
Address : 278 I EASTBOUND - BQE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0360.000 / 15374 **Yr Built/Renovated** :
Area Sq Ft : 2,352 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 07-Jul-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230888

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$87,000	\$276,300
Total	\$87,000	\$276,300
Importance Code B	\$87,000	\$187,200
Importance Code C		\$89,000
Total	\$87,000	\$276,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$70,800		\$2,500	\$1,400
Total	\$70,800		\$2,500	\$1,400
Importance Code A	\$1,300		\$2,500	
Importance Code B	\$21,000			
Importance Code C	\$48,500			\$1,400
Total	\$70,800		\$2,500	\$1,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278 I EASTBOUND - BQE CADMAN PLZA / 278I WESTBOUND

Asset # : 15374

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Backwall								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Stem (breastwall)								
Concrete	100%	Now	\$87,000	LIFE	**			
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Both Abutments On South End</i>					
			<i>Other Observation, Extent : Severe, Area Affected : 80%</i>					
			<i>Location : Both Abutment Fascias</i>					
			<i>Explanation : Light Scaling/ Honeycomb In 2 Percent Of Area.</i>					
			<i>Fascia Panels Missing.</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Concrete	100%	Now	\$48,500	LIFE	**			
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 60%</i>					
			<i>Location : Missing Panels Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Southeast Wingwall.</i>					
			<i>Explanation : Under Construction</i>					
Masonry	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Northeast Wingwall</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Approaches								
Pavement								
Asphalt	100%			2033	\$89,000	4	\$2,700	
Curbs								
Concrete	100%			LIFE	**			
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278 I EASTBOUND - BQE CADMAN PLZA / 278I WESTBOUND
Asset # : 15374

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets								
Steel	100%	4+	\$600	LIFE		**		
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Stem,Solid Pier								
Concrete	100%	Now	\$9,100	LIFE		**		
<i>Other Observation, Extent : Severe, Area Affected : 20%</i>								
<i>Location : On Both Faces Of Pier</i>								
<i>Explanation : Fascia Panels Missing</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%			2052		**		
Railings/Parapets								
Steel	100%	4+	\$700	LIFE		**	2-8	\$5,200
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%			2033	\$20,900		5	
Superstructure								
Deck,Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE		**	2-8	\$43,500
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Concrete	8%	4+	\$12,000	LIFE		**	5	\$93,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Infill Between Girders As Counterweight</i>								
Concrete	92%			LIFE		**	5	\$93,600

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 278 I SOUTHBOUND - BQE WEST LEG OVER 31ST AVENUE
Address : BROOKLYN QUEENS EXPRESSWAY 31ST AVE BET 61ST & 68TH STS
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0352.000 / 15366 **Yr Built/Renovated** :
Area Sq Ft : 5,208 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Jul-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230740

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure				\$2,200
Total				\$2,200
Importance Code A				\$2,200
Total				\$2,200



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
278 I SOUTHBOUND - BQE WEST LEG OVER 31ST AVENUE
Asset # : 15366

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE			**
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Concrete	100%			LIFE			**
<i>Cracks, Extent : Light, Area Affected : 2%</i>							
<i>Location : Full Height Vertical Crack On Both Abutments</i>							
<i>Spalling, Extent : Light, Area Affected : 1%</i>							
<i>Location : South Abutment At Construction Joint Near Middle And Top Of Wall</i>							
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>							
<i>Location : East End Of Both Abutments</i>							
<i>Explanation : Vegetation Growth</i>							
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE			**
Piles							
Not Accessible	100%						
Walls							
Masonry	100%			LIFE			**
<i>Vegetation Growth, Extent : Severe, Area Affected : 50%</i>							
<i>Location : Both Wingwalls At East End</i>							
Feature Crossed							
Mat (scour & erosion)							
Generic	100%			LIFE			**
Approaches							
Pavement							
Concrete	100%			2041		4	**
<i>Cracks, Extent : Light, Area Affected : 10%</i>							
<i>Location : Both Approaches</i>							
Embankment							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278 I SOUTHBOUND - BQE WEST LEG OVER 31ST AVENUE

Asset # : 15366

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041	**	4	\$1,900	
		<i>Other Observation, Extent : Moderate, Area Affected : 40%</i>						
		<i>Location : Southeast And Northeast Approach</i>						
		<i>Explanation : Vegetation Growth</i>						
Deck Elements								
Railings/Parapets								
Concrete	100%			2041	**	4	\$2,600	
		<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>						
		<i>Location : Northeast And Southeast Corner</i>						
		<i>Explanation : Vegetation Growth</i>						
Wearing Surface								
Concrete	100%			2041	**	5		
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
Superstructure								
Deck,Structural								
Not Accessible	100%							
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			
		<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Light Vegetation Near Abutments In 2 Percent Of Area. Water Stains.</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 278I EASTBOUND - BQE 278I WESTBOUND - BQE
Address : BTWN WASHINGTON & OLD FULTON STS
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0377.000 / 15395 **Yr Built/Renovated** :
Area Sq Ft : 9,274 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 25-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2268518

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$568,600	\$88,400
Total	\$568,600	\$88,400
Importance Code B	\$568,600	
Importance Code C		\$88,400
Total	\$568,600	\$88,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,000		\$400	\$5,600
Total	\$2,000		\$400	\$5,600
Importance Code A	\$1,400		\$400	
Importance Code C	\$600			\$5,600
Total	\$2,000		\$400	\$5,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I EASTBOUND - BQE 278I WESTBOUND - BQE

Asset # : 15395

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Wingwall Only On Southeast Side</i>						
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	100%			2034	\$40,400	4	\$1,900	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Curbs								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I EASTBOUND - BQE 278I WESTBOUND - BQE

Asset # : 15395

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%	0-2	\$568,600	LIFE				**
<i>Cracks, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Delaminations, Extent : Moderate, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Moderate, Area Affected : 5%</i> <i>Location : South End</i> <i>Explanation : Limited Access To Stem Solid Pier On 50 Percent Of Area. Vegetation Growth</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%			2053				**
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Railings/Parapets								
Steel	100%	2-4	\$1,400	LIFE		**	2-8	\$10,600
<i>Other Observation, Extent : Severe, Area Affected : 10%</i> <i>Location : Near South End</i> <i>Explanation : Limited Access To Railings Throughout. Vegetation Growth</i>								
Wearing Surface								
Asphalt	100%			2034	\$88,400	5	\$11,300	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I EASTBOUND - BQE 278I WESTBOUND - BQE
Asset # : 15395

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 278I NORTH BOUND - BQE EAST LEG 32ND AVENUE TO BQE WEST LEG
 Address : BQE EAST OVER 32ND AVENUE AT ABOUT 68TH STREET
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0231.000 / 14970 Yr Built/Renovated : 2004 /
 Area Sq Ft : 31,319 Project Type : HIGHWAY BRIDGES
 Date of Survey : 17-Jan-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2230700

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$119,200	\$393,800
Total	\$119,200	\$393,800
Importance Code A		\$310,000
Importance Code C	\$119,200	\$83,800
Total	\$119,200	\$393,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$15,600	\$12,100	\$34,400	
Total	\$15,600	\$12,100	\$34,400	
Importance Code A		\$12,100	\$32,600	
Importance Code B			\$1,900	
Importance Code C	\$15,600			
Total	\$15,600	\$12,100	\$34,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I NORTH BOUND - BQE EAST LEG 32ND AVENUE TO BQE WEST LEG
Asset # : 14970

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Multi-Rotational Bearing	100%			2062		**		
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%			LIFE		**		
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Form Liner</i>					
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Paved Roadway</i>					
Pier Protection Concrete	100%			LIFE		**		
Approaches								
Pavement Concrete	100%	4+	\$15,600	2043		**	4	\$12,100
			<i>Cracks, Extent : Light, Area Affected : 7%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment Generic	100%			LIFE		**		
Mat (scour & erosion) Not Accessible	100%							
Pavement Base Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I NORTH BOUND - BQE EAST LEG 32ND AVENUE TO BQE WEST LEG
Asset # : 14970

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Concrete	100%			2043	**	4	\$2,600	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Barrier</i>								
Piers								
Cap Beam Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 25 Percent Concrete</i>								
Steel	100%			LIFE	**	2-8	\$34,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 75 Percent Steel</i>								
Pier,Columns Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads Multi-Rotational Bearing	100%			2062	**			
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Piles Not Accessible	100%							
Deck Elements								
Railings/Parapets Concrete	100%			2043	**	4	\$33,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Barrier</i>								
Wearing Surface Concrete	100%	4+	\$119,200	2043	**	5	\$83,800	
<i>Cracks, Extent : Light, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 4 Scuppers Observed</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I NORTH BOUND - BQE EAST LEG 32ND AVENUE TO BQE WEST LEG
Asset # : 14970

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : Stay-in-place Form</i>						
Joins								
Generic	100%			LIFE			* *	
Primary Member								
Steel	100%			LIFE		2-8	\$579,000	
Secondary Member								
Steel	100%			LIFE		2-8	\$29,100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 278I SOUTH BOUND - BQE EAST LEG 278I NORTH BOUND - BQE WEST LEG
 Address : BQE SOUTH BOUND OVER NORTH BOUND BQE ABOUT 32ND AVE & 68TH STREET
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0235.000 / 14975 Yr Built/Renovated : 2003 /
 Area Sq Ft : 20,821 Project Type : HIGHWAY BRIDGES
 Date of Survey : 17-Jan-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2230720

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$104,600
Total		\$104,600
Importance Code A		\$49,000
Importance Code C		\$55,600
Total		\$104,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$107,500	\$7,700	\$6,200	
Total	\$107,500	\$7,700	\$6,200	
Importance Code A	\$8,700	\$7,700	\$4,900	
Importance Code B	\$35,400		\$1,200	
Importance Code C	\$63,400			
Total	\$107,500	\$7,700	\$6,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I SOUTH BOUND - BQE EAST LEG 278I NORTH BOUND - BQE WEST LEG
Asset # : 14975

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Masonry	100%	4+	\$8,700	LIFE			**	
	<i>Other Observation, Extent : N/A, Area Affected : 5%</i>							
	<i>Location : South Abutment</i>							
	<i>Explanation : Cracks, 50 Percent Masonry</i>							
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : 50 Percent Not Accessible</i>							
Backwall								
Concrete	50%	4+	\$10,200	LIFE			**	
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : South Abutment</i>							
	<i>Efflorescence, Extent : Light, Area Affected : 10%</i>							
	<i>Location : South Abutment</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 50 Percent Concrete</i>							
Concrete	50%			LIFE			**	
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : 50 Percent Not Accessible</i>							
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2062			**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : South Abutment</i>							
	<i>Explanation : 50 Percent Multi-rotational Bearing</i>							
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : 50 Percent Not Accessible</i>							
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	100%	2-4	\$35,400	LIFE			**	
	<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I SOUTH BOUND - BQE EAST LEG 278I NORTH BOUND - BQE WEST LEG
Asset # : 14975

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : South Abutment</i>						
		<i>Explanation : 50 Percent Generic</i>						
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : South Abutment</i>						
		<i>Explanation : 50 Percent Not Accessible</i>						
Pedestals								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : South Abutment</i>						
		<i>Explanation : 50 Percent Concrete</i>						
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : South Abutment</i>						
		<i>Explanation : 50 Percent Not Accessible</i>						
Stem (breastwall)								
Masonry	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : South Abutment</i>						
		<i>Explanation : 50 Percent Masonry</i>						
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : 50 Percent Not Accessible</i>						
Walls								
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : 50 Percent Not Accessible</i>						
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 50 Percent Generic</i>						
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 50 Percent Not Accessible</i>						
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I SOUTH BOUND - BQE EAST LEG 278I NORTH BOUND - BQE WEST LEG
Asset # : 14975

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Masonry	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South Abutment</i>								
<i>Explanation : 50 Percent Masonry</i>								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : 50 Percent Not Accessible</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Roadway</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$18,500	2043		**	4	\$13,200
<i>Cracks, Extent : Light, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2043		**	4	\$2,500
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$113,300
Pier,Columns								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2062		**		
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2043		**	4	\$20,600

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I SOUTH BOUND - BQE EAST LEG 278I NORTH BOUND - BQE WEST LEG
Asset # : 14975

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface Concrete	100%	4+	\$34,600	2043	**	5	\$55,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stay-in-place Form</i>								
Joints								
Steel	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Box Girders</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$19,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 278I WEST BOUND BQE CADMAN PLAZA
Address : BQE WEST BOUND OVER CADMAN PLAZA
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0248.000 / 14988 **Yr Built/Renovated** :
Area Sq Ft : 4,464 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 21-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230887

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$395,000	\$317,900
Total	\$395,000	\$317,900
Importance Code A	\$161,300	
Importance Code B	\$129,100	
Importance Code C	\$104,700	\$317,900
Total	\$395,000	\$317,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$52,700		\$300	
Total	\$52,700		\$300	
Importance Code A	\$10,900			
Importance Code B	\$35,500		\$300	
Importance Code C	\$6,400			
Total	\$52,700		\$300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
278I WEST BOUND BQE CADMAN PLAZA
Asset # : 14988

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals Concrete	100%			LIFE		**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>							
<i>Location : Throughout</i>							
<i>Explanation : Limited Access</i>							
Backwall Not Accessible	100%						
Brngs,Ancr Blts,Pads Not Accessible	100%						
Footings Not Accessible	100%						
Joint with Deck Not Accessible	100%						
Mat (scour & erosion) Concrete	100%			LIFE		**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
<i>Location : Throughout</i>							
<i>Explanation : Sidewalk In Front Of Abutments</i>							
Pedestals Not Accessible	100%						
Stem (breastwall) Concrete	100%	4+	\$129,100	LIFE		**	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 90%</i>							
<i>Location : Missing Concrete Cladding Throughout</i>							
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Spalling, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>							
<i>Location : In Front Of Stem On Both Abutments</i>							
<i>Explanation : Timber Columns Supporting Girders At Southwest Corner. Steel Columns Supporting Girders At Northeast And Southeast Corners</i>							
Wingwalls							
Footings Not Accessible	100%						
Mat (scour & erosion) Generic	100%			LIFE		**	
Piles Not Accessible	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I WEST BOUND BQE CADMAN PLAZA
Asset # : 14988

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	100%	2-4	\$104,700	LIFE			**	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Missing Concrete Cladding On Northwest Wingwall</i>								
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Severe Cases On Northwest Wingwall</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Severe Cases On Northwest Wingwall</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Wingwalls Only At North Side</i>								
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Roadway</i>								
Approaches								
Pavement								
Asphalt	100%	4+	\$4,700	2035	\$236,500	4	\$3,900	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete	100%	4+	\$4,300	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	85%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On Northeast And Northwest Approaches</i>								
Cast Iron	15%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On North Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Northeast And Northwest Approaches</i>								
<i>Explanation : Ornamental Top Railing</i>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I WEST BOUND BQE CADMAN PLAZA
Asset # : 14988

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%	4+	\$35,500	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
Pedestals Concrete	100%			LIFE			**	
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete	100%	4+	\$6,600	2054			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets Cast Iron	85%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Cast Iron	15%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Ornamental Top Railing</i>								
Wearing Surface Asphalt	100%	4+	\$1,600	2035	\$81,400	5	\$2,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I WEST BOUND BQE CADMAN PLAZA
Asset # : 14988

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure Deck, Structural Concrete	100%	4+	\$161,300	LIFE	**	5	\$4,900	
<i>Cracks, Extent : Moderate, Area Affected : 15%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Efflorescence, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Other Observation, Extent : Moderate, Area Affected : 15%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Explanation : Timber Shielding On East 40 Percent Area On Underside Of East Span.</i> <i>Scaling</i>								
Joints Not Accessible	100%							
Primary Member Steel	100%			LIFE	**	2-8		
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								
Secondary Member Steel	100%			LIFE	**	2-8	\$4,200	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 278I WESTBOUND - BQE FURMAN STREET
Address : BQE WESTBOUND OVER FURMAN STREET
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0376.000 / 15394 **Yr Built/Renovated** :
Area Sq Ft : 10,824 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 25-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2268517

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,063,100	\$169,900
Total	\$1,063,100	\$169,900
Importance Code A	\$885,500	\$55,700
Importance Code B	\$177,600	
Importance Code C		\$114,200
Total	\$1,063,100	\$169,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$4,600		\$200	\$7,300
Total	\$4,600		\$200	\$7,300
Importance Code A	\$4,100		\$200	
Importance Code C	\$600			\$7,300
Total	\$4,600		\$200	\$7,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I WESTBOUND - BQE FURMAN STREET
Asset # : 15394

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE	**			
			<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Southwest Side</i>					
			<i>Explanation : One Wingwall Only</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Asphalt Pavement</i>					
Approaches								
Pavement								
Asphalt	100%			2034	\$36,100	4	\$1,700	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Curbs								
Concrete	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4	\$1,200	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					

Piers

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I WESTBOUND - BQE FURMAN STREET
Asset # : 15394

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%	4+	\$177,600	LIFE				**
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : At Missing Panels And At Random Locations</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Limited Access In 50 Percent Area. Enclosed By Concrete Wall. Broken/ Missing Concrete Panels</i>								
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Generic	100%			LIFE				**
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Paving</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete	15%	4+	\$1,400	2053				**
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
<hr/>								
Concrete	85%			2053				**
<hr/>								
Railings/Parapets								
Steel	100%	2-4	\$2,300	LIFE		**	2-8	\$7,000
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
<hr/>								
Wearing Surface								
Asphalt	100%			2034	\$114,200	5		\$14,500
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
<hr/>								
Superstructure								
Deck,Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
278I WESTBOUND - BQE FURMAN STREET
Asset # : 15394

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Joints								
Not Accessible	100%							
Primary Member								
Concrete	100%	4+	\$885,500	LIFE	**	5	\$55,700	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Concentrated At Joints</i>					
			<i>Explanation : Scaling</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 28TH AVENUE PEDESTRIAN BRIDGE CROSS ISLAND PARKWAY
Address : BETWEEN 28TH AVE AND 28TH RD LITTLE NECK BAY
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0267.000 / 15021 **Yr Built/Renovated** :
Area Sq Ft : 7,380 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 05-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231890

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$76,900		\$7,700	
Total	\$76,900		\$7,700	
Importance Code A	\$73,600		\$3,100	
Importance Code B	\$3,400		\$300	
Importance Code C			\$4,400	
Total	\$76,900		\$7,700	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
28TH AVENUE PEDESTRIAN BRIDGE CROSS ISLAND PARKWAY
Asset # : 15021

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE	**			
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE	**			
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Underneath Primary Spans</i>					
			<i>Explanation : Asphalt Roadway</i>					
Pier Protection Concrete	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Piers On Cross Island Parkway</i>					
			<i>Explanation : Concrete Barrier</i>					
Approaches								
Pavement Asphalt	100%			2036	**	4	\$8,700	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pavement Base Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
28TH AVENUE PEDESTRIAN BRIDGE CROSS ISLAND PARKWAY
Asset # : 15021

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets								
Steel	100%			LIFE		**		
	<i>Damaged Railing, Extent : Light, Area Affected : 2%</i>							
	<i>Location : W Beam At Northwest Approach</i>							
Timber	100%	4+	\$3,200	LIFE		**		
	<i>Other Observation, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Checks/ Splits</i>							
Piers								
Cap Beam								
Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Timber Cap On Primary Spans. Limited Access To Ramp Spans Due To Timber Shielding.</i>							
Pier,Columns								
Timber	100%			LIFE		**		
	<i>Split/Dry/Cracked, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$28,400
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Primary Spans</i>							
	<i>Explanation : Chain Link Fence Behind Timber Railing</i>							
Timber	100%	2-4	\$8,200	LIFE		**		
	<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 20%</i>							
	<i>Location : Steel Base Plates For Timber Railing Posts On Primary Spans</i>							
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Checks/ Splits</i>							
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
28TH AVENUE PEDESTRIAN BRIDGE CROSS ISLAND PARKWAY
Asset # : 15021

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Timber	100%	2-4	\$1,700	LIFE		**		
	<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Broken Missing/ Checks/ Splits</i>							
Primary Member								
Steel	100%	4+	\$49,500	LIFE		**	2-8	\$45,500
	<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout With Worse Cases On Top Flanges On Primary Spans</i>							
	<i>Delaminations, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Top Flanges On Primary Spans</i>							
	<i>Rust Stains, Extent : Light, Area Affected : 1%</i>							
	<i>Location : Primary Spans Over Cross Island Parkway</i>							
	<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>							
	<i>Location : Primary Spans Over Cross Island Parkway</i>							
	<i>Explanation : Paint Peeling</i>							
Secondary Member								
Steel	100%			LIFE		**	2-8	\$7,800
	<i>Corrosion, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Primary Spans Over Cross Island Parkway</i>							
	<i>Rust Stains, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Primary Spans Over Cross Island Parkway</i>							
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Primary Spans Over Cross Island Parkway</i>							
	<i>Explanation : Paint Peeling</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 31ST STREET BRIDGE
Address : 31ST STREET OVER BROOKLYN/QUEENS EXPRESSWAY
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0175.000 / 13670 **Yr Built/Renovated** :
Area Sq Ft : 9,500 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 29-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230657

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$2,061,400	\$795,500
Total	\$2,061,400	\$795,500
Importance Code A	\$1,157,700	\$701,500
Importance Code B	\$789,400	\$94,000
Importance Code C	\$114,200	
Total	\$2,061,400	\$795,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$95,900		\$19,000	
Total	\$95,900		\$19,000	
Importance Code A	\$7,500		\$9,600	
Importance Code B	\$55,500		\$9,400	
Importance Code C	\$32,900			
Total	\$95,900		\$19,000	



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
31ST STREET BRIDGE
Asset # : 13670

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$10,300	LIFE			**	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Center Lanes, Both Abutments Joint Headers</i>								
Mat (scour & erosion) Generic	100%			LIFE			**	
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	100%	4+	\$28,000	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
Piles Not Accessible	100%							
Walls Concrete	90%			LIFE			**	
Concrete	10%	4+	\$114,200	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Approaches								
Pavement Asphalt	100%	4+	\$6,500	2036		**	4	\$2,700
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
31ST STREET BRIDGE
Asset # : 13670

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Curbs								
Concrete w/ Steel Face	90%			LIFE		**		
Concrete w/ Steel Face	10%	4+	\$5,000	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 50%</i>								
<i>Location : Southwest Corner</i>								
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Sidewalks								
Concrete	100%	4+	\$4,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Piers								
Stem,Solid Pier								
Concrete	60%	4+	\$695,400	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	40%			LIFE		**		
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Roadway</i>								
<hr/>								
Pedestals								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
31ST STREET BRIDGE
Asset # : 13670

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets Steel	100%			LIFE	**	2-8	\$6,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 4-rail Railing</i>								
<hr/>								
Sidewalks								
Concrete	5%	4+	\$15,200	2040	**	5	\$3,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout, Near The Joints</i>								
Concrete	95%			2040	**	5	\$6,800	
<hr/>								
Wearing Surface								
Asphalt	100%	4+	\$7,300	2036	**	5	\$6,200	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	25%	4+	\$791,000	LIFE	**	5	\$303,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	75%			LIFE	**	5	\$607,400	
<hr/>								
Primary Member								
Steel	100%	4+	\$63,000	LIFE	**	2-8	\$175,600	
<i>Other Observation, Extent : Moderate, Area Affected : 4%</i>								
<i>Location : Above Southbound Lane</i>								
<i>Explanation : Impact Damage</i>								
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$258,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 32ND STREET BRIDGE 32ND ST./278I (B.Q.E.)
Address : 32ND STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0176.000 / 13710 **Yr Built/Renovated** : 1930 / 1982
Area Sq Ft : 8,100 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230640

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$206,500	\$80,200
Total	\$206,500	\$80,200
Importance Code A		\$80,200
Importance Code B	\$149,800	
Importance Code C	\$56,700	
Total	\$206,500	\$80,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$23,800	\$19,600	\$8,200	
Total	\$23,800	\$19,600	\$8,200	
Importance Code A	\$2,100		\$8,200	
Importance Code B	\$1,700			
Importance Code C	\$19,900	\$19,600		
Total	\$23,800	\$19,600	\$8,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
32ND STREET BRIDGE 32ND ST./278I (B.Q.E.)

Asset # : 13710

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Bridge Seat And Pedestals Consist Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$1,700	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : At Both Abutments</i>								
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pedestals Consist Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Stem (breastwall) Concrete	100%	4+	\$68,400	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem Consists Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
32ND STREET BRIDGE 32ND ST./278I (B.Q.E.)**

Asset # : 13710

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	100%	4+	\$56,700	LIFE		**		
<i>Cracking/Crumbling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Walls Consist Of 40 Percent Concrete, 60 Percent Not Accessible</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$13,700	2041		**	4	\$13,400
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Both Approaches</i>								
Curbs								
Concrete w/ Steel Face	100%	2-4	\$2,100	LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Approach</i>								
Embankment								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Steel Fence Behind Railing Throughout With Minor Corrosion</i>								
Sidewalks								
Concrete	100%	4+	\$6,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Approach</i>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
32ND STREET BRIDGE 32ND ST./278I (B.Q.E.)
Asset # : 13710

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	5%	4+	\$81,400	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem Consists Of 5 Percent Concrete, 95 Percent Not Accessible</i>								
Concrete	95%			LIFE			**	
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Mono Deck Surface Concrete	100%			2052		**	5	\$35,900
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 45%</i>								
<i>Location : West Side</i>								
<i>Explanation : Concrete Patches</i>								
Railings/Parapets Steel	100%			LIFE		**	2-8	\$3,600
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind Railing</i>								
Sidewalks Concrete	100%			2037		**	5	\$3,400
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural Not Accessible	100%							
Primary Member Steel	100%			LIFE		**	2-8	\$149,700
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Primary Member Consists Of 10 Percent Steel, 90 Percent Not Accessible</i>								
Secondary Member Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
32ND STREET BRIDGE 32ND ST./278I (B.Q.E.)
Asset # : 13710**

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 35TH STREET 287I B.Q.E
 Address : 35TH STREET BET. ASTORIA BLVD. S AND ASTORIA BLVD. N
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0232.000 / 14972 Yr Built/Renovated : 1935 /
 Area Sq Ft : 7,921 Project Type : HIGHWAY BRIDGES
 Date of Survey : 17-Jan-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2230630

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$125,200	\$301,100
Total	\$125,200	\$301,100
Importance Code A	\$125,200	\$55,100
Importance Code B		\$30,100
Importance Code C		\$215,900
Total	\$125,200	\$301,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$64,600	\$1,600	\$9,300	
Total	\$64,600	\$1,600	\$9,300	
Importance Code A	\$36,900		\$5,800	
Importance Code B			\$3,500	
Importance Code C	\$27,700	\$1,600		
Total	\$64,600	\$1,600	\$9,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
35TH STREET 287I B.Q.E
Asset # : 14972

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE	**		
Piles							
Not Accessible	100%						
Walls							
Concrete	100%			LIFE	**		
Feature Crossed							
Mat (scour & erosion)							
Generic	100%			LIFE	**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : Throughout</i>				
			<i>Explanation : Paved Roadway</i>				
Pier Protection							
Concrete	100%			LIFE	**		
Approaches							
Pavement							
Asphalt	100%			2035	\$215,900	4	\$4,800
Curbs							
Concrete w/ Steel Face	100%			LIFE	**		
Embankment							
Generic	100%			LIFE	**		
Mat (scour & erosion)							
Not Accessible	100%						
Pavement Base							
Not Accessible	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
35TH STREET 287I B.Q.E
Asset # : 14972

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets								
Concrete	100%	4+	\$6,800	2043	**	4	\$1,500	
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 10 Percent Concrete</i>								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 90 Percent Steel, Chain Link Fence And Four Rail Railing</i>								
Sidewalks								
Concrete	100%	4+	\$4,100	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$127,300	
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$86,800	
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
35TH STREET 287I B.Q.E
Asset # : 14972

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Concrete	100%	4+	\$30,100	2043	**	4	\$4,800	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 5 Percent Concrete</i>								
Steel	100%			LIFE	**	2-8	\$6,600	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 95 Percent Steel, Chain Link Fence And Four Rail Railing</i>								
Sidewalks								
Concrete	100%	4+	\$14,500	2039	**	5	\$2,900	
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$9,000	2043	**	5	\$14,500	
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural Concrete	100%	4+	\$125,200	LIFE	**	5	\$8,700	
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Per 2022 - Inspection</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Per 2022 - Inspection</i>								
Joints								
Steel	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8		
Secondary Member								
Steel	100%			LIFE	**	2-8	\$7,400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 3RD AVE. BRIDGE
Address : 3RD AVE. OVER LIRR BAY RIDGE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0165.000 / 13573 **Yr Built/Renovated** : 1914 /
Area Sq Ft : 17,230 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 04-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243320

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$134,400	
Total	\$134,400	
Importance Code C	\$134,400	
Total	\$134,400	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$138,900		\$6,200	
Total	\$138,900		\$6,200	
Importance Code A	\$80,000		\$400	
Importance Code B	\$7,000			
Importance Code C	\$51,900		\$5,800	
Total	\$138,900		\$6,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
3RD AVE. BRIDGE
Asset # : 13573

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	2-4	\$7,000	LIFE			**	
			<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Both Abutments</i>					
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Both Abutments</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%	0-2	\$134,400	2042			** 4	\$31,600
			<i>Broken,Missing Pave, Extent : Severe, Area Affected : 5%</i>					
			<i>Location : Both Approaches</i>					
			<i>Cracks, Extent : Moderate, Area Affected : 15%</i>					
			<i>Location : Both Approaches</i>					
			<i>Spalling, Extent : Severe, Area Affected : 5%</i>					
			<i>Location : Both Approaches</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
3RD AVE. BRIDGE
Asset # : 13573

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	Now	\$24,100	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Corner</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Corner</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042		**	4	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Northeast Corner</i>								
Steel	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Bottom Rails</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Railing On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%	2-4	\$21,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Southeast And Southwest Corner</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Total 4 Scuppers</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
3RD AVE. BRIDGE
Asset # : 13573

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$39,400	LIFE		**		
			<i>Rust Stains, Extent : Moderate, Area Affected : 40%</i>					
			<i>Location : Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Median								
Concrete	100%	4+	\$12,800	LIFE		**	5	\$5,300
			<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Near North Abutment Joint</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Near North Abutment Joint</i>					
Railings/Parapets								
Concrete	100%			2042		**	4	\$11,000
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE		**	2-8	\$10,100
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Bottom Bar</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : On Top Of Concrete Parapets Throughout</i>					
			<i>Explanation : Chain Link Fence</i>					
Sidewalks								
Concrete	100%			2038		**	5	\$11,700
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	100%	4+	\$24,400	2042		**	5	\$32,400
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
3RD AVE. BRIDGE
Asset # : 13573

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Generic	100%	4+	\$6,400	LIFE				* *
		<i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 41ST AVENUE 278I BROOKLYN-QUEENS EXPRESSWAY
Address : 41ST AVE BET 70TH AND 71ST AVES. WOODSIDE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0319.000 / 15178 **Yr Built/Renovated** : 1955 /
Area Sq Ft : 8,320 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230570

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$87,000
Total		\$87,000
Importance Code A		\$87,000
Total		\$87,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$26,400	\$2,700	\$8,900	\$2,700
Total	\$26,400	\$2,700	\$8,900	\$2,700
Importance Code A			\$8,900	\$2,700
Importance Code B	\$900			
Importance Code C	\$25,500	\$2,700		
Total	\$26,400	\$2,700	\$8,900	\$2,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
41ST AVENUE 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15178

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals Not Accessible	100%						
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Access Required On Brooklyn Queens Expressway Below</i>						
<hr/>							
Backwall Not Accessible	100%						
<hr/>							
Brngs,Ancr Blts,Pads Not Accessible	100%						
<hr/>							
Footings Not Accessible	100%						
<hr/>							
Joint with Deck							
Generic	10%	2-4	\$900	LIFE		**	
	<i>Misaligned/Bulging, Extent : Light, Area Affected : 10%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Explanation : Debris Build Up</i>						
<hr/>							
Generic	90%			LIFE		**	
<hr/>							
Mat (scour & erosion)							
Generic	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 95%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Mat Consists Of 5 Percent Generic, 95 Percent Not Accessible</i>						
<hr/>							
Pedestals							
Not Accessible	100%						
<hr/>							
Stem (breastwall)							
Not Accessible	100%						
<hr/>							
Wingwalls							
Footings							
Not Accessible	100%						
<hr/>							
Mat (scour & erosion)							
Generic	100%			LIFE		**	
<hr/>							
Piles							
Not Accessible	100%						
<hr/>							
Walls							
Concrete	100%			LIFE		**	
	<i>Cracks, Extent : Light, Area Affected : 5%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Other Observation, Extent : N/A, Area Affected : 75%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Walls Consist Of 25 Percent Concrete, 75 Percent Not Accessible</i>						
<hr/>							
Feature Crossed							
Mat (scour & erosion)							
Generic	100%			LIFE		**	
<hr/>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
41ST AVENUE 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15178

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Cracks. Pier Protection Consists Of 5 Percent Concrete, 95 Percent Not Accessible</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$9,100	2041		**	4	\$13,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 2%</i>								
<i>Location : East Approach</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041		**	4	\$1,300
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Railing And Fence On Top Of Concrete</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem, Solid Pier Consists Of 5 Percent Concrete, 95 Percent Not Accessible</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
41ST AVENUE 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15178

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Concrete	100%			2041	**	4	\$4,100	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE	**	2-8	\$5,600	
			<i>Other Observation, Extent : N/A, Area Affected : 95%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Steel Railing And Fence On Top Of Concrete</i>					
Sidewalks								
Concrete	100%			2037	**	5	\$5,300	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	100%			2041	**	5	\$32,900	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	**	2-8	\$162,400	
			<i>Corrosion, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 95%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Primary Member Consists Of 5 Percent Steel, 95 Percent Not Accessible</i>					
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 44TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY
 Address : 44TH STREET OVER BQE BETWEEN ASTORIA BLVDS. N AND S
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0323.000 / 15182 Yr Built/Renovated :
 Area Sq Ft : 5,472 Project Type : HIGHWAY BRIDGES
 Date of Survey : 12-Jan-2021 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2230840

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$247,200
Total		\$247,200
Importance Code A		\$138,900
Importance Code C		\$108,200
Total		\$247,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$40,200	\$1,800	\$17,100	\$1,700
Total	\$40,200	\$1,800	\$17,100	\$1,700
Importance Code A	\$16,400		\$16,100	
Importance Code B			\$1,100	
Importance Code C	\$23,800	\$1,800		\$1,700
Total	\$40,200	\$1,800	\$17,100	\$1,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
44TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15182

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Bridge Seat And Pedestals Consist Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem Consists Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Walls Consist Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
Pier Protection Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier Protection Consists Of 20 Percent Concrete, 80 Percent Not Accessible</i>								
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
44TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15182

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	100%			2033	\$108,200	4	\$3,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%	2-4	\$14,500	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	0-2	\$1,900	2041		**	4	\$400
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Southeast Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Southeast Approach</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Includes Steel Bridge Rail And Chain Link Fence.</i>								
Sidewalks								
Concrete	100%	0-2	\$9,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northeast Approach</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$45,700
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Cap Beam Consists Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$30,900
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : At The Base Of Column</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier, Column Consists Of 10 Percent Steel, 90 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
44TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15182

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$4,100	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Includes Steel Bridge Rail And Chain Link Fence.</i>								
Sidewalks								
Concrete	100%			2037	**	5	\$3,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%	4+	\$14,600	2033	\$36,400	5	\$2,300	
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : West Span</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$259,500	
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : On Top Flange On Both Sides</i>								
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Primary Member Consists Of 20 Percent Steel, 80 Percent Not Accessible</i>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 47TH STREET GRAND CENTRAL PARKWAY
Address : 47TH ST OVER GRAND CENTRAL PKWY BET ASTORIA BLVDS. N AND S
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0322.000 / 15181 **Yr Built/Renovated** : 1937 /
Area Sq Ft : 5,700 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230820

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$406,800
Total		\$406,800
Importance Code A		\$158,200
Importance Code C		\$248,600
Total		\$406,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$20,900	\$1,800	\$19,300	\$300
Total	\$20,900	\$1,800	\$19,300	\$300
Importance Code A	\$4,700		\$18,100	\$300
Importance Code B	\$1,200		\$1,100	
Importance Code C	\$15,000	\$1,800		
Total	\$20,900	\$1,800	\$19,300	\$300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
47TH STREET GRAND CENTRAL PARKWAY
Asset # : 15181

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	2-4	\$1,200	LIFE			**	
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>					
			<i>Location : North Approach</i>					
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 70%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stem Consists Of 30 Percent Concrete, 70 Percent Not Accessible</i>					
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE			**	
			<i>Vegetation Growth, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Southwest Side</i>					
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
Pier Protection Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Pier Protection Consists Of 40 Percent Concrete, 60 Percent Not Accessible</i>					
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
47TH STREET GRAND CENTRAL PARKWAY
Asset # : 15181

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	100%	4+	\$5,000	2033	\$248,600	4	\$7,700	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Approach</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$3,300	LIFE	**			
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southwest Approach</i>								
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Guide Railing								
Concrete	100%			2041	**	4	\$600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Northeast Approach Only</i>								
<i>Explanation : Placed For Protection Of Traffic Sign Post</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southeast Side</i>								
<i>Explanation : Railing Is Only On 1 Location</i>								
Sidewalks								
Concrete	100%	Now	\$2,100	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Approach</i>								
<i>Settlement, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Approach</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$48,900	
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Cap Beam Consists Of 10 Percent Steel, 90 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
47TH STREET GRAND CENTRAL PARKWAY
Asset # : 15181

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns Steel	100%			LIFE	**	2-8	\$32,400	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier, Columns Consist Of 10 Percent Steel, 90 Percent Not Accessible</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 35%</i>								
<i>Location : Random Locations Throughout</i>								
Guide Railing Concrete	100%			2045	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Near Northeast Approach</i>								
<i>Explanation : Placed For Protection Of Traffic Sign Post</i>								
Railings/Parapets Steel	100%	Now	\$1,400	LIFE	**	2-8	\$4,300	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : East Side</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Impact Damage At Southwest Side</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind Steel Railing</i>								
Sidewalks Concrete	100%			2037	**	5	\$3,700	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
47TH STREET GRAND CENTRAL PARKWAY
Asset # : 15181

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Concrete	100%	4+	\$7,900	2041	**	5	\$10,500	
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Midspan Along Lane Strip</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	**	2-8	\$295,500	
<i>Corrosion, Extent : Light, Area Affected : 2%</i> <i>Location : On Top Flange Of West Side</i> <i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Primary Member Consists Of 10 Percent Steel, 90 Percent Not Accessible</i>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 49TH AVE. BRIDGE
Address : 49TH AVE.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0167.000 / 13575 **Yr Built/Renovated** :
Area Sq Ft : 20,200 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 10-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247290

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$846,200	\$748,500
Total	\$846,200	\$748,500
Importance Code A	\$92,000	\$399,900
Importance Code B	\$578,000	\$348,700
Importance Code C	\$176,100	
Total	\$846,200	\$748,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$165,300	\$40,700	\$82,400	
Total	\$165,300	\$40,700	\$82,400	
Importance Code A	\$25,200		\$40,600	
Importance Code B	\$1,900		\$35,000	
Importance Code C	\$138,200	\$40,700	\$6,800	
Total	\$165,300	\$40,700	\$82,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
49TH AVE. BRIDGE
Asset # : 13575

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$1,900	LIFE		**		
			<i>Cracks, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Header Concrete</i>					
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Northwest Corner</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Stem (breastwall)								
Concrete	70%			LIFE		**		
Concrete	30%	4+	\$374,000	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Both Abutments</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	85%			LIFE		**		
Concrete	15%	4+	\$114,800	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Northwest Wingwall</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pier Protection								
Concrete	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
49TH AVE. BRIDGE
Asset # : 13575

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	20%	4+	\$49,800	2042	**	4	\$58,500	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	80%			2042	**	4	\$87,800	
Curbs								
Concrete w/ Steel Face	100%	4+	\$9,000	LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Stone	100%			LIFE	**			
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%	4+	\$38,900	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8		
Pier,Columns								
Steel	20%			LIFE	**	2-8	\$214,100	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	80%			LIFE	**	2-8	\$214,100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
49TH AVE. BRIDGE
Asset # : 13575

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier								
Concrete	80%			LIFE		**		
Concrete	20%	4+	\$204,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	90%			LIFE		**		
Concrete w/ Steel Face	10%	4+	\$11,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Severe, Area Affected : 70%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : At East Joint</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2042		**	4	\$15,400
Steel	100%			LIFE		**	2-8	\$14,100
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Entire Length</i>								
<i>Explanation : Chain Link Fence</i>								
<hr/>								
Sidewalks								
Concrete	80%			2038		**	5	\$13,600
Concrete	20%	4+	\$20,300	2038		**	5	\$6,800
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	90%			2042		**	5	\$81,400
Concrete	10%	4+	\$61,300	2042		**	5	\$40,700
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Joint Header Concrete</i>								
<i>Spalling, Extent : Light, Area Affected : 70%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 70%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Large Patched Areas</i>								
<hr/>								
Superstructure								
Deck,Structural								
Concrete	100%			LIFE		**	5	\$29,800

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
49TH AVE. BRIDGE
Asset # : 13575

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Generic	100%			LIFE		**		
Primary Member								
Steel	80%			LIFE		**	2-8	\$373,400
Steel	20%	4+	\$92,000	LIFE		**	2-8	\$373,400
			<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Minor Section Loss</i>					
Secondary Member								
Steel	100%			LIFE		**	2-8	\$312,800
			<i>Corrosion, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 49TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY
Address : 49TH STREET OVER BQE WEST WOODSIDE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0321.000 / 15180 **Yr Built/Renovated** : 1947 /
Area Sq Ft : 5,200 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230800

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$90,500
Total		\$90,500
Importance Code A		\$90,500
Total		\$90,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$26,600		\$9,200	\$2,700
Total	\$26,600		\$9,200	\$2,700
Importance Code A	\$9,400		\$9,200	
Importance Code C	\$17,200			\$2,700
Total	\$26,600		\$9,200	\$2,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
49TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15180

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Bridge Seat And Pedestals Consists Of 10 Percent Of Concrete, 90 Percent Not Accessible</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem Consists Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Walls Consist Of 40 Percent Concrete, 60 Percent Not Accessible</i>								
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
Pier Protection Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier Protection Consists Of 40 Percent Concrete, 60 Percent Not Accessible</i>								
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
49TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15180

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	90%			2041	**	4	\$5,300	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	10%	Now	\$3,600	2041	**	4	\$5,300	
<i>Spalling, Extent : Light, Area Affected : 30%</i>								
<i>Location : West Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Cap Beam Consists Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Pier, Columns								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier, Column Consists Of 10 Percent Of Concrete, 90 Percent Not Accessible</i>								
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
49TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15180

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Concrete	100%	4+	\$9,400	2041	**	4	\$3,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Side</i>								
Steel	100%			LIFE	**	2-8	\$4,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%	4+	\$4,800	2037	**	5	\$2,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2041	**	5	\$17,500	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	**	2-8	\$169,000	
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Primary Member Consists Of 20 Percent Steel, 80 Percent Not Accessible</i>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 49TH STREET GCP - GRAND CENTRAL PARKWAY
Address : 49TH STREET BET. ASTORIA BLVD N. AND ASTORIA BLVD S.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0279.000 / 15033 **Yr Built/Renovated** :
Area Sq Ft : 6,160 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 28-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230890

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$209,300	\$61,000
Total	\$209,300	\$61,000
Importance Code A	\$61,000	\$61,000
Importance Code C	\$148,300	
Total	\$209,300	\$61,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$111,300		\$10,100	\$11,300
Total	\$111,300		\$10,100	\$11,300
Importance Code A	\$63,500		\$8,500	
Importance Code B	\$28,900		\$1,600	
Importance Code C	\$18,900			\$11,300
Total	\$111,300		\$10,100	\$11,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
49TH STREET GCP - GRAND CENTRAL PARKWAY
Asset # : 15033

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Elastomeric	100%			2055		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,600	LIFE		**		
			<i>Cracks, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : South Deck Joint</i>					
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 2%</i>					
			<i>Location : South Deck Joint</i>					
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : South Deck Joint</i>					
			<i>Explanation : Edge Spalls/ Chipping</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : At Both Abutments, Moderate At South Abutment</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : At Both Abutments</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	5%	4+	\$148,300	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 80%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Location Throughout</i>					
Concrete	95%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Roadway</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
49TH STREET GCP - GRAND CENTRAL PARKWAY
Asset # : 15033

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains</i>								
Approaches								
Pavement								
Asphalt	100%	0-2	\$18,900	2036		**	4	\$5,600
<i>Cracks, Extent : Severe, Area Affected : 10%</i>								
<i>Location : On Both Approaches, Mostly At South Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : South Approach</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Both Approaches</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%	4+	\$2,200	LIFE		**		
<i>Corrosion, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Chain Link Fence And 4- Rail Railing</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Near Abutment Joints</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$87,100
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$56,400
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055		**		
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
49TH STREET GCP - GRAND CENTRAL PARKWAY
Asset # : 15033

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$3,000	LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : Along Steel Face</i>								
<i>Explanation : Edge Spalls</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$7,600
<i>Corrosion, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Chain Link Fence And 4 Rail Railing</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Corner And Random Locations</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Fence Posts And Random Locations</i>								
<i>Explanation : Rust Stains On Chain Link Fence Attached To Steel Railing</i>								
Sidewalks								
Concrete	100%			2040		**	5	\$4,400
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044		**	5	\$22,500
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE		**	2-8	\$195,200
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Only On Interior Girders</i>								
<i>Explanation : Concrete Encased Web With Exposed Reinforcement</i>								
Secondary Member								
Steel	100%			LIFE		**	2-8	\$10,100

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 4TH AVE. BRIDGE
Address : FOURTH AVE. OVER LIRR BAY RIDGE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0168.000 / 13576 **Yr Built/Renovated** : 1919 /
Area Sq Ft : 19,400 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 04-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243330

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$553,900
Total		\$553,900
Importance Code A		\$192,000
Importance Code C		\$361,900
Total		\$553,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$48,100		\$25,300	
Total	\$48,100		\$25,300	
Importance Code A	\$16,900		\$19,600	
Importance Code C	\$31,200		\$5,700	
Total	\$48,100		\$25,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
4TH AVE. BRIDGE
Asset # : 13576

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Paved Over With Asphalt</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 60%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Railway Tracks Underneath Bridge Structure</i>						
Approaches								
Pavement Asphalt	100%	4+	\$2,600	2034	\$129,900	4	\$1,900	
		<i>Cracks, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
4TH AVE. BRIDGE
Asset # : 13576

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	4+	\$6,500	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast Corner</i>								
<i>Settlement, Extent : Light, Area Affected : 5%</i>								
<i>Location : At Northwest Corner</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$2,900	2042		**	4	\$1,500
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%	4+	\$5,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : East Approach</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Approaches</i>								
<i>Explanation : Total Of 2 Scuppers</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Pier,Columns								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
4TH AVE. BRIDGE
Asset # : 13576

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads Steel	100%			LIFE	**	2-8	\$3,000	
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE	**			
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$4,900	LIFE	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Middle Of The West Side Curb</i>								
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets Concrete	100%			2042	**	4	\$7,900	
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$7,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks Concrete	10%	Now	\$7,300	2038	**	5	\$5,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northeast Corner</i>								
Concrete	90%			2038	**	5	\$11,300	
Wearing Surface Asphalt	100%	4+	\$11,600	2034	\$232,100	5	\$6,900	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
4TH AVE. BRIDGE
Asset # : 13576

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	10%	2-4	\$4,000	LIFE				**
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : All Joints At Curb Except Southeast Corner</i>					
			<i>Explanation : Missing Steel Cover Plate</i>					
Generic	90%			LIFE				**
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Expansion Joint Observed Along Sidewalks And Transverse Joints Paved Over With Asphalt On Roadway</i>					
Primary Member								
Steel	100%			LIFE				**
			<i>Other Observation, Extent : Light, Area Affected : 90%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Light Paint Peeling On Exterior Girder Bottom Flanges On 5 Percent Of Area. Limited Access On Interior Girders.</i>					
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 4TH AVENUE OVER BELT PARKWAY
Address : 4TH AVE AND BELT PARKWAY FORT HAMILTON
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0354.000 / 15368 **Yr Built/Renovated** :
Area Sq Ft : 5,796 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 07-Jul-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231270

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$167,400
Total		\$167,400
Importance Code C		\$167,400
Total		\$167,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$31,900			
Total	\$31,900			
Importance Code A	\$7,200			
Importance Code C	\$24,700			
Total	\$31,900			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
4TH AVENUE OVER BELT PARKWAY
Asset # : 15368

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Stem (breastwall)								
Concrete	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE	**			
		<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Southwest Wall</i>						
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pier Protection								
Concrete	100%			LIFE	**			
Approaches								
Pavement								
Asphalt	100%	4+	\$8,400	2033	\$167,400	4	\$5,200	
		<i>Cracks, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Both Approaches</i>						
Concrete	100%	4+	\$11,200	2041	**	4		
		<i>Cracks, Extent : Light, Area Affected : 15%</i>						
		<i>Location : Random Locations Throughout On West Approach</i>						
		<i>Old Repair, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Asphalt Patch On Southwest Approach</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : On West Approach</i>						
		<i>Explanation : Approach Consists Of 75 Percent Of Asphalt And 25 Percent Of Concrete</i>						
Curbs								
Concrete	100%	4+	\$3,300	LIFE	**			
		<i>Cracks, Extent : Moderate, Area Affected : 2%</i>						
		<i>Location : Southwest Approach</i>						
Concrete w/ Steel Face	100%			LIFE	**			
		<i>Rust Stains, Extent : Light, Area Affected : 15%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 75%</i>						
		<i>Location : On Both Approaches</i>						
		<i>Explanation : Curbs Consist Of 75 Percent Concrete With Steel Face And 25 Percent Concrete</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
4TH AVENUE OVER BELT PARKWAY
Asset # : 15368

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Masonry	100%	4+	\$2,100	2041		**		
		<i>Other Observation, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout With Moderate Cases On Southwest Corner.</i>						
		<i>Explanation : Joint Mortar Missing/ Eroded</i>						
Steel	100%	2-4	\$1,000	LIFE		**		
		<i>Corrosion, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Loss of Section, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Southwest Corner</i>						
Sidewalks								
Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Scupper								
Cast Iron	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 2 Scuppers Observed</i>						
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
		<i>Rust Stains, Extent : Light, Area Affected : 30%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
4TH AVENUE OVER BELT PARKWAY
Asset # : 15368

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Median								
Concrete	100%			LIFE	**	5	\$1,000	
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Masonry	100%			2041	**	5	\$1,800	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
Steel	100%			LIFE	**	2-8		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides</i>								
<i>Explanation : Chain Link Fence On Top Of Stone Masonry Parapet</i>								
Sidewalks								
Concrete	100%	4+	\$2,600	2037	**	5		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%	4+	\$2,500	2033	\$49,500	5		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Concrete	100%			LIFE	**	5	\$43,100	
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Mesh Covering</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 65TH PLACE 278I BROOKLYN-QUEENS EXPRESSWAY
Address : 65TH PLACE BET. LAUREL HILL BLVD WEST & LAUREL HILL BLVD EAST
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0316.000 / 15175 **Yr Built/Renovated** : 1957 /
Area Sq Ft : 11,256 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230520

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$125,300
Total		\$125,300
Importance Code A		\$125,300
Total		\$125,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$8,100	\$4,100	\$12,800	\$13,100
Total	\$8,100	\$4,100	\$12,800	\$13,100
Importance Code A			\$12,800	\$2,800
Importance Code B	\$2,200			
Importance Code C	\$5,900	\$4,100		\$10,300
Total	\$8,100	\$4,100	\$12,800	\$13,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
65TH PLACE 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15175

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Access Required On Brooklyn Queens Expressway Below</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	8%	Now	\$2,200	LIFE			**	
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : North Side</i>								
<i>Settlement, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : North Side</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : North Side</i>								
Generic	92%			LIFE			**	
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Mat Consists Of 20 Percent Generic, 80 Percent Not Accessible</i>								
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem Consists Of 20 Percent Concrete, 80 Percent Not Accessible</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
<i>Vegetation Growth, Extent : Light, Area Affected : 20%</i>								
<i>Location : Southeast Wingwall</i>								
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
65TH PLACE 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15175

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pier Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Cracks. Pier Protection Consists Of 40 Percent Concrete, 60 Percent Not Accessible</i>								
Approaches								
Pavement								
Concrete	100%			2041		**	4	\$20,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 70%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041		**	4	\$1,500
Steel	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Both Approaches</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem, Solid Pier Consists Of 40 Percent Concrete, 60 Percent Not Accessible</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
65TH PLACE 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15175

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 80%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Concrete	100%			2041		**	4	\$4,100
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE		**	2-8	\$5,700
			<i>Corrosion, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Both Sides</i>					
			<i>Explanation : Steel Railing On Top Of Concrete Parapet</i>					
Sidewalks								
Concrete	100%			2037		**	5	\$8,300
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	100%	4+	\$5,900	2041		**	5	\$19,600
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE		**	2-8	\$234,100
			<i>Corrosion, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 95%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Primary Member Consists Of 5 Percent Steel, 95 Percent Not Accessible</i>					
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 65TH PLACE LIRR MAIN LINE
Address : 65TH PL. BET. WOODSIDE AVE. AND QUEENS BLVD.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0270.000 / 15024 **Yr Built/Renovated** :
Area Sq Ft : 8,107 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 28-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247160

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$13,000		\$6,900	
Total	\$13,000		\$6,900	
Importance Code A	\$3,200		\$2,400	
Importance Code C	\$9,800		\$4,500	
Total	\$13,000		\$6,900	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
65TH PLACE LIRR MAIN LINE
Asset # : 15024

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : No Access To Railroad Property Underneath</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
		<i>Other Observation, Extent : Light, Area Affected : 70%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Debris</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Walls Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Bank Protection Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								
Pavement Concrete	100%			2044		**	4	\$9,000
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
65TH PLACE LIRR MAIN LINE
Asset # : 15024

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
		<i>Rust Stains, Extent : Moderate, Area Affected : 25%</i>						
		<i>Location : Random Locations Throughout</i>						
<hr/>								
Embankment								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Concrete	100%			2044	**	4	\$800	
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Northwest Approach</i>						
Steel	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : On Top Of Concrete Parapet</i>						
		<i>Explanation : Chain Link Fence</i>						
<hr/>								
Sidewalks								
Concrete	100%			LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Settlement, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Northwest Corner</i>						
<hr/>								
Piers								
Cap Beam								
Not Accessible	100%							
<hr/>								
Pier,Columns								
Not Accessible	100%							
<hr/>								
Stem,Solid Pier								
Not Accessible	100%							
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pedestals								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
		<i>Rust Stains, Extent : Light, Area Affected : 20%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
65TH PLACE LIRR MAIN LINE
Asset # : 15024

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets Concrete	100%			2044	**	4	\$3,700	
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Peeling Paint</i>								
Steel	100%			LIFE	**	2-8	\$8,200	
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Post Base And Random Locations</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : On Top Of Concrete Parapet</i>								
<i>Explanation : Chain Link Fence</i>								
Sidewalks								
Concrete	100%			2040	**	5	\$5,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$9,800	2044	**	5	\$15,200	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout With Moderate Cases Near Deck Joints</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Near South Deck Joint</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 69TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY
Address : 69TH STREET BET. 41ST AVE. AND WOODSIDE AVE.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0318.000 / 15177 **Yr Built/Renovated** : 1957 /
Area Sq Ft : 12,106 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230550

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$277,600
Total		\$277,600
Importance Code C		\$277,600
Total		\$277,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$4,000	\$2,300	\$100	\$5,500
Total	\$4,000	\$2,300	\$100	\$5,500
Importance Code A			\$100	\$1,200
Importance Code C	\$4,000	\$2,300		\$4,300
Total	\$4,000	\$2,300	\$100	\$5,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
69TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15177

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Access Required On Brooklyn Queens Expressway Below</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Joint Paved Over At Both Abutments</i>						
Mat (scour & erosion) Generic	100%			LIFE			* *	
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			* *	
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE			* *	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Walls Consist Of 50 Percent Concrete, 50 Percent Not Accessible</i>						
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			* *	
Pier Protection Not Accessible	100%							
Approaches								
Pavement Asphalt	100%			2033	\$277,600	4	\$8,600	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Both Approaches</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
69TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15177

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Fencing</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Both Approaches</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier, Columns								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2041	**	4	\$2,400	
Steel	100%			LIFE	**	2-8	\$3,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Chain Link Fence And Steel Railing On Top Of Concrete Parapet</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
69TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15177

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%			2037	**	5	\$4,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Earth	100%			LIFE	**	5	\$3,600	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Gardens On Bridge Adjacent To Sidewalk</i>								
Wearing Surface								
Asphalt	100%	4+	\$4,000	2033	\$40,100	5	\$2,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 69TH STREET 495I - LONG ISLAND EXPRESSWAY
 Address : 69TH STREET BETWEEN BORDEN AVE AND QUEENS MIDTOWN EXPRESSWAY
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0278.000 / 15032 Yr Built/Renovated :
 Area Sq Ft : 10,268 Project Type : HIGHWAY BRIDGES
 Date of Survey : 31-Oct-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2065950

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$5,000		\$2,600	\$22,000
Total	\$5,000		\$2,600	\$22,000
Importance Code A	\$4,000		\$600	
Importance Code C	\$1,000		\$2,000	\$22,000
Total	\$5,000		\$2,600	\$22,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
69TH STREET 495I - LONG ISLAND EXPRESSWAY

Asset # : 15032

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pier Protection								
Concrete	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Concrete Barrier</i>					
Approaches								
Pavement								
Asphalt	100%			2036		**	4	\$4,100
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location : South Approach</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
69TH STREET 495I - LONG ISLAND EXPRESSWAY
Asset # : 15032

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$700	
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%	4+	\$1,000	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : South Approach</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Southwest Sidewalk</i>								
<i>Explanation : Large Asphalt Patch</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Southeast Corner</i>								
<i>Explanation : 1 Scupper</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Granite	100%			LIFE	**			
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$10,400	
Sidewalks								
Concrete	100%			2040	**	5	\$4,900	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044	**	5	\$44,100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
69TH STREET 495I - LONG ISLAND EXPRESSWAY
Asset # : 15032

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 6TH AVENUE LIRR ATLANTIC AVENUE
Address : 6TH AVE OVER LIRR ATLANTIC AVE BET. ATLANTIC AVE & PACIFIC ST.
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0243.000 / 14983 **Yr Built/Renovated** :
Area Sq Ft : 9,982 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 10-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243280

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$366,000	\$536,200
Total	\$366,000	\$536,200
Importance Code A	\$366,000	\$319,700
Importance Code B		\$42,800
Importance Code C		\$173,700
Total	\$366,000	\$536,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$80,300		\$37,300	\$4,000
Total	\$80,300		\$37,300	\$4,000
Importance Code A			\$32,400	
Importance Code B	\$68,100		\$4,900	
Importance Code C	\$12,300			\$4,000
Total	\$80,300		\$37,300	\$4,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
6TH AVENUE LIRR ATLANTIC AVENUE
Asset # : 14983

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,600	LIFE			**	
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 25%</i>					
			<i>Location : Throughout</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 90%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Under Construction	100%							
			<i>Other Observation, Extent : N/A, Area Affected : 0%</i>					
			<i>Location : On East Side</i>					
			<i>Explanation : Reinforced Concrete Wingwall Under Construction With Limited Access On 90 Percent Area</i>					
Feature Crossed								
Mat (scour & erosion)								
Earth	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Under End Span At North Side</i>					
			<i>Explanation : Limited Access On 90 Percent Area. Railroad Tracks.</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
6TH AVENUE LIRR ATLANTIC AVENUE
Asset # : 14983

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	5%	Now	\$15,500	LIFE			**	
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : South Of Railroad Tracks</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Concrete	95%			LIFE			**	
Approaches								
Pavement								
Asphalt	100%	4+	\$8,700	2035	\$173,700	4	\$2,500	
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout With Severe Cases On South Approach</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : South Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Both Approaches</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Temporary Fence For Construction</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 75%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 75 Percent Not Accessible</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout On East Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On East Side Only</i>								
<i>Explanation : Chain Link Fence Attached To Steel Railings</i>								
Sidewalks								
Concrete	100%	Now	\$3,600	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Severe Case On Southeast Corner</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : Southeast Corner</i>								

Piers

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
6TH AVENUE LIRR ATLANTIC AVENUE
Asset # : 14983

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam Steel	100%	4+	\$172,800	LIFE	**	2-8	\$510,800	
<i>Corrosion, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Pier,Columns Steel	100%	4+	\$33,700	LIFE	**	2-8	\$123,200	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 80%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								
Railings/Parapets Steel	100%			LIFE	**	2-8	\$8,500	
<i>Rust Stains, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations On East Side Only</i> <i>Other Observation, Extent : N/A, Area Affected : 20%</i> <i>Location : On East Side</i> <i>Explanation : Opening In The Railing In The Middle To Adjacent Ramp Structure. Chain Link Fence And Four Rail Railing.</i>								
Sidewalks Concrete	100%			2039	**	5	\$8,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
6TH AVENUE LIRR ATLANTIC AVENUE
Asset # : 14983

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$11,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Top Of Deck Is Revealed Due To Removal Of Wearing Surface. Underside Of Deck Is Not Accessible</i>								
Joints								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On West Side</i>								
<i>Explanation : Covered With Steel Cover Plate. Longitudinal Joint Along The Structure With Adjacent Building</i>								
Primary Member								
Steel	100%	4+	\$193,300	LIFE	**	2-8	\$184,500	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Secondary Member								
Steel	100%	4+	\$16,400	LIFE	**	2-8	\$9,300	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 70TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY
Address : 70TH ST BET 41ST AVE AND WOODSIDE AVE, WOODSIDE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0324.000 / 15183 **Yr Built/Renovated** : 1957 /
Area Sq Ft : 8,270 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230560

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$14,600	\$3,200	\$200	\$5,900
Total	\$14,600	\$3,200	\$200	\$5,900
Importance Code A			\$200	\$2,800
Importance Code B	\$700			
Importance Code C	\$13,900	\$3,200		\$3,100
Total	\$14,600	\$3,200	\$200	\$5,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
70TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15183

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Access Required On Brooklyn Queens Expressway Below</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$700	LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Debris Build Up</i>								
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
Pier Protection Not Accessible	100%							
Approaches								
Pavement Concrete	100%			2041		**	4	\$6,200
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
70TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15183

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041	**	4	\$700	
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Steel Fencing And Steel Railing On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Both Approaches</i>								
Piers								
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 60%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2041	**	4	\$5,000	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$6,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Steel Railing On Top Concrete Parapet</i>								
Sidewalks								
Concrete	100%			2037	**	5	\$6,400	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2041	**	5	\$27,900	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
70TH STREET 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15183

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 7TH AVENUE LIRR & SEA BEACH
Address : 7TH AVENUE BET. 62ND & 63RD STS
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0294.000 / 15052 **Yr Built/Renovated** :
Area Sq Ft : 18,882 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243600

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$74,000		\$4,100	
Total	\$74,000		\$4,100	
Importance Code A			\$4,100	
Importance Code B	\$6,400			
Importance Code C	\$67,600			
Total	\$74,000		\$4,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
7TH AVENUE LIRR & SEA BEACH
Asset # : 15052

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Railroad Property Underneath</i>								
<hr/>								
Backwall Not Accessible	100%							
<hr/>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
<hr/>								
Footings Not Accessible	100%							
<hr/>								
Joint with Deck Generic	100%	0-2	\$6,400	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i>								
<i>Location : Chipped Armor At Northbound Lane Of South Abutment</i>								
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : South Abutment</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Severe Cases At North Abutment</i>								
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Pedestals Not Accessible	100%							
<hr/>								
Stem (breastwall) Not Accessible	100%							
<hr/>								
Wingwalls								
Footings Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Piles Not Accessible	100%							
<hr/>								
Walls Not Accessible	100%							
<hr/>								
Feature Crossed								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Pier Protection Not Accessible	100%							
<hr/>								
Approaches								
Pavement Concrete	100%	0-2	\$42,900	2044		**	4	\$29,200
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations With Worse Cases At North Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Corners Of Both Approaches And Centerline Near North Abutment</i>								
<i>Deck Joint</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
7TH AVENUE LIRR & SEA BEACH
Asset # : 15052

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northwest Approach</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044		**	4	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On Southwest And Northeast Approaches</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 67%</i>								
<i>Location : Southeast And Northwest Approaches</i>								
<i>Explanation : Chain Link Fence</i>								
Sidewalks								
Concrete	100%	2-4	\$2,600	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Southeast And Northwest Approaches And Random Locations</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast Approach And Random Locations</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
7TH AVENUE LIRR & SEA BEACH
Asset # : 15052

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Concrete	100%			2044		**	4	\$8,100
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			2040		**	5	\$14,400
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$22,100	2044		**	5	\$34,100
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout With Worse Cases On Southbound Lanes Near North Abutment</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Over Pier At East End</i>								
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 80TH ROAD LIRR MAIN LINE
Address : 80TH ROAD BET GRENFELL STREET AND AUSTIN STREET, KEW GARDENS
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0326.000 / 15185 **Yr Built/Renovated** : 1909 /
Area Sq Ft : 3,872 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 02-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247220

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$7,700	\$1,200	\$100	\$9,800
Total	\$7,700	\$1,200	\$100	\$9,800
Importance Code A			\$100	\$1,400
Importance Code C	\$7,700	\$1,200		\$8,500
Total	\$7,700	\$1,200	\$100	\$9,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
80TH ROAD LIRR MAIN LINE
Asset # : 15185

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Underside Of Deck Throughout</i>						
		<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Joint Paved Over At Both Abutments</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								
Pavement Concrete	100%			2041	**	4	\$17,000	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Curbs Concrete	100%			LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Embankment Earth	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
80TH ROAD LIRR MAIN LINE
Asset # : 15185

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
Sidewalks								
Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Both Approaches</i>						
Piers								
Cap Beam								
Not Accessible	100%							
Pier, Columns								
Not Accessible	100%							
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
		<i>Rust Stains, Extent : Light, Area Affected : 20%</i>						
		<i>Location : Random Locations Throughout</i>						
Railings/Parapets								
Concrete	100%			2041	**	4	\$2,700	
Steel	100%			LIFE	**	2-8	\$3,700	
		<i>Other Observation, Extent : Light, Area Affected : 50%</i>						
		<i>Location : West Side</i>						
		<i>Explanation : Vegetation Growth</i>						
Sidewalks								
Concrete	100%			2037	**	5	\$2,300	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Wearing Surface								
Concrete	100%			2041	**	5	\$15,400	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Superstructure								
Deck, Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
80TH ROAD LIRR MAIN LINE
Asset # : 15185**

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 80TH STREET 77TH AVE - LIRR MT
Address : 80TH ST & 77TH AVE., GLENDALE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0379.000 / 15399 **Yr Built/Renovated** :
Area Sq Ft : 11,542 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 29-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247570

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$91,000		\$2,400	
Total	\$91,000		\$2,400	
Importance Code A	\$16,200		\$300	
Importance Code B	\$31,000			
Importance Code C	\$43,800		\$2,000	
Total	\$91,000		\$2,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
80TH STREET 77TH AVE - LIRR MT
Asset # : 15399

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	Now	\$4,800	LIFE		**		
<i>Cracks, Extent : Severe, Area Affected : 15%</i>								
<i>Location : South Abutment</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : South Abutment</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$2,900	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Both Abutments</i>								
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations On Both Abutments</i>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	10%	4+	\$28,000	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations On Both Abutments</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On South Abutment</i>								
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations On South Abutment</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Both Abutments</i>								
Concrete	90%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
80TH STREET 77TH AVE - LIRR MT
Asset # : 15399

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	20%	4+	\$13,600	LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northwest Wingwall</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Wingwall</i>								
Concrete	80%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pier Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers Adjacent To Track</i>								
<i>Explanation : Concrete Wall</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$11,200	2042		**	4	\$16,400
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On Both Approaches</i>								
<i>Spalling, Extent : Moderate, Area Affected : 3%</i>								
<i>Location : Random Locations On Both Approaches</i>								
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : South Approach</i>								
<i>Explanation : Concrete Patch</i>								
Curbs								
Concrete w/ Steel Face	100%	0-2	\$8,400	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northeast Approach</i>								
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Approach</i>								
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northwest Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
80TH STREET 77TH AVE - LIRR MT
Asset # : 15399

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Steel	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Chain Link Fence Attached To Steel Railing</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Transverse Cracks On East Sidewalk</i>								
Piers								
Cap Beam Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>								
Pier,Columns Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%	4+	\$3,000	LIFE	**			
<i>Delaminations, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 50%</i> <i>Location : Throughout</i>								
Railings/Parapets Steel	100%			LIFE	**	2-8	\$9,700	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Chain Link Fence Attached To Steel Railing</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
80TH STREET 77TH AVE - LIRR MT
Asset # : 15399

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2038	**	5	\$4,000	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	0-2	\$8,000	2042	**	5	\$26,600	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Asphalt Patches</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%	4+	\$10,900	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near North Abutment</i>								
<i>Explanation : Light Efflorescence And Rust Stains On 1 Percent Of Area. Evidence Of Leakage Between Beams.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 82ND AVENUE LIRR MAIN LINE
Address : 82ND AVE OVER LIRR BET GRENFELL AND AUSTIN ST, KEW GARDENS
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0327.000 / 15186 **Yr Built/Renovated** : 1909 /
Area Sq Ft : 3,872 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 02-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247230

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$6,900	\$1,100	\$100	\$5,200
Total	\$6,900	\$1,100	\$100	\$5,200
Importance Code A	\$4,500		\$100	\$1,400
Importance Code B				
Importance Code C	\$2,300	\$1,100		\$3,900
Total	\$6,900	\$1,100	\$100	\$5,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
82ND AVENUE LIRR MAIN LINE
Asset # : 15186

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE	**			
Backwall								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE	**			
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pier Protection								
Concrete	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Concrete Barrier</i>					
Approaches								
Pavement								
Concrete	100%			2041	**	4	\$7,700	
Curbs								
Concrete w/ Steel Face	100%	0-2	\$4,500	LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Settlement, Extent : Moderate, Area Affected : 25%</i>					
			<i>Location : Northeast Side</i>					
Embankment								
Earth	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
82ND AVENUE LIRR MAIN LINE
Asset # : 15186

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Concrete Encased Steel	100%			LIFE	**	5	\$10,700	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Pier,Columns								
Concrete Encased Steel	100%			LIFE	**	5	\$600	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
		<i>Rust Stains, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
Railings/Parapets								
Concrete	100%			2041	**	4	\$2,700	
Steel	100%			LIFE	**	2-8	\$3,700	
Sidewalks								
Concrete	100%			2037	**	5	\$2,100	
Wearing Surface								
Concrete	100%	4+	\$2,300	2041	**	5	\$7,700	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Settlement, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Moderate, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
82ND AVENUE LIRR MAIN LINE
Asset # : 15186

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Not Accessible		100%						
Primary Member								
Concrete Encased Steel		100%		LIFE	**	5	\$27,700	
<i>Efflorescence, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Secondary Member								
Not Accessible		100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 86TH ST. BRIDGE
Address : 86TH ST.
Borough : BROOKLYN
Program / Asset # : DOT0171.000 / 13579
Area Sq Ft : 18,200
Date of Survey : 22-Mar-2022
Areas Surveyed :
Block : **Lot** : **BIN** : 2243570
Agency's Number : N/A
Yr Built/Renovated : 1995 /
Project Type : HIGHWAY BRIDGES
Landmark Status : NONE

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$75,200	\$360,300
Total	\$75,200	\$360,300
Importance Code A		\$180,100
Importance Code B		\$180,100
Importance Code C	\$75,200	
Total	\$75,200	\$360,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$125,700		\$42,800	
Total	\$125,700		\$42,800	
Importance Code A	\$59,900		\$18,100	
Importance Code B	\$3,200		\$18,100	
Importance Code C	\$62,600		\$6,700	
Total	\$125,700		\$42,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
86TH ST. BRIDGE
Asset # : 13579

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	10%	4+	\$12,100	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	90%			LIFE		**		
Brngs,Ancr Blts,Pads								
Elastomeric	100%	2-4	\$49,300	2053		**		
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : East Abutment</i>					
			<i>Explanation : Fixed Elastomeric Bearings On West Abutment. Unusual Expansion From Skew</i>					
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$3,200	LIFE		**		
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : At Concrete Headers</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Not Accessible	100%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : Both Abutments</i>					
			<i>Explanation : Behind Station Platform Wall</i>					
Walls								
Concrete	100%			LIFE		**		
			<i>Cracking/Crumbling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
86TH ST. BRIDGE
Asset # : 13579

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	100%	4+	\$34,500	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast And Southwest Wingwalls</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast And Southwest Wingwalls</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railroad Tracks Underneath Bridge</i>								
Approaches								
Pavement								
Concrete	100%	0-2	\$75,200	2042		4	\$44,200	**
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>								
<i>Location : East Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : East Approach</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$8,600	LIFE			**	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Corner</i>								
<i>Rust Stains, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Southeast Corner Only</i>								
<i>Explanation : Steel Railing And Chain Link Fence</i>								
Sidewalks								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : One Scupper</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
86TH ST. BRIDGE
Asset # : 13579

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2042	**	4	\$5,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Parapet At South Side Only</i>								
Steel	100%			LIFE	**	2-8		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout South Side</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
<hr/>								
Sidewalks								
Concrete	100%			2038	**	5	\$13,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$16,000	2042	**	5	\$21,300	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Northeast Abutment</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$7,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Deck</i>								
<i>Explanation : Limited Access. Underside Covered With Stay-in-place Forms Except Middle Bay.</i>								
<hr/>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$336,500	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$281,900	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 8TH AVENUE LIRR & SEA BEACH
Address : 8TH AVENUE OVER LIRR & SEA BEACH RAIL LINE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0333.000 / 15192 **Yr Built/Renovated** : 1912 /
Area Sq Ft : 10,319 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243610

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$129,100	\$404,200
Total	\$129,100	\$404,200
Importance Code A	\$74,000	\$212,300
Importance Code C	\$55,100	\$191,900
Total	\$129,100	\$404,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$25,800	\$2,800	\$21,900	\$2,300
Total	\$25,800	\$2,800	\$21,900	\$2,300
Importance Code A	\$4,800		\$21,500	\$2,300
Importance Code B			\$400	
Importance Code C	\$21,000	\$2,800		
Total	\$25,800	\$2,800	\$21,900	\$2,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
8TH AVENUE LIRR & SEA BEACH
Asset # : 15192

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2052		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
Walls								
Concrete	100%	0-2	\$74,000	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : North Side</i>								
<i>Explanation : Misaligned/ Rotated Portion Of Wall</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%	4+	\$55,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Walls Consist Of 50 Percent Concrete, 50 Percent Not Accessible</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Asphalt	100%	Now	\$5,800	2033	\$115,700	4	\$3,600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Both Approaches</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
8TH AVENUE LIRR & SEA BEACH
Asset # : 15192

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	2-4	\$4,800	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southwest Approach</i>								
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041	**	4	\$300	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Approaches</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Railing</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Approaches</i>								
<i>Explanation : 2 Scuppers Observed</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$78,300	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Cap Beam Consists Of 50 Percent Steel, 50 Percent Not Accessible</i>								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$11,700	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier, Columns Consist Of 50 Percent Steel, 50 Percent Not Accessible</i>								
Stem,Solid Pier								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem, Solid Pier Consists Of 20 Percent Concrete, 80 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
8TH AVENUE LIRR & SEA BEACH
Asset # : 15192

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Brngs,Ancr Blts,Pads Elastomeric	100%			2052		**		
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Bearings Consist Of 20 Percent Elastomeric, 80 Percent Not Accessible</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Steel	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2041		**	4	\$4,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$5,900
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Railing</i>								
Sidewalks								
Concrete	100%			2037		**	5	\$5,600
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%	Now	\$15,200	2033	\$76,200		5	\$4,900
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : South Side</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Deck Bottom Covered With Stay In Place Forms</i>								
Primary Member								
Steel	100%			LIFE		**	2-8	\$333,300
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Primary Member Consists Of 10 Percent Steel, 90 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
8TH AVENUE LIRR & SEA BEACH
Asset # : 15192**

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Secondary Member								
Not Accessible		100%						

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 9TH AVENUE NYCTA BMT YARD
Address : 9TH AVE. OVER NYCTA BMT YARD
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0296.000 / 15054 **Yr Built/Renovated** :
Area Sq Ft : 12,080 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243840

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$15,500		\$9,200	\$19,400
Total	\$15,500		\$9,200	\$19,400
Importance Code A	\$9,200		\$3,000	
Importance Code B	\$3,300			
Importance Code C	\$3,000		\$6,200	\$19,400
Total	\$15,500		\$9,200	\$19,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
9TH AVENUE NYCTA BMT YARD
Asset # : 15054

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$3,300	LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations On Header Blocks</i>					
			<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 10%</i>					
			<i>Location : West Sidewalk At South Abutment</i>					
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Debris</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
9TH AVENUE NYCTA BMT YARD
Asset # : 15054

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$12,300	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On South Approach</i>								
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$900	LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Along Steel Faces At Southwest Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$900	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Northwest Approach</i>								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Northeast And Northwest Approaches</i>								
<i>Explanation : 2 Approach Scuppers</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
9TH AVENUE NYCTA BMT YARD
Asset # : 15054

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$4,300	LIFE		**		
<i>Delaminations, Extent : Light, Area Affected : 15%</i>								
<i>Location : Along Steel Face On West Side</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Concrete	100%			2044		**	4	\$4,700
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$10,400
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%	Now	\$3,000	2040		**	5	\$600
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Broken Sign Post With Protruding Metal Up To 3 Inches On West Sidewalk Causing Tripping Hazard</i>								
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : West Sidewalk And Random Locations</i>								
Wearing Surface								
Concrete	100%			2044		**	5	\$38,800
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
9TH AVENUE NYCTA BMT YARD
Asset # : 15054

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 9TH AVENUE NYCTA IND SUBWAY
Address : 9TH AVE. AND NEW UTRECHT AVENUE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0297.000 / 15055 **Yr Built/Renovated** :
Area Sq Ft : 6,240 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243940

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$570,300	\$323,700
Total	\$570,300	\$323,700
Importance Code A	\$337,200	\$174,000
Importance Code B	\$149,700	\$149,700
Importance Code C	\$83,500	
Total	\$570,300	\$323,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$258,400		\$38,000	
Total	\$258,400		\$38,000	
Importance Code A	\$98,700		\$18,500	
Importance Code B	\$136,700		\$15,400	
Importance Code C	\$23,000		\$4,200	
Total	\$258,400		\$38,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
9TH AVENUE NYCTA IND SUBWAY
Asset # : 15055

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Backwall								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$6,700	LIFE			**	
			<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 15%</i>					
			<i>Location : West Sidewalk At North Abutment, Less Severe At Other Random Locations</i>					
			<i>Spalling, Extent : Severe, Area Affected : 10%</i>					
			<i>Location : West Sidewalk At North Abutment</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Debris</i>					
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railroad Tracks</i>					
Stem (breastwall)								
Concrete Encased Steel	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Along Column Flanges</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Paint Peeling</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%	4+	\$83,500	LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Northwest Wingwall And Random Locations</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations On West Side</i>					
			<i>Explanation : Scaling</i>					
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
9TH AVENUE NYCTA IND SUBWAY
Asset # : 15055

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Platforms And Tracks</i>								
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$8,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%	2-4	\$600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Worse Cases On West Side</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Southwest And Northwest Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	Now	\$1,100	2044		**	4	\$600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>								
<i>Location : Back Face Of Northwest Approach Parapet</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout On Top Of Concrete Parapet</i>								
<i>Explanation : Chain Link Fence On West Side, Steel Fence On East Side</i>								
Sidewalks								
Concrete	100%	2-4	\$1,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations With Worse Cases On West Side</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Southwest And Northwest Approach</i>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
9TH AVENUE NYCTA IND SUBWAY
Asset # : 15055

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Cap Beam Steel	100%			LIFE	**	2-8	\$434,100	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								
Pier, Columns Steel	100%			LIFE	**	2-8	\$706,100	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Base Of Columns Near Platform And Random Locations</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Railway Platforms</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	0-2	\$5,500	LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 15%</i> <i>Location : Along Steel Face On West Side</i>								
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$4,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout On West Side</i> <i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%	4+	\$15,600	2040	**	5	\$3,000	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
9TH AVENUE NYCTA IND SUBWAY
Asset # : 15055

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Wearing Surface Concrete	100%	4+	\$6,400	2044	**	5	\$9,900	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$13,700	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Stay In Place Forms</i>								
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Throughout On East And West Ends</i>								
<i>Explanation : Stay In Place Forms</i>								
<hr/>								
Primary Member								
Concrete Encased Steel	100%	4+	\$163,200	LIFE	**	5	\$31,400	
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On Center Section</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On Center Section</i>								
<i>Explanation : Paint Peeling</i>								
Steel	100%			LIFE	**	2-8	\$197,700	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On East And West Ends</i>								
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$10,200	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ALBEE AVENUE SIRT SOUTH SHORE
Address : ALBEE AVENUE BETWEEN S. RAILROAD & N. RAILROAD STREETS
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0229.000 / 14968 **Yr Built/Renovated** : 1940 /
Area Sq Ft : 6,420 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 07-Mar-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249320

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$29,900		\$13,900	\$1,600
Total	\$29,900		\$13,900	\$1,600
Importance Code A	\$12,500		\$200	
Importance Code C	\$17,400		\$13,700	\$1,600
Total	\$29,900		\$13,900	\$1,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ALBEE AVENUE SIRT SOUTH SHORE
Asset # : 14968

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railroad Tracks</i>								
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%	4+	\$10,000	2043		**	4	\$6,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete	100%	4+	\$1,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ALBEE AVENUE SIRT SOUTH SHORE
Asset # : 14968

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%	4+	\$2,600	2054		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout With Moderate Cases On South Side</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout With Moderate Cases On South Side</i>					
Railings/Parapets								
Concrete	100%	4+	\$8,700	2043		**	4	\$3,300
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE		**	2-8	\$4,500
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ALBEE AVENUE SIRT SOUTH SHORE
Asset # : 14968

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	5%	4+	\$2,100	2039	**	5	\$1,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Moderate Cases On South Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout With Moderate Cases On South Side</i>								
Concrete	95%			2039	**	5	\$3,300	
Wearing Surface								
Concrete	12%	4+	\$5,400	2043	**	5	\$13,700	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	88%			2043	**	5	\$27,500	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On Concrete Header</i>								
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ARTHUR KILL ROAD SIRT SOUTH SHORE
Address : ARTHUR KILL RD. BET. ELLIS ST. AND ST. ANDREWS PLACE
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0266.000 / 15020 **Yr Built/Renovated** :
Area Sq Ft : 3,617 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249240

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$1,900		\$11,500	
Total	\$1,900		\$11,500	
Importance Code A	\$1,900		\$1,200	
Importance Code C			\$10,300	
Total	\$1,900		\$11,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTHUR KILL ROAD SIRT SOUTH SHORE
Asset # : 15020

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals Concrete	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 70%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Limited Access To Abutment Components</i>						
Backwall Not Accessible	100%						
Brngs,Ancr Blts,Pads Not Accessible	100%						
Footings Not Accessible	100%						
Joint with Deck Generic	100%			LIFE		**	
	<i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i>						
	<i>Location : South Side</i>						
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Throughout</i>						
Mat (scour & erosion) Generic	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Railway Ballasts</i>						
Pedestals Concrete	100%			LIFE		**	
Stem (breastwall) Concrete	100%			LIFE		**	
Wingwalls							
Footings Not Accessible	100%						
Mat (scour & erosion) Generic	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Railway Ballasts</i>						
Piles Not Accessible	100%						
Walls Concrete	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 40%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Limited Access</i>						
Feature Crossed							
Mat (scour & erosion) Generic	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Railroad Tracks</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTHUR KILL ROAD SIRT SOUTH SHORE
Asset # : 15020

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$20,600	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : South Approach And Random Locations</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Rust Stains, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4		
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i>								
Steel	100%			LIFE	**			
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout Except Northwest Approach</i> <i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	12%			LIFE	**			
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i>								
Concrete	88%			LIFE	**			
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Rust Stains, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ARTHUR KILL ROAD SIRT SOUTH SHORE
Asset # : 15020

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Concrete	100%			2044	**	4	\$2,200	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Steel	100%			LIFE	**	2-8	\$5,000	
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Top Of Concrete Parapet</i>								
<i>Explanation : Chain Link Fence</i>								
<hr/>								
Sidewalks Concrete	100%			2040	**	5	\$2,200	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<hr/>								
Wearing Surface Concrete	100%			2050	**	5	\$14,400	
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural Not Accessible	100%							
<hr/>								
Primary Member Steel	100%			LIFE	**	2-8		
<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Superstructure Components</i>								
<hr/>								
Secondary Member Concrete Encased Steel	100%			2063	**			
<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ASTORIA BLVD. EAST BOUND 278I B.Q.E. WEST LEG
Address : ASTORIA BLVD. SOUTH OVER B.Q.E WEST
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0233.000 / 14973 **Yr Built/Renovated** : 1941 /
Area Sq Ft : 8,181 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 17-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230810

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$156,600	\$302,000
Total	\$156,600	\$302,000
Importance Code A	\$156,600	\$54,700
Importance Code C		\$247,300
Total	\$156,600	\$302,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$111,700	\$4,300	\$6,300	
Total	\$111,700	\$4,300	\$6,300	
Importance Code A	\$47,200	\$1,300	\$5,900	
Importance Code B	\$2,700		\$500	
Importance Code C	\$61,800	\$2,900		
Total	\$111,700	\$4,300	\$6,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ASTORIA BLVD. EAST BOUND 278I B.Q.E. WEST LEG

Asset # : 14973

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	4%	4+	\$2,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : East Abutment</i>								
<i>Explanation : Electrical Box</i>								
Concrete	96%			LIFE		**		
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	4%	4+	\$5,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	96%			LIFE		**		
<i>Vegetation Growth, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Roadway</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ASTORIA BLVD. EAST BOUND 278I B.Q.E. WEST LEG

Asset # : 14973

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Steel	100%			LIFE		**		
Approaches								
Pavement								
Asphalt	10%	4+	\$1,900	2035	\$18,900	4	\$5,800	
	<i>Cracks, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Asphalt	90%			2035	\$170,500	4	\$8,800	
Curbs								
Concrete	100%	4+	\$2,500	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
Embankment								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	10%	4+	\$1,100	2043		**	4	\$2,700
	<i>Cracks, Extent : Moderate, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Moderate, Area Affected : 15%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 20 Percent Concrete</i>							
Concrete	90%			2043		**	4	\$4,000
Steel	100%	4+	\$2,400	LIFE		**		
	<i>Loss of Section, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 80 Percent Steel</i>							
Sidewalks								
Concrete	100%	4+	\$2,400	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 8%</i>							
	<i>Location : Random Locations Throughout</i>							

Piers

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ASTORIA BLVD. EAST BOUND 278I B.Q.E. WEST LEG

Asset # : 14973

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam Steel	100%	4+	\$19,900	LIFE	**	2-8	\$126,500	
<i>Loss of Section, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Pier,Columns Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads Steel	100%			LIFE	**	2-8	\$2,700	
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs Concrete	7%	4+	\$1,300	2054	**			
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	93%			2054	**			
Railings/Parapets Concrete	100%	4+	\$15,300	2043	**	4	\$5,000	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 20 Percent Concrete</i>								
Steel	100%	4+	\$4,600	LIFE	**	2-8	\$6,900	
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 80 Percent Steel</i>								
Sidewalks Concrete	100%	4+	\$23,400	2039	**	5	\$2,000	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ASTORIA BLVD. EAST BOUND 278I B.Q.E. WEST LEG

Asset # : 14973

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface Asphalt	100%	4+	\$28,900	2035	\$57,900	5	\$3,700	
<i>Cracks, Extent : Moderate, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Settlement, Extent : Light, Area Affected : 15%</i> <i>Location : Random Locations Throughout And Near Joints</i> <i>Spalling, Extent : Light, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural Concrete	100%	4+	\$156,600	LIFE	**	5	\$9,000	
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 4%</i> <i>Location : Random Locations Throughout</i>								
Joints								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location :</i> <i>Explanation : Paved Over</i>								
Primary Member								
Steel	100%			LIFE	**	2-8		
<i>Rust Stains, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$7,600	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : AVENUE H. BRIDGE AVENUE H./LIRR BAY RIDGE
Address : OVER LIRR - BAY RIDGE LINE ALBANY AVE. AND E39TH STREET
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0156.000 / 13519 **Yr Built/Renovated** : 1906 /
Area Sq Ft : 35,100 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243530

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$58,500	\$440,200
Total	\$58,500	\$440,200
Importance Code A		\$347,400
Importance Code C	\$58,500	\$92,800
Total	\$58,500	\$440,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$120,900		\$35,200	\$88,000
Total	\$120,900		\$35,200	\$88,000
Importance Code A	\$42,900		\$35,200	\$200
Importance Code B	\$3,000			
Importance Code C	\$75,000			\$87,800
Total	\$120,900		\$35,200	\$88,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
AVENUE H. BRIDGE AVENUE H./LIRR BAY RIDGE

Asset # : 13519

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$3,000	LIFE			**	
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Both Abutments</i>					
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Peeling Paint. Walls Consist Of 30 Percent Concrete, 70 Percent Not Accessible</i>					
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
Pier Protection Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 90%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Pier Protection Consists Of 10 Percent Concrete, 90 Percent Not Accessible</i>					
Approaches								
Pavement Concrete	100%			2041		**	4	\$175,600
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Both Approaches</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
AVENUE H. BRIDGE AVENUE H./LIRR BAY RIDGE

Asset # : 13519

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Curbs								
Concrete w/ Steel Face	100%	0-2	\$42,900	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 10%</i>								
<i>Location : On Both Approaches</i>								
<i>Rust Stains, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Northeast Approach</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041		**	4	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%	4+	\$22,500	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Cap Beam Consists Of 15 Percent Concrete, 85 Percent Not Accessible</i>								
Pier,Columns								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 85%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier Columns Consist Of 15 Percent Concrete, 85 Percent Not Accessible</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
AVENUE H. BRIDGE AVENUE H./LIRR BAY RIDGE

Asset # : 13519

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 85%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pedestals Consist Of 15 Percent Concrete, 85 Percent Not Accessible</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2041		**	4	\$400
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northeast Side</i>								
<hr/>								
Steel	100%			LIFE		**	2-8	\$9,100
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$6,100	2037		**	5	\$800
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Northwest Side</i>								
<i>Explanation : Sidewalks Consist Of 70 Percent Concrete, 30 Percent Not Accessible Due To Obstruction From Private Property</i>								
<hr/>								
Wearing Surface								
Concrete	33%	Now	\$58,500	2041		**	5	\$46,400
<i>Cracks, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Concrete	67%			2041		**	5	\$92,800
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Steel	100%			LIFE		**	2-8	\$648,900
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling. Primary Member Consists Of 5 Percent Steel, 95 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
 AVENUE H. BRIDGE AVENUE H./LIRR BAY RIDGE
 Asset # : 13519**

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Secondary Member								
Not Accessible		100%						

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BANCROFT AVENUE SIRT SOUTH SHORE
 Address : BANCROFT AVE BET N. RAILROAD AVE AND S. RAILROAD AVE
 Borough : STATEN ISLAND Agency's Number : N/A
 Program / Asset # : DOT0259.000 / 15013 Yr Built/Renovated :
 Area Sq Ft : 5,858 Project Type : HIGHWAY BRIDGES
 Date of Survey : 12-Dec-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2249440

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$72,000		\$7,600	
Total	\$72,000		\$7,600	
Importance Code A	\$5,500		\$200	
Importance Code B	\$32,600			
Importance Code C	\$33,900		\$7,500	
Total	\$72,000		\$7,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BANCROFT AVENUE SIRT SOUTH SHORE
Asset # : 15013

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	2-4	\$4,900	LIFE			**	
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railway Tracks</i>					
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$14,900
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BANCROFT AVENUE SIRT SOUTH SHORE
Asset # : 15013

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE			**	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Vertical Bars At Northwest Corner And Random Locations</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind Steel Railing</i>								
Sidewalks								
Concrete	100%	0-2	\$2,400	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Southwest Approach</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 75%</i>								
<i>Location : Northwest, Northeast And Southeast Corners</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Pier Components</i>								
Pier,Columns								
Concrete	100%	4+	\$27,700	LIFE			**	
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Stem,Solid Pier								
Concrete	100%			LIFE			**	
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BANCROFT AVENUE SIRT SOUTH SHORE
Asset # : 15013

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Ballast</i>								
<hr/>								
Pedestals								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$2,800	LIFE		**		
<i>Delaminations, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Steel Face</i>								
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Along Steel Face</i>								
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$7,000
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Vertical Bars At Northwest Corner, Post Base And Random Locations</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind Steel Railing</i>								
<hr/>								
Sidewalks								
Concrete	100%	Now	\$10,200	2040		**	5	\$2,000
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Severe Cases On South Sidewalk</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
<hr/>								
Wearing Surface								
Concrete	100%	Now	\$16,900	2044		**	5	\$10,400
<i>Cracks, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Eastbound Lane At Pier And Random Locations</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Eastbound Lane At Pier</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BANCROFT AVENUE SIRT SOUTH SHORE
Asset # : 15013

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Generic	100%	4+	\$4,400	LIFE				* *
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Debris</i>					
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BATTERY PARK TUNNEL BATTERY PLACE/FDR DRIVE
Address : BATTERY PLACE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0082.000 / 2511 **Yr Built/Renovated** : 1954 /
Area Sq Ft : 69,993 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2232000

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$606,000	\$874,400
Total	\$606,000	\$874,400
Importance Code A	\$410,300	\$410,300
Importance Code C	\$195,700	\$464,100
Total	\$606,000	\$874,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$104,900		\$39,000	
Total	\$104,900		\$39,000	
Importance Code A	\$64,500		\$5,500	
Importance Code C	\$40,400		\$33,600	
Total	\$104,900		\$39,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BATTERY PARK TUNNEL BATTERY PLACE/FDR DRIVE

Asset # : 2511

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 95%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE	**			
		<i>Efflorescence, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations On Both Portal Wingwalls</i>						
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	100%			2036	**	4	\$67,100	
		<i>Cracks, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations With Worse Cases On Woodhull Street, Brooklyn</i>						
Curbs								
Concrete	100%	2-4	\$11,700	LIFE	**			
		<i>Cracks, Extent : Moderate, Area Affected : 25%</i>						
		<i>Location : Random Locations At Woodhull Street, Brooklyn</i>						
Concrete w/ Steel Face	100%	2-4	\$6,900	LIFE	**			
		<i>Spalling, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Along Steel Face At Woodhull Street, Brooklyn</i>						
Granite	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Granite Curbs At Battery Place, Manhattan</i>						
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	2-4	\$8,400	LIFE	**			
		<i>Cracks, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Random Locations On Northeast And Northwest Approach At Woodhull Street, Brooklyn</i>						
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BATTERY PARK TUNNEL BATTERY PLACE/FDR DRIVE
Asset # : 2511

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Footings								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%			2055		**		
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On South Side At Woodhull Street</i>								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 60%</i>								
<i>Location : Random Locations On Woodhull Street, Brooklyn</i>								
Granite	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout Battery Place, Manhattan</i>								
<i>Explanation : Granite Curbs</i>								
Median								
Granite	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Battery Place, Manhattan</i>								
<i>Explanation : Vegetative Island With Granite Curbs</i>								
Railings/Parapets								
Masonry	100%			2044		**	5	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Woodhull Street, Brooklyn</i>								
<i>Explanation : Joint Mortar Missing, Eroded</i>								
Steel	100%			LIFE		**	2-8	\$249,100
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Fencing</i>								
Sidewalks								
Concrete	12%	Now	\$32,000	2040		**	5	\$54,000
<i>Cracks, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Random Locations On Woodhull Street, Brooklyn</i>								
<i>Spalling, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Random Locations On Woodhull Street, Brooklyn</i>								
Concrete	88%			2040		**	5	\$108,000
Granite Paver	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : North Fascia</i>								
<i>Explanation : Pavers At Battery Place, Manhattan</i>								
Wearing Surface								
Asphalt	100%	4+	\$195,700	2036		**	5	\$302,100
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations On Woodhull Street, Brooklyn</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BATTERY PARK TUNNEL BATTERY PLACE/FDR DRIVE

Asset # : 2511

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Superstructure	Primary Member							
	Concrete	100%			LIFE	**	5	\$720,100
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BAY 8TH STREET BELT PARKWAY
Address : BAY 8TH STREET OVER BELT PARKWAY
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0225.000 / 14960 **Yr Built/Renovated** :
Area Sq Ft : 4,827 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231290

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$243,200
Total		\$243,200
Importance Code A		\$243,200
Total		\$243,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$44,400	\$9,900	\$27,100	
Total	\$44,400	\$9,900	\$27,100	
Importance Code A	\$7,100		\$24,700	
Importance Code B			\$1,500	
Importance Code C	\$37,300	\$9,900	\$900	
Total	\$44,400	\$9,900	\$27,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BAY 8TH STREET BELT PARKWAY
Asset # : 14960

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE	**			
Backwall Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads Multi-Rotational Bearing	100%			2061	**			
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE	**			
Mat (scour & erosion) Generic	100%			LIFE	**			
Pedestals Concrete	100%			LIFE	**			
Stem (breastwall) Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout With Moderate Cases On North Abutment</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Northwest Corner</i> <i>Explanation : Vegetation Growth</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE	**			
Piles Not Accessible	100%							
Walls Masonry	100%			LIFE	**			
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Vegetation Growth, Extent : Moderate, Area Affected : 40%</i> <i>Location : Random Locations Throughout With Severe Cases On Southwest Wingwall</i>								
Feature Crossed								
Mat (scour & erosion) Asphalt Paving	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Belt Parkway</i>								
Approaches								
Pavement Concrete	100%	4+	\$37,300	2042	**	4	\$26,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 2%</i> <i>Location : South Approach</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BAY 8TH STREET BELT PARKWAY
Asset # : 14960

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Not Accessible	100%							
Guide Railing								
Concrete	100%			2042	**	4	\$8,300	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout On West Side</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE	**	5	\$1,100	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4	\$4,500	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Vegetation Growth</i>					
Steel	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Steel Railing And Chain Link Fence On Top Of Concrete Parapet</i>					
Sidewalks								
Concrete	100%			LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout On West Side</i>					
Deck Elements								
Guide Railing								
Concrete	100%			2046	**			
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout On West Side</i>					
Median								
Concrete	100%			LIFE	**	5	\$1,000	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BAY 8TH STREET BELT PARKWAY
Asset # : 14960

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets Concrete	100%			2042	**	4	\$8,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Moderate, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Vegetation Growth</i>								
Steel	100%			LIFE	**	2-8	\$7,700	
<i>Other Observation, Extent : N/A, Area Affected : 5%</i> <i>Location : Small Holes Patched Near North Abutment On West Side</i> <i>Explanation : Recent Repair Evident</i>								
Sidewalks								
Concrete	100%			2038	**	5	\$1,900	
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout On West Side</i> <i>Explanation : Map Cracks</i>								
Wearing Surface								
Concrete	100%			2042	**	5	\$19,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural Concrete	100%			LIFE	**	5	\$5,300	
<i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations On Overhang Portions</i> <i>Explanation : Limited Access Due To Stay In Place Forms In 90 Percent Area. Vegetation Growth.</i>								
Primary Member Steel	100%			LIFE	**	2-8	\$454,200	
Secondary Member Steel	100%			LIFE	**	2-8	\$22,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BEACH AVENUE SIRT SOUTH SHORE
Address : BEACH AVE BET NEW DORP PLAZA AND S. RAILROAD AVE
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0260.000 / 15014 **Yr Built/Renovated** :
Area Sq Ft : 3,700 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249400

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$23,900		\$10,400	\$7,300
Total	\$23,900		\$10,400	\$7,300
Importance Code A	\$4,400		\$100	
Importance Code B	\$4,200			
Importance Code C	\$15,300		\$10,300	\$7,300
Total	\$23,900		\$10,400	\$7,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BEACH AVENUE SIRT SOUTH SHORE
Asset # : 15014

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$4,200	LIFE			**	
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railway Ballast</i>					
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : East Side</i>					
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railway Tracks</i>					
Approaches								
Pavement Concrete	100%			2044		**	4	\$20,600
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Southeast Approach And Random Locations</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BEACH AVENUE SIRT SOUTH SHORE
Asset # : 15014

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Recent Repair Evident, Extent : N/A, Area Affected : 20%</i>								
<i>Location : Northeast Curb</i>								
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%	4+	\$2,400	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Missing Anchor Bolt At Northeast Approach</i>								
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Base Of Posts And Random Locations</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind Steel Railing</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Northeast And Southwest Approach</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Pier Components</i>								
Pier,Columns								
Concrete	100%			LIFE		**		
Stem,Solid Pier								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Ballast</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BEACH AVENUE SIRT SOUTH SHORE
Asset # : 15014

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 40%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$5,100
			<i>Corrosion, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Base Of Posts And Random Locations</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout Behind Steel Railing</i>					
			<i>Explanation : Chain Link Fence</i>					
Sidewalks								
Concrete	100%	Now	\$13,300	2040		**	5	\$1,000
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Severe, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout On North Side</i>					
Wearing Surface								
Concrete	100%			2044		**	5	\$14,700
			<i>Cracks, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%	4+	\$2,000	LIFE		**		
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 40%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Debris</i>					
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT PARKWAY OCEAN PARKWAY
Address : BELT PARKWAY EAST AND WEST BOUND OVER OCEAN AVENUE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0224.000 / 14959 **Yr Built/Renovated** : 2003 /
Area Sq Ft : 28,819 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 18-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231360

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$80,400	\$1,251,400
Total	\$80,400	\$1,251,400
Importance Code A		\$1,104,700
Importance Code B		\$66,300
Importance Code C	\$80,400	\$80,400
Total	\$80,400	\$1,251,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$27,600		\$117,900	
Total	\$27,600		\$117,900	
Importance Code A	\$6,000		\$111,300	
Importance Code B			\$6,600	
Importance Code C	\$21,600			
Total	\$27,600		\$117,900	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY OCEAN PARKWAY
Asset # : 14959

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE	**			
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE	**			
Mat (scour & erosion) Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : On Both Sides</i>						
		<i>Explanation : Concrete Sidewalk</i>						
Pedestals Concrete	100%			LIFE	**			
Stem (breastwall) Concrete	100%			LIFE	**			
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE	**			
Piles Not Accessible	100%							
Walls Masonry: Stone	100%			LIFE	**			
		<i>Other Observation, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Light Joint Mortar Missing / Eroded On 2 Percent Area. Efflorescence</i>						
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Ocean Avenue And Concrete Sidewalks</i>						
Pier Protection Concrete	100%			LIFE	**			
Approaches								
Pavement Concrete	100%			2042	**	4	\$64,800	
Embankment Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY OCEAN PARKWAY
Asset # : 14959

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Median								
Concrete	100%			LIFE	**	5	\$700	
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4	\$2,900	
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Pier,Columns								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2053	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Concrete</i>						
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Median								
Concrete	100%			LIFE	**	5	\$2,400	
Railings/Parapets								
Concrete	100%			2042	**	4	\$15,000	
		<i>Other Observation, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Water Stains</i>						
Steel	100%			LIFE	**	2-8	\$13,800	
Wearing Surface								
Concrete	100%			2042	**	5	\$160,700	
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$31,700	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout Underside Of Deck</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY OCEAN PARKWAY
Asset # : 14959

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$2,063,400	
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$103,700	
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT PARKWAY BRIDGE / ROCKAWAY PARKWAY
Address : BELT SHORE PARKWAY
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0023.030 / 14785 **Yr Built/Renovated** : 2011 /
Area Sq Ft : 10,370 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 06-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231499

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,191,700	\$1,191,700
Total	\$1,191,700	\$1,191,700
Importance Code A	\$1,132,000	\$1,132,000
Importance Code B	\$59,600	\$59,600
Total	\$1,191,700	\$1,191,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$345,900		\$130,400	
Total	\$345,900		\$130,400	
Importance Code A	\$335,100		\$102,500	
Importance Code B	\$10,900		\$6,000	
Importance Code C			\$21,900	
Total	\$345,900		\$130,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY BRIDGE / ROCKAWAY PARKWAY

Asset # : 14785

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
	<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Pigeon Debris And Pigeon Spikes Present</i>							
Backwall Concrete	100%			LIFE		**		
	<i>Spalling, Extent : Light, Area Affected : 1%</i>							
	<i>Location : Southeast End</i>							
Brngs,Ancr Blts,Pads Elastomeric	100%			2055		**		
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Mat (scour & erosion) Generic	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Sidewalk</i>							
Pedestals Concrete	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Pigeon Debris And Pigeon Spikes Present</i>							
Stem (breastwall) Concrete	100%			LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 1%</i>							
	<i>Location : Random Locations Throughout</i>							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
Granite	100%			LIFE		**		
	<i>Efflorescence, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY BRIDGE / ROCKAWAY PARKWAY

Asset # : 14785

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Underneath Bridge</i>							
	<i>Explanation : Roadway</i>							
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$43,900
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044		**	4	\$2,500
Steel	100%			LIFE		**		
Deck Elements								
Median								
Concrete	100%			LIFE		**	5	\$2,100
Railings/Parapets								
Concrete	100%			2044		**	4	\$2,800
	<i>Cracks, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Steel	100%			LIFE		**	2-8	\$6,400
Wearing Surface								
Concrete	100%			2044		**	5	
Superstructure								
Deck, Structural								
Concrete	100%			LIFE		**	5	\$276,300
	<i>Corrosion, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout On Stay In Place Forms</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Stay In Place Forms Present</i>							
Primary Member								
Steel	100%			LIFE		**	2-8	\$3,181,800
	<i>Other Observation, Extent : Light, Area Affected : 1%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Peeling Of Paint</i>							
Secondary Member								
Steel	100%			LIFE		**	2-8	\$163,800

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT SYSTEM - SHORE PARKWAY BEDFORD AVENUE
Address : BELT PKWY OVER BEDFORD AVE. BET E 23RD & E 26TH STREETS
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0246.000 / 14986 **Yr Built/Renovated** : 1942 /
Area Sq Ft : 11,517 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 20-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231429

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$680,500	\$939,200
Total	\$680,500	\$939,200
Importance Code A	\$610,700	\$187,900
Importance Code B	\$69,800	
Importance Code C		\$751,200
Total	\$680,500	\$939,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$120,200		\$20,000	
Total	\$120,200		\$20,000	
Importance Code A	\$39,200		\$19,300	
Importance Code B	\$12,200		\$700	
Importance Code C	\$68,900			
Total	\$120,200		\$20,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY BEDFORD AVENUE

Asset # : 14986

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$3,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Backwall Concrete	100%	4+	\$31,900	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads Steel	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : Paved Over With Asphalt</i>								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Stone Pavers On Slope</i>								
Pedestals Concrete	100%	4+	\$4,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Stem (breastwall) Concrete	100%	4+	\$69,800	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : East Abutment</i> <i>Explanation : Open Electrical Box</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY BEDFORD AVENUE

Asset # : 14986

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Walls								
Concrete	100%	4+	\$4,700	LIFE			**	
<i>Joints Missing, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Masonry Stone Under Fascias</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry	100%	4+	\$5,600	LIFE			**	
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Roadway</i>								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides Of Asphalt Roadway</i>								
<i>Explanation : Concrete Sidewalk</i>								
Approaches								
Pavement								
Asphalt	100%	2-4	\$27,200	2035	\$544,800	4	\$8,900	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete	100%	4+	\$4,200	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY BEDFORD AVENUE

Asset # : 14986

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Median								
Concrete	100%	4+	\$4,100	LIFE	**	5	\$900	
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 75 Percent Concrete</i>							
Steel	100%	0-2	\$2,700	LIFE	**			
	<i>Damaged Railing, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations On Both Eastbound And Westbound Roadway</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 25 Percent Steel</i>							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Abandoned And Deteriorated Steel Railing Adjacent To New Railing</i>							
Piers								
Cap Beam								
Steel	100%	4+	\$50,700	LIFE	**	2-8	\$170,900	
	<i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Loss of Section, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>							
Pier,Columns								
Masonry	100%			LIFE	**			
	<i>Joints Missing, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>							
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**	2-8	\$1,800	
	<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY BEDFORD AVENUE

Asset # : 14986

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%	4+	\$5,900	2054		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
<hr/>								
Median								
Concrete	100%	4+	\$7,100	LIFE		**	5	\$1,600
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 75 Percent Concrete</i>								
Steel	100%	0-2	\$2,300	LIFE		**	4-8	\$4,200
<i>Damaged Railing, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout With Severe Cases On Eastbound Roadway</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 25 Percent Steel</i>								
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$11,800
<i>Other Observation, Extent : Light, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Abandoned And Deteriorated Steel Railing Adjacent To New Railing</i>								
<hr/>								
Wearing Surface								
Asphalt	100%	4+	\$4,100	2035	\$206,500		5	\$7,000
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$416,200	LIFE		**	5	\$12,700
<i>Cracks, Extent : Light, Area Affected : 20%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Efflorescence, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations At Underside Of Deck Overhang</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Explanation : Scaling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY BEDFORD AVENUE**

Asset # : 14986

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%	4+	\$143,900	LIFE	**	2-8	\$212,900	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout With Severe Cases On Outside Girders</i>								
Secondary Member								
Steel	100%	4+	\$12,200	LIFE	**	2-8	\$10,700	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout With Severe Cases On Outside Overhang</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT SYSTEM - SHORE PARKWAY NOSTRAND AVENUE
Address : BELT PARKWAY OVER NOSTRAND AVE. BET. E 28TH & HARING STREETS
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0247.000 / 14987 **Yr Built/Renovated** : 1942 /
Area Sq Ft : 11,361 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 20-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231439

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,046,600	\$916,300
Total	\$1,046,600	\$916,300
Importance Code A	\$897,100	\$186,400
Importance Code B	\$69,800	
Importance Code C	\$79,800	\$729,900
Total	\$1,046,600	\$916,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$155,400		\$19,900	
Total	\$155,400		\$19,900	
Importance Code A	\$86,300		\$19,200	
Importance Code B	\$33,500		\$700	
Importance Code C	\$35,600			
Total	\$155,400		\$19,900	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY NOSTRAND AVENUE

Asset # : 14987

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$9,000	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Backwall								
Concrete	100%	4+	\$79,800	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout With Severe Cases On West Side</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Rusted</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$3,000	LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Westbound Lanes</i> <i>Explanation : Only At East Abutment. Damaged Steel Armor</i>								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Stone Pavers On Slope</i>								
Pedestals								
Concrete	100%	4+	\$4,600	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								
Stem (breastwall)								
Concrete	100%	4+	\$69,800	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 1%</i> <i>Location : East Abutment</i> <i>Explanation : Electrical Box</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY NOSTRAND AVENUE

Asset # : 14987

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Walls								
Concrete	100%	4+	\$4,700	LIFE			**	
<i>Joints Missing, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Masonry Stone Under Fascias</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry	100%	4+	\$4,600	LIFE			**	
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Roadway</i>								
Concrete	2%	0-2	\$29,700	LIFE			**	
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : West Sidewalk</i>								
<i>Explanation : Concrete Sidewalk On Both Sides Of Asphalt Roadway. Moderate Cracks And Spalls On 5 Percent Area</i>								
Concrete	98%			LIFE			**	
Approaches								
Pavement								
Asphalt	100%	2-4	\$27,200	2035	\$544,800	4	\$8,900	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete	100%	2-4	\$8,500	LIFE			**	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY NOSTRAND AVENUE

Asset # : 14987

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%	4+	\$8,200	LIFE	**	5	\$900	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 75 Percent Concrete</i>								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 25 Percent Steel</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Abandoned And Deteriorated Steel Railing Adjacent To New Railing</i>								
Piers								
Cap Beam								
Steel	100%	4+	\$126,700	LIFE	**	2-8	\$170,900	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Pier,Columns								
Masonry	100%			LIFE	**			
<i>Joints Missing, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Steel	100%	4+	\$9,200	LIFE	**	2-8	\$1,800	
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							

Deck Elements

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY NOSTRAND AVENUE

Asset # : 14987

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%	4+	\$5,400	2054		**		
Cracks, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout								
Spalling, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout								
<hr/>								
Median								
Concrete	100%	4+	\$7,000	LIFE		**	5	\$1,500
Cracks, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout								
Spalling, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout								
Other Observation, Extent : N/A, Area Affected : 100%								
Location : Throughout								
Explanation : 75 Percent Concrete								
Steel	100%			LIFE		**	4-8	
Rust Stains, Extent : Light, Area Affected : 15%								
Location : Random Locations Throughout								
Other Observation, Extent : N/A, Area Affected : 100%								
Location : Throughout								
Explanation : 25 Percent Steel								
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$11,600
Other Observation, Extent : N/A, Area Affected : 100%								
Location : Throughout								
Explanation : Abandoned And Deteriorated Steel Railing Adjacent To New Railing								
<hr/>								
Wearing Surface								
Asphalt	100%	4+	\$3,700	2035	\$185,200		5	\$6,300
Cracks, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$411,000	LIFE		**	5	\$12,500
Cracks, Extent : Light, Area Affected : 25%								
Location : Random Locations Throughout Underside Of Deck								
Efflorescence, Extent : Light, Area Affected : 10%								
Location : Random Locations Throughout Underside Of Deck								
Spalling, Extent : Light, Area Affected : 2%								
Location : Random Locations Throughout Underside Of Deck								
Other Observation, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout Underside Of Deck								
Explanation : Scaling								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY NOSTRAND AVENUE**

Asset # : 14987

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%	4+	\$359,400	LIFE	* *	2-8	\$210,000	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout With Severe Cases Near Abutments And Outside Girders</i>								
Secondary Member								
Steel	100%	4+	\$30,500	LIFE	* *	2-8	\$10,600	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout With Severe Cases On Outside Overhang</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT SYSTEM - SHORE PARKWAY OVER BAY RIDGE AVENUE
Address : BELT PARKWAY AT BAY RIDGE AVENUE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0353.000 / 15367 **Yr Built/Renovated** :
Area Sq Ft : 6,960 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 07-Jul-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231249


CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure				\$2,100
Total				\$2,100
Importance Code A				\$2,100
Total				\$2,100



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY OVER BAY RIDGE AVENUE

Asset # : 15367

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : South Abutment</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE	**			
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Southwest Wing Wall</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Southeast And Southwest Wing Walls</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Approaches								
Pavement								
Concrete	100%			2041	**	4		
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE	**	5		
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PARKWAY OVER BAY RIDGE AVENUE

Asset # : 15367

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Approaches							
Railings/Parapets Concrete	100%			2041	**	4	\$1,400
<i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Southeast Parapet</i> <i>Explanation : Vegetation Growth</i>							
Deck Elements							
Median Concrete	100%			LIFE	**	5	\$1,000
Railings/Parapets Concrete	100%			2041	**	4	\$2,700
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations On East Side</i>							
Wearing Surface Concrete	100%			2041	**	5	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>							
Superstructure							
Deck, Structural Not Accessible	100%						
Primary Member Prestressed Concrete Box Beam	100%			LIFE	**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT SYSTEM - SHORE PKWY OCEAN AVENUE
Address : BELT PKWY OVER OCEAN AVE SHORE PKWY EB & SHORE PKWY WB
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0245.000 / 14985 **Yr Built/Renovated** : 1942 /
Area Sq Ft : 13,735 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 20-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231419

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$567,400	\$849,200
Total	\$567,400	\$849,200
Importance Code A	\$496,800	\$74,400
Importance Code B	\$70,600	
Importance Code C		\$774,800
Total	\$567,400	\$849,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$180,100		\$8,600	
Total	\$180,100		\$8,600	
Importance Code A	\$63,800		\$7,800	
Importance Code B	\$20,800		\$800	
Importance Code C	\$95,400			
Total	\$180,100		\$8,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PKWY OCEAN AVENUE

Asset # : 14985

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$3,600	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout With Severe Cases On West Side</i>								
Backwall								
Concrete	100%	4+	\$32,600	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE			**	
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Only At West Abutment</i>								
Mat (scour & erosion)								
Generic	100%	4+	\$6,600	LIFE			**	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Stone Pavers On Slope</i>								
Pedestals								
Concrete	100%	4+	\$5,100	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Stem (breastwall)								
Concrete	100%	4+	\$70,600	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 1%</i> <i>Location : East Abutment</i> <i>Explanation : Electrical Box</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PKWY OCEAN AVENUE

Asset # : 14985

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Walls								
Concrete	100%			LIFE			**	
<i>Joints Missing, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Masonry Stone Under Fascias</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry	100%	2-4	\$12,900	LIFE			**	
<i>Joint Mortar Miss/Erod, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southwest Wingwall</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Roadway</i>								
Concrete	5%	2-4	\$22,700	LIFE			**	
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : West Sidewalk</i>								
<i>Explanation : Concrete Sidewalk On Both Sides Of Asphalt Roadway. Light Settlement On 5 Percent Area And Moderate Cracks On 10 Percent Area</i>								
Concrete	95%			LIFE			**	
Approaches								
Pavement								
Asphalt	100%	4+	\$27,500	2035	\$550,000	4	\$9,000	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete	100%	4+	\$1,700	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PKWY OCEAN AVENUE

Asset # : 14985

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%	4+	\$4,100	LIFE	**	5	\$900	
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 75 Percent Concrete</i>								
Steel	100%	0-2	\$2,700	LIFE	**			
<i>Damaged Railing, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Eastbound Roadway At East Approach</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 25 Percent Steel</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Abandoned And Deteriorated Steel Railing Adjacent To New Railing</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$172,000	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Pier, Columns								
Masonry	100%			LIFE	**			
<i>Joints Missing, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs, Ancr Blts, Pads								
Steel	100%			LIFE	**	2-8	\$1,800	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Outside Bearings</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PKWY OCEAN AVENUE**

Asset # : 14985

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%	2-4	\$10,000	2054		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Median								
Concrete	100%	4+	\$8,400	LIFE		**	5	\$1,900
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 75 Percent Concrete</i>								
Steel	100%	0-2	\$5,500	LIFE		**	4-8	\$5,000
<i>Damaged Railing, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Eastbound Roadway</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 25 Percent Steel</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$7,000
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Abandoned And Deteriorated Steel Railing Adjacent To New Railing</i>								
Wearing Surface								
Asphalt	100%	Now	\$22,500	2035	\$224,900		5	\$7,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations On Eastbound Roadway</i>								
<i>Explanation : Potholes</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM - SHORE PKWY OCEAN AVENUE
Asset # : 14985

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure Deck, Structural Concrete	100%	4+	\$496,800	LIFE	**	5	\$15,100	
<i>Cracks, Extent : Light, Area Affected : 20%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Efflorescence, Extent : Light, Area Affected : 15%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations On Underside Of Outside Overhang</i> <i>Spalling, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout Underside Of Deck</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Scaling</i>								
Primary Member Steel	100%			LIFE	**	2-8		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Secondary Member Steel	100%	4+	\$14,200	LIFE	**	2-8	\$12,800	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout With Severe Cases On Outside Overhang</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT SYSTEM SHORE PKWY EB MILL BASIN
Address : BELT PKWAY OVER MILL BASIN
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0022.200 / 15675 **Yr Built/Renovated** : 2018 /
Area Sq Ft : 191,908 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 26-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231472

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$2,664,300	\$2,664,300
Total	\$2,664,300	\$2,664,300
Importance Code A	\$2,110,600	\$2,110,600
Importance Code B	\$114,000	\$114,000
Importance Code C	\$439,600	\$439,600
Total	\$2,664,300	\$2,664,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$658,600		\$230,500	
Total	\$658,600		\$230,500	
Importance Code A	\$633,700		\$211,300	
Importance Code B	\$25,000		\$11,400	
Importance Code C			\$7,700	
Total	\$658,600		\$230,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM SHORE PKWY EB MILL BASIN
Asset # : 15675

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2070		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	100%			LIFE		**		
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations With Worse Cases On Joints At Sidewalks</i>					
			<i>Explanation : Debris</i>					
Mat (scour & erosion)								
Generic	100%	4+	\$4,200	LIFE		**		
			<i>Erosion, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Southeast Corner</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Ballast Stones</i>					
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations On South Side</i>					
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM SHORE PKWY EB MILL BASIN**

Asset # : 15675

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion) Stream Bed	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 75%</i>						
		<i>Location : Throughout Except Waterway</i>						
		<i>Explanation : Ballast Stones</i>						
Pier Protection Timber	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout Piers On Waterway</i>						
		<i>Explanation : Polymer Fascia On Timber Protection</i>						
Approaches								
Pavement Concrete	100%			2048		**	4	\$15,500
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations On West Approach</i>						
Embankment Not Accessible	100%							
Guide Railing Concrete	100%			2048		**	4	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations On South Side</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations On South Side</i>						
Steel	100%			LIFE		**	2-8	
Mat (scour & erosion) Not Accessible	100%							
Pavement Base Not Accessible	100%							
Railings/Parapets Concrete	100%			2048		**	4	\$700
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations On North Side</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations On North Side</i>						
Steel	100%			LIFE		**		
Sidewalks Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations On South Side</i>						
Piers								
Cap Beam Concrete	100%			LIFE		**		
Pier,Columns Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Multi-Rotational Bearing	100%			2070		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM SHORE PKWY EB MILL BASIN
Asset # : 15675

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Footings								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Footings Are Partially Visible At Piers On Waterway On 10 Percent Area. No Access To Rest Of The Footing.</i>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 75%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Streambed On 25 Percent Area On Waterway. Ballast Stones Elsewhere</i>								
Pedestals								
Concrete	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing								
Concrete	100%			2052		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Location On South Side</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Location On South Side</i>								
Steel	100%			LIFE		**		
Railings/Parapets								
Concrete	100%			2048		**	4	\$40,900
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On North Side</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On North Side</i>								
Steel	100%			LIFE		**	2-8	
Sidewalks								
Concrete	100%			2043		**	5	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On South Side</i>								
Wearing Surface								
Concrete	100%			2048		**	5	\$879,300
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 10 Scuppers</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM SHORE PKWY EB MILL BASIN**

Asset # : 15675

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure Deck, Structural Concrete	100%			LIFE	**	5	\$422,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On Bay 4 And On Both Overhangs</i> <i>Corrosion, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations On Stay In Place Forms</i> <i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations On Bay 4 And On Both Overhangs</i> <i>Other Observation, Extent : N/A, Area Affected : 80%</i> <i>Location : Throughout</i> <i>Explanation : Stay In Place Forms On All Interior Bays Except Bay 4</i>								
Joints Steel	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations With Worse Case On Sidewalk Joints</i> <i>Explanation : Debris</i>								
Primary Member Steel	100%			LIFE	**	2-8	\$6,080,900	
Secondary Member Steel	100%			LIFE	**	2-8	\$313,000	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT SYSTEM SHORE PKWY WB MILL BASIN
Address : BELT PKWAY OVER MILL BASIN
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0022.100 / 15674 **Yr Built/Renovated** : 2018 /
Area Sq Ft : 143,305 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 26-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231471

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$2,056,700	\$2,056,700
Total	\$2,056,700	\$2,056,700
Importance Code A	\$1,576,100	\$1,576,100
Importance Code B	\$85,100	\$85,100
Importance Code C	\$395,500	\$395,500
Total	\$2,056,700	\$2,056,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$488,700		\$199,700	
Total	\$488,700		\$199,700	
Importance Code A	\$473,200		\$184,000	
Importance Code B	\$15,500		\$8,500	
Importance Code C			\$7,200	
Total	\$488,700		\$199,700	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM SHORE PKWY WB MILL BASIN
Asset # : 15674

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE			**	
Backwall								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2070			**	
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	100%			LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Debris</i>					
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Ballast Stones</i>					
Pedestals								
Concrete	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations On North Side</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations On North Side</i>					
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM SHORE PKWY WB MILL BASIN
Asset # : 15674

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion) Stream Bed	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 75%</i>						
		<i>Location : Throughout Except Waterway</i>						
		<i>Explanation : Ballast Stones</i>						
Pier Protection Timber	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout Piers On Waterway</i>						
		<i>Explanation : Polymer Fascia On Timber Protection</i>						
Approaches								
Pavement Concrete	100%			2048		**	4	\$14,400
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Embankment Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pavement Base Not Accessible	100%							
Railings/Parapets Concrete	100%			2048		**	4	\$1,600
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Piers								
Cap Beam Concrete	100%			LIFE		**		
Pier, Columns Concrete	100%			LIFE		**		
Brngs, Ancr Blts, Pads Multi-Rotational Bearing	100%			2070		**		
Footings Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 90%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Footings Are Partially Visible At Piers On Waterway On 10 Percent Area. No Access To Rest Of The Footing.</i>						
Mat (scour & erosion) Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 75%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Streambed On 25 Percent Area On Waterway. Ballast Stones Elsewhere</i>						
Pedestals Concrete	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT SYSTEM SHORE PKWY WB MILL BASIN
Asset # : 15674

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2048	**	4	\$81,900	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Wearing Surface								
Concrete	100%			2048	**	5	\$790,900	
Scupper								
Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 13 Scuppers</i>						
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$315,400	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations On Both Overhangs</i>						
		<i>Corrosion, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations On Stay In Place Forms</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations On Both Overhangs</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Stay In Place Forms On All Interior Bays</i>						
Joints								
Steel	100%			LIFE	**			
		<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Debris</i>						
Primary Member								
Steel	100%			LIFE	**	2-8	\$4,540,800	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$233,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BEVERLY ROAD BMT SUBWAY, BRIGHTON
Address : BEVERLY ROAD BET. E16TH STREET MARLBOROUGH ROAD
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0299.000 / 15057 **Yr Built/Renovated** :
Area Sq Ft : 4,224 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 30-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243100

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$935,500	\$57,000
Total	\$935,500	\$57,000
Importance Code A	\$512,900	\$57,000
Importance Code B	\$422,500	
Total	\$935,500	\$57,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$136,600		\$8,600	
Total	\$136,600		\$8,600	
Importance Code A	\$37,200		\$5,800	
Importance Code B	\$38,600		\$2,700	
Importance Code C	\$60,800		\$200	
Total	\$136,600		\$8,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BEVERLY ROAD BMT SUBWAY, BRIGHTON
Asset # : 15057

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Concrete	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Location Throughout</i>					
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Covered By Asphalt Wearing Surface</i>					
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Station Platforms</i>					
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Bottom Of West Abutment And Random Locations</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Station Platforms</i>					
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railway Tracks</i>					
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BEVERLY ROAD BMT SUBWAY, BRIGHTON
Asset # : 15057

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	30%	Now	\$29,500	2036	**	4	\$300	
<i>Cracks, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Near Deck And Random Locations</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Near Deck And Random Locations</i>								
<i>Explanation : Rutting</i>								
Asphalt	70%			2036	**	4	\$300	
Curbs								
Concrete	100%			LIFE	**			
Granite	100%			LIFE	**			
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	4+	\$1,400	LIFE	**			
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$220,500	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Pier, Columns								
Steel	10%	Now	\$2,400	LIFE	**	2-8	\$35,100	
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations With Severe Cases At Base And Near Pier Caps</i>								
<i>Loss of Section, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations With Severe Cases Near Pier Caps</i>								
Steel	90%			LIFE	**	2-8	\$57,600	
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Platform</i>								
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BEVERLY ROAD BMT SUBWAY, BRIGHTON
Asset # : 15057

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	Now	\$94,800	LIFE		**		
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$2,300
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Fence On Both Sides. Abandoned Railing With Corrosion And Section Loss On North Side Behind Steel Railing Repair</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$6,000	2040		**	5	\$1,200
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : At Northeast Corner</i>								
<i>Explanation : Steel Plates Placed Over Sidewalk</i>								
<hr/>								
Wearing Surface								
Asphalt	100%	0-2	\$23,900	2036		**	5	\$200
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout With Severe Cases Near Deck Joints</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout Along Wheel Paths</i>								
<i>Explanation : Rutting</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	20%	Now	\$138,900	LIFE		**	5	\$4,600
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations At Underside Of Sidewalk</i>								
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations At Underside Of Sidewalk</i>								
<i>Spalling, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Random Locations At Underside Of Sidewalk</i>								
<hr/>								
Concrete	80%			LIFE		**	5	\$9,300
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BEVERLY ROAD BMT SUBWAY, BRIGHTON
Asset # : 15057

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Concrete Encased Steel	7%	Now	\$60,800	LIFE	**	5	\$21,300	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations On Exposed Girders Above Deck</i> <i>Loss of Section, Steel, Extent : Moderate, Area Affected : 5%</i> <i>Location : Web And Stiffeners On The Traffic Side Of Exposed Girders Above Deck</i> <i>Other Observation, Extent : Severe, Area Affected : 5%</i> <i>Location : Random Locations On Exposed Girders Above Deck</i> <i>Explanation : Severe Impact Damage On South Girder Stiffener On 2 Percent Area. Peeling Paint</i>								
Concrete Encased Steel	93%	4+	\$161,500	LIFE	**	5	\$21,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Corrosion, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Delaminations, Extent : Moderate, Area Affected : 2%</i> <i>Location : Random Locations On Bottom Flanges</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On Bottom Flanges</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Location Along Bottom Flanges</i>								
Secondary Member								
Concrete Encased Steel	100%	Now	\$422,500	2063	**			
<i>Corrosion, Extent : Severe, Area Affected : 50%</i> <i>Location : Random Locations On Fascia Below Sidewalk</i> <i>Other Observation, Extent : Severe, Area Affected : 30%</i> <i>Location : Random Locations On Fascia Below Sidewalk</i> <i>Explanation : Loss Of Section And Paint Peeling</i>								
Steel	100%	2-4	\$13,700	LIFE	**	2-8	\$3,900	
<i>Corrosion, Extent : Moderate, Area Affected : 30%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BMT SUBWAY BRIDGE PARKSIDE AVE/BMT SUBWAY
Address : PARKSIDE AVE,OCEAN-FLATBUSH
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0064.000 / 2489 **Yr Built/Renovated** : 1916 /
Area Sq Ft : 48,720 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 25-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243020

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$7,476,900	\$2,027,200
Total	\$7,476,900	\$2,027,200
Importance Code A	\$1,300,200	\$250,600
Importance Code B	\$1,376,200	
Importance Code C	\$4,800,500	\$1,776,600
Total	\$7,476,900	\$2,027,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$115,900	\$6,200	\$2,400	\$46,200
Total	\$115,900	\$6,200	\$2,400	\$46,200
Importance Code C	\$115,900	\$6,200	\$2,400	\$46,200
Total	\$115,900	\$6,200	\$2,400	\$46,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BMT SUBWAY BRIDGE PARKSIDE AVE/BMT SUBWAY

Asset # : 2489

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Concrete	15%	4+	\$127,300	LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Concrete	85%			LIFE		**		
Tile	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Ceramic Tiles Obscure View Of Structural Wall</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access. Wingwall Only Present At South Abutment</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Tracks</i>								
Approaches								
Pavement								
Asphalt	55%	4+	\$23,900	2034	\$477,700	4	\$12,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Both Approaches</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Beginning Approach</i>								
<i>Explanation : Rutting, Uneven Pavement</i>								
Asphalt	45%			2027	\$390,900	4	\$18,700	
Concrete	35%	4+	\$47,500	2042	**	4	\$92,500	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	65%			2029	\$4,409,600	4	\$92,500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BMT SUBWAY BRIDGE PARKSIDE AVE/BMT SUBWAY

Asset # : 2489

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete w/ Steel Face	100%			LIFE		**		
		<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>						
		<i>Location : Random Locations Throughout</i>						
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Piers								
Pier, Columns								
Concrete	100%			LIFE		**		
Stem, Solid Pier								
Concrete	100%	Now	\$1,248,900	LIFE		**		
		<i>Cracks, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Delaminations, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Moderate, Area Affected : 20%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Exposed Reinforcement, Extent : Severe, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Severe, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Railway Tracks</i>						
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BMT SUBWAY BRIDGE PARKSIDE AVE/BMT SUBWAY
Asset # : 2489

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%			2053		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Gratings								
Steel	100%			LIFE		**		
Sidewalks								
Asphalt	100%	4+	\$5,000	2031	\$248,300	4	\$18,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Plaza Entrance To Station Building</i>								
Concrete	90%			2038		**	\$4,800	
Concrete	10%	Now	\$18,500	2038		**	\$2,400	
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Near South End</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Near South End</i>								
Wearing Surface								
Asphalt	100%	4+	\$21,000	2034	\$1,050,500	5	\$31,100	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : At South End</i>								
<i>Explanation : Asphalt Pavers</i>								
Superstructure								
Primary Member								
Concrete	100%	Now	\$1,300,200	LIFE		**	\$250,600	1
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BRONX PELHAM PARKWAY BRIDGE BRONX PELHAM PKWY/AMTRAK,METRO N
Address : OVER BRONX RIVER PARKWAY
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0152.000 / 13515 **Yr Built/Renovated** : 1907 /
Area Sq Ft : 24,591 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 09-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2229560

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$127,200	\$227,700
Total	\$127,200	\$227,700
Importance Code C	\$127,200	\$227,700
Total	\$127,200	\$227,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$96,500		\$400	\$600
Total	\$96,500		\$400	\$600
Importance Code A	\$35,200		\$400	\$600
Importance Code B	\$10,700			
Importance Code C	\$50,600			
Total	\$96,500		\$400	\$600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BRONX PELHAM PARKWAY BRIDGE BRONX PELHAM PKWY/AMTRAK,METRO N
Asset # : 13515

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Underside Of Bridge Throughout</i>							
	<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	90%			LIFE		**		
Steel	10%	4+	\$10,700	LIFE		**		
	<i>Spalling, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : South Sidewalk</i>							
	<i>Other Observation, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Damaged Filler Material</i>							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%	4+	\$62,600	2041		**	4	\$57,000
	<i>Cracks, Extent : Light, Area Affected : 10%</i>							
	<i>Location : At Both Approaches</i>							
	<i>Spalling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : At Both Approaches</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRONX PELHAM PARKWAY BRIDGE BRONX PELHAM PKWY/AMTRAK,METRO N
Asset # : 13515

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	4+	\$6,500	LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Embankment								
Earth	100%			LIFE		**		
Guide Railing								
Concrete	100%	4+	\$3,900	2041		**	4	\$1,100
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : West Approach South Side</i>								
<i>Explanation : Total Guide Railing Consists Of 20 Percent Concrete, 30 Percent Steel And 50 Percent Timber</i>								
Steel	100%			LIFE		**	2-8	\$1,700
Timber	100%	4+	\$500	2033	\$10,800		4	\$1,600
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout Timber Rail</i>								
<i>Dry Rot, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : West Approach South End</i>								
<i>Explanation : Timber Railing</i>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$1,100	2041		**	4	\$300
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRONX PELHAM PARKWAY BRIDGE BRONX PELHAM PKWY/AMTRAK,METRO N
Asset # : 13515

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Asphalt	100%	4+	\$8,200	2033	\$163,200	4	\$7,900	
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Settlement, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 3%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Vegetation Growth</i>							
Concrete	100%	4+	\$19,200	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Vegetation Growth, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>							
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
	<i>Rust Stains, Extent : Light, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : North Side Curb</i> <i>Explanation : North Side Curb Is Concrete With Steel Face</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRONX PELHAM PARKWAY BRIDGE BRONX PELHAM PKWY/AMTRAK,METRO N
Asset # : 13515

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Guide Railing Concrete	100%	2-4	\$23,200	2045		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 15%</i>								
<i>Location : South Face Of Concrete Barrier</i>								
<i>Spalling, Extent : Severe, Area Affected : 25%</i>								
<i>Location : South Face Of Concrete Barrier</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Along The South Side Of The Bridge</i>								
<i>Explanation : Concrete Guide Rail With Steel Fencing</i>								
Steel	100%			LIFE		**		
Railings/Parapets								
Concrete	100%			2041		**	4	\$1,100
Steel	100%			LIFE		**	2-8	\$9,500
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Exterior Surface</i>								
Sidewalks								
Concrete	100%	4+	\$23,300	2037		**	5	\$6,000
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2041		**	5	\$129,100
Superstructure								
Deck,Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BRUCKNER BLVD. OVERPASS BRIDGE 278I - BRUCKNER BLVD
Address : 133RD - 135TH ST
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0077.000 / 2508 **Yr Built/Renovated** : 1938 /
Area Sq Ft : 32,900 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2266540

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,635,100	\$1,152,700
Total	\$1,635,100	\$1,152,700
Importance Code A	\$538,700	\$501,400
Importance Code B	\$1,096,400	\$651,300
Total	\$1,635,100	\$1,152,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$477,100		\$177,200	
Total	\$477,100		\$177,200	
Importance Code A	\$69,500		\$1,700	
Importance Code B	\$332,600		\$65,300	
Importance Code C	\$75,000		\$110,100	
Total	\$477,100		\$177,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRUCKNER BLVD. OVERPASS BRIDGE 278I - BRUCKNER BLVD
Asset # : 2508

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Backwall								
Concrete	100%			LIFE		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Roadway Pavement</i>								
Stem (breastwall)								
Concrete Encased Steel	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Missing Broken Element Of Brick Fascia</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Roadway/pavement</i>								
Piles								
Not Accessible	100%							
Walls								
Brick	95%			LIFE		**		
Brick	5%	4+	\$16,300	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Broken/missing Element</i>								
Concrete	5%	4+	\$13,700	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i>								
<i>Location : Joint Filler At Southwest Wingwall Joint</i>								
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Wingwall</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southwest Wingwall</i>								
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Minor Peeling Paint</i>								
Concrete	95%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		

Approaches

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRUCKNER BLVD. OVERPASS BRIDGE 278I - BRUCKNER BLVD

Asset # : 2508

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%			2036	**	4	\$3,200	
Concrete	10%	4+	\$27,900	2044	**	4	\$217,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	90%			2044	**	4	\$217,000	
Curbs								
Concrete	100%			LIFE	**			
Embankment								
Earth	100%			LIFE	**			
Guide Railing								
Concrete	100%			2044	**	4		
Steel	100%			LIFE	**	2-8	\$40,900	
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4		
Steel	100%	4+	\$4,700	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northern Approach</i>								
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Concrete Encased Steel	100%	2-4	\$187,600	LIFE	**	5	\$73,200	
<i>Spalling, Extent : Severe, Area Affected : 2%</i>								
<i>Location : North Fascia And Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRUCKNER BLVD. OVERPASS BRIDGE 278I - BRUCKNER BLVD
Asset # : 2508

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier, Columns								
Concrete Encased Steel	100%	4+	\$445,100	LIFE	**	5	\$12,700	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Severe, Area Affected : 3%</i>								
<i>Location : Near North Fascia</i>								
<i>Explanation : Delamination And Exposed Reinforcement</i>								
Steel	100%			LIFE	**	2-8	\$1,536,500	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Stem, Solid Pier								
Concrete	100%			LIFE	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%			2055	**			
Gratings								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Guide Railing								
Concrete	100%			2048	**			
<i>Other Observation, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Peeling Paint</i>								
Steel	100%	4+	\$1,300	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Broken Support At Southwest Side</i>								
Median								
Concrete	100%			LIFE	**	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : West Side</i>								
<i>Explanation : Raised Concrete Island</i>								
Railings/Parapets								
Concrete	100%			2044	**	4	\$2,100	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Above South Entrance</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Above South Entrance</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRUCKNER BLVD. OVERPASS BRIDGE 278I - BRUCKNER BLVD
Asset # : 2508

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2040	**	5	\$800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%			2036	**	5	\$34,200	
Superstructure								
Deck, Structural								
Concrete	80%			LIFE	**	5	\$96,700	
Concrete	20%	2-4	\$126,900	LIFE	**	5	\$48,300	
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : On Underside Of Deck</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Near Beginning And End Of Southbound Travel Lane</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : On Underside Of Deck</i>								
Primary Member								
Concrete Encased Steel	9%	4+	\$58,400	LIFE	**	5	\$165,800	
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Peeling Paint</i>								
Concrete Encased Steel	91%			LIFE	**	5	\$331,600	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$894,400	
<i>Other Observation, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BRUCKNER EXPWY NORTH BOUND AMTRAK - CSX
Address : BRUCKNER BLVD NB AT ABOUT LONGFELLOW AVE
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0313.000 / 15083 **Yr Built/Renovated** :
Area Sq Ft : 11,716 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 11-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2075352

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$116,000	\$116,000
Total	\$116,000	\$116,000
Importance Code A	\$116,000	\$116,000
Total	\$116,000	\$116,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$40,900		\$12,500	
Total	\$40,900		\$12,500	
Importance Code A	\$40,900		\$12,500	
Importance Code C				
Total	\$40,900		\$12,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BRUCKNER EXPWY NORTH BOUND AMTRAK - CSX

Asset # : 15083

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Railroad Track At South Side, Earth At The North Side</i>								
<i>Explanation : Railroad Track And Earth</i>								
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Amtrak Railroad Track</i>								
Approaches								
Pavement								
Concrete	100%			2044			**	4
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Guide Railing								
Concrete	100%			2044			**	4
								\$1,400
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BRUCKNER EXPWY NORTH BOUND AMTRAK - CSX

Asset # : 15083

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Railings/Parapets Steel	100%			LIFE	**			
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : North End</i>							
	<i>Explanation : Under Construction</i>							
<hr/>								
Sidewalks Concrete	100%			LIFE	**			
	<i>Cracks, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
<hr/>								
Deck Elements								
Guide Railing Concrete	100%			2048	**			
Railings/Parapets Steel	100%			LIFE	**	2-8	\$5,600	
Sidewalks Concrete	100%			2040	**	5	\$3,300	
	<i>Cracks, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Wearing Surface Concrete	100%			2044	**	5		
	<i>Cracks, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
<hr/>								
Superstructure								
Deck, Structural Not Accessible	100%							
Primary Member Steel	100%			LIFE	**	2-8	\$371,200	
Secondary Member Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BULOVA AVENUE 278I BROOKLYN-QUEENS EXPRESSWAY
Address : BULOVA AVENUE OVER BQE WEST
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0320.000 / 15179 **Yr Built/Renovated** : 1942 /
Area Sq Ft : 3,168 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230790

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$28,200	\$900	\$100	\$2,900
Total	\$28,200	\$900	\$100	\$2,900
Importance Code A			\$100	\$1,100
Importance Code C	\$28,200	\$900		\$1,800
Total	\$28,200	\$900	\$100	\$2,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BULOVA AVENUE 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15179

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	28%	4+	\$26,200	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	72%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier Protection Consists Of 30 Percent Concrete, 70 Percent Not Accessible</i>								
Approaches								
Pavement								
Concrete	100%			2041		**	4	\$3,600
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BULOVA AVENUE 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15179

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Cap Beam Consists Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Pier,Columns								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier, Column Consists Of 20 Percent Concrete, 80 Percent Not Accessible</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pedestals Consist Of 5 Percent Concrete, 95 Percent Not Accessible</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2041		**	4	\$2,200
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$3,100
<i>Corrosion, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BULOVA AVENUE 278I BROOKLYN-QUEENS EXPRESSWAY

Asset # : 15179

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2037	**	5	\$1,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Concrete Patches</i>								
Wearing Surface								
Concrete	100%	4+	\$2,000	2041	**	5	\$6,600	
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : On Edges Of Concrete Patches</i> <i>Other Observation, Extent : N/A, Area Affected : 45%</i> <i>Location : On North Side</i> <i>Explanation : Concrete Patches</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BUS STATION ENTRANCE RAMP STATEN ISLAND RAILWAY
Address : STATEN ISLAND FERRY TERMINAL RAMP TO BUS STATION
Borough : STATEN ISLAND Agency's Number : N/A
Program / Asset # : DOT0346.000 / 15205 Yr Built/Renovated : 1948 /
Area Sq Ft : 51,573 Project Type : HIGHWAY BRIDGES
Date of Survey : 24-Nov-2020 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2269770

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$116,500	\$1,791,200
Total	\$116,500	\$1,791,200
Importance Code A		\$1,447,900
Importance Code B		\$226,800
Importance Code C	\$116,500	\$116,500
Total	\$116,500	\$1,791,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$43,300	\$11,700	\$163,000	\$10,100
Total	\$43,300	\$11,700	\$163,000	\$10,100
Importance Code A			\$140,200	\$7,400
Importance Code B	\$43,300		\$22,700	
Importance Code C		\$11,700		\$2,800
Total	\$43,300	\$11,700	\$163,000	\$10,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BUS STATION ENTRANCE RAMP STATEN ISLAND RAILWAY

Asset # : 15205

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE			**	
Mat (scour & erosion) Generic	100%			LIFE			**	
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	100%	4+	\$43,300	LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
Pier Protection Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Spalling; Cracks</i>					
Approaches								
Pavement Concrete	100%			2041		**	4	\$5,500
Curbs Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BUS STATION ENTRANCE RAMP STATEN ISLAND RAILWAY

Asset # : 15205

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Guide Railing Concrete	100%			2041	**	4	\$500	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion) Not Accessible	100%							
Pavement Base Not Accessible	100%							
Railings/Parapets Masonry	100%			2041	**			
Sidewalks Concrete	100%			LIFE	**			
Piers								
Cap Beam Steel	100%			LIFE	**	2-8	\$1,110,100	
Pier, Columns Steel	100%			LIFE	**	2-8	\$495,500	
Brngs, Ancr Blts, Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 90%</i>								
<i>Location : Random Locations Throughout</i>								
Guide Railing Concrete	100%			2045	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railing On Top Of Concrete</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BUS STATION ENTRANCE RAMP STATEN ISLAND RAILWAY

Asset # : 15205

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Deck Elements							
Railings/Parapets Concrete	100%			2041	**	4	\$14,200
	<i>Cracks, Extent : Light, Area Affected : 1%</i>						
	<i>Location : Random Locations Throughout</i>						
Steel	100%			LIFE	**	2-8	\$19,500
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : South Side</i>						
	<i>Explanation : Chain Link Fence</i>						
Sidewalks							
Concrete	100%			2037	**	5	\$23,500
	<i>Cracks, Extent : Light, Area Affected : 1%</i>						
	<i>Location : Random Locations Throughout</i>						
Wearing Surface							
Concrete	100%			2041	**	5	\$232,900
	<i>Cracks, Extent : Light, Area Affected : 5%</i>						
	<i>Location : Random Locations Throughout</i>						
Scupper							
Cast Iron	100%			LIFE	**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Explanation : 24 Scuppers Observed</i>						
Superstructure							
Deck,Structural Concrete	100%			LIFE	**	5	\$56,800
	<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Entire Deck</i>						
	<i>Explanation : Bottom Covered With Stay In Place Forms</i>						
Joints							
Generic	100%			LIFE	**		
Primary Member							
Steel	100%			LIFE	**	2-8	\$1,701,600
Secondary Member							
Steel	100%			LIFE	**	2-8	\$85,500

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CARLTON AVENUE LIRR ATLANTIC AVE
Address : CARLTON AVE OVER LIRR YARD BET. ATLANTIC AVE & PACIFIC ST.
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0244.000 / 14984 **Yr Built/Renovated** :
Area Sq Ft : 15,720 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 10-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243290

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$50,900	\$4,700	\$300	\$6,500
Total	\$50,900	\$4,700	\$300	\$6,500
Importance Code A	\$22,900	\$300	\$300	
Importance Code C	\$28,000	\$4,300		\$6,500
Total	\$50,900	\$4,700	\$300	\$6,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CARLTON AVENUE LIRR ATLANTIC AVE
Asset # : 14984

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Backwall								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2054		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Both Headers</i>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Stem (breastwall)								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CARLTON AVENUE LIRR ATLANTIC AVE
Asset # : 14984

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Under Construction	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Reinforced Concrete Wingwalls Under Construction With Limited Access On 90 Percent Area</i>								
Feature Crossed								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Under Span 2</i>								
<i>Explanation : Railroad Tracks</i>								
Approaches								
Pavement								
Concrete	100%			2043		**	4	\$13,000
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Header Joints</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2043		**	4	\$1,000
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : In Northwest, Southeast And Southwest Corners.</i>								
<i>Explanation : Temporary Concrete Barriers.</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Northwest, Southeast And Southwest Corners</i>								
<i>Explanation : Temporary Chain Link Fence</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southeast Corner</i>								
<i>Explanation : 1 Scupper</i>								

Piers

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CARLTON AVENUE LIRR ATLANTIC AVE
Asset # : 14984

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads Elastomeric	100%			2054		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%	4+	\$6,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Southeast Corner</i>								
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Southeast Corner</i>								
Railings/Parapets Concrete	100%	4+	\$16,600	2043		**	4	\$6,400
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Light, Area Affected : 5%</i>								
<i>Location : Decorative Cladding On Random Locations</i>								
Steel	100%			LIFE		**	2-8	\$8,700
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout On Both Sides</i>								
<i>Explanation : Steel Wire Mesh On Top Of Concrete Parapet</i>								
Sidewalks Concrete	100%			2039		**	5	\$13,000
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Transverse Cracks On Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CARLTON AVENUE LIRR ATLANTIC AVE
Asset # : 14984

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Wearing Surface								
Concrete	100%	4+	\$17,100	2043	**	5	\$26,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Moderate, Area Affected : 2%</i> <i>Location : Throughout</i> <i>Explanation : Uneven Surface</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%	Now	\$11,000	LIFE	**			
<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 50%</i> <i>Location : Throughout On Both Lanes Between Span 1 And 2</i> <i>Spalling, Extent : Moderate, Area Affected : 15%</i> <i>Location : Header Between Span 1 And 2 In Northbound Lane</i> <i>Other Observation, Extent : Moderate, Area Affected : 30%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Debris Accumulation</i>								
Primary Member								
Steel	100%			LIFE	**	2-8		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CLINTONVILLE STREET BELT SYSTEM - CROSS ISLAND
Address : CLINTONVILLE ST CROSS ISLAND PKWY BTWN 14TH RD & LOCKE AVE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0389.000 / 15409 **Yr Built/Renovated** :
Area Sq Ft : 6,310 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231940

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$236,500
Total		\$236,500
Importance Code C		\$236,500
Total		\$236,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$63,100		\$2,100	
Total	\$63,100		\$2,100	
Importance Code A	\$18,600		\$200	
Importance Code B	\$24,400			
Importance Code C	\$20,200		\$1,900	
Total	\$63,100		\$2,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
CLINTONVILLE STREET BELT SYSTEM - CROSS ISLAND

Asset # : 15409

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 80%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Brick Veneer	100%			LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Vegetation Growth</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Asphalt Paved Underneath</i>					
Pier Protection								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 70%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Approaches								
Pavement								
Asphalt	100%	Now	\$11,800	2034	\$236,500	4	\$7,300	
			<i>Cracks, Extent : Severe, Area Affected : 25%</i>					
			<i>Location : Both Approaches</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations On Both Approaches</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CLINTONVILLE STREET BELT SYSTEM - CROSS ISLAND

Asset # : 15409

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete	100%	4+	\$7,500	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%			LIFE		**		
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Cast Iron Railing</i>								
Sidewalks								
Concrete	100%	4+	\$3,800	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Stem,Solid Pier								
Concrete	100%	4+	\$24,400	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Near West End Of South Fascia</i>								
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : At East And West Ends</i>								
<i>Explanation : Limited Access On 70 Percent Area, Masonry Granite Facing At Ends.</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CLINTONVILLE STREET BELT SYSTEM - CROSS ISLAND

Asset # : 15409

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%	4+	\$600	2053		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Cast Iron	100%	0-2	\$10,500	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$4,300
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Cast Iron Railing</i>								
<hr/>								
Sidewalks								
Concrete	100%			2038		**	5	\$3,900
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Asphalt	100%	4+	\$4,600	2034	\$46,100		5	\$300
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Concrete	100%			LIFE		**	5	\$32,500
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CLOVE ROAD SIRT SOUTH SHORE
Address : CLOVE ROAD BET. HILLCREST TERR. AND GILES PLACE
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0258.000 / 15012 **Yr Built/Renovated** :
Area Sq Ft : 5,237 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249490

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$41,700		\$2,000	\$8,100
Total	\$41,700		\$2,000	\$8,100
Importance Code A	\$7,300		\$2,000	
Importance Code B	\$2,100			
Importance Code C	\$32,300			\$8,100
Total	\$41,700		\$2,000	\$8,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CLOVE ROAD SIRT SOUTH SHORE
Asset # : 15012

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$2,100	LIFE				**
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations On Header Blocks</i> <i>Missing/Damaged Seal, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations On Header Block Edges</i> <i>Other Observation, Extent : Light, Area Affected : 15%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Scaling</i>								
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Walls Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE				**
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Southwest Wingwall</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Southwest Wingwall</i>								
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE				**
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Railway Tracks</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CLOVE ROAD SIRT SOUTH SHORE
Asset # : 15012

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Feature Crossed								
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%	4+	\$29,500	2044	**	4	\$8,000	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Along Slab Edges</i>								
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Corner</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%	4+	\$4,200	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 1%</i>								
<i>Location : Southeast Approach</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind W Beam</i>								
Sidewalks								
Concrete	100%	4+	\$2,800	LIFE	**			
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northeast Approach And Random Locations</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southwest Approach</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CLOVE ROAD SIRT SOUTH SHORE
Asset # : 15012

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Along Steel Face</i>					
Railings/Parapets								
Concrete	100%			2044		**	4	\$3,600
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE		**	2-8	\$8,000
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : North Parapet</i>					
			<i>Explanation : Chain Link Fence On Top Of Concrete Parapet Throughout. Vegetation Growth</i>					
Sidewalks								
Concrete	100%			2040		**	5	\$3,900
			<i>Cracks, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling</i>					
Wearing Surface								
Concrete	100%			2044		**	5	\$16,300
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Along Pier Line And Random Locations</i>					
			<i>Other Observation, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling</i>					
Superstructure								
Deck,Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CLOVE ROAD SIRT SOUTH SHORE
Asset # : 15012

Bridge Structure		Current Repair		Future Replacement		Maintenance			
System	Component	% of	Fail Date	Estimated Cost	Year	Estimated Cost	Cycle	Estimated Cost	Priority
	Type	Total	(Years)		FY		(Yrs)		
Superstructure									
	Primary Member								
	Not Accessible	100%							
	Secondary Member								
	Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : COHANCY STREET BELT SYSTEM - SOUTHERN PARKWAY
Address : COHANCY STREET OVER BELT PARKWAY BTWN N CONDUIT AVE & MIA MEM HWY
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0382.000 / 15402 **Yr Built/Renovated** :
Area Sq Ft : 6,213 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 21-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231570

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$203,300	
Total	\$203,300	
Importance Code A	\$203,300	
Total	\$203,300	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$74,400		\$2,300	
Total	\$74,400		\$2,300	
Importance Code A			\$200	
Importance Code B	\$45,900			
Importance Code C	\$28,500		\$2,200	
Total	\$74,400		\$2,300	



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
COHANCY STREET BELT SYSTEM - SOUTHERN PARKWAY

Asset # : 15402

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$1,100	LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 40%</i>								
<i>Location : Both Abutment Joints</i>								
<i>Explanation : Worn Out Filler</i>								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE			**	
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Northwest And Southeast Wingwalls</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Paving Underneath</i>								
Pier Protection								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$16,000	2042		**	4	\$23,400
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On Both Approaches</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On North Approach</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 60%</i>								
<i>Location : Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
COHANCY STREET BELT SYSTEM - SOUTHERN PARKWAY

Asset # : 15402

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								
Sidewalks								
Concrete	100%	4+	\$3,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : South Approach</i> <i>Explanation : Total Of 2 Scuppers</i>								
Piers								
Stem,Solid Pier								
Concrete	100%	2-4	\$44,800	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Delaminations, Extent : Light, Area Affected : 2%</i> <i>Location : South Face Of Pier</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i> <i>Location : South Face</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout With Severe Cases On South Face</i> <i>Other Observation, Extent : N/A, Area Affected : 60%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							

Deck Elements

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
COHANCY STREET BELT SYSTEM - SOUTHERN PARKWAY

Asset # : 15402

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Cracks, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout								
Rust Stains, Extent : Light, Area Affected : 50%								
Location : Random Locations Throughout								
Spalling, Extent : Light, Area Affected : 2%								
Location : Random Locations Throughout								
<hr/>								
Railings/Parapets								
Cast Iron	100%			LIFE		**		
Corrosion, Extent : Light, Area Affected : 2%								
Location : Random Locations Throughout								
Other Observation, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout								
Explanation : Paint Peeling								
Steel	100%			LIFE		**	2-8	\$4,600
Rust Stains, Extent : Light, Area Affected : 20%								
Location : Random Locations Throughout								
Other Observation, Extent : N/A, Area Affected : 100%								
Location : Throughout								
Explanation : Chain Link Fence Attached To Cast Iron Railing								
<hr/>								
Sidewalks								
Concrete	100%			2038		**	5	\$4,400
Cracks, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$8,900	2042		**	5	\$11,800
Cracks, Extent : Light, Area Affected : 15%								
Location : Random Locations Throughout								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Concrete	100%	4+	\$203,300	LIFE		**	5	\$46,200
Cracks, Extent : Light, Area Affected : 5%								
Location : Random Locations Throughout								
Efflorescence, Extent : Moderate, Area Affected : 5%								
Location : Random Locations Throughout								
Other Observation, Extent : N/A, Area Affected : 10%								
Location : Along Longitudinal Joints On Both Spans								
Explanation : Limited Access On 80 Percent Of Area. Covered With Wire Mesh.								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CONEY ISLAND AVE. BRIDGE
Address : CONEY ISLAND AVE.
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0169.000 / 13577 **Yr Built/Renovated** :
Area Sq Ft : 20,600 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 18-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231380

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$141,300	\$461,800
Total	\$141,300	\$461,800
Importance Code A		\$257,900
Importance Code B	\$88,200	\$203,900
Importance Code C	\$53,000	
Total	\$141,300	\$461,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$126,500		\$46,800	
Total	\$126,500		\$46,800	
Importance Code A	\$30,900		\$26,400	
Importance Code B	\$2,700		\$20,400	
Importance Code C	\$92,900			
Total	\$126,500		\$46,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
CONEY ISLAND AVE. BRIDGE
Asset # : 13577

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$2,700	LIFE		**		
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Both Abutments</i>					
Mat (scour & erosion) Earth	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%	2-4	\$88,200	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout On Both Abutments</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : South Abutment</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 20%</i>					
			<i>Location : Around Corners And In The Middle</i>					
			<i>Explanation : Masonry Facing</i>					
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	5%	4+	\$33,300	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Wingwall Consists Of Concrete With Masonry Facing Throughout. Joint Mortar Missing/ Eroded</i>					
Concrete	95%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CONEY ISLAND AVE. BRIDGE
Asset # : 13577

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Belt Parkway Underneath The Bridge</i>								
Approaches								
Pavement								
Concrete	100%			2042		**	4	\$27,200
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout West Side</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%	4+	\$26,300	LIFE		**	5	\$5,100
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Approach</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Approach</i>								
<i>Explanation : Uneven</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042		**	4	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both East And West Parapets</i>								
<i>Explanation : Steel Fence On Top Of Concrete Parapet</i>								
Steel	100%			LIFE		**		
Sidewalks								
Concrete	100%	4+	\$53,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Southeast Corner</i>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CONEY ISLAND AVE. BRIDGE
Asset # : 13577

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam Steel	100%			LIFE	**	2-8	\$124,800	
Pier, Columns Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stone Facing</i>								
Brngs, Ancr Blts, Pads Elastomeric	100%			2053	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 1 And 3</i>								
<i>Explanation : Elastomeric Bearing (Expansion Bearing)</i>								
Steel	100%			LIFE	**	2-8	\$1,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Pier 2</i>								
<i>Explanation : Steel Bearing Assembly (Fixed Bearing)</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Median								
Concrete	100%			LIFE	**	5	\$3,400	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2042	**	4	\$13,800	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Concrete Parapet With Steel Fence On Top</i>								
Steel	100%			LIFE	**	2-8	\$12,700	
Sidewalks								
Concrete	100%	4+	\$24,600	2038	**	5	\$4,800	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$26,000	2042	**	5	\$40,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Near Cold Joints At Piers</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CONEY ISLAND AVE. BRIDGE
Asset # : 13577

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure Deck, Structural Concrete	100%			LIFE	**	5	\$18,000	
<i>Corrosion, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout Stay In Place Forms</i> <i>Other Observation, Extent : N/A, Area Affected : 95%</i> <i>Location : Throughout Except Bay Along Centerline Of Bridge</i> <i>Explanation : 95 Percent Is Not Accessible Because Of Stay In Place Forms</i>								
Primary Member Steel	100%			LIFE	**	2-8	\$380,800	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								
Secondary Member Steel	100%			LIFE	**	2-8	\$319,000	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CONGRESS STREET 278I (B.Q.E.)
Address : CONGRESS ST OVER BKLYN QNS EXPWY BET. HENRY ST & COLUMBIA ST
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0304.000 / 15062 **Yr Built/Renovated** : 1952 /
Area Sq Ft : 4,856 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230390

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,100		\$12,700	\$9,600
Total	\$2,100		\$12,700	\$9,600
Importance Code A	\$2,100		\$100	
Importance Code C			\$12,600	\$9,600
Total	\$2,100		\$12,700	\$9,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
CONGRESS STREET 278I (B.Q.E.)
Asset # : 15062

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Brick Veneer	100%			LIFE			**	
			<i>Other Observation, Extent : Moderate, Area Affected : 80%</i>					
			<i>Location : Northwest Wingwall</i>					
			<i>Explanation : Vegetation Growth</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$25,200
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Northwest Approach</i>					
Embankment								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CONGRESS STREET 278I (B.Q.E.)
Asset # : 15062

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Northwest Approach</i>								
<i>Explanation : Steel Fence With Vegetation Growth</i>								
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Concrete	100%			2044	**	4		
Steel	100%			LIFE	**	2-8	\$5,500	
<i>Other Observation, Extent : Light, Area Affected : 40%</i>								
<i>Location : North Chain Link Fence</i>								
<i>Explanation : Vegetation Growth On Chain Link Fence</i>								
Sidewalks								
Concrete	100%			2040	**	5	\$3,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044	**	5	\$19,100	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CONGRESS STREET 278I (B.Q.E.)
Asset # : 15062

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CONRAIL NE REG BRIDGE MELROSE AVE/CONRAIL PT MORRIS
Address : MELROSE-WEBSTER,E163 TO 165 ST
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0054.000 / 2661 **Yr Built/Renovated** : 1897 /
Area Sq Ft : 37,481 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 03-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241110

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$51,000	\$809,600
Total	\$51,000	\$809,600
Importance Code A		\$371,000
Importance Code B		\$371,000
Importance Code C	\$51,000	\$67,700
Total	\$51,000	\$809,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$134,100		\$88,500	
Total	\$134,100		\$88,500	
Importance Code A	\$54,100		\$38,100	
Importance Code B	\$16,300		\$37,200	
Importance Code C	\$63,700		\$13,200	
Total	\$134,100		\$88,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
CONRAIL NE REG BRIDGE MELROSE AVE/CONRAIL PT MORRIS
Asset # : 2661

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$1,800	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Masonry	100%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Masonry	100%	4+	\$8,100	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%	4+	\$23,800	2042		**	4	\$14,000
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Pavement Patching</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CONRAIL NE REG BRIDGE MELROSE AVE/CONRAIL PT MORRIS
Asset # : 2661

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	38%	4+	\$7,800	2042		**	4	\$9,700
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	62%			2042		**	4	\$14,500
Steel	100%			LIFE		**		
Sidewalks								
Concrete	100%	4+	\$8,100	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Pier,Columns								
Concrete	100%			LIFE		**		
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Water Stains</i>					
Stem,Solid Pier								
Masonry	100%	4+	\$14,400	LIFE		**		
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Efflorescence Staining</i>					
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**	2-8	\$10,300
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CONRAIL NE REG BRIDGE MELROSE AVE/CONRAIL PT MORRIS
Asset # : 2661

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$18,500	LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Median								
Concrete	35%	4+	\$5,700	LIFE		**	5	\$1,400
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	65%			LIFE		**	5	\$1,400
<hr/>								
Railings/Parapets								
Concrete	20%	4+	\$13,000	2042		**	4	\$8,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	80%			2042		**	4	\$12,900
Steel	100%			LIFE		**	2-8	\$11,700
<i>Corrosion, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Sidewalks								
Concrete	12%	4+	\$23,800	2038		**	5	\$13,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	88%			2038		**	5	\$26,500
<hr/>								
Wearing Surface								
Asphalt	100%			2034			5	
Concrete	100%	4+	\$51,000	2042		**	5	\$67,700
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout Along The Curbs</i>								
<i>Explanation : Total Of 14 Scuppers</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CONRAIL NE REG BRIDGE MELROSE AVE/CONRAIL PT MORRIS
Asset # : 2661

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$36,600	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stay-in-place Forms - Good Condition</i>								
Joints								
Steel	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$692,900	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$580,400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CORTELYOU ROAD BMT SUBWAY, BRIGHTON
Address : CORTELYOU ROAD BET. E16TH STREET AND MARLBOROUGH ROAD
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0300.000 / 15058 **Yr Built/Renovated** :
Area Sq Ft : 3,373 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 21-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243110

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$40,200	\$40,200
Total	\$40,200	\$40,200
Importance Code A	\$40,200	\$40,200
Total	\$40,200	\$40,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$180,400		\$9,800	\$8,100
Total	\$180,400		\$9,800	\$8,100
Importance Code A	\$71,700		\$7,400	
Importance Code B	\$63,700		\$2,400	
Importance Code C	\$45,000			\$8,100
Total	\$180,400		\$9,800	\$8,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

**DEPARTMENT OF TRANSPORTATION - 841
CORTELYOU ROAD BMT SUBWAY, BRIGHTON**

Asset # : 15058

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	100%			LIFE		**		
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Station Platforms</i>					
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Station Platforms</i>					
Piles								
Not Accessible	100%							
Walls								
Concrete	5%	4+	\$4,200	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 75%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Vegetation Growth</i>					
Concrete	95%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
CORTELYOU ROAD BMT SUBWAY, BRIGHTON**

Asset # : 15058

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	100%	4+	\$32,200	2044	**	4	\$22,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Joints, Both Approaches</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Rust Stains</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$155,400	
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$102,100	
Stem,Solid Pier								
Concrete	100%	4+	\$21,500	LIFE	**			
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Below The Station Platform</i>								
<i>Explanation : Concrete Wall</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Steel	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
CORTELYOU ROAD BMT SUBWAY, BRIGHTON**

Asset # : 15058

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Rust Stains</i>								
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$2,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Fence</i>								
Sidewalks								
Concrete	100%	4+	\$8,600	2040	**	5	\$1,700	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044	**	5	\$16,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$7,400	
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Grid Deck</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$106,900	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$5,500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CROPSEY AVENUE BELY SYSTEM SHORE PARKWAY
Address : CROPSEY AVE OVER BELT PARKWAY BET. BAY 50TH & BAY 52ND STREETS
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0249.000 / 14989 **Yr Built/Renovated** :
Area Sq Ft : 12,106 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 20-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231340

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$531,700	\$61,900
Total	\$531,700	\$61,900
Importance Code A		\$61,900
Importance Code B	\$531,700	
Total	\$531,700	\$61,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$100,500		\$8,600	
Total	\$100,500		\$8,600	
Importance Code A	\$24,000		\$6,400	
Importance Code B	\$5,500		\$2,200	
Importance Code C	\$71,100			
Total	\$100,500		\$8,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE BELY SYSTEM SHORE PARKWAY

Asset # : 14989

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$6,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Backwall Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$5,500	LIFE		**		
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%	4+	\$7,300	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Stem (breastwall) Concrete	100%	4+	\$362,400	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Center Stem</i> <i>Explanation : 80 Percent Concrete</i>								
Masonry	100%	4+	\$86,100	LIFE		**		
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Outer Edge Of Stem</i> <i>Explanation : 20 Percent Masonry</i>								
Wingwalls								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE BELY SYSTEM SHORE PARKWAY

Asset # : 14989

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Masonry	100%	4+	\$10,000	LIFE	**			
			<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Paved Roadway</i>					
Pier Protection								
Concrete	100%	4+	\$83,200	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>					
			<i>Location : West Face Of Barrier</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Approaches								
Pavement								
Concrete	100%	4+	\$1,900	2043	**	4	\$500	
			<i>Cracks, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE BELY SYSTEM SHORE PARKWAY

Asset # : 14989

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Median								
Concrete	100%	4+	\$3,000	LIFE	**	5	\$600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Corner</i>								
<i>Explanation : Vegetation Growth</i>								
Sidewalks								
Concrete	100%	2-4	\$1,400	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Corner</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Corner</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$143,100	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$43,600	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Over With Asphalt</i>								
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE BELY SYSTEM SHORE PARKWAY

Asset # : 14989

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Median								
Concrete	100%	4+	\$7,100	LIFE		**	5	\$1,400
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$5,400
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Steel Railing</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$14,000	2039		**	5	\$2,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$43,700	2043		**	5	\$28,100
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Severe Cases On Northbound Roadway</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Underside Covered With Stay In Place Forms</i>								
<hr/>								
Joints								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Longitudinal Joint Along Median</i>								
<hr/>								
Primary Member								
Steel	100%			LIFE		**	2-8	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE BELY SYSTEM SHORE PARKWAY

Asset # : 14989

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure Secondary Member Steel	100%			LIFE	**	2-8	\$11,200	
<i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CROPSEY AVENUE NORTHBOUND CONEY ISLAND CREEK
Address : CROPSEY AVE NB OVER CONEY ISLAND CREEK
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0375.000 / 15393 **Yr Built/Renovated** :
Area Sq Ft : 9,404 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240302

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$253,900
Total		\$253,900
Importance Code A		\$253,900
Total		\$253,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$75,200	\$400	\$25,700	
Total	\$75,200	\$400	\$25,700	
Importance Code A	\$29,400	\$400	\$25,700	
Importance Code C	\$45,700			
Total	\$75,200	\$400	\$25,700	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE NORTHBOUND CONEY ISLAND CREEK

Asset # : 15393

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals Not Accessible	100%						
Backwall Not Accessible	100%						
Brngs,Ancr Blts,Pads Not Accessible	100%						
Footings Not Accessible	100%						
Joint with Deck Generic	100%			LIFE			**
Mat (scour & erosion) Not Accessible	100%						
Stem (breastwall) Not Accessible	100%						
Walls							
Concrete	100%	4+	\$9,400	LIFE			**
<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Joints Missing, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Piles							
Not Accessible	100%						
Walls							
Masonry	100%			LIFE			**
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
<i>Location : Throughout</i>							
<i>Explanation : No Access To West Side</i>							
Feature Crossed							
Bank Protection							
Riprap	100%			LIFE			**
Mat (scour & erosion)							
Stream Bed	100%			LIFE			**
Pier Protection							
Timber	100%			LIFE			**

Approaches

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE NORTHBOUND CONEY ISLAND CREEK
Asset # : 15393

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%	Now	\$33,200	2042	**	4	\$19,500	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Corner Of North Approach</i>								
<hr/>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Of Both Approaches</i>								
<i>Explanation : Curb Is Only On West Side</i>								
<hr/>								
Embankment								
Not Accessible	100%							
<hr/>								
Guide Railing								
Concrete	100%			2042	**	4	\$1,700	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout On East Side</i>								
Steel	100%			LIFE	**	2-8	\$1,200	
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Steel	80%	2-4	\$4,500	LIFE	**			
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Severe, Area Affected : 5%</i>								
<i>Location : At The Base Of Railing Posts Throughout</i>								
Steel	20%			LIFE	**			
<hr/>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout On East Side</i>								
<hr/>								
Piers								
Stem,Solid Pier								
Not Accessible	100%							
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE NORTHBOUND CONEY ISLAND CREEK
Asset # : 15393

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion) Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stream Bed</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing Concrete	100%			2046	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout On East Side</i>								
Steel	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout On East Side</i>								
Railings/Parapets								
Concrete	100%			2042	**	4	\$1,600	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On Span 1 And 3</i>								
Masonry	100%			2042	**	5	\$800	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing</i>								
Steel	100%	2-4	\$14,400	LIFE	**	2-8	\$5,400	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 5%</i>								
<i>Location : At Base Of Railing Posts Throughout On East Side</i>								
Sidewalks								
Concrete	100%	4+	\$4,600	2038	**	5	\$1,900	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout East Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near North Pier On East Side</i>								
Wearing Surface								
Concrete	100%	4+	\$7,900	2042	**	5	\$26,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE NORTHBOUND CONEY ISLAND CREEK
Asset # : 15393

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Scupper								
Cast Iron	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Total Of 4 Scuppers</i>							
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%			LIFE		**		
Primary Member								
Steel	100%			LIFE		**	2-8	\$474,200
	<i>Corrosion, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout On Overhang Brackets</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 80%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Limited Access</i>							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CROPSEY AVENUE SOUTHBOUND CONEY ISLAND CREEK
Address : CROPSEY AVE & CONEY ISLAND CREEK BET BAY 54TH ST AND HART PLACE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0358.000 / 15372 **Yr Built/Renovated** :
Area Sq Ft : 8,976 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 07-Jul-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240301

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$12,300		\$200	\$300
Total	\$12,300		\$200	\$300
Importance Code A	\$12,300		\$200	\$300
Total	\$12,300		\$200	\$300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE SOUTHBOUND CONEY ISLAND CREEK
Asset # : 15372

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%			2041		**	4	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Both Approaches</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Curbs Only On Northeast And Southeast Corners</i>					
Embankment								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE SOUTHBOUND CONEY ISLAND CREEK

Asset # : 15372

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Guide Railing								
Concrete	100%	4+	\$1,000	2041		**	4	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Corner</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Northwest Corner</i>								
Steel	100%			LIFE		**	2-8	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Northwest And Southwest Corner</i>								
<i>Explanation : Railing On Top Of Concrete Guide Rail</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Masonry	100%	4+	\$2,300	2041		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northwest And Southwest Corner</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
Steel	100%	2-4	\$2,200	LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Base Of The Steel Posts On Northwest And Southwest Corner</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Both Approaches</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southwest Approach</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROPSEY AVENUE SOUTHBOUND CONEY ISLAND CREEK
Asset # : 15372

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing								
Concrete	100%	4+	\$2,400	2045		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Corner</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Northwest Corner</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Northwest And Southwest Corner</i>								
<i>Explanation : Railing On Top Of Concrete Guide Rail</i>								
Railings/Parapets								
Concrete	100%			2041		**	4	\$600
Masonry	100%	4+	\$2,400	2041		**	5	\$400
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On West Side Of Span 1 And 3</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
Steel	100%	2-4	\$2,000	LIFE		**	2-8	\$5,900
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Base Of Steel Posts</i>								
Wearing Surface								
Concrete	100%			2041		**	5	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : In Span 2</i>								
<i>Explanation : 4 Scuppers</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%			LIFE		**		
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CROSS BAY BLVD. BRIDGE CONDUIT BLVD
Address : CROSS BAY BLVD.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0160.000 / 13568 **Yr Built/Renovated** :
Area Sq Ft : 17,000 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2248039

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$336,500
Total		\$336,500
Importance Code A		\$168,300
Importance Code B		\$168,300
Total		\$336,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$63,100		\$36,300	
Total	\$63,100		\$36,300	
Importance Code A	\$45,100		\$16,900	
Importance Code B	\$2,300		\$16,900	
Importance Code C	\$15,700		\$2,600	
Total	\$63,100		\$36,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROSS BAY BLVD. BRIDGE CONDUIT BLVD
Asset # : 13568

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,300	LIFE		**		
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i>								
<i>Location : South Joint</i>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Stem (breastwall)								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Paving Underneath</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROSS BAY BLVD. BRIDGE CONDUIT BLVD
Asset # : 13568

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Approaches								
Pavement								
Concrete	100%			2042		**	4	\$47,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southbound Lane Of South Approach Near Joint</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$9,200	LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 20%</i>								
<i>Location : Northeast Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	2-4	\$18,200	2042		**	4	\$11,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout Outside Fascia</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Near Northwest Abutment</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Piers

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROSS BAY BLVD. BRIDGE CONDUIT BLVD
Asset # : 13568

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Pier,Columns Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 15%</i>								
<i>Location : On Both Fascias</i>								
<i>Explanation : Limited Access On 50 Percent Of Area. Fascia Columns Are Concrete With Cut Stone Masonry Facing - Veneer</i>								
Brngs,Ancr Blts,Pads Elastomeric	100%			2053		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Median Concrete	100%			LIFE		**	5	\$1,400
Railings/Parapets Concrete	100%	4+	\$17,800	2042		**	4	\$7,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout Outside Fascia</i>								
<i>Delaminations, Extent : Light, Area Affected : 1%</i>								
<i>Location : Near Pier On West Side</i>								
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Near Northeast Abutment</i>								
Steel	100%			LIFE		**	2-8	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROSS BAY BLVD. BRIDGE CONDUIT BLVD
Asset # : 13568

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2038	**	5	\$5,100	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2042	**	5		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$18,700	
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Entire Deck Except At The Overhangs</i>								
<i>Explanation : Concrete Deck With Stay-In-Place Metal Forms</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$314,300	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$263,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CROSS BAY BOULEVARD BRIDGE BELT SYSTEM --SHORE PARKWAY
Address : OVER BELT SHORE PARKWAY
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0153.000 / 13516 **Yr Built/Renovated** : 1941 /
Area Sq Ft : 23,205 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231559

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$107,400	\$986,900
Total	\$107,400	\$986,900
Importance Code A		\$459,400
Importance Code B	\$107,400	\$459,400
Importance Code C		\$68,200
Total	\$107,400	\$986,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$337,600		\$93,100	
Total	\$337,600		\$93,100	
Importance Code A	\$73,900		\$47,100	
Importance Code B	\$121,300		\$46,100	
Importance Code C	\$142,400			
Total	\$337,600		\$93,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
CROSS BAY BOULEVARD BRIDGE BELT SYSTEM --SHORE PARKWAY
Asset # : 13516

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	30%	4+	\$6,900	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	70%			LIFE		**		
Backwall								
Concrete	12%	4+	\$17,900	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Concrete	88%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	65%	4+	\$5,200	LIFE		**		
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Both Abutments</i>								
Generic	35%			LIFE		**		
Mat (scour & erosion)								
Generic	100%	4+	\$107,400	LIFE		**		
<i>Joints Missing, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stone Pavers In Front Slope And Earth On Sides</i>								
Pedestals								
Concrete	100%	4+	\$1,200	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Both Abutments</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : South Abutment, Southwest Corner</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : South Abutment, Southwest Corner</i>								
Stem (breastwall)								
Concrete	100%	2-4	\$33,400	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Exposed Rebars At North Abutment</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : North Abutment</i>								
Wingwalls								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROSS BAY BOULEVARD BRIDGE BELT SYSTEM --SHORE PARKWAY
Asset # : 13516

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost		
Wingwalls									
Footings									
Not Accessible	100%								
Mat (scour & erosion)									
Generic	100%			LIFE	**				
Piles									
Not Accessible	100%								
Walls									
Masonry: Stone	100%			LIFE	**				
Feature Crossed									
Mat (scour & erosion)									
Generic	100%			LIFE	**				
Pier Protection									
Concrete	100%			LIFE	**				
Approaches									
Pavement									
Concrete	100%	4+	\$35,900	2041	**	4	\$35,200		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>						
			<i>Location : Random Locations Throughout</i>						
			<i>Spalling, Extent : Light, Area Affected : 5%</i>						
			<i>Location : Random Locations Throughout</i>						
Curbs									
Concrete w/ Steel Face	100%	Now	\$19,800	LIFE	**				
			<i>Rust Stains, Extent : Light, Area Affected : 20%</i>						
			<i>Location : Random Locations Throughout</i>						
			<i>Settlement, Extent : Moderate, Area Affected : 10%</i>						
			<i>Location : South Approach</i>						
Embankment									
Earth	100%			LIFE	**				
Mat (scour & erosion)									
Earth	100%			LIFE	**				
Median									
Concrete	100%			LIFE	**	5			
			<i>Rust Stains, Extent : Light, Area Affected : 20%</i>						
			<i>Location : Random Locations Throughout</i>						
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
			<i>Location : Throughout</i>						
			<i>Explanation : Concrete Median With Steel Face</i>						
Pavement Base									
Not Accessible	100%								
Railings/Parapets									
Steel	100%			LIFE	**				
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
			<i>Location : Throughout</i>						
			<i>Explanation : Chain Link Fence Behind Steel Railing</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROSS BAY BOULEVARD BRIDGE BELT SYSTEM --SHORE PARKWAY
Asset # : 13516

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%	4+	\$30,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Isolated Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Both Approaches</i>								
<hr/>								
Piers								
Pier,Columns								
Concrete	100%	4+	\$49,200	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Pier</i>								
<i>Explanation : Pier Column Is 65 Percent Concrete And 35 Percent Stone Masonry</i>								
Masonry	100%	4+	\$14,600	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Missing Joint/ Mortar</i>								
<hr/>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**	2-8	\$16,500
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Median								
Concrete	100%	4+	\$40,100	LIFE		**	5	\$27,900
<i>Rust Stains, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near End Approach</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Median With Steel Face</i>								
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$7,500
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind Railing</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROSS BAY BOULEVARD BRIDGE BELT SYSTEM --SHORE PARKWAY
Asset # : 13516

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%	4+	\$13,000	2037	**	5	\$3,600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Isolated Locations</i>								
Wearing Surface								
Concrete	100%	4+	\$30,800	2041	**	5	\$68,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Approach</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Southbound Lane</i>								
<i>Explanation : Concrete Patches</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stay In Place Forms Covering The Deck</i>								
Joints								
Generic	100%	4+	\$14,800	LIFE	**			
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 35%</i>								
<i>Location : Random Locations Throughout</i>								
Primary Member								
Steel	2%	2-4	\$6,000	LIFE	**	2-8	\$429,000	
<i>Loss of Section, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Near North Center Pier</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Bird Nesting</i>								
Steel	98%			LIFE	**	2-8	\$429,000	
Secondary Member								
Steel	2%	Now	\$19,000	LIFE	**	2-8	\$359,400	
<i>Loss of Section, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Near North Center Pier</i>								
Steel	98%			LIFE	**	2-8	\$359,400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CROTONA AVENUE BRONX PELHAM PARKWAY
Address : CROTONA AVE & BX PELHAM PKWY
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0372.000 / 15390 Yr Built/Renovated :
Area Sq Ft : 7,636 Project Type : HIGHWAY BRIDGES
Date of Survey : 16-Mar-2022 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2242030

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$62,500	\$294,300
Total	\$62,500	\$294,300
Importance Code A	\$62,500	\$113,500
Importance Code C		\$180,800
Total	\$62,500	\$294,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$56,900		\$2,900	\$3,100
Total	\$56,900		\$2,900	\$3,100
Importance Code A			\$100	
Importance Code C	\$56,900		\$2,800	\$3,100
Total	\$56,900		\$2,900	\$3,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROTONA AVENUE BRONX PELHAM PARKWAY

Asset # : 15390

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Stem (breastwall)								
Masonry: Granite	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE	**			
			<i>Efflorescence, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE	**			
Approaches								
Pavement								
Asphalt	100%	4+	\$18,100	2034	\$180,800	4	\$5,600	
			<i>Cracks, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Granite	100%			LIFE	**			
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%	4+	\$10,200	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 8%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Near Curb line</i>					
Piers								
Stem,Solid Pier								
Granite	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROTONA AVENUE BRONX PELHAM PARKWAY
Asset # : 15390

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
Railings/Parapets								
Granite	100%			LIFE	**			
Steel	100%			LIFE	**	2-8	\$3,900	
Sidewalks								
Concrete	11%	4+	\$21,800	2038	**	5	\$2,800	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	89%			2038	**	5	\$5,500	
Wearing Surface								
Asphalt	14%	4+	\$6,800	2034	\$6,800	5	\$3,100	
			<i>Spalling, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Map Cracks</i>					
Asphalt	86%			2034	\$41,700	5	\$6,200	
Superstructure								
Primary Member								
Concrete	5%	4+	\$62,500	LIFE	**	5	\$56,800	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Fascia</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 2%</i>					
			<i>Location : Northeast Side</i>					
			<i>Explanation : Large Hollow Area</i>					
Concrete	95%			LIFE	**	5	\$56,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CROWN STREET FRANKLIN SHUTTLE
Address : CROWN STREET BET. FRANKLIN AVE AND WASHINGTON AVE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0332.000 / 15191 **Yr Built/Renovated** : 1925 /
Area Sq Ft : 3,850 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243230

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$5,800	\$1,900		\$8,100
Total	\$5,800	\$1,900		\$8,100
Importance Code A				
Importance Code C	\$5,800	\$1,900		\$8,100
Total	\$5,800	\$1,900		\$8,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROWN STREET FRANKLIN SHUTTLE
Asset # : 15191

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Generic	100%			LIFE	**		
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Not Accessible	100%						
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Piles							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Feature Crossed							
Mat (scour & erosion)							
Not Accessible	100%						
Pier Protection							
Not Accessible	100%						
Approaches							
Pavement							
Concrete	100%			2041	**	4	\$16,200
			<i>Cracks, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Random Locations Throughout</i>				
Curbs							
Concrete w/ Steel Face	100%			LIFE	**		
			<i>Rust Stains, Extent : Light, Area Affected : 25%</i>				
			<i>Location : Random Locations Throughout</i>				
Embankment							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Pavement Base							
Not Accessible	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROWN STREET FRANKLIN SHUTTLE
Asset # : 15191

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South Side Only</i>								
<i>Explanation : Chain Link Fence Behind Steel Railing</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam Not Accessible	100%							
Pier,Columns Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets Steel	100%			LIFE	**	2-8	\$1,200	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On South Side Only</i>								
<i>Explanation : Chain Link Fence Behind Steel Railing</i>								
Sidewalks Concrete	100%			2037	**	5	\$3,700	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface Concrete	100%			2041	**	5	\$11,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CROWN STREET FRANKLIN SHUTTLE
Asset # : 15191

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DEPOT PLACE BRIDGE DEPOT PLACE/CONRAIL HUDSON DV
Address : METRO NORTH
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0008.000 / 2443 **Yr Built/Renovated** : 1983 /
Area Sq Ft : 30,192 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Oct-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2076640

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$481,100	\$1,026,100
Total	\$481,100	\$1,026,100
Importance Code A	\$61,700	\$298,800
Importance Code B	\$116,300	\$597,700
Importance Code C	\$303,100	\$129,600
Total	\$481,100	\$1,026,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$125,900		\$91,600	\$8,000
Total	\$125,900		\$91,600	\$8,000
Importance Code A	\$26,800		\$31,700	\$8,000
Importance Code B	\$19,700		\$59,900	
Importance Code C	\$79,400			
Total	\$125,900		\$91,600	\$8,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
DEPOT PLACE BRIDGE DEPOT PLACE/CONRAIL HUDSON DV
Asset # : 2443

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
Feature Crossed								
Bank Protection								
Riprap	100%	Now	\$238,300	LIFE			**	
								<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 60%</i>
								<i>Location : Along West Fascia - Harlem River</i>
								<i>Erosion, Extent : Moderate, Area Affected : 40%</i>
								<i>Location : Along Bank Of Harlem River</i>
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Concrete	100%	4+	\$39,300	2041		**	4	\$14,900
								<i>Cracks, Extent : Light, Area Affected : 15%</i>
								<i>Location : Both Approaches</i>

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DEPOT PLACE BRIDGE DEPOT PLACE/CONRAIL HUDSON DV
Asset # : 2443

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete	100%	4+	\$7,100	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : More Severe At South Approach</i>								
Granite	100%			LIFE		**		
Embankment								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Earth	80%			LIFE		**		
Earth	20%	Now	\$5,800	LIFE		**		
<i>Erosion, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : South Approach Along Bank Of Harlem River</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041		**	4	
Steel	100%			LIFE		**		
Sidewalks								
Concrete	100%			LIFE		**		
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 1 Scupper</i>								
Piers								
Stem,Solid Pier								
Concrete	100%	4+	\$116,300	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Spall With Exposed Rebars</i>								
Brngs,Ancr Blts,Pads								
Steel	13%	4+	\$13,900	LIFE		**	2-8	\$16,000
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Under Leaky Deck Joints</i>								
Steel	87%			LIFE		**	2-8	\$16,000
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DEPOT PLACE BRIDGE DEPOT PLACE/CONRAIL HUDSON DV
Asset # : 2443

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Mat (scour & erosion)								
Riprap	100%	2-4	\$61,700	LIFE		**		
	<i>Other Observation, Extent : Severe, Area Affected : 20%</i>							
	<i>Location : Along Harlem River</i>							
	<i>Explanation : Broken/ Missing</i>							
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%	4+	\$6,800	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Piers 5, 6 And 7</i>							
	<i>Spalling, Extent : Moderate, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Granite	100%			LIFE		**		
	<i>Other Observation, Extent : Light, Area Affected : 1%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Vegetation Growth</i>							
Railings/Parapets								
Concrete	100%			2041		**	4	\$16,000
Steel	100%			LIFE		**	2-8	\$9,400
	<i>Rust Stains, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Steel Railing On Top Of Concrete Parapet On Both Sides. Also Chain-link Fence On Both Sides In The Spans Over Tracks, Total Length Approximately 125 Feet</i>							
Sidewalks								
Concrete	100%	4+	\$24,800	2037		**	5	\$4,100
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Wearing Surface								
Concrete	95%			2041		**	5	\$129,600
Concrete	5%	4+	\$2,400	2041		**	5	\$64,800
	<i>Cracks, Extent : Light, Area Affected : 50%</i>							
	<i>Location : Spans 1 To 5</i>							
	<i>Spalling, Extent : Light, Area Affected : 20%</i>							
	<i>Location : Near South End</i>							
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DEPOT PLACE BRIDGE DEPOT PLACE/CONRAIL HUDSON DV
Asset # : 2443

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$29,500	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Spans 5 To 11</i> <i>Explanation : Stay In Place Forms At Underdeck</i>								
Joints								
Generic	100%	2-4	\$12,900	LIFE	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Leakage, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 20%</i> <i>Location : Near South Abutment</i> <i>Explanation : Consists Of 20 Percent Precast Box Beam Girders And 80 Percent Steel Girders</i>								
Steel	100%			LIFE	**	2-8	\$558,200	
Secondary Member								
Steel	5%	2-4	\$12,900	LIFE	**	2-8	\$467,600	
<i>Corrosion, Extent : Light, Area Affected : 40%</i> <i>Location : Adjacent To Deck Joints</i> <i>Loss of Section, Extent : Light, Area Affected : 5%</i> <i>Location : Adjacent To Deck Joints</i>								
Steel	95%			LIFE	**	2-8	\$467,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DOUGLASTON PARKWAY LIRR PORT WASHINGTON BRANCH
Address : DOUGLASTON PKWY BET. 40TH AVE AND POPLAR STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0271.000 / 15025 **Yr Built/Renovated** :
Area Sq Ft : 6,120 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 05-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247170

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$71,500	\$80,400
Total	\$71,500	\$80,400
Importance Code B	\$71,500	
Importance Code C		\$80,400
Total	\$71,500	\$80,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$77,600		\$200	
Total	\$77,600		\$200	
Importance Code A	\$48,000		\$200	
Importance Code B	\$5,000			
Importance Code C	\$24,600			
Total	\$77,600		\$200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOUGLSTON PARKWAY LIRR PORT WASHINGTON BRANCH
Asset # : 15025

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%	Now	\$15,400	LIFE		**		
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Worse Cases On North Abutment</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$5,000	LIFE		**		
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Along Header Block On Both Abutments</i>								
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : On Both Sides With Worse Cases On South Abutment</i>								
<i>Explanation : Deck Is Lower Than Approach</i>								
Mat (scour & erosion)								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Pavers</i>								
Stem (breastwall)								
Concrete	100%	0-2	\$71,500	LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : North Abutment</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Timber	100%			2048		**		
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOUGLSTON PARKWAY LIRR PORT WASHINGTON BRANCH

Asset # : 15025

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railroad Tracks</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$18,800	2044		**	4	\$12,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout, Worst On South Approach</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind Steel Railings</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Piers								
Cap Beam								
Concrete	100%	4+	\$29,900	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOUGLSTON PARKWAY LIRR PORT WASHINGTON BRANCH

Asset # : 15025

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : On Track Side</i>						
		<i>Explanation : Railway Ballasts</i>						
Piles								
Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE	**			
		<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>						
		<i>Location : Throughout</i>						
Railings/Parapets Steel	100%			LIFE	**	2-8	\$7,100	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Chain Link Fence Behind Steel Railings</i>						
Sidewalks Concrete	100%			2040	**	5	\$6,100	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout, Worst In Northeast Side</i>						
Wearing Surface Concrete	100%	4+	\$5,800	2044	**	5	\$80,400	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Longitudinal And Transverse Cracks On Random Locations</i>						
Superstructure								
Deck,Structural Not Accessible	100%							
Primary Member Prestressed Concrete Box Beam	100%			LIFE	**			
		<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Along Beam Joints</i>						
		<i>Explanation : Rust Stains And Efflorescence</i>						
Secondary Member Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : E 103RD STREET PEDESTRIAN BRIDGE FDR DRIVE
Address : FROM E103RD STREET OVER FDR DR. BET. E102ND AND E105TH STREETS
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0284.000 / 15042 **Yr Built/Renovated** :
Area Sq Ft : 5,240 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 17-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2232180

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$503,700	\$503,700
Total	\$503,700	\$503,700
Importance Code A	\$131,900	\$131,900
Importance Code B	\$371,800	\$371,800
Total	\$503,700	\$503,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$294,200		\$52,300	
Total	\$294,200		\$52,300	
Importance Code A	\$110,000		\$14,200	
Importance Code B	\$174,600		\$37,300	
Importance Code C	\$9,500		\$800	
Total	\$294,200		\$52,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
E 103RD STREET PEDESTRIAN BRIDGE FDR DRIVE
Asset # : 15042

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Abutments</i>								
<i>Explanation : Walls Enclose Abutment</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$1,600
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$359,700
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$767,900
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout, Worst At Median Of FDR</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Bottom Of Steel Column</i>								
<i>Explanation : The Condition Of Base Plate Is Recorded With The Column</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E 103RD STREET PEDESTRIAN BRIDGE FDR DRIVE
Asset # : 15042

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%			2055		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$45,300
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	100%	0-2	\$9,500	2044		**	5	\$15,300
			<i>Cracks, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Scupper								
Cast Iron	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : At Both Ends Of Primary Span</i>					
			<i>Explanation : 2 Scuppers</i>					
Superstructure								
Deck, Structural								
Concrete	20%	0-2	\$22,100	LIFE		**	5	\$5,800
			<i>Exposed Reinforcement, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Under Deck Joints</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Under Deck Joints</i>					
Concrete	80%			LIFE		**	5	\$11,500
Joints								
Generic	100%			LIFE		**		
Primary Member								
Steel	100%			LIFE		**	2-8	\$124,500
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling On Concrete Encasement</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
E 103RD STREET PEDESTRIAN BRIDGE FDR DRIVE**

Asset # : 15042

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure Secondary Member Steel	100%			LIFE	**	2-8	\$574,200	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling On Concrete Encasement</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : E 177TH STREET AMTRAK - CSX
Address : E 177TH STREET OVER AMTRAK - CSX N.E OF WEST FARMS BUS DEPOT
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0311.000 / 15069 **Yr Built/Renovated** :
Area Sq Ft : 13,448 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 11-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241269

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$75,700		\$3,800	
Total	\$75,700		\$3,800	
Importance Code A	\$22,300		\$3,800	
Importance Code B	\$4,200			
Importance Code C	\$49,200			
Total	\$75,700		\$3,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E 177TH STREET AMTRAK - CSX
Asset # : 15069

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$4,200	LIFE			**	
			<i>Spalling, Extent : Severe, Area Affected : 5%</i>					
			<i>Location : Both Abutments</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Pavement And Railroad Tracks</i>					
Pier Protection								
Concrete	100%			LIFE			**	
Approaches								
Pavement								
Concrete	100%	Now	\$22,600	2044		**	4	\$13,300
			<i>Cracks, Extent : Light, Area Affected : 6%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : West Abutment</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E 177TH STREET AMTRAK - CSX
Asset # : 15069

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Curbs								
Concrete w/ Steel Face	6%	Now	\$4,300	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 100%</i>								
<i>Location : Both Approaches</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Concrete w/ Steel Face	94%			LIFE		**		
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%	0-2	\$5,800	LIFE		**	5	\$500
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout And East Side</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
Sidewalks								
Concrete	100%	Now	\$8,400	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Southeast Approach</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E 177TH STREET AMTRAK - CSX
Asset # : 15069

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Median								
Concrete	100%	4+	\$6,100	LIFE		**	5	\$2,500
<i>Rust Stains, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Adjacent To Steel Facing Along The Length</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Facing</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2044		**	4	\$7,000
Steel	100%			LIFE		**	2-8	\$15,600
<hr/>								
Sidewalks								
Concrete	100%			2040		**	5	\$10,300
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : South Travel Lane At Pavement Marking</i>								
<hr/>								
Wearing Surface								
Concrete	100%	Now	\$18,300	2044		**	5	\$24,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : E 78TH STREET PEDESTRIAN BRIDGE FDR DRIVE
Address : E78TH STREET OVER FDR DRIVE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0285.000 / 15043 **Yr Built/Renovated** :
Area Sq Ft : 2,032 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 17-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2232140

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$155,000	\$155,000
Total	\$155,000	\$155,000
Importance Code A	\$62,000	\$62,000
Importance Code B	\$93,000	\$93,000
Total	\$155,000	\$155,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$145,300		\$20,700	\$5,900
Total	\$145,300		\$20,700	\$5,900
Importance Code A	\$63,600		\$8,100	
Importance Code B	\$81,800		\$9,500	
Importance Code C			\$3,100	\$5,900
Total	\$145,300		\$20,700	\$5,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E 78TH STREET PEDESTRIAN BRIDGE FDR DRIVE
Asset # : 15043

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE			**	
Backwall								
Concrete	100%			LIFE			**	
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055			**	
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$1,300	LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : West Header</i>					
			<i>Explanation : Broken Header</i>					
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Concrete	100%			LIFE			**	
Stem (breastwall)								
Masonry	100%			LIFE			**	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$6,200
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E 78TH STREET PEDESTRIAN BRIDGE FDR DRIVE
Asset # : 15043

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets								
Steel	100%			LIFE	**			
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$239,800	
			<i>Rust Stains, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$438,800	
			<i>Rust Stains, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Steel	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$17,600	
			<i>Rust Stains, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	100%			2044	**	5	\$11,900	
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$4,500	
			<i>Rust Stains, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout Stay In Place Forms</i>					
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$48,300	
			<i>Rust Stains, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Paint Peeling</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
E 78TH STREET PEDESTRIAN BRIDGE FDR DRIVE**

Asset # : 15043

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$5,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : E. 12TH STREET BRIDGE
Address : E. 12TH STREET
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0163.000 / 13571 **Yr Built/Renovated** :
Area Sq Ft : 17,200 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 18-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231390

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$239,300	\$387,500
Total	\$239,300	\$387,500
Importance Code A		\$217,300
Importance Code B		\$170,200
Importance Code C	\$239,300	
Total	\$239,300	\$387,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$275,700	\$34,600	\$39,300	
Total	\$275,700	\$34,600	\$39,300	
Importance Code A	\$45,800		\$22,200	
Importance Code B	\$19,300		\$17,100	
Importance Code C	\$210,600	\$34,600		
Total	\$275,700	\$34,600	\$39,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
E. 12TH STREET BRIDGE
Asset # : 13571

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	Now	\$700	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Abutment</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : North Abutment</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : North Abutment</i>								
Backwall								
Concrete	100%			LIFE			**	
<i>Efflorescence, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2053			**	
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,500	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : At Concrete Headers</i>								
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : At Concrete Headers</i>								
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pedestals								
Concrete	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Stem (breastwall)								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : On Both Abutments</i>								
<i>Explanation : Concrete Stem With Masonry Facing</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E. 12TH STREET BRIDGE
Asset # : 13571

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	95%			LIFE			**	
Concrete	5%	4+	\$85,900	LIFE			**	
<i>Efflorescence, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Joints Missing, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Wingwall</i>								
<i>Explanation : Concrete Wingwall With Masonry Facing Throughout. Water Stains</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Belt Parkway And Earth</i>								
Approaches								
Pavement								
Concrete	98%			2042			**	4
Concrete	2%	0-2	\$153,400	2042			**	4
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Near South Abutment Joint</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%	4+	\$23,400	LIFE			**	5
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E. 12TH STREET BRIDGE
Asset # : 13571

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%	4+	\$32,300	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$108,700
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Pier, Columns								
Concrete	100%	4+	\$16,900	LIFE		**		
<i>Joints Missing, Extent : Light, Area Affected : 5%</i>								
<i>Location : West Center Pier</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : All Piers</i>								
<i>Explanation : Outer Face Finished With Stone Masonry</i>								
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$15,500	LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Median								
Concrete	100%	4+	\$6,300	LIFE		**	5	\$3,000
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$11,400

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E. 12TH STREET BRIDGE
Asset # : 13571

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%	4+	\$27,700	2038	**	5	\$2,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%			2042	**	5	\$69,100	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered With Stay In Place Forms</i>								
<hr/>								
Joints								
Generic								
	100%	4+	\$46,000	LIFE	**			
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : At Concrete Headers</i>								
<hr/>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$318,000	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Painted Throughout</i>								
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$266,400	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Painted Throughout</i>								
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : E. 165TH ST. BRIDGE / METRO-NORTH RR
Address : E. 165TH ST
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0166.000 / 13574 **Yr Built/Renovated** : 1897 /
Area Sq Ft : 16,400 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 03-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241630

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,365,600	\$2,313,500
Total	\$1,365,600	\$2,313,500
Importance Code C	\$1,365,600	\$2,313,500
Total	\$1,365,600	\$2,313,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$92,100	\$22,800	\$500	
Total	\$92,100	\$22,800	\$500	
Importance Code A	\$9,300		\$500	
Importance Code C	\$82,800	\$22,800		
Total	\$92,100	\$22,800	\$500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E. 165TH ST. BRIDGE / METRO-NORTH RR
Asset # : 13574

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE	**			
Masonry: Stone	100%			LIFE	**			
Approaches								
Pavement								
Asphalt	60%	2-4	\$95,300	2034	\$1,905,500	4	\$45,500	
<i>Cracks, Extent : Moderate, Area Affected : 35%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Asphalt	40%			2027	\$1,270,300	4	\$68,300	
Concrete	100%			2042	**	4		
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Median								
Concrete	100%			LIFE	**	5		
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	4+	\$28,700	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
E. 165TH ST. BRIDGE / METRO-NORTH RR
Asset # : 13574

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southwest Side</i>								
<i>Explanation : One Scupper</i>								
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<hr/>								
Median								
Concrete	100%	4+	\$4,400	LIFE		**	5	\$2,100
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2042		**	4	\$14,500
Steel	100%			LIFE		**	2-8	\$13,300
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$13,400	2038		**	5	\$2,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Asphalt	100%	2-4	\$40,800	2034	\$408,000		5	\$12,100
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 111TH ST. PEDESTRIAN BRIDGE FDR DRIVE
Address : E 111TH ST PED BRDG OVER FDR DR
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0336.000 / 15195 **Yr Built/Renovated** :
Area Sq Ft : 4,275 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2232190

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$82,100	\$242,400
Total	\$82,100	\$242,400
Importance Code A	\$82,100	\$56,400
Importance Code B		\$186,000
Total	\$82,100	\$242,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$77,000		\$25,000	\$100
Total	\$77,000		\$25,000	\$100
Importance Code A	\$35,100		\$6,400	
Importance Code B	\$38,100		\$18,700	
Importance Code C	\$3,800			\$100
Total	\$77,000		\$25,000	\$100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 111TH ST. PEDESTRIAN BRIDGE FDR DRIVE

Asset # : 15195

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Joint with Deck								
Generic	100%			LIFE			**	
Walls								
Concrete	100%			LIFE			**	
			<i>Cracking/Crumbling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Asphalt	100%			2033	\$5,100	4	\$200	
Pavement Base								
Not Accessible	100%							
Piers								
Pier,Columns								
Steel	90%			LIFE		2-8	\$267,800	
			<i>Corrosion, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Paint Peeling</i>					
Steel	10%	Now	\$34,000	LIFE		2-8	\$267,800	
			<i>Other Observation, Extent : Severe, Area Affected : 100%</i>					
			<i>Location : On East Side</i>					
			<i>Explanation : Temporary Timber Pier In Place</i>					
Stem,Solid Pier								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Peeling Paint</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	7%	0-2	\$400	2052			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	93%			2052			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 111TH ST. PEDESTRIAN BRIDGE FDR DRIVE
Asset # : 15195

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Steel	100%			LIFE	**	2-8	\$20,200	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Main Deck Above Traffic</i>								
<i>Explanation : Chain Link Fence On Both Sides</i>								
<hr/>								
Wearing Surface Concrete	100%	4+	\$3,800	2041	**	5	\$12,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains On Concrete</i>								
<hr/>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 2 Scuppers Observed</i>								
<hr/>								
Superstructure								
Deck,Structural Concrete	100%	0-2	\$82,100	LIFE	**	5	\$4,700	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Spalls Covered With Steel Wire Mesh</i>								
<hr/>								
Joints								
Steel	100%			LIFE	**			
<hr/>								
Primary Member Steel	5%	2-4	\$34,800	LIFE	**	2-8	\$52,700	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Steel	95%			LIFE	**	2-8	\$52,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
EAST 111TH ST. PEDESTRIAN BRIDGE FDR DRIVE**

Asset # : 15195

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Superstructure

Secondary Member

Concrete Encased Steel 100% 4+ \$4,000 2060 * *

Cracks, Extent : Light, Area Affected : 2%

Location : Random Locations Throughout

Spalling, Extent : Light, Area Affected : 2%

Location : Random Locations Throughout

Other Observation, Extent : Light, Area Affected : 2%

Location : Random Locations Throughout

Explanation : Rust

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.*

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 128TH ST. PEDESTRIAN BRIDGE 3RD AVENUE BRIDGE APPROACH
Address : EAST 128TH STREET AND 3RD AVE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0338.000 / 15197 **Yr Built/Renovated** :
Area Sq Ft : 4,545 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2246620

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$86,200	\$358,300
Total	\$86,200	\$358,300
Importance Code A	\$86,200	\$187,800
Importance Code B		\$170,500
Total	\$86,200	\$358,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$63,300		\$37,500	\$1,400
Total	\$63,300		\$37,500	\$1,400
Importance Code A	\$43,300		\$20,400	
Importance Code B			\$17,100	
Importance Code C	\$20,000			\$1,400
Total	\$63,300		\$37,500	\$1,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
EAST 128TH ST. PEDESTRIAN BRIDGE 3RD AVENUE BRIDGE APPROACH
Asset # : 15197

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Walls								
Concrete	100%	4+	\$10,100	LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Wall Consists Of 100% Brick.</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%			2041		**	4	\$2,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides</i>								
<i>Explanation : Concrete Sidewalks Serves As Approach.</i>								
Pavement Base								
Not Accessible	100%							
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$295,600
Pier, Columns								
Steel	100%			LIFE		**	2-8	\$490,900
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 128TH ST. PEDESTRIAN BRIDGE 3RD AVENUE BRIDGE APPROACH
Asset # : 15197

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Concrete	100%	4+	\$19,000	2041	**	4	\$15,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	90%			LIFE	**	2-8	\$21,500	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides Of Sloping Deck At All 3 Approaches</i>								
<i>Explanation : Chain Link Fence Behind Steel Posts</i>								
Steel	10%	Now	\$14,200	LIFE	**	2-8	\$21,500	
<i>Other Observation, Extent : Severe, Area Affected : 40%</i>								
<i>Location : East Girder Over 128th Street</i>								
<i>Explanation : Impact Damage To Primary Member Caused Bending And Shifting In Position Of Railing.</i>								
Wearing Surface								
Concrete	100%	Now	\$20,000	2041	**	5	\$13,300	
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered In Timber And Steel Mesh</i>								
Joints								
Steel	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Primary Member								
Steel	90%			LIFE	**	2-8	\$56,000	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	10%	Now	\$86,200	LIFE	**	2-8	\$56,000	
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : East Girder Over 128th Street</i>								
<i>Explanation : Impact Damage</i>								
Secondary Member								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered With Timber And Steel Mesh</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 129TH ST. PEDESTRIAN BRIDGE 3RD AVENUE BRIDGE RAMP
Address : NORTH SIDE OF E 129TH STREET OFF LEXINGTON AVENUE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0339.000 / 15198 **Yr Built/Renovated** :
Area Sq Ft : 960 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2246990

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$103,300
Total		\$103,300
Importance Code A		\$41,300
Importance Code B		\$62,000
Total		\$103,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$800		\$11,400	\$1,500
Total	\$800		\$11,400	\$1,500
Importance Code A			\$5,000	\$700
Importance Code B			\$6,300	
Importance Code C	\$800			\$800
Total	\$800		\$11,400	\$1,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 129TH ST. PEDESTRIAN BRIDGE 3RD AVENUE BRIDGE RAMP
Asset # : 15198

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Approaches								
Pavement								
Concrete	100%			2041	**	4	\$1,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides</i>								
<i>Explanation : Concrete Sidewalks Serves As Approach</i>								
Pavement Base								
Not Accessible	100%							
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$95,600	
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$178,500	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2041	**	4	\$1,400	
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$5,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Chain Link Fence</i>								
Wearing Surface								
Concrete	100%	4+	\$800	2041	**	5	\$2,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered With Timber And Steel Mesh</i>								
Joints								
Generic	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 129TH ST. PEDESTRIAN BRIDGE 3RD AVENUE BRIDGE RAMP
Asset # : 15198

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$13,300	
	<i>Corrosion, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$2,000	
	<i>Corrosion, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 70%</i>							
	<i>Location : Main Deck</i>							
	<i>Explanation : Secondary Member Consists Of 30 Percent Steel, 70 Percent Not Accessible From Timber Covering</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 144TH STREET BRIDGE E. 144TH ST./METRO NORTH RR HAR
Address : EAST 144TH STREET
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0184.000 / 13718 **Yr Built/Renovated** : 1920 /
Area Sq Ft : 8,290 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 09-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241550

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$26,100			
Total	\$26,100			
Importance Code B	\$2,300			
Importance Code C	\$23,800			
Total	\$26,100			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
EAST 144TH STREET BRIDGE E. 144TH ST./METRO NORTH RR HAR
Asset # : 13718

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Underside Of Bridge Throughout</i>								
<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	25%	Now	\$2,300	LIFE			**	
<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Both Sides</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : East Side</i>								
<i>Explanation : Debris</i>								
Generic	75%			LIFE			**	
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem Breastwall 50 Percent Concrete And 50 Percent Not Accessible</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Walls Consist Of 25 Percent Concrete, 25 Percent Masonry, 25 Percent Not Accessible, And 25% Under Construction.</i>								
Masonry	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 144TH STREET BRIDGE E. 144TH ST./METRO NORTH RR HAR
Asset # : 13718

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Cracks</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$13,200	2041		**	4	\$3,100
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : East Approach</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Beginning at Right Side</i>								
<i>Explanation : Begin Right Wingwall Is Earth And Concrete Cribbing</i>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041		**	4	
Steel	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Chain-link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 144TH STREET BRIDGE E. 144TH ST./METRO NORTH RR HAR
Asset # : 13718

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Random Locations Throughout</i>					
Mono Deck Surface								
Concrete	100%			2052	**	5		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Concrete	100%			2041	**	4		
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Both Sides</i>					
			<i>Explanation : Chain-link Fence On Top Of Concrete Parapet</i>					
Sidewalks								
Concrete	100%	4+	\$10,600	2037	**	5	\$3,500	
			<i>Cracks, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 149TH STREET BRIDGE
Address : EAST 149TH STREET / AMTRAK RAILS
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0179.000 / 13713 **Yr Built/Renovated** : 1907 / 1981
Area Sq Ft : 12,575 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 09-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241129

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$248,900
Total		\$248,900
Importance Code A		\$124,500
Importance Code B		\$124,500
Total		\$248,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$96,400		\$25,300	\$1,300
Total	\$96,400		\$25,300	\$1,300
Importance Code A	\$7,700		\$12,800	\$1,300
Importance Code B			\$12,500	
Importance Code C	\$88,700			
Total	\$96,400		\$25,300	\$1,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 149TH STREET BRIDGE
Asset # : 13713

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location : Underside Of Bridge Throughout</i>								
<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%	2-4	\$31,800	2041		**	4	\$5,800
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Adjacent To Joints At West Abutment And Random Locations At South Abutment</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 149TH STREET BRIDGE
Asset # : 13713

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Guide Railing								
Concrete	80%	4+	\$3,600	2041	**	4	\$2,600	
	<i>Cracks, Extent : Light, Area Affected : 4%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Vegetation Growth, Extent : Light, Area Affected : 3%</i>							
	<i>Location : Random Locations Throughout</i>							
Concrete	20%			2041	**	4	\$2,600	
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Median								
Concrete	100%			LIFE	**	5		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	90%	4+	\$6,400	LIFE	**			
	<i>Cracks, Extent : Light, Area Affected : 15%</i>							
	<i>Location : Random Locations Throughout</i>							
Concrete	10%	4+	\$10,600	LIFE	**			
	<i>Settlement, Extent : Moderate, Area Affected : 30%</i>							
	<i>Location : Random Locations Throughout</i>							
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 149TH STREET BRIDGE
Asset # : 13713

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Median								
Concrete	100%	4+	\$4,100	LIFE	**	5	\$2,600	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Mono Deck Surface								
Concrete	100%	4+	\$17,700	2052	**	5	\$33,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$9,900	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Steel Fascia With Steel Railing And Cladding On Top</i>								
Sidewalks								
Concrete	100%	4+	\$22,200	2037	**	5	\$5,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	**	2-8	\$232,500	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$194,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 149TH STREET/JACKSON AVE CONRAIL PORT MORRIS
Address : JACKSON,MARYS,ANNS,150TH STS
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0053.000 / 2479 **Yr Built/Renovated** : 1905 /
Area Sq Ft : 65,000 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 03-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241050

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$1,593,000
Total		\$1,593,000
Importance Code C		\$1,593,000
Total		\$1,593,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$172,500			
Total	\$172,500			
Importance Code A	\$23,600			
Importance Code C	\$148,900			
Total	\$172,500			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
EAST 149TH STREET/JACKSON AVE CONRAIL PORT MORRIS

Asset # : 2479

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	50%			2034	\$796,500	4	\$34,200	
Asphalt	50%	4+	\$39,800	2034	\$796,500	4	\$22,800	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Uneven Asphalt Surface</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$21,500	LIFE			**	
<i>Corrosion, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Earth	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 149TH STREET/JACKSON AVE CONRAIL PORT MORRIS

Asset # : 2479

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	4+	\$46,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2042		**	4	\$6,300
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : North Side Of Deck</i>								
<i>Explanation : Concrete Parapet</i>								
Sidewalks								
Concrete	100%	4+	\$23,200	2038		**	5	\$4,500
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$27,700	2042		**	5	\$17,100
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Along Both Sides Of Approach Joints</i>								
<i>Delaminations, Extent : Light, Area Affected : 2%</i>								
<i>Location : Along Both Sides Of Approach Joints</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Along Both Sides Of Approach Joints</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 14TH STREET PEDESTRIAN BRDG BELT SYSTEM - SHORE PARKWAY
 Address : E 14 ST PED BRDG OVER BELT PKWY AT VOORHIES AVE, SHEEPSHEAD BAY
 Borough : BROOKLYN Agency's Number : N/A
 Program / Asset # : DOT0390.000 / 15410 Yr Built/Renovated :
 Area Sq Ft : 5,148 Project Type : HIGHWAY BRIDGES
 Date of Survey : 18-Mar-2022 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2233080

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$52,700	\$74,100
Total	\$52,700	\$74,100
Importance Code A	\$52,700	\$74,100
Total	\$52,700	\$74,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$46,500		\$8,200	
Total	\$46,500		\$8,200	
Importance Code A	\$14,300		\$8,100	
Importance Code B	\$23,500			
Importance Code C	\$8,700			
Total	\$46,500		\$8,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 14TH STREET PEDESTRIAN BRDG BELT SYSTEM - SHORE PARKWAY
Asset # : 15410

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : No Abutment On North Side. Stair Deck Rests On Ground On Northeast Side. Bridge Shares Abutment With Railroad Abutment On South End.</i>								
Backwall								
Concrete	100%			LIFE			* *	
Brngs,Ancr Blts,Pads								
Steel	100%	4+	\$3,000	LIFE			* *	
<i>Corrosion, Extent : Light, Area Affected : 10%</i> <i>Location : Southeast Side</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Southwest Side</i> <i>Explanation : Limited Access To Bearings</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			* *	
Mat (scour & erosion)								
Generic	100%			LIFE			* *	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout South Abutment</i> <i>Explanation : Concrete Sidewalk</i>								
Pedestals								
Concrete	100%	4+	\$1,400	LIFE			* *	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i> <i>Location : South Abutment</i> <i>Efflorescence, Extent : Moderate, Area Affected : 10%</i> <i>Location : South Abutment</i>								
Stem (breastwall)								
Concrete	100%	4+	\$2,500	LIFE			* *	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout South Abutment</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout South Abutment</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout South Abutment</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : South End</i> <i>Explanation : Stem Extends From Railway Bridge Abutment</i>								
Wingwalls								
Footings								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i> <i>Location : Southeast Corner</i> <i>Explanation : Wingwall Is Only At One Side</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 14TH STREET PEDESTRIAN BRDG BELT SYSTEM - SHORE PARKWAY
Asset # : 15410

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
			<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Southeast Side</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stairs On Wingwall</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Belt Parkway, Concrete Sidewalk And Earth</i>					
Pier Protection								
Concrete	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : On Both Sides</i>					
			<i>Explanation : Adjacent To Belt Parkway</i>					
Approaches								
Pavement								
Concrete	100%	4+	\$1,900	2042		**	4	\$1,100
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : South Approach</i>					
			<i>Spalling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : South Approach</i>					
Curbs								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : South Approach</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
			<i>Corrosion, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 14TH STREET PEDESTRIAN BRDG BELT SYSTEM - SHORE PARKWAY
Asset # : 15410

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Cap Beam Steel	100%			LIFE	**	2-8		
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Pier,Columns Steel	100%			LIFE	**	2-8		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion) Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs Concrete	100%			2053	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets Steel	100%	4+	\$2,600	LIFE	**	2-8	\$19,900	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Moderate Cases On East Side</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Steel Wire Mesh Throughout Main Deck On 80 Percent Of Area. Pack Rust</i>								
Wearing Surface Concrete	100%	2-4	\$4,100	2042	**	5	\$1,400	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Patches With Water Ponding</i>								
Scupper Cast Iron	100%	Now	\$2,600	LIFE	**			
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 10%</i>								
<i>Location : At North End</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 14TH STREET PEDESTRIAN BRDG BELT SYSTEM - SHORE PARKWAY
Asset # : 15410

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$52,700	LIFE	**	5	\$200	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>								
<i>Location : At North End</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : At North End</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Over Sidewalk On North Side</i>								
<i>Explanation : Moderate Water Stains At 10 Percent Of Underdeck Area. Covered With Mesh</i>								
Primary Member								
Steel	40%	4+	\$7,300	LIFE	**	2-8	\$69,200	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Severe Cases At North End</i>								
Steel	60%			LIFE	**	2-8	\$69,200	
Secondary Member								
Concrete Encased Steel	100%	Now	\$15,900	2061	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Exposed Bottom Flanges</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 80 Percent Of Concrete Encased Steel Not Accessible As Floor Beams Are Covered With Timber Shielding.</i>								
Steel	100%	4+	\$5,200	LIFE	**	2-8	\$600	
<i>Corrosion, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Throughout Stair</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 156TH STREET ACCESS TO HOUSING
Address : EAST 156TH AVE. CONCOURSE VILLAGE W & MORRIS AVE
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0250.000 / 14990 **Yr Built/Renovated** : 1968 /
Area Sq Ft : 49,204 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 25-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2270030

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$823,000	\$1,286,000
Total	\$823,000	\$1,286,000
Importance Code A	\$767,400	\$541,200
Importance Code B	\$55,500	
Importance Code C		\$744,800
Total	\$823,000	\$1,286,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$223,200		\$51,900	\$19,700
Total	\$223,200		\$51,900	\$19,700
Importance Code A	\$11,100		\$48,900	
Importance Code B	\$74,100		\$2,900	
Importance Code C	\$138,000			\$19,700
Total	\$223,200		\$51,900	\$19,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
EAST 156TH STREET ACCESS TO HOUSING
Asset # : 14990

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	90%	4+	\$2,000	LIFE				**
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Missing Elements</i>					
Generic	10%			LIFE				**
Mat (scour & erosion)								
Generic	100%			LIFE				**
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	40%	4+	\$33,600	LIFE				**
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 50 Percent Concrete</i>					
Concrete	60%			LIFE				**
Masonry	100%			LIFE				**
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 50 Percent Masonry</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE				**
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 156TH STREET ACCESS TO HOUSING
Asset # : 14990

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	30%	4+	\$41,900	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	70%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Roadway</i>								
Approaches								
Pavement								
Asphalt	100%	4+	\$7,400	2035	\$147,100	4	\$2,400	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
Embankment								
Generic	100%			LIFE			**	
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	4+	\$1,500	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Northwest Corner</i>								
<i>Explanation : One Scupper Observed</i>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 156TH STREET ACCESS TO HOUSING
Asset # : 14990

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam Concrete	12%	4+	\$56,300	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>							
Concrete	88%			LIFE		**		
Pier, Columns Concrete	10%	4+	\$55,500	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 3%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>							
Concrete	90%			LIFE		**		
Brngs, Ancr Blts, Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%	4+	\$38,500	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 3%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>							
Piles Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 156TH STREET ACCESS TO HOUSING
Asset # : 14990

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Railings/Parapets								
Concrete	100%	4+	\$11,100	2043		**	4	\$1,900
	<i>Cracks, Extent : Light, Area Affected : 8%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 1%</i>							
	<i>Location : Southeast Corner</i>							
	<i>Spalling, Extent : Light, Area Affected : 3%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 25 Percent Concrete; 25 Percent Brick</i>							
Steel	100%			LIFE		**	2-8	\$2,700
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 50 Percent Steel</i>							
Sidewalks								
Concrete	35%	4+	\$31,100	2039		**	5	\$19,700
	<i>Cracks, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Concrete	65%			2039		**	5	\$39,300
	<i>Other Observation, Extent : N/A, Area Affected : 10%</i>							
	<i>Location : Center Of The Bridge And South Side</i>							
	<i>Explanation : Gratings And Longitudinal Joint</i>							
Wearing Surface								
Asphalt	100%	4+	\$29,900	2035	\$597,700		5	\$20,200
	<i>Cracks, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Settlement, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$711,100	LIFE		**	5	\$54,200
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 3%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Limited Access</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
EAST 156TH STREET ACCESS TO HOUSING
Asset # : 14990**

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Generic	100%	4+	\$26,200	LIFE			* *	
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Missing Elements</i>								
Primary Member								
Steel	100%			LIFE			* *	2-8 \$909,600
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rusted</i>								
Secondary Member								
Steel	100%			LIFE			* *	2-8 \$45,700
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rusted</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 170 ST. BRIDGE GRAND CONCOURSE/EAST 170TH ST
Address : GRAND CONCOURSE
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0063.000 / 2488 **Yr Built/Renovated** : 1923 /
Area Sq Ft : 35,917 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2242300

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,512,600	\$975,100
Total	\$1,512,600	\$975,100
Importance Code A	\$804,100	\$292,700
Importance Code B	\$571,500	\$682,300
Importance Code C	\$137,000	
Total	\$1,512,600	\$975,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$413,900		\$82,800	
Total	\$413,900		\$82,800	
Importance Code A	\$35,100		\$6,200	
Importance Code B	\$313,700		\$68,400	
Importance Code C	\$65,100		\$8,200	
Total	\$413,900		\$82,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 170 ST. BRIDGE GRAND CONCOURSE/EAST 170TH ST
Asset # : 2488

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Backwall								
Concrete	100%			LIFE		**		
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%	4+	\$27,400	LIFE		**		
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Pothole At Eastern Portal Of Tunnel</i>					
Stem (breastwall)								
Concrete	100%	4+	\$171,500	LIFE		**		
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Leakage, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Spalling At Interface With Soldier Piles, Water Infiltration At One Spall In South Abutment</i>					
Steel	100%			LIFE		**		
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Rust Stains</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%	4+	\$137,000	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 75%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Peeling Paint</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Roadway Pavement</i>					
Pier Protection								
Concrete	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 170 ST. BRIDGE GRAND CONCOURSE/EAST 170TH ST
Asset # : 2488

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	70%			2036	**	4	\$16,300	
Asphalt	30%	4+	\$29,900	2036	**	4	\$16,300	
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	20%	4+	\$3,100	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	80%			LIFE	**			
Piers								
Cap Beam								
Concrete Encased Steel	100%			LIFE	**	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 15 Percent Of Total</i>								
Steel	100%			LIFE	**	2-8	\$235,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 15 Percent Of Total</i>								
Pier,Columns								
Steel	90%			LIFE	**	2-8	\$1,609,800	
Steel	10%	4+	\$58,800	LIFE	**	2-8	\$982,300	
<i>Corrosion, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Pitting Throughout</i>								
Stem,Solid Pier								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Wall Between Columns At Bottom</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							

Deck Elements

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 170 ST. BRIDGE GRAND CONCOURSE/EAST 170TH ST
Asset # : 2488

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Gratings								
Steel	100%			LIFE	**			
Median								
Concrete	100%			LIFE	**	5	\$101,700	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : West Side</i>								
<i>Explanation : Concrete With Walls And Brick Paving</i>								
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$3,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence And Box Beam Railing</i>								
Sidewalks								
Concrete	80%			2040	**	5	\$7,200	
Concrete	20%	4+	\$8,200	2040	**	5	\$3,600	
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout, Large Crack At Sidewalk Over Eastern End Of Tunnel</i>								
<i>Spalling, Extent : Light, Area Affected : 25%</i>								
<i>Location : Eastern End</i>								
Wearing Surface								
Asphalt	70%			2036	**	5	\$33,000	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : West Side</i>								
<i>Explanation : Plants And Garden</i>								
Asphalt	30%	4+	\$7,300	2036	**	5	\$16,500	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$511,400	LIFE	**	5	\$38,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Cracks With Efflorescence At Deck In Vicinity Of Subway</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Underside Of Deck</i>								
<i>Explanation : Peeling Paint</i>								
Primary Member								
Concrete Encased Steel	100%			LIFE	**	5	\$362,000	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 174TH STREET/AMTRAK BRIDGE SHERIDAN EXPRESSWAY I895/AMTRAK
Address : E. 174ST, BRONX RIVER, I895
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0005.000 / 2440 **Yr Built/Renovated** : 1909 /
Area Sq Ft : 46,200 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 01-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2066720

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$949,500	\$1,543,900
Total	\$949,500	\$1,543,900
Importance Code A	\$395,200	\$517,900
Importance Code B	\$401,300	\$944,200
Importance Code C	\$153,000	\$81,700
Total	\$949,500	\$1,543,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$189,900		\$157,500	
Total	\$189,900		\$157,500	
Importance Code A	\$97,500		\$47,500	
Importance Code B	\$26,400		\$94,700	
Importance Code C	\$66,000		\$15,300	
Total	\$189,900		\$157,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
EAST 174TH STREET/AMTRAK BRIDGE SHERIDAN EXPRESSWAY I895/AMTRAK
Asset # : 2440

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	20%			LIFE		**		
Concrete	30%	4+	\$3,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On Bridge Seat, West Abutment</i>								
Concrete	50%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East Abutment</i>								
<i>Explanation : Not Accessible</i>								
Backwall								
Concrete	10%	4+	\$3,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : West Abutment</i>								
Concrete	40%			LIFE		**		
Concrete	50%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East Abutment</i>								
<i>Explanation : Not Accessible</i>								
Brngs,Ancr Blts,Pads								
Steel	50%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East Abutment</i>								
<i>Explanation : Not Accessible</i>								
Steel	50%			LIFE		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$3,000	LIFE		**		
<i>Loose Elements, Extent : Light, Area Affected : 15%</i>								
<i>Location : West Abutment</i>								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : East Abutment</i>								
<i>Explanation : Location Noted</i>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : East Abutment</i>								
<i>Explanation : Location Noted</i>								
Pedestals								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : East Abutment</i>								
<i>Explanation : Location Noted</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 174TH STREET/AMTRAK BRIDGE SHERIDAN EXPRESSWAY I895/AMTRAK
Asset # : 2440

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Stem (breastwall)								
Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Moderate, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : East Abutment</i>						
		<i>Explanation : Location Noted</i>						
Wingwalls								
Footings								
Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : East Abutment</i>						
		<i>Explanation : Location Noted</i>						
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : River Banks</i>						
		<i>Explanation : East Bank Has Riprap, West Bank Is Earth</i>						
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%	4+	\$26,200	2042		**	4	\$15,400
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
		<i>Rust Stains, Extent : Light, Area Affected : 50%</i>						
		<i>Location : Random Locations Throughout</i>						
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Earth	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 174TH STREET/AMTRAK BRIDGE SHERIDAN EXPRESSWAY I895/AMTRAK
Asset # : 2440

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Median								
Concrete	100%	4+	\$20,900	LIFE	**	5	\$900	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : East End</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4		
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East Approach</i>								
<i>Explanation : Steel Wall Panel 230 Feet, And Chain Link Fence With 4-steel Rails.</i>								
Sidewalks								
Concrete	55%	4+	\$19,500	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : East Corner</i>								
<i>Explanation : Uneven Surface</i>								
Concrete	45%			LIFE	**			
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : North Approach</i>								
<i>Explanation : Two Scuppers</i>								
Piers								
Cap Beam								
Concrete	100%	4+	\$25,900	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Pier,Columns								
Concrete	100%	4+	\$168,800	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Coping At Top Of Pier 5</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$85,500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 174TH STREET/AMTRAK BRIDGE SHERIDAN EXPRESSWAY I895/AMTRAK
Asset # : 2440

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Stem,Solid Pier Concrete	100%	4+	\$232,500	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Spall With Exposed Rebar</i>								
<hr/>								
Brngs,Ancr Blts,Pads								
Steel	50%			LIFE		**	2-8	\$5,900
Steel	50%			LIFE		**	2-8	\$5,900
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Earth	100%	4+	\$3,700	LIFE		**		
<i>Erosion, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Near Pier 6</i>								
<hr/>								
Pedestals								
Concrete	80%			LIFE		**		
Concrete	20%	4+	\$3,500	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Piers 5 And 6, Temporary Shoring At Pier 5</i>								
<i>Loss of Section, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Piers 5 And 6, Temporary Shoring Installed</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Guide Railing								
Steel	100%			LIFE		**		
<i>Loose Fastenings, Extent : Light, Area Affected : 2%</i>								
<i>Location : Midspan South Sidewalk</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Both Sides Of The Truss Bridge</i>								
<i>Explanation : Corrugated Guide Rail With 3-pipe Railing</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 174TH STREET/AMTRAK BRIDGE SHERIDAN EXPRESSWAY I895/AMTRAK
Asset # : 2440

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Median								
Concrete	100%	4+	\$40,600	LIFE	**	5	\$16,800	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2042	**	4	\$8,400	
Steel	100%			LIFE	**	2-8	\$32,500	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Sidewalks								
Concrete	90%			2038	**	5	\$30,600	
Concrete	10%	4+	\$91,500	2038	**	5	\$15,300	
<i>Cracks, Extent : Light, Area Affected : 35%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$61,600	2042	**	5	\$81,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout Along The Curb</i>								
<i>Explanation : Total Of 8 Scuppers</i>								
Superstructure								
Deck, Structural								
Concrete	85%			LIFE	**	5	\$30,300	
Concrete	15%	4+	\$395,200	LIFE	**	5	\$30,300	
<i>Cracks, Extent : Light, Area Affected : 25%</i>								
<i>Location : Throughout, Concentrated At Piers 3 And 5</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 25%</i>								
<i>Location : Throughout, Concentrated At Piers 3 And 5</i>								
Joints								
Generic	80%			LIFE	**			
Generic	20%	4+	\$16,600	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loose Elements, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : At Span 4</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 174TH STREET/AMTRAK BRIDGE SHERIDAN EXPRESSWAY I895/AMTRAK
Asset # : 2440

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$854,100	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Secondary Member								
Steel	99%			LIFE	**	2-8	\$715,500	
Steel	1%	4+	\$19,900	LIFE	**	2-8	\$715,500	
<i>Loss of Section, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : At Span 6</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 60TH STREET FDR DRIVE
Address : EASTERN END OF E 60TH STREET JOHN FINLEY WALK OVER FDR
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0237.000 / 14977 **Yr Built/Renovated** : 1941 /
Area Sq Ft : 23,007 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 14-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2233040

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$59,200	\$748,700
Total	\$59,200	\$748,700
Importance Code A	\$59,200	\$115,900
Importance Code C		\$632,700
Total	\$59,200	\$748,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$66,300	\$11,100	\$1,000	\$1,500
Total	\$66,300	\$11,100	\$1,000	\$1,500
Importance Code A		\$11,100	\$1,000	
Importance Code C	\$66,300			\$1,500
Total	\$66,300	\$11,100	\$1,000	\$1,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 60TH STREET FDR DRIVE
Asset # : 14977

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%	4+	\$17,500	LIFE			**	
			<i>Cracks, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Random Locations On Southwest Wingwall</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Southeast Wingwall</i>					
			<i>Explanation : No Wingwall On North Approach. Limited Access</i>					
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	100%	4+	\$3,100	2035	\$155,300	4	\$2,300	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : North Approach</i>					
			<i>Explanation : Asphalt Pavers</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 60TH STREET FDR DRIVE
Asset # : 14977

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2043	**	4	\$2,300	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Sidewalks								
Concrete	100%			LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Southeast Approach</i>					
Scupper								
Cast Iron	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : South Approach</i>					
			<i>Explanation : 1 Scupper</i>					
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Pier,Columns								
Concrete	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Stem,Solid Pier								
Concrete	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							

Deck Elements

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 60TH STREET FDR DRIVE
Asset # : 14977

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations On East Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On East Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout West Side</i>								
<i>Explanation : Under Construction</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2043		**	4	\$30,900
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$28,300
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout East Side</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
<hr/>								
Sidewalks								
Concrete	100%			2039		**	5	\$3,000
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations On East Side</i>								
<hr/>								
Wearing Surface								
Asphalt	100%	4+	\$8,400	2035	\$421,000		5	\$13,000
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	100%	4+	\$35,200	2043		**	5	\$56,500
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On South Spans</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Joints								
Generic	100%	4+	\$2,100	LIFE		**		
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Debris Accumulation</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 60TH STREET FDR DRIVE
Asset # : 14977

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Primary Member								
Concrete Encased Steel	100%	4+	\$59,200	LIFE	**	5	\$115,900	
<i>Corrosion, Extent : Light, Area Affected : 15%</i>								
<i>Location : Bottom Flanges Of Beams Over F D R</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Span Over Southbound F D R</i>								
<i>Explanation : Limited Access</i>								
Prestressed Concrete Box Beam	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Spans West Of Southbound F D R</i>								
<i>Explanation : Limited Access</i>								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Spans East Of Southbound F D R</i>								
<i>Explanation : No Access To Underside Of The Bridge</i>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 6TH ST. PEDESTRIAN BRIDGE FDR DRIVE
Address : EAST 6TH ST OVER FDR DRIVE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0334.000 / 15193 **Yr Built/Renovated** :
Area Sq Ft : 3,880 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 17-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2232050

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$74,500	\$186,000
Total	\$74,500	\$186,000
Importance Code A	\$74,500	\$186,000
Total	\$74,500	\$186,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$31,800		\$24,600	\$1,200
Total	\$31,800		\$24,600	\$1,200
Importance Code A	\$28,400		\$22,300	
Importance Code B			\$2,300	
Importance Code C	\$3,400			\$1,200
Total	\$31,800		\$24,600	\$1,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

**DEPARTMENT OF TRANSPORTATION - 841
EAST 6TH ST. PEDESTRIAN BRIDGE FDR DRIVE**

Asset # : 15193

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Cracks</i>					
Approaches								
Pavement								
Concrete	100%			2041		**	4	\$2,500
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Settlement, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : East Side</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 6TH ST. PEDESTRIAN BRIDGE FDR DRIVE

Asset # : 15193

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
			<i>Corrosion, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$430,000
Pier, Columns								
Steel	100%			LIFE		**	2-8	\$66,900
			<i>Corrosion, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 30%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 30 Percent Not Accessible</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%			2052		**		
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$20,600
			<i>Corrosion, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 40%</i>					
			<i>Location : On Bridge And West Side</i>					
			<i>Explanation : Chain Link Fence</i>					
Wearing Surface								
Concrete	100%	4+	\$3,400	2041		**	5	\$11,300
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Scupper								
Cast Iron	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 2 Scuppers Observed</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
EAST 6TH ST. PEDESTRIAN BRIDGE FDR DRIVE**

Asset # : 15193

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%	Now	\$74,500	LIFE	**	5	\$4,300	
<i>Spalling, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Northbound FDR Lane</i>								
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : 30 Percent Not Accessible. Covered In Mesh</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%	Now	\$28,400	LIFE	**	2-8	\$53,800	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Damaged Railing, Extent : Severe, Area Affected : 3%</i>								
<i>Location : Primary Steel Member Over Northbound FDR Lanes</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 30 Percent Not Accessible.</i>								
Secondary Member								
Concrete Encased Steel	100%			2060	**			
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 30 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 71ST ST. PEDESTRIAN BRIDGE FDR DRIVE
Address : E 71ST STREET OVER FDR DRIVE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0335.000 / 15194 **Yr Built/Renovated** :
Area Sq Ft : 4,815 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2232120

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$155,000
Total		\$155,000
Importance Code B		\$155,000
Total		\$155,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$14,300		\$22,400	\$3,500
Total	\$14,300		\$22,400	\$3,500
Importance Code A	\$300		\$6,300	
Importance Code B			\$16,000	
Importance Code C	\$14,100			\$3,500
Total	\$14,300		\$22,400	\$3,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
EAST 71ST ST. PEDESTRIAN BRIDGE FDR DRIVE**

Asset # : 15194

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Backwall								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2052		**		
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Masonry Plate On West Abutments</i>					
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%	4+	\$300	LIFE		**		
			<i>Delaminations, Extent : Light, Area Affected : 1%</i>					
			<i>Location : West Abutment</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : West Abutment</i>					
Stem (breastwall)								
Concrete	100%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
			<i>Cracking/Crumbling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : On Both Abutments</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%			2041		**	4	\$6,900
Curbs								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
EAST 71ST ST. PEDESTRIAN BRIDGE FDR DRIVE**

Asset # : 15194

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Steel	100%			LIFE	**			
Scupper Galvanized Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 2 Scuppers Observed</i>								
Piers								
Cap Beam Steel	100%			LIFE	**	2-8	\$53,800	
Pier,Columns Steel	100%			LIFE	**	2-8	\$446,300	
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Piles Not Accessible	100%							
Deck Elements								
Railings/Parapets Steel	100%			LIFE	**	2-8	\$22,700	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Both Sides Of Main Deck Above Traffic</i>								
<i>Explanation : Wire Mesh Fence</i>								
Wearing Surface Concrete	100%			2041	**	5	\$28,100	
Scupper Galvanized Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 6 Scuppers Observed</i>								
Superstructure								
Deck,Structural Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Deck Is Covered With Stay In Place Forms With Light Corrosion In Scattered Areas.</i>								
Joints Steel	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
EAST 71ST ST. PEDESTRIAN BRIDGE FDR DRIVE**

Asset # : 15194

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	* *	2-8	\$59,300	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	100%			LIFE	* *	2-8	\$7,800	
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST TREMONT AVENUE BRONX RIVER
Address : E. TREMONT AVE OVER BRONX RIVER AT E 177TH STREET & BOSTON RD.
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0254.000 / 14994 Yr Built/Renovated : 1938 /
Area Sq Ft : 12,160 Project Type : HIGHWAY BRIDGES
Date of Survey : 25-Jan-2023 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2242149

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$1,268,500
Total		\$1,268,500
Importance Code A		\$120,400
Importance Code C		\$1,148,200
Total		\$1,268,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$83,300	\$7,600	\$45,000	
Total	\$83,300	\$7,600	\$45,000	
Importance Code A	\$12,500		\$12,200	
Importance Code B			\$700	
Importance Code C	\$70,800	\$7,600	\$32,100	
Total	\$83,300	\$7,600	\$45,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE BRONX RIVER
Asset # : 14994

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Masonry	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2054		**		
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
			<i>Other Observation, Extent : N/A, Area Affected : 0%</i>					
			<i>Location :</i>					
			<i>Explanation : Paved Over With Asphalt</i>					
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stone Block</i>					
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Masonry: Granite	100%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE		**		
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE		**		
Mat (scour & erosion)								
Stream Bed	100%			LIFE		**		
Pier Protection								
Concrete	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE BRONX RIVER
Asset # : 14994

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	3%	4+	\$13,800	2035	\$34,400	4	\$15,200	
<i>Cracks, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Asphalt	97%			2035	\$1,113,700	4	\$22,800	
Curbs								
Concrete w/ Steel Face	98%	4+	\$5,900	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout, Southeast Corner</i>								
Concrete w/ Steel Face	2%	Now		LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 100%</i>								
<i>Location : Northeast Corner</i>								
Embankment								
Generic	100%			LIFE	**			
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE	**	5	\$900	
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%	4+	\$3,200	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : One At Each Approach</i>								
<i>Explanation : 2 Scuppers</i>								
Piers								
Stem,Solid Pier								
Masonry	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2054	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE BRONX RIVER
Asset # : 14994

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Riprap	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$6,500	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 8%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 6%</i>					
			<i>Location : Random Locations Throughout</i>					
Median								
Concrete	100%			LIFE	**	5	\$1,000	
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$3,600	
Sidewalks								
Concrete	100%	4+	\$36,900	2039	**	5	\$2,600	
			<i>Cracks, Extent : Light, Area Affected : 8%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	5%	4+	\$16,900	2043	**	5	\$32,100	
			<i>Cracks, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	95%			2043	**	5	\$64,200	
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$13,400	
			<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Southeast Corner</i>					
Joints								
Steel	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$224,800	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$11,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST TREMONT AVENUE HUTCHINSON RIVER PARKWAY
Address : E. TRMONT AVE OVER HUTCHINSON RIVER PKWY
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0253.000 / 14993 **Yr Built/Renovated** : 1940 /
Area Sq Ft : 10,274 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 25-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2075820

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$81,100	\$645,700
Total	\$81,100	\$645,700
Importance Code A	\$81,100	\$101,700
Importance Code C		\$544,000
Total	\$81,100	\$645,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$102,900		\$11,500	
Total	\$102,900		\$11,500	
Importance Code A	\$7,600		\$10,900	
Importance Code B	\$30,900		\$600	
Importance Code C	\$64,400			
Total	\$102,900		\$11,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE HUTCHINSON RIVER PARKWAY

Asset # : 14993

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Abutments							
Bridge Seat&pedestals Concrete	100%	4+	\$4,600	LIFE		**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Spalling, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
Backwall Not Accessible	100%						
Brngs,Ancr Blts,Pads Elastomeric	100%			2054		**	
Footings Not Accessible	100%						
Joint with Deck Not Accessible	100%						
Mat (scour & erosion) Generic	100%			LIFE		**	
Pedestals Concrete	100%			LIFE		**	
<i>Cracks, Extent : Light, Area Affected : 1%</i>							
<i>Location : Random Locations Throughout</i>							
Stem (breastwall) Concrete	100%			LIFE		**	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Explanation : Paint Peeling</i>							
Wingwalls							
Footings Not Accessible	100%						
Mat (scour & erosion) Generic	100%			LIFE		**	
Piles Not Accessible	100%						
Walls Masonry: Brownstone	100%			LIFE		**	
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>							
<i>Location : Random Locations Throughout</i>							
Feature Crossed							
Mat (scour & erosion) Generic	100%			LIFE		**	
<i>Roadway/Path, Extent : Light, Area Affected : 100%</i>							
<i>Location : Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE HUTCHINSON RIVER PARKWAY

Asset # : 14993

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides Of The Center Pier</i>								
<i>Explanation : Steel Guide Railing</i>								
Approaches								
Pavement								
Asphalt	100%	4+	\$18,900	2035	\$377,600	4	\$5,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Masonry	100%			2043		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 75 Percent Masonry</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 25 Percent Steel</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Stem,Solid Pier								
Concrete	1%	4+	\$30,900	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	99%			LIFE		**		
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2054		**		
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE HUTCHINSON RIVER PARKWAY

Asset # : 14993

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$3,000	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Recent Repair Evident, Extent : N/A, Area Affected : 25%</i>					
			<i>Location : West Side</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Masonry	100%			2043	**	5	\$1,200	
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Missing Joint. 10 Percent Masonry</i>					
Steel	100%			LIFE	**	2-8	\$2,600	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 90 Percent Steel, Four - Rail Railing With Chain - Link Fence</i>					
Sidewalks								
Concrete	100%	4+	\$28,900	2039	**	5	\$2,300	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 8%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Asphalt	100%	4+	\$16,600	2035	\$166,300	5	\$5,100	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Settlement, Extent : Light, Area Affected : 3%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Concrete	1%	4+	\$81,100	LIFE	**	5	\$11,300	
			<i>Cracks, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	99%			LIFE	**	5	\$11,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE HUTCHINSON RIVER PARKWAY

Asset # : 14993

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	* *	2-8	\$189,900	
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Secondary Member								
Steel	100%			LIFE	* *	2-8	\$9,500	
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST TREMONT AVENUE BRIDGE EAST TREMONT AVE./AMTRAK
Address : OVER AMTRAK AT EAST TREMONT AVE / E. 180TH ST.
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0155.000 / 13518 Yr Built/Renovated : 1907 /
Area Sq Ft : 22,300 Project Type : HIGHWAY BRIDGES
Date of Survey : 19-Oct-2020 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2241270

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$91,500	\$333,100
Total	\$91,500	\$333,100
Importance Code A		\$220,700
Importance Code B	\$91,500	\$39,300
Importance Code C		\$73,000
Total	\$91,500	\$333,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$96,800		\$26,300	\$300
Total	\$96,800		\$26,300	\$300
Importance Code A	\$22,400		\$22,300	\$300
Importance Code B			\$3,900	
Importance Code C	\$74,400			
Total	\$96,800		\$26,300	\$300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE BRIDGE EAST TREMONT AVE./AMTRAK
Asset # : 13518

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	10%	4+	\$91,500	LIFE			**	
			<i>Cracks, Extent : Moderate, Area Affected : 40%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 90%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>					
Concrete	90%			LIFE			**	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
Approaches								
Pavement								
Concrete	100%	4+	\$24,000	2041		**	4	\$11,100
			<i>Cracks, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Both Joint Headers</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
			<i>Corrosion, Extent : Light, Area Affected : 80%</i>					
			<i>Location : Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE BRIDGE EAST TREMONT AVE./AMTRAK
Asset # : 13518

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Median								
Concrete	100%	4+	\$15,800	LIFE	**	5	\$2,600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	4+	\$6,500	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$113,200	
Stem,Solid Pier								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 80%</i>								
<i>Location : Random Locations</i>								
Median								
Concrete	75%			LIFE	**	5	\$21,700	
Concrete	25%	4+	\$6,600	LIFE	**	5	\$21,700	
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST TREMONT AVENUE BRIDGE EAST TREMONT AVE./AMTRAK
Asset # : 13518

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets								
Concrete	100%			2041	**	4	\$500	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Concrete Parapet</i>							
Steel	100%			LIFE	**	2-8	\$4,800	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Steel Railing</i>							
Sidewalks								
Concrete	100%	4+	\$16,000	2037	**	5	\$5,300	
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Wearing Surface								
Concrete	100%	4+	\$27,900	2041	**	5	\$73,000	
	<i>Spalling, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Along Armored Joint Along East And West Abutments</i>							
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	**	2-8	\$412,300	
	<i>Corrosion, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 90%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ELIOT AVENUE QUEENS BOULEVARD
Address : ELIOT AVE OVER QUEENS BLVD BET 59TH AND 62ND AVENUES, REGO PARK
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0328.000 / 15187 **Yr Built/Renovated** :
Area Sq Ft : 12,866 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2248160

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$244,800
Total		\$244,800
Importance Code C		\$244,800
Total		\$244,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$24,900	\$4,800	\$5,400	
Total	\$24,900	\$4,800	\$5,400	
Importance Code A	\$800			
Importance Code B				
Importance Code C	\$24,100	\$4,800	\$5,400	
Total	\$24,900	\$4,800	\$5,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ELIOT AVENUE QUEENS BOULEVARD
Asset # : 15187

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Backwall								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 90%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Mat Consists Of 10 Percent Generic, 90 Percent Not Accessible.</i>					
Stem (breastwall)								
Concrete Encased Steel	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 90%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stem Consists Of 10 Percent Concrete Encased Steel, 90 Percent Not Accessible With Stone Facing On Both Abutments.</i>					
Wingwalls								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Wingwalls Are Concrete With Stone Facing</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Asphalt	100%	4+	\$3,200	2033	\$160,000	4	\$4,900	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Both Approaches</i>					
			<i>Settlement, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Both Approaches</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Piers								
Pier,Columns								
Concrete Encased Steel	100%			LIFE		**	5	\$3,500
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Efflorescence. Pier, Columns Consist Of 10 Percent Concrete Encased Steel, 90 Percent Not Accessible With Stone Facing At Pier Ends.</i>					
Stem,Solid Pier								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ELIOT AVENUE QUEENS BOULEVARD
Asset # : 15187

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Mat Consists Of 10 Percent Generic, 90 Percent Not Accessible.</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	10%	4+	\$100	2052		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	90%			2052		**		
Guide Railing								
Concrete	100%			2045		**		
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : North Side Only</i>								
<i>Explanation : 1 Guide Railing</i>								
Railings/Parapets								
Masonry	100%			2041		**	5	\$1,400
<i>Efflorescence, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint/ Mortar Missing</i>								
Sidewalks								
Concrete	100%			2037		**	5	\$9,700
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	92%			2033	\$78,000		5	\$10,800
Asphalt	8%	4+	\$6,800	2033	\$6,800		5	\$5,400
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	100%			2041		**	5	\$28,200
Superstructure								
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ERSKINE STREET BELT PARKWAY
Address : ERSKINE STREET OVER BELT PARKWAY
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0226.000 / 14961 **Yr Built/Renovated** : 2000 /
Area Sq Ft : 8,258 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2269600

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$364,700
Total		\$364,700
Importance Code A		\$364,700
Total		\$364,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$15,400	\$21,000	\$39,700	
Total	\$15,400	\$21,000	\$39,700	
Importance Code A	\$3,100		\$36,800	
Importance Code B	\$2,700		\$2,200	
Importance Code C	\$9,700	\$21,000	\$700	
Total	\$15,400	\$21,000	\$39,700	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ERSKINE STREET BELT PARKWAY
Asset # : 14961

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Backwall Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Both Abutments</i>								
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads Elastomeric	100%			2053		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$2,700	LIFE		**		
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 20%</i>								
<i>Location : South Abutment</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : South Abutment</i>								
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Stem (breastwall) Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ERSKINE STREET BELT PARKWAY
Asset # : 14961

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Wingwalls								
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Paving Underneath</i>								
Approaches								
Pavement								
Concrete	100%			2042	**	4	\$29,000	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Longitudinal Cracks On Both Approaches</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout On West Side</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$3,100	2042	**	4	\$1,700	
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Northeast Barrier</i>								
Steel	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet On West And Concrete Barrier On East Side</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout On West Side</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ERSKINE STREET BELT PARKWAY
Asset # : 14961

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets								
Concrete	100%			2042	**	4		
Steel	100%			LIFE	**	2-8	\$5,300	
	<i>Rust Stains, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Chain Link Fence On Top Of Concrete Parapet On West And Concrete Barrier On East Side</i>							
<hr/>								
Sidewalks								
Concrete	100%			2038	**	5	\$1,500	
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
<hr/>								
Wearing Surface								
Concrete	100%			2042	**	5	\$42,000	
<hr/>								
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$9,100	
	<i>Other Observation, Extent : N/A, Area Affected : 95%</i>							
	<i>Location : Throughout Except At Deck Overhangs</i>							
	<i>Explanation : Covered By Stay In Place Forms</i>							
<hr/>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$681,200	
	<i>Corrosion, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout Bottom Flange</i>							
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$34,200	
	<i>Rust Stains, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FARMERS BOULEVARD BELT SYSTEM-SOUTHERN PKWY
Address : FARMERS BLVD OVER BELT PARKWAY BET N. CONDUIT & S. CONDUIT AVES
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0355.000 / 15369 **Yr Built/Renovated** :
Area Sq Ft : 6,298 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Jul-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231620

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$71,800	
Total	\$71,800	
Importance Code B	\$71,800	
Total	\$71,800	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$78,300		\$100	
Total	\$78,300		\$100	
Importance Code A	\$5,900		\$100	
Importance Code B	\$46,600			
Importance Code C	\$25,800			
Total	\$78,300		\$100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FARMERS BOULEVARD BELT SYSTEM-SOUTHERN PKWY

Asset # : 15369

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%	4+	\$71,800	LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : On Both Abutments</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : North Abutment</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations</i>					
			<i>Explanation : Cracks</i>					
Approaches								
Pavement								
Concrete	100%	4+	\$17,600	2041			**	4
			<i>Cracks, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Both Approaches</i>					
Curbs								
Concrete w/ Steel Face	100%	4+	\$5,000	LIFE			**	
			<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Northeast Approach</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FARMERS BOULEVARD BELT SYSTEM-SOUTHERN PKWY

Asset # : 15369

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets								
Masonry	100%			2041		**		
		<i>Other Observation, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Joint Mortar Missing/ Eroded</i>						
Steel	100%			LIFE		**		
		<i>Corrosion, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Chain Link Fence Behind Steel Railing</i>						
Sidewalks								
Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : On Both Approaches</i>						
		<i>Settlement, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Northeast And Southeast Approach</i>						
		<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>						
		<i>Location : On All Sides</i>						
Piers								
Stem,Solid Pier								
Concrete	100%	Now	\$46,600	LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : North Face Of Pier</i>						
		<i>Spalling, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : North Face Of Pier</i>						
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
		<i>Rust Stains, Extent : Light, Area Affected : 30%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FARMERS BOULEVARD BELT SYSTEM-SOUTHERN PKWY

Asset # : 15369

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Masonry	100%			2041	**	5	\$1,900	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
Steel	100%			LIFE	**	2-8	\$4,000	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind Steel Railing</i>								
Sidewalks								
Concrete	100%	4+	\$4,500	2037	**	5		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Near Curb Edges On Random Locations</i>								
Wearing Surface								
Concrete	100%	4+	\$3,600	2041	**	5		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural Not Accessible	100%							
Primary Member Concrete	100%			LIFE	**	5	\$46,800	
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered With Steel Mesh</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FDR DRIVE NB RAMP TO HOUSTON ST RELIEF
Address : FDR DRIVE & HOUSTON ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0359.100 / 15381 **Yr Built/Renovated** :
Area Sq Ft : 7,425 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 223204A

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$71,000
Total		\$71,000
Importance Code C		\$71,000
Total		\$71,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$5,000	\$18,200	\$2,300	
Total	\$5,000	\$18,200	\$2,300	
Importance Code A	\$3,900		\$200	
Importance Code C	\$1,100	\$18,200	\$2,100	
Total	\$5,000	\$18,200	\$2,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
FDR DRIVE NB RAMP TO HOUSTON ST RELIEF

Asset # : 15381

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE	**			
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Wingwalls Only At South Abutment</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 50 Percent Wingwall Is Not Accessible</i>						
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	100%			2034	\$71,000	4	\$3,300	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Approach Only At South Side</i>						
Embankment								
Not Accessible	100%							
Guide Railing								
Concrete	100%			2042	**	4	\$2,600	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout On East Side</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR DRIVE NB RAMP TO HOUSTON ST RELIEF

Asset # : 15381

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Concrete	100%			2042	**	4	\$2,800	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Stem,Solid Pier Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 75%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 75 Percent Of Stem Is Not Accessible</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing Concrete	100%			2046	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets Concrete	100%			2042	**	4	\$6,300	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$5,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On East Side Only</i>								
<i>Explanation : Chain Link Fencing Attached To Steel Railing</i>								
Sidewalks Concrete	100%			2038	**	5	\$4,100	
Wearing Surface Concrete	100%			2042	**	5	\$36,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FDR DRIVE VIADUCT BRIDGE AVE C TO EAST 23RD ST
Address : AVE C TO E. 25ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0028.000 / 2459 **Yr Built/Renovated** : 1947 /
Area Sq Ft : 183,900 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 14-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2232060

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,777,900	\$9,213,300
Total	\$1,777,900	\$9,213,300
Importance Code A	\$983,300	\$8,257,100
Importance Code B	\$299,200	\$460,800
Importance Code C	\$495,400	\$495,400
Total	\$1,777,900	\$9,213,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure		\$116,400	\$854,300	
Total		\$116,400	\$854,300	
Importance Code A		\$60,700	\$808,100	
Importance Code B			\$46,200	
Importance Code C		\$55,700		
Total		\$116,400	\$854,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
FDR DRIVE VIADUCT BRIDGE AVE C TO EAST 23RD ST
Asset # : 2459

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To South Abutment</i>								
<hr/>								
Backwall Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On North Abutment</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On North Abutment</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To South Abutment</i>								
<hr/>								
Brngs,Ancr Blts,Pads Elastomeric	100%			2054		**		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On North Abutment</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To South Abutment</i>								
<hr/>								
Footings Not Accessible	100%							
<hr/>								
Joint with Deck Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
<hr/>								
Mat (scour & erosion) Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To South Abutment</i>								
<hr/>								
Pedestals Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On North Abutment</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations On North Abutment</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To South Abutment</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR DRIVE VIADUCT BRIDGE AVE C TO EAST 23RD ST
Asset # : 2459

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Stem (breastwall) Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On North Abutment</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To South Abutment</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To South And Northwest Wingwalls</i>								
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On Northeast Wingwall</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On Northeast Wingwall</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To South And Northwest Wingwalls.</i>								
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE		**		
Pier Protection								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Approaches								
Pavement								
Concrete	100%			2043		**	4	\$167,200
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	\$4,700

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR DRIVE VIADUCT BRIDGE AVE C TO EAST 23RD ST
Asset # : 2459

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Concrete	100%			2043	**	4	\$19,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 2 Scuppers Total</i>								
Piers								
Pier,Columns Steel	100%	4+	\$299,200	LIFE	**	2-8	\$1,094,800	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout With Severe Cases Near Joints</i>								
Brngs,Ancr Blts,Pads Multi-Rotational Bearing	100%			2062	**			
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Asphalt Paving</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Median Concrete	100%			LIFE	**	5	\$9,200	
<i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Railings/Parapets Concrete	100%			2043	**	4	\$162,500	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR DRIVE VIADUCT BRIDGE AVE C TO EAST 23RD ST
Asset # : 2459

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Wearing Surface Concrete	100%			2043	**	5	\$990,700	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 64 Scuppers Total</i>								
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$199,100	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout Underside Of Deck At The Middle Bay</i> <i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout Underside Of Deck At The Middle Bay</i> <i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Stay In Place Forms Placed Underside Of Deck Except At The Middle Bay</i>								
Joints								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Primary Member								
Steel	26%	4+	\$983,300	LIFE	**	2-8	\$7,525,300	
<i>Corrosion, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout With Severe Cases Near Joints</i> <i>Other Observation, Extent : Moderate, Area Affected : 2%</i> <i>Location : Random Locations Near Joints</i> <i>Explanation : Pack Rust</i>								
Steel	74%			LIFE	**	2-8	\$7,525,300	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$126,100	
<i>Corrosion, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FDR NB E 42ND TO E 49TH STREET EAST RIVER SHORELINE
Address : FDR NORTHBOUND FROM E 42ND ST. TO E 49TH .
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0236.000 / 14976 **Yr Built/Renovated** :
Area Sq Ft : 24,758 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 14-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2268650

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$194,300	\$473,700
Total	\$194,300	\$473,700
Importance Code A	\$92,500	
Importance Code C	\$101,700	\$473,700
Total	\$194,300	\$473,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$54,700			
Total	\$54,700			
Importance Code A	\$13,100			
Importance Code C	\$41,600			
Total	\$54,700			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR NB E 42ND TO E 49TH STREET EAST RIVER SHORELINE

Asset # : 14976

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Piles							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Feature Crossed							
Bank Protection							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Pier Protection							
Not Accessible	100%						
Approaches							
Pavement							
Asphalt	100%	4+	\$20,400	2035	\$51,100	4	\$700
			<i>Cracks, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Random Locations Throughout</i>				
			<i>Spalling, Extent : Light, Area Affected : 2%</i>				
			<i>Location : Random Locations Throughout</i>				
Curbs							
Concrete w/ Steel Face	100%			LIFE		**	
			<i>Rust Stains, Extent : Light, Area Affected : 60%</i>				
			<i>Location : Throughout East Side</i>				
Embankment							
Not Accessible	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR NB E 42ND TO E 49TH STREET EAST RIVER SHORELINE

Asset # : 14976

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On East Side</i>								
Concrete	100%	4+	\$13,100	2043			** 4	\$1,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On East Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On East Side</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 60%</i>								
<i>Location : Throughout East Side</i>								
Railings/Parapets								
Cast Iron	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations On East Side</i>								
Concrete	100%	4+	\$92,500	2043			** 4	\$32,700
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On East Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On East Side</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR NB E 42ND TO E 49TH STREET EAST RIVER SHORELINE

Asset # : 14976

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface Asphalt	100%	4+	\$21,100	2035	\$422,600	5	\$11,600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Near Curb Side</i>								
<i>Explanation : 24 Scuppers Observed</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Steel	100%	4+	\$101,700	LIFE			**	
<i>Joints Missing, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 5%</i>								
<i>Location : Near Concrete Header</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Near Concrete Header</i>								
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FDR NB RAMP/SOUTH ST
Address : OFF RAMP @PACK SLIP
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0027.0A0 / 4323 **Yr Built/Renovated** : 1954 /
Area Sq Ft : 102,200 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 30-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 223201A

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$2,672,400	\$3,683,900
Total	\$2,672,400	\$3,683,900
Importance Code A	\$1,502,500	\$1,502,500
Importance Code B	\$1,169,900	\$2,181,400
Total	\$2,672,400	\$3,683,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$1,001,600		\$371,500	
Total	\$1,001,600		\$371,500	
Importance Code A	\$655,900		\$151,500	
Importance Code B	\$329,300		\$218,800	
Importance Code C	\$16,400		\$1,200	
Total	\$1,001,600		\$371,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR NB RAMP/SOUTH ST
Asset # : 4323

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Generic	100%			LIFE			**
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Not Accessible	100%						
Walls							
Concrete	100%			LIFE			**
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : Enclosure Walls On West End.</i>				
			<i>Explanation : Concrete With Granite Facing</i>				
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE			**
Piles							
Not Accessible	100%						
Walls							
Concrete	100%			LIFE			**
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>				
			<i>Location : Random Locations On West End</i>				
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : Throughout On West End</i>				
			<i>Explanation : Concrete With Granite Facing</i>				
Feature Crossed							
Mat (scour & erosion)							
Asphalt Paving	100%			LIFE			**
Concrete	100%			LIFE			**
Pier Protection							
Concrete	5%	Now	\$4,400	LIFE			**
			<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 10%</i>				
			<i>Location : Pier 7</i>				
			<i>Spalling, Extent : Moderate, Area Affected : 15%</i>				
			<i>Location : Pier 7</i>				
Concrete	95%			LIFE			**
Steel	100%			LIFE			**

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR NB RAMP/SOUTH ST
Asset # : 4323

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%			2036	**	4	\$2,400	
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4		
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$1,898,800	
			<i>Corrosion, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Loss of Section, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Pier 7, 8, 9 And Random Locations</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Pier 8,9 And 10</i>					
			<i>Explanation : Loss Of Section Is Arrested By Paint Where Occurred</i>					
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$747,200	
			<i>Corrosion, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Bottom Of Pier 7 And Random Locations</i>					
			<i>Loss of Section, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Pier 7, 8, 9, 10 And Random Locations and Random Locations</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Pier 7, 8, 9,10 And Random Locations</i>					
			<i>Explanation : Loss Of Section Is Arrested By Paint Where Occurred</i>					
Stem,Solid Pier								
Concrete	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : On Pier 14</i>					
			<i>Explanation : Concrete Stem With Granite Facing</i>					
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Asphalt Pavement</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR NB RAMP/SOUTH ST
Asset # : 4323

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On West Side</i>								
<i>Explanation : At Pier 14 Only</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At South End</i>								
<i>Explanation : At Pier 1</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Steel	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Deck</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$36,000
Wearing Surface								
Asphalt	100%			2036		**	5	\$32,900
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout Deck</i>								
<i>Explanation : 21 Scuppers</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE		**	5	\$63,400
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Underside Of Deck At Span 12</i>								
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Between Panel Joints</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stay In Place Forms Underside Of Deck</i>								
Joints								
Generic	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Steel Armour</i>								
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR NB RAMP/SOUTH ST
Asset # : 4323

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$3,238,300	
		<i>Corrosion, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Secondary Member								
Steel	1%	Now	\$7,900	LIFE	**	2-8	\$1,582,700	
		<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Loss of Section, Extent : Severe, Area Affected : 5%</i>						
		<i>Location : Bottom Flanges At Pier 2 And 14</i>						
Steel	99%			LIFE	**	2-8	\$2,778,400	
		<i>Rust Stains, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FDR SB RAMP/SOUTH ST
Address : DOVER AND SOUTH STREETS
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0027.0B0 / 4324 **Yr Built/Renovated** : 1954 /
Area Sq Ft : 44,600 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 27-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 223201B

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,417,300	\$1,417,300
Total	\$1,417,300	\$1,417,300
Importance Code A	\$857,100	\$857,100
Importance Code B	\$560,200	\$560,200
Total	\$1,417,300	\$1,417,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$605,100		\$143,000	
Total	\$605,100		\$143,000	
Importance Code A	\$415,200		\$86,800	
Importance Code B	\$180,000		\$56,200	
Importance Code C	\$9,900			
Total	\$605,100		\$143,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR SB RAMP/SOUTH ST
Asset # : 4324

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : 3 Spans Are Enclosed</i>						
		<i>Explanation : Not Accessible</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 3 End Spans</i>						
		<i>Explanation : Enclosed Walls; Limited Access</i>						
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : South Wall</i>						
Granite	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : North Side</i>						
		<i>Explanation : Granite Facing</i>						
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR SB RAMP/SOUTH ST
Asset # : 4324

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%	0-2	\$3,400	2036	**	4	\$2,400	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Pot Holes</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4		
Steel	100%	Now	\$3,000	LIFE	**			
<i>Damaged Railing, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : North Side Near Abutment</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$1,607,900	
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$560,400	
Stem,Solid Pier								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Granite Facing</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**	2-8	\$8,400	
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Steel	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust</i>								
Railings/Parapets								
Concrete	100%			2044	**	4		
Steel	100%			LIFE	**	2-8	\$27,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR SB RAMP/SOUTH ST
Asset # : 4324

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface Asphalt	100%	0-2	\$6,500	2036	**	5	\$9,700	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Pot Holes</i>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout Deck</i> <i>Explanation : 3 Scuppers</i>								
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$39,600	
Joints Generic	100%			LIFE	**			
Primary Member Steel	100%			LIFE	**	2-8	\$1,413,200	
Secondary Member Steel	100%			LIFE	**	2-8	\$1,212,500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FDR SB VIADUCT (62ND ST) BRIDGE FDR DR/62ND STREET
Address : 62ND ST.
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0033.080 / 4208 **Yr Built/Renovated** : 1941 / 2006
Area Sq Ft : 70,113 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 17-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2233038

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,443,700	\$1,387,900
Total	\$1,443,700	\$1,387,900
Importance Code A	\$749,800	\$694,000
Importance Code B	\$694,000	\$694,000
Total	\$1,443,700	\$1,387,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$373,700		\$139,200	\$29,400
Total	\$373,700		\$139,200	\$29,400
Importance Code A	\$247,400		\$69,600	
Importance Code B	\$126,300		\$69,600	
Importance Code C				\$29,400
Total	\$373,700		\$139,200	\$29,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
FDR SB VIADUCT (62ND ST) BRIDGE FDR DR/62ND STREET
Asset # : 4208

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Abutments							
Bridge Seat&pedestals Concrete	100%			LIFE		**	
Backwall Concrete	100%			LIFE		**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
		<i>Location : North Abutment Visible Only</i>					
		<i>Explanation : North Abutment Visible Only</i>					
Brngs,Ancr Blts,Pads Elastomeric	100%			2055		**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
		<i>Location : North Abutment Visible Only</i>					
		<i>Explanation : North Abutment Visible Only</i>					
Footings							
Not Accessible	100%						
Joint with Deck							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE		**	
Pedestals							
Concrete	100%			LIFE		**	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>					
		<i>Location : Random Locations Throughout</i>					
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
		<i>Location : North Abutment</i>					
		<i>Explanation : North Side Visible Only</i>					
Stem (breastwall)							
Concrete	100%			LIFE		**	
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE		**	
Piles							
Not Accessible	100%						
Walls							
Concrete	100%			LIFE		**	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>					
		<i>Location : Random Locations Throughout</i>					
		<i>Efflorescence, Extent : Light, Area Affected : 1%</i>					
		<i>Location : Random Locations Throughout</i>					
Feature Crossed							
Mat (scour & erosion)							
Generic	100%			LIFE		**	
Approaches							
Pavement							
Not Accessible	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR SB VIADUCT (62ND ST) BRIDGE FDR DR/62ND STREET
Asset # : 4208

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4		
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
Steel	100%			LIFE	**	2-8		
Pier,Columns								
Concrete	100%			LIFE	**			
Concrete Encased Steel	100%			LIFE	**	5		
Stem,Solid Pier								
Concrete	100%			LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : At East Face Of Pier 33</i>						
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%	4+	\$55,800	2044	**	4	\$9,700	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : At Joints Along Fascia</i>						
Wearing Surface								
Concrete	100%			2044	**	5	\$58,900	
Scupper								
Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 10 Scuppers</i>						
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$31,700	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Rust Stains On Stay In Place Forms Under Deck. North Span Only Accessible</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FDR SB VIADUCT (62ND ST) BRIDGE FDR DR/62ND STREET
Asset # : 4208

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$2,221,600	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$1,906,100	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FIRST AVE. TUNNEL UNITED NATIONS PL/FIRST AVE TUNL
Address : 42ND ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0084.000 / 2513 **Yr Built/Renovated** : 1950 /
Area Sq Ft : 92,200 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2246570

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$7,392,100
Total		\$7,392,100
Importance Code A		\$474,300
Importance Code C		\$6,917,800
Total		\$7,392,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$51,300	\$41,300	\$31,700	\$34,800
Total	\$51,300	\$41,300	\$31,700	\$34,800
Importance Code A	\$6,000		\$1,200	\$10,700
Importance Code C	\$45,300	\$41,300	\$30,500	\$24,200
Total	\$51,300	\$41,300	\$31,700	\$34,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FIRST AVE. TUNNEL UNITED NATIONS PL/FIRST AVE TUNL

Asset # : 2513

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Footings								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE			**	
Tile	100%			LIFE			**	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
Granite	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Asphalt	96%			2033	\$5,433,800	4	\$48,300	
Asphalt	4%	2-4	\$45,300	2033	\$226,400	4	\$48,300	
			<i>Cracks, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Settlement, Extent : Light, Area Affected : 50%</i>					
			<i>Location : East Approach</i>					
			<i>Spalling, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
Granite	100%			LIFE			**	
Embankment								
Not Accessible	100%							
Guide Railing								
Steel	100%			LIFE		**	2-8	\$5,800
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stainless Steel Bollard</i>					
Median								
Concrete	100%			LIFE		**	5	
Railings/Parapets								
Steel	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FIRST AVE. TUNNEL UNITED NATIONS PL/FIRST AVE TUNL
Asset # : 2513

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Cobblestone	100%			LIFE		**		
<i>Broken, Missing Pave, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout East Approach</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : East Approach</i> <i>Explanation : Consists Of 50 Percent Concrete, 20 Percent Cobblestone And 30 Percent Concrete.</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : 1 Scupper Observed.</i>								
Piers								
Stem, Solid Pier								
Concrete	100%			LIFE		**		
Tile	100%			LIFE		**		
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Granite	100%			LIFE		**		
Guide Railing								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Stainless Steel Bollard</i>								
Median								
Concrete	100%			LIFE		**	5	\$15,600
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Granite	100%	4+	\$6,000	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : North Side</i> <i>Explanation : Granite Pavers With Presence Of Vegetation Growth</i>								
Railings/Parapets								
Concrete	100%			2041		**	4	\$21,300
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$29,300
<i>Corrosion, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FIRST AVE. TUNNEL UNITED NATIONS PL/FIRST AVE TUNL

Asset # : 2513

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2037	**	5	\$82,600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%			2033	\$1,257,600	5	\$61,000	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Concrete	100%			LIFE	**	5	\$474,300	
Secondary Member								
Concrete	100%			LIFE	**	5		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FLATBUSH AVE. BRIDGE
Address : FLATBUSH AVE OVER BELT - SHORE PARKWAY
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0174.000 / 13669 **Yr Built/Renovated** : 1941 / 1996
Area Sq Ft : 14,058 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 05-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231460

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$622,700	\$278,300
Total	\$622,700	\$278,300
Importance Code A	\$300,100	\$139,100
Importance Code B	\$139,100	\$139,100
Importance Code C	\$183,500	
Total	\$622,700	\$278,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$178,400		\$32,600	
Total	\$178,400		\$32,600	
Importance Code A	\$74,100		\$18,600	
Importance Code B	\$33,900		\$14,000	
Importance Code C	\$70,300			
Total	\$178,400		\$32,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVE. BRIDGE
Asset # : 13669

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Abutment Components</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Elastomeric	100%			2055		**		
Footings Not Accessible	100%							
Joint with Deck Generic	100%	2-4	\$8,600	LIFE		**		
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 75%</i>								
<i>Location : Throughout With More Severe Cases At Northeast Corner And Joint With Sidewalk Along Northeast Parapet</i>								
Mat (scour & erosion) Asphalt Paving	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Roadway</i>								
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Water Stains</i>								
Granite	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Ends</i>								
<i>Explanation : Stone Facing Over Concrete</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVE. BRIDGE
Asset # : 13669

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	100%	4+	\$183,500	LIFE			**	
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 25%</i> <i>Location : Northeast Wingwall</i> <i>Explanation : Cantilever Sign Structures Attached To Southwest And Northeast Wingwalls. Leaning Outward.</i>								
Granite	100%			LIFE			**	
<i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Joints Missing, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Vegetation Growth, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : All Wingwalls</i> <i>Explanation : Stone Facing Over Concrete Wingwalls</i>								
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Roadway</i>								
Pier Protection								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$42,300	2044		4	\$16,600	**
<i>Cracks, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Moderate, Area Affected : 20%</i> <i>Location : On Both Approaches</i> <i>Explanation : Missing Joints With Asphalt With Edge Spalls Along Joints</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$5,000	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Along Steel Face</i> <i>Delaminations, Extent : Moderate, Area Affected : 20%</i> <i>Location : Northeast And Southeast Approaches</i> <i>Rust Stains, Extent : Moderate, Area Affected : 100%</i> <i>Location : Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVE. BRIDGE
Asset # : 13669

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	Now	\$9,900	2044		**	4	\$1,500
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Delaminations, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Northeast Corner</i>					
			<i>Spalling, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : Southeast Corner And Random Locations</i>					
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Southeast Corner</i>					
			<i>Explanation : Vegetation Growth</i>					
Steel	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>					
Sidewalks								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 25%</i>					
			<i>Location : Northeast Corner</i>					
			<i>Explanation : Damaged Joint Along Parapet Base</i>					

Piers

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVE. BRIDGE
Asset # : 13669

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : South Face And Random Locations</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>								
<i>Location : South Face And Random Locations</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : South Face And Random Locations</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Random Locations On Both Faces</i>								
<i>Explanation : Concrete Patches</i>								
Granite	100%			LIFE		**		
<i>Joints Missing, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Both Ends</i>								
<i>Explanation : Stone Facing On Full Height Of Pier</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Roadway</i>								
Pedestals Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Along Steel Face</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : East Side And Random Locations</i>								
<i>Rust Stains, Extent : Light, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
Median Concrete	100%			LIFE		**	5	\$3,100
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVE. BRIDGE
Asset # : 13669

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Mono Deck Surface								
Concrete	100%	4+	\$18,000	2055	**	5	\$36,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Over The Pier And Random Locations</i>								
<hr/>								
Railings/Parapets								
Concrete	95%			2044	**	4	\$8,500	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast Corner</i>								
<i>Explanation : Vegetation Growth</i>								
Concrete	5%	Now	\$3,900	2044	**	4	\$8,500	
<i>Cracks, Extent : Light, Area Affected : 60%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Southeast Corner Near Deck Joint</i>								
Steel	100%			LIFE	**	2-8	\$19,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$10,000	2040	**	5	\$2,800	
<i>Cracks, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northeast Corner Near Deck Joint</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$161,000	LIFE	**	5	\$15,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Underside Of Overhang On Both Sides</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Stay In Place In Southeast Bay</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : On Stay In Place Forms</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Deck, Structural Components</i>								
<hr/>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$445,400	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Moderate Cases On Bottom Flanges</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$382,200	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVE. BRIDGE
Asset # : 13669**

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FLATBUSH AVENUE FRANKLIN SHUTTLE
 Address : FLATBUSH AVE AND EMPIRE BLVD
 Borough : BROOKLYN Agency's Number : N/A
 Program / Asset # : DOT0307.000 / 15065 Yr Built/Renovated :
 Area Sq Ft : 13,168 Project Type : HIGHWAY BRIDGES
 Date of Survey : 21-Dec-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2243260

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$26,700		\$3,600	
Total	\$26,700		\$3,600	
Importance Code A	\$1,600		\$1,500	
Importance Code C	\$25,100		\$2,100	
Total	\$26,700		\$3,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVENUE FRANKLIN SHUTTLE
Asset # : 15065

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Covered By Asphalt Wearing Surface</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	10%	4+	\$13,500	2036		**	4	\$4,200
	<i>Cracks, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Random Locations Throughout</i>							
Asphalt	90%			2036		**	4	\$4,200
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
	<i>Other Observation, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Rust Stains</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVENUE FRANKLIN SHUTTLE
Asset # : 15065

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,500	
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Chain Link Fence On Top Of Concrete Parapet, Vegetation On South Side</i>								
<i>Explanation : Chain Link Fence, Vegetation Growth</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Rust Stains</i>								
Median								
Concrete	100%			LIFE	**	5	\$1,000	
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,300	
Steel	100%			LIFE	**	2-8	\$2,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Chain Link Fence On Top Of Concrete Parapet, Vegetation On South Side</i>								
<i>Explanation : Chain Link Fence & Vegetation Growth</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVENUE FRANKLIN SHUTTLE
Asset # : 15065

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2040	**	5	\$3,100	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 15%</i>								
<i>Location : Near The Curb line On Both Sidewalks</i>								
<i>Explanation : Brick Pavers</i>								
Wearing Surface								
Asphalt	15%	4+	\$9,900	2036	**	5	\$1,700	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Asphalt	85%			2036	**	5	\$3,400	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FLATBUSH AVENUE LIRR BAY RIDGE
Address : FLATBUSH AVENUE AND E32ND STREET
Borough : BROOKLYN:QNS. **Agency's Number** : N/A
Program / Asset # : DOT0309.000 / 15067 **Yr Built/Renovated** :
Area Sq Ft : 5,712 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 21-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243510

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$67,200			
Total	\$67,200			
Importance Code A	\$4,100			
Importance Code C	\$63,100			
Total	\$67,200			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVENUE LIRR BAY RIDGE
Asset # : 15067

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Covered By Asphalt Wearing Surface</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	6%	4+	\$28,000	LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Southeast Wingwall</i>						
Concrete	94%			LIFE		**		
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	100%	4+	\$7,900	2036		**	4	\$5,600
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVENUE LIRR BAY RIDGE
Asset # : 15067

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout, Southeast Corner</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%	4+	\$4,100	2055		**		
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout And East Side Adjacent To The Parking Lot</i>								
Sidewalks								
Concrete	100%	4+	\$24,300	2040		**	5	\$1,900
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout, East Side, Adjacent To The Parking Lot</i>								
Wearing Surface								
Asphalt	100%			2036		**	5	\$5,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLATBUSH AVENUE LIRR BAY RIDGE
Asset # : 15067

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FLUSHING BRIDGE N.BLVD WB TO VWE SB/VACANT LAND
Address : NORTHERN BLVD. X-ING FLUSH. RIV.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0001.0A0 / 2561 **Yr Built/Renovated** :
Area Sq Ft : 9,600 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 05-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 205580A

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$80,700	
Total	\$80,700	
Importance Code C	\$80,700	
Total	\$80,700	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$46,900	\$1,900	\$200	\$5,400
Total	\$46,900	\$1,900	\$200	\$5,400
Importance Code A			\$200	\$5,400
Importance Code B	\$900			
Importance Code C	\$46,000	\$1,900		
Total	\$46,900	\$1,900	\$200	\$5,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE N.BLVD WB TO VWE SB/VACANT LAND

Asset # : 2561

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$900	LIFE		**		
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Both Abutments</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location :</i>					
			<i>Explanation : Stem Wall Is Located Behind Enclosure Wall With Locked Door At West Side Abutment</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%	4+	\$13,200	2041		**	4	\$10,300
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete	100%			LIFE		**		
Embankment								
Generic	100%			LIFE		**		
Guide Railing								
Concrete	100%			2041		**	4	\$2,900
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Concrete Barrier</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE N.BLVD WB TO VWE SB/VACANT LAND

Asset # : 2561

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : East Side</i>						
		<i>Explanation : Steel Fence</i>						
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Deck Elements								
Guide Railing								
Concrete	100%			2045	**			
Mono Deck Surface								
Concrete	100%	0-2	\$32,800	2052	**	5	\$21,100	
		<i>Cracks, Extent : Light, Area Affected : 20%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 40%</i>						
		<i>Location : Random Locations Throughout</i>						
Railings/Parapets								
Concrete	100%			2041	**	4	\$7,900	
Steel	100%			LIFE	**	2-8	\$6,400	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Steel Fence</i>						
Sidewalks								
Concrete	100%			2037	**	5	\$3,800	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Scupper								
Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : 1 Scupper Observed.</i>						

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE N.BLVD WB TO VWE SB/VACANT LAND

Asset # : 2561

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%	Now	\$80,700	LIFE				* *
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 40%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Broken/ Missing Steel Plates</i>					
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FORDHAM PLAZA METRO NORTH RAILROAD
Address : E 189TH ST, PARK AVE.
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0057.000 / 2482 **Yr Built/Renovated** : 1889 /
Area Sq Ft : 40,080 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Oct-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241839

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$525,700
Total		\$525,700
Importance Code A		\$455,500
Importance Code C		\$70,200
Total		\$525,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$56,700		\$39,900	\$32,600
Total	\$56,700		\$39,900	\$32,600
Importance Code A	\$1,000		\$39,900	
Importance Code C	\$55,700			\$32,600
Total	\$56,700		\$39,900	\$32,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FORDHAM PLAZA METRO NORTH RAILROAD
Asset # : 2482

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	2%	4+	\$1,000	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 1%</i>							
	<i>Location : Throughout</i>							
Concrete	98%			LIFE		**		
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman. Concrete 25 Percent Of Stem.</i>							
Masonry	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman. Masonry 75 Percent Of Stem.</i>							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Masonry: Schist/Gneiss	100%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%			2041		**	4	\$65,300
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Consists Of 10 Percent Concrete And 90 Percent Concrete Pavers</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FORDHAM PLAZA METRO NORTH RAILROAD
Asset # : 2482

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Granite	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Missing Joints</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : North Side</i>								
<i>Explanation : Only One Side Of Bridge Has Railing</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Granite	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Missing Joints</i>								
Median								
Concrete	100%			LIFE		**	5	\$5,400
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2041		**	4	
Steel	100%			LIFE		**	2-8	\$2,500
Sidewalks								
Concrete	100%	4+	\$10,100	2037		**	5	\$2,000
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$45,600	2041		**	5	\$70,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
FORDHAM PLAZA METRO NORTH RAILROAD**

Asset # : 2482

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$58,800	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On Stay In Place Forms</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Not Accessible And Covered With Stay In Place Forms For Inspection.</i> <i>Requires Railroad Flagman.</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$740,900	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : South Side Of Bridge</i> <i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : South Side Of Bridge</i> <i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FORT HAMILTON BRIDGE
Address : FORT HAMILTON PARKWAY
Borough : BROOKLYN
Program / Asset # : DOT0162.000 / 13570
Area Sq Ft : 14,800
Date of Survey : 04-Apr-2022
Areas Surveyed :
Block : Lot : BIN : 2243620
Agency's Number : N/A
Yr Built/Renovated : 1984 /
Project Type : HIGHWAY BRIDGES
Landmark Status : NONE

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$150,200			
Total	\$150,200			
Importance Code A	\$17,800			
Importance Code B	\$4,700			
Importance Code C	\$127,700			
Total	\$150,200			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FORT HAMILTON BRIDGE
Asset # : 13570

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	Now	\$4,700	LIFE			**	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 5%</i>								
<i>Location : South Approach</i>								
Mat (scour & erosion) Earth	100%			LIFE			**	
Stem (breastwall) Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE			**	
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Track Under The Bridge</i>								
Approaches								
Pavement Concrete	100%	4+	\$21,900	2042		**	4	\$12,800
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FORT HAMILTON BRIDGE
Asset # : 13570

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	0-2	\$10,200	LIFE		**		
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northwest Corner At Scupper</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$2,300	2042		**	4	\$1,100
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Parapet On Southeast Side</i>								
Sidewalks								
Concrete	75%			LIFE		**		
Concrete	25%	4+	\$20,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Northwest Corner</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Total Of 4 Scuppers</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FORT HAMILTON BRIDGE
Asset # : 13570

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Mono Deck Surface								
Concrete	100%	0-2	\$43,200	2053		**	5	\$21,000
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Longitudinal Cracks On Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout With Severe Cases Near Both Abutment Joints</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southbound Lane In Front Of Train Station</i>								
<i>Explanation : Asphalt Patches In 2 Percent Area On Random Locations. Scaling</i>								
Railings/Parapets								
Concrete	100%			2042		**	4	\$15,800
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%	4+	\$42,700	2038		**	5	\$7,100
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Adjacent To Joint Header</i>								
Superstructure								
Joints								
Generic	100%			LIFE		**		
Primary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FRANCIS LEWIS BOULEVARD BELT SYSTEM - CROSS ISLAND
Address : FRANCIS LEWIS BLVD BTWN BROOKVILLE BLVD & LAURELTON PKWY
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0381.000 / 15401 **Yr Built/Renovated** :
Area Sq Ft : 8,874 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231930

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$366,200	\$271,600
Total	\$366,200	\$271,600
Importance Code A	\$290,400	
Importance Code B	\$75,800	
Importance Code C		\$271,600
Total	\$366,200	\$271,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$59,900		\$2,400	
Total	\$59,900		\$2,400	
Importance Code A	\$7,600		\$300	
Importance Code B	\$39,500			
Importance Code C	\$12,800		\$2,100	
Total	\$59,900		\$2,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
FRANCIS LEWIS BOULEVARD BELT SYSTEM - CROSS ISLAND

Asset # : 15401

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			* *	
Stem (breastwall)								
Concrete	100%	4+	\$75,800	LIFE			* *	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : South Abutment</i>					
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Vegetation Growth</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			* *	
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE			* *	
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Joint Mortar Missing/ Eroded</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			* *	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Asphalt Paved Underneath</i>					
Pier Protection								
Concrete	100%			LIFE			* *	
Approaches								
Pavement								
Asphalt	100%			2034	\$200,000	4	\$9,200	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE			* *	
			<i>Rust Stains, Extent : Moderate, Area Affected : 60%</i>					
			<i>Location : Both Approaches</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Northeast Corner</i>					
Embankment								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FRANCIS LEWIS BOULEVARD BELT SYSTEM - CROSS ISLAND

Asset # : 15401

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Masonry	100%	4+	\$2,300	2042				**
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Joint Mortar Missing/ Eroded</i>					
Steel	100%			LIFE				**
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Chain Link Fence On Top Of Parapet</i>					
Sidewalks								
Concrete	100%	4+	\$6,100	LIFE				**
			<i>Cracks, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Northeast Corner</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : East Side</i>					
			<i>Explanation : Sidewalk Only On One Side</i>					
Piers								
Stem,Solid Pier								
Concrete	100%	4+	\$39,500	LIFE				**
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 10%</i>					
			<i>Location : At East And West End.</i>					
			<i>Explanation : Limited Access On 60 Percent Area. Masonry Granite Facing At Ends.</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE				**
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FRANCIS LEWIS BOULEVARD BELT SYSTEM - CROSS ISLAND

Asset # : 15401

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%	0-2	\$1,000	2053		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations On West Side</i>								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Throughout On East Side</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On East Side</i>								
Railings/Parapets								
Masonry	100%	4+	\$4,400	2042		**	5	\$1,700
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
Steel	100%			LIFE		**	2-8	\$7,400
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Parapet</i>								
Sidewalks								
Concrete	100%			2038		**	5	\$4,200
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On East Side</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On East Side</i>								
Wearing Surface								
Asphalt	100%	4+	\$3,600	2034	\$71,600		5	\$4,600
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations With Severe Cases Near Both Approaches</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On West Side</i>								
<i>Explanation : Total Of 2 Scuppers</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FRANCIS LEWIS BOULEVARD BELT SYSTEM - CROSS ISLAND

Asset # : 15401

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure Primary Member Concrete	100%	4+	\$290,400	LIFE	**	5	\$45,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 60%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GRAND AVENUE 495I - LONG ISLAND EXPRESSWAY
Address : GRAND AVE. BETWEEN BORDEN AVE. AND QUEENS MIDTOWN EXPRESSWAY
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0277.000 / 15031 **Yr Built/Renovated** :
Area Sq Ft : 12,376 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 31-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2065940

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$16,600		\$4,600	\$26,600
Total	\$16,600		\$4,600	\$26,600
Importance Code A	\$10,800		\$1,000	
Importance Code B	\$2,000			
Importance Code C	\$3,800		\$3,600	\$26,600
Total	\$16,600		\$4,600	\$26,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND AVENUE 495I - LONG ISLAND EXPRESSWAY

Asset # : 15031

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,000	LIFE			**	
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 2%</i>					
			<i>Location : South Abutment Joint</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Concrete Barrier</i>					
Approaches								
Pavement								
Asphalt	100%			2036		**	4	\$7,200
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					
Granite	100%	Now	\$3,200	LIFE		**		
			<i>Settlement, Extent : Severe, Area Affected : 20%</i>					
			<i>Location : Southwest Quadrant</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND AVENUE 495I - LONG ISLAND EXPRESSWAY

Asset # : 15031

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Not Accessible	100%							
Guide Railing								
Steel	100%			LIFE	**	2-8	\$7,400	
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,200	
Steel	100%			LIFE	**			
			<i>Corrosion, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Sidewalks								
Concrete	100%	Now	\$3,800	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Southeast Corner</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Scupper								
Cast Iron	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Southwest Approach Only</i>					
			<i>Explanation : 2 Scuppers</i>					
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND AVENUE 495I - LONG ISLAND EXPRESSWAY

Asset # : 15031

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Granite	100%			LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Along Granite Curb Inside Line</i> <i>Other Observation, Extent : N/A, Area Affected : 15%</i> <i>Location : Random Locations Along West Curb Line</i> <i>Explanation : Granite Curb Replaced With Concrete Curb</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$12,600
Sidewalks								
Concrete	100%			2040		**	5	\$6,600
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044		**	5	\$53,100
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : At Mid Span Next To West Side Curb</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GRAND CONCOURSE BEDFORD PARK BOULEVARD
Address : GRAND CONCOURSE & BEDFORD PARK BOULEVARD
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0373.000 / 15391 Yr Built/Renovated :
Area Sq Ft : 9,065 Project Type : HIGHWAY BRIDGES
Date of Survey : 16-Mar-2022 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2242370

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$821,000	
Total	\$821,000	
Importance Code A	\$165,500	
Importance Code B	\$598,800	
Importance Code C	\$56,600	
Total	\$821,000	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$44,100		\$2,000	
Total	\$44,100		\$2,000	
Importance Code A	\$11,200		\$100	
Importance Code B	\$1,400			
Importance Code C	\$31,500		\$2,000	
Total	\$44,100		\$2,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BEDFORD PARK BOULEVARD
Asset # : 15391

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$11,200	LIFE				**
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Wire Mesh</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$1,400	LIFE				**
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Joint Header</i>								
Mat (scour & erosion)								
Generic	100%			LIFE				**
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%	4+	\$598,800	LIFE				**
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE				**
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BEDFORD PARK BOULEVARD

Asset # : 15391

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	100%	4+	\$56,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%	4+	\$25,200	2042		**	4	\$37,000
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pavement Base								
Not Accessible	100%							
Piers								
Footings								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$2,100
Sidewalks								
Concrete	100%			2038		**	5	\$3,900
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$6,300	2042		**	5	\$20,700
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BEDFORD PARK BOULEVARD**

Asset # : 15391

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Utility Bay</i>							
	<i>Explanation : Stay-in-place Form</i>							
Primary Member								
Prestressed Concrete	100%	4+	\$165,500	LIFE			* *	
Box Beam								
	<i>Other Observation, Extent : Moderate, Area Affected : 3%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Cracks</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GRAND CONCOURSE EAST BURNSIDE AVENUE
Address : GRAND CONCOURSE OVER E. BURNSIDE AVE. BET. E 179TH & E 180TH STS.
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0256.000 / 14996 Yr Built/Renovated : 1923 /
Area Sq Ft : 8,190 Project Type : HIGHWAY BRIDGES
Date of Survey : 26-Jan-2023 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2242360

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$237,600	\$1,050,300
Total	\$237,600	\$1,050,300
Importance Code A		\$144,100
Importance Code B	\$106,800	\$31,800
Importance Code C	\$130,900	\$874,300
Total	\$237,600	\$1,050,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$35,600	\$700	\$18,200	
Total	\$35,600	\$700	\$18,200	
Importance Code A	\$7,800	\$700	\$14,500	
Importance Code B	\$13,300		\$3,700	
Importance Code C	\$14,500			
Total	\$35,600	\$700	\$18,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE EAST BURNSIDE AVENUE

Asset # : 14996

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$7,800	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Stem (breastwall) Concrete	5%	4+	\$106,800	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	95%			LIFE		**		
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	5%	4+	\$56,100	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 40%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	95%			LIFE		**		
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
			<i>Roadway/Path, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE EAST BURNSIDE AVENUE

Asset # : 14996

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%	4+	\$13,300	LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Cracks</i>								
Approaches								
Pavement								
Asphalt	100%	4+	\$74,700	2035	\$747,300	4	\$12,200	
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 7%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$145,800
Pier, Columns								
Steel	100%			LIFE		**	2-8	\$91,600
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Steel	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Railings/Parapets								
Concrete	100%			2043		**	4	\$2,100
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Concrete</i>								
Steel	100%			LIFE		**	2-8	\$1,900
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Steel</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE EAST BURNSIDE AVENUE**

Asset # : 14996

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%	4+	\$8,100	2039	**	5	\$1,800	
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%	4+	\$6,400	2035	\$127,000	5	\$4,300	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$9,000	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Joints								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	**	2-8	\$151,400	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$7,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GRAND CONCOURSE EAST KINGSBRIDGE ROAD
Address : GRAND CONCOURSE BETWEEN E 193RD AND E 196TH STS.
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0255.000 / 14995 Yr Built/Renovated : 1920 /
Area Sq Ft : 18,630 Project Type : HIGHWAY BRIDGES
Date of Survey : 25-Jan-2023 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2242340

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$229,000	\$2,113,500
Total	\$229,000	\$2,113,500
Importance Code A	\$67,400	\$184,400
Importance Code B	\$161,700	\$114,000
Importance Code C		\$1,815,100
Total	\$229,000	\$2,113,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$115,600	\$11,900	\$31,100	
Total	\$115,600	\$11,900	\$31,100	
Importance Code A	\$6,700		\$18,600	
Importance Code B	\$10,300		\$12,500	
Importance Code C	\$98,600	\$11,900		
Total	\$115,600	\$11,900	\$31,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE EAST KINGSBRIDGE ROAD
Asset # : 14995

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Stem (breastwall)								
Concrete Encased Steel	4%	4+	\$161,700	LIFE		**		
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Cracks</i>					
Concrete Encased Steel	96%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	1%	4+	\$18,900	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	99%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Roadway/Path, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
Pier Protection								
Concrete	100%	4+	\$10,300	LIFE		**		
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Cracks</i>					
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE EAST KINGSBRIDGE ROAD

Asset # : 14995

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	5%	4+	\$36,400	2035	\$72,900	4	\$23,800	
			<i>Cracks, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Asphalt	95%			2035	\$1,384,800	4	\$35,700	
Embankment								
Generic	100%			LIFE	**			
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Piers								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$328,100	
			<i>Corrosion, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$2,800	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 3%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Concrete	100%	4+	\$3,900	2043	**	4	\$1,700	
			<i>Cracks, Extent : Light, Area Affected : 3%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 50 Percent Concrete</i>					
Steel	100%			LIFE	**	2-8	\$2,300	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 50 Percent Steel</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE EAST KINGSBRIDGE ROAD
Asset # : 14995

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%	4+	\$7,300	2039	**	5	\$600	
<i>Cracks, Extent : Light, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Asphalt	100%	4+	\$17,900	2035	\$357,500	5	\$12,100	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 80 Percent Asphalt</i>								
Cobblestone	1%	4+	\$18,000	2039	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Spalling</i>								
Cobblestone	99%			2039	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 20 Percent Cobblestone</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	1%	4+	\$67,400	LIFE	**	5	\$20,500	
<i>Cracks, Extent : Light, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	99%			LIFE	**	5	\$20,500	
<hr/>								
Joints								
Not Accessible	100%							
<hr/>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$344,400	
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$17,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GRAND CONCOURSE BRIDGE
Address : GRAND CONCOURSE
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0158.000 / 13566 **Yr Built/Renovated** : 1906 / 2006
Area Sq Ft : 16,100 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 03-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241409

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$194,600	
Total	\$194,600	
Importance Code C	\$194,600	
Total	\$194,600	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$119,600		\$200	
Total	\$119,600		\$200	
Importance Code A	\$38,400		\$200	
Importance Code B	\$2,600			
Importance Code C	\$78,600			
Total	\$119,600		\$200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BRIDGE
Asset # : 13566

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	80%	4+	\$2,600	LIFE			* *	
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Concrete Joint Headers (1 Foot High By 1 Foot Wide)</i>					
			<i>Loose Joint Plates, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
Generic	20%			LIFE			* *	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BRIDGE
Asset # : 13566

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	80%	4+	\$64,900	2042	**	4	\$47,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 20%</i> <i>Location : Northeast</i> <i>Explanation : Steel Plates</i>								
Concrete	20%			2042	**	4	\$71,500	
Curbs								
Concrete w/ Steel Face	100%	4+	\$17,500	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i> <i>Location : 18 Inch Long Broken Piece Of Curb At Southwest Side</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Southeast Approach</i>								
Embankment								
Earth	100%			LIFE	**			
Median								
Concrete	100%	4+	\$4,100	LIFE	**	5	\$700	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%	4+	\$32,400	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 20%</i> <i>Location : Southeast Corner</i> <i>Explanation : Steel Plates</i>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$8,300	LIFE	**			
<i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Median								
Concrete	100%	4+	\$8,500	LIFE	**	5	\$1,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BRIDGE
Asset # : 13566

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets Steel	100%			LIFE	**	2-8	\$5,300	
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Sidewalks Concrete	100%	4+	\$22,400	2038	**	5	\$3,800	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface Concrete	100%	4+	\$129,700	2042	**	5	\$34,400	
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck,Structural Not Accessible	100%							
<hr/>								
Primary Member Not Accessible	100%							
<hr/>								
Secondary Member Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GRAND CONCOURSE BRIDGE GRAND CONCOURSE/EAST 167TH ST
Address : 167TH ST
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0062.000 / 2501 **Yr Built/Renovated** : 1923 /
Area Sq Ft : 38,100 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2242280

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$2,227,200	\$1,258,100
Total	\$2,227,200	\$1,258,100
Importance Code A	\$745,500	\$276,300
Importance Code B	\$1,423,300	\$981,800
Importance Code C	\$58,400	
Total	\$2,227,200	\$1,258,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$668,100		\$111,400	
Total	\$668,100		\$111,400	
Importance Code A	\$73,900		\$1,100	
Importance Code B	\$455,900		\$98,500	
Importance Code C	\$138,300		\$11,900	
Total	\$668,100		\$111,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BRIDGE GRAND CONCOURSE/EAST 167TH ST
Asset # : 2501

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Roadway</i>								
Stem (breastwall)								
Concrete	35%	4+	\$562,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	65%			LIFE		**		
Concrete Encased Steel	70%	4+	\$370,300	LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
Concrete Encased Steel	30%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Roadway Pavement</i>								
Piles								
Not Accessible	100%							
Walls								
Concrete	65%			LIFE		**		
Concrete	35%	4+	\$38,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Mat (scour & erosion)								
Concrete	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BRIDGE GRAND CONCOURSE/EAST 167TH ST
Asset # : 2501

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	60%			2036	**	4	\$23,800	
Asphalt	40%	2-4	\$58,400	2036	**	4	\$23,800	
<i>Cracks, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Along Wingwalls</i>								
<i>Settlement, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout And Along Wingwall Curbs</i>								
<i>Spalling, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	80%			LIFE	**			
Concrete w/ Steel Face	20%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	80%			LIFE	**			
Concrete	20%	4+	\$6,500	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$38,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 20 Percent Of Total</i>								
Pier,Columns								
Steel	98%			LIFE	**	2-8	\$2,316,400	
Steel	2%	4+	\$6,800	LIFE	**	2-8	\$1,413,400	
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Stem,Solid Pier								
Concrete	75%			LIFE	**			
Concrete	25%	4+	\$37,100	LIFE	**			
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout, At The Base Of Columns</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Roadway</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BRIDGE GRAND CONCOURSE/EAST 167TH ST
Asset # : 2501

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	93%			LIFE		**		
Concrete w/ Steel Face	7%	Now	\$1,600	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : West And East Sidewalk</i>								
Gratings								
Steel	100%			LIFE		**		
Median								
Concrete	100%	4+	\$9,200	LIFE		**	5	\$5,100
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%	4+	\$4,400	2044		**	4	\$800
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$3,100
Sidewalks								
Concrete	70%			2040		**	5	\$6,200
Concrete	20%	4+	\$13,900	2040		**	5	\$3,100
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : West Sidewalk</i>								
<i>Explanation : Scaling</i>								
Concrete	10%	2-4	\$13,900	2040		**	5	\$3,100
<i>Cracks, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : East Sidewalk</i>								
<i>Spalling, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : East Sidewalk</i>								
Wearing Surface								
Asphalt	70%			2036		**	5	\$47,100
Asphalt	30%	2-4	\$41,900	2036		**	5	\$23,600
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Near Curbs</i>								
<i>Spalling, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE BRIDGE GRAND CONCOURSE/EAST 167TH ST
Asset # : 2501

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Concrete	80%			LIFE	**	5	\$84,300	
Concrete	20%	4+	\$553,500	LIFE	**	5	\$42,200	
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Primary Member								
Concrete Encased Steel	100%			LIFE	**	5	\$384,000	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GRAND CONCOURSE OVER E.161 ST. GRAND CONCOURSE/E.161 ST.
Address : GRAND CONCOURSE AND E.161 ST.
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0135.000 / 4215 **Yr Built/Renovated** : 1931 / 2008
Area Sq Ft : 24,075 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2242259

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$2,507,800	\$644,000
Total	\$2,507,800	\$644,000
Importance Code A	\$253,900	\$253,900
Importance Code B	\$2,137,200	\$253,900
Importance Code C	\$116,700	\$136,300
Total	\$2,507,800	\$644,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$183,000		\$60,100	
Total	\$183,000		\$60,100	
Importance Code A	\$136,800		\$34,600	
Importance Code B	\$46,200		\$25,500	
Importance Code C				
Total	\$183,000		\$60,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE OVER E.161 ST. GRAND CONCOURSE/E.161 ST.
Asset # : 4215

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 3%</i>								
<i>Location : Near Both Ends Of The Tunnel</i>								
<i>Explanation : Bird Debris</i>								
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Appears To Be Jointless Detail. Approach Slab To Asphalt In Good Condition</i>								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Sidewalk</i>								
Pedestals Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 1%</i>								
<i>Location : Under Deck Joints</i>								
Stem (breastwall) Concrete	100%	4+	\$1,883,400	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Ends Of Bridge</i>								
<i>Explanation : Concrete At Sidewalk</i>								
Piles Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE OVER E.161 ST. GRAND CONCOURSE/E.161 ST.
Asset # : 4215

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Wingwall</i>								
<i>Explanation : Water Stains</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Roadway Pavement</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$116,700	2044		**	4	\$90,700
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044		**	4	
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stainless Steel</i>								
Sidewalks								
Concrete	100%			LIFE		**		
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE OVER E.161 ST. GRAND CONCOURSE/E.161 ST.
Asset # : 4215

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Random Locations Throughout</i>					
Granite	100%			LIFE		**		
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 85 Percent Of Total Curb</i>					
Steel	100%			LIFE		**		
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Primarily At Curbs Not In Plaza</i>					
			<i>Explanation : 15 Percent Of Total Curb</i>					
Gratings								
Steel	100%			LIFE		**		
Median								
Concrete	100%			LIFE		**	5	
Granite	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Lou Gehrig Plaza</i>					
			<i>Explanation : Pavers And Planter Boxes Throughout Plaza</i>					
Mono Deck Surface								
Concrete	100%			2055		**	5	\$136,300
Railings/Parapets								
Concrete	100%			2044		**	4	\$16,700
Steel	100%			LIFE		**	2-8	\$37,400
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stainless Steel</i>					
Sidewalks								
Concrete	100%			2040		**	5	\$16,200
			<i>Cracking/Crumbling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Sidewalks At Fascia</i>					
			<i>Explanation : Concrete Sidewalks At Each Fascia</i>					

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND CONCOURSE OVER E.161 ST. GRAND CONCOURSE/E.161 ST.
Asset # : 4215

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure Deck, Structural Concrete	100%			LIFE	**	5	\$75,300	
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Adjacent To Construction Joints</i> <i>Leakage, Extent : Moderate, Area Affected : 30%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Precast Concrete Deck</i>								
Joints Generic	100%			LIFE	**			
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>								
Primary Member Steel	100%			LIFE	**	2-8	\$812,800	
<i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Peeling Paint.</i>								
Secondary Member Steel	100%			LIFE	**	2-8	\$697,300	
<i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Bird Debris</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GUIDER AVENUE RAMP TO BSHP BELT PARKWAY
Address : GUIDER AVENUE TO WEST BOUND BSHP OFF CONEY ISLAND AVENUE
Borough : BROOKLYN Agency's Number : N/A
Program / Asset # : DOT0222.000 / 14957 Yr Built/Renovated : 2015 /
Area Sq Ft : 10,537 Project Type : HIGHWAY BRIDGES
Date of Survey : 18-Mar-2022 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2231370

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$333,200
Total		\$333,200
Importance Code A		\$333,200
Total		\$333,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$3,300	\$19,600	\$39,100	
Total	\$3,300	\$19,600	\$39,100	
Importance Code A			\$33,900	
Importance Code B			\$2,000	
Importance Code C	\$3,300	\$19,600	\$3,200	
Total	\$3,300	\$19,600	\$39,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUIDER AVENUE RAMP TO BSHP BELT PARKWAY

Asset # : 14957

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE	**			
Backwall Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads Multi-Rotational Bearing	100%			2061	**			
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE	**			
		<i>Corrosion, Extent : Moderate, Area Affected : 90%</i>						
		<i>Location : Throughout</i>						
Mat (scour & erosion) Generic	100%			LIFE	**			
Pedestals Concrete	100%			LIFE	**			
Stem (breastwall) Concrete	100%			LIFE	**			
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE	**			
Piles Not Accessible	100%							
Walls Masonry: Granite	100%			LIFE	**			
		<i>Other Observation, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Joint Mortar Missing/ Eroded</i>						
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 90%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Asphalt Paving Underneath</i>						
Pier Protection Concrete	100%			LIFE	**			
Approaches								
Pavement Concrete	100%			2042	**	4	\$10,000	
Curbs Concrete	100%			LIFE	**			
Embankment Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUIDER AVENUE RAMP TO BSHP BELT PARKWAY

Asset # : 14957

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Guide Railing								
Steel	100%			LIFE	**	2-8	\$2,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Northeast Approach Only</i>								
<i>Explanation : Steel Guide Rail</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Masonry	100%			2042	**			
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast Approach</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
Pier,Columns								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2036	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$12,100	
Sidewalks								
Concrete	100%			2038	**	5	\$6,400	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On East Side</i>								
Wearing Surface								
Concrete	100%			2042	**	5	\$39,200	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
GUIDER AVENUE RAMP TO BSHP BELT PARKWAY

Asset # : 14957

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Superstructure							
Deck, Structural Concrete	100%			LIFE	**	5	\$11,600
	<i>Corrosion, Extent : Light, Area Affected : 5%</i>						
	<i>Location : Random Locations Throughout</i>						
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Covered By Stay In Place Forms</i>						
Primary Member							
Steel	100%			LIFE	**	2-8	\$622,400
	<i>Rust Stains, Extent : Light, Area Affected : 2%</i>						
	<i>Location : Random Locations Throughout</i>						
Secondary Member							
Steel	100%			LIFE	**	2-8	\$31,300
	<i>Rust Stains, Extent : Light, Area Affected : 2%</i>						
	<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GUN HILL ROAD BRONX BLVD
Address : E. GUN HILL ROAD OVER BRONX BLVD
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0310.000 / 15068 **Yr Built/Renovated** :
Area Sq Ft : 8,004 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 14-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2242430

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$388,800	
Total	\$388,800	
Importance Code A	\$326,000	
Importance Code C	\$62,800	
Total	\$388,800	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$37,300		\$2,600	
Total	\$37,300		\$2,600	
Importance Code A	\$2,300		\$600	
Importance Code B	\$31,500			
Importance Code C	\$3,500		\$2,000	
Total	\$37,300		\$2,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUN HILL ROAD BRONX BLVD
Asset # : 15068

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE			**	
Backwall								
Concrete	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Southwest End</i>					
			<i>Explanation : Scaling Of Concrete Surface</i>					
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Buried By Wearing Surface</i>					
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout Concrete Surface</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Southwest End On Brick Facade</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 80%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Brick Facade</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Brick Facade</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	

Approaches

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUN HILL ROAD BRONX BLVD
Asset # : 15068

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%			2036	**	4	\$4,000	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : West Approach</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout Brick Fascia</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Missing Mortar Joints In Brick Fascia</i>								
Masonry	100%			2044	**			
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : All Corners</i>								
<i>Explanation : 4 Scuppers</i>								
Piers								
Cap Beam								
Concrete Encased Steel	100%	4+	\$67,100	LIFE	**	5	\$26,200	
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Eastern Side</i>								
<i>Explanation : Spalling With Exposed Rebars</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUN HILL ROAD BRONX BLVD
Asset # : 15068

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns Concrete	100%	4+	\$31,500	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Brick Facade</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$6,000
Sidewalks								
Concrete	100%	4+	\$62,800	2040		**	5	\$2,800
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Surface Peeling</i>								
Wearing Surface								
Asphalt	100%			2036		**	5	\$7,000
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
Primary Member								
Concrete Encased Steel	100%	4+	\$258,800	LIFE		**	5	\$40,300
<i>Delaminations, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUN HILL ROAD BRONX BLVD
Asset # : 15068

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GUY R. BREWER BLVD BRIDGE
Address : GUY R. BREWER BOULEVARD OVER BELT - SOUTHERN PARKWAY
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0173.000 / 13668 **Yr Built/Renovated** :
Area Sq Ft : 7,300 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 30-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231610

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$193,300	\$193,300
Total	\$193,300	\$193,300
Importance Code A	\$72,300	\$72,300
Importance Code B	\$121,000	\$121,000
Total	\$193,300	\$193,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$158,600		\$22,600	
Total	\$158,600		\$22,600	
Importance Code A	\$38,900		\$10,400	
Importance Code B	\$58,800		\$12,100	
Importance Code C	\$60,900			
Total	\$158,600		\$22,600	



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
GUY R. BREWER BLVD BRIDGE
Asset # : 13668

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE			**	
	<i>Rust Stains, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
<hr/>								
Backwall Concrete	20%	2-4	\$20,600	LIFE			**	
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Delaminations, Extent : Light, Area Affected : 3%</i>							
	<i>Location : Both Sides</i>							
	<i>Efflorescence, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Leakage, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Both Sides Of South Abutment With Severe Cases At West Fascia</i>							
Concrete	80%			LIFE			**	
<hr/>								
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2063			**	
	<i>Corrosion, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Rust Stains, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Paint Peeling</i>							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Joint with Deck								
Generic	100%	2-4	\$4,700	LIFE			**	
	<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 50%</i>							
	<i>Location : Random Locations Throughout</i>							
<hr/>								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
	<i>Joints Missing, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Granite Rock Pavers</i>							
<hr/>								
Pedestals								
Concrete	100%			LIFE			**	
	<i>Rust Stains, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUY R. BREWER BLVD BRIDGE
Asset # : 13668

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Stem (breastwall) Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : South Abutment</i>								
<i>Explanation : Scaling</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%	4+	\$15,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Southwest Wingwall</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout Except Southwest Wingwall</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Roadway</i>								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Barrier</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$8,300	2044		**	4	\$8,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUY R. BREWER BLVD BRIDGE
Asset # : 13668

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	4+	\$2,000	LIFE		**		
<i>Delaminations, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On Steel Face</i>								
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northwest And Southeast Approaches</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Along Steel Face</i>								
<i>Explanation : Edge Spalls</i>								
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044		**	4	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast Approach</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations On Fence</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet Throughout. Vegetation Growth</i>								
Sidewalks								
Concrete	100%	4+	\$6,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Approach</i>								
Piers								
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$230,200
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Base Plates, Bracings And Random Locations</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : The Condition Of Base Plate And Upper Braces Are Recorded With The Column. Light Paint Peeling On 5 Percent Area Of Base Plates.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUY R. BREWER BLVD BRIDGE
Asset # : 13668

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Pier</i>								
<i>Explanation : Scaling</i>								
<hr/>								
Brngs,Ancr Blts,Pads Multi-Rotational Bearing	100%			2063		**		
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout Except Abutment Side Of End Piers</i>								
<i>Explanation : Roadway</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Delaminations, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Steel Face</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Along Steel Face</i>								
<i>Explanation : Edge Spalls</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2044		**	4	\$5,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast Corner</i>								
Steel	100%			LIFE		**	2-8	\$13,000
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Top Of Concrete Parapet</i>								
<i>Explanation : Chain Link Fence</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUY R. BREWER BLVD BRIDGE
Asset # : 13668

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2040	**	5	\$7,500	
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout With Areas Of Map Cracking</i>								
Wearing Surface								
Concrete	100%	4+	\$10,900	2044	**	5	\$24,100	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Worst Cases Near Deck Joints.</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout With Severe Cases On Southwest Corner.</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$15,600	
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Underside Of Deck Throughout</i>								
<i>Explanation : Stay In Place Forms</i>								
Joints								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Debris</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$231,300	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Moderate Cases Along Bottom Flanges</i>								
<i>Explanation : Peeling Paint</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$198,500	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Peeling Paint</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GUYON AVENUE SIRT SOUTH SHORE
Address : GUYON AVE BET. N. RAILROAD AVE AND S. RAILROAD AVE
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0257.000 / 15011 **Yr Built/Renovated** :
Area Sq Ft : 7,926 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249380

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$14,100		\$3,600	
Total	\$14,100		\$3,600	
Importance Code A	\$7,300		\$100	
Importance Code B	\$1,200			
Importance Code C	\$5,600		\$3,400	
Total	\$14,100		\$3,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
GUYON AVENUE SIRT SOUTH SHORE
Asset # : 15011

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Buried By Asphalt</i>					
Mat (scour & erosion)								
Generic	100%	4+	\$1,200	LIFE		**		
			<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : North Side On Both Abutments</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access To 80 Percent Area. Concrete Pavers</i>					
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railroad Tracks</i>					
Approaches								
Pavement								
Asphalt	10%	4+	\$2,400	2036		**	4	\$6,900
			<i>Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Across Pavements On Both Approaches Near Deck And Random Locations</i>					
Asphalt	90%			2036		**	4	\$6,900

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUYON AVENUE SIRT SOUTH SHORE
Asset # : 15011

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Approaches							
Curbs							
Concrete	100%			LIFE		**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Recent Replace Evident, Extent : N/A, Area Affected : 20%</i>							
<i>Location : Southeast Corner</i>							
<hr/>							
Embankment							
Not Accessible	100%						
<hr/>							
Mat (scour & erosion)							
Not Accessible	100%						
<hr/>							
Pavement Base							
Not Accessible	100%						
<hr/>							
Sidewalks							
Concrete	100%			LIFE		**	
<i>Cracks, Extent : Light, Area Affected : 10%</i>							
<i>Location : Random Locations On East Side</i>							
<i>Recent Replace Evident, Extent : N/A, Area Affected : 40%</i>							
<i>Location : Southeast And Northeast Corners</i>							
<hr/>							
Piers							
Cap Beam							
Concrete	100%			LIFE		**	
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>							
<i>Location : Random Locations Throughout</i>							
<hr/>							
Pier,Columns							
Concrete	100%			LIFE		**	
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>							
<i>Location : Random Locations Throughout</i>							
<hr/>							
Stem,Solid Pier							
Concrete	100%			LIFE		**	
<i>Other Observation, Extent : Light, Area Affected : 30%</i>							
<i>Location : Random Locations Throughout</i>							
<i>Explanation : Peeling Paint</i>							
<hr/>							
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
<hr/>							
Footings							
Not Accessible	100%						
<hr/>							
Mat (scour & erosion)							
Generic	100%			LIFE		**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
<i>Location : Throughout</i>							
<i>Explanation : Railway Ballast</i>							
<hr/>							
Pedestals							
Not Accessible	100%						
<hr/>							
Piles							
Not Accessible	100%						
<hr/>							
Deck Elements							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GUYON AVENUE SIRT SOUTH SHORE
Asset # : 15011

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%	4+	\$2,700	2055	**			
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Along Edges</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Railings/Parapets								
Steel	100%	Now	\$4,700	LIFE	**	2-8	\$3,300	
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On Bottom Rails And Post Bases</i>								
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On Fence Posts</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Steel Railing</i>								
Sidewalks								
Concrete	100%			2040	**	5	\$4,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 15%</i>								
<i>Location : On Both Sides</i>								
<i>Explanation : Recent Repair Evident</i>								
Wearing Surface								
Asphalt	100%			2036	**	5	\$6,400	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Along Pier And Random Locations</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HAMILTON PLACE 495 - LONG ISLAND EXPRESSWAY
Address : HAMILTON PL. BETWEEN BORDEN AVE. AND HULL AVE.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0276.000 / 15030 **Yr Built/Renovated** :
Area Sq Ft : 11,152 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 31-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2065930

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$26,200		\$3,000	
Total	\$26,200		\$3,000	
Importance Code A	\$6,400		\$300	
Importance Code C	\$19,700		\$2,700	
Total	\$26,200		\$3,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON PLACE 495 - LONG ISLAND EXPRESSWAY

Asset # : 15030

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Granite	100%			LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Moderate, Area Affected : 25%</i> <i>Location : Northeast Side Behind The Curb</i> <i>Explanation : Vegetation Growth</i>								
Embankment								
Not Accessible	100%							
Guide Railing								
Steel	100%			LIFE	**	2-8	\$5,500	
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%	Now	\$2,500	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Settlement, Extent : Moderate, Area Affected : 2%</i> <i>Location : Southeast Approach Near Joint</i> <i>Other Observation, Extent : Moderate, Area Affected : 2%</i> <i>Location : Southeast Approach Near Joint</i> <i>Explanation : 2 By 2 Feet Concrete Approach Sidewalk Is Cracked And Settled</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Northwest Approach</i> <i>Explanation : 1 Scupper</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON PLACE 495 - LONG ISLAND EXPRESSWAY

Asset # : 15030

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Granite	100%			LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout Along Inside Granite Curb Line</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$11,300
Sidewalks								
Concrete	100%			2040		**	5	\$5,200
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$17,200	2044		**	5	\$23,900
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HARBOR ROAD CONRAIL - EXB&O RR
Address : HARBOR ROAD BET. LEYDEN AVENUE AND RICHMOND TERRACE
Borough : STATEN ISLAND Agency's Number : N/A
Program / Asset # : DOT0227.000 / 14966 Yr Built/Renovated : 1935 /
Area Sq Ft : 5,761 Project Type : HIGHWAY BRIDGES
Date of Survey : 24-Feb-2023 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2249180

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$62,600	\$2,100	\$200	
Total	\$62,600	\$2,100	\$200	
Importance Code A	\$13,300	\$2,100	\$200	
Importance Code B	\$3,500			
Importance Code C	\$45,800			
Total	\$62,600	\$2,100	\$200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARBOR ROAD CONRAIL - EXB&O RR
Asset # : 14966

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$3,500	LIFE				**
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Walls Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE				**
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railroad Tracks</i>					
Pier Protection Not Accessible	100%							
Approaches								
Pavement Concrete	100%	4+	\$16,100	2043		**	4	\$11,000
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Near Joints</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARBOR ROAD CONRAIL - EXB&O RR
Asset # : 14966

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Curbs								
Concrete w/ Steel Face	100%	4+	\$3,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Along Concrete - Steel Interface</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Guide Rails</i>								
Sidewalks								
Concrete	100%	4+	\$3,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARBOR ROAD CONRAIL - EXB&O RR
Asset # : 14966

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$9,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Along Concrete - Steel Interface</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2043		**	4	\$6,200
Steel	100%			LIFE		**	2-8	\$5,700
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$8,800	2039		**	5	\$1,700
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$17,900	2043		**	5	\$11,000
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Joints								
Not Accessible	100%							
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HARLEM RIVER DRIVE NORTHBOUND NB HRD RAMP TO E 127TH ST
Address : E. 127TH ST AT HARLEM RIVER DR.
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0400.000 / 15476 **Yr Built/Renovated** : 2018 /
Area Sq Ft : 46,038 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 29-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2233052

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$50,700
Total		\$50,700
Importance Code A		\$50,700
Total		\$50,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$16,400			
Total	\$16,400			
Importance Code A	\$16,400			
Importance Code B				
Total	\$16,400			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE NORTHBOUND NB HRD RAMP TO E 127TH ST
Asset # : 15476

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE	**			
Backwall								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2053	**			
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Stem (breastwall)								
Concrete	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE	**			
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 80%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Asphalt Paving Underneath</i>						
Approaches								
Pavement								
Not Accessible	100%							
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4	\$3,300	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Scupper								
Not Accessible	100%							

Piers

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE NORTHBOUND NB HRD RAMP TO E 127TH ST
Asset # : 15476

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
Pier,Columns								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2053	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2042	**	4	\$46,000	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Not Accessible	100%							
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 4 Scuppers Total</i>								
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$50,700	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations On Central Bay With Longitudinal Joint</i>								
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout On Stay Place Forms</i>								
<i>Efflorescence, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout Except At Overhangs And Central Bay With Longitudinal Joint</i>								
<i>Explanation : Stay In Place Forms</i>								
Joints								
Not Accessible	100%							
Primary Member								
Prestressed Concrete I Beam	100%			LIFE	**	5		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE NORTHBOUND NB HRD RAMP TO E 127TH ST
Asset # : 15476

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Secondary Member								
Concrete	100%			LIFE	**	5	\$4,100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HARLEM RIVER DRIVE RAMP TO GWB H.R.D. NB (RAMP)TO E 127TH ST
Address : 172ND ST, AMSTERDAM AVE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0079.000 / 2509 **Yr Built/Renovated** : 1939 /
Area Sq Ft : 112,860 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2267240

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$34,381,300	\$1,910,000
Total	\$34,381,300	\$1,910,000
Importance Code A	\$26,193,400	\$1,500,000
Importance Code B	\$6,181,000	\$274,300
Importance Code C	\$2,006,900	\$135,600
Total	\$34,381,300	\$1,910,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$173,600		\$51,900	
Total	\$173,600		\$51,900	
Importance Code A	\$148,700		\$48,500	
Importance Code B	\$6,800			
Importance Code C	\$18,100		\$3,400	
Total	\$173,600		\$51,900	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE RAMP TO GWB H.R.D. NB (RAMP) TO E 127TH ST
Asset # : 2509

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	40%			LIFE			**	
Generic	60%	Now	\$6,800	LIFE			**	
	<i>Corrosion, Extent : Severe, Area Affected : 60%</i>							
	<i>Location : Beginning Abutment</i>							
	<i>Leakage, Extent : Severe, Area Affected : 60%</i>							
	<i>Location : Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Joint Is Paved Over For Entire Length.</i>							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	50%			LIFE			**	
Concrete	50%	2-4	\$211,500	LIFE			**	
	<i>Cracks, Extent : Severe, Area Affected : 55%</i>							
	<i>Location : Random Locations Per Biennial Inspection Report</i>							
	<i>Efflorescence, Extent : Severe, Area Affected : 40%</i>							
	<i>Location : Light Scaling, Water Stains On Stem Wall Surface Per Biennial Inspection</i>							
	<i>Exposed Reinforcement, Extent : Severe, Area Affected : 50%</i>							
	<i>Location : Random Locations Per Biennial Inspection</i>							
	<i>Spalling, Extent : Severe, Area Affected : 40%</i>							
	<i>Location : Random Locations Per Biennial Inspection</i>							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE RAMP TO GWB H.R.D. NB (RAMP) TO E 127TH ST
Asset # : 2509

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Wingwalls								
Walls								
Concrete	100%	4+	\$133,400	LIFE		**		
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Spans 9 And 10 Left Curtain Wall Per Biennial Inspection</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Brick Fascia</i>								
Approaches								
Pavement								
Asphalt	80%			2036		**	4	\$6,800
Asphalt	20%	4+	\$18,100	2036		**	4	\$6,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete	20%	2-4	\$3,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Near The Joint At 49th Pier</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	80%			LIFE		**		
Concrete w/ Steel Face	75%			LIFE		**		
Concrete w/ Steel Face	25%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains</i>								
Guide Railing								
Concrete	40%			2044		**	4	\$5,200
Concrete	60%	Now	\$68,900	2044		**	4	\$5,200
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 60%</i>								
<i>Location : Heavily Spalled, Random Locations Throughout Exposed Surfaces</i>								
Pavement Base								
Not Accessible	100%							

Piers

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE RAMP TO GWB H.R.D. NB (RAMP) TO E 127TH ST
Asset # : 2509

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier, Columns Concrete	35%	2-4	\$3,155,800	LIFE		**		
			<i>Cracks, Extent : Severe, Area Affected : 30%</i>					
			<i>Location : Throughout</i>					
			<i>Spalling, Extent : Severe, Area Affected : 30%</i>					
			<i>Location : Throughout</i>					
Concrete	25%	Now	\$2,254,100	LIFE		**		
			<i>Delaminations, Extent : Severe, Area Affected : 40%</i>					
			<i>Location : Spans 1 To 11</i>					
			<i>Spalling, Extent : Severe, Area Affected : 40%</i>					
			<i>Location : Spans 1 To 11</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Vegetation Growth</i>					
Concrete	40%			LIFE		**		
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$272,700	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations On West Side And Median Island</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations On West Side</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 5%</i>					
			<i>Location : Random Locations On West Side</i>					
			<i>Explanation : Vegetation Growth</i>					
Median								
Concrete	80%			LIFE		**	5	\$46,200
Concrete	20%	4+	\$183,100	LIFE		**	5	\$23,100
			<i>Cracks, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE		**	4-8	\$190,000

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE RAMP TO GWB H.R.D. NB (RAMP) TO E 127TH ST
Asset # : 2509

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Concrete	80%			2044	**	4	\$47,100	
Concrete	20%	0-2	\$353,800	2044	**	4	\$47,100	
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Sidewalks								
Concrete	70%			2040	**	5	\$80,400	
Concrete	30%	2-4	\$893,800	2040	**	5	\$40,200	
<i>Cracks, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Vegetation Growth</i>								
<hr/>								
Wearing Surface								
Asphalt	70%			2036	**	5	\$135,600	
Asphalt	30%	4+	\$263,500	2036	**	5	\$67,800	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rutting</i>								
<hr/>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 24 Scuppers</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	25%			LIFE	**	5	\$324,600	
Concrete	75%	4+	\$17,481,200	LIFE	**	5	\$162,300	
<i>Broken, Missing Pave, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Under Span 11</i>								
<i>Explanation : Recent Repairs Evident</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE RAMP TO GWB H.R.D. NB (RAMP) TO E 127TH ST
Asset # : 2509

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Generic	25%			LIFE		**		
Generic	75%	Now	\$648,500	LIFE		**		
<i>Leakage, Extent : Severe, Area Affected : 60%</i>								
<i>Location : Most Of The Joints, Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Most Of The Joints, Throughout</i>								
<i>Explanation : Paved Over</i>								
Primary Member								
Concrete	60%			LIFE		**	5	\$928,900
Concrete	40%	2-4	\$6,960,400	LIFE		**	5	\$464,500
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Various, Throughout Arches</i>								
<i>Spalling, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Various, Throughout Arches</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Vegetation Growth</i>								
Steel	100%			LIFE		**	2-8	\$715,200
Secondary Member								
Concrete	80%			LIFE		**	5	\$274,300
Concrete	20%	4+	\$338,700	LIFE		**	5	\$137,200
<i>Spalling, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete Encased Steel	85%			2063		**		
Concrete Encased Steel	15%	4+	\$83,700	2063		**		
<i>Corrosion, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HARLEM RIVER DRIVE SOUTHBOUND NB HRD RAMP TO E 127TH ST
Address : E. 127TH ST AT HARLEM RIVER DR.
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0286.000 / 15044 **Yr Built/Renovated** : 2017 /
Area Sq Ft : 55,702 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 29-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2233051

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$61,300
Total		\$61,300
Importance Code A		\$61,300
Total		\$61,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$15,900			
Total	\$15,900			
Importance Code A	\$15,900			
Importance Code B				
Total	\$15,900			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE SOUTHBOUND NB HRD RAMP TO E 127TH ST
Asset # : 15044

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE	**			
Backwall Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads Elastomeric	100%			2053	**			
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Pedestals Concrete	100%			LIFE	**			
Stem (breastwall) Concrete	100%			LIFE	**			
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Piles Not Accessible	100%							
Walls Masonry	100%			LIFE	**			
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Asphalt Paved Underneath</i>						
Approaches								
Pavement Not Accessible	100%							
Embankment Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pavement Base Not Accessible	100%							
Railings/Parapets Concrete	100%			2042	**	4	\$2,300	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Scupper Not Accessible	100%							
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE SOUTHBOUND NB HRD RAMP TO E 127TH ST
Asset # : 15044

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam Concrete	100%			LIFE	**			
Pier,Columns Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads Elastomeric	100%			2053	**			
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Pedestals Concrete	100%			LIFE	**			
Piles Not Accessible	100%							
Deck Elements								
Railings/Parapets Concrete	100%			2042	**	4	\$45,400	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Wearing Surface Not Accessible	100%							
Scupper Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 11 Scuppers Total</i>						
Superstructure								
Deck,Structural Concrete	100%			LIFE	**	5	\$61,300	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations On Central Bay With Longitudinal Joint</i>						
		<i>Corrosion, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout On Stay In Place Forms</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 95%</i>						
		<i>Location : Throughout Except At Overhangs And Central Bay With Longitudinal Joint</i>						
		<i>Explanation : Stay In Place Forms</i>						
Joints Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARLEM RIVER DRIVE SOUTHBOUND NB HRD RAMP TO E 127TH ST
Asset # : 15044

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Primary Member								
Prestressed Concrete I Beam	100%			LIFE	**	5		
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations On Bottom Flanges</i> <i>Explanation : Rust Stains</i>								
Secondary Member								
Concrete	100%			LIFE	**	5	\$5,500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HEMPSTEAD AVENUE BELT SYSTEM CROSS ISLAND RAMP NB
Address : HEMPSTEAD AVE OVER CROSS ISLAND PKWY RAMP NB, QUEENS VILLAGE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0329.000 / 15188 **Yr Built/Renovated** : 1935 /
Area Sq Ft : 9,710 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2266149

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$449,500
Total		\$449,500
Importance Code A		\$99,100
Importance Code B		\$38,100
Importance Code C		\$312,300
Total		\$449,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$66,900	\$1,200	\$13,800	
Total	\$66,900	\$1,200	\$13,800	
Importance Code A	\$4,400		\$10,000	
Importance Code B			\$3,800	
Importance Code C	\$62,500	\$1,200		
Total	\$66,900	\$1,200	\$13,800	



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
HEMPSTEAD AVENUE BELT SYSTEM CROSS ISLAND RAMP NB
Asset # : 15188

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 90%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stem Consists Of 10 Percent Concrete, 90 Percent Not Accessible.</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Vegetation Growth, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Southwest Wingwall</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HEMPSTEAD AVENUE BELT SYSTEM CROSS ISLAND RAMP NB
Asset # : 15188

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%	Now	\$49,800	2033	\$249,000	4	\$7,700	
<i>Cracks, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Both Approaches</i>								
<i>Spalling, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Southeast Approach</i>								
<i>Explanation : Uneven Surface And Potholes Present</i>								
Curbs								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%	2-4	\$2,200	LIFE		**	5	\$200
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Vegetation Growth</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Both Approach Sidewalks</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Southeast Approach</i>								
<i>Explanation : 1 Observed - Clogged With Debris</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$229,100
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Cap Beam Consists Of 10 Percent Steel, 90 Percent Not Accessible.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HEMPSTEAD AVENUE BELT SYSTEM CROSS ISLAND RAMP NB
Asset # : 15188

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns Steel	100%			LIFE	**	2-8	\$109,800	
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pier, Columns Consist Of 10 Percent Steel, 90 Percent Not Accessible.</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Median Concrete	12%	2-4	\$2,200	LIFE	**	5	\$400	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	88%			LIFE	**	5	\$400	
Railings/Parapets Steel	100%			LIFE	**	2-8	\$700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides</i>								
<i>Explanation : Chain Link Fence Behind Steel Bridge Railing With Minor Dried Vegetation</i>								
Sidewalks Concrete	100%			2037	**	5	\$2,300	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface Asphalt	100%	0-2	\$12,700	2033	\$63,300	5	\$4,000	
<i>Cracks, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Uneven Surface</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HEMPSTEAD AVENUE BELT SYSTEM CROSS ISLAND RAMP NB
Asset # : 15188

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HEN HUD PKWAY VIADUCT BRIDGE HHP VIADUCT/W72 ST TO W79 ST
Address : W. 72ST TO W. 79ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0009.000 / 2444 **Yr Built/Renovated** : 1937 /
Area Sq Ft : 232,394 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2229289

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$419,200	\$144,900
Total	\$419,200	\$144,900
Importance Code A	\$325,600	\$51,300
Importance Code C	\$93,600	\$93,600
Total	\$419,200	\$144,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$6,500		\$400	
Total	\$6,500		\$400	
Importance Code A	\$6,500		\$400	
Total	\$6,500		\$400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HEN HUD PKWAY VIADUCT BRIDGE HHP VIADUCT/W72 ST TO W79 ST
Asset # : 2444

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Bank Protection								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Piers								
Cap Beam								
Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Pier Components Are Not Accessible As The Spans Are Over Railroad Tracks</i>						
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Gratings								
Steel	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Placed Over Median Barrier</i>						
Median								
Concrete	100%	4+	\$105,100	LIFE		**	5	\$51,300
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Rust Stains, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Scrape Marks And Scaling</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HEN HUD PKWAY VIADUCT BRIDGE HHP VIADUCT/W72 ST TO W79 ST
Asset # : 2444

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Concrete	100%	4+	\$220,500	2044	**	4	\$84,400	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Scape Marks And Scaling</i>								
Steel	100%			LIFE	**	2-8	\$16,900	
Wearing Surface Asphalt	100%			2036	**	5	\$187,200	
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 24 Scuppers</i>								
Superstructure								
Deck,Structural Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : Deck And Superstructural Components Are Not Accessible As The Spans Are Over Railroad Tracks</i>								
Joints Generic	100%			LIFE	**			
Primary Member Not Accessible	100%							
Secondary Member Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HENRY HUDSON PKWY, W. 158TH ST. HENRY HUDSON PKWY/W 158 ST
 Address : HENRY HUDSON PKWY AT W. 158TH ST
 Borough : MANHATTAN Agency's Number : N/A
 Program / Asset # : DOT0011.090 / 2820 Yr Built/Renovated : 1939 /
 Area Sq Ft : 140,000 Project Type : HIGHWAY BRIDGES
 Date of Survey : 19-Oct-2020 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2229349

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$4,860,800	\$4,133,700
Total	\$4,860,800	\$4,133,700
Importance Code A	\$4,494,600	\$1,522,600
Importance Code B	\$105,100	\$1,685,000
Importance Code C	\$261,200	\$926,200
Total	\$4,860,800	\$4,133,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$74,900		\$308,000	\$40,100
Total	\$74,900		\$308,000	\$40,100
Importance Code A	\$26,900		\$139,000	\$27,400
Importance Code B	\$10,100		\$169,000	
Importance Code C	\$37,800			\$12,700
Total	\$74,900		\$308,000	\$40,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HENRY HUDSON PKWY, W. 158TH ST. HENRY HUDSON PKWY/W 158 ST
Asset # : 2820

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$1,800	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Signs Of Water Leakage Through Joints</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	2-4	\$10,100	LIFE			**	
<i>Loose Joint Plates, Extent : Moderate, Area Affected : 90%</i>								
<i>Location : South End</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : South End And North Abutments</i>								
<i>Explanation : Uneven Surface Of Expansion Joint Cover Observed At South End. Also, North Abutment Not Accessible</i>								
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pedestals								
Concrete	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%	4+	\$105,100	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Both Abutments</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Water Seepage</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HENRY HUDSON PKWY, W. 158TH ST. HENRY HUDSON PKWY/W 158 ST
Asset # : 2820

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	100%	4+	\$37,800	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Wingwalls At Both Abutments</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : South Wingwall West Face</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout All Wingwalls</i>								
<i>Explanation : Missing Mortar Between And Underneath Granite Coping Stones</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Approaches								
Pavement								
Asphalt	100%			2033	\$599,500	4	\$9,800	
Concrete	100%			2041	**	4	\$15,700	
Embankment								
Generic	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Median								
Concrete	100%			LIFE	**	5		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041	**	4		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : End Approach</i>								
<i>Explanation : Concrete Barrier</i>								
Steel	100%			LIFE	**			
Piers								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$861,700	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Median								
Concrete	100%			LIFE	**	5	\$31,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HENRY HUDSON PKWY, W. 158TH ST. HENRY HUDSON PKWY/W 158 ST
Asset # : 2820

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Concrete	20%	4+	\$25,100	2041	**	4	\$54,800	
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : East And West Fascia At Bottom Of Light pole</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains</i>								
Concrete	80%			2041	**	4	\$54,800	
Steel	100%			LIFE	**	2-8		
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$185,900	2041	**	5	\$326,700	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 1%</i>								
<i>Location : South Abutment West Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : 51 Scuppers Observed</i>								
Superstructure								
Deck,Structural								
Concrete	100%	2-4	\$4,494,600	LIFE	**	5	\$136,900	
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Exposed Rebar With Light Corrosion</i>								
Joints								
Generic	100%	2-4	\$75,300	LIFE	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Leakage, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HENRY HUDSON PKWY, W. 158TH ST. HENRY HUDSON PKWY/W 158 ST
Asset # : 2820

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$2,588,100	
		<i>Corrosion, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Loss of Section, Extent : Light, Area Affected : 5%</i>						
		<i>Location : At End Of Overhang Brackets</i>						
		<i>Other Observation, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Paint Peeling</i>						
Secondary Member								
Steel	100%			LIFE	**	2-8	\$2,168,100	
		<i>Corrosion, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HENRY HUDSON PKWY. BRIDGE HENRY HUD PKY/AMTRAK 30 ST LINE
Address : AMTRAK, 94TH-98TH ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0080.000 / 2510 **Yr Built/Renovated** : 1936 /
Area Sq Ft : 60,258 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2267250

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$599,100	\$494,000
Total	\$599,100	\$494,000
Importance Code A	\$256,400	
Importance Code C	\$342,700	\$494,000
Total	\$599,100	\$494,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$73,100	\$1,400	\$400	
Total	\$73,100	\$1,400	\$400	
Importance Code A	\$39,400		\$400	
Importance Code C	\$33,700	\$1,400		
Total	\$73,100	\$1,400	\$400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HENRY HUDSON PKWY. BRIDGE HENRY HUD PKY/AMTRAK 30 ST LINE
Asset # : 2510

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : No Access To Tracks</i>							
Backwall								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : No Access To Tracks</i>							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : No Access To Tracks</i>							
Footings								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : No Access To Tracks</i>							
Joint with Deck								
Generic	100%			LIFE			**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Recent Repair Evident</i>							
Mat (scour & erosion)								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : No Access To Tracks</i>							
Pedestals								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : No Access To Tracks</i>							
Stem (breastwall)								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : No Access To Tracks</i>							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HENRY HUDSON PKWY. BRIDGE HENRY HUD PKY/AMTRAK 30 ST LINE
Asset # : 2510

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	100%	Now	\$33,700	2033	\$337,300	4	\$4,800	
			<i>Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 3%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	100%	0-2	\$124,400	2041	**	4	\$33,900	
			<i>Cracks, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete	100%			LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Generic	100%			LIFE	**			
Guide Railing								
Concrete	50%	4+	\$16,000	2041	**	4	\$1,700	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Both Approaches</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : On West Side</i>					
			<i>Explanation : Concrete Guide Rail</i>					
Concrete	50%	Now	\$16,000	2041	**	4	\$1,700	
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : 95th Street Approach</i>					
			<i>Explanation : Impact Damage. Masonry Guide Rail On East Side</i>					
Steel	100%	0-2	\$2,900	LIFE	**	2-8	\$5,800	
			<i>Corrosion, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Begin Approach</i>					
			<i>Loss of Section, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HENRY HUDSON PKWY. BRIDGE HENRY HUD PKY/AMTRAK 30 ST LINE
Asset # : 2510

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Masonry	100%	0-2	\$4,100	2041				**
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : W-95th Street Approach</i>					
			<i>Explanation : Impact Damage</i>					
Steel	100%			LIFE				**
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	2%	4+	\$500	2052				**
			<i>Cracks, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	98%			2052				**
Gratings								
Steel	100%			LIFE				**
			<i>Other Observation, Extent : N/A, Area Affected : 10%</i>					
			<i>Location : Spans 1 And 3</i>					
			<i>Explanation : Rusted Areas, The Gratings Cover The Air Vents. Vents In Span 3 Are Good</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HENRY HUDSON PKWY. BRIDGE HENRY HUD PKY/AMTRAK 30 ST LINE
Asset # : 2510

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Guide Railing Concrete	100%			2045	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout East Side</i> <i>Explanation : Missing Joint Mortar. Guide Rail Consists Of Masonry And Is Only On East Side.</i>								
Mono Deck Surface Concrete	100%	4+	\$110,900	2052	**	5	\$156,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%	4+	\$202,200	2041	**	4	\$30,900	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On West Side</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations On West Side</i>								
Masonry	100%	4+	\$54,200	2041	**	5	\$9,900	
<i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations On East Side, Span 1 Through 6</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : East Side, Span 1 Through 6</i> <i>Explanation : Missing Joint/ Mortar</i>								
Steel	100%			LIFE	**	2-8	\$7,600	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout East Side</i> <i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout East Side</i>								
Sidewalks								
Concrete	100%			2037	**	5	\$2,700	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 12 Scuppers Observed</i>								
Superstructure								
Deck, Structural Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HENRY HUDSON PKWY. BRIDGE HENRY HUD PKY/AMTRAK 30 ST LINE
Asset # : 2510

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Generic	5%	4+	\$107,400	LIFE			**	
	<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Generic	95%			LIFE			**	
	<i>Other Observation, Extent : N/A, Area Affected : 95%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Recent Repair Evident</i>							
Primary Member								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : No Access To Tracks</i>							
Secondary Member								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location :</i>							
	<i>Explanation : No Access To Tracks</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HIGHLAND BOULEVARD WB JACKIE ROBINSON PKWY EB ENTRAMP
 Address : HIGHLAND BLVD OVER JACKIE ROBINSON PKWY EB ENTRANCE RAMP
 Borough : BROOKLYN Agency's Number : N/A
 Program / Asset # : DOT0374.000 / 15392 Yr Built/Renovated :
 Area Sq Ft : 4,094 Project Type : HIGHWAY BRIDGES
 Date of Survey : 25-Mar-2022 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2230020

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$134,000	
Total	\$134,000	
Importance Code A	\$134,000	
Total	\$134,000	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$15,400		\$1,000	
Total	\$15,400		\$1,000	
Importance Code A	\$3,500		\$100	
Importance Code C	\$11,900		\$900	
Total	\$15,400		\$1,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HIGHLAND BOULEVARD WB JACKIE ROBINSON PKWY EB ENTRAMP
Asset # : 15392

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Abutments</i>								
<i>Explanation : Concrete Sidewalk Throughout</i>								
Stem (breastwall)								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : North And South End Of Both Abutments</i>								
<i>Explanation : Granite Facing</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE			**	
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Steel	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Guide Rail On West Side Of Pier</i>								
Approaches								
Pavement								
Concrete	100%			2042		4	\$28,400	**
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HIGHLAND BOULEVARD WB JACKIE ROBINSON PKWY EB ENTRAMP
Asset # : 15392

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Corner</i>								
<i>Rust Stains, Extent : Light, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<hr/>								
Embankment								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Concrete	100%	4+	\$2,100	2042		**	4	\$2,500
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northeast Corner</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Southwest Corner</i>								
<i>Explanation : Vegetation Growth</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
<hr/>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Om North Side</i>								
<hr/>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : North And South End Of Both Abutments</i>								
<i>Explanation : Granite Facing</i>								
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Sidewalk On East Side, Asphalt Sidewalk On West Side.</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HIGHLAND BOULEVARD WB JACKIE ROBINSON PKWY EB ENTRAMP
Asset # : 15392

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 40%</i>								
<i>Location : Throughout North Side</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2042		**	4	\$4,100
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$3,800
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : At The Base Of Railing Posts</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
<hr/>								
Sidewalks								
Concrete	100%			2038		**	5	\$1,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout On North Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Northeast Corner</i>								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$2,400	2042		**	5	\$8,100
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Near West Abutment Joint</i>								
<i>Explanation : Potholes</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Concrete	100%	4+	\$134,000	LIFE		**	5	\$21,100
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Over Defect Areas</i>								
<i>Explanation : Primary Member Is Concrete Arch. Covered With Wire Mesh</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HIGHLAWN AVE BRIDGE OVER BMT SEA BEACH LINE
Asset # : 13597

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : Both Abutments</i>						
		<i>Explanation : Abutment Is Behind The Station Platform Wall</i>						
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Both Abutments</i>						
		<i>Leakage, Extent : Light, Area Affected : 2%</i>						
		<i>Location : West Abutment</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 95%</i>						
		<i>Location : Covered By Platform Wall Throughout</i>						
		<i>Explanation : Limited Access</i>						
Walls								
Concrete	100%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Railway Tracks Underneath Bridge</i>						
Approaches								
Pavement								
Concrete	100%			2042		**	4	\$9,100
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
		<i>Rust Stains, Extent : Light, Area Affected : 40%</i>						
		<i>Location : Throughout</i>						
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HIGHLAWN AVE BRIDGE OVER BMT SEA BEACH LINE

Asset # : 13597

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%	4+	\$13,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Concrete	100%	0-2	\$1,400	2042		**	4	\$900
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : At North End</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : At North End</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Railing On North Side Only</i>								
Steel	100%			LIFE		**	2-8	\$1,300
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : North Fascia</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%			2038		**	5	\$6,600
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$4,000	2042		**	5	\$10,600
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Longitudinal Cracks</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE		**	5	\$6,300
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Covered With Stay In Place Forms</i>								
<i>Explanation : Limited Access</i>								
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains</i>								
Secondary Member								
Steel	100%			LIFE		**	2-8	\$175,000
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


**DEPARTMENT OF TRANSPORTATION - 841
 HIGHLAWN AVE BRIDGE OVER BMT SEA BEACH LINE
 Asset # : 13597**

Print Date : 07-Oct-2024 **DEPARTMENT OF TRANSPORTATION - FY 2025**

Asset Name : HOUSTON ST RAMP TO FDR DRIVE NB RELIEF
 Address : HOUSTON ST & FDR DRIVE NB
 Borough : MANHATTAN Agency's Number : N/A
 Program / Asset # : DOT0359.200 / 15382 Yr Built/Renovated :
 Area Sq Ft : 7,125 Project Type : HIGHWAY BRIDGES
 Date of Survey : 15-Mar-2022 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 223204B

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$196,000
Total		\$196,000
Importance Code C		\$196,000
Total		\$196,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$7,000		\$2,000	\$4,100
Total	\$7,000		\$2,000	\$4,100
Importance Code A	\$5,000		\$200	
Importance Code C	\$2,000		\$1,800	\$4,100
Total	\$7,000		\$2,000	\$4,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HOUSTON ST RAMP TO FDR DRIVE NB RELIEF

Asset # : 15382

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE	**			
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Wingwalls Only At North Abutment</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 50 Percent Wingwall Is Not Accessible</i>						
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	100%			2034	\$132,200	4	\$6,100	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Approach Only At North Side</i>						
Embankment								
Not Accessible	100%							
Guide Railing								
Concrete	100%			2042	**	4	\$4,400	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout On East Side</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HOUSTON ST RAMP TO FDR DRIVE NB RELIEF

Asset # : 15382

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Concrete	100%			2042	**	4	\$4,800	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Stem,Solid Pier Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 75%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 75 Percent Of Stem Is Not Accessible</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing Concrete	100%			2046	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Mono Deck Surface								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4	\$5,600	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$5,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On East Side Only</i>								
<i>Explanation : Chain Link Fence Attached To Steel Railing</i>								
Sidewalks								
Concrete	100%			2038	**	5	\$3,600	
Wearing Surface								
Asphalt	100%			2034	\$63,900	5	\$8,100	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HOUSTON STREET OVER FDR DRIVE
Address : HOUSTON STREET OVER FDR DRIVE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0359.000 / 15373 **Yr Built/Renovated** :
Area Sq Ft : 10,951 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 07-Jul-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2232040

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$460,600
Total		\$460,600
Importance Code C		\$460,600
Total		\$460,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$25,700		\$100	\$3,100
Total	\$25,700		\$100	\$3,100
Importance Code A			\$100	\$1,100
Importance Code C	\$25,700			\$2,000
Total	\$25,700		\$100	\$3,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HOUSTON STREET OVER FDR DRIVE
Asset # : 15373

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier, Columns								
Steel	100%			LIFE	**	2-8		
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Median								
Concrete	100%			LIFE	**	5	\$800	
Railings/Parapets								
Concrete	100%			2041	**	4	\$2,300	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE	**	2-8	\$3,100	
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : On Both Sides</i>					
			<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>					
Sidewalks								
Asphalt	100%			2030	\$330,800	4	\$77,200	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : On Both Sides</i>					
			<i>Explanation : Bicycle Tracks Covers 10 Percent Of The Sidewalk</i>					
Concrete	100%			2037	**	5		
Wearing Surface								
Concrete	100%			2041	**	5		
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HUGUENOT AVENUE SIRT SOUTH SHORE
Address : HUGUENOT AVE BET HAWLEY AVE AND AMBOY ROAD
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0261.000 / 15015 **Yr Built/Renovated** :
Area Sq Ft : 5,468 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249300

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$26,000		\$3,000	
Total	\$26,000		\$3,000	
Importance Code A	\$3,700		\$100	
Importance Code C	\$22,300		\$3,000	
Total	\$26,000		\$3,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
HUGUENOT AVENUE SIRT SOUTH SHORE
Asset # : 15015

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Buried By Asphalt Wearing Surface</i>					
Mat (scour & erosion) Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : South Abutment</i>					
			<i>Explanation : Railway Ballasts</i>					
Pedestals Concrete	100%			LIFE			**	
Stem (breastwall) Concrete	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access To Stem</i>					
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : South Side</i>					
			<i>Explanation : Railway Ballasts</i>					
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					

Feature Crossed

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
HUGUENOT AVENUE SIRT SOUTH SHORE
Asset # : 15015

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railroad Tracks</i>								
Approaches								
Pavement								
Asphalt	100%			2036		**	4	\$5,900
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout With Worse Cases Near North Abutment Joint</i>								
Curbs								
Concrete	100%			LIFE		**		
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%	4+	\$2,200	LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Fence Posts And Random Locations</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence</i>								
Sidewalks								
Concrete	100%	Now	\$1,300	LIFE		**		
<i>Cracks, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Northwest Corner</i>								
<i>Settlement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northeast Corner</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Pier Components</i>								
Pier,Columns								
Concrete	100%			LIFE		**		
Stem,Solid Pier								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUGUENOT AVENUE SIRT SOUTH SHORE
Asset # : 15015

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : South Side</i>						
		<i>Explanation : Railway Ballasts</i>						
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
		<i>Rust Stains, Extent : Light, Area Affected : 15%</i>						
		<i>Location : Random Locations Throughout</i>						
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$3,900	
		<i>Corrosion, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Base Of Posts And Random Locations</i>						
		<i>Rust Stains, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Chain Link Fence In Front Of Steel Railings</i>						
Sidewalks								
Concrete	100%	2-4	\$17,300	2040	**	5	\$1,300	
		<i>Cracks, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Scaling</i>						
Wearing Surface								
Asphalt	100%	0-2	\$3,700	2036	**	5	\$2,200	
		<i>Cracks, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout With Worse Cases Near Abutment Joints</i>						
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Along Centerline And Edges Of Roadway</i>						
		<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Right Wheel Path Along Southbound Lane</i>						
		<i>Explanation : Rutting</i>						
Superstructure								
Deck, Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
HUGUENOT AVENUE SIRT SOUTH SHORE
Asset # : 15015**

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							
<hr/>								

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HUNTS POINT AVE. BRIDGE HUNTS POINT AVE./AMTRAK
Address : HUNTS POINT AVE
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0183.000 / 13717 **Yr Built/Renovated** : 1908 / 1992
Area Sq Ft : 13,700 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 09-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241190

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$84,200		\$200	\$5,100
Total	\$84,200		\$200	\$5,100
Importance Code A	\$1,400		\$200	
Importance Code B	\$3,600			
Importance Code C	\$79,200			\$5,100
Total	\$84,200		\$200	\$5,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTS POINT AVE. BRIDGE HUNTS POINT AVE./AMTRAK

Asset # : 13717

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Underside Of Bridge Throughout</i>								
<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	17%	Now	\$3,600	LIFE		**		
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Generic	83%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	80%			2041		**	4	\$10,300
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Scattered Throughout</i>								
Concrete	20%	Now	\$35,500	2041		**	4	\$10,300
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout And Near Supports</i>								
<i>Spalling, Extent : Severe, Area Affected : 40%</i>								
<i>Location : Adjacent To Joints</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTS POINT AVE. BRIDGE HUNTS POINT AVE./AMTRAK

Asset # : 13717

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	4+	\$700	LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Embankment								
Earth	100%			LIFE		**		
<hr/>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South Side Of Bridge</i>								
<i>Explanation : Steel Railing Of One Side Of Bridge Only</i>								
<hr/>								
Sidewalks								
Concrete	100%	Now	\$10,300	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Mono Deck Surface								
Concrete	100%	4+	\$11,700	2052		**	5	\$28,100
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2041		**	4	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : South Side Only</i>								
<i>Explanation : Concrete With Corrugated Steel Sheeting On South Side. No Parapets Due To Building On North Side.</i>								
Steel	100%	4+	\$800	LIFE		**	2-8	\$4,600
<i>Damaged Railing, Extent : Light, Area Affected : 1%</i>								
<i>Location : South Parapet</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$21,700	2037		**	5	\$2,900
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTS POINT AVE. BRIDGE HUNTS POINT AVE./AMTRAK

Asset # : 13717

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%			LIFE		* *		
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HUTCHINSON RIVER PARKWAY BRIDGE
Address : HUTCHINSON RIVER PARKWAY
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0159.000 / 13567 **Yr Built/Renovated** : 1940 /
Area Sq Ft : 15,444 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 16-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241959

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$52,100	\$305,700
Total	\$52,100	\$305,700
Importance Code A		\$305,700
Importance Code C	\$52,100	
Total	\$52,100	\$305,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$124,400	\$38,400	\$33,600	
Total	\$124,400	\$38,400	\$33,600	
Importance Code A	\$88,200		\$32,200	
Importance Code C	\$36,300	\$38,400	\$1,300	
Total	\$124,400	\$38,400	\$33,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE
Asset # : 13567

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	1%	4+	\$5,700	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Joints Missing, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Vegetation Growth, Extent : Light, Area Affected : 30%</i> <i>Location : North Abutment West Face</i>							
Concrete	99%			LIFE		**		
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Railroad Tracks</i>							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE
Asset # : 13567

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	60%	4+	\$52,100	2042	**	4	\$51,000	
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Near Joint</i>								
Concrete	40%			2042	**	4	\$76,500	
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Embankment								
Earth	100%			LIFE	**			
Guide Railing								
Steel	100%	4+	\$29,800	LIFE	**	2-8	\$51,300	
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : South Approach East And West Face</i>								
<i>Explanation : Impact Damage</i>								
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Median								
Concrete	100%			LIFE	**	5		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Masonry	60%	4+	\$11,800	2042	**			
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Missing/ Eroded Joint Mortar And Misaligned Coping Stones</i>								
Masonry	40%			2042	**			
Steel	100%			LIFE	**			
Sidewalks								
Concrete	30%	4+	\$5,100	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Severe, Area Affected : 60%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Dirt Accumulation</i>								
Concrete	70%			LIFE	**			
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE
Asset # : 13567

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At East Side</i>								
<i>Explanation : Only One Side Of The Bridge Has Curbs</i>								
Guide Railing								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At East Side</i>								
<i>Explanation : Only One Side Of The Bridge Has Guide Railings</i>								
Median								
Concrete	100%			LIFE		**	5	\$1,800
Railings/Parapets								
Concrete	100%			2042		**	4	\$3,600
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At West Side</i>								
<i>Explanation : One Side Of The Bridge Has Concrete Parapets</i>								
Steel	100%	4+	\$5,500	LIFE		**	2-8	\$6,700
<i>Corrosion, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			2038		**	5	\$2,700
<i>Other Observation, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Random Locations Throughout On West Side</i>								
<i>Explanation : Dirt Accumulation</i>								
Wearing Surface								
Concrete	100%			2042		**	5	\$76,800
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	92%			LIFE		**	2-8	\$285,500
Steel	8%	4+	\$39,800	LIFE		**	2-8	\$285,500
<i>Corrosion, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : KANE STREET 278I (B.Q.E.)
Address : KANE ST OVER BKLYN QNS EXPWY BET. HENRY ST & COLUMBIA ST
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0303.000 / 15061 **Yr Built/Renovated** : 1952 /
Area Sq Ft : 4,920 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230380

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$10,400		\$3,400	
Total	\$10,400		\$3,400	
Importance Code A	\$2,100		\$100	
Importance Code B	\$2,400			
Importance Code C	\$5,800		\$3,300	
Total	\$10,400		\$3,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
KANE STREET 278I (B.Q.E.)
Asset # : 15061

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	Now	\$2,400	LIFE			**	
			<i>Spalling, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : West Side Joint Header</i>					
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Damaged Joint Fill Material</i>					
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Bank Protection Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 1%</i>					
			<i>Location : South End</i>					
			<i>Explanation : Broken Concrete; 90 Percent Not Accessible</i>					
Approaches								
Pavement Asphalt	100%			2036		**	4	\$6,600
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : West Approach</i>					
Embankment Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pavement Base Not Accessible	100%							
Piers								
Cap Beam Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LAFAYETTE AVE. BRIDGE AMTRAK - CSX
 Address : LAFAYETTE AVE.
 Borough : BRONX Agency's Number : N/A
 Program / Asset # : DOT0181.000 / 13715 Yr Built/Renovated : 1906 /
 Area Sq Ft : 12,000 Project Type : HIGHWAY BRIDGES
 Date of Survey : 09-Nov-2020 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2241169

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$356,300
Total		\$356,300
Importance Code A		\$237,500
Importance Code B		\$118,800
Total		\$356,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$76,700		\$35,900	
Total	\$76,700		\$35,900	
Importance Code A	\$11,300		\$24,000	
Importance Code B			\$11,900	
Importance Code C	\$65,400			
Total	\$76,700		\$35,900	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LAFAYETTE AVE. BRIDGE AMTRAK - CSX
Asset # : 13715

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Underside Of Bridge Throughout</i>							
	<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Not Accessible	100%							
Approaches								
Pavement Concrete	100%	4+	\$28,200	2041		**	4	\$25,700
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Both Approaches</i>							
Curbs Concrete w/ Steel Face	100%			LIFE		**		
	<i>Rust Stains, Extent : Light, Area Affected : 50%</i>							
	<i>Location : Random Locations Throughout</i>							
Embankment Earth	100%			LIFE		**		
Guide Railing Concrete	100%			2041		**	4	
	<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LAFAYETTE AVE. BRIDGE AMTRAK - CSX
Asset # : 13715

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Median								
Concrete	100%			LIFE		**	5	
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : West Side</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 3 Scuppers Observed</i>								
Deck Elements								
Guide Railing								
Concrete	100%			2045		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Median								
Concrete	100%			LIFE		**	5	\$2,800
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Mono Deck Surface								
Concrete	100%	4+	\$17,700	2052		**	5	\$33,400
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LAFAYETTE AVE. BRIDGE AMTRAK - CSX
Asset # : 13715

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Concrete	100%	4+	\$10,600	2041	**	4	\$5,400	
<i>Cracks, Extent : Light, Area Affected : 3%</i>								
<i>Location : North Parapet</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Parapets Are Concrete With Corrugated Metal Sheeting</i>								
Steel	100%			LIFE	**	2-8	\$5,400	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$19,400	2037	**	5	\$5,000	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Steel	99%			LIFE	**	2-8	\$221,800	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 20%</i>								
<i>Location : Below Portion Of Truss</i>								
<i>Explanation : 20 Percent Of Truss Not Accessible</i>								
Steel	1%	4+	\$700	LIFE	**	2-8	\$221,800	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : South Truss</i>								
<i>Explanation : Impact Damage</i>								
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$185,800	
<i>Other Observation, Extent : N/A, Area Affected : 20%</i>								
<i>Location : Below Portion Of Truss</i>								
<i>Explanation : 20 Percent Of Truss Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LEFFERTS BLVD. LIRR MAIN LINE
Address : LEFFERTS BLVD BET. AUDLEY STREET AND AUSTIN STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0272.000 / 15026 **Yr Built/Renovated** :
Area Sq Ft : 5,280 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 05-Jan-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247240

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$108,800	\$52,300
Total	\$108,800	\$52,300
Importance Code A	\$52,300	\$52,300
Importance Code C	\$56,500	
Total	\$108,800	\$52,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$47,800		\$5,600	
Total	\$47,800		\$5,600	
Importance Code A	\$32,500		\$5,200	
Importance Code B	\$9,400		\$300	
Importance Code C	\$5,900			
Total	\$47,800		\$5,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LEFFERTS BLVD. LIRR MAIN LINE
Asset # : 15026

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals Concrete	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Limited Access</i>						
Backwall Not Accessible	100%						
Brngs,Ancr Blts,Pads Not Accessible	100%						
Footings Not Accessible	100%						
Joint with Deck							
Generic	100%	Now	\$5,000	LIFE		**	
	<i>Broken/Missing Elements, Extent : Severe, Area Affected : 10%</i>						
	<i>Location : Broken Steel Armour Near Centerline At West Abutment</i>						
	<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 50%</i>						
	<i>Location : Throughout</i>						
Mat (scour & erosion)							
Generic	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Railway Ballasts</i>						
Pedestals							
Concrete	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Limited Access</i>						
Stem (breastwall)							
Concrete	100%			LIFE		**	
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Railway Ballasts</i>						
Piles							
Not Accessible	100%						
Walls							
Concrete	100%			LIFE		**	
Feature Crossed							
Mat (scour & erosion)							
Generic	100%			LIFE		**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
	<i>Location : Throughout</i>						
	<i>Explanation : Railroad Tracks</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LEFFERTS BLVD. LIRR MAIN LINE
Asset # : 15026

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%	2-4	\$56,500	2044		**	4	\$15,400
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Old Repair, Extent : Light, Area Affected : 5%</i>								
<i>Location : Asphalt Patches On Both Approaches</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations With Worse Cases At Centerline Near West Abutment</i>								
<i>Explanation : Scaling</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$1,400	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Approach</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Along Steel Face On Random Locations</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Concrete Encased Steel	100%			LIFE		**	5	\$27,300
Pier, Columns								
Concrete Encased Steel	100%			LIFE		**	5	\$1,400
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LEFFERTS BLVD. LIRR MAIN LINE
Asset # : 15026

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Ballasts</i>								
Pedestals Steel	100%			LIFE		**		
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Along Steel Face</i>								
Sidewalks Concrete	100%			2040		**	5	\$4,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface Concrete	100%	0-2	\$5,900	2044		**	5	\$9,100
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Old Repair, Extent : Light, Area Affected : 2%</i>								
<i>Location : Asphalt Patch At Centerline Near East Abutment</i>								
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Northwest Corner</i>								
<i>Explanation : Steel Plate Repair</i>								
Superstructure								
Deck, Structural Not Accessible	100%							
Primary Member Steel	100%			LIFE		**	2-8	\$167,300
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Secondary Member Steel	100%			LIFE		**	2-8	\$8,600
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LEGGETT AVENUE AMTRAK - CSX
Address : LEGGETT AVE,BRUCKNER GARRISON
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0055.000 / 2480 **Yr Built/Renovated** : 1906 /
Area Sq Ft : 28,209 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241139

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,382,700	\$642,800
Total	\$1,382,700	\$642,800
Importance Code A	\$280,100	\$280,100
Importance Code B	\$928,000	\$280,100
Importance Code C	\$174,500	\$82,600
Total	\$1,382,700	\$642,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$116,500		\$78,400	
Total	\$116,500		\$78,400	
Importance Code A	\$111,700		\$28,800	
Importance Code B	\$4,800		\$28,100	
Importance Code C			\$21,600	
Total	\$116,500		\$78,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LEGGETT AVENUE AMTRAK - CSX
Asset # : 2480

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$4,800	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : East Approach</i>								
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : Both Abutments</i>								
<i>Explanation : Filled Debris</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	50%			2044		**	4	\$43,200
Concrete	50%	4+	\$91,900	2044		**	4	\$43,200
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : At East Abutment Joint</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LEGGETT AVENUE AMTRAK - CSX
Asset # : 2480

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete	100%			LIFE			**	
Concrete w/ Steel Face	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%	Now	\$1,600	LIFE			**	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 4%</i>								
<i>Location : Northwest Corner</i>								
Sidewalks								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier, Columns								
Not Accessible	100%							
Stem, Solid Pier								
Not Accessible	100%							
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing								
Concrete	5%			2048			**	
Concrete	95%			2048			**	
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : South Outer Barrier</i>								
<i>Explanation : Misaligned Tops</i>								
Median								
Concrete	100%			LIFE		**	5	\$9,900
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$30,400
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LEGGETT AVENUE AMTRAK - CSX
Asset # : 2480

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2040	**	5	\$29,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On North Side</i>								
Wearing Surface								
Concrete	100%			2044	**	5	\$165,200	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$896,700	
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : Did Not Access Underside Of Truss/deck</i>								
Secondary Member								
Steel	100%	4+	\$928,000	LIFE	**	2-8	\$438,300	
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Impact Damage To Top Lateral Cross Frames With Recent Repair Evident In East Truss</i>								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : Did Not Access Underside Of Truss/deck</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LIBERTY AVENUE LIRR BAY RIDGE
Address : LIBERTY AVENUE BET JUNIUS STREET & VAN SINDEREN AVENUE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0298.000 / 15056 **Yr Built/Renovated** :
Area Sq Ft : 6,688 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243850

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$5,900		\$3,000	
Total	\$5,900		\$3,000	
Importance Code A	\$3,100		\$2,000	
Importance Code C	\$2,800		\$1,000	
Total	\$5,900		\$3,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
LIBERTY AVENUE LIRR BAY RIDGE
Asset # : 15056

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Buried By Asphalt Wearing Surface</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
Pier Protection Concrete	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Bottom Of Pier Column</i>						
		<i>Explanation : 5 Feet High Concrete</i>						
Approaches								
Pavement Asphalt	100%			2036		**	4	\$2,000
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
Curbs Concrete w/ Steel Face	100%			LIFE			**	
		<i>Rust Stains, Extent : Light, Area Affected : 25%</i>						
		<i>Location : Random Locations Throughout</i>						
Embankment Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIBERTY AVENUE LIRR BAY RIDGE
Asset # : 15056

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railroad Tracks Below</i>								
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2044	**	4	\$3,600	
Steel	100%			LIFE	**	2-8	\$8,000	
<i>Corrosion, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Top Of Concrete Parapet</i>								
<i>Explanation : Chain Link Fence</i>								
Sidewalks								
Concrete	100%			2040	**	5	\$4,400	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIBERTY AVENUE LIRR BAY RIDGE
Asset # : 15056

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Asphalt	100%			2036	**	5	\$5,600	
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Severe, Area Affected : 2%</i>						
		<i>Location : Near Van Sinderen Avenue</i>						
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LIRR BUSHWICK DIVISION BRIDGE ATLANTIC AVE/LIRR ATLANTIC AVE
 Address : ATLANTIC AVE,EASTERN-GEORGIA
 Borough : BROOKLYN Agency's Number : N/A
 Program / Asset # : DOT0065.000 / 2490 Yr Built/Renovated : 1942 /
 Area Sq Ft : 135,162 Project Type : HIGHWAY BRIDGES
 Date of Survey : 08-Dec-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2243569

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$3,534,800	\$3,336,200
Total	\$3,534,800	\$3,336,200
Importance Code A	\$1,787,600	\$1,589,000
Importance Code B	\$1,425,700	\$1,425,700
Importance Code C	\$321,500	\$321,500
Total	\$3,534,800	\$3,336,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$781,600		\$312,000	
Total	\$781,600		\$312,000	
Importance Code A	\$446,300		\$169,000	
Importance Code B	\$317,300		\$143,000	
Importance Code C	\$18,000			
Total	\$781,600		\$312,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR BUSHWICK DIVISION BRIDGE ATLANTIC AVE/LIRR ATLANTIC AVE
Asset # : 2490

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Brownstone/ Sandstone Facade</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Bottom Of Pier</i>					
			<i>Explanation : About 18 Inches High Concrete</i>					
Approaches								
Pavement								
Asphalt	100%	4+	\$18,000	2036		**	4	\$12,900
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Southeast Approach</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR BUSHWICK DIVISION BRIDGE ATLANTIC AVE/LIRR ATLANTIC AVE
Asset # : 2490

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete	100%			LIFE	**			
		<i>Spalling, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete w/ Steel Face	100%			LIFE	**			
		<i>Corrosion, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Pier, Columns								
Concrete	100%			LIFE	**			
Steel	95%			LIFE	**	2-8	\$207,400	
		<i>Other Observation, Extent : Light, Area Affected : 15%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Peeling Paint And Minor Pitting</i>						
Steel	5%			LIFE	**	2-8	\$207,400	
		<i>Corrosion, Extent : Moderate, Area Affected : 60%</i>						
		<i>Location : Random Locations Throughout</i>						
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : L I R R Tracks</i>						
Piles								
Not Accessible	100%							
Deck Elements								
Median								
Concrete	100%			LIFE	**	5	\$113,100	
Railings/Parapets								
Concrete	100%			2044	**	4	\$69,700	
Granite	100%	4+	\$198,600	LIFE	**			
		<i>Joints Missing, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Top Of The Concrete Barrier</i>						
Wearing Surface								
Concrete	100%			2044	**	5	\$643,000	
Scupper								
Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 96 Scuppers</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR BUSHWICK DIVISION BRIDGE ATLANTIC AVE/LIRR ATLANTIC AVE
Asset # : 2490

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$389,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stay In Place Forms</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$4,282,800	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$3,674,500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LIRR, AMT, CON NE BRIDGE 39 ST(SOUTH)/ AMTRAK, LIRR YARD
 Address : 39TH ST SO, NORTHERN-SKILLMAN
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0074.000 / 2498 Yr Built/Renovated : 1911 /
 Area Sq Ft : 32,550 Project Type : HIGHWAY BRIDGES
 Date of Survey : 08-Dec-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2247640

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$126,900	
Total	\$126,900	
Importance Code C	\$126,900	
Total	\$126,900	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$32,500		\$800	
Total	\$32,500		\$800	
Importance Code A	\$14,000		\$800	
Importance Code C	\$18,400			
Total	\$32,500		\$800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE 39 ST(SOUTH)/ AMTRAK, LIRR YARD
Asset # : 2498

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
			<i>Misaligned/Bulging, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Both Abutments</i>					
			<i>Other Observation, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Both Abutments</i>					
			<i>Explanation : Debris Buildup</i>					
Mat (scour & erosion)								
Riprap	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Riprap	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railroad Tracks, Sunnyside Yard Below</i>					
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%	4+	\$62,500	2044		**	4	\$36,700
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE 39 ST(SOUTH)/ AMTRAK, LIRR YARD

Asset # : 2498

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<hr/>								
Embankment								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Concrete	100%			2044		**		4
Steel	100%			LIFE		**		
<hr/>								
Sidewalks								
Concrete	100%	4+	\$10,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Along Steel Curb line, Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Piers								
Cap Beam								
Not Accessible	100%							
<hr/>								
Pier,Columns								
Not Accessible	100%							
<hr/>								
Stem,Solid Pier								
Not Accessible	100%							
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pedestals								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE 39 ST(SOUTH)/ AMTRAK, LIRR YARD

Asset # : 2498

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Mono Deck Surface								
Concrete	75%			2055	**	5	\$4,800	
Concrete	25%	4+	\$4,900	2055	**	5	\$2,400	
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : Transverse Cracks Throughout</i>								
Railings/Parapets								
Concrete	100%			2044	**	4		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Peeling Paint And Graffiti</i>								
Steel	100%			LIFE	**	2-8	\$36,400	
Sidewalks								
Concrete	100%	4+	\$64,500	2040	**	5	\$10,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : At Interface With Curb</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Debris Filled; 6 Total Scuppers</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%	Now	\$3,400	LIFE	**			
<i>Misaligned/Bulging, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LIRR, AMT, CON NE BRIDGE 39 STREET(NORTH)/SUNNYSIDE YARDS
 Address : 39TH ST NO, NORTHERN-SKILLMAN
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0073.000 / 2497 Yr Built/Renovated : 1910 /
 Area Sq Ft : 45,446 Project Type : HIGHWAY BRIDGES
 Date of Survey : 08-Dec-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2247330

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$961,900	\$655,200
Total	\$961,900	\$655,200
Importance Code C	\$961,900	\$655,200
Total	\$961,900	\$655,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$82,800		\$14,000	
Total	\$82,800		\$14,000	
Importance Code A	\$69,400		\$14,000	
Importance Code C	\$13,400			
Total	\$82,800		\$14,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE 39 STREET(NORTH)/SUNNYSIDE YARDS
Asset # : 2497

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Riprap	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4		
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : South Approach</i>								
<i>Explanation : 1 Scupper</i>								
Piers								
Cap Beam								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Limited Access</i>								
<i>Explanation : Sunnyside Yard Below</i>								
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE 39 STREET(NORTH)/SUNNYSIDE YARDS
Asset # : 2497

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	99%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
Concrete w/ Steel Face	1%	Now	\$26,700	LIFE	**			
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 100%</i>								
<i>Location : One Third Of The Bridge, Measured From The North End</i>								
Mono Deck Surface								
Concrete	30%	4+	\$269,100	2055	**	5	\$218,400	
<i>Cracks, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Transverse Cracks</i>								
<i>Spalling, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	70%			2055	**	5	\$436,800	
Railings/Parapets								
Concrete	100%			2044	**	4	\$23,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$110,700	
Sidewalks								
Concrete	100%	4+	\$430,400	2040	**	5	\$28,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Cracking/Crumbling, Extent : Light, Area Affected : 10%</i>								
<i>Location : At Interface With Curb</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 10 Total</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
Joints								
Generic	98%			LIFE	**			
<i>Misaligned/Bulging, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Debris Collecting In Joints</i>								
Generic	2%	Now	\$13,400	LIFE	**			
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Primary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE 39 STREET(NORTH)/SUNNYSIDE YARDS
Asset # : 2497

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Secondary Member								
Not Accessible	100%							

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LIRR, AMT, CON NE BRIDGE HONEYWELL ST/AMTRAK, LIRR YARD
 Address : HONEYWELL,NORTHERN-SKILLMAN AV
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0072.000 / 2496 Yr Built/Renovated : 1910 / 2006
 Area Sq Ft : 104,561 Project Type : HIGHWAY BRIDGES
 Date of Survey : 10-Mar-2022 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2247320

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$15,864,000	\$1,590,200
Total	\$15,864,000	\$1,590,200
Importance Code C	\$15,864,000	\$1,590,200
Total	\$15,864,000	\$1,590,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$92,200		\$34,100	
Total	\$92,200		\$34,100	
Importance Code A			\$2,400	
Importance Code B	\$600			
Importance Code C	\$91,600		\$31,700	
Total	\$92,200		\$34,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE HONEYWELL ST/AMTRAK, LIRR YARD
Asset # : 2496

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	2%	4+	\$600	LIFE			* *	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : North Side</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : North Side</i>					
Generic	98%			LIFE			* *	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			* *	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railroad Tracks</i>					
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE HONEYWELL ST/AMTRAK, LIRR YARD
Asset # : 2496

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	16%	4+	\$18,800	2034	\$187,900	4	\$16,300	
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Asphalt	84%			2034	\$986,500	4	\$24,500	
Concrete	100%	4+	\$17,500	2042	**	4	\$10,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : South Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : South Approach</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4		
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Railings/Parapets								
Concrete	100%			2042	**	4		
Steel	100%			LIFE	**	2-8	\$66,900	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE HONEYWELL ST/AMTRAK, LIRR YARD
Asset # : 2496

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	5%	4+	\$23,700	2038	**	5	\$31,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	95%			2028	\$9,000,100	5	\$63,400	
Wearing Surface								
Concrete	15%	4+	\$23,500	2042	**	5	\$207,900	
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 2%</i>								
<i>Location : South Side</i>								
<i>Explanation : Asphalt Patches</i>								
Concrete	85%			2029	\$6,655,900	5	\$415,800	
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Total Of 6 Scuppers</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%			LIFE	**			
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LIRR, AMT, CON NE BRIDGE QUEENS BLVD/AMTRAK AND LIRR YARD
Address : QUEENS BLVD, JACKSON-SKILLMAN
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0071.000 / 2495 **Yr Built/Renovated** : 1910 /
Area Sq Ft : 92,432 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 10-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247310

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$4,751,900	\$2,964,600
Total	\$4,751,900	\$2,964,600
Importance Code A		\$2,964,600
Importance Code C	\$4,751,900	
Total	\$4,751,900	\$2,964,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$66,400		\$22,800	
Total	\$66,400		\$22,800	
Importance Code A	\$14,800		\$1,600	
Importance Code C	\$51,600		\$21,200	
Total	\$66,400		\$22,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE QUEENS BLVD/AMTRAK AND LIRR YARD
Asset # : 2495

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Generic	100%			LIFE	**		
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Earth	100%			LIFE	**		
Piles							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Feature Crossed							
Bank Protection							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE	**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
		<i>Location : Throughout</i>					
		<i>Explanation : Railroad Tracks</i>					
Pier Protection							
Not Accessible	100%						
Approaches							
Pavement							
Concrete	100%			2042	**	4	
Curbs							
Concrete w/ Steel Face	100%			LIFE	**		
Embankment							
Generic	100%			LIFE	**		
Mat (scour & erosion)							
Earth	100%			LIFE	**		

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE QUEENS BLVD/AMTRAK AND LIRR YARD
Asset # : 2495

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%	4+	\$7,100	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Settlement, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Northeast Electrical Box</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Piers								
Cap Beam								
Not Accessible	100%							
Pier, Columns								
Not Accessible	100%							
Stem, Solid Pier								
Not Accessible	100%							
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing								
Concrete	20%	4+	\$14,800	2046	**			
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	80%			2031	\$2,964,600			
Steel	100%			LIFE	**			
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$45,000	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Chain-link Fence And Steel Panel</i>					
Sidewalks								
Concrete	25%	4+	\$31,700	2038	**	5	\$21,200	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	75%			2028	\$4,751,900	5	\$42,400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE QUEENS BLVD/AMTRAK AND LIRR YARD

Asset # : 2495

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Concrete	100%			2042		**	5	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Scupper								
Cast Iron	11%			LIFE		**		
		<i>Drains Clogged, Extent : Moderate, Area Affected : 40%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Total Of 24 Scuppers</i>						
Cast Iron	89%			LIFE		**		
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%	4+	\$12,800	LIFE		**		
		<i>Other Observation, Extent : Light, Area Affected : 25%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Depressed Seal With Dirt And Debris</i>						
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LIRR, AMT, CON NE BRIDGE THOMSON AVE/AMTRAK YARD
Address : THOMSON AVE, JACKSON-SKILLMAN
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0070.000 / 2494 **Yr Built/Renovated** : 1908 /
Area Sq Ft : 59,840 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 10-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247300

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$195,900	\$14,700	\$17,400	
Total	\$195,900	\$14,700	\$17,400	
Importance Code A	\$34,700		\$2,300	
Importance Code C	\$161,200	\$14,700	\$15,100	
Total	\$195,900	\$14,700	\$17,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE THOMSON AVE/AMTRAK YARD

Asset # : 2494

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railroad Tracks</i>								
Approaches								
Pavement								
Concrete	5%	4+	\$20,800	2042		**	4	\$243,900
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	95%			2042		**	4	\$365,800

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE THOMSON AVE/AMTRAK YARD

Asset # : 2494

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	30%			LIFE	**			
		<i>Rust Stains, Extent : Light, Area Affected : 70%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete w/ Steel Face	70%			LIFE	**			
Embankment								
Earth	100%			LIFE	**			
Guide Railing								
Concrete	100%			2042	**	4	\$67,900	
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4	\$1,200	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Steel	100%			LIFE	**			
Sidewalks								
Concrete	4%	4+	\$9,600	LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete	96%			LIFE	**			
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
		<i>Rust Stains, Extent : Light, Area Affected : 40%</i>						
		<i>Location : Curb Located On North Side Only, Stains At Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LIRR, AMT, CON NE BRIDGE THOMSON AVE/AMTRAK YARD

Asset # : 2494

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Guide Railing Concrete	100%			2046		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South Side</i>								
<i>Explanation : Concrete Barrier Acting As Guide Rail</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2042		**	4	\$35,100
Steel	95%			LIFE		**	2-8	\$32,200
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Solid Vertical Panels</i>								
Steel	5%			LIFE		**	2-8	\$32,200
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Northwest</i>								
<i>Explanation : Chain Link Fence</i>								
<hr/>								
Sidewalks								
Concrete	100%			2038		**	5	\$30,300
<hr/>								
Wearing Surface								
Concrete	8%	4+	\$8,900	2042		**	5	\$14,700
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Asphalt Patches</i>								
Concrete	92%			2042		**	5	\$29,500
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Joints								
Generic	100%			LIFE		**		
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LONG ISLAND EXPWY BRIDGE LONG ISLAND EXPWY/WOODHAVEN BLVD
Address : WOODHAVEN BLVD
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0002.000 / 2461 **Yr Built/Renovated** : 1955 / 2006
Area Sq Ft : 25,288 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 10-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2066002

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,763,800	\$648,200
Total	\$1,763,800	\$648,200
Importance Code A	\$234,800	\$250,300
Importance Code B		\$250,300
Importance Code C	\$1,529,000	\$147,700
Total	\$1,763,800	\$648,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$52,300		\$50,200	
Total	\$52,300		\$50,200	
Importance Code A			\$25,100	
Importance Code B	\$40,200		\$25,100	
Importance Code C	\$12,100			
Total	\$52,300		\$50,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
LONG ISLAND EXPWY BRIDGE LONG ISLAND EXPWY/WOODHAVEN BLVD
Asset # : 2461

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
Backwall Concrete	100%	4+	\$6,600	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : East Abutment</i>					
			<i>Spalling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : West Abutment</i>					
Brngs,Ancr Blts,Pads Generic	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Footings								
Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%	4+	\$15,900	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Granite	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Northwest Corner</i>					
			<i>Explanation : Granite Stone Wall</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	8%	4+	\$5,500	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : East Abutment</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Northwest Corner</i>					
			<i>Explanation : Brick Facing</i>					
Concrete	92%			LIFE		**		

Feature Crossed

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LONG ISLAND EXPWY BRIDGE LONG ISLAND EXPWY/WOODHAVEN BLVD
Asset # : 2461

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Approaches								
Pavement								
Concrete	100%	4+	\$62,600	2042	**	4	\$38,500	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Median								
Concrete	100%			LIFE	**	5		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4		
Piers								
Stem,Solid Pier								
Concrete	6%	4+	\$24,300	LIFE	**			
			<i>Cracks, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : East Face Of Pier</i>					
Concrete	94%			LIFE	**			
Brngs,Ancr Blts,Pads								
Generic	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Median								
Concrete	100%			LIFE	**	5	\$11,800	
Railings/Parapets								
Concrete	100%			2042	**	4		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LONG ISLAND EXPWY BRIDGE LONG ISLAND EXPWY/WOODHAVEN BLVD
Asset # : 2461

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Concrete	50%	4+	\$66,300	2042	**	5	\$73,800	
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Concrete	50%			2029	\$1,326,300	5	\$147,700	
Superstructure								
Deck, Structural								
Concrete	57%	4+	\$234,800	LIFE	**	5	\$24,800	
	<i>Cracks, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Fascia Overhangs And Light Blister</i>							
	<i>Rust Stains, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Underside Of Stay-in-place Forms</i>							
	<i>Other Observation, Extent : Light, Area Affected : 100%</i>							
	<i>Location : All Bays Except The Center Bay And Fascia Bays</i>							
	<i>Explanation : Covered By Stay-in-place Forms, Some Corroded Areas With Efflorescence</i>							
Concrete	43%			LIFE	**	5	\$24,800	
Primary Member								
Steel	100%			LIFE	**	2-8	\$467,500	
	<i>Rust Stains, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
Secondary Member								
Steel	100%			LIFE	**	2-8	\$391,600	
	<i>Rust Stains, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : LONGWOOD AVE. BRIDGE
Address : LONGWOOD AVE. / AMTRAK RAILS
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0180.000 / 13714 **Yr Built/Renovated** : 1908 /
Area Sq Ft : 10,625 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 09-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241159

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$63,100
Total		\$63,100
Importance Code C		\$63,100
Total		\$63,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$118,800		\$200	
Total	\$118,800		\$200	
Importance Code A	\$6,100		\$200	
Importance Code B	\$3,700			
Importance Code C	\$109,000			
Total	\$118,800		\$200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LONGWOOD AVE. BRIDGE
Asset # : 13714

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Underside Of Bridge Throughout</i>								
<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>								
<hr/>								
Backwall Not Accessible	100%							
<hr/>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
<hr/>								
Footings Not Accessible	100%							
<hr/>								
Joint with Deck Generic	100%	Now	\$3,700	LIFE			**	
<i>Loose Elements, Extent : Light, Area Affected : 10%</i>								
<i>Location : Both Abutments</i>								
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Both Abutments</i>								
<i>Explanation : Deteriorated Joint Membrane</i>								
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Pedestals Not Accessible	100%							
<hr/>								
Stem (breastwall) Not Accessible	100%							
<hr/>								
Wingwalls								
Footings Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Earth	100%			LIFE			**	
<hr/>								
Piles Not Accessible	100%							
<hr/>								
Walls Not Accessible	100%							
<hr/>								
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
<hr/>								
Approaches								
Pavement Concrete	100%	4+	\$45,700	2041		**	4	\$41,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Both Abutments</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LONGWOOD AVE. BRIDGE
Asset # : 13714

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Approaches							
Curbs							
Concrete w/ Steel Face	100%			LIFE		**	
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>				
			<i>Location : Random Locations Throughout</i>				
<hr/>							
Embankment							
Earth	100%			LIFE		**	
<hr/>							
Mat (scour & erosion)							
Earth	100%			LIFE		**	
<hr/>							
Pavement Base							
Not Accessible	100%						
<hr/>							
Railings/Parapets							
Concrete	100%			2041		**	4
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>				
			<i>Location : Consists Of 50 Percent Concrete And 50 Percent Metal Fence</i>				
			<i>Explanation : Both Approaches</i>				
<hr/>							
Steel	100%			LIFE		**	
<hr/>							
Sidewalks							
Concrete	100%	4+	\$10,500	LIFE		**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Random Locations Throughout</i>				
			<i>Spalling, Extent : Light, Area Affected : 1%</i>				
			<i>Location : Random Locations Throughout</i>				
			<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Northeast Approach</i>				
<hr/>							
Piers							
Cap Beam							
Not Accessible	100%						
<hr/>							
Pier,Columns							
Not Accessible	100%						
<hr/>							
Stem,Solid Pier							
Not Accessible	100%						
<hr/>							
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
<hr/>							
Footings							
Not Accessible	100%						
<hr/>							
Mat (scour & erosion)							
Not Accessible	100%						
<hr/>							
Pedestals							
Not Accessible	100%						
<hr/>							
Piles							
Not Accessible	100%						
<hr/>							
Deck Elements							
Curbs							
Concrete w/ Steel Face	100%			LIFE		**	
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>				
			<i>Location : Throughout</i>				

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
LONGWOOD AVE. BRIDGE
Asset # : 13714

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Concrete	100%	4+	\$6,100	2041	**	4	\$3,100	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Parapet</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Parapet Is Concrete With Corrugated Steel</i>								
Steel	100%			LIFE	**	2-8	\$4,300	
Sidewalks								
Concrete	100%	4+	\$15,100	2037	**	5	\$3,900	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	4%	4+	\$6,100	2041	**	5	\$31,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	96%			2041	**	5	\$63,100	
Superstructure								
Deck,Structural Not Accessible	100%							
Joints Generic	100%			LIFE	**			
Primary Member Not Accessible	100%							
Secondary Member Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : MANHATTAN COLLEGE PARKWAY HENRY HUDSON PARKWAY
Address : MANHATTAN COLLEGE PARKWAY & HENRY HUDSON PKWY
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0368.000 / 15386 Yr Built/Renovated :
Area Sq Ft : 5,010 Project Type : HIGHWAY BRIDGES
Date of Survey : 22-Mar-2022 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2229480


CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$7,900		\$1,300	
Total	\$7,900		\$1,300	
Importance Code A	\$4,400		\$200	
Importance Code C	\$3,500		\$1,100	
Total	\$7,900		\$1,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MANHATTAN COLLEGE PARKWAY HENRY HUDSON PARKWAY
Asset # : 15386

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE		**		
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Pier Protection								
Concrete	100%			LIFE		**		
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 60%</i>					
			<i>Location : Random Locations Throughout</i>					
Guide Railing								
Steel	100%			LIFE		**		
Timber	100%	4+	\$1,400	2053		**		
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Bottom Of Timber Railing - North Railing</i>					
			<i>Loss of Section, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MANHATTAN COLLEGE PARKWAY HENRY HUDSON PARKWAY
Asset # : 15386

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Granite	10%	4+	\$3,100	LIFE	**			
<i>Joints Missing, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Granite	90%			LIFE	**			
Steel	100%			LIFE	**	2-8	\$6,300	
Sidewalks								
Concrete	100%			2038	**	5	\$2,200	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$3,500	2042	**	5	\$11,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Right Side</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$5,500	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout In All Spans</i>								
<i>Efflorescence, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout In All Spans</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout In All Spans</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : METRO NORTH BRIDGE E 149 ST/METRO NORTH RR HAR
Address : E149TH ST, PARK AVE.
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0056.000 / 2481 **Yr Built/Renovated** : 1906 /
Area Sq Ft : 27,900 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 09-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241560

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$166,800	
Total	\$166,800	
Importance Code C	\$166,800	
Total	\$166,800	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$85,900	\$16,200	\$400	
Total	\$85,900	\$16,200	\$400	
Importance Code A	\$8,600		\$400	
Importance Code C	\$77,300	\$16,200		
Total	\$85,900	\$16,200	\$400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
METRO NORTH BRIDGE E 149 ST/METRO NORTH RR HAR
Asset # : 2481

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : Underside Of Bridge Throughout</i>						
		<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
		<i>Other Observation, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Debris At Joint</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
Pier Protection Concrete	100%			LIFE		**		
Approaches								
Pavement Concrete	100%	4+	\$113,100	2041		**	4	\$30,800
		<i>Cracks, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Both Approaches</i>						
		<i>Spalling, Extent : Moderate, Area Affected : 2%</i>						
		<i>Location : West Approach North Side</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
METRO NORTH BRIDGE E 149 ST/METRO NORTH RR HAR
Asset # : 2481

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	4+	\$8,600	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 75%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : East Side And West Side Of North Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE			**	
Sidewalks								
Concrete	15%	4+	\$3,900	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Sidewalk</i>								
Concrete	85%			LIFE			**	
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
METRO NORTH BRIDGE E 149 ST/METRO NORTH RR HAR

Asset # : 2481

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$11,900
		<i>Rust Stains, Extent : Light, Area Affected : 75%</i>						
		<i>Location : Random Locations Throughout</i>						
Sidewalks								
Concrete	5%	4+	\$41,700	2037		**	5	\$16,200
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete	95%			2037		**	5	\$32,400
Wearing Surface								
Concrete	100%	4+	\$31,700	2041		**	5	\$48,900
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Near West Approach</i>						
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%	0-2	\$53,700	LIFE		**		
		<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 50%</i>						
		<i>Location : Deteriorated Filler, Only One Joint At Span 5.</i>						
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : METRO NORTH BRIDGE E 241 ST/BRCP, METRO NORTH HAR
Address : E241ST ST,BX RIV RD,CARPENTER
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0058.000 / 2483 **Yr Built/Renovated** : 1913 /
Area Sq Ft : 49,501 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 24-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241890

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$2,172,000	\$1,817,400
Total	\$2,172,000	\$1,817,400
Importance Code A	\$813,000	\$813,000
Importance Code B	\$1,047,800	\$899,700
Importance Code C	\$311,300	\$104,700
Total	\$2,172,000	\$1,817,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$808,300		\$166,000	
Total	\$808,300		\$166,000	
Importance Code A	\$332,400		\$75,800	
Importance Code B	\$438,400		\$90,200	
Importance Code C	\$37,600			
Total	\$808,300		\$166,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
METRO NORTH BRIDGE E 241 ST/BRCP, METRO NORTH HAR

Asset # : 2483

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$3,200	LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : West Abutment</i>								
Backwall Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : East Abutment</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	2-4	\$5,300	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Deteriorated Joint Membrane</i>								
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%	4+	\$148,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : East Abutment</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : West Abutment</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : West Abutment</i>								
<i>Efflorescence, Extent : Light, Area Affected : 1%</i>								
<i>Location : West Abutment</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : West Abutment</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
METRO NORTH BRIDGE E 241 ST/BRCP, METRO NORTH HAR
Asset # : 2483

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Bank Protection								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : At Stream</i>								
<i>Explanation : Earth</i>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt, Stream, Rail, Concrete, And Earth</i>								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : At Piers</i>								
<i>Explanation : Cracking And Rust Stains. Concrete Crash Wall Observed Throughout.</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$31,500	2044		**	4	\$18,500
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 75%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
Sidewalks								
Concrete	100%	4+	\$6,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northwest Side</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$968,500
Pier, Columns								
Concrete	100%			LIFE		**		
Steel	100%			LIFE		**	2-8	\$1,933,400

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
METRO NORTH BRIDGE E 241 ST/BRCP, METRO NORTH HAR

Asset # : 2483

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
Steel	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 75%</i>								
<i>Location : Steel Facing Throughout</i>								
Railings/Parapets Steel	100%			LIFE		**	2-8	\$68,900
Sidewalks Concrete	100%	4+	\$178,600	2040		**	5	\$11,900
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout - Primarily Around Curbs And Staircases</i>								
Wearing Surface Concrete	100%	4+	\$78,900	2044		**	5	\$104,700
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 22 Scuppers</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
METRO NORTH BRIDGE E 241 ST/BRCP, METRO NORTH HAR
Asset # : 2483

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$145,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Construction Joint At Center Bay</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Light Random Cracks With Efflorescence Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Joints								
Generic	100%	2-4	\$53,900	LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 30%</i> <i>Location : Numerous Joint Fillers Throughout</i> <i>Explanation : Deteriorated Joint Membrane</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$1,568,500	
<i>Corrosion, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$1,345,700	
<i>Corrosion, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : METROPOLITAN AVENUE LIRR - NY&ATL
Address : METROPOLITAN AVE BET. 62ND ST. AND FRESH POND ROAD
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0275.000 / 15029 **Yr Built/Renovated** : 1915 /
Area Sq Ft : 15,184 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 31-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 1247560

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$14,200		\$66,700	
Total	\$14,200		\$66,700	
Importance Code A	\$14,200			
Importance Code C			\$66,700	
Total	\$14,200		\$66,700	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
METROPOLITAN AVENUE LIRR - NY&ATL
Asset # : 15029

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : No Access To Railroad Property Underneath</i>						
<hr/>								
Backwall Not Accessible	100%							
<hr/>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
<hr/>								
Footings Not Accessible	100%							
<hr/>								
Joint with Deck Generic	100%			LIFE			**	
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Along The Joint Headers</i>						
		<i>Other Observation, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Deteriorated Joint Seal</i>						
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Pedestals Not Accessible	100%							
<hr/>								
Stem (breastwall) Not Accessible	100%							
<hr/>								
Walls Not Accessible	100%							
<hr/>								
Wingwalls								
Footings Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Piles Not Accessible	100%							
<hr/>								
Walls Not Accessible	100%							
<hr/>								
Feature Crossed								
Bank Protection Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Pier Protection Concrete	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Concrete Barrier</i>						
<hr/>								
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
METROPOLITAN AVENUE LIRR - NY&ATL
Asset # : 15029

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$76,900	
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	Now	\$8,300	2044	**	4	\$1,800	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout; Severe At Southeast Approach</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
METROPOLITAN AVENUE LIRR - NY&ATL
Asset # : 15029

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets Concrete	100%	Now	\$5,900	2044	**	4	\$900	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			2043	**	5	\$5,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2048	**	5	\$50,600	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : MILLER HIGHWAY BRIDGE MILLER HIGHWAY/TERRAIN
Address : 59TH ST - 72ND ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0076.090 / 4177 **Yr Built/Renovated** : 1931 /
Area Sq Ft : 307,370 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 20-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2257569

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$8,272,200	\$9,666,600
Total	\$8,272,200	\$9,666,600
Importance Code A	\$4,916,200	\$6,632,800
Importance Code B	\$3,033,800	\$3,033,800
Importance Code C	\$322,200	
Total	\$8,272,200	\$9,666,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,245,500		\$950,000	
Total	\$2,245,500		\$950,000	
Importance Code A	\$1,353,700		\$645,800	
Importance Code B	\$891,800		\$304,300	
Total	\$2,245,500		\$950,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MILLER HIGHWAY BRIDGE MILLER HIGHWAY/TERRAIN
Asset # : 4177

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$3,152,900	
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : North Of 70th Street</i>								
<i>Explanation : Cap Beams</i>								
Pier,Columns								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$2,437,800	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**	2-8	\$142,400	
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Median								
Concrete	100%			LIFE	**	5	\$80,900	
Railings/Parapets								
Concrete	100%			2044	**	4	\$110,900	
Wearing Surface								
Concrete	100%			2044	**	5		
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Deck</i>								
<i>Explanation : 204 Scuppers</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MILLER HIGHWAY BRIDGE MILLER HIGHWAY/TERRAIN

Asset # : 4177

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Concrete	98%			LIFE	**	5	\$746,400	
Concrete	2%			LIFE	**	5	\$746,400	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Corrosion To Stay In Place Forms In Several Bays</i>								
<hr/>								
Joints								
Generic	30%	4+	\$322,200	LIFE	**			
<i>Leakage, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : At Inside Face Of Fascia Girders Below Deck Joints</i>								
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Over Several Piers</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : At Inner Faces Of Fascia Girders Below Deck Joints</i>								
Generic	70%			LIFE	**			
<hr/>								
Primary Member								
Steel	15%	4+	\$800,600	LIFE	**	2-8	\$4,701,600	
<i>Corrosion, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Girders, Floor Beams, Web And Flanges At Deck Joints And Drainage Pipes</i>								
<i>Other Observation, Extent : Light, Area Affected : 75%</i>								
<i>Location : Throughout Superstructure Steel</i>								
<i>Explanation : Rust Flakes To Light Rusting. Paint System Is Failing</i>								
Steel	85%			LIFE	**	2-8	\$8,058,500	
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$6,913,900	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : MOSHOLU PARKWAY METRO NORTH
Address : MOSHOLU PARKWAY & SOUTHERN BLVD
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0314.000 / 15084 **Yr Built/Renovated** :
Area Sq Ft : 7,453 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 14-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230260

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$5,400		\$10,000	\$15,200
Total	\$5,400		\$10,000	\$15,200
Importance Code A	\$3,800		\$1,700	
Importance Code B	\$1,500			
Importance Code C			\$8,200	\$15,200
Total	\$5,400		\$10,000	\$15,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
MOSHOLU PARKWAY METRO NORTH
Asset # : 15084

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	Now	\$1,500	LIFE		**		
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 80%</i>					
			<i>Location : Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Spall On Header</i>					
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								
Pavement Concrete	100%			2044		**	4	\$16,400
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MOSHOLU PARKWAY METRO NORTH
Asset # : 15084

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Curbs								
Concrete w/ Steel Face	100%	4+	\$1,300	LIFE		**		
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Northeast Corner</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Embankment								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Concrete	100%			2044	**	4	\$300	
Masonry	100%			2044	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : East Side</i>								
<i>Explanation : Missing Mortar In Joints</i>								
Steel	100%			LIFE	**			
<hr/>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2044	**	4	\$2,900	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$6,400	
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust On Chain-link Fence</i>								
<hr/>								
Sidewalks								
Concrete	100%			2040	**	5	\$4,500	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%			2044	**	5	\$30,500	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MOSHOLU PARKWAY METRO NORTH
Asset # : 15084

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : MOSHOLU PARKWAY WEBSTER AVENUE
Address : MOSHOLU PARKWAY OVER WEBSTER AVE SOUTHWEST OF MARION AVE
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0315.000 / 15085 **Yr Built/Renovated** :
Area Sq Ft : 8,480 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 14-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230270

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$83,900	\$83,900
Total	\$83,900	\$83,900
Importance Code A	\$83,900	\$83,900
Total	\$83,900	\$83,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$49,400		\$21,800	\$24,800
Total	\$49,400		\$21,800	\$24,800
Importance Code A	\$41,900		\$10,400	
Importance Code B	\$7,500		\$500	
Importance Code C			\$10,800	\$24,800
Total	\$49,400		\$21,800	\$24,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
MOSHOLU PARKWAY WEBSTER AVENUE
Asset # : 15085

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Masonry	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$1,500	LIFE		**		
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 70%</i>					
			<i>Location : Both Abutment Joints</i>					
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Masonry	100%			LIFE		**		
			<i>Efflorescence, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Missing Mortar In Joints</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE		**		
			<i>Efflorescence, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Missing Mortar In Joints</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MOSHOLU PARKWAY WEBSTER AVENUE
Asset # : 15085

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$21,700	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$1,800	LIFE	**			
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Southwest Corner</i>								
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$400	
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Southeast Concrete Parapet</i>								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2044	**	4	\$3,300	
Steel	100%			LIFE	**	2-8	\$7,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Top Of Concrete Parapet</i>								
<i>Explanation : Chain Link Fence</i>								
Sidewalks								
Concrete	100%			2040	**	5	\$4,400	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044	**	5	\$49,500	
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : North End</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MOSHOLU PARKWAY WEBSTER AVENUE
Asset # : 15085

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$18,700	
		<i>Rust Stains, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout On Stay In Place Forms</i>						
Primary Member								
Steel	100%			LIFE	**	2-8	\$268,700	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$13,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : NASSAU STREET BRIDGE B.Q.E./NASSAU STREET
Address : 278I
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0018.000 / 2451 **Yr Built/Renovated** : 1956 / 2006
Area Sq Ft : 51,200 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 25-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230510

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$123,700	\$656,100
Total	\$123,700	\$656,100
Importance Code A		\$656,100
Importance Code B	\$123,700	
Total	\$123,700	\$656,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$38,800		\$63,800	
Total	\$38,800		\$63,800	
Importance Code A			\$59,300	
Importance Code B			\$4,500	
Importance Code C	\$38,800			
Total	\$38,800		\$63,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NASSAU STREET BRIDGE B.Q.E./NASSAU STREET
Asset # : 2451

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
<hr/>								
Backwall Concrete	100%	4+	\$38,800	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Both Abutments</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : At Middle Of Wall</i>								
<i>Explanation : Brick Facing 5 Feet Wide On Both Fascias On 15 Percent Area. Light Water Stains On South Abutment.</i>								
<hr/>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
<hr/>								
Footings Not Accessible	100%							
<hr/>								
Joint with Deck Generic	100%			LIFE		**		
<hr/>								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stone Pavers At North And Asphalt Paving At South Abutment</i>								
<hr/>								
Pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : At North Abutment Only</i>								
<i>Explanation : Steel Bolster Bolted To Front Face Abutment</i>								
<hr/>								
Stem (breastwall) Concrete	100%	4+	\$123,700	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : At Both Abutments</i>								
<i>Explanation : Brick Facade On 5 Percent Of Area In Both Abutments. Water Stains</i>								
<hr/>								
Wingwalls								
Footings Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Earth	100%			LIFE		**		
<hr/>								
Piles Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NASSAU STREET BRIDGE B.Q.E./NASSAU STREET
Asset # : 2451

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	100%			LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 35%</i>								
<i>Location : All Walls Except Northeast Wingwall</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Brick Facade</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Skate Park</i>								
Approaches								
Pavement								
Concrete	100%			2042		**	4	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042		**	4	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At North Approach</i>								
<i>Explanation : Total Of 2 Scuppers</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$171,600
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NASSAU STREET BRIDGE B.Q.E./NASSAU STREET
Asset # : 2451

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns Steel	100%			LIFE	**	2-8	\$42,700	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads Generic	100%			LIFE	**			
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt, Pavers And Concrete</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Median Concrete	100%			LIFE	**	5	\$5,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Mono Deck Surface Concrete	100%			2053	**	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Railings/Parapets Concrete	100%			2042	**	4		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Steel	100%			LIFE	**	2-8	\$29,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Concrete Barrier</i>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Total Of 32 Scuppers</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NASSAU STREET BRIDGE B.Q.E./NASSAU STREET
Asset # : 2451

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$75,100	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 40%</i> <i>Location : Fascias And Utility Bay</i> <i>Explanation : Stay In Place Forms On 3 Of 8 Bays</i>								
Joints								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Armorless Joint</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$946,500	
<i>Corrosion, Extent : Moderate, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$47,600	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : NEREID AVENUE (2241880)
Address : EAST 238TH ST. / OVER BRONX RIVER PARKWAY
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0151.000 / 13514 Yr Built/Renovated : 1930 /
Area Sq Ft : 57,750 Project Type : HIGHWAY BRIDGES
Date of Survey : 19-Oct-2020 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 1067150

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$2,200,600	\$2,211,800
Total	\$2,200,600	\$2,211,800
Importance Code A	\$775,800	\$1,618,800
Importance Code B	\$1,149,900	
Importance Code C	\$274,900	\$593,000
Total	\$2,200,600	\$2,211,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$139,400		\$1,000	
Total	\$139,400		\$1,000	
Importance Code A	\$13,600		\$1,000	
Importance Code B	\$26,200			
Importance Code C	\$99,600			
Total	\$139,400		\$1,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NEREID AVENUE (2241880)
Asset # : 13514

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			* *	
Stem (breastwall)								
Concrete	1%	4+	\$26,200	LIFE			* *	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	99%			LIFE			* *	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			* *	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%	4+	\$140,400	LIFE			* *	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 40%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Bank Protection								
Generic	100%			LIFE			* *	
Mat (scour & erosion)								
Generic	100%			LIFE			* *	
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NEREID AVENUE (2241880)
Asset # : 13514

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	100%	4+	\$9,500	2033	\$473,900	4	\$9,800	
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Both Approaches</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : East Side</i>								
Concrete	100%	4+	\$39,800	2041	**	4	\$39,000	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : West Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041	**	4		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%	4+	\$8,800	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : 4 Scuppers</i>								
Piers								
Cap Beam								
Concrete	40%	4+	\$242,600	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	60%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NEREID AVENUE (2241880)
Asset # : 13514

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns Concrete	40%	4+	\$238,400	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>							
Concrete	60%			LIFE		**		
Stem,Solid Pier Concrete	2%	4+	\$911,600	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 75%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Moderate, Area Affected : 100%</i> <i>Location : Random Locations Throughout</i>							
Concrete	98%			LIFE		**		
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%	4+	\$13,600	LIFE		**		
	<i>Recent Repair Evident, Extent : N/A, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 100%</i> <i>Location : Random Locations Throughout</i>							
Railings/Parapets Steel	100%			LIFE		**	2-8	\$28,900
	<i>Corrosion, Extent : Light, Area Affected : 30%</i> <i>Location : Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Steel Railing Without Parapets</i>							
Sidewalks Concrete	100%	4+	\$41,500	2037		**	5	\$11,600
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Vegetation Growth, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NEREID AVENUE (2241880)
Asset # : 13514

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface Concrete	100%	4+	\$134,500	2041	**	5	\$119,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : 4 Scuppers Observed</i>								
<hr/>								
Superstructure								
Primary Member Concrete	10%	4+	\$533,200	LIFE	**	5	\$809,400	
<i>Cracks, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Underside Of The Arch Barrels</i>								
<i>Efflorescence, Extent : Light, Area Affected : 100%</i>								
<i>Location : Underside Of The Arch Barrels</i>								
<i>Leakage, Extent : Light, Area Affected : 80%</i>								
<i>Location : Random Locations At The Arch Barrels</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Underside Of The Arch Barrels</i>								
<i>Explanation : Deteriorated Surface With Steel Mesh Installed</i>								
Concrete	90%			LIFE	**	5	\$809,400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : NEW DORP LANE SIRT SOUTH SHORE
Address : NEW DORP LANE AT NEW DORP PLAZA AND S. RAILROAD AVENUE
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0264.000 / 15018 **Yr Built/Renovated** :
Area Sq Ft : 7,411 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249430

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$172,800	
Total	\$172,800	
Importance Code A	\$172,800	
Total	\$172,800	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$73,500		\$20,700	
Total	\$73,500		\$20,700	
Importance Code A	\$26,900		\$100	
Importance Code C	\$46,600		\$20,600	
Total	\$73,500		\$20,700	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
NEW DORP LANE SIRT SOUTH SHORE
Asset # : 15018

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On East Abutment</i> <i>Other Observation, Extent : N/A, Area Affected : 80%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access To Abutment Components</i>								
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : West Abutment</i> <i>Explanation : Concrete Pavers</i>								
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations On East Abutment</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout On East Side</i> <i>Explanation : Railway Ballasts</i>								
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations On East Side</i>								

Feature Crossed

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NEW DORP LANE SIRT SOUTH SHORE
Asset # : 15018

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railroad Tracks</i>								
Approaches								
Pavement								
Concrete	10%	Now	\$15,100	2044		**	4	\$41,200
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	90%			2044		**	4	\$41,200
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Southeast Approach</i>								
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Southeast Approach</i>								
Piers								
Cap Beam								
Concrete	100%	Now	\$25,700	LIFE		**		
<i>Spalling, Extent : Severe, Area Affected : 2%</i>								
<i>Location : North End Of Cap</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Pier Components</i>								
Pier,Columns								
Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NEW DORP LANE SIRT SOUTH SHORE
Asset # : 15018

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Ballasts</i>								
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets Steel	100%			LIFE		**	2-8	\$3,100
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Base Of Posts And Random Locations On West Side</i>								
Sidewalks Concrete	100%	Now	\$23,800	2040		**	5	\$1,800
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Worse Cases On North Side</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface Concrete	100%	0-2	\$7,700	2044		**	5	\$11,900
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Near Pier Joint</i>								
Superstructure								
Deck,Structural Not Accessible	100%							
Joints Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout On South Side</i>								
<i>Explanation : Joint Along Sidewalk With Adjacent Building</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NEW DORP LANE SIRT SOUTH SHORE
Asset # : 15018

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Primary Member								
Concrete Encased Steel	100%	Now	\$172,800	LIFE	**	5	\$25,900	
			<i>Cracks, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : West Half On Both Fascia Beams</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations On Fascia Beams</i>					
			<i>Spalling, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : East Half At North Fascia Beam</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 90%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access To Interior Girders</i>					
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : NORTH RAMP STATEN ISLAND RAILWAY
Address : NORTH RAMP TO TERMINAL STATEN ISLAND FERRY TERMINAL
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0345.000 / 15204 **Yr Built/Renovated** :
Area Sq Ft : 5,236 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2269760

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$14,000		\$4,900	
Total	\$14,000		\$4,900	
Importance Code A			\$3,700	
Importance Code B	\$500			
Importance Code C	\$13,500		\$1,300	
Total	\$14,000		\$4,900	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
NORTH RAMP STATEN ISLAND RAILWAY
Asset # : 15204

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$500	LIFE				**
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>					
			<i>Location : North End</i>					
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE				**
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railroad Tracks</i>					
Pier Protection								
Not Accessible	100%							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTH RAMP STATEN ISLAND RAILWAY
Asset # : 15204

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%	4+	\$10,000	2042	**	4	\$5,900	
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$3,400	
Sidewalks								
Concrete	100%			2038	**	5	\$2,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTH RAMP STATEN ISLAND RAILWAY
Asset # : 15204

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Concrete	100%	4+	\$3,500	2042	**	5	\$11,500	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	**	2-8	\$65,800	
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : NORTHERN BLVD. BRIDGE NORTHERN BLVD./BELT CROSS ISLAND
Address : NORTHERN BLVD. CROSS ISLAND PKWY.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0177.000 / 13711 **Yr Built/Renovated** :
Area Sq Ft : 8,951 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 05-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231870

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$88,600
Total		\$88,600
Importance Code A		\$88,600
Total		\$88,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$63,100	\$200	\$9,000	\$2,600
Total	\$63,100	\$200	\$9,000	\$2,600
Importance Code A			\$9,000	
Importance Code B	\$38,000			
Importance Code C	\$25,100	\$200		\$2,600
Total	\$63,100	\$200	\$9,000	\$2,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTHERN BLVD. BRIDGE NORTHERN BLVD./BELT CROSS ISLAND
Asset # : 13711

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	0-2	\$2,600	LIFE			**	
			<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Northeast Quadrant</i>					
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Northeast Quadrant</i>					
Mat (scour & erosion) Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Under Road Paving And Safety Shape Barrier Adjacent To Abutment Stem</i>					
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	17%	4+	\$35,400	LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	83%			LIFE			**	
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE			**	
Piles Not Accessible	100%							
Walls Concrete	5%	4+	\$11,800	LIFE			**	
			<i>Cracking/Crumbling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 35%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Wingwalls Are Concrete With Stone Facing</i>					
Concrete	95%			LIFE			**	
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTHERN BLVD. BRIDGE NORTHERN BLVD./BELT CROSS ISLAND
Asset # : 13711

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Feature Crossed							
Mat (scour & erosion)							
Generic	100%			LIFE	**		
Pier Protection							
Concrete	100%			LIFE	**		
Approaches							
Pavement							
Concrete	100%			2041	**	4	\$5,100
			<i>Cracks, Extent : Light, Area Affected : 2%</i>				
			<i>Location : Random Locations Throughout</i>				
			<i>Spalling, Extent : Light, Area Affected : 2%</i>				
			<i>Location : Random Locations Throughout</i>				
Curbs							
Concrete w/ Steel Face	100%			LIFE	**		
			<i>Rust Stains, Extent : Light, Area Affected : 50%</i>				
			<i>Location : Random Locations Throughout</i>				
Embankment							
Earth	100%			LIFE	**		
Guide Railing							
Concrete	100%			2041	**	4	
Mat (scour & erosion)							
Not Accessible	100%						
Pavement Base							
Not Accessible	100%						
Railings/Parapets							
Steel	100%			LIFE	**		
Sidewalks							
Concrete	100%	4+	\$5,600	LIFE	**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>				
			<i>Location : Both Approaches</i>				
			<i>Settlement, Extent : Light, Area Affected : 3%</i>				
			<i>Location : Both Approaches</i>				
Piers							
Cap Beam							
Concrete	100%			LIFE	**		
Pier, Columns							
Concrete	100%			LIFE	**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : All Columns</i>				
			<i>Explanation : The Columns Are Concrete With Stone Veneer</i>				
Brngs, Ancr Blts, Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE	**		
Pedestals							
Not Accessible	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTHERN BLVD. BRIDGE NORTHERN BLVD./BELT CROSS ISLAND
Asset # : 13711

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Random Locations Throughout</i>					
Guide Railing								
Concrete	100%			2045	**			
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$3,800	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : North And South Sides</i>					
			<i>Explanation : Chain Link Fence Behind Steel Bridge Railing</i>					
Sidewalks								
Concrete	100%			2037	**	5	\$400	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	100%	4+	\$7,600	2041	**	5	\$16,800	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	**	2-8	\$165,500	
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : **NORTHERN BOULEVARD LITTLE NECK BRIDGE ALLEY CREEK**
 Address : **NORTHERN BLVD OVER ALLEY CREEK IN ALLEY POND PARK**
 Borough : **QUEENS** Agency's Number : **N/A**
 Program / Asset # : **DOT0384.000 / 15404** Yr Built/Renovated :
 Area Sq Ft : **7,984** Project Type : **HIGHWAY BRIDGES**
 Date of Survey : **08-Apr-2022** Landmark Status : **NONE**
 Areas Surveyed :
 Block : Lot : BIN : **2240440**

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$205,900	
Total	\$205,900	
Importance Code A	\$205,900	
Total	\$205,900	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$128,800		\$1,600	
Total	\$128,800		\$1,600	
Importance Code A	\$32,700		\$1,300	
Importance Code B	\$49,700		\$300	
Importance Code C	\$46,400			
Total	\$128,800		\$1,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTHERN BOULEVARD LITTLE NECK BRIDGE ALLEY CREEK
Asset # : 15404

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	Now	\$3,800	LIFE			**	
			<i>Broken,Missing Pave, Extent : Light, Area Affected : 2%</i>					
			<i>Location : West Abutment</i>					
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : At Both Abutments</i>					
Mat (scour & erosion) Generic	100%			LIFE			**	
Pedestals Not Accessible	100%							
Stem (breastwall) Granite	100%	4+	\$27,100	LIFE			**	
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Southeast Corner</i>					
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Joint Mortar Missing/ Eroded</i>					
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE			**	
Piles Not Accessible	100%							
Walls Granite	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Severe, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Joint Mortar Missing/ Eroded</i>					
Feature Crossed								
Mat (scour & erosion) Stream Bed	100%			LIFE			**	
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTHERN BOULEVARD LITTLE NECK BRIDGE ALLEY CREEK
Asset # : 15404

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%	Now	\$31,900	2042	**	4	\$18,700	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Both Approaches</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Both Approaches In Eastbound Lane</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Both Approaches In Eastbound Lane</i>								
<i>Explanation : Asphalt Patches</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$7,800	LIFE	**			
<i>Corrosion, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast Approach</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northwest Corner</i>								
Embankment								
Not Accessible	100%							
Guide Railing								
Concrete	100%			2042	**	4	\$3,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Guide Railing Only At North Side</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Granite	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Old Repair, Extent : Light, Area Affected : 10%</i>								
<i>Location : Asphalt Patch In Northwest Corner</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Southeast And Northwest Corner</i>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTHERN BOULEVARD LITTLE NECK BRIDGE ALLEY CREEK
Asset # : 15404

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Granite	100%	4+	\$10,100	LIFE		**		
<i>Joints Missing, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : North End</i>								
<i>Explanation : Misaligned</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Streambed</i>								
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%	2-4	\$3,000	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations On North Side</i>								
<i>Rust Stains, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On North Side</i>								
Guide Railing Concrete	100%			2046		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Guide Railing On North Side Only</i>								
Mono Deck Surface Concrete	100%	4+	\$5,500	2053		**	5	\$16,700
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Full Width Cracks Near Pier</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTHERN BOULEVARD LITTLE NECK BRIDGE ALLEY CREEK
Asset # : 15404

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Cast Iron	100%	Now	\$8,900	LIFE		**		
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On North Side</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Northwest Corner</i>								
<i>Explanation : Railing Leaning Outwards</i>								
Granite	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
Sidewalks								
Concrete	100%	4+	\$8,900	2038		**	5	\$1,500
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Near Pier At Both Sides And At Northwest Sidewalk</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : North Side Near Pier</i>								
Superstructure								
Deck,Structural								
Concrete	100%	2-4	\$153,200	LIFE		**	5	\$8,800
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 75%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Primary Member								
Concrete Encased Steel	100%	4+	\$52,700	LIFE		**	5	\$28,200
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Limited Access On 75 Percent Area. Exposed Rebar</i>								
Steel	100%	4+	\$11,900	LIFE		**	2-8	\$25,000
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Limited Access On 75 Percent Area. Paint Peeling.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NORTHERN BOULEVARD LITTLE NECK BRIDGE ALLEY CREEK
Asset # : 15404

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure Secondary Member Steel	100%	4+	\$8,600	LIFE	**	2-8	\$4,500	
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations On Fascia Girder Supporting Railing On South Side</i> <i>Other Observation, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Limited Access On 75 Percent Area. Paint Peeling.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : NY 25X TO/FROM 2ND AVENUE NYC GARAGE
Address : 2ND AVE BTWN E 59TH & E 60TH STS
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0365.000 / 15383 **Yr Built/Renovated** :
Area Sq Ft : 43,622 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 11-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224004J

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$320,000
Total		\$320,000
Importance Code A		\$246,600
Importance Code C		\$73,400
Total		\$320,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$95,400		\$34,300	
Total	\$95,400		\$34,300	
Importance Code A	\$68,900		\$24,700	
Importance Code B			\$1,400	
Importance Code C	\$26,500		\$8,100	
Total	\$95,400		\$34,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
NY 25X TO/FROM 2ND AVENUE NYC GARAGE**

Asset # : 15383

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Concrete	20%	4+	\$47,800	LIFE			**	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Joints Missing, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southwest Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Granite Facing</i>								
Concrete	80%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%			2042		**	4	\$13,100
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : West Approach</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Approach On East Side</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Only On West Side</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	\$100
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
NY 25X TO/FROM 2ND AVENUE NYC GARAGE**

Asset # : 15383

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Pier, Columns								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	10%	4+	\$100	2053		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	90%			2053		**		
Concrete w/ Steel Face	100%	Now	\$3,800	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Near Approach At Median</i>								
Guide Railing								
Concrete	100%	4+	\$3,100	2046		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%	4+	\$600	LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
Median								
Concrete	100%	Now	\$5,200	LIFE		**	5	\$2,200
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : East Bound Roadway</i>								
<i>Explanation : Impact Damage To Four Concrete Bollards</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
NY 25X TO/FROM 2ND AVENUE NYC GARAGE**

Asset # : 15383

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Granite	100%	4+	\$7,400	LIFE		**		
<i>Joins Missing, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Vegetation Growth, Extent : Light, Area Affected : 2%</i> <i>Location : Near Southwest End</i> <i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Broken / Missing Elements</i>								
Steel	100%	4+	\$800	LIFE		**	2-8	\$600
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			2038		**	5	\$16,200
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	Now	\$22,200	2042		**	5	\$73,400
<i>Cracks, Extent : Moderate, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Failed Asphalt Patches</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Total Of 2 Scuppers</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE		**	2-8	\$460,500
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 95%</i> <i>Location : Throughout</i> <i>Explanation : 95 Percent Not Accessible</i>								
Secondary Member								
Steel	100%			LIFE		**	2-8	\$22,600
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 95%</i> <i>Location : Throughout</i> <i>Explanation : 95 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
 NY 25X TO/FROM 2ND AVENUE NYC GARAGE
 Asset # : 15383**

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : OCEAN AVENUE LIRR BAY RIDGE
 Address : OCEAN AVENUE BET. AVE H & AVE I
 Borough : BROOKLYN Agency's Number : N/A
 Program / Asset # : DOT0308.000 / 15066 Yr Built/Renovated :
 Area Sq Ft : 5,104 Project Type : HIGHWAY BRIDGES
 Date of Survey : 21-Dec-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2243480

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$37,500		\$1,200	
Total	\$37,500		\$1,200	
Importance Code A	\$1,500		\$100	
Importance Code B	\$20,100		\$1,100	
Importance Code C	\$15,900			
Total	\$37,500		\$1,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
OCEAN AVENUE LIRR BAY RIDGE
Asset # : 15066

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 75%</i>						
		<i>Location : Most Paved Over With Asphalt</i>						
		<i>Explanation : Joint</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : East And West Sides</i>						
		<i>Explanation : Limited Access</i>						
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : LIRR Tracks</i>						
Pier Protection								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 10%</i>						
		<i>Location : East And West Sides</i>						
		<i>Explanation : Limited Access</i>						
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
OCEAN AVENUE LIRR BAY RIDGE
Asset # : 15066

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	100%	4+	\$13,200	2036	**	4	\$9,500	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Northbound Lane</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$51,500	
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : East And West Sides</i>								
<i>Explanation : Limited Access</i>								
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Stains</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
OCEAN AVENUE LIRR BAY RIDGE
Asset # : 15066

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$4,000	
Sidewalks								
Concrete	100%			2040	**	5	\$2,100	
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Asphalt	100%			2036	**	5	\$5,500	
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PARK AVE. TUNNEL EAST 34TH ST/PARK AVE TUNNEL
Address : E34TH ST-39TH ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0083.000 / 2512 **Yr Built/Renovated** : 1919 /
Area Sq Ft : 36,200 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2246540

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$4,591,100	\$204,200
Total	\$4,591,100	\$204,200
Importance Code A	\$4,295,300	\$204,200
Importance Code C	\$295,800	
Total	\$4,591,100	\$204,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$82,300		\$17,600	
Total	\$82,300		\$17,600	
Importance Code A	\$56,400		\$2,100	
Importance Code B	\$1,600			
Importance Code C	\$24,300		\$15,400	
Total	\$82,300		\$17,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK AVE. TUNNEL EAST 34TH ST/PARK AVE TUNNEL
Asset # : 2512

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Limited Access To Abutment Components On 85 Percent Area</i>							
<hr/>								
Backwall								
Concrete	10%	Now	\$235,300	LIFE		**		
	<i>Spalling, Extent : Severe, Area Affected : 50%</i>							
	<i>Location : Both Abutments At South End</i>							
Concrete	90%			LIFE		**		
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE		**		
<hr/>								
Stem (breastwall)								
Brick Veneer	100%	4+	\$1,600	LIFE		**		
	<i>Efflorescence, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations On South End</i>							
	<i>Joints Missing, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Random Locations On South End</i>							
Concrete	100%			LIFE		**		
	<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations At North End</i>							
	<i>Spalling, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations At North End</i>							
<hr/>								
Wingwalls								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Walls								
Concrete	100%			LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations On North End</i>							
	<i>Efflorescence, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations On North End</i>							
Granite	90%			LIFE		**		
	<i>Efflorescence, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations On South End</i>							
Granite	10%			LIFE		**		
	<i>Joints Missing, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations On South End</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK AVE. TUNNEL EAST 34TH ST/PARK AVE TUNNEL
Asset # : 2512

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE	**			
Approaches								
Pavement								
Asphalt	100%			2036	**	4	\$30,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Granite	95%			LIFE	**			
Granite	5%	4+	\$19,200	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Gratings								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Vegetation Growth</i>								
Guide Railing								
Concrete	100%			2048	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : North End At 39th Street</i>								
<i>Explanation : Masonry Guide Rail</i>								
Railings/Parapets								
Granite	50%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On North End</i>								
<i>Explanation : Broken/ Missing Elements</i>								
Granite	50%			LIFE	**			
<i>Joints Missing, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On South End</i>								
Steel	100%			LIFE	**	2-8	\$96,500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK AVE. TUNNEL EAST 34TH ST/PARK AVE TUNNEL
Asset # : 2512

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%	2-4	\$60,500	2040	**	5	\$4,900	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Granite Paver	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : North End At 39th St</i>								
<i>Explanation : Paver Sidewalk</i>								
<hr/>								
Wearing Surface								
Asphalt	100%			2036	**	5	\$48,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : At 34th St</i>								
<i>Explanation : Steel Plates Over Roadway</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%	Now	\$3,966,300	LIFE	**	5	\$55,200	
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 10%</i>								
<i>Location : At North End</i>								
<i>Spalling, Extent : Severe, Area Affected : 15%</i>								
<i>Location : At North End</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : At South End</i>								
<i>Explanation : Scaling</i>								
<hr/>								
Primary Member								
Concrete	100%			LIFE	**	5	\$298,000	
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Concrete Arch</i>								
Concrete Encased Steel	100%	Now	\$180,100	LIFE	**	5	\$11,300	
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : At South End</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations At North End</i>								
<i>Spalling, Extent : Severe, Area Affected : 20%</i>								
<i>Location : At South End</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Bottom Flanges At North End</i>								
<i>Explanation : Pitting</i>								
<hr/>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
 PARK AVE. TUNNEL EAST 34TH ST/PARK AVE TUNNEL
 Asset # : 2512**

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PARK AVENUE NORTHBOUND EAST 45TH STREET
 Address : PARK AVE NB & E 45TH ST
 Borough : MANHATTAN Agency's Number : N/A
 Program / Asset # : DOT0363.000 / 15379 Yr Built/Renovated : 1920 /
 Area Sq Ft : 2,271 Project Type : HIGHWAY BRIDGES
 Date of Survey : 11-Mar-2022 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2245470

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$37,600		\$5,300	\$1,300
Total	\$37,600		\$5,300	\$1,300
Importance Code A	\$37,600		\$4,300	
Importance Code B			\$1,000	
Importance Code C				\$1,300
Total	\$37,600		\$5,300	\$1,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK AVENUE NORTHBOUND EAST 45TH STREET
Asset # : 15379

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Paved Roadway Underneath.</i>								
Piers								
Cap Beam								
Concrete Encased Steel	100%	0-2	\$4,400	LIFE		**	5	\$3,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : South End</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : South End</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : South End</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South End</i>								
<i>Explanation : Concrete Encased Steel Cap Beam</i>								
Steel	100%			LIFE		**	2-8	\$29,600
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : North End</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : North End</i>								
<i>Explanation : Covered With Decorative Plates</i>								
Pier, Columns								
Steel	100%			LIFE		**	2-8	\$23,500
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered With Decorative Plates</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Paving On Southeast Side. Concrete Sidewalk On All Other Locations.</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 60%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK AVENUE NORTHBOUND EAST 45TH STREET
Asset # : 15379

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Wearing Surface Asphalt	100%			2034	\$20,100	5	\$2,600	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Southeast Corner</i>								
<i>Explanation : Raveling</i>								
<hr/>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At North End</i>								
<i>Explanation : Total Of 2 Scuppers</i>								
<hr/>								
Superstructure								
Deck, Structural Not Accessible	100%							
<hr/>								
Joints								
Generic	100%			LIFE	**			
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 1%</i>								
<i>Location : Northeast Corner</i>								
<hr/>								
Primary Member								
Concrete Encased Steel	100%	4+	\$33,200	LIFE	**	5	\$35,600	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Floor beams Are Encased</i>								
<hr/>								
Steel	100%			LIFE	**	2-8	\$55,500	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Girders</i>								
<i>Explanation : Girders Are Covered With Steel Decorative Plates. Removed Decorative Plates On Bottom Flanges.</i>								
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$3,100	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On North End</i>								
<i>Explanation : Framed Around Scuppers</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date: 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PARK AVENUE SOUTHBOUND EAST 45TH STREET
Address : PARK AVE SB & EAST 45TH ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0362.000 / 15378 **Yr Built/Renovated** :
Area Sq Ft : 2,228 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 11-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245460

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$33,400
Total		\$33,400
Importance Code A		\$33,400
Total		\$33,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$27,600		\$7,400	\$1,200
Total	\$27,600		\$7,400	\$1,200
Importance Code A	\$27,600		\$6,000	
Importance Code B			\$1,000	
Importance Code C			\$500	\$1,200
Total	\$27,600		\$7,400	\$1,200



Note: All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
PARK AVENUE SOUTHBOUND EAST 45TH STREET
Asset # : 15378

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$77,200	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered With Decorative Plates</i>								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$22,500	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered With Decorative Plates</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Piers</i>								
<i>Explanation : Concrete Sidewalk</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			2038	**	5	\$900	
Wearing Surface								
Asphalt	100%			2034	\$18,500	5	\$2,400	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Near South End</i>								
<i>Explanation : 1 Scupper</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK AVENUE SOUTHBOUND EAST 45TH STREET
Asset # : 15378

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Generic	100%			LIFE		**		
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Primary Member								
Concrete Encased Steel	100%	4+	\$27,600	LIFE		**	5	\$29,500
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : With Exposed Rebar On Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Encased Floor Beams</i>								
Steel	100%			LIFE		**	2-8	\$48,800
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Decorative Facing On Web And Top Flanges. Visible Bottom Flange</i>								
Secondary Member								
Steel	100%			LIFE		**	2-8	\$2,600
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Framing Around Scupper</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PARK AVENUE VIADUCT EAST 42ND STREET
Address : PARK AVE & E 42ND ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0364.000 / 15380 **Yr Built/Renovated** :
Area Sq Ft : 24,564 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 11-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2246550

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$484,500	\$567,300
Total	\$484,500	\$567,300
Importance Code A	\$484,500	\$467,800
Importance Code B		\$37,400
Importance Code C		\$62,100
Total	\$484,500	\$567,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$69,400	\$1,400	\$28,300	
Total	\$69,400	\$1,400	\$28,300	
Importance Code A	\$32,400	\$1,400	\$22,800	
Importance Code B	\$7,800		\$5,000	
Importance Code C	\$29,100		\$500	
Total	\$69,400	\$1,400	\$28,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
PARK AVENUE VIADUCT EAST 42ND STREET
Asset # : 15380

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Bridge Connects To Different Bridge On South End And On Grand Central Terminal Building Wall On North End.</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Paving At East 42nd Street Under Span 6 And East 41st Street Under Span 3 . There Is A Cafe Under Span 5. Span 1, 2, 4, 5 & 7 Are Not Accessible.</i>								
Piers								
Cap Beam Not Accessible	100%							
Pier,Columns Steel	100%			LIFE		**	2-8	\$107,700
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Enclosed Within Walls Throughout</i>								
<i>Explanation : Steel Pier Encased In Masonry. Light Joint Mortar Missing On 5 Percent Of Area. 100 Percent Pier, Columns Are Not Accessible.</i>								
Stem,Solid Pier Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Light Joint Mortar Missing On 5 Percent Of Area. 100 Percent Stem, Solid Pier Not Accessible.</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK AVENUE VIADUCT EAST 42ND STREET
Asset # : 15380

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Sidewalk And Street Adjacent To The Wall</i>								
<i>Explanation : 95 Percent Not Accessible</i>								
<hr/>								
Pedestals								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	Now	\$18,700	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Guide Railing								
Concrete	100%			2046		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span 7</i>								
<i>Explanation : On North End Only</i>								
<hr/>								
Railings/Parapets								
Cast Iron	100%	4+	\$13,700	LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
<hr/>								
Masonry	100%			2042		**	5	\$2,800
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides</i>								
<i>Explanation : Masonry Railings At Span 1, 3 And 5.</i>								
<hr/>								
Steel	100%			LIFE		**	2-8	\$16,200
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Interior Rail</i>								
<i>Explanation : Location Noted</i>								
<hr/>								
Sidewalks								
Concrete	100%			2038		**	5	\$1,100
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At North End</i>								
<i>Explanation : Concrete Sidewalk At Span 7 Only</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK AVENUE VIADUCT EAST 42ND STREET
Asset # : 15380

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Wearing Surface								
Asphalt	100%	Now	\$5,000	2034	\$16,700	5	\$1,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Southbound Road On Span 7</i>								
<i>Explanation : 3 Pot Holes</i>								
Concrete	100%	4+	\$18,700	2042	**	5	\$62,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Full Width Transverse Cracks At Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span 6</i>								
<i>Explanation : Two Scuppers</i>								
Superstructure								
Deck, Structural								
Concrete	99%	4+	\$186,300	LIFE	**	5	\$27,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout Mostly Covered With Steel Mesh</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Spans 1, 2, 4, 5 And 7</i>								
<i>Explanation : Restaurant Underdeck And Wall Enclosure Causing 60 Percent Of Deck Not Accessible</i>								
Concrete	1%	Now	\$9,400	LIFE	**	5	\$27,000	
<i>Spalling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : East Fascia Of Span 3 Over East 41st Street</i>								
Joints								
Generic	100%	4+	\$5,400	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK AVENUE VIADUCT EAST 42ND STREET
Asset # : 15380

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Concrete Encased Steel	100%	4+	\$179,600	LIFE	**	5	\$192,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Edges Of Floor Beam Bottom Flanges Throughout</i>								
Steel	100%	4+	\$109,200	LIFE	**	2-8	\$413,800	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling. Pin And Hanger Connection At Both Ends. Steel Girder Arch At Span 3, 5 And 6.</i>								
Secondary Member								
Steel	100%	4+	\$7,800	LIFE	**	2-8	\$18,800	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : At Spans 1, 2, 4, 5 And 7</i>								
<i>Explanation : 70 Percent Of Secondary Member Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PARK ROW TO BROOKLYN WILLIAM STREET NORTHBOUND
Address : BKLY BRDG ON RAMP FROM PARK ROW OVER WILLIAM STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0341.000 / 15200 **Yr Built/Renovated** : 1956 /
Area Sq Ft : 3,388 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 17-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224001A

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$375,900
Total		\$375,900
Importance Code A		\$204,100
Importance Code C		\$171,800
Total		\$375,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure			\$30,800	\$4,800
Total			\$30,800	\$4,800
Importance Code A			\$22,900	\$3,500
Importance Code B			\$2,400	
Importance Code C			\$5,400	\$1,300
Total			\$30,800	\$4,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK ROW TO BROOKLYN WILLIAM STREET NORTHBOUND
Asset # : 15200

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : West Span</i>						
		<i>Explanation : Span Is Completely Enclosed And Not Accessible</i>						
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Paved Over With Asphalt Wearing Surface</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Enclosure Walls Of West Span And Stone Facing</i>						
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Wingwalls Are Concrete With Stone Facing</i>						
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK ROW TO BROOKLYN WILLIAM STREET NORTHBOUND
Asset # : 15200

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%			2033	\$87,100	4	\$2,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041	**	4	\$3,300	
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 1 Scupper Observed</i>								
Piers								
Cap Beam								
Masonry	100%			LIFE	**			
Steel	100%			LIFE	**	2-8	\$46,500	
Pier,Columns								
Masonry	100%			LIFE	**			
Steel	100%			LIFE	**	2-8	\$34,500	
Stem,Solid Pier								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stone Facing</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**	2-8	\$3,400	
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : East Side</i>								
<i>Explanation : Located On Masonry Pier</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%			2052	**			
Railings/Parapets								
Concrete	100%			2041	**	4	\$3,600	
Steel	100%			LIFE	**	2-8	\$8,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARK ROW TO BROOKLYN WILLIAM STREET NORTHBOUND
Asset # : 15200

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Wearing Surface Asphalt	100%			2033	\$84,800	5	\$10,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Galvanized Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : West Side</i>								
<i>Explanation : 3 Scuppers Observed</i>								
Superstructure								
Deck, Structural Grating w/ Concrete	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : West Span Not Accessible. Bottom Covered With Stay In Place Forms</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$381,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : West Span</i>								
<i>Explanation : Span Not Accessible</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$19,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : West Span</i>								
<i>Explanation : Span Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PARKING ENTRANCE RAMP STATEN ISLAND RAILWAY
Address : RAMP TO PARKING LOT SIRT STATEN ISLAND FERRY TERMINAL
Borough : STATEN ISLAND Agency's Number : N/A
Program / Asset # : DOT0347.000 / 15206 Yr Built/Renovated : 1948 /
Area Sq Ft : 8,821 Project Type : HIGHWAY BRIDGES
Date of Survey : 24-Nov-2020 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2269780

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$6,300	\$1,200	\$1,300	\$9,300
Total	\$6,300	\$1,200	\$1,300	\$9,300
Importance Code A			\$200	\$3,400
Importance Code B			\$1,200	
Importance Code C	\$6,300	\$1,200		\$5,900
Total	\$6,300	\$1,200	\$1,300	\$9,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARKING ENTRANCE RAMP STATEN ISLAND RAILWAY
Asset # : 15206

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Generic	100%			LIFE		**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Random Locations Throughout</i>				
			<i>Spalling, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Random Locations Throughout</i>				
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Concrete	100%			LIFE		**	
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Random Locations Throughout</i>				
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Piles							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Feature Crossed							
Mat (scour & erosion)							
Not Accessible	100%						
Approaches							
Pavement							
Concrete	100%			2041		**	4 \$11,800
			<i>Cracks, Extent : Light, Area Affected : 1%</i>				
			<i>Location : Random Locations Throughout</i>				
Curbs							
Concrete w/ Steel Face	100%			LIFE		**	
			<i>Cracks, Extent : Light, Area Affected : 1%</i>				
			<i>Location : Random Locations Throughout</i>				
Mat (scour & erosion)							
Not Accessible	100%						
Pavement Base							
Not Accessible	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARKING ENTRANCE RAMP STATEN ISLAND RAILWAY
Asset # : 15206

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets								
Concrete	100%			2041	**	4	\$800	
Masonry	100%			2041	**			
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railing And Chainlink Fence</i>								
<hr/>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Piers								
Cap Beam								
Not Accessible	100%							
<hr/>								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$33,100	
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2041	**	4	\$6,000	
<i>Damaged Railing, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$4,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South Side</i>								
<i>Explanation : Chain Link Fence Behind Concrete Wall</i>								
<hr/>								
Sidewalks								
Concrete	100%			2037	**	5	\$2,300	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$6,300	2041	**	5	\$20,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARKING ENTRANCE RAMP STATEN ISLAND RAILWAY
Asset # : 15206

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Scupper								
Cast Iron	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : 4 Scuppers Observed</i>						
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PARKING EXIT RAMP STATEN ISLAND RAILWAY
Address : RAMP FROM PARKING LOT
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0344.000 / 15203 **Yr Built/Renovated** : 1948 /
Area Sq Ft : 24,504 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 24-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2269730

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$64,300	\$663,000
Total	\$64,300	\$663,000
Importance Code A		\$550,400
Importance Code B		\$48,300
Importance Code C	\$64,300	\$64,300
Total	\$64,300	\$663,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,900	\$2,500	\$64,100	\$6,200
Total	\$2,900	\$2,500	\$64,100	\$6,200
Importance Code A			\$56,000	
Importance Code B	\$2,900		\$8,200	
Importance Code C		\$2,500		\$6,200
Total	\$2,900	\$2,500	\$64,100	\$6,200



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
PARKING EXIT RAMP STATEN ISLAND RAILWAY

Asset # : 15203

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck								
Generic	13%	Now	\$2,900	LIFE			**	
		<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : West Side</i>						
Generic	87%			LIFE			**	
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Concrete	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Pedestals Consist Of 50 Percent Concrete, 50 Percent Not Accessible.</i>						
Stem (breastwall)								
Concrete	100%			LIFE			**	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Rust Stains, Extent : Light, Area Affected : 50%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : North Abutment</i>						
		<i>Explanation : Stem Consist Of 50 Percent Concrete, 50 Percent Not Accessible Due To Art Piece.</i>						
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Rust Stains, Extent : Light, Area Affected : 20%</i>						
		<i>Location : Random Locations Throughout</i>						
Masonry	100%			LIFE			**	
		<i>Vegetation Growth, Extent : Light, Area Affected : 40%</i>						
		<i>Location : Northeast Corner</i>						

Feature Crossed

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

**DEPARTMENT OF TRANSPORTATION - 841
PARKING EXIT RAMP STATEN ISLAND RAILWAY**

Asset # : 15203

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Approaches								
Pavement								
Concrete	100%			2041	**	4	\$12,300	
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Masonry	100%			2041	**			
Sidewalks								
Concrete	100%			LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Both Approaches</i>					
Scupper								
Cast Iron	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 2 Scuppers Observed</i>					
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$139,100	
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$21,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PARKING EXIT RAMP STATEN ISLAND RAILWAY

Asset # : 15203

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%			2037	**	5	\$5,100	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2041	**	5	\$128,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 12 Scuppers Observed</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$27,000	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Entire Deck</i>								
<i>Explanation : Bottom Covered With Stay In Place Forms</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$1,028,000	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$51,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PEARL STREET TO BROOKLYN BRIDGE LAND ADJACENT TO BRIDGE
 Address : ON RAMP FROM PEARL STREET
 Borough : MANHATTAN Agency's Number : N/A
 Program / Asset # : DOT0342.000 / 15201 Yr Built/Renovated : 1964 /
 Area Sq Ft : 2,473 Project Type : HIGHWAY BRIDGES
 Date of Survey : 17-Nov-2020 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 224001C

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$132,300
Total		\$132,300
Importance Code A		\$132,300
Total		\$132,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$56,800		\$16,600	\$500
Total	\$56,800		\$16,600	\$500
Importance Code A	\$3,100		\$15,300	
Importance Code B	\$8,100		\$1,300	
Importance Code C	\$45,700			\$500
Total	\$56,800		\$16,600	\$500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEARL STREET TO BROOKLYN BRIDGE LAND ADJACENT TO BRIDGE
Asset # : 15201

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Construction Taking Place Underneath Bridge</i>								
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$8,100	LIFE			**	
<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 100%</i>								
<i>Location : At Approach</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southeast Side</i>								
<i>Explanation : Covering Span 1 And 2</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Asphalt	100%			2033	\$34,900	4	\$1,100	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEARL STREET TO BROOKLYN BRIDGE LAND ADJACENT TO BRIDGE
Asset # : 15201

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Concrete	100%	4+	\$2,600	2041	**	4	\$1,200	
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Exposed Reinforcement, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : Middle Of Span</i>					
			<i>Spalling, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : Middle Of Span</i>					
			<hr/>					
Steel	100%			LIFE	**			
			<i>Corrosion, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Chain Link Fence</i>					
<hr/>								
Sidewalks								
Concrete	100%	4+	\$1,900	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
<hr/>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$37,100	
<hr/>								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$13,200	
<hr/>								
Stem,Solid Pier								
Not Accessible	100%							
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pedestals								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEARL STREET TO BROOKLYN BRIDGE LAND ADJACENT TO BRIDGE
Asset # : 15201

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Concrete	100%			2041	**	4	\$1,400	
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Severe, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$11,800	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 20%</i> <i>Location : Near Approach</i> <i>Explanation : Chain-link Fence Behind Concrete Railing</i>								
Sidewalks								
Concrete	100%	4+	\$2,200	2037	**	5	\$400	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Vegetation Growth, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	2-4	\$11,700	2041	**	5	\$15,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Settlement, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 5 Scuppers</i>								
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$2,700	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Entire Deck</i> <i>Explanation : 15 Percent Not Accessible. Bottom Covered With Stay In Place Forms</i>								
Joints								
Generic	100%	Now	\$30,000	LIFE	**			
<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 100%</i> <i>Location : Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEARL STREET TO BROOKLYN BRIDGE LAND ADJACENT TO BRIDGE
Asset # : 15201

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$247,200	
<i>Other Observation, Extent : N/A, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 15 Percent Not Accessible</i>								
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$12,400	
<i>Other Observation, Extent : N/A, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 15 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PEDESTRIAN BRIDGE E. 174ST. / 895IX
Address : E. 174ST,BRONX RIVER, I895
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0005.0A0 / 2918 **Yr Built/Renovated** : 1909 /
Area Sq Ft : 1,800 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 01-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 206672A

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$43,300		\$8,400	
Total	\$43,300		\$8,400	
Importance Code A	\$42,400		\$2,500	
Importance Code B			\$2,200	
Importance Code C	\$900		\$3,700	
Total	\$43,300		\$8,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEDESTRIAN BRIDGE E. 174ST. / 895IX
Asset # : 2918

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE	**			
Backwall								
Concrete	100%			LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**			
			<i>Corrosion, Extent : Light, Area Affected : 15%</i>					
			<i>Location : East Side Bearing</i>					
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : East Side Pedestal</i>					
Stem (breastwall)								
Concrete	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout The Abutment</i>					
			<i>Explanation : With Brick Veneer</i>					
Approaches								
Pavement								
Concrete	100%			2042	**	4	\$2,700	
Curbs								
Granite	100%	4+	\$1,400	LIFE	**			
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Joint Mortar Between Granite Curbs</i>					
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEDESTRIAN BRIDGE E. 174ST. / 895IX
Asset # : 2918

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	95%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : At Parapet Base</i>								
Steel	5%	4+	\$300	LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Span 4</i>								
<i>Explanation : Panel Detached</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$8,200	
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$11,400	
Stem,Solid Pier								
Brick Veneer	100%			LIFE	**			
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Solid Pier</i>								
<i>Explanation : With Brick Veneer</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**	2-8	\$1,400	
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Solid Concrete Pier With Brick Veneer</i>								
<i>Explanation : 4 Concrete Pedestals</i>								
Deck Elements								
Curbs								
Concrete	100%			2053	**			
Mono Deck Surface								
Concrete	100%			2053	**	5	\$7,400	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEDESTRIAN BRIDGE E. 174ST. / 895IX
Asset # : 2918

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Steel	100%	4+	\$2,300	LIFE	**	2-8	\$8,500	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : At Base Of Parapet</i>								
<i>Missing Fastenings, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 3</i>								
<i>Explanation : Frame Detached</i>								
Scupper								
Cast Iron	35%			LIFE	**			
<i>Drains Clogged, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout The Deck</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Deck</i>								
<i>Explanation : Total Of 6 Drains</i>								
Cast Iron	65%			LIFE	**			
Superstructure								
Deck,Structural								
Concrete	70%			LIFE	**	5	\$1,800	
Concrete	30%	4+	\$38,400	LIFE	**	5	\$1,800	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Top Joint Along 147 Street Main Bridge</i>								
<i>Explanation : Underside Of Deck Spalled Area With Rusted Rebars Covered By Steel Mesh With Bolted Steel Plates.</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$33,300	
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$27,900	
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PEDESTRIAN BRIDGE E. 174ST. / 895IX
Address : E. 174ST,BRONX RIVER, I895
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0005.0B0 / 2919 **Yr Built/Renovated** : 1909 /
Area Sq Ft : 1,900 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 01-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 206672B

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$30,000		\$9,100	
Total	\$30,000		\$9,100	
Importance Code A	\$26,200		\$2,700	
Importance Code B			\$2,700	
Importance Code C	\$3,800		\$3,700	
Total	\$30,000		\$9,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEDESTRIAN BRIDGE E. 174ST. / 895IX
Asset # : 2919

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE	**			
Backwall								
Concrete	100%			LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : End Abutment</i>						
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**			
		<i>Corrosion, Extent : Light, Area Affected : 30%</i>						
		<i>Location : End Abutment</i>						
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Stem (breastwall)								
Concrete	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Locations Throughout</i>						
		<i>Explanation : With Brick Veneer</i>						
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : End Abutment</i>						
		<i>Explanation : With Brick Veneer And Three Weep Holes On Each Wall</i>						
Approaches								
Pavement								
Concrete	100%			2042	**	4	\$2,700	
Curbs								
Granite	100%			LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEDESTRIAN BRIDGE E. 174ST. / 895IX
Asset # : 2919

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Steel	100%	4+	\$500	LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Missing Fastenings, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Connection Angle Detached</i>								
Piers								
Cap Beam Steel	100%			LIFE		**	2-8	\$8,200
Pier,Columns Steel	65%			LIFE		**	2-8	\$11,400
Steel	35%			LIFE		**	2-8	\$11,400
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Base Of Center Pier</i>								
Stem,Solid Pier Brick Veneer	100%			LIFE		**		
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South End Pier</i>								
<i>Explanation : Concrete With Brick Veneer</i>								
Brngs,Ancr Blts,Pads Steel	90%			LIFE		**	2-8	\$1,400
Steel	10%			LIFE		**	2-8	\$1,400
<i>Corrosion, Extent : Light, Area Affected : 50%</i>								
<i>Location : At Pier With Brick Veneer</i>								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : South End Pier</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : South End Pier</i>								
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete	99%			2053		**		
Concrete	1%	4+	\$100	2053		**		
<i>Cracks, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PEDESTRIAN BRIDGE E. 174ST. / 895IX
Asset # : 2919

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Mono Deck Surface Concrete	100%			2053	**	5	\$7,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets Steel	100%			LIFE	**	2-8	\$8,500	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper Cast Iron	35%	4+	\$2,900	LIFE	**			
<i>Drains Clogged, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : All Drains Throughout The Deck</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout The Deck</i>								
<i>Explanation : Total Of 6 Drains</i>								
Cast Iron	65%			LIFE	**			
Superstructure								
Deck,Structural Concrete	100%	4+	\$25,600	LIFE	**	5	\$1,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$35,100	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$29,400	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PENNSYLVANIA AVENUE TO BSHP BELT PARKWAY
Address : PENNSYLVANIA AVE SOUTH BOUND TO EAST BOUND BELT PARKWAY
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0223.000 / 14958 **Yr Built/Renovated** :
Area Sq Ft : 6,570 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231519

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$274,200
Total		\$274,200
Importance Code A		\$274,200
Total		\$274,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$45,000	\$13,300	\$34,200	
Total	\$45,000	\$13,300	\$34,200	
Importance Code A	\$3,700		\$30,600	
Importance Code B	\$27,800		\$1,700	
Importance Code C	\$13,500	\$13,300	\$2,000	
Total	\$45,000	\$13,300	\$34,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

**DEPARTMENT OF TRANSPORTATION - 841
PENNSYLVANIA AVENUE TO BSHP BELT PARKWAY**

Asset # : 14958

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Backwall								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2053		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,600	LIFE		**		
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Stem (breastwall)								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Abutment</i>								
<i>Explanation : Limited Access On 30 Percent Of Area. Rust Stains On Utility Access Door.</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PENNSYLVANIA AVENUE TO BSHP BELT PARKWAY

Asset # : 14958

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Paving Underneath</i>								
Pier Protection								
Concrete	100%	4+	\$15,800	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Middle Pier North Face</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Middle Pier North Face</i>								
Approaches								
Pavement								
Concrete	100%			2042		4	\$40,500	**
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Corrosion, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 5%</i>								
<i>Location : Both Sides At South Approach</i>								
Embankment								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		5	\$900	**
<i>Delaminations, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042		4	\$3,700	**
Steel	100%	4+	\$900	LIFE			**	
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : North Approach</i>								
<i>Explanation : Vegetation Growth</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PENNSYLVANIA AVENUE TO BSHP BELT PARKWAY

Asset # : 14958

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$68,000	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Pier, Columns								
Concrete	100%	4+	\$9,400	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 3%</i>								
<i>Location : Top Of Pier Columns</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Top Of Middle Pier Column</i>								
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Brngs, Ancr Blts, Pads								
Elastomeric	100%			2053	**			
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Median								
Concrete	100%			LIFE	**	5	\$1,100	
<i>Delaminations, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2042	**	4	\$4,600	
Steel	100%			LIFE	**	2-8	\$4,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PENNSYLVANIA AVENUE TO BSHP BELT PARKWAY

Asset # : 14958

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%			2038	**	5	\$4,000	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2042	**	5	\$26,700	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$7,300	
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout Except At Both Overhangs</i>								
<i>Explanation : Covered By Stay In Place Forms</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$512,100	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$25,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PRESIDENT STREET FRANKLIN SHUTTLE
Address : PRESIDENT STREET BET CLASSON AVE & FRANKLIN AVE
Borough : BROOKLYN Agency's Number : N/A
Program / Asset # : DOT0306.000 / 15064 Yr Built/Renovated :
Area Sq Ft : 2,380 Project Type : HIGHWAY BRIDGES
Date of Survey : 21-Dec-2023 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2243210

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$53,000	\$53,000
Total	\$53,000	\$53,000
Importance Code B	\$53,000	\$53,000
Total	\$53,000	\$53,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$58,400		\$5,900	\$800
Total	\$58,400		\$5,900	\$800
Importance Code A	\$3,400		\$600	
Importance Code B	\$44,500		\$5,300	
Importance Code C	\$10,500			\$800
Total	\$58,400		\$5,900	\$800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PRESIDENT STREET FRANKLIN SHUTTLE
Asset # : 15064

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Covered By Asphalt Wearing Surface</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : South Side</i>						
		<i>Explanation : Concrete Crib Wall</i>						
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 10%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : MTA Subway Tracks</i>						
Approaches								
Pavement Asphalt	100%	4+	\$3,500	2039		**	4	\$2,500
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Curbs Concrete w/ Steel Face	100%			LIFE		**		
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Rust Stains</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PRESIDENT STREET FRANKLIN SHUTTLE
Asset # : 15064

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Chain Link Fence And Corrugated Rail</i>						
Sidewalks								
Concrete	10%	4+	\$1,100	LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Settlement, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Near Curb line</i>						
Concrete	90%			LIFE		**		
Scupper								
Cast Iron	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Southwest And Northwest Corners</i>						
		<i>Explanation : 2 Scuppers</i>						
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$250,300
		<i>Other Observation, Extent : N/A, Area Affected : 15%</i>						
		<i>Location : School Parking Lot</i>						
		<i>Explanation : Limited Access</i>						
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PRESIDENT STREET FRANKLIN SHUTTLE
Asset # : 15064

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$2,400	LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : North Curb</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : North Side At The Center Of The Bridge</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Rust Stains</i>								
Railings/Parapets								
Concrete	100%			2044		**	4	\$1,100
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Parapet With Brick Fascia</i>								
Steel	100%			LIFE		**	2-8	\$2,400
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Top Of Concrete Parapet</i>								
<i>Explanation : Chain Link Fence</i>								
Sidewalks								
Concrete	100%	4+	\$6,000	2040		**	5	\$1,200
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Asphalt	100%			2039		**	5	\$1,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PROMENADE OVER FDR / 81ST TO 90TH STREET
Address : 81ST TO 90TH STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0031.070 / 2925 **Yr Built/Renovated** : 1942 /
Area Sq Ft : 93,000 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2232167

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$19,538,100	\$9,822,700
Total	\$19,538,100	\$9,822,700
Importance Code A	\$17,466,000	\$7,403,700
Importance Code B	\$1,903,100	
Importance Code C	\$169,000	\$2,419,000
Total	\$19,538,100	\$9,822,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$155,300		\$4,600	
Total	\$155,300		\$4,600	
Importance Code A	\$27,700		\$4,100	
Importance Code B	\$28,900		\$500	
Importance Code C	\$98,700			
Total	\$155,300		\$4,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PROMENADE OVER FDR / 81ST TO 90TH STREET

Asset # : 2925

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Steel Railing On Top Of Wall</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>								
<i>Location : Northwest Corner</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Northwest Corner</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : North End</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 90th Street. North Side</i>								
<i>Explanation : Location Noted</i>								
Granite	65%			LIFE		**		
Granite	35%	4+	\$3,900	LIFE		**		
<i>Efflorescence, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Lower Two Courses Of Stones</i>								
<i>Loose Elements, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 81st Street, South Side</i>								
<i>Explanation : Location Noted</i>								
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Around Lower Structure</i>								
<i>Explanation : Location Noted</i>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Lower Structure Under Gracie Mansion</i>								
<i>Explanation : Pavement</i>								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PROMENADE OVER FDR / 81ST TO 90TH STREET
Asset # : 2925

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam Concrete	100%	4+	\$1,124,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Exposed Reinforcement</i>								
Steel	100%			LIFE		**	2-8	\$11,400
<i>Corrosion, Extent : Light, Area Affected : 15%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>								
Pier, Columns								
Concrete	10%	2-4	\$25,200	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 25%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Concrete	90%			LIFE		**		
Steel	100%	4+	\$3,700	LIFE		**	2-8	\$14,200
<i>Corrosion, Extent : Light, Area Affected : 15%</i> <i>Location : Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Stem, Solid Pier								
Concrete	100%	4+	\$1,903,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PROMENADE OVER FDR / 81ST TO 90TH STREET
Asset # : 2925

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Lower Structure Under Gracie Mansion</i>								
<i>Explanation : Pavement</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Gratings								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Tunnel Vent North Of Gracie Mansion At About 89th Street</i>								
<i>Explanation : Large Grating Area</i>								
<hr/>								
Railings/Parapets								
Concrete	100%	Now	\$462,400	2042		**	4	\$73,800
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Concentrated At Joints</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout, Also Concentrated At Joints</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Concentrated At Joints</i>								
<i>Explanation : Vegetation Growth</i>								
<hr/>								
Steel	100%	Now	\$27,700	LIFE		**	2-8	\$101,300
<i>Corrosion, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : At Second Joint From South End</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Railing Supports At Joints</i>								
<i>Explanation : Dislocated Anchors, Missing Concrete Around Anchors</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PROMENADE OVER FDR / 81ST TO 90TH STREET

Asset # : 2925

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Asphalt	5%	2-4	\$10,100	2034	\$101,100	5	\$62,400	
<i>Cracks, Extent : Moderate, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Settlement, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout With Ponding</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Failed Asphalt Patches</i>								
Asphalt	95%	4+	\$38,400	2034	\$1,921,500	5	\$62,400	
<i>Broken, Missing Pave, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Loose Elements, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Settlement, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Asphalt Pavers</i>								
Concrete	100%	Now	\$169,000	2042	* *	5	\$271,500	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%	4+	\$10,300	LIFE	* *			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 15%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 19 Scuppers</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PROMENADE OVER FDR / 81ST TO 90TH STREET

Asset # : 2925

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Concrete	30%	2-4	\$15,879,000	LIFE	**	5	\$3,685,200	
			<i>Cracks, Extent : Severe, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Defect Areas Are Covered In Mesh In 25 Percent Area. Limited Access To Deck, Structural.</i>					
Concrete	70%			LIFE	**	5	\$3,685,200	
Joints								
Generic	100%	4+	\$35,900	LIFE	**			
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 1%</i>					
			<i>Location : Near 84th Street</i>					
			<i>Explanation : Uneven Joint</i>					
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : QUEENS BLVD. BRIDGE QUEENS BLVD/INTERBOROUGH PKWY
 Address : IND SUBWAY STATION
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0016.090 / 2577 Yr Built/Renovated :
 Area Sq Ft : 37,753 Project Type : HIGHWAY BRIDGES
 Date of Survey : 02-Nov-2020 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2230209

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$72,800	\$4,277,500
Total	\$72,800	\$4,277,500
Importance Code A	\$72,800	\$1,341,600
Importance Code B		\$747,300
Importance Code C		\$2,188,500
Total	\$72,800	\$4,277,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$78,200	\$4,600	\$149,900	\$126,900
Total	\$78,200	\$4,600	\$149,900	\$126,900
Importance Code A	\$24,900		\$75,000	
Importance Code B	\$7,000		\$75,000	\$115,800
Importance Code C	\$46,200	\$4,600		\$11,100
Total	\$78,200	\$4,600	\$149,900	\$126,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS BLVD. BRIDGE QUEENS BLVD/INTERBOROUGH PKWY
Asset # : 2577

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Masonry: Brick	95%			LIFE	**	3-5	\$84,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stone Facing</i>								
Masonry: Brick	5%	4+	\$2,000	LIFE	**	3-5	\$84,100	
<i>Joints Missing, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Joint Mortar Missing Throughout Both Abutments</i>								
Masonry: Schist/Gneiss	5%	4+	\$5,000	LIFE	**	3-5	\$101,800	
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : End Of Abutment</i>								
<i>Explanation : Cracks</i>								
Masonry: Schist/Gneiss	95%			LIFE	**	3-5	\$101,800	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Spans 1-5</i>								
Pier Protection								
Not Accessible	100%							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS BLVD. BRIDGE QUEENS BLVD/INTERBOROUGH PKWY
Asset # : 2577

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%			2033	\$1,491,100	4	\$22,300	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	80%			LIFE		**		
Concrete w/ Steel Face	20%	4+	\$2,800	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i>								
<i>Location : Northwest Quadrant Asphalt Patch</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Guide Railing								
Steel	100%			LIFE		**	2-8	
Median								
Concrete	100%	4+	\$4,500	LIFE		**	5	\$500
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i>								
<i>Location : Northwest Quadrant Asphalt Patch</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Concrete Encased Steel	4%	2-4	\$72,800	LIFE		**	5	\$259,500
<i>Spalling, Extent : Severe, Area Affected : 80%</i>								
<i>Location : Northeast Beam End</i>								
Concrete Encased Steel	96%			LIFE		**	5	\$259,500
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Not Accessible</i>								
Pier,Columns								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS BLVD. BRIDGE QUEENS BLVD/INTERBOROUGH PKWY
Asset # : 2577

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Curbs								
Concrete w/ Steel Face	80%			LIFE		**		
Concrete w/ Steel Face	20%	2-4	\$4,500	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Guide Railing								
Steel	100%			LIFE		**		
<hr/>								
Median								
Concrete	98%	4+	\$9,000	LIFE		**	5	\$1,900
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	2%	0-2	\$1,800	LIFE		**	5	\$1,900
<i>Other Observation, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Misaligned/ Bulging</i>								
<hr/>								
Railings/Parapets								
Masonry	2%	2-4	\$1,400	2041		**	5	\$900
<i>Spalling, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Southwest Corner</i>								
Masonry	98%			2041		**	5	\$1,800
<hr/>								
Sidewalks								
Brick	100%			2052		**		
Concrete	10%	4+	\$11,300	2037		**	5	\$4,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	90%			2037		**	5	\$9,200

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS BLVD. BRIDGE QUEENS BLVD/INTERBOROUGH PKWY
Asset # : 2577

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface Asphalt	100%	4+	\$34,900	2033	\$697,500	5	\$21,500	
	<i>Cracks, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Settlement, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Superstructure								
Deck, Structural								
Concrete	10%			LIFE	**	5	\$37,600	
Concrete	90%			LIFE	**	5	\$37,600	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Not Accessible</i>							
Primary Member								
Steel	90%			LIFE	**	2-8	\$697,900	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Not Accessible</i>							
Steel	10%			LIFE	**	2-8	\$697,900	
Secondary Member								
Steel	90%			LIFE	**	2-8	\$584,700	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Not Accessible</i>							
Steel	10%			LIFE	**	2-8	\$584,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : QUEENS BOULEVARD 278I BROOKLYN-QUEENS EXPRESSWAY
Address : QUEENS BLVD. EAST OF 65TH PLACE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0317.000 / 15176 **Yr Built/Renovated** : 1957 /
Area Sq Ft : 25,704 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230530

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$301,900
Total		\$301,900
Importance Code A		\$241,800
Importance Code C		\$60,100
Total		\$301,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$18,100	\$4,200	\$24,500	\$41,300
Total	\$18,100	\$4,200	\$24,500	\$41,300
Importance Code A			\$24,500	\$2,400
Importance Code C	\$18,100	\$4,200		\$38,800
Total	\$18,100	\$4,200	\$24,500	\$41,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
QUEENS BOULEVARD 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15176

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals Not Accessible	100%						
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>					
		<i>Location : Throughout</i>					
		<i>Explanation : Access Required On Brooklyn Queens Expressway Below</i>					
<hr/>							
Backwall Not Accessible	100%						
<hr/>							
Brngs,Ancr Blts,Pads Not Accessible	100%						
<hr/>							
Footings Not Accessible	100%						
<hr/>							
Joint with Deck Generic	100%			LIFE		**	
<hr/>							
Mat (scour & erosion) Generic	100%			LIFE		**	
		<i>Other Observation, Extent : N/A, Area Affected : 98%</i>					
		<i>Location : Throughout</i>					
		<i>Explanation : Mat Consists Of 2 Percent Generic, 98 Percent Not Accessible</i>					
<hr/>							
Pedestals Not Accessible	100%						
<hr/>							
Stem (breastwall) Concrete	100%			LIFE		**	
		<i>Cracks, Extent : Light, Area Affected : 20%</i>					
		<i>Location : Random Locations Throughout</i>					
		<i>Other Observation, Extent : N/A, Area Affected : 98%</i>					
		<i>Location : Throughout</i>					
		<i>Explanation : Stem Consists Of 2 Percent Concrete, 98 Percent Not Accessible</i>					
<hr/>							
Wingwalls							
Footings Not Accessible	100%						
<hr/>							
Mat (scour & erosion) Earth	100%			LIFE		**	
<hr/>							
Piles Not Accessible	100%						
<hr/>							
Walls Concrete	100%			LIFE		**	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>					
		<i>Location : Random Locations Throughout</i>					
<hr/>							
Feature Crossed							
Mat (scour & erosion) Generic	100%			LIFE		**	
<hr/>							
Pier Protection Concrete	100%			LIFE		**	
		<i>Other Observation, Extent : N/A, Area Affected : 98%</i>					
		<i>Location : Random Locations Throughout</i>					
		<i>Explanation : Pier Protection Consists Of 2 Percent Concrete, 98 Percent Not Accessible</i>					
<hr/>							
Approaches							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS BOULEVARD 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15176

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	100%			2041	**	4	\$77,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Northeast Approach Slab</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 70%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Median								
Concrete	100%			LIFE	**	5	\$3,100	
Steel	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Fence In Between Lanes</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Both Approaches</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 98%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stem, Solid Pier Consists Of 2 Percent Concrete, 98 Percent Not Accessible</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS BOULEVARD 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15176

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion) Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 98%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Mat Consists Of 2 Percent Generic, 98 Percent Not Accessible</i>								
<hr/>								
Pedestals								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 70%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Median								
Concrete	100%			LIFE	**	5	\$5,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 33 Percent Temporary Concrete Barrier; 67 Percent Concrete Median</i>								
Steel	100%			LIFE	**	4-8	\$14,500	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Railing On Top Of Concrete Parapet</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2041	**	4	\$4,900	
Steel	100%			LIFE	**	2-8	\$6,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Railing On Top Of Concrete Parapet</i>								
<hr/>								
Sidewalks								
Concrete	100%			2037	**	5	\$8,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$18,100	2041	**	5	\$60,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
QUEENS BOULEVARD 278I BROOKLYN-QUEENS EXPRESSWAY
Asset # : 15176

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$451,600	
		<i>Corrosion, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 98%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Primary Member Consists Of 2 Percent Steel, 98 Percent Not Accessible</i>						
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RAMP TO HHP NB /RAMP TO NB HHP/AMTRAK WEST SIDE
 Address : RAMP TO HENRY HUDSON PKWY. / W.158TH ST.
 Borough : MANHATTAN Agency's Number : N/A
 Program / Asset # : DOT0011.0A0 / 2574 Yr Built/Renovated :
 Area Sq Ft : 10,800 Project Type : HIGHWAY BRIDGES
 Date of Survey : 19-Oct-2020 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 222934A

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$86,900	\$757,500
Total	\$86,900	\$757,500
Importance Code A	\$86,900	\$332,600
Importance Code B		\$312,800
Importance Code C		\$112,200
Total	\$86,900	\$757,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$134,600		\$65,300	\$1,800
Total	\$134,600		\$65,300	\$1,800
Importance Code A	\$49,700		\$33,900	\$1,000
Importance Code B	\$11,000		\$31,400	
Importance Code C	\$73,900			\$800
Total	\$134,600		\$65,300	\$1,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO HHP NB /RAMP TO NB HHP/AMTRAK WEST SIDE

Asset # : 2574

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	2-4	\$1,000	LIFE			**	
<i>Other Observation, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : South End</i>								
<i>Explanation : Torn And Detached Expansion Joint Material</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE			**	
Walls								
Concrete	100%			LIFE			**	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Asphalt	100%			2033	\$112,200	4	\$1,600	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Isolated Locations Throughout</i>								
Concrete	100%	4+	\$22,600	2041		**	4	\$6,200
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Granite	100%			LIFE			**	
Embankment								
Earth	100%			LIFE			**	
Railings/Parapets								
Steel	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO HHP NB /RAMP TO NB HHP/AMTRAK WEST SIDE

Asset # : 2574

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%			LIFE		**		
Scupper								
Cast Iron	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Locations Throughout</i>						
		<i>Explanation : 1 Scupper</i>						
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$274,600
		<i>Corrosion, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$285,000
Stem,Solid Pier								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	2%	Now	\$100	2052		**		
		<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 35%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete	98%			2052		**		
Granite	99%	4+	\$6,600	LIFE		**		
		<i>Settlement, Extent : Light, Area Affected : 5%</i>						
		<i>Location : On The Northwest Side</i>						
		<i>Other Observation, Extent : Light, Area Affected : 30%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Deteriorated/ Missing Joints At Granite Blocks</i>						
Granite	1%	Now	\$3,300	LIFE		**		
		<i>Broken/Missing Elements, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : On West Side</i>						
Guide Railing								
Steel	100%	4+	\$4,800	LIFE		**		
		<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Near End Of Approach</i>						
		<i>Explanation : Impact Damage</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO HHP NB /RAMP TO NB HHP/AMTRAK WEST SIDE

Asset # : 2574

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Median								
Concrete	100%	4+	\$5,400	LIFE	**	5	\$2,600	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 4%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 90%</i> <i>Location : Throughout</i> <i>Explanation : Grass Area</i>								
Mono Deck Surface								
Concrete	100%	4+	\$20,300	2052	**	5	\$28,700	
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 50%</i> <i>Location : On East Side Around Span 20</i>								
Railings/Parapets								
Concrete	25%	Now	\$6,800	2041	**	4	\$2,100	
<i>Spalling, Extent : Severe, Area Affected : 100%</i> <i>Location : Southwest Side On Top Of Parapet</i>								
Concrete	75%			2041	**	4	\$2,100	
Steel	100%			LIFE	**	2-8	\$16,300	
Sidewalks								
Cobblestone	100%			2052	**			
<i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : Along East Side</i> <i>Other Observation, Extent : Light, Area Affected : 100%</i> <i>Location : West And East Side</i> <i>Explanation : Vegetation Growth. Cobblestone Along West Side And Grassy Area Along East Side.</i>								
Concrete	100%	4+	\$29,200	2037	**	5	\$5,700	
<i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Vegetation Growth, Extent : Light, Area Affected : 5%</i> <i>Location : At West Side Of Sidewalk</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : 4 Scuppers Observed</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO HHP NB /RAMP TO NB HHP/AMTRAK WEST SIDE

Asset # : 2574

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Concrete	95%			LIFE	**	5	\$11,600	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Entire Deck</i>								
<i>Explanation : No Access To Tracks</i>								
Concrete	5%	4+	\$86,900	LIFE	**	5	\$11,600	
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Joints								
Generic	5%	2-4	\$1,800	LIFE	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
Generic	95%			LIFE	**			
Primary Member								
Steel	90%			LIFE	**	2-8	\$199,700	
Steel	10%	0-2	\$22,700	LIFE	**	2-8	\$199,700	
<i>Corrosion, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : On Floor Beam Bottom Flanges, Particularly Heavy At Joints</i>								
<i>Loss of Section, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	95%			LIFE	**	2-8	\$167,300	
Steel	5%	4+	\$10,000	LIFE	**	2-8	\$167,300	
<i>Corrosion, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RAMP TO THOMSON AVE. FROM NYC JACKSON AVENUE
 Address : OFF RAMP FROM ED KOCH QUEENSBORO BRIDGE TO THOMSON AVE
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0230.000 / 14969 Yr Built/Renovated :
 Area Sq Ft : 58,807 Project Type : HIGHWAY BRIDGES
 Date of Survey : 13-Jan-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 224004I

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$313,900	\$1,301,200
Total	\$313,900	\$1,301,200
Importance Code A		\$1,129,500
Importance Code C	\$313,900	\$171,700
Total	\$313,900	\$1,301,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$20,300	\$31,700	\$117,600	
Total	\$20,300	\$31,700	\$117,600	
Importance Code A		\$31,700	\$114,100	
Importance Code B	\$10,900		\$3,500	
Importance Code C	\$9,500			
Total	\$20,300	\$31,700	\$117,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO THOMSON AVE. FROM NYC JACKSON AVENUE

Asset # : 14969

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Roadway/ Parking Lot/ Under Construction</i>								
Pier Protection								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Bottom Of The Pier Columns</i>								
<i>Explanation : About 4 Feet And 0 Inches In Height, 3 Feet And 0 Inches X 3 Feet And 0 Inches Width X Length Concrete.</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$9,500	2043	**	4	\$7,400	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2043	**	4		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Approach Belongs To Other Assets</i>								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Approach Belongs To Other Assets</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$1,199,700	
Pier, Columns								
Concrete Encased Steel	7%	4+	\$10,900	LIFE	**	5	\$11,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete Encased Steel	93%			LIFE	**	5	\$11,100	
Brngs, Ancr Blts, Pads								
Steel	100%			LIFE	**	2-8	\$13,700	
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Steel	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO THOMSON AVE. FROM NYC JACKSON AVENUE

Asset # : 14969

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles	100%							
Not Accessible	100%							
Deck Elements								
Railings/Parapets	100%			2043	**	4	\$95,100	
Concrete								
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 95 Percent Concrete</i>					
Steel	100%			LIFE	**	2-8	\$87,100	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 5 Percent Steel</i>					
Wearing Surface	100%	4+	\$244,200	2043	**	5	\$171,700	
Concrete								
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Scupper	100%			LIFE	**			
Cast Iron								
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : 46 Scupper Observed</i>					
Superstructure								
Deck,Structural	100%							
Not Accessible								
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stay-in-place Form</i>					
Joints	100%	4+	\$69,700	LIFE	**			
Steel								
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Debris</i>					
Primary Member	100%			LIFE	**	2-8	\$1,087,100	
Steel								
Secondary Member	100%			LIFE	**	2-8	\$54,600	
Steel								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RICHMOND VALLEY ROAD SIRT SOUTH SHORE
Address : RICHMOND VALLY ROAD BETWEEN AMBOY ROAD & WEINER STREET
Borough : STATEN ISLAND Agency's Number : N/A
Program / Asset # : DOT0228.000 / 14967 Yr Built/Renovated : 1938 /
Area Sq Ft : 9,300 Project Type : HIGHWAY BRIDGES
Date of Survey : 07-Mar-2023 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2249270

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,465,500	\$92,000
Total	\$1,465,500	\$92,000
Importance Code A	\$1,363,600	\$92,000
Importance Code B	\$101,900	
Total	\$1,465,500	\$92,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$88,800	\$10,300	\$28,200	
Total	\$88,800	\$10,300	\$28,200	
Importance Code A	\$5,400		\$9,500	
Importance Code B	\$39,300		\$200	
Importance Code C	\$44,200	\$10,300	\$18,500	
Total	\$88,800	\$10,300	\$28,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
RICHMOND VALLEY ROAD SIRT SOUTH SHORE**

Asset # : 14967

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 70%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Backwall Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 90%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Mat (scour & erosion) Earth	100%			LIFE		**		
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	100%			LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 70%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Feature Crossed								
Mat (scour & erosion) Earth	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Railroad Tracks</i>						
Pier Protection Concrete	100%	4+	\$29,200	LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Approaches								
Pavement Concrete	100%			2043		**	4	\$30,800
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RICHMOND VALLEY ROAD SIRT SOUTH SHORE

Asset # : 14967

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Embankment								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Behind Guide Rails</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$1,500	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Piers								
Cap Beam								
Concrete	100%	Now	\$288,200	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Severe Cases At The Middle Pier</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Severe Cases At The Middle Pier</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Severe Cases At The Middle Pier</i>								
<hr/>								
Pier,Columns								
Concrete	100%	4+	\$101,900	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RICHMOND VALLEY ROAD SIRT SOUTH SHORE
Asset # : 14967

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$5,400	LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Along Concrete Steel Interface</i>								
<hr/>								
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$8,000	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Near Approaches On All Four Corners</i>								
<i>Explanation : Chain Link Fence Attached To Steel Railing Throughout. Vegetation Growth</i>								
<hr/>								
Sidewalks								
Concrete	100%	Now	\$36,700	2039	**	5	\$2,900	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%			2043	**	5	\$36,900	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%	0-2	\$765,600	LIFE	**	5	\$10,200	
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Wire Mesh Underside Deck Over Platform Area. Stay-In-Place Forms</i>								
<hr/>								
Joints								
Generic	100%	Now	\$6,000	LIFE	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Around Joint Headers</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RICHMOND VALLEY ROAD SIRT SOUTH SHORE

Asset # : 14967

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Concrete Encased Steel	100%	0-2	\$309,800	LIFE	**	5	\$46,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$171,900	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Concrete Encased Steel	100%	4+	\$10,100	2062	**			
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Scattered Locations</i>								
<i>Explanation : Loss Of Section</i>								
Steel	100%			LIFE	**	2-8	\$3,700	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RIVERDALE AVENUE HENRY HUDSON PARKWAY
Address : RIVERDALE AVENUE OVER HENRY HUDSON PKWY
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0370.000 / 15388 **Yr Built/Renovated** :
Area Sq Ft : 4,940 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2229510

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$89,800		\$200	
Total	\$89,800		\$200	
Importance Code A	\$37,800		\$200	
Importance Code B	\$29,800			
Importance Code C	\$22,200			
Total	\$89,800		\$200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
RIVERDALE AVENUE HENRY HUDSON PARKWAY

Asset # : 15388

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Stem (breastwall)								
Concrete	10%	4+	\$12,400	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	90%			LIFE	**			
Granite	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE	**			
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE	**			
Pier Protection								
Concrete	5%	4+	\$4,500	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Southbound Henry Hudson Parkway</i>					
Concrete	95%			LIFE	**			
Approaches								
Pavement								
Concrete	100%			2042	**	4	\$29,200	
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Granite	100%			LIFE	**			
Steel	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERDALE AVENUE HENRY HUDSON PARKWAY

Asset # : 15388

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%			LIFE			**	
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southeast And Southwest Corners</i>								
<i>Explanation : Earth</i>								
Piers								
Stem,Solid Pier								
Concrete	100%	4+	\$12,900	LIFE			**	
<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northbound Henry Hudson Parkway</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Granite	100%			LIFE			**	
Steel	100%			LIFE		2-8	\$4,300	
Sidewalks								
Concrete	100%	4+	\$9,700	2038		5	\$1,600	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$2,800	2042		5	\$9,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Curb line</i>								
Superstructure								
Deck,Structural								
Concrete	100%	4+	\$37,800	LIFE		5	\$5,400	
<i>Efflorescence, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Above Northbound Henry Hudson Parkway</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RIVERSIDE DR. VIADUCT BRIDGE RIVERSIDE DR/W. 158TH ST
Address : 152ND ST- W161ST ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0069.000 / 2493 **Yr Built/Renovated** : 1908 /
Area Sq Ft : 181,487 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 04-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2246720

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$21,980,600	\$7,827,000
Total	\$21,980,600	\$7,827,000
Importance Code A	\$15,877,400	\$5,155,700
Importance Code B	\$4,209,100	
Importance Code C	\$1,894,000	\$2,671,400
Total	\$21,980,600	\$7,827,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$54,900		\$298,000	
Total	\$54,900		\$298,000	
Importance Code A	\$11,800		\$298,000	
Importance Code B	\$21,100			
Importance Code C	\$22,000			
Total	\$54,900		\$298,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DR. VIADUCT BRIDGE RIVERSIDE DR/W. 158TH ST
Asset # : 2493

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$60,100	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 25%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 25%</i> <i>Location : At Begin Abutment</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Substructure. Bridge Components And Defects Identified From Biennial.</i>								
Granite	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Substructure. Bridge Components Identified From Biennial.</i>								
Backwall								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Substructure. Bridge Components Identified From Biennial.</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE			**	
<i>Corrosion, Extent : Moderate, Area Affected : 25%</i> <i>Location : Both Abutments</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Substructure. Bridge Components And Defects Identified From Biennial.</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	2-4	\$21,100	LIFE			**	
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i> <i>Location : End Abutment</i> <i>Explanation : Worn Out Filler. West Side Not Accessible Due To Construction.</i>								
Mat (scour & erosion)								
Earth	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Substructure. Bridge Components Identified From Biennial.</i>								
Pedestals								
Concrete	100%	4+	\$93,900	LIFE			**	
<i>Spalling, Extent : Moderate, Area Affected : 10%</i> <i>Location : At Begin Abutment</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Substructure. Bridge Components And Defects Identified From Biennial.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DR. VIADUCT BRIDGE RIVERSIDE DR/W. 158TH ST
Asset # : 2493

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Stem (breastwall)								
Concrete	100%	4+	\$195,500	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Substructure. Bridge Components And Defects Identified From Biennial.</i>								
Granite	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Substructure. Bridge Components Identified From Biennial.</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Wingwall. Bridge Components Identified From Biennial.</i>								
Piles								
Not Accessible	100%							
Walls								
Granite	100%	4+	\$22,000	LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : No Access To Wingwall Throughout. Bridge Components And Defects Identified From Biennial. Paint Peeling</i>								
Masonry	100%			LIFE		**		
<i>Vegetation Growth, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : At Begin Abutment</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Wingwalls. Bridge Components And Defects Identified From Biennial.</i>								
Feature Crossed								
Bank Protection								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DR. VIADUCT BRIDGE RIVERSIDE DR/W. 158TH ST
Asset # : 2493

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	100%	2-4	\$396,600	2042	**	4	\$30,800	
<i>Cracks, Extent : Light, Area Affected : 25%</i>								
<i>Location : North Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : North Approach</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Failed Asphalt Patches. West Half Not Accessible Due To Construction.</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Southeast Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout Southwest Side</i>								
<i>Explanation : Not Accessible Due To Construction</i>								
Granite	100%	4+	\$5,000	LIFE	**			
<i>Settlement, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout Northwest Side</i>								
<i>Explanation : Not Accessible Due To Construction</i>								
Embankment								
Generic	100%			LIFE	**			
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout West Half</i>								
<i>Explanation : Not Accessible Due To Construction</i>								
Granite	100%	4+	\$6,800	LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Missing Joint Mortar</i>								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Southeast Corner</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout West Half</i>								
<i>Explanation : Not Accessible Due To Construction</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DR. VIADUCT BRIDGE RIVERSIDE DR/W. 158TH ST
Asset # : 2493

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Total Of 2 Scuppers. West Half Not Accessible Due To Construction</i>								
<hr/>								
Piers								
Cap Beam								
Concrete Encased Steel	100%			LIFE		**	5	\$19,100
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Piers. Bridge Components Identified From Biennial.</i>								
Steel	100%			LIFE		**	2-8	\$3,374,000
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Piers. Bridge Components And Defects Identified From Biennial.</i>								
<hr/>								
Pier,Columns								
Concrete Encased Steel	100%	0-2	\$1,358,300	LIFE		**	5	\$1,900
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : No Access To Piers Throughout. Bridge Components And Defects Identified From Biennial. Corrosion</i>								
<hr/>								
Stem,Solid Pier								
Masonry	100%	4+	\$2,597,300	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : On Face And Base Of Pier Respectively</i>								
<i>Explanation : No Access To Piers Throughout. Bridge Components Identified From Biennial. Hollow Sound Area And Vertical Cracks And Vegetation Growth</i>								
<hr/>								
Brngs,Ancr Blts,Pads								
Steel	100%	2-4	\$876,800	LIFE		**	2-8	\$173,900
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Missing Anchor Bolts On Several Spans</i>								
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Several Spans</i>								
<i>Explanation : No Access To Piers. Bridge Components And Defects Identified From Biennial.</i>								
<hr/>								
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DR. VIADUCT BRIDGE RIVERSIDE DR/W. 158TH ST
Asset # : 2493

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Piers. Bridge Components Identified From Biennial.</i>								
<hr/>								
Pedestals								
Concrete	100%	4+	\$58,000	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Crack On Right Wall That Propagates Into Pedestal</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Piers. Bridge Components And Defects Identified From Biennial.</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout West Half</i>								
<i>Explanation : Not Accessible Due To Construction</i>								
<hr/>								
Granite	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout West Half</i>								
<i>Explanation : Not Accessible Due To Construction</i>								
<hr/>								
Railings/Parapets								
Granite	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Significant Defects On East Side. West Side Is Under Construction.</i>								
<hr/>								
Masonry	100%	4+	\$62,200	2042		**	5	\$12,900
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout East Side</i>								
<i>Explanation : West Side Is Under Construction Throughout. Joint Mortar Missing/ Eroded.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DR. VIADUCT BRIDGE RIVERSIDE DR/W. 158TH ST
Asset # : 2493

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%	4+	\$265,200	2038	**	5	\$58,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout East Half</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout</i> <i>Explanation : Not Accessible Due To Construction On West Side. Temporary Asphalt Sidewalk On 80 Percent Of East Side.</i>								
<hr/>								
Wearing Surface								
Asphalt	100%			2034	\$2,212,900	5	\$149,500	
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout East Side</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout</i> <i>Explanation : West Side Is Under Construction</i>								
Concrete	100%	2-4	\$462,300	2042	**	5	\$325,000	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout East Side</i> <i>Spalling, Extent : Moderate, Area Affected : 2%</i> <i>Location : Random Locations Throughout East Side</i> <i>Other Observation, Extent : Moderate, Area Affected : 2%</i> <i>Location : At Riverside Dr East And Riverside Dr West</i> <i>Explanation : West Side Is Under Construction Throughout. Failed Asphalt Patches</i>								
<hr/>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout West Side</i> <i>Explanation : Not Accessible Due To Construction</i>								
<hr/>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DR. VIADUCT BRIDGE RIVERSIDE DR/W. 158TH ST
Asset # : 2493

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Concrete	70%			LIFE	**	5	\$177,500	
Concrete	30%	4+	\$10,489,600	LIFE	**	5	\$177,500	
<i>Cracks, Extent : Moderate, Area Affected : 25%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Superstructure. Bridge Components And Defects Identified From Biennial.</i>								
Joints								
Steel	100%	2-4	\$695,200	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i> <i>Location : On East Side</i> <i>Other Observation, Extent : N/A, Area Affected : 30%</i> <i>Location : At South End</i> <i>Explanation : Paved Over With Asphalt On East Side. Not Accessible Due To Construction On West Side.</i>								
Primary Member								
Concrete Encased Steel	90%			LIFE	**	5	\$914,500	
Concrete Encased Steel	10%	2-4	\$4,294,700	LIFE	**	5	\$914,500	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Corrosion, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Superstructure. Bridge Components And Defects Identified From Biennial.</i>								
Steel	100%			LIFE	**	2-8	\$2,684,100	
<i>Rust Stains, Extent : Light, Area Affected : 25%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Superstructure. Bridge Components And Defects Identified From Biennial.</i>								
Secondary Member								
Concrete Encased Steel	100%			2061	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : No Access To Superstructure. Bridge Components Identified From Biennial.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DR. VIADUCT BRIDGE RIVERSIDE DR/W. 158TH ST
Asset # : 2493

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RIVERSIDE DRIVE SOUTH AMTRAK
Address : RIVERSIDE DRIVE(BLVD) & W70TH ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0288.000 / 15046 **Yr Built/Renovated** :
Area Sq Ft : 68,869 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 20-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2269200

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$876,500	\$876,500
Total	\$876,500	\$876,500
Importance Code A	\$757,400	\$757,400
Importance Code C	\$119,000	\$119,000
Total	\$876,500	\$876,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$310,100		\$87,300	
Total	\$310,100		\$87,300	
Importance Code A	\$232,700		\$76,100	
Importance Code B	\$58,900		\$4,100	
Importance Code C	\$18,400		\$7,100	
Total	\$310,100		\$87,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DRIVE SOUTH AMTRAK
Asset # : 15046

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South Side</i>								
<i>Explanation : Only South Abutment</i>								
Backwall Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : South Abutment</i>								
Brngs,Ancr Blts,Pads Elastomeric	100%			2055		**		
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
<i>Leakage, Extent : Light, Area Affected : 30%</i>								
<i>Location : South Abutment</i>								
Mat (scour & erosion) Earth	100%	Now	\$10,600	LIFE		**		
<i>Erosion, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Southeast Corner Of South Abutment</i>								
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Walls Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location : Adjacent To Amtrak</i>								
<i>Explanation : Wall Located Behind Final Pier On North End</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southwest Wall</i>								
Feature Crossed								
Mat (scour & erosion) Earth	100%			LIFE		**		

Approaches

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DRIVE SOUTH AMTRAK
Asset # : 15046

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$14,300	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete	100%			LIFE	**			
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Northwest Approach</i>								
Concrete w/ Steel Face	100%			LIFE	**			
Granite	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 75%</i>								
<i>Location : North Approach</i>								
<i>Explanation : Stone Curbs On North Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southwest Approach</i>								
<i>Explanation : Only On Southwest Corner</i>								
Sidewalks								
Concrete	100%			LIFE	**			
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South Approach</i>								
<i>Explanation : 2 Scuppers</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Underside Of Several Pier Caps Throughout</i>								
<i>Explanation : Water Stains</i>								
Pier,Columns								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIVERSIDE DRIVE SOUTH AMTRAK
Asset # : 15046

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2044	**	4	\$13,800	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout West Side</i>								
Steel	100%			LIFE	**	2-8	\$13,800	
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Northwest Parapet</i>								
<i>Explanation : Steel Fence On North Portion Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%			2040	**	5	\$54,900	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044	**	5	\$238,100	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Bridge Deck</i>								
<i>Explanation : 3 Scuppers</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$151,600	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout On Stay In Place Forms</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Joints								
Generic	100%	0-2	\$18,400	LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Depressed And Dislodged. Collecting Debris.</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$2,182,200	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$112,300	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ROCKAWAY BOULEVARD OVER HOOK CREEK
Address : ROCKAWAY BLVD BTWN 3RD ST & EAST AVE, JAMAICA
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0378.000 / 15397 **Yr Built/Renovated** :
Area Sq Ft : 18,135 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2300130

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$26,500	\$40,300	\$2,900	
Total	\$26,500	\$40,300	\$2,900	
Importance Code A	\$11,400		\$300	
Importance Code C	\$15,100	\$40,300	\$2,600	
Total	\$26,500	\$40,300	\$2,900	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

**DEPARTMENT OF TRANSPORTATION - 841
ROCKAWAY BOULEVARD OVER HOOK CREEK**

Asset # : 15397

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 95%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Feature Crossed								
Bank Protection								
Sheet Piling	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : At South Abutment Only</i>					
Mat (scour & erosion)								
Stream Bed	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%	4+	\$15,100	2042		**	4	\$22,100
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Near South Abutment Joint</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
ROCKAWAY BOULEVARD OVER HOOK CREEK**

Asset # : 15397

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	4+	\$5,200	LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southwest Corner</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$3,600	2042		**	4	\$900
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Southwest Corner</i>								
Steel	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stream Channel</i>								
Pedestals								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
ROCKAWAY BOULEVARD OVER HOOK CREEK**

Asset # : 15397

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Concrete	100%			2042		**	4	\$7,700
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$7,000
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Concrete Parapet</i>								
Sidewalks								
Concrete	100%			2038		**	5	\$5,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2042		**	5	\$80,600
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Full Width Transverse Cracks Along Pier And Longitudinal Crack On Westbound Lane</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ROOSEVELT AVENUE SHEA ROAD
Address : OVER SHEA ROAD BETWEEN OLMSTED DR. AND STADIUM PLACE N.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0234.000 / 14974 **Yr Built/Renovated** :
Area Sq Ft : 6,617 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2267160

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$126,900	\$269,400
Total	\$126,900	\$269,400
Importance Code A	\$126,900	\$131,000
Importance Code C		\$138,400
Total	\$126,900	\$269,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$65,700		\$13,500	
Total	\$65,700		\$13,500	
Importance Code A	\$9,300		\$13,100	
Importance Code B	\$27,900		\$400	
Importance Code C	\$28,500			
Total	\$65,700		\$13,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT AVENUE SHEA ROAD
Asset # : 14974

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$1,900	LIFE			**	
	<i>Cracks, Extent : Light, Area Affected : 4%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 3%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 50 Percent Concrete</i>							
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : End Abutment; 50 Percent Not Accessible</i>							
Backwall								
Concrete	4%	4+	\$6,200	LIFE			**	
	<i>Cracks, Extent : Light, Area Affected : 4%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 3%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 50 Percent Concrete</i>							
Concrete	96%			LIFE			**	
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : End Abutment; 50 Percent Not Accessible</i>							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 50 Percent Generic</i>							
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : End Abutment; 50 Percent Not Accessible</i>							
Pedestals								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT AVENUE SHEA ROAD
Asset # : 14974

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Stem (breastwall) Concrete	3%	4+	\$12,700	LIFE			**	
	<i>Cracks, Extent : Light, Area Affected : 8%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 50 Percent Concrete</i>							
Concrete	97%			LIFE			**	
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : End Abutment; 50 Percent Not Accessible</i>							
Walls								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : End Abutment; 50 Percent Not Accessible</i>							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE			**	
	<i>Efflorescence, Extent : Light, Area Affected : 3%</i> <i>Location : Random Locations Throughout</i>							
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE			**	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Paved Roadway</i>							
Approaches								
Pavement								
Asphalt	100%	4+	\$2,800	2035	\$138,400	4	\$4,300	
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>							
Curbs								
Concrete	100%	4+	\$1,400	LIFE			**	
	<i>Spalling, Extent : Light, Area Affected : 3%</i> <i>Location : Random Locations Throughout</i>							
Embankment								
Earth	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT AVENUE SHEA ROAD
Asset # : 14974

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 70 Percent Concrete</i>						
Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 30 Percent Generic - Earth</i>						
Scupper								
Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 1 Scupper Observed</i>						
Piers								
Stem,Solid Pier								
Concrete	4%	4+	\$15,200	LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 3%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 45 Percent Concrete</i>						
Concrete	96%			LIFE	**			
Masonry	100%			LIFE	**			
		<i>Efflorescence, Extent : Light, Area Affected : 4%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 10 Percent Masonry</i>						
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : Pier 3</i>						
		<i>Explanation : 45 Percent Not Accessible</i>						
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT AVENUE SHEA ROAD
Asset # : 14974

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 50 Percent Generic</i>						
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Pier 3; 50 Percent Not Accessible</i>						
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	7%	4+	\$1,200	2054		**		
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete	93%			2054		**		
Railings/Parapets								
Cast Iron	100%			LIFE		**		
Sidewalks								
Concrete	100%	4+	\$18,600	2039		**	5	\$3,100
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Wearing Surface								
Asphalt	100%	4+	\$1,000	2035	\$48,200		5	\$3,100
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT AVENUE SHEA ROAD
Asset # : 14974

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%	4+	\$126,900	LIFE	**	5	\$7,300	
	<i>Cracks, Extent : Light, Area Affected : 8%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 4%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 4%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 50 Percent Concrete</i>							
Not Accessible	100%	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : 50 Percent Not Accessible</i>						
Joints								
Not Accessible	100%							
Primary Member								
Steel	3%	4+	\$4,700	LIFE	**	2-8	\$122,300	
	<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Southeast Fascia And Northwest Fascia</i> <i>Explanation : Impact Damage; 50 Percent Steel</i>							
Steel	97%			LIFE	**	2-8	\$122,300	
Not Accessible	100%	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : Spans 2 And 4; 50 Percent Not Accessible</i>						
Secondary Member								
Steel	100%			LIFE	**	2-8	\$6,100	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 50 Percent Steel</i>							
Not Accessible	100%	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : Span 2 And 4; 50 Percent Not Accessible</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ROSE AVE SIRT SOUTH SHORE
Address : ROSE AVENUE AT NEW DORP PLAZA AND S. RAILROAD AVENUE
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0263.000 / 15017 **Yr Built/Renovated** :
Area Sq Ft : 3,700 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249420

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$123,700		\$14,300	
Total	\$123,700		\$14,300	
Importance Code A	\$67,500		\$3,800	
Importance Code B	\$11,900		\$200	
Importance Code C	\$44,300		\$10,300	
Total	\$123,700		\$14,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ROSE AVE SIRT SOUTH SHORE
Asset # : 15017

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Northeast Corner</i>						
		<i>Rust Stains, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Northeast Corner</i>						
<hr/>								
Backwall Concrete	100%	4+	\$22,200	LIFE		**		
		<i>Cracks, Extent : Moderate, Area Affected : 2%</i>						
		<i>Location : West Abutment Near North End And Random Locations</i>						
<hr/>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
<hr/>								
Footings Not Accessible	100%							
<hr/>								
Joint with Deck Generic	100%	2-4	\$8,300	LIFE		**		
		<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 60%</i>						
		<i>Location : Throughout</i>						
<hr/>								
Mat (scour & erosion) Generic	100%	0-2	\$900	LIFE		**		
		<i>Broken,Missing Pave, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : North End Of West Abutment</i>						
		<i>Other Observation, Extent : Light, Area Affected : 50%</i>						
		<i>Location : West Abutment</i>						
		<i>Explanation : Concrete Paver</i>						
<hr/>								
Stem (breastwall) Concrete	100%			LIFE		**		
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : North End Of East Abutment</i>						
		<i>Rust Stains, Extent : Light, Area Affected : 2%</i>						
		<i>Location : North End Of East Abutment</i>						
<hr/>								
Wingwalls								
Footings Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : Throughout East Side</i>						
		<i>Explanation : Railway Ballasts</i>						
<hr/>								
Piles Not Accessible	100%							
<hr/>								
Walls Concrete	100%			LIFE		**		
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations On East Side</i>						
<hr/>								
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROSE AVE SIRT SOUTH SHORE
Asset # : 15017

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Tracks</i>								
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$20,600
<i>Cracks, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	2-4	\$600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Approach</i>								
Piers								
Cap Beam								
Concrete	100%	4+	\$12,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Cap Ends And Random Locations</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Pier,Columns								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROSE AVE SIRT SOUTH SHORE
Asset # : 15017

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$5,100
			<i>Corrosion, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Base Of Posts And Random Locations</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Chain Link Fence Behind Steel Railings</i>					
Sidewalks								
Concrete	100%	Now	\$5,900	2040		**	5	\$1,100
			<i>Cracks, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : Midspan On North Side And Random Locations</i>					
			<i>Other Observation, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling</i>					
Wearing Surface								
Concrete	100%	Now	\$11,900	2044		**	5	\$7,300
			<i>Cracks, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Delaminations, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout With Worst Cases At Centerline Near West Abutment Joint</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Concrete	100%			LIFE		**	5	\$8,100
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 20%</i>					
			<i>Location : Over Platform On West Side</i>					
			<i>Explanation : Timber Shielding</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROSE AVE SIRT SOUTH SHORE
Asset # : 15017

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Joints								
Generic	100%	4+	\$3,800	LIFE		**		
	<i>Missing/Damaged Seal, Extent : Light, Area Affected : 30%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : Light, Area Affected : 30%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Debris</i>							
Primary Member								
Steel	100%			LIFE		**	2-8	\$117,200
	<i>Corrosion, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations On Fascia Girders</i>							
	<i>Rust Stains, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations On Flanges</i>							
Secondary Member								
Steel	100%			LIFE		**	2-8	\$6,000
	<i>Corrosion, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Near Fascia Girders</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ROSS AVENUE SIRT SOUTH SHORE
Address : ROSS AVE AT NEW DORP PLAZA AND S. RAILROAD AVE
Borough : STATEN ISLAND Agency's Number : N/A
Program / Asset # : DOT0262.000 / 15016 Yr Built/Renovated :
Area Sq Ft : 3,700 Project Type : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2023 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2249410

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$83,900	
Total	\$83,900	
Importance Code A	\$83,900	
Total	\$83,900	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$58,500		\$10,400	\$7,300
Total	\$58,500		\$10,400	\$7,300
Importance Code A	\$16,700		\$100	
Importance Code B	\$6,600			
Importance Code C	\$35,100		\$10,300	\$7,300
Total	\$58,500		\$10,400	\$7,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROSS AVENUE SIRT SOUTH SHORE
Asset # : 15016

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	2-4	\$4,200	LIFE			**	
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
Mat (scour & erosion)								
Generic	100%	Now	\$2,400	LIFE			**	
			<i>Broken/Missing Elements, Extent : Severe, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout, Worst On Northwest Corner</i>					
			<i>Cracks, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Concrete Pavers On West Side. Limited Access</i>					
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : On East Side</i>					
			<i>Explanation : Railway Ballasts</i>					
Piles								
Not Accessible	100%							
Walls								
Concrete	15%	4+	\$15,100	LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations On East Side</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations On East Side</i>					
Concrete	85%			LIFE			**	
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROSS AVENUE SIRT SOUTH SHORE
Asset # : 15016

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railway Tracks</i>								
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$20,600
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Curbs								
Concrete w/ Steel Face	100%	4+	\$2,300	LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	4+	\$1,500	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Southeast Approach</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Southeast Approach</i>								
Piers								
Cap Beam								
Concrete	100%	Now	\$12,200	LIFE		**		
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : End Of Cap</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : End Of Cap</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Pier Components</i>								
Pier,Columns								
Concrete	100%			LIFE		**		
Stem,Solid Pier								
Concrete	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROSS AVENUE SIRT SOUTH SHORE
Asset # : 15016

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Railway Ballasts</i>						
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
		<i>Rust Stains, Extent : Light, Area Affected : 30%</i>						
		<i>Location : Random Locations Throughout</i>						
Railings/Parapets								
Steel	100%	Now	\$2,200	LIFE	**	2-8	\$3,100	
		<i>Corrosion, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Base Of Posts And Random Locations</i>						
		<i>Damaged Railing, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Southeast Corner And Random Locations</i>						
		<i>Loss of Section, Extent : Severe, Area Affected : 5%</i>						
		<i>Location : Southeast End Post</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Chain Link Fence Behind Steel Railing</i>						
Sidewalks								
Concrete	100%	Now	\$14,600	2040	**	5	\$1,100	
		<i>Cracks, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Severe, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout With Worst Cases Near Southeast Corner And Middle Of North Sidewalk</i>						
Wearing Surface								
Concrete	100%			2044	**	5	\$14,700	
		<i>Cracks, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout On Westbound Lane</i>						
Superstructure								
Deck,Structural								
Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access To Superstructure Components On 90 Percent Area</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROSS AVENUE SIRT SOUTH SHORE
Asset # : 15016

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Joints								
Generic	100%	4+	\$3,900	LIFE				**
	<i>Missing/Damaged Seal, Extent : Light, Area Affected : 40%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : Light, Area Affected : 30%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Debris</i>							
Primary Member								
Concrete Encased Steel	100%	Now	\$83,900	LIFE		**	5	\$12,600
	<i>Cracks, Extent : Severe, Area Affected : 5%</i>							
	<i>Location : Both Fascia Girders On East Half</i>							
	<i>Other Observation, Extent : Severe, Area Affected : 5%</i>							
	<i>Location : Both Fascia Girders</i>							
	<i>Explanation : Scaling</i>							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SACKETT STREET 278I (B.Q.E.)
Address : SACKETT ST OVER BKLN QNS EXPWY BET. HENRY ST & COLUMBIA ST
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0302.000 / 15060 **Yr Built/Renovated** : 1952 /
Area Sq Ft : 4,856 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230370

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$9,200		\$3,500	
Total	\$9,200		\$3,500	
Importance Code A	\$4,600		\$100	
Importance Code B	\$2,500			
Importance Code C	\$2,100		\$3,400	
Total	\$9,200		\$3,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SACKETT STREET 278I (B.Q.E.)
Asset # : 15060

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$2,500	LIFE		**		
			<i>Spalling, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : East And West Hearers</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	100%			2036		**	4	\$6,700
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : West Approach</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SHORE ROAD BRIDGE
Address : SHORE ROAD CIRCLE AMTRAK - CSX
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0213.000 / 14581 **Yr Built/Renovated** :
Area Sq Ft : 4,800 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 11-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241390

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,900		\$7,900	\$24,600
Total	\$2,900		\$7,900	\$24,600
Importance Code A	\$2,900		\$1,800	
Importance Code C			\$6,000	\$24,600
Total	\$2,900		\$7,900	\$24,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SHORE ROAD BRIDGE
Asset # : 14581

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Railroad Tracks</i>					
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$11,300
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SHORE ROAD BRIDGE
Asset # : 14581

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets								
Steel	100%			LIFE	**			
<hr/>								
Sidewalks								
Asphalt	100%			2036	**	4	\$800	
Concrete	100%			LIFE	**			
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Grass Strips</i>								
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2044	**	4	\$3,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At The Base Of The Railing</i>								
<i>Explanation : Concrete Base</i>								
<hr/>								
Steel	100%			LIFE	**	2-8	\$7,400	
<hr/>								
Sidewalks								
Concrete	100%			2040	**	5		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%			2044	**	5	\$49,200	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SIRT SOUTH SHORE BRIDGE PAGE AVE/SIRT SOUTH SHORE
Address : PAGE AVE,AMBOY-RICHMOND VALLEY
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0075.000 / 2499 **Yr Built/Renovated** : 1930 / 1989
Area Sq Ft : 44,400 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249269

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$976,100	\$976,100
Total	\$976,100	\$976,100
Importance Code A	\$439,500	\$439,500
Importance Code B	\$439,500	\$439,500
Importance Code C	\$97,200	\$97,200
Total	\$976,100	\$976,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$401,300		\$108,300	
Total	\$401,300		\$108,300	
Importance Code A	\$198,600		\$48,800	
Importance Code B	\$93,100		\$44,100	
Importance Code C	\$109,700		\$15,400	
Total	\$401,300		\$108,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SIRT SOUTH SHORE BRIDGE PAGE AVE/SIRT SOUTH SHORE

Asset # : 2499

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE			**	
Backwall								
Concrete	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2063			**	
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$11,300	LIFE			**	
			<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 80%</i>					
			<i>Location : Throughout On Both Abutments</i>					
			<i>Spalling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations On Edge Of Header Blocks On Both Abutments</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 5%</i>					
			<i>Location : North Abutment Near West End</i>					
			<i>Explanation : Steel Plate Repair</i>					
Mat (scour & erosion)								
Generic	100%	4+	\$1,800	LIFE			**	
			<i>Settlement, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Concrete Pavers</i>					
Pedestals								
Concrete	100%			LIFE			**	
			<i>Rust Stains, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Stem (breastwall)								
Concrete	100%			LIFE			**	
			<i>Rust Stains, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SIRT SOUTH SHORE BRIDGE PAGE AVE/SIRT SOUTH SHORE
Asset # : 2499

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Bank Protection								
Concrete	10%	2-4	\$34,900	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Most Severe Cases Near Ends</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Wall Ends And Random Locations</i>								
<i>Explanation : Moderate Erosion Behind Wall Ends On 5 Percent Area. Light Efflorescence On 10 Percent Area. Scaling</i>								
Concrete	90%			LIFE		**		
Mat (scour & erosion)								
Stream Bed	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout On South Side</i>								
<i>Explanation : Railway Tracks</i>								
Approaches								
Pavement								
Concrete	90%			2044		**	4	\$30,800
Concrete	10%	4+	\$13,100	2044		**	4	\$30,800
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Both Sides On South Approach</i>								
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$2,300	2044		**	4	\$1,100
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Southwest Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence And W Beam Attached To Concrete Parapet</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SIRT SOUTH SHORE BRIDGE PAGE AVE/SIRT SOUTH SHORE
Asset # : 2499

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Pier Components</i>								
Pier,Columns								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2063		**		
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$45,800	LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Along Steel Face</i>								
Railings/Parapets								
Concrete	100%			2044		**	4	\$8,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%	Now	\$3,900	LIFE		**	2-8	\$11,800
<i>Damaged Railing, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Near Southwest Corner</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Railing And Chain Link Fence On Top Of Concrete Parapet</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SIRT SOUTH SHORE BRIDGE PAGE AVE/SIRT SOUTH SHORE

Asset # : 2499

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	14%	4+	\$23,200	2040	**	5	\$11,100	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	86%			2040	**	5	\$22,200	
Wearing Surface								
Concrete	100%			2044	**	5	\$194,400	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Underside Of Deck And Superstructure Components On 70 Percent Area</i>								
Joints								
Generic	15%	4+	\$38,500	LIFE	**			
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Generic	85%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$1,406,900	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$1,207,000	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SOUTH CONDUIT BLVD. BELT SYSTEM - SOUTHERN PKWY
Address : SOUTH CONDUIT BLVD OVER THE BELT PARKWAY
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0280.000 / 15034 **Yr Built/Renovated** :
Area Sq Ft : 15,774 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 08-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231560

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$156,100	\$156,100
Total	\$156,100	\$156,100
Importance Code A	\$156,100	\$156,100
Total	\$156,100	\$156,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$86,700		\$35,700	\$43,900
Total	\$86,700		\$35,700	\$43,900
Importance Code A	\$75,700		\$20,900	
Importance Code B	\$11,100		\$900	
Importance Code C			\$13,900	\$43,900
Total	\$86,700		\$35,700	\$43,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
SOUTH CONDUIT BLVD. BELT SYSTEM - SOUTHERN PKWY
Asset # : 15034

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE			**	
Backwall								
Concrete	100%			LIFE			**	
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Concrete	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%			LIFE			**	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	10%			LIFE			**	
		<i>Efflorescence, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Southwest Wing Wall</i>						
Concrete	90%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Roadway Pavement</i>						
Pier Protection								
Concrete	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Concrete Barrier</i>						
Approaches								
Pavement								
Concrete	100%			2044		4	\$27,800	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Near Bridge Joints</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SOUTH CONDUIT BLVD. BELT SYSTEM - SOUTHERN PKWY

Asset # : 15034

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$2,500	
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Top Of Concrete Parapet</i>								
<i>Explanation : Chain Link Fence</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2044	**	4	\$7,200	
Steel	100%			LIFE	**	2-8	\$16,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Top Of Concrete Parapet</i>								
<i>Explanation : Chain Link Fence</i>								
Wearing Surface								
Concrete	100%			2044	**	5	\$87,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$34,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Bottom Of The Deck</i>								
<i>Explanation : Stay In Place Form</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$499,800	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$25,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SOUTH ST RAMP TO FDR/SOUTH ST
Address : SOUTH ST,ENTRY RAMP TO FDR DR
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0027.0C0 / 4325 **Yr Built/Renovated** : 1954 /
Area Sq Ft : 39,200 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 27-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 223201C

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,189,900	\$1,189,900
Total	\$1,189,900	\$1,189,900
Importance Code A	\$707,700	\$707,700
Importance Code B	\$482,200	\$482,200
Total	\$1,189,900	\$1,189,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$480,600		\$134,800	
Total	\$480,600		\$134,800	
Importance Code A	\$324,700		\$71,400	
Importance Code B	\$149,700		\$48,400	
Importance Code C	\$6,200		\$15,100	
Total	\$480,600		\$134,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SOUTH ST RAMP TO FDR/SOUTH ST
Asset # : 4325

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Under Construction; Enclosed Walls; Limited Access</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Under Construction	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Asphalt	100%			2036		**	4	\$30,200
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044		**	4	
Scupper								
Cast Iron	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : West Side</i>								
<i>Explanation : 1 Scupper</i>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SOUTH ST RAMP TO FDR/SOUTH ST
Asset # : 4325

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Cap Beam Steel	100%			LIFE	**	2-8	\$1,236,500	
Pier,Columns Steel	100%			LIFE	**	2-8	\$444,600	
Stem,Solid Pier Concrete	100%			LIFE	**			
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Pier 7</i>						
		<i>Explanation : Granite Facing</i>						
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Piles Not Accessible	100%							
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE	**			
		<i>Other Observation, Extent : Moderate, Area Affected : 40%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Rust</i>						
Railings/Parapets Steel	100%			LIFE	**	2-8	\$18,700	
Wearing Surface Asphalt	100%			2036	**	5	\$12,400	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Scupper Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout Deck</i>						
		<i>Explanation : 10 Scuppers</i>						
Superstructure								
Deck,Structural Concrete	100%			LIFE	**	5	\$20,800	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Stay In Place Forms Under Deck</i>						
Joints Generic	100%			LIFE	**			
Primary Member Steel	100%			LIFE	**	2-8	\$1,242,100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SOUTH ST RAMP TO FDR/SOUTH ST
Asset # : 4325

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Secondary Member								
Steel	100%			LIFE		* *	2-8	\$1,065,700

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SOUTH ST/FDR SB RAMP
 Address : SOUTH ST,ENTRY RAMP TO FDR DR
 Borough : MANHATTAN Agency's Number : N/A
 Program / Asset # : DOT0027.0D0 / 4326 Yr Built/Renovated : 1954 /
 Area Sq Ft : 187,500 Project Type : HIGHWAY BRIDGES
 Date of Survey : 27-Oct-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 223201D

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$181,100	\$181,100
Total	\$181,100	\$181,100
Importance Code A	\$144,500	\$144,500
Importance Code B	\$36,600	\$36,600
Total	\$181,100	\$181,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$123,700		\$18,500	
Total	\$123,700		\$18,500	
Importance Code A	\$89,600		\$14,500	
Importance Code B	\$34,100		\$4,000	
Total	\$123,700		\$18,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SOUTH ST/FDR SB RAMP
Asset # : 4326

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pier Protection								
Concrete	100%			LIFE	**			
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$375,200	
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$172,800	
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Not Accessible	100%							
Wearing Surface								
Not Accessible	100%							
Scupper								
Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 16 Scuppers</i>						
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$39,600	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Stay In Place Forms</i>						
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$152,100	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$7,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SOUTHERN BOULEVARD EAST FORDHAM ROAD
Address : SOUTHERN BLVD & E. FORDHAM ROAD
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0371.000 / 15389 Yr Built/Renovated :
Area Sq Ft : 12,900 Project Type : HIGHWAY BRIDGES
Date of Survey : 16-Mar-2022 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2242029

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$278,500
Total		\$278,500
Importance Code A		\$191,700
Importance Code C		\$86,800
Total		\$278,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$53,500		\$4,600	\$5,500
Total	\$53,500		\$4,600	\$5,500
Importance Code A	\$29,000		\$300	
Importance Code C	\$24,500		\$4,300	\$5,500
Total	\$53,500		\$4,600	\$5,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SOUTHERN BOULEVARD EAST FORDHAM ROAD

Asset # : 15389

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Stem (breastwall)								
Masonry: Granite	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE	**			
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE	**			
Piers								
Stem,Solid Pier								
Granite	100%			LIFE	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Median								
Concrete	100%	4+	\$20,500	LIFE	**	5	\$2,100	
			<i>Spalling, Extent : Moderate, Area Affected : 8%</i>					
			<i>Location : Near Curb line</i>					
Railings/Parapets								
Granite	100%			LIFE	**			
Steel	100%			LIFE	**	2-8	\$8,000	
Sidewalks								
Concrete	12%	4+	\$18,500	2038	**	5	\$4,300	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 3%</i>					
			<i>Location : Near Curb line</i>					
Concrete	88%			2038	**	5	\$8,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
SOUTHERN BOULEVARD EAST FORDHAM ROAD**

Asset # : 15389

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Asphalt	7%	4+	\$6,100	2034	\$6,100	5	\$5,500	
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Asphalt	93%			2034	\$80,800	5	\$11,100	
Superstructure								
Primary Member								
Concrete	2%	4+	\$8,400	LIFE	**	5	\$95,800	
	<i>Efflorescence, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 1%</i>							
	<i>Location : Southwest Side</i>							
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 30%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Water Leakage</i>							
Concrete	98%			LIFE	**	5	\$95,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SPRINGFIELD BOULEVARD BELT SYSTEM-SOUTHERN PKWY
Address : SPRINGFIELD BLVD OVER BSOP BTW N & S CONDUITS
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0396.000 / 15416 **Yr Built/Renovated** :
Area Sq Ft : 8,091 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231630

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$247,000	\$634,200
Total	\$247,000	\$634,200
Importance Code A	\$189,200	\$83,200
Importance Code C	\$57,800	\$550,900
Total	\$247,000	\$634,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$118,100	\$1,800	\$300	
Total	\$118,100	\$1,800	\$300	
Importance Code A	\$82,000	\$1,800	\$300	
Importance Code C	\$36,100			
Total	\$118,100	\$1,800	\$300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SPRINGFIELD BOULEVARD BELT SYSTEM-SOUTHERN PKWY
Asset # : 15416

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Vertical Cracks On Random Locations</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Masonry: Granite	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Asphalt Paving Underneath</i>					
Pier Protection								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 60%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Approaches								
Pavement								
Asphalt	100%	2-4	\$20,300	2034	\$406,100	4	\$5,300	
			<i>Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Near Median On Southbound Lane</i>					
			<i>Explanation : Uneven Surface</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SPRINGFIELD BOULEVARD BELT SYSTEM-SOUTHERN PKWY
Asset # : 15416

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete	100%	4+	\$2,400	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%	Now	\$5,800	LIFE		**	5	\$1,000
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Cast Iron	100%	2-4	\$26,600	LIFE		**		
<i>Corrosion, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Cast Iron Railing On Top Of Masonry Parapet</i>								
Masonry	100%			2042		**		
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence On Top Of Masonry Parapet</i>								
Sidewalks								
Concrete	100%	Now	\$1,300	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : At East And West Ends</i>								
<i>Explanation : Limited Access On 70 Percent Area. Masonry Granite Fascia At Both Ends.</i>								
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SPRINGFIELD BOULEVARD BELT SYSTEM-SOUTHERN PKWY
Asset # : 15416

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	11%	0-2	\$600	2053			**	
		<i>Cracks, Extent : Moderate, Area Affected : 20%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
Concrete	89%			2053			**	
Railings/Parapets								
Cast Iron	100%	0-2	\$46,600	LIFE			**	
		<i>Corrosion, Extent : Moderate, Area Affected : 15%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Loss of Section, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Random Locations Near Base Of Railing Posts</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Cast Iron Railing On Top Of Masonry Parapet</i>						
Masonry	100%			2042			**	5 \$3,700
		<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Joint Mortar Missing/ Eroded</i>						
Steel	100%			LIFE			**	2-8 \$7,900
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Chain Link Fence On Top Of Masonry Parapet</i>						
Sidewalks								
Concrete	100%	Now	\$57,800	2038			**	5 \$2,000
		<i>Cracks, Extent : Moderate, Area Affected : 20%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
Wearing Surface								
Asphalt	100%	0-2	\$14,500	2034	\$144,800	5		\$3,900
		<i>Cracks, Extent : Moderate, Area Affected : 15%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Uneven Surface</i>						
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SPRINGFIELD BOULEVARD BELT SYSTEM-SOUTHERN PKWY

Asset # : 15416

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Concrete	30%	4+	\$189,200	LIFE	**	5	\$41,600	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Limited Access On 60 Percent Of Area. Covered With Wire Mesh.</i>					
Concrete	70%			LIFE	**	5	\$41,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : STILLWELL AVE. BRIDGE
Address : CONEY ISLAND CREEK
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0164.000 / 13572 **Yr Built/Renovated** :
Area Sq Ft : 17,000 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240540

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$263,100	
Total	\$263,100	
Importance Code C	\$263,100	
Total	\$263,100	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$11,900	\$35,900	\$5,500	
Total	\$11,900	\$35,900	\$5,500	
Importance Code A	\$11,900		\$400	
Importance Code C		\$35,900	\$5,100	
Total	\$11,900	\$35,900	\$5,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
STILLWELL AVE. BRIDGE
Asset # : 13572

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 95%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE		**		
Mat (scour & erosion)								
Stream Bed	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%	4+	\$182,900	2042		**	4	\$39,400
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : South Approach Replaced</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Approach</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
STILLWELL AVE. BRIDGE
Asset # : 13572

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	4+	\$11,900	LIFE				**
<i>Corrosion, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Southwest Corner</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE				**
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides</i>								
<i>Explanation : Chain Link Fence Attached To Steel Railing</i>								
Sidewalks								
Concrete	100%	2-4	\$80,200	LIFE				**
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Southwest Corner</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : Northeast Corner And Southeast Corner</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE				**
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2061				**
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
STILLWELL AVE. BRIDGE
Asset # : 13572

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stream Bed</i>								
<hr/>								
Pedestals								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$10,900
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout Chain Link Fence Posts</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On Both Sides</i>								
<i>Explanation : Chain Link Fence Attached To Steel Railings</i>								
<hr/>								
Sidewalks								
Concrete	100%			2038		**	5	\$10,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%			2042		**	5	\$71,700
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Total 4 Of Scuppers</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SUNRISE HIGHWAY WESTBOUND OVER BELT PARKWAY EASTBOUND
Address : SUNRISE HIGHWAY OVER BELT PKWY LAURELTON PKWY EASTBOUND
Borough : QUEENS Agency's Number : N/A
Program / Asset # : DOT0356.000 / 15370 Yr Built/Renovated :
Area Sq Ft : 3,922 Project Type : HIGHWAY BRIDGES
Date of Survey : 13-Jul-2021 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2231650

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$158,400	\$38,800
Total	\$158,400	\$38,800
Importance Code A	\$75,200	\$38,800
Importance Code B	\$83,200	
Total	\$158,400	\$38,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$24,200		\$3,900	\$2,900
Total	\$24,200		\$3,900	\$2,900
Importance Code A			\$3,900	\$2,900
Importance Code C	\$24,200			
Total	\$24,200		\$3,900	\$2,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE HIGHWAY WESTBOUND OVER BELT PARKWAY EASTBOUND
Asset # : 15370

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Concrete	100%	0-2	\$14,400	LIFE				**
			<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>					
			<i>Location : West Abutment</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : West Abutment</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : On East Abutment</i>					
			<i>Explanation : Backwall Is Not Accessible</i>					
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE				**
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Only At West Abutment</i>					
			<i>Explanation : Deck Joint Observed</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%	Now	\$83,200	LIFE				**
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : West Abutment</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : West Abutment</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : On East Abutment</i>					
			<i>Explanation : Stem Not Accessible</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE				**
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE HIGHWAY WESTBOUND OVER BELT PARKWAY EASTBOUND
Asset # : 15370

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Masonry	100%			LIFE		**		
			<i>Efflorescence, Extent : Light, Area Affected : 2%</i>					
			<i>Location : At Random Locations</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Southeast Wing Wall</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%			2041		**	4	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041		**	4	\$2,500
Deck Elements								
Railings/Parapets								
Concrete	100%			2041		**	4	\$3,300
Wearing Surface								
Concrete	70%	4+	\$9,800	2041		**	5	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Near Northeast Corner</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Near Northeast Corner</i>					
Concrete	30%			2041		**	5	
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$75,200	LIFE		**	5	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE HIGHWAY WESTBOUND OVER BELT PARKWAY EASTBOUND
Asset # : 15370

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$72,500	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Bottom Flange Of South Girder</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : North Girder Is Not Accessible</i>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : SUNRISE HIGHWAY WESTBOUND OVER BELT PARKWAY WESTBOUND
Address : SUNRISE HIGHWAY WEST BOUND LAURELTON PKWY WESTBOUND
Borough : QUEENS Agency's Number : N/A
Program / Asset # : DOT0357.000 / 15371 Yr Built/Renovated :
Area Sq Ft : 5,341 Project Type : HIGHWAY BRIDGES
Date of Survey : 13-Jul-2021 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2231660

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$52,900
Total		\$52,900
Importance Code A		\$52,900
Total		\$52,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure			\$5,300	\$3,000
Total			\$5,300	\$3,000
Importance Code A			\$5,300	\$3,000
Total			\$5,300	\$3,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE HIGHWAY WESTBOUND OVER BELT PARKWAY WESTBOUND
Asset # : 15371

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : On East Side Only</i>					
			<i>Explanation : Deck Joint Observed</i>					
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : West Abutment. East Abutment Is Not Accessible.</i>					
			<i>Other Observation, Extent : Light, Area Affected : 5%</i>					
			<i>Location : West Abutment</i>					
			<i>Explanation : Scaling. East Abutment Is Not Accessible.</i>					
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
Piles Not Accessible	100%							
Walls Masonry	100%			LIFE			**	
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Joint Mortar Missing/ Eroded</i>					
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE HIGHWAY WESTBOUND OVER BELT PARKWAY WESTBOUND
Asset # : 15371

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Cracks</i>						
Approaches								
Pavement								
Concrete	100%			2041		**	4	
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041		**	4	\$1,100
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
Pier,Columns								
Concrete	100%			LIFE		**		
Stem,Solid Pier								
Masonry	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : South End Only</i>						
		<i>Explanation : Masonry Solid Stem Pier Is Located At South End Of Pier</i>						
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2041		**	4	\$4,900
Wearing Surface								
Concrete	100%			2041		**	5	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
SUNRISE HIGHWAY WESTBOUND OVER BELT PARKWAY WESTBOUND

Asset # : 15371

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE	**	2-8	\$98,700	
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : On North Side</i>						
		<i>Explanation : Steel Girder Is Not Accessible</i>						
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TIFFANY STREET BRIDGE TIFFANY ST./AMTRAK
Address : TIFFANY STREET
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0182.000 / 13716 **Yr Built/Renovated** : 1908 /
Area Sq Ft : 7,267 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 09-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241170

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$47,100	\$1,700	\$100	
Total	\$47,100	\$1,700	\$100	
Importance Code A			\$100	
Importance Code B	\$3,800			
Importance Code C	\$43,400	\$1,700		
Total	\$47,100	\$1,700	\$100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
TIFFANY STREET BRIDGE TIFFANY ST./AMTRAK
Asset # : 13716

Bridge Structure	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Underside Of Bridge Throughout</i>							
	<i>Explanation : Not Accessible For Inspection. Requires Railroad Flagman.</i>							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$3,800	LIFE			**	
	<i>Loose Elements, Extent : Light, Area Affected : 15%</i>							
	<i>Location : Both Abutments</i>							
	<i>Misaligned/Bulging, Extent : Light, Area Affected : 50%</i>							
	<i>Location : Random Locations Throughout</i>							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE			**	
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Stem Breastwall 50 Percent Concrete And 50 Percent Not Accessible</i>							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Walls Consist Of 50 Percent Concrete And 50 Percent Not Accessible</i>							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TIFFANY STREET BRIDGE TIFFANY ST./AMTRAK
Asset # : 13716

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%	4+	\$19,900	2041	**	4	\$18,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041	**	4		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Both Approaches</i>								
<i>Explanation : Consists Of 50 Percent Concrete And 50 Percent Metal Fence</i>								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	95%			LIFE	**			
Concrete	5%	4+	\$2,900	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Concrete	100%			2041	**	4		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Both Sides</i>								
<i>Explanation : Consists Of 50 Percent Concrete And 50 Percent Corrugated Steel Sheeting</i>								
Steel	100%			LIFE	**	2-8	\$3,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TIFFANY STREET BRIDGE TIFFANY ST./AMTRAK

Asset # : 13716

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2037	**	5	\$3,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2041	**	5	\$41,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TO BROOKLYN FROM FDR DR FRANKFORT AND PEARL STREET
Address : BROOKLYN BRIDGE ACCESS FROM FDR OVER FRANKFORT AND PEARL STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0282.000 / 15040 **Yr Built/Renovated** :
Area Sq Ft : 63,280 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 05-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224001B

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,233,500	\$1,705,100
Total	\$1,233,500	\$1,705,100
Importance Code A	\$1,121,300	\$1,517,700
Importance Code B	\$112,200	\$187,400
Total	\$1,233,500	\$1,705,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$654,100		\$164,300	
Total	\$654,100		\$164,300	
Importance Code A	\$471,100		\$145,500	
Importance Code B	\$145,000		\$18,800	
Importance Code C	\$38,000			
Total	\$654,100		\$164,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
TO BROOKLYN FROM FDR DR FRANKFORT AND PEARL STREET
Asset # : 15040

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Middle Piers</i>								
<i>Explanation : Limited Access Due To Ongoing Construction</i>								
Pier Protection								
Concrete	100%	Now	\$4,500	LIFE	**			
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 3%</i>								
<i>Location : On Piers Exposed To Traffic</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : On Piers Exposed To Traffic</i>								
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Middle Piers</i>								
<i>Explanation : Limited Access Due To Ongoing Construction</i>								
Piers								
Cap Beam								
Steel	98%			LIFE	**	2-8	\$1,533,200	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Middle Piers</i>								
<i>Explanation : Limited Access To Pier Components</i>								
Steel	2%	4+	\$15,500	LIFE	**	2-8	\$916,500	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$529,600	
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Loss Of Section Arrested By Paint</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Steel	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TO BROOKLYN FROM FDR DR FRANKFORT AND PEARL STREET
Asset # : 15040

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Deck Components</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$143,300
Wearing Surface								
Asphalt	100%			2036		**	5	\$76,100
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 30 Scuppers</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE		**	5	\$139,300
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Along Joints</i>								
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Bottom Of The Deck</i>								
<i>Explanation : Limited Access To Underside Of Deck And Superstructure On 30 Percent Area. Stay In Place Forms</i>								
Joints								
Generic	100%			LIFE		**		
Primary Member								
Steel	100%			LIFE		**	2-8	\$2,005,100
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	99%			LIFE		**	2-8	\$103,200
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	1%	4+	\$1,800	LIFE		**	2-8	\$58,800
<i>Loss of Section, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TO EAST 62ND STREET FROM QUEENS EAST 60TH ST - EAST 61ST ST
Address : QUEENS BORO BRIDGE OFF RAMP TO EST 62ND STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0343.000 / 15202 **Yr Built/Renovated** : 1952 /
Area Sq Ft : 17,595 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224004C

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$368,800
Total		\$368,800
Importance Code A		\$368,800
Total		\$368,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure			\$39,200	
Total			\$39,200	
Importance Code A			\$37,000	
Importance Code B			\$2,200	
Total			\$39,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
TO EAST 62ND STREET FROM QUEENS EAST 60TH ST - EAST 61ST ST
Asset # : 15202

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paint Peeling. Walls That Enclose Span 10.</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Peeling Paint</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : At The Base Of Piers</i>								
<i>Explanation : Rust Stains</i>								
Approaches								
Pavement								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041			**	4

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TO EAST 62ND STREET FROM QUEENS EAST 60TH ST - EAST 61ST ST
Asset # : 15202

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 2 Scuppers Observed</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	
Pier,Columns								
Steel	100%			LIFE		**	2-8	
Stem,Solid Pier								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Not Accessible Due To Fence</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Steel	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2041		**	4	
Wearing Surface								
Not Accessible	100%							
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 6 Scuppers Observed</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stay In Place Forms In Place With Light Corrosion In 2 Percent Of The Surface In Random Locations</i>								
Joints								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TO EAST 62ND STREET FROM QUEENS EAST 60TH ST - EAST 61ST ST
Asset # : 15202

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$688,800	
		<i>Corrosion, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Secondary Member								
Steel	100%			LIFE	**	2-8	\$34,600	
		<i>Corrosion, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TO FDR DR. NORTH BOUND PEARL STREET
Address : FDR NB ACCESS FROM BKLYN BRIDGE OVER PEARL STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0283.000 / 15041 **Yr Built/Renovated** :
Area Sq Ft : 58,253 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 05-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224001D

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,423,500	\$2,705,400
Total	\$1,423,500	\$2,705,400
Importance Code A	\$1,166,200	\$1,166,200
Importance Code B	\$157,600	\$157,600
Importance Code C	\$99,600	\$1,381,500
Total	\$1,423,500	\$2,705,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$706,600		\$161,000	
Total	\$706,600		\$161,000	
Importance Code A	\$533,400		\$141,700	
Importance Code B	\$173,200		\$19,300	
Total	\$706,600		\$161,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
TO FDR DR. NORTH BOUND PEARL STREET
Asset # : 15041**

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Limited Access To 40 Percent Area. Rust Stains</i>								
Piers								
Cap Beam Steel	100%			LIFE		**	2-8	\$2,032,800
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Pier Components</i>								
Pier,Columns Steel	100%			LIFE		**	2-8	\$743,700
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Steel	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piles Not Accessible	100%							
Deck Elements								
Railings/Parapets Concrete	100%			2044		**	4	\$56,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$126,900
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
TO FDR DR. NORTH BOUND PEARL STREET**

Asset # : 15041

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Wearing Surface Concrete	100%	4+	\$99,600	2044	**	5	\$1,381,500	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Patches And Random Locations</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Asphalt Patches</i>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 19 Scuppers</i>								
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$128,200	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Underside Of The Deck</i>								
<i>Explanation : Limited Access To Underside Of Deck And Superstructure On 40 Percent Area. Stay In Place Forms</i>								
Joints								
Generic	100%			LIFE	**			
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Header Block Edges</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Debris</i>								
Primary Member Steel	100%			LIFE	**	2-8	\$1,845,800	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Near Deck Joints And Random Locations</i>								
Secondary Member Steel	100%			LIFE	**	2-8	\$95,000	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TO NEW YORK FROM 21ST STREET 21ST STREET
Address : FROM 21ST ST. OVER 21ST ST. LONG ISLAND CITY
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0331.000 / 15190 **Yr Built/Renovated** : 1957 /
Area Sq Ft : 65,293 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224004F

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$389,500	\$2,737,800
Total	\$389,500	\$2,737,800
Importance Code A		\$2,306,300
Importance Code B	\$389,500	\$431,600
Total	\$389,500	\$2,737,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$48,500		\$274,600	\$36,100
Total	\$48,500		\$274,600	\$36,100
Importance Code A	\$32,700		\$231,300	\$34,200
Importance Code B	\$15,800		\$43,300	
Importance Code C				\$1,900
Total	\$48,500		\$274,600	\$36,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
TO NEW YORK FROM 21ST STREET 21ST STREET**

Asset # : 15190

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Concrete	2%	4+	\$32,700	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Cracking/Crumbling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 2%</i>								
<i>Location : Northwest Side</i>								
<i>Explanation : Steel Mesh Coverings. Walls Are 30 Percent Concrete, 70 Percent Not Accessible</i>								
Concrete	98%			LIFE			**	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Concrete	100%			LIFE			**	
Approaches								
Pavement								
Concrete	100%			2041	**	4	\$3,800	
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
TO NEW YORK FROM 21ST STREET 21ST STREET**

Asset # : 15190

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Railings/Parapets Concrete	100%			2041	**	4	\$800	
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railings Consist Of 20 Percent Concrete, 80 Percent Not Accessible</i>								
<hr/>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 1 Scupper Observed</i>								
<hr/>								
Piers								
Cap Beam Steel	100%			LIFE	**	2-8	\$1,649,700	
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Cap Beam Consists Of 60 Percent Steel, 40 Percent Not Accessible</i>								
<hr/>								
Pier, Columns								
Concrete Encased Steel	100%	4+	\$389,500	LIFE	**	5	\$1,100	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Corrosion. Pier, Columns Consist Of 4 Percent Concrete Encased Steel, 56 Percent Steel, 40 Percent Not Accessible</i>								
Steel	100%			LIFE	**	2-8	\$967,500	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Stem, Solid Pier								
Concrete	100%	4+	\$15,800	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 2%</i>								
<i>Location : West Side</i>								
<i>Explanation : Steel Mesh Coverings</i>								
<hr/>								
Brngs, Ancr Blts, Pads								
Elastomeric	100%			2052	**			
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Consists Of 60 Percent Generic And 40 Percent Not Accessible.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
TO NEW YORK FROM 21ST STREET 21ST STREET**

Asset # : 15190

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Pedestals Not Present In Concrete Encased Steel Piers</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2041		**	4	\$67,600
<i>Other Observation, Extent : N/A, Area Affected : 90%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railings/ Parapets Consist Of 10 Percent Concrete, 90 Percent Not Accessible</i>								
Wearing Surface								
Not Accessible	100%							
Scupper								
Not Accessible	100%							
Superstructure								
Deck, Structural								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Bottom Covered With Stay In Place Forms With Light Efflorescence In 2 Percent Of Area</i>								
Joints								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE		**	2-8	\$2,974,900
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Primary Member Consists Of 60 Percent Steel, 40 Percent Not Accessible</i>								
Secondary Member								
Steel	100%			LIFE		**	2-8	\$149,500
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Secondary Member Consists Of 60 Percent Steel, 40 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TO PARK ROW ROSE STREET
Address : FROM BROOKLYN BRIDGE TO PARK ROW OVER ROSE STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0287.000 / 15045 **Yr Built/Renovated** :
Area Sq Ft : 16,370 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 05-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224001G

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$236,900	\$236,900
Total	\$236,900	\$236,900
Importance Code A	\$236,900	\$236,900
Total	\$236,900	\$236,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$169,700		\$39,400	\$39,200
Total	\$169,700		\$39,400	\$39,200
Importance Code A	\$113,700		\$33,800	
Importance Code B	\$53,500		\$3,300	
Importance Code C	\$2,500		\$2,300	\$39,200
Total	\$169,700		\$39,400	\$39,200



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
TO PARK ROW ROSE STREET
Asset # : 15045

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : On West End</i>								
<i>Explanation : Bridge Abuts To Another Bridge On East End. Limited Access To Abutment Components Due To Ongoing Construction.</i>								
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Elastomeric	100%			2055		**		
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : On Header Edges At West End</i>								
Mat (scour & erosion) Brick	100%			LIFE		**	4	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Brick Pavers</i>								
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%			LIFE		**		
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Brick	100%			2048		**	4	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Brick Pavers</i>								
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : Near Abutment At West End</i>								
<i>Explanation : Limited Access To Underside Of Deck Due To Ongoing Construction On 60 Percent Area. Brick Pavers</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TO PARK ROW ROSE STREET
Asset # : 15045

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access Due To Ongoing Construction</i>								
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$4,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Both Ends</i>								
<i>Explanation : Bridge Is Closed To Traffic</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$289,400	
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Pier Components Due To Ongoing Construction</i>								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$107,900	
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Steel	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TO PARK ROW ROSE STREET
Asset # : 15045

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets Concrete	100%			2044	**	4	\$19,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Wearing Surface Concrete	100%			2044	**	5	\$78,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Scaling</i>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 9 Scuppers</i>								
Superstructure								
Deck,Structural Concrete	100%			LIFE	**	5	\$36,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Underside Of The Deck</i> <i>Explanation : Limited Access To Underside Of Deck On 60 Percent Area. Stay In Place Forms</i>								
Joints								
Generic	100%	4+	\$2,500	LIFE	**			
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations On Header Block Edges</i> <i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Debris</i>								
Primary Member Steel	100%			LIFE	**	2-8	\$518,700	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								
Secondary Member Steel	100%			LIFE	**	2-8	\$26,700	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TO PEARL STREET LAND ADJACENT TO BRIDGE
Address : FROM BKLYN BRDG TO PEARL ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0340.000 / 15199 **Yr Built/Renovated** :
Area Sq Ft : 5,362 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 17-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224001E

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$172,200
Total		\$172,200
Importance Code A		\$172,200
Total		\$172,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$4,000		\$21,100	\$6,200
Total	\$4,000		\$21,100	\$6,200
Importance Code A			\$19,600	\$3,700
Importance Code B			\$1,500	
Importance Code C	\$4,000			\$2,400
Total	\$4,000		\$21,100	\$6,200



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.*

**DEPARTMENT OF TRANSPORTATION - 841
TO PEARL STREET LAND ADJACENT TO BRIDGE**

Asset # : 15199

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Construction Taking Place Underneath Bridge</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE			**	
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE			**	
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Wingwalls Are Concrete With Stone Facing</i>								
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE			**	
Approaches								
Pavement Concrete	100%			2041		**	4	\$4,900
Mat (scour & erosion) Not Accessible	100%							
Pavement Base Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
TO PEARL STREET LAND ADJACENT TO BRIDGE**

Asset # : 15199

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Concrete	100%			2041	**	4	\$1,100	
		<i>Efflorescence, Extent : Light, Area Affected : 20%</i>						
		<i>Location : Random Locations Throughout</i>						
Steel	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : On Top Of Concrete Railing</i>						
		<i>Explanation : Steel Chain-link Fence</i>						
Piers								
Cap Beam Steel	100%			LIFE	**	2-8	\$53,600	
		<i>Corrosion, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Pier,Columns Steel	100%			LIFE	**	2-8	\$13,500	
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Railings/Parapets Concrete	100%			2041	**	4	\$6,400	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Near Pier 1</i>						
Steel	100%			LIFE	**	2-8	\$200	
		<i>Other Observation, Extent : N/A, Area Affected : 5%</i>						
		<i>Location : North East Side</i>						
		<i>Explanation : Chain-link Fence Behind Concrete Barrier</i>						
Wearing Surface Concrete	100%	4+	\$4,000	2041	**	5	\$13,200	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Scupper Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : 2 Scuppers Observed</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
TO PEARL STREET LAND ADJACENT TO BRIDGE**

Asset # : 15199

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural								
Grating w/ Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Entire Deck</i>						
		<i>Explanation : Bottom Covered With Stay In Place Forms</i>						
Joints								
Generic	100%			LIFE		**		
		<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 20%</i>						
		<i>Location : Pier 1</i>						
		<i>Other Observation, Extent : Light, Area Affected : 20%</i>						
		<i>Location : Pier 1</i>						
		<i>Explanation : Debris Build Up</i>						
Primary Member								
Steel	100%			LIFE		**	2-8	\$321,700
Secondary Member								
Steel	100%			LIFE		**	2-8	\$16,200

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TO QUEENSBORO BRDG FROM E58 ST EAST 59TH STREET
Address : E58TH STREET RAMP TO QUEENSBORO BETWEEN 1ST AND 2ND AVENUES
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0238.000 / 14978 **Yr Built/Renovated** : 1929 /
Area Sq Ft : 15,495 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 14-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224004D

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$555,100	\$867,600
Total	\$555,100	\$867,600
Importance Code A	\$230,600	\$62,400
Importance Code B		\$156,300
Importance Code C	\$324,500	\$648,900
Total	\$555,100	\$867,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$57,200	\$6,000	\$22,900	
Total	\$57,200	\$6,000	\$22,900	
Importance Code A	\$5,000	\$6,000	\$6,300	
Importance Code B			\$16,600	
Importance Code C	\$52,100			
Total	\$57,200	\$6,000	\$22,900	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
TO QUEENSBORO BRDG FROM E58 ST EAST 59TH STREET
Asset # : 14978

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : At East End</i>								
<i>Explanation : No Access To West Abutment. Bridge Abuts Queensboro Bridge</i>								
<hr/>								
Backwall Not Accessible	100%							
<hr/>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
<hr/>								
Footings Not Accessible	100%							
<hr/>								
Joint with Deck Generic	100%			LIFE		**		
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Pedestals Not Accessible	100%							
<hr/>								
Stem (breastwall) Not Accessible	100%							
<hr/>								
Feature Crossed								
Mat (scour & erosion) Asphalt Paving	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At 59th Street</i>								
<i>Explanation : Roadway/ Path</i>								
<hr/>								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Ramp To Outer Roadway</i>								
<i>Explanation : Roadway/ Path</i>								
<hr/>								
Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Spans South Of 59th Street And Spans Between Ramp And 59th Street</i>								
<i>Explanation : No Access To Underside Of Structure</i>								
<hr/>								
Pier Protection Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Pedestal</i>								
<hr/>								
Approaches								
Pavement Concrete	100%	4+	\$29,100	2043		**	4	\$9,000
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On West Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On West Approach</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TO QUEENSBORO BRDG FROM E58 ST EAST 59TH STREET

Asset # : 14978

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations On West Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%	4+	\$2,300	LIFE		**	5	\$500
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On West Side</i>								
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On West Side</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At West Approach</i>								
<i>Explanation : 2 Scuppers</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$144,200
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$450,000
Stem,Solid Pier								
Masonry	100%			LIFE		**		
<i>Joint Mortar Miss/Erod, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Spans North And South Of 59th Street</i>								
<i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Roadway</i>								
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TO QUEENSBORO BRDG FROM E58 ST EAST 59TH STREET
Asset # : 14978

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Concrete	10%	4+	\$2,800	2043	**	4	\$12,000	
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Concrete Barrier</i>							
Concrete	90%			2043	**	4	\$18,100	
Wearing Surface								
Concrete	5%	4+	\$23,100	2043	**	5	\$324,500	
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>							
Concrete	95%			2043	**	5	\$648,900	
Scupper								
Cast Iron	100%			LIFE	**			
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 4 Scuppers</i>							
Superstructure								
Deck, Structural								
Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : Covered With Stay-in-place Forms And Timber Shielding</i>							
Joints								
Not Accessible	100%							
Primary Member								
Concrete	100%	4+	\$230,600	LIFE	**	5	\$27,800	
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations At 59th Street Span</i> <i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations At 59th Street Span</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations At 59th Street Span</i> <i>Other Observation, Extent : N/A, Area Affected : 70%</i> <i>Location : Spans North And South Of 59th Street</i> <i>Explanation : Limited Access</i>							
Steel	100%			LIFE	**	2-8		
Secondary Member								
Steel	100%			LIFE	**	2-8	\$14,400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TOMPKINS AVENUE GREENFIELD AVENUE
Address : TOMPKINS AVE OVER GREENFIELD AVE BTW KIMBERLY LN & WILLOW AVE
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0398.000 / 15418 **Yr Built/Renovated** :
Area Sq Ft : 2,475 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249840

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$41,000		\$500	
Total	\$41,000		\$500	
Importance Code A	\$1,500		\$100	
Importance Code C	\$39,600		\$500	
Total	\$41,000		\$500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
TOMPKINS AVENUE GREENFIELD AVENUE
Asset # : 15418

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE	**			
Backwall								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2053	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Concrete	20%	4+	\$10,100	LIFE	**			
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	80%			LIFE	**			
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Pavement</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$20,300	2042	**	4	\$13,800	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TOMPKINS AVENUE GREENFIELD AVENUE
Asset # : 15418

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4	\$2,300	
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
Railings/Parapets								
Concrete	100%			2042	**	4	\$2,100	
			<i>Other Observation, Extent : N/A, Area Affected : 25%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Vegetation Growth</i>					
Steel	100%			LIFE	**	2-8	\$1,900	
Sidewalks								
Concrete	100%			2038	**	5	\$900	
Wearing Surface								
Concrete	100%	4+	\$9,200	2042	**	5	\$5,600	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$2,700	
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TOMPKINS AVENUE WILLOW AVENUE & SIRT
Address : TOMPKINS AVE OVER WILLOW AVE & STATEN ISLAND RAPID TRANSIT
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0399.000 / 15419 **Yr Built/Renovated** :
Area Sq Ft : 5,372 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249510

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$230,300	
Total	\$230,300	
Importance Code B	\$124,100	
Importance Code C	\$106,200	
Total	\$230,300	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$64,700		\$1,200	
Total	\$64,700		\$1,200	
Importance Code A	\$6,600		\$200	
Importance Code B	\$18,900			
Importance Code C	\$39,200		\$1,000	
Total	\$64,700		\$1,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TOMPKINS AVENUE WILLOW AVENUE & SIRT
Asset # : 15419

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$4,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$1,200	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete	50%	4+	\$124,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	50%			LIFE		**		
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	90%	4+	\$106,200	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	10%			LIFE		**		
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
TOMPKINS AVENUE WILLOW AVENUE & SIRT**

Asset # : 15419

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railroad Tracks And Asphalt Pavement</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$31,100	2042		**	4	\$18,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042		**	4	\$3,200
Steel	100%			LIFE		**		
Sidewalks								
Concrete	100%			LIFE		**		
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Pier, Columns								
Concrete	100%	4+	\$17,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 3%</i>								
<i>Location : The Second Column Observed From The West Side</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : East Column</i>								
<i>Explanation : Map Cracking</i>								
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
TOMPKINS AVENUE WILLOW AVENUE & SIRT**

Asset # : 15419

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Railings/Parapets								
Concrete	100%			2042	**	4	\$4,800	
Steel	100%			LIFE	**	2-8	\$4,400	
Sidewalks								
Concrete	100%			2038	**	5	\$2,100	
Wearing Surface								
Concrete	100%	4+	\$8,100	2042	**	5	\$10,800	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$5,900	
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Water Leakage</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TRANSIT AUTHORITY YARD BRIDGE BEDFORD PARK BLVD/NYCTA IND YARD
Address : BEDFORD PK BLVD,JEROME-PAUL AV
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0059.000 / 2484 **Yr Built/Renovated** : 1936 / 2000
Area Sq Ft : 46,300 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 14-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241930

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$81,100	\$81,100
Total	\$81,100	\$81,100
Importance Code C	\$81,100	\$81,100
Total	\$81,100	\$81,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$14,300		\$23,300	
Total	\$14,300		\$23,300	
Importance Code A	\$12,400		\$7,900	
Importance Code B	\$1,900			
Importance Code C			\$15,400	
Total	\$14,300		\$23,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
TRANSIT AUTHORITY YARD BRIDGE BEDFORD PARK BLVD/NYCTA IND YARD
Asset # : 2484

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$1,900	LIFE			**	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Both Sides</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$30,800
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : At Joint Of West Abutment</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TRANSIT AUTHORITY YARD BRIDGE BEDFORD PARK BLVD/NYCTA IND YARD
Asset # : 2484

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4		
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Sidewalks								
Concrete	100%			LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : North Approach</i>					
Piers								
Cap Beam								
Not Accessible	100%							
Pier, Columns								
Not Accessible	100%							
Stem, Solid Pier								
Not Accessible	100%							
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Corrosion, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Concrete	100%			2044	**	4	\$14,300	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : North Side</i>					
Steel	100%			LIFE	**	2-8	\$32,000	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Chain Link Fence</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TRANSIT AUTHORITY YARD BRIDGE BEDFORD PARK BLVD/NYCTA IND YARD
Asset # : 2484

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2040	**	5	\$34,300	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Map Cracking On North Sidewalk, Random Cracks Throughout Both Sides</i>								
Wearing Surface								
Concrete	100%			2044	**	5	\$162,200	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : TRANSIT AUTHORITY YARD BRIDGE W 205 ST/NYCTA IND YARDS
Address : W205TH ST, JEROME-PAUL AVES
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0060.000 / 2485 **Yr Built/Renovated** : 1935 /
Area Sq Ft : 37,800 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 16-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2241940

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$3,466,600	\$229,400
Total	\$3,466,600	\$229,400
Importance Code C	\$3,466,600	\$229,400
Total	\$3,466,600	\$229,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$190,900	\$4,000	\$600	\$30,800
Total	\$190,900	\$4,000	\$600	\$30,800
Importance Code A	\$38,100		\$600	
Importance Code B	\$4,800			
Importance Code C	\$148,000	\$4,000		\$30,800
Total	\$190,900	\$4,000	\$600	\$30,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TRANSIT AUTHORITY YARD BRIDGE W 205 ST/NYCTA IND YARDS
Asset # : 2485

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Generic	100%	4+	\$4,800	LIFE			**
			<i>Cracks, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Random Locations Throughout</i>				
			<i>Spalling, Extent : Moderate, Area Affected : 30%</i>				
			<i>Location : Along West Joint Header</i>				
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Earth	100%			LIFE			**
Piles							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Feature Crossed							
Mat (scour & erosion)							
Generic	100%			LIFE			**
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : Throughout</i>				
			<i>Explanation : Railroad Track</i>				
Pier Protection							
Not Accessible	100%						
Approaches							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TRANSIT AUTHORITY YARD BRIDGE W 205 ST/NYCTA IND YARDS
Asset # : 2485

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	25%	2-4	\$32,600	2034	\$163,200	4	\$8,100	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : East Approach</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : East Approach</i>								
<i>Explanation : Uneven Surface</i>								
Asphalt	75%			2027	\$489,600	4	\$12,100	
Concrete	45%	4+	\$47,200	2042	**	4	\$61,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	55%			2029	\$2,886,700	4	\$61,700	
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042	**	4	\$1,700	
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence</i>								
Sidewalks								
Concrete	100%	4+	\$18,200	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
TRANSIT AUTHORITY YARD BRIDGE W 205 ST/NYCTA IND YARDS
Asset # : 2485

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
Railings/Parapets								
Concrete	100%	4+	\$37,500	2042		**	4	\$12,400
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : North Side</i>					
Steel	100%			LIFE		**	2-8	\$16,100
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Chain Link Fence</i>					
Sidewalks								
Concrete	100%	4+	\$90,400	2038		**	5	\$15,100
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	100%	4+	\$49,900	2042		**	5	\$66,200
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : UNION STREET 278I (B.Q.E.)
Address : UNION STREET OVER B.Q.E BET. HENRY ST & COLUMBIA ST
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0301.000 / 15059 **Yr Built/Renovated** : 1952 /
Area Sq Ft : 4,856 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 15-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2230360

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,100		\$500	\$9,100
Total	\$2,100		\$500	\$9,100
Importance Code A	\$2,100		\$100	
Importance Code C			\$400	\$9,100
Total	\$2,100		\$500	\$9,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNION STREET 278I (B.Q.E.)
Asset # : 15059

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Generic	100%			LIFE		**	
		<i>Spalling, Extent : Light, Area Affected : 2%</i>					
		<i>Location : East And West Joint Headers</i>					
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Not Accessible	100%						
Feature Crossed							
Mat (scour & erosion)							
Not Accessible	100%						
Pier Protection							
Not Accessible	100%						
Approaches							
Pavement							
Asphalt	100%			2036		**	4 \$700
		<i>Cracks, Extent : Light, Area Affected : 1%</i>					
		<i>Location : West Approach</i>					
Embankment							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Pavement Base							
Not Accessible	100%						
Piers							
Cap Beam							
Not Accessible	100%						
Pier,Columns							
Not Accessible	100%						
Stem,Solid Pier							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE		**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNION STREET 278I (B.Q.E.)
Asset # : 15059

Bridge Structure System Component Type	Current Repair		Future Replacement		Maintenance		Priority
	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Piers							
Pedestals							
Not Accessible	100%						
Piles							
Not Accessible	100%						
Deck Elements							
Curbs							
Concrete w/ Steel Face	100%		LIFE		**		
			<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>				
			<i>Location : Throughout</i>				
Railings/Parapets							
Steel	100%		LIFE		**	2-8	\$5,500
			<i>Corrosion, Extent : Moderate, Area Affected : 50%</i>				
			<i>Location : Chain Link Fence</i>				
Sidewalks							
Concrete	100%		2040		**	5	\$3,400
			<i>Cracks, Extent : Light, Area Affected : 2%</i>				
			<i>Location : Random Locations Throughout</i>				
Wearing Surface							
Concrete	100%		2044		**	5	\$18,100
			<i>Cracks, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Random Locations Throughout</i>				
Superstructure							
Deck, Structural							
Not Accessible	100%						
Primary Member							
Not Accessible	100%						
Secondary Member							
Not Accessible	100%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : UNION STREET FRANKLIN SHUTTLE
Address : UNION STREET BETWEEN CLASSON AVE & FRANKLIN AVE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0305.000 / 15063 **Yr Built/Renovated** :
Area Sq Ft : 3,952 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 21-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2243200

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$85,700	\$33,900
Total	\$85,700	\$33,900
Importance Code B	\$33,900	\$33,900
Importance Code C	\$51,800	
Total	\$85,700	\$33,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$88,900		\$7,300	
Total	\$88,900		\$7,300	
Importance Code A	\$49,700		\$3,900	
Importance Code B	\$28,400		\$3,400	
Importance Code C	\$10,800			
Total	\$88,900		\$7,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
UNION STREET FRANKLIN SHUTTLE
Asset # : 15063

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
Backwall Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 10%</i>						
		<i>Location : South Side</i>						
		<i>Explanation : Limited Access</i>						
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Granite Rock Pavers</i>						
Pedestals Not Accessible	100%							
Stem (breastwall) Concrete Encased Steel	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 10%</i>						
		<i>Location : South Side</i>						
		<i>Explanation : Limited Access</i>						
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%	4+	\$51,800	LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Vegetation Growth, Extent : Severe, Area Affected : 75%</i>						
		<i>Location : Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>						
		<i>Location : South Side</i>						
		<i>Explanation : Concrete Crib Wall</i>						
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNION STREET FRANKLIN SHUTTLE
Asset # : 15063

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Mta Subway Tracks</i>								
Approaches								
Pavement								
Asphalt	100%	4+	\$8,900	2036		**	4	\$2,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain-link Fence And Corrugated Railing</i>								
Sidewalks								
Concrete	100%	4+	\$1,800	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Moderate, Area Affected : 3%</i>								
<i>Location : Southwest Corner</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southwest Corner</i>								
<i>Explanation : 1 Scupper</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$120,600
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$159,800
<i>Other Observation, Extent : N/A, Area Affected : 10%</i>								
<i>Location : South Side</i>								
<i>Explanation : Limited Access</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNION STREET FRANKLIN SHUTTLE
Asset # : 15063

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : MTA Subway Tracks</i>						
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	100%			2055	**			
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,400	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : South Side Only</i>						
		<i>Explanation : Parapet Wall With Brick Fascia</i>						
Steel	100%			LIFE	**	2-8	\$3,000	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : On Top Of Concrete Parapet South Side, Stand Alone At North Side</i>						
		<i>Explanation : Chain Link Fence</i>						
Sidewalks								
Concrete	100%			2040	**	5	\$3,100	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Wearing Surface								
Asphalt	100%			2036	**	5	\$200	
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : W 134TH STREET TERRAIN
Address : W 134TH STREET & RIVERSIDE DRIVE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0289.000 / 15047 **Yr Built/Renovated** :
Area Sq Ft : 7,434 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2246670

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$180,500	\$239,400
Total	\$180,500	\$239,400
Importance Code A	\$180,500	\$180,500
Importance Code B		\$58,900
Total	\$180,500	\$239,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$158,000		\$25,500	\$14,300
Total	\$158,000		\$25,500	\$14,300
Importance Code A	\$92,100		\$18,100	
Importance Code B	\$45,800		\$6,300	
Importance Code C	\$20,100		\$1,100	\$14,300
Total	\$158,000		\$25,500	\$14,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
W 134TH STREET TERRAIN
Asset # : 15047

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pier Protection								
Concrete	100%			LIFE		**		
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 1%</i>					
			<i>Location : Steel Casing Around Concrete Protection</i>					
			<i>Explanation : Rust Stains</i>					
Approaches								
Pavement								
Asphalt	10%	0-2	\$3,900	2036		**	4	\$2,100
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Northeast And Southeast Sides</i>					
Asphalt	90%			2036		**	4	\$2,100
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Southeast Approach Near Joint</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Rust Stains</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 134TH STREET TERRAIN
Asset # : 15047

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Sidewalks								
Concrete	100%	2-4	\$1,100	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Southeast Corner Adjacent To Joint</i>								
<i>Explanation : Gap Between Sidewalk And Joint</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$413,400
Pier,Columns								
Steel	100%	4+	\$40,600	LIFE		**	2-8	\$169,600
<i>Loss of Section, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Loss of Section, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Random Sections Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Peeling Paint</i>								
Sidewalks								
Concrete	100%	4+	\$11,000	2040		**	5	\$2,400
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044		**	5	\$28,600
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 134TH STREET TERRAIN
Asset # : 15047

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Scupper Cast Iron	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 5%</i> <i>Location : All Quadrants Except Southwest</i> <i>Explanation : 3 Scuppers On Bridge</i>								
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$16,400	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Stay In Place Forms</i>								
Joints								
Generic	100%	0-2	\$4,000	LIFE	**			
<i>Leakage, Extent : Light, Area Affected : 50%</i> <i>Location : Random Locations Throughout</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$235,600	
<i>Other Observation, Extent : N/A, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Rust Stains</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$12,100	
<i>Other Observation, Extent : N/A, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Rust Stains</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : W 53RD STREET AMTRAK 30 ST BRANCH
Address : W 53RD ST BET. 10TH & 11TH AVES
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0292.000 / 15050 **Yr Built/Renovated** : 1936 /
Area Sq Ft : 4,476 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245180

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,000		\$2,200	\$5,200
Total	\$2,000		\$2,200	\$5,200
Importance Code A	\$2,000			
Importance Code C			\$2,200	\$5,200
Total	\$2,000		\$2,200	\$5,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 53RD STREET AMTRAK 30 ST BRANCH
Asset # : 15050

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : No Access To Amtrak Property Underneath</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Walls Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Bank Protection Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								
Pavement Asphalt	100%			2036	**	4	\$4,300	
Curbs Concrete w/ Steel Face	100%			LIFE	**			
		<i>Misaligned/Bulging, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>						
		<i>Location : Throughout</i>						

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.*

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
W 53RD STREET AMTRAK 30 ST BRANCH
Asset # : 15050

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	Now	\$2,000	LIFE		**		
			<i>Cracks, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : North Side</i>					
			<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					
			<i>Spalling, Extent : Severe, Area Affected : 5%</i>					
			<i>Location : North Side</i>					
Sidewalks								
Concrete	100%			2040		**	5	\$3,400
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Recent Replace Evident, Extent : N/A, Area Affected : 10%</i>					
			<i>Location : Random Locations On South Side</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 53RD STREET AMTRAK 30 ST BRANCH
Asset # : 15050

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Asphalt	100%			2039	**	5	\$10,300	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Recent Repair Evident</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : W 57TH STREET AMTRAK 30 ST BRANCH
Address : W 57TH ST. BET. 10TH & 11TH AVES
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0290.000 / 15048 **Yr Built/Renovated** :
Area Sq Ft : 8,882 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245220

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$5,900		\$1,600	
Total	\$5,900		\$1,600	
Importance Code C	\$5,900		\$1,600	
Total	\$5,900		\$1,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 57TH STREET AMTRAK 30 ST BRANCH
Asset # : 15048

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : No Access To Amtrak Property Underneath</i>								
<hr/>								
Backwall Not Accessible	100%							
<hr/>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
<hr/>								
Footings Not Accessible	100%							
<hr/>								
Joint with Deck Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Pedestals Not Accessible	100%							
<hr/>								
Stem (breastwall) Not Accessible	100%							
<hr/>								
Walls Not Accessible	100%							
<hr/>								
Wingwalls								
Footings Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Piles Not Accessible	100%							
<hr/>								
Walls Not Accessible	100%							
<hr/>								
Feature Crossed								
Bank Protection Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Not Accessible	100%							
<hr/>								
Pier Protection Not Accessible	100%							
<hr/>								
Approaches								
Pavement Asphalt	100%			2036	**	4	\$3,200	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Repair Evident, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Westbound Lane</i>								
<hr/>								

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
W 57TH STREET AMTRAK 30 ST BRANCH
Asset # : 15048

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	4+	\$2,300	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northwest Approach</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
Sidewalks								
Concrete	100%			2040		**	5	\$7,100
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 57TH STREET AMTRAK 30 ST BRANCH
Asset # : 15048

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Asphalt	100%			2036	**	5	\$7,200	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 5%</i>						
		<i>Location : Westbound Lane</i>						
		<i>Explanation : Recent Repair Evident</i>						
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : W 70TH STREET AMTRAK
Address : WEST 70TH STREET BET. 11TH AVE AND HENRY HUDSON PKWY
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0291.000 / 15049 **Yr Built/Renovated** :
Area Sq Ft : 16,866 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 20-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2269190

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$166,900	\$166,900
Total	\$166,900	\$166,900
Importance Code A	\$166,900	\$166,900
Total	\$166,900	\$166,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$92,300		\$19,700	\$32,600
Total	\$92,300		\$19,700	\$32,600
Importance Code A	\$80,400		\$16,700	
Importance Code B	\$11,800		\$1,000	
Importance Code C			\$1,900	\$32,600
Total	\$92,300		\$19,700	\$32,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
W 70TH STREET AMTRAK
Asset # : 15049

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
		<i>Spalling, Extent : Light, Area Affected : 1%</i>						
		<i>Location : On East Side Concrete Header</i>						
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$3,800
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
		<i>Rust Stains, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 70TH STREET AMTRAK
Asset # : 15049

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Southeast Corner</i>								
<i>Explanation : 1 Scupper</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Second Pier From West</i>								
Pier,Columns								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Second Pier From West</i>								
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : 2nd Pier From Left</i>								
Stem,Solid Pier								
Concrete	100%			LIFE			**	
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Concrete	100%			LIFE			**	
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$6,200	LIFE			**	
<i>Corrosion, Extent : Moderate, Area Affected : 70%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%			2040		**	5	\$12,500
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2044		**	5	\$65,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 70TH STREET AMTRAK
Asset # : 15049

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$37,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Bottom Of The Deck</i>								
<i>Explanation : Stay In Place Is In Good Condition</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$534,400	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$27,500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : W125TH ST. VIADUCT BRIDGE RIVERSIDE DR/W.125 ST AND OTHERS
Address : RIVERSIDE DR,ST.CLAIRES,134 ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0068.000 / 2662 **Yr Built/Renovated** : 1897 /
Area Sq Ft : 148,338 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 04-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2246660

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$723,100	\$4,867,100
Total	\$723,100	\$4,867,100
Importance Code A		\$1,612,500
Importance Code B	\$244,400	\$2,152,300
Importance Code C	\$478,700	\$1,102,200
Total	\$723,100	\$4,867,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$133,300	\$800	\$402,600	
Total	\$133,300	\$800	\$402,600	
Importance Code A	\$34,000	\$800	\$150,600	
Importance Code B	\$25,500		\$215,900	
Importance Code C	\$73,800		\$36,200	
Total	\$133,300	\$800	\$402,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W125TH ST. VIADUCT BRIDGE RIVERSIDE DR/W.125 ST AND OTHERS
Asset # : 2662

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Granite	100%	4+	\$11,000	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : At Top Of End Abutment</i>								
<i>Explanation : Missing Mortar</i>								
Backwall								
Granite	100%	4+	\$15,900	LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : End Abutment</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing / Eroded</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	0-2	\$3,400	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : At End Abutment</i>								
<i>Explanation : Cracks In Header Concrete</i>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Granite	90%			LIFE		**		
Granite	10%	0-2	\$22,200	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 35%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rust Staining</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W125TH ST. VIADUCT BRIDGE RIVERSIDE DR/W.125 ST AND OTHERS
Asset # : 2662

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Wingwalls								
Walls								
Granite	90%			LIFE			**	
Granite	10%	4+	\$20,100	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Missing Mortar</i>								
Feature Crossed								
Pier Protection								
Steel	100%			LIFE			**	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Concrete Filled On Steel Casing</i>								
Approaches								
Pavement								
Asphalt	100%	4+	\$11,300	2034	\$562,500	4	\$8,100	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : At End Abutment</i>								
Concrete	50%			2042		4	\$46,300	**
Concrete	50%	Now	\$56,600	2042		4	\$30,800	**
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout North Side</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout North Side</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout North Side</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Rust Stains, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Earth	100%			LIFE			**	
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W125TH ST. VIADUCT BRIDGE RIVERSIDE DR/W.125 ST AND OTHERS
Asset # : 2662

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets								
Concrete	100%	4+	\$3,200	2042	**	4	\$700	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Granite	90%			LIFE	**			
Granite	10%	4+	\$7,100	LIFE	**			
<i>Vegetation Growth, Extent : Light, Area Affected : 30%</i>								
<i>Location : Below Capstone Of Beginning And End Approaches</i>								
<i>Other Observation, Extent : Severe, Area Affected : 20%</i>								
<i>Location : End Approach And Begin Approach</i>								
<i>Explanation : Missing And Broken Element And Missing Mortar</i>								
Sidewalks								
Asphalt	100%	4+	\$11,100	2034	\$222,900	4	\$8,100	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Northwest Corner</i>								
Concrete	100%			LIFE	**			
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Total Of 3 Scuppers</i>								
Piers								
Cap Beam								
Steel	90%			LIFE	**	2-8	\$74,800	
Steel	10%	4+	\$12,600	LIFE	**	2-8	\$74,800	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Moderate Rust Staining On Lattice Members</i>								
Pier,Columns								
Steel	100%			LIFE	**	2-8	\$1,969,700	
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Stem,Solid Pier								
Granite	90%			LIFE	**			
Granite	10%	4+	\$244,400	LIFE	**			
<i>Efflorescence, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Cracks</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W125TH ST. VIADUCT BRIDGE RIVERSIDE DR/W.125 ST AND OTHERS
Asset # : 2662

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Underneath</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Misaligned/Bulging, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Masonry	100%			2042	**	5	\$1,600	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
Steel	100%			LIFE	**	2-8	\$76,900	
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Chain Link Fence Attached To Steel Railing</i>								
Sidewalks								
Concrete	12%	4+	\$55,900	2038	**	5	\$36,200	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	88%			2038	**	5	\$72,300	
Wearing Surface								
Asphalt	100%			2034		5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span No. 1</i>								
<i>Explanation : At Span No. 1 Only</i>								
Concrete	100%	4+	\$205,700	2042	**	5	\$316,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Around Deck Joints</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W125TH ST. VIADUCT BRIDGE RIVERSIDE DR/W.125 ST AND OTHERS
Asset # : 2662

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Total Of 16 Scuppers</i>								
<hr/>								
Superstructure								
Deck,Structural Concrete	100%			LIFE	**	5	\$138,400	
<i>Rust Stains, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout Stay-in-place Forms</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Bottom Side Of Slab Covered By Stay-in-place Forms</i>								
<hr/>								
Joints								
Steel	100%	Now	\$160,600	LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Damaged Seal</i>								
<hr/>								
Primary Member								
Masonry: Granite	100%			LIFE	**			
<i>Joints Missing, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Near East And West Ends</i>								
<i>Explanation : Arch Intrados Covered With Steel Mesh</i>								
Steel	100%			LIFE	**	2-8	\$2,632,600	
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Peeling Paint</i>								
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$2,297,200	
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST 158TH STREET BRIDGE / W 158TH ST/AMTRAK 30TH ST BRANCH
Address : RAMP TO W. 158TH STREET / AMTRAK RAILS
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0157.000 / 13520 **Yr Built/Renovated** :
Area Sq Ft : 29,170 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 19-Oct-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245250

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$666,900
Total		\$666,900
Importance Code A		\$288,700
Importance Code B		\$288,700
Importance Code C		\$89,500
Total		\$666,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$155,100		\$58,100	
Total	\$155,100		\$58,100	
Importance Code A	\$20,000		\$29,100	
Importance Code B	\$2,300		\$29,000	
Importance Code C	\$132,800			
Total	\$155,100		\$58,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 158TH STREET BRIDGE / W 158TH ST/AMTRAK 30TH ST BRANCH
Asset # : 13520

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Brngs,Ancr Blts,Pads								
Elastomeric	100%	0-2	\$8,600	2052		**		
			<i>Corrosion, Extent : Severe, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,300	LIFE		**		
			<i>Leakage, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : At Sidewalk At End Of Abutment</i>					
			<i>Explanation : Damaged/ Misaligned Expansion Joint Membrane</i>					
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stem Breastwall Consists Of 50 Percent Concrete, 50 Percent Not Accessible</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 158TH STREET BRIDGE / W 158TH ST/AMTRAK 30TH ST BRANCH
Asset # : 13520

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	100%	4+	\$47,900	2041	**	4	\$55,500	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041	**	4		
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : 1 Scupper</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Pier 5</i>								
Pier,Columns								
Concrete	100%			LIFE	**			
Stem,Solid Pier								
Concrete	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Pier 6</i>								
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2060	**			
<i>Corrosion, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 158TH STREET BRIDGE / W 158TH ST/AMTRAK 30TH ST BRANCH
Asset # : 13520

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : East Side Only</i>								
<hr/>								
Railings/Parapets								
Concrete	100%	4+	\$11,400	2041		**	4	\$400
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Span 4</i>								
Steel	100%			LIFE		**	2-8	\$4,600
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East And West Sides</i>								
<i>Explanation : Steel Railing And Concrete Parapet At West Side. Steel Fence And Steel Railing At East Sides</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$22,300	2037		**	5	\$7,400
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$34,200	2041		**	5	\$89,500
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : 2 Scuppers Observed</i>								
<hr/>								
Superstructure								
Deck,Structural								
Concrete	100%			LIFE		**	5	\$32,500
<i>Other Observation, Extent : N/A, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Stay In Place Forms</i>								
<hr/>								
Joints								
Generic	100%	Now	\$28,400	LIFE		**		
<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 33%</i>								
<i>Location : Span 4 Expansion Joint</i>								
<hr/>								
Primary Member								
Steel	100%			LIFE		**	2-8	\$539,300
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 158TH STREET BRIDGE / W 158TH ST/AMTRAK 30TH ST BRANCH
Asset # : 13520

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure Secondary Member Steel	100%			LIFE	**	2-8	\$451,700	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST 232ND STREET HENRY HUDSON PARKWAY
 Address : W 232ND ST & HENRY HUDSON PKWY
 Borough : BRONX Agency's Number : N/A
 Program / Asset # : DOT0366.000 / 15384 Yr Built/Renovated :
 Area Sq Ft : 5,084 Project Type : HIGHWAY BRIDGES
 Date of Survey : 22-Mar-2022 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2229450

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$89,800
Total		\$89,800
Importance Code C		\$89,800
Total		\$89,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$65,200		\$200	
Total	\$65,200		\$200	
Importance Code A	\$47,000		\$200	
Importance Code C	\$18,200			
Total	\$65,200		\$200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 232ND STREET HENRY HUDSON PARKWAY
Asset # : 15384

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Stem (breastwall)								
Concrete	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Granite	100%	4+	\$5,700	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Joints Missing, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE	**			
Pier Protection								
Concrete	100%			LIFE	**			
Approaches								
Pavement								
Asphalt	100%	4+	\$1,800	2034	\$89,800	4	\$2,800	
			<i>Cracks, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE	**			
			<i>Recent Repair Evident, Extent : N/A, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 232ND STREET HENRY HUDSON PARKWAY

Asset # : 15384

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Guide Railing								
Steel	100%			LIFE		**		
Timber	100%	4+	\$1,500	2053		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Wood Blocks At Steel Posts</i>								
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loss of Section, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : North Side</i>								
<i>Explanation : Impact Damage</i>								
<hr/>								
Railings/Parapets								
Granite	100%	4+	\$6,600	LIFE		**		
<i>Joints Missing, Extent : Light, Area Affected : 7%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Southwest Side</i>								
<i>Explanation : Cracks</i>								
Steel	100%			LIFE		**	2-8	\$6,800
<hr/>								
Sidewalks								
Concrete	100%	4+	\$7,700	2038		**	5	\$3,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Concrete	100%	4+	\$3,000	2042		**	5	\$10,100
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$38,900	LIFE		**	5	\$5,600
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Above The Southbound Henry Hudson Parkway</i>								
<i>Other Observation, Extent : N/A, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Recent Repairs Evident</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST 236TH ST. PEDESTRIAN BRDG HENRY HUDSON PARKWAY
Address : W 236TH ST PED. BRDG OVER HHP BET W 236TH & W 235TH STS
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0395.000 / 15415 Yr Built/Renovated :
Area Sq Ft : 2,412 Project Type : HIGHWAY BRIDGES
Date of Survey : 22-Mar-2022 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2229460

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$126,000	
Total	\$126,000	
Importance Code C	\$126,000	
Total	\$126,000	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$114,500		\$4,000	
Total	\$114,500		\$4,000	
Importance Code A	\$66,700		\$1,600	
Importance Code B	\$16,900		\$2,400	
Importance Code C	\$30,900			
Total	\$114,500		\$4,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 236TH ST. PEDESTRIAN BRDG HENRY HUDSON PARKWAY
Asset # : 15415

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%	4+	\$1,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Steel	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Steel	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Stem (breastwall) Concrete	35%	4+	\$16,900	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	65%			LIFE		**		
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Granite	100%			LIFE		**		
<i>Joints Missing, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Mat (scour & erosion) Asphalt Paving	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Pavement</i>								
Pier Protection Concrete	100%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 236TH ST. PEDESTRIAN BRDG HENRY HUDSON PARKWAY
Asset # : 15415

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Concrete	70%	4+	\$126,000	2042	**	4	\$26,400	
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	30%			2042	**	4	\$39,600	
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$11,300	2042	**	4	\$13,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout And North Approach</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout And North Approach</i>								
Steel	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 50%</i>								
<i>Location : Chain-link Fence Posts</i>								
Piers								
Stem,Solid Pier								
Granite	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Cracks</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**	2-8	\$1,800	
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Steel	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%	4+	\$7,600	2042	**	4	\$6,200	
<i>Cracks, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$8,500	
<i>Rust Stains, Extent : Light, Area Affected : 40%</i>								
<i>Location : Chain-link Fence Posts</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 236TH ST. PEDESTRIAN BRDG HENRY HUDSON PARKWAY
Asset # : 15415

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface Concrete	100%	4+	\$17,700	2042	**	5	\$1,200	
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 6%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East Side And West Side</i>								
<i>Explanation : Two Scuppers</i>								
<hr/>								
Superstructure								
Deck, Structural Concrete	100%	4+	\$46,200	LIFE	**	5	\$2,700	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
<hr/>								
Primary Member Steel	100%			LIFE	**	2-8	\$22,300	
<hr/>								
Secondary Member Steel	100%			LIFE	**	2-8	\$37,100	
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST 239TH STREET HENRY HUDSON PARKWAY
Address : WEST 239TH STREET OVER HH PKWY
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0367.000 / 15385 **Yr Built/Renovated** :
Area Sq Ft : 5,440 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2229470

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$58,500		\$100	
Total	\$58,500		\$100	
Importance Code A	\$51,400		\$100	
Importance Code C	\$7,100			
Total	\$58,500		\$100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WEST 239TH STREET HENRY HUDSON PARKWAY
Asset # : 15385

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
			<i>Recent Repair Evident, Extent : N/A, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE		**		
			<i>Efflorescence, Extent : Light, Area Affected : 8%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE		**		
Pier Protection								
Concrete	100%			LIFE		**		
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
			<i>Recent Repair Evident, Extent : N/A, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Light, Area Affected : 70%</i>					
			<i>Location : Random Locations Throughout</i>					
Guide Railing								
Steel	100%			LIFE		**		
Timber	100%	4+	\$1,500	2053		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Loss of Section, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 239TH STREET HENRY HUDSON PARKWAY
Asset # : 15385

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Granite	100%	4+	\$8,200	LIFE	**			
<i>Joints Missing, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE	**	2-8	\$3,400	
Sidewalks								
Concrete	100%	4+	\$3,600	2038	**	5	\$1,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$3,500	2042	**	5	\$11,400	
<i>Cracks, Extent : Moderate, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural Concrete	100%	4+	\$41,700	LIFE	**	5	\$6,000	
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Above Southbound Henry Hudson Parkway</i>								
<i>Other Observation, Extent : N/A, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Recent Repairs Evident</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST 246TH STREET HENRY HUDSON PARKWAY
Address : W 246TH ST & HENRY HUDSON PKW
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0369.000 / 15387 **Yr Built/Renovated** :
Area Sq Ft : 5,092 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2229490

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$51,000	\$11,000	\$100	
Total	\$51,000	\$11,000	\$100	
Importance Code A	\$38,900		\$100	
Importance Code B	\$8,300			
Importance Code C	\$3,800	\$11,000		
Total	\$51,000	\$11,000	\$100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WEST 246TH STREET HENRY HUDSON PARKWAY

Asset # : 15387

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Stem (breastwall)								
Concrete	100%			LIFE	**			
Granite	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE	**			
			<i>Joints Missing, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE	**			
Pier Protection								
Concrete	100%	4+	\$8,300	LIFE	**			
			<i>Cracks, Extent : Light, Area Affected : 4%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 3%</i>					
			<i>Location : Northbound Henry Hudson Parkway</i>					
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE	**			
Granite	100%			LIFE	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
			<i>Rust Stains, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
Railings/Parapets								
Granite	100%			LIFE	**			
			<i>Joints Missing, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE	**	2-8	\$3,400	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
WEST 246TH STREET HENRY HUDSON PARKWAY**

Asset # : 15387

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%	4+	\$3,800	2038	**	5	\$1,600	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%			2042	**	5	\$22,000	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$38,900	LIFE	**	5	\$5,600	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Above Southbound Henry Hudson Parkway</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST 37TH STREET AMTRAK 30TH STREET BRANCH
Address : WEST 37TH STREET BETWEEN 10TH & 11TH AVENUES
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0239.000 / 14979 **Yr Built/Renovated** : 1938 /
Area Sq Ft : 7,062 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245060

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure		\$5,200	\$12,600	\$2,600
Total		\$5,200	\$12,600	\$2,600
Importance Code A		\$2,100	\$200	
Importance Code C		\$3,100	\$12,500	\$2,600
Total		\$5,200	\$12,600	\$2,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WEST 37TH STREET AMTRAK 30TH STREET BRANCH
Asset # : 14979

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Underside Of Structure</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
<i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								
Pavement Concrete	100%			2043		**	4	\$9,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 2%</i>								
<i>Location : Northeast Corner</i>								
<i>Explanation : Asphalt Patches</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 37TH STREET AMTRAK 30TH STREET BRANCH
Asset # : 14979

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast Corner</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Southeast Corner</i>								
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2043	**	4	\$900	
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Southeast Corner</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Recent Replace Evident, Extent : N/A, Area Affected : 40%</i>								
<i>Location : South Side</i>								
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On North Side</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 37TH STREET AMTRAK 30TH STREET BRANCH
Asset # : 14979

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets								
Concrete	100%			2043	**	4	\$5,500	
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Steel	100%			LIFE	**	2-8	\$5,000	
Sidewalks								
Concrete	100%			2039	**	5	\$5,200	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 40%</i>						
		<i>Location : South Side</i>						
Wearing Surface								
Concrete	100%			2043	**	5	\$24,900	
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST 38TH STREET AMTRAK 30TH STREET BRANCH
Address : WEST 38TH STREET BETWEEN 10TH AND 11TH AVENUES
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0240.000 / 14980 **Yr Built/Renovated** : 1934 /
Area Sq Ft : 6,160 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245070

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$444,500
Total		\$444,500
Importance Code C		\$444,500
Total		\$444,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$127,900		\$200	
Total	\$127,900		\$200	
Importance Code A	\$68,400		\$200	
Importance Code C	\$59,500			
Total	\$127,900		\$200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WEST 38TH STREET AMTRAK 30TH STREET BRANCH
Asset # : 14980

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Underside Of Structure</i>								
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Paved Over With Asphalt</i>								
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								
Pavement Asphalt	100%	2-4	\$35,600	2035	\$355,900	4	\$5,100	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Uneven Surface With Ponding</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 38TH STREET AMTRAK 30TH STREET BRANCH
Asset # : 14980

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Curbs								
Concrete w/ Steel Face	100%	Now	\$9,000	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Severe Cases On Northwest Corner</i>								
<i>Rust Stains, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%	4+	\$11,400	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%	2-4	\$3,400	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Severe Cases On Southwest Corner</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 38TH STREET AMTRAK 30TH STREET BRANCH
Asset # : 14980

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	2-4	\$7,300	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Misaligned/Bulging, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%	2-4	\$40,800	2043		**	4	\$3,100
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	\$4,300
<hr/>								
Sidewalks								
Concrete	100%	4+	\$11,600	2039		**	5	\$2,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wearing Surface								
Asphalt	100%	0-2	\$8,900	2035	\$88,600		5	\$2,600
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Uneven Surface</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Joints								
Not Accessible	100%							
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST 39TH STREET AMTRAK 30TH STREET BRANCH
Address : WEST 39TH STREET BETWEEN 10TH AND 11TH AVENUES
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0241.000 / 14981 **Yr Built/Renovated** : 1934 /
Area Sq Ft : 6,159 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245080

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$570,400
Total		\$570,400
Importance Code C		\$570,400
Total		\$570,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$75,200		\$100	
Total	\$75,200		\$100	
Importance Code A	\$29,300		\$100	
Importance Code C	\$45,900			
Total	\$75,200		\$100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WEST 39TH STREET AMTRAK 30TH STREET BRANCH
Asset # : 14981

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : No Access To Underside Of Structure</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Paved Over With Asphalt</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								
Pavement Asphalt	100%	Now	\$22,900	2035	\$458,800	4	\$6,600	
		<i>Cracks, Extent : Moderate, Area Affected : 15%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : Severe, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout With Severe Cases On West Approach</i>						
		<i>Explanation : Potholes</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 39TH STREET AMTRAK 30TH STREET BRANCH
Asset # : 14981

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%	Now	\$11,600	LIFE				**
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Southwest Corner</i>								
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	2-4	\$2,000	LIFE				**
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout With Severe Cases At Northwest Corner</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout With Severe Cases At Northwest Corner</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 39TH STREET AMTRAK 30TH STREET BRANCH
Asset # : 14981

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	0-2	\$7,300	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations On South Side</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On South Side</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On South Side</i>								
Railings/Parapets								
Concrete	100%	2-4	\$10,300	2043		**	4	\$1,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On South Side</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations On South Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On South Side</i>								
Steel	100%			LIFE		**	2-8	\$2,200
<i>Rust Stains, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%	2-4	\$5,300	2039		**	5	\$1,000
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations On South Side</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On South Side</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On South Side</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations On South Side</i>								
<i>Explanation : Uneven Surface</i>								
Wearing Surface								
Asphalt	100%	2-4	\$11,200	2035	\$111,600		5	\$3,300
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Uneven Surface</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 39TH STREET AMTRAK 30TH STREET BRANCH

Asset # : 14981

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Joints								
Generic	100%	4+	\$4,500	LIFE				* *
			<i>Rust Stains, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Random Locations On North Side</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 60%</i>					
			<i>Location : North Side</i>					
			<i>Explanation : Longitudinal Joint Connected To Adjacent Bridge On North Side. Debris Accumulation</i>					
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST 41ST STREET AMTRAK 30TH STREET BRANCH
Address : WEST 41ST STREET BETWEEN 10TH AND 11TH AVENUES
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0242.000 / 14982 **Yr Built/Renovated** : 1935 /
Area Sq Ft : 6,282 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2245330

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$427,500
Total		\$427,500
Importance Code C		\$427,500
Total		\$427,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$47,900			
Total	\$47,900			
Importance Code A	\$18,100			
Importance Code C	\$29,800			
Total	\$47,900			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WEST 41ST STREET AMTRAK 30TH STREET BRANCH
Asset # : 14982

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : No Access To Underside Of Structure</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Paved Over With Asphalt</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								
Pavement Asphalt	100%	4+	\$16,900	2035	\$337,300	4	\$4,800	
		<i>Cracks, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Random Locations On Both Approaches</i>						
		<i>Explanation : Uneven Surface</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 41ST STREET AMTRAK 30TH STREET BRANCH
Asset # : 14982

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations On North Side</i>					
			<i>Misaligned/Bulging, Extent : Severe, Area Affected : 10%</i>					
			<i>Location : Random Locations On North Side</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Under Construction	100%							
			<i>Other Observation, Extent : N/A, Area Affected : 0%</i>					
			<i>Location : Southwest Corner</i>					
			<i>Explanation : Plywood Fencing</i>					
Sidewalks								
Concrete	100%	2-4	\$4,500	LIFE		**		
			<i>Cracks, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Southwest Corner</i>					
			<i>Explanation : Scaling</i>					
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST 41ST STREET AMTRAK 30TH STREET BRANCH
Asset # : 14982

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	0-2	\$18,100	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations On North Side</i>								
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On North Side</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations On North Side</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$8,400	2039		**	5	\$1,600
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On North Side</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On North Side</i>								
<hr/>								
Wearing Surface								
Asphalt	100%			2035	\$90,200		5	\$5,300
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
<hr/>								
Joints								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Longitudinal Joints On Both Sides Of Bridges</i>								
<hr/>								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST FINGERBOARD ROAD SIRT SOUTH SHORE
Address : W. FINGERBOARD RD. BET MARIE ST. AND N. RAILROAD AVENUE
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0265.000 / 15019 **Yr Built/Renovated** :
Area Sq Ft : 5,126 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 12-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2249480

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$21,500		\$10,600	
Total	\$21,500		\$10,600	
Importance Code A	\$11,600		\$2,600	
Importance Code B	\$2,700			
Importance Code C	\$7,200		\$8,000	
Total	\$21,500		\$10,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST FINGERBOARD ROAD SIRT SOUTH SHORE
Asset # : 15019

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,700	LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Along Header Blocks</i>					
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 15%</i>					
			<i>Location : Random Locations Along Header Block Edges</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 75%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Limited Access</i>					
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Not Accessible	100%							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST FINGERBOARD ROAD SIRT SOUTH SHORE

Asset # : 15019

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$16,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
Curbs								
Concrete w/ Steel Face	100%	2-4	\$1,700	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Along Steel Face</i>								
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : West Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : Southeast Corner</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : Southeast Corner</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST FINGERBOARD ROAD SIRT SOUTH SHORE
Asset # : 15019

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	2-4	\$7,200	LIFE		**		
			<i>Rust Stains, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 30%</i>					
			<i>Location : Random Locations Along Steel Face</i>					
Railings/Parapets								
Concrete	100%			2044		**	4	\$3,100
Steel	100%			LIFE		**	2-8	\$6,900
			<i>Rust Stains, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : On Top Of Concrete Parapet</i>					
			<i>Explanation : Chain Link Fence</i>					
Sidewalks								
Concrete	100%			2040		**	5	\$2,000
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Wearing Surface								
Concrete	100%	4+	\$7,200	2044		**	5	\$11,100
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Along Pier And Random Locations</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Near Header Joints</i>					
			<i>Other Observation, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling</i>					
Superstructure								
Deck, Structural								
Not Accessible	100%							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST FORDHAM ROAD METRO NORTH RAILROAD HUDSON
Address : W. FORDHAM RD. OVER METRO NORTH HUDSON LINE
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0252.000 / 14992 Yr Built/Renovated :
Area Sq Ft : 23,545 Project Type : HIGHWAY BRIDGES
Date of Survey : 26-Jan-2023 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2241470

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$60,100	\$1,027,800
Total	\$60,100	\$1,027,800
Importance Code A		\$233,000
Importance Code C	\$60,100	\$794,800
Total	\$60,100	\$1,027,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$76,700	\$8,200	\$25,000	
Total	\$76,700	\$8,200	\$25,000	
Importance Code A	\$6,500	\$3,100	\$23,600	
Importance Code B			\$1,400	
Importance Code C	\$70,200	\$5,100		
Total	\$76,700	\$8,200	\$25,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST FORDHAM ROAD METRO NORTH RAILROAD HUDSON
Asset # : 14992

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Generic	100%			LIFE		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 50 Percent Concrete</i>						
Masonry	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 50 Percent Masonry</i>						
Steel	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Southeast Corner</i>						
		<i>Explanation : Steel Column Observed - 10 Percent Steel</i>						
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 50 Percent Concrete</i>						
Masonry	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 50 Percent Masonry</i>						
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST FORDHAM ROAD METRO NORTH RAILROAD HUDSON

Asset # : 14992

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Asphalt Paving	100%			LIFE		**		
	<i>Roadway/Path, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 33 Percent Asphalt Paving</i>							
Earth	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Railroad Tracks. 67 Percent Earth</i>							
Pier Protection								
Concrete	100%			LIFE		**		
Approaches								
Pavement								
Asphalt	5%	4+	\$35,500	2039		**	4	\$10,200
	<i>Cracks, Extent : Light, Area Affected : 80%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 50%</i>							
	<i>Location : Random Locations Throughout</i>							
Asphalt	95%			2035	\$674,600		4	\$15,300
Curbs								
Concrete w/ Steel Face	100%	4+	\$1,800	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 3%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 4%</i>							
	<i>Location : Random Locations Throughout</i>							
Embankment								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2043		**	4	\$1,200
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 50 Percent Concrete</i>							
Steel	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 50 Percent Steel</i>							
Sidewalks								
Concrete	100%			LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST FORDHAM ROAD METRO NORTH RAILROAD HUDSON

Asset # : 14992

Bridge Structure		Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost		
Piers									
Stem,Solid Pier									
Concrete	100%			LIFE		**			
Brngs,Ancr Blts,Pads									
Multi-Rotational Bearing	100%			2062		**			
Footings									
Not Accessible	100%								
Mat (scour & erosion)									
Generic	100%			LIFE		**			
Pedestals									
Concrete	100%			LIFE		**			
Piles									
Not Accessible	100%								
Deck Elements									
Curbs									
Concrete w/ Steel Face	100%	4+	\$4,700	LIFE		**			
<i>Cracks, Extent : Light, Area Affected : 2%</i>									
<i>Location : Random Locations Throughout</i>									
<i>Spalling, Extent : Light, Area Affected : 5%</i>									
<i>Location : Random Locations Throughout</i>									
Median									
Concrete	100%			LIFE		**	5	\$800	
Railings/Parapets									
Concrete	100%			2043		**	4	\$8,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>									
<i>Location : Throughout</i>									
<i>Explanation : 50 Percent Concrete</i>									
Steel	100%			LIFE		**	2-8	\$7,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>									
<i>Location : Throughout</i>									
<i>Explanation : 50 Percent Steel</i>									
Sidewalks									
Concrete	100%	4+	\$15,200	2039		**	5	\$3,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>									
<i>Location : Random Locations Throughout</i>									
<i>Spalling, Extent : Light, Area Affected : 3%</i>									
<i>Location : Random Locations Throughout</i>									
Wearing Surface									
Concrete	5%	4+	\$19,500	2043		**	5	\$60,100	
<i>Cracks, Extent : Light, Area Affected : 30%</i>									
<i>Location : Random Locations Throughout</i>									
Concrete	95%			2043		**	5	\$120,200	
Scupper									
Cast Iron	100%			LIFE		**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>									
<i>Location : At The Center Of The Bridge</i>									
<i>Explanation : Two Scuppers Observed</i>									

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST FORDHAM ROAD METRO NORTH RAILROAD HUDSON

Asset # : 14992

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$25,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Covered With Stay-in-place Form</i>								
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$435,300	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$21,900	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST TREMONT AVENUE METRO NORTH RAILROAD HUDSON
 Address : W. TREMONT AVE. OVER METRO NORTH BET. MATTHEWSON RD AND CEDAR AVE
 Borough : BRONX Agency's Number : N/A
 Program / Asset # : DOT0251.000 / 14991 Yr Built/Renovated :
 Area Sq Ft : 21,960 Project Type : HIGHWAY BRIDGES
 Date of Survey : 26-Jan-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2241460

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$306,600	\$694,000
Total	\$306,600	\$694,000
Importance Code A	\$175,400	\$510,900
Importance Code B	\$75,900	\$42,200
Importance Code C	\$55,300	\$140,800
Total	\$306,600	\$694,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$79,800		\$105,600	
Total	\$79,800		\$105,600	
Importance Code A	\$29,600		\$51,400	
Importance Code B	\$4,800		\$5,500	
Importance Code C	\$45,300		\$48,600	
Total	\$79,800		\$105,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST TREMONT AVENUE METRO NORTH RAILROAD HUDSON
Asset # : 14991

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Abutments							
Bridge Seat&pedestals							
Not Accessible	100%						
Backwall							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Joint with Deck							
Generic	100%	4+	\$2,500	LIFE		**	
			<i>Cracks, Extent : Light, Area Affected : 5%</i>				
			<i>Location : Random Locations Throughout</i>				
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Stem (breastwall)							
Not Accessible	100%						
Walls							
Not Accessible	100%						
Wingwalls							
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Piles							
Not Accessible	100%						
Walls							
Masonry: Stone	100%			LIFE		**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : Throughout</i>				
			<i>Explanation : 50 Percent Not Accessible</i>				
Feature Crossed							
Mat (scour & erosion)							
Asphalt Paving	100%			LIFE		**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : Throughout</i>				
			<i>Explanation : Paved Roadway, 75 Percent Asphalt Paving</i>				
Earth	100%			LIFE		**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>				
			<i>Location : Throughout</i>				
			<i>Explanation : Railroad Tracks, 25 Percent Earth</i>				
Pier Protection							
Concrete	100%			LIFE		**	
Approaches							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST TREMONT AVENUE METRO NORTH RAILROAD HUDSON
Asset # : 14991

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%	4+	\$7,000	2035	\$140,800	4	\$2,000	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Curbs								
Concrete	100%	4+	\$1,500	LIFE			**	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : East Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 25 Percent Concrete</i>								
Concrete w/ Steel Face	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 25 Percent Concrete With Steel Face</i>								
Granite	100%	4+	\$3,600	LIFE			**	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 8%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 4%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Granite</i>								
<hr/>								
Embankment								
Generic	100%			LIFE			**	
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Masonry	100%	4+	\$6,800	2043			**	
<i>Spalling, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Northeast Corner</i>								
<i>Explanation : Missing Element, Impact Damage, 50 Percent Masonry</i>								
Steel	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Steel</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST TREMONT AVENUE METRO NORTH RAILROAD HUDSON
Asset # : 14991

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	65%	4+	\$1,800	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	35%			LIFE		**		
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At East Approach</i>								
<i>Explanation : 2 Scuppers</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	\$176,200
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 25 Percent Steel</i>								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : 75 Percent Not Accessible</i>								
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$121,500
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Steel And Rust Stains</i>								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : 50 Percent Not Accessible</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST TREMONT AVENUE METRO NORTH RAILROAD HUDSON
Asset # : 14991

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	40%	4+	\$75,900	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 50 Percent Concrete</i>							
Concrete	60%			LIFE		**		
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location :</i> <i>Explanation : 50 Percent Not Accessible</i>							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals								
Concrete	100%	4+	\$2,300	LIFE		**		
	<i>Cracks, Extent : Light, Area Affected : 4%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 40 Percent Concrete</i>							
Steel	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 10 Percent Steel</i>							
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : Throughout</i> <i>Explanation : 50 Percent Not Accessible</i>							
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST TREMONT AVENUE METRO NORTH RAILROAD HUDSON
Asset # : 14991

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%			2054	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 45 Percent Concrete</i>								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 10 Percent Concrete With Steel Face</i>								
Granite	100%	4+	\$6,600	LIFE	**			
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Northwest Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 45 Percent Granite</i>								
Railings/Parapets								
Concrete	100%	4+	\$11,200	2043	**	4	\$4,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Concrete</i>								
Steel	100%			LIFE	**	2-8	\$5,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Steel</i>								
Sidewalks								
Concrete	100%	4+	\$27,300	2039	**	5	\$5,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 3%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	70%	4+	\$55,300	2043	**	5	\$48,600	
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	30%			2043	**	5	\$97,300	
Superstructure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST TREMONT AVENUE METRO NORTH RAILROAD HUDSON
Asset # : 14991

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$24,200	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 50 Percent Concrete</i>							
Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 50 Percent Not Accessible; 10 Percent Stay In Place Forms Observed</i>							
Joints								
Generic	100%	4+	\$9,200	LIFE	**			
	<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 15 Percent Concrete</i>							
Steel	98%			LIFE	**	2-8	\$406,000	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 85 Percent Steel</i>							
Steel	2%	0-2	\$175,400	LIFE	**	2-8	\$406,000	
	<i>Other Observation, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : Fascia Girder Above South Bound Traffic</i>							
	<i>Explanation : Impact Damage</i>							
Secondary Member								
Steel	100%			LIFE	**	2-8	\$20,400	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 15 Percent Pre Stressed Concrete; 85 Percent Steel. Secondary Member Is Steel Section Only.</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WESTCHESTER AVE. BRIDGE OVER AMTRAK/ CSXT/ P AND W
 Address : WESTCHESTER AVE.
 Borough : BRONX Agency's Number : N/A
 Program / Asset # : DOT0161.000 / 13569 Yr Built/Renovated : 1907 /
 Area Sq Ft : 15,600 Project Type : HIGHWAY BRIDGES
 Date of Survey : 01-Mar-2022 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2241230

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$1,300,400
Total		\$1,300,400
Importance Code C		\$1,300,400
Total		\$1,300,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$63,600	\$34,900	\$3,900	
Total	\$63,600	\$34,900	\$3,900	
Importance Code A	\$1,600		\$200	
Importance Code B	\$23,100			
Importance Code C	\$38,900	\$34,900	\$3,700	
Total	\$63,600	\$34,900	\$3,900	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WESTCHESTER AVE. BRIDGE OVER AMTRAK/ CSXT/ P AND W
Asset # : 13569

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	100%	4+	\$23,100	LIFE			**	
			<i>Cracks, Extent : Moderate, Area Affected : 15%</i>					
			<i>Location : Northwest Corner</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 15%</i>					
			<i>Location : Northwest And Southeast Sides</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	22%	4+	\$14,300	2034	\$286,100	4	\$18,600	
			<i>Cracks, Extent : Light, Area Affected : 15%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 3%</i>					
			<i>Location : South Approach</i>					
			<i>Explanation : A Steel Plate</i>					
Asphalt	78%			2034	\$1,014,300	4	\$28,000	
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : East Approach South Side</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 16%</i>					
			<i>Location : Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WESTCHESTER AVE. BRIDGE OVER AMTRAK/ CSXT/ P AND W
Asset # : 13569

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Median								
Concrete	100%			LIFE		**	5	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : North Approach</i>						
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$1,400	2042		**	4	\$300
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Northeast Corner</i>						
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Northeast Corner</i>						
Steel	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Steel Panel Wall</i>						
Sidewalks								
Concrete	100%	4+	\$15,300	LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 4%</i>						
		<i>Location : Random Locations Throughout</i>						
Scupper								
Cast Iron	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : North Approach</i>						
		<i>Explanation : One Scupper</i>						
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							

Deck Elements

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WESTCHESTER AVE. BRIDGE OVER AMTRAK/ CSXT/ P AND W
Asset # : 13569

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Throughout</i>								
Median								
Concrete	100%			LIFE		**	5	\$700
Railings/Parapets								
Concrete	100%			2042		**	4	\$600
Steel	100%			LIFE		**	2-8	\$5,300
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Panel Wall</i>								
Sidewalks								
Concrete	100%			2038		**	5	\$7,500
Wearing Surface								
Concrete	100%			2042		**	5	\$69,800
Superstructure								
Deck,Structural								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : Material Is Concrete</i>								
Joints								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 20%</i>								
<i>Location : Southwest Corner</i>								
<i>Explanation : Depressed Joint Seal</i>								
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WESTCHESTER AVENUE HUTCHINSON RIVER PARKWAY
Address : WESTCHESTER AVE OVER HR PKWY
Borough : BRONX Agency's Number : N/A
Program / Asset # : DOT0312.000 / 15070 Yr Built/Renovated :
Area Sq Ft : 12,173 Project Type : HIGHWAY BRIDGES
Date of Survey : 11-Dec-2023 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2075837

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$120,500	\$120,500
Total	\$120,500	\$120,500
Importance Code A	\$120,500	\$120,500
Total	\$120,500	\$120,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$53,000		\$18,700	\$32,800
Total	\$53,000		\$18,700	\$32,800
Importance Code A	\$44,500		\$13,100	
Importance Code B	\$8,500		\$700	
Importance Code C			\$4,900	\$32,800
Total	\$53,000		\$18,700	\$32,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WESTCHESTER AVENUE HUTCHINSON RIVER PARKWAY

Asset # : 15070

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : North Side</i>								
<i>Explanation : Under Construction</i>								
Backwall Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : North Side</i>								
<i>Explanation : Under Construction</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : North Side</i>								
<i>Explanation : Under Construction</i>								
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : North Side</i>								
<i>Explanation : Under Construction</i>								
Stem (breastwall) Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : North Side</i>								
<i>Explanation : Under Construction</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Masonry	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Northeast Side</i>								
<i>Explanation : Under Construction</i>								
Feature Crossed								
Mat (scour & erosion) Asphalt Paving	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WESTCHESTER AVENUE HUTCHINSON RIVER PARKWAY

Asset # : 15070

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Feature Crossed								
Pier Protection								
Concrete	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Concrete Barrier</i>							
Approaches								
Pavement								
Concrete	100%			2044		**	4	\$9,700
	<i>Other Observation, Extent : N/A, Area Affected : 30%</i>							
	<i>Location : North Side</i>							
	<i>Explanation : Under Construction</i>							
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Embankment								
Earth	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044		**	4	\$1,500
Sidewalks								
Concrete	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 25%</i>							
	<i>Location : North Side</i>							
	<i>Explanation : Under Construction</i>							
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 40%</i>							
	<i>Location : North Side</i>							
	<i>Explanation : Under Construction</i>							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location : North Side</i>							
	<i>Explanation : Under Construction</i>							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 30%</i>							
	<i>Location : North Side</i>							
	<i>Explanation : Under Construction</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WESTCHESTER AVENUE HUTCHINSON RIVER PARKWAY

Asset # : 15070

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$11,100	
Sidewalks								
Concrete	100%			2040	**	5	\$9,600	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 30%</i>					
			<i>Location : North Side</i>					
			<i>Explanation : Under Construction</i>					
Wearing Surface								
Concrete	100%			2044	**	5	\$65,600	
Superstructure								
Deck, Structural								
Not Accessible	100%							
			<i>Other Observation, Extent : N/A, Area Affected : 0%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stay-in-place Forms</i>					
Primary Member								
Steel	100%			LIFE	**	2-8	\$385,700	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$19,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WHITELAW PEDESTRIAN BRIDGE NORTH & SOUTH CONDUIT AVENUE
Address : FROM ARION ROAD BET. WHITELAW STREET AND 149TH AVENUE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0268.000 / 15022 **Yr Built/Renovated** :
Area Sq Ft : 6,264 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 22-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2248020

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$441,000	\$621,200
Total	\$441,000	\$621,200
Importance Code A	\$278,800	\$621,200
Importance Code C	\$162,200	
Total	\$441,000	\$621,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$91,800		\$14,600	
Total	\$91,800		\$14,600	
Importance Code A	\$11,300		\$13,500	
Importance Code B	\$37,400		\$1,100	
Importance Code C	\$43,100			
Total	\$91,800		\$14,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WHITELAW PEDESTRIAN BRIDGE NORTH & SOUTH CONDUIT AVENUE
Asset # : 15022

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Granite	100%	4+	\$4,600	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast Abutment</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Southeast Abutment</i>								
Backwall								
Concrete	100%	4+	\$7,900	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Southeast Abutment</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Both Abutments</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : North Abutment</i>								
<i>Explanation : Brick Veneer Fascia On 50 Percent Of Area On Both Abutments. Light Scaling.</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE			**	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Both Abutments</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Pedestals								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On Both Abutments</i>								
Stem (breastwall)								
Concrete	100%	4+	\$3,400	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Both Abutments</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Southeast Abutment</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Brick Veneer Fascia</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Piles								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITELAW PEDESTRIAN BRIDGE NORTH & SOUTH CONDUIT AVENUE
Asset # : 15022

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Brick Veneer	100%	4+	\$62,700	LIFE			**	
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Base Of Wall At Southeast Ramp</i>								
<i>Missing Bricks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations On Northeast Wingwall</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Northeast Wingwall</i>								
<i>Explanation : Limited Access On 40 Percent Of Area. Vegetation Growth.</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Around Pier 2 And 3</i>								
<i>Explanation : Limited Access</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$99,500	2042			**	4 \$27,100
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations On Both Approaches</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations On Both Approaches</i>								
Curbs								
Concrete	100%			LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Northeast Approach</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Approach</i>								
<i>Explanation : Vegetation Growth</i>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITELAW PEDESTRIAN BRIDGE NORTH & SOUTH CONDUIT AVENUE
Asset # : 15022

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Concrete	100%	4+	\$34,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Piers 1 And 4 From South End</i>								
<i>Missing Bricks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Pier 1 From South End</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access On 50 Percent Of Area. Brick Veneer Fascia.</i>								
Brngs,Ancr Blts,Pads Steel	100%			LIFE		**	2-8	\$3,700
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Pier 2 And 3</i>								
<i>Explanation : Limited Access</i>								
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 70%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	3%	2-4	\$400	2053		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Misaligned/Bulging, Extent : Light, Area Affected : 1%</i>								
<i>Location : 1st Joint From South Pier</i>								
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : 1st Joint From South Pier</i>								
Concrete	97%			2053		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITELAW PEDESTRIAN BRIDGE NORTH & SOUTH CONDUIT AVENUE
Asset # : 15022

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets Steel	100%	4+	\$6,300	LIFE	**	2-8	\$22,200	
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i> <i>Location : Base Of Chain Link Fence Posts</i> <i>Loss of Section, Extent : Moderate, Area Affected : 15%</i> <i>Location : Base Of Chain Link Fence Posts</i> <i>Rust Stains, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Chain Link Fence Attached To Steel Railing</i>								
Wearing Surface Concrete	100%	2-4	\$29,700	2042	**	5	\$18,300	
<i>Cracks, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Delaminations, Extent : Light, Area Affected : 2%</i> <i>Location : Near South Abutment</i> <i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>								
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 2 Scuppers Observed</i>								
Superstructure								
Deck, Structural Concrete	3%	4+	\$278,800	LIFE	**	5	\$248,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Corrosion, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Limited Access On 70 Percent Of Area. Stay In Place Forms Between Girders. Wire Mesh Coverings.</i>								
Concrete	97%			LIFE	**	5	\$248,200	
Joints Generic	100%	2-4	\$5,500	LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i> <i>Location : 1st And 2nd Joint From South Pier</i> <i>Explanation : Joint Material Squeezed Out</i>								
Primary Member Steel	100%			LIFE	**	2-8	\$233,200	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
 WHITELAW PEDESTRIAN BRIDGE NORTH & SOUTH CONDUIT AVENUE
 Asset # : 15022**

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Secondary Member								
Steel	100%			LIFE		* *	2-8	\$17,800

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WOODHAVEN BLVD QUEENS BLVD
 Address : WOODHAVEN BLVD OVER QUEENS BLVD
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0281.000 / 15039 Yr Built/Renovated : 1940 /
 Area Sq Ft : 10,732 Project Type : HIGHWAY BRIDGES
 Date of Survey : 05-Jan-2024 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2248159

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$94,800	
Total	\$94,800	
Importance Code B	\$94,800	
Total	\$94,800	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$115,400		\$2,100	\$700
Total	\$115,400		\$2,100	\$700
Importance Code A	\$56,700			\$700
Importance Code C	\$58,800		\$2,100	
Total	\$115,400		\$2,100	\$700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WOODHAVEN BLVD QUEENS BLVD
Asset # : 15039

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : Buried By Asphalt Wearing Surface</i>						
Mat (scour & erosion) Generic	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Asphalt Roadway</i>						
Pedestals Not Accessible	100%							
Stem (breastwall) Masonry	100%			LIFE			**	
		<i>Efflorescence, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 80%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Limited Access</i>						
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Asphalt Roadway</i>						
Piles Not Accessible	100%							
Walls Masonry	100%			LIFE			**	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Moderate, Area Affected : 20%</i>						
		<i>Location : Random Locations Throughout</i>						
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WOODHAVEN BLVD QUEENS BLVD
Asset # : 15039

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Asphalt Roadway</i>							
Approaches								
Pavement								
Asphalt	20%	2-4	\$11,000	2036		**	4	\$4,100
	<i>Cracks, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Throughout</i>							
	<i>Other Observation, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : Rutting</i>							
Asphalt	80%			2036		**	4	\$4,100
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>							
	<i>Location : Southwest Approach</i>							
	<i>Rust Stains, Extent : Moderate, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	\$500
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>							
	<i>Location : Southwest Approach</i>							
Piers								
Stem,Solid Pier								
Concrete	100%	Now	\$94,800	LIFE		**		
	<i>Exposed Reinforcement, Extent : Severe, Area Affected : 1%</i>							
	<i>Location : Bottom Corner At North End</i>							
	<i>Spalling, Extent : Severe, Area Affected : 2%</i>							
	<i>Location : Bottom Corner At North End</i>							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WOODHAVEN BLVD QUEENS BLVD
Asset # : 15039

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion) Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Asphalt Roadway</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	Now	\$19,300	LIFE		**		
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 80%</i>								
<i>Location : Throughout Along Median And Both Sidewalks</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout Along Median And Both Sidewalks</i>								
<i>Spalling, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Along Steel Face On Both Sides</i>								
<hr/>								
Median								
Concrete	100%			LIFE		**	5	\$1,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Masonry	50%			2044		**	5	\$1,400
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations On South Parapet</i>								
Masonry	50%	Now	\$36,400	2050		**	5	\$700
<i>Damaged Railing, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout North Parapet</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout North Parapet</i>								
<i>Explanation : Temporary Barrier In Front Of Missing Barrier</i>								
<hr/>								
Sidewalks								
Concrete	100%	4+	\$8,900	2040		**	5	\$1,800
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Scaling</i>								
<hr/>								
Wearing Surface								
Asphalt	100%	Now	\$38,800	2036		**	5	\$6,000
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Severe, Area Affected : 15%</i>								
<i>Location : East Bound Turning Lane</i>								
<i>Explanation : Rutting</i>								
<hr/>								
Superstructure								
Deck, Structural								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WOODHAVEN BLVD QUEENS BLVD
Asset # : 15039

Bridge Structure		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Primary Member								
Not Accessible	100%							
<hr/>								
Secondary Member								
Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WOODHAVEN BOULEVARD OVER ATLANTIC AVENUE
Address : WOODHAVEN BLVD & ATLANTIC AVE BETWEEN 93RD AND 95TH STREETS
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0361.000 / 15375 **Yr Built/Renovated** :
Area Sq Ft : 19,462 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 13-Jul-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2248019

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$62,400	\$719,600
Total	\$62,400	\$719,600
Importance Code A		\$385,300
Importance Code B	\$62,400	
Importance Code C		\$334,300
Total	\$62,400	\$719,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$80,900		\$38,600	
Total	\$80,900		\$38,600	
Importance Code A	\$31,500		\$38,600	
Importance Code B	\$22,500			
Importance Code C	\$26,900			
Total	\$80,900		\$38,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WOODHAVEN BOULEVARD OVER ATLANTIC AVENUE

Asset # : 15375

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Masonry	100%	4+	\$21,200	LIFE			**	
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
<hr/>								
Backwall Concrete	100%	4+	\$15,500	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout With More Severe Near East Corner Of North Abutment.</i>								
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>								
<i>Location : Near East End Of North Abutment</i>								
<i>Settlement, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Near East End Of North Abutment</i>								
<hr/>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
<hr/>								
Footings Not Accessible	100%							
<hr/>								
Joint with Deck Generic	100%			LIFE			**	
<hr/>								
Mat (scour & erosion) Generic	100%			LIFE			**	
<hr/>								
Pedestals Not Accessible	100%							
<hr/>								
Stem (breastwall) Concrete	100%	4+	\$62,400	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout Both Abutments</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : On Both Abutments</i>								
<hr/>								
Masonry	100%	4+	\$9,900	LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Mortar Missing/ Eroded</i>								
<hr/>								
Wingwalls								
Footings Not Accessible	100%							
<hr/>								
Mat (scour & erosion) Generic	100%			LIFE			**	
<hr/>								
Piles Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WOODHAVEN BOULEVARD OVER ATLANTIC AVENUE

Asset # : 15375

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Masonry	100%			LIFE		**		
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Asphalt	100%	4+	\$3,100	2033	\$156,900	4	\$4,800	
		<i>Cracks, Extent : Light, Area Affected : 15%</i>						
		<i>Location : Random Locations Throughout</i>						
Curbs								
Concrete	100%			LIFE		**		
		<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$1,900	2041		**	4	\$900
		<i>Cracks, Extent : Light, Area Affected : 15%</i>						
		<i>Location : On Both Approaches</i>						
Masonry	100%			2041		**		
		<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Joint Mortar Missing/ Eroded</i>						
Piers								
Pier,Columns								
Masonry	100%			LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Efflorescence, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Spalling, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Top Of South Middle Pier</i>						
		<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Random Locations Throughout</i>						
		<i>Explanation : Joint Mortar Missing/ Eroded</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WOODHAVEN BOULEVARD OVER ATLANTIC AVENUE

Asset # : 15375

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE	**			
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete	4%	2-4	\$200	2052	**			
			<i>Cracks, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Concrete	96%			2052	**			
Median								
Concrete	100%			LIFE	**	5	\$3,100	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Steel Girder Acts As Median Barrier</i>					
Wearing Surface								
Asphalt	100%			2033	\$177,500	5		
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 10%</i>					
			<i>Location : Scattered Locations</i>					
			<i>Explanation : Bottom Covered With Stay In Place Forms</i>					
Joints								
Generic	100%	Now	\$8,300	LIFE	**			
			<i>Corrosion, Extent : Moderate, Area Affected : 40%</i>					
			<i>Location : Throughout</i>					
			<i>Other Observation, Extent : Severe, Area Affected : 10%</i>					
			<i>Location : Span 2 Near Center Pier</i>					
			<i>Explanation : Filler Material Squeezed Out</i>					
Primary Member								
Steel	2%	4+	\$8,300	LIFE	**	2-8	\$359,800	
			<i>Efflorescence, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout With Moderate Condition Near Piers</i>					
			<i>Loss of Section, Extent : Light, Area Affected : 1%</i>					
			<i>Location : West Girder Near Pier 2</i>					
Steel	98%			LIFE	**	2-8	\$359,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
WOODHAVEN BOULEVARD OVER ATLANTIC AVENUE**

Asset # : 15375

Bridge Structure		Current Repair		Future Replacement		Maintenance			
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Superstructure	Secondary Member								
	Concrete	100%	4+	\$12,600	LIFE		* *	5	\$7,900
<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout With Moderate Condition Near All Piers</i>									
<i>Efflorescence, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i>									
<i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i>									
<i>Other Observation, Extent : N/A, Area Affected : 2%</i> <i>Location : Scattered Locations</i> <i>Explanation : Covered With Steel Mesh</i>									

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WOODSIDE AVENUE LIRR MAIN LINE
Address : WOODSIDE AVE. BET 62ND STREET AND 65TH STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0269.000 / 15023 **Yr Built/Renovated** :
Area Sq Ft : 14,925 **Project Type** : HIGHWAY BRIDGES
Date of Survey : 28-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2247120

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$27,900		\$2,500	
Total	\$27,900		\$2,500	
Importance Code A	\$22,000			
Importance Code C	\$5,900		\$2,500	
Total	\$27,900		\$2,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WOODSIDE AVENUE LIRR MAIN LINE
Asset # : 15023

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : No Access To Railroad Property Underneath</i>						
Backwall Not Accessible	100%							
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Joint with Deck Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location :</i>						
		<i>Explanation : Covered By Asphalt Wearing Surface</i>						
Mat (scour & erosion) Not Accessible	100%							
Pedestals Not Accessible	100%							
Stem (breastwall) Not Accessible	100%							
Walls Not Accessible	100%							
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Not Accessible	100%							
Feature Crossed								
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Not Accessible	100%							
Approaches								
Pavement Asphalt	100%			2036	**	4	\$5,000	
		<i>Cracks, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
Curbs Concrete w/ Steel Face	100%			LIFE	**			
		<i>Rust Stains, Extent : Moderate, Area Affected : 60%</i>						
		<i>Location : Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WOODSIDE AVENUE LIRR MAIN LINE
Asset # : 15023

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%	4+	\$3,300	2044		**	4	\$1,500
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Southeast Approach</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Southeast Approach</i>					
			<i>Other Observation, Extent : Light, Area Affected : 20%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Scaling</i>					
Sidewalks								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout With Moderate Cases On Southwest Approach</i>					
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
			<i>Rust Stains, Extent : Moderate, Area Affected : 70%</i>					
			<i>Location : Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WOODSIDE AVENUE LIRR MAIN LINE
Asset # : 15023

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets Concrete	100%	Now	\$18,700	2044	**	4	\$6,200	
<i>Cracks, Extent : Moderate, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Moderate, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Moderate, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Moderate, Area Affected : 30%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Scaling</i>								
Sidewalks Concrete	100%			2040	**	5	\$9,200	
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Settlement, Extent : Light, Area Affected : 2%</i> <i>Location : Southeast Corner</i> <i>Vegetation Growth, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Along Curb And Parapet Base</i>								
Wearing Surface Asphalt	100%			2036	**	5	\$11,800	
Superstructure								
Deck, Structural Not Accessible	100%							
Primary Member Not Accessible	100%							
Secondary Member Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : 145TH STREET BRIDGE 145TH ST BRIDGE/HARLEM RIVER
Address : HARLEM RIVER, HARLEM RIV DR.
Borough : MANHATTAN:BX. **Agency's Number** : N/A
Program / Asset # : DOT0043.000 / 2468 **Yr Built/Renovated** : 1900 / 2007
Area Sq Ft : 56,732 **Project Type** : WATERWAY BRIDGES
Date of Survey : 05-Apr-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240089

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,005,100	\$1,047,800
Bridge Mechanical	\$792,900	
Total	\$1,798,000	\$1,047,800
Importance Code A		\$650,000
Importance Code B	\$861,000	\$397,800
Importance Code C	\$937,100	
Total	\$1,798,000	\$1,047,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$22,700		\$99,200	
Bridge Electrical	\$29,600	\$6,600	\$6,600	\$6,600
Bridge Mechanical	\$99,400	\$44,900	\$80,800	\$44,900
Total	\$151,700	\$51,500	\$186,700	\$51,500
Importance Code A			\$59,300	
Importance Code B	\$129,000	\$51,500	\$127,300	\$51,500
Importance Code C	\$22,700			
Total	\$151,700	\$51,500	\$186,700	\$51,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
145TH STREET BRIDGE 145TH ST BRIDGE/HARLEM RIVER
Asset # : 2468

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
Backwall Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : The Concrete Backwall Exhibits Vertical Cracks Up To 1/8" Wide In Bays 2, 4 And 5. Bay 5 Exhibits Leaching Efflorescence Also.</i>								
Brngs,Ancr Blts,Pads Elastomeric	100%			2058		**		
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%			LIFE		**		
Wingwalls								
Footings Not Accessible	100%							
Piles Not Accessible	100%							
Walls Granite	100%			LIFE		**		
Feature Crossed								
Bank Protection Concrete	100%	2-4	\$591,000	LIFE		**		
<i>Spalling, Extent : Severe, Area Affected : 25%</i>								
<i>Location : The Concrete Bulkhead Under Span 3 On The Right Side Is Spalled On Rotting Timber Cribbing.</i>								
Riprap	100%			LIFE		**		
Timber	100%			2040		**		
Mat (scour & erosion) Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
145TH STREET BRIDGE 145TH ST BRIDGE/HARLEM RIVER
Asset # : 2468

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Timber	10%	0-2	\$68,100	LIFE			**	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Piers 3 And 5 Right Side Dolphins</i>								
<i>Rotted, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Piers 3 And 5 Right Side Dolphins</i>								
<i>Split/Dry/Cracked, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Piers 3 And 5</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Piers 3 And 5</i>								
<i>Explanation : Exhibits Impact Damage To Dolphins.</i>								
Timber	90%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Pier 4</i>								
<i>Explanation : New Pier Protection.</i>								
Approaches								
Pavement								
Asphalt	100%	4+	\$346,100	2036		4	\$53,300	**
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Both Beginning And End Approaches.</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE				**
Guide Railing								
Steel	100%			LIFE		2-8		**
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE				**
Piers								
Cap Beam								
Concrete	100%			LIFE				**
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 6 And 7.</i>								
<i>Explanation : Concrete Cap Beam</i>								
Stem,Solid Pier								
Concrete	100%			LIFE				**
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 1 Through 3 And 5 Through 7.</i>								
<i>Explanation : Concrete Pier Stem</i>								
Granite	100%			LIFE				**
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Piers 3 And 5.</i>								
<i>Explanation : Granite Facade.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
145TH STREET BRIDGE 145TH ST BRIDGE/HARLEM RIVER
Asset # : 2468

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Brngs,Ancr Blts,Pads Elastomeric	100%			2058	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 1 Through 3 And 5 Through 7.</i>								
<i>Explanation : Elastomeric Bearings. For Spans 1 Through 3 And 6 Through 8.</i>								
Steel	100%			LIFE	**	2-8		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 3, 4, 5.</i>								
<i>Explanation : Steel Bearings. For Spans 4 And 5.</i>								
Footings Not Accessible	100%							
Pedestals Concrete	100%			LIFE	**			
Deck Elements								
Curbs Concrete w/ Steel Face	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 1 Through 3 And 6 Through 8.</i>								
<i>Explanation : Locations Noted.</i>								
Guide Railing Steel	100%			LIFE	**			
Railings/Parapets Steel	75%			LIFE	**	2-8	\$42,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 Through 3 And 6 Through 8.</i>								
<i>Explanation : Chain Link Fence Both Sides</i>								
Steel	25%			LIFE	**	2-8	\$42,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 4 And 5.</i>								
<i>Explanation : Chain Link Fence And Pedestrian Railing On Both Sides.</i>								
Sidewalks Concrete	100%			2040	**	5	\$29,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 Through 3 And 6 Through 8.</i>								
<i>Explanation : Location Noted.</i>								
Grating w/ Concrete	100%			2058	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 4 And 5.</i>								
<i>Explanation : Location Noted.</i>								
Wearing Surface Asphalt	100%			2036	**	5	\$45,500	
Scupper Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Beg. And End Appr. Have 8 Scuppers. Span 2 Has 2 Scuppers, Span 4 Has 4 Scuppers And Span 5 Has 4 Scuppers.</i>								
<i>Explanation : Scuppers Were Noted.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
145TH STREET BRIDGE 145TH ST BRIDGE/HARLEM RIVER
Asset # : 2468

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$60,700	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Spans 1, 3 And 6 Through 8.</i>								
<i>Explanation : Location Noted.</i>								
Grating w/ Concrete	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Spans 4 And 5.</i>								
<i>Explanation : Location Noted.</i>								
Joints								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Piers 3 And 5.</i>								
<i>Explanation : Location Noted.</i>								
Generic	100%			LIFE	**			
<i>Leakage, Extent : Light, Area Affected : 2%</i>								
<i>Location : Pier 3</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Piers 1, Through 3 And 5 Through 7.</i>								
<i>Explanation : Location Noted.</i>								
Primary Member								
Concrete	100%			LIFE	**	5		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Span 2.</i>								
<i>Explanation : Location Noted.</i>								
Steel	100%			LIFE	**	2-8	\$1,048,800	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Spans 1, 3 And 6 Through 8.</i>								
<i>Explanation : Location Noted.</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$622,400	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Spans 1, 3 And 6 Through 8.</i>								
<i>Explanation : Location Noted.</i>								
Movable Bridges								
Swing Span Truss								
Steel	100%			LIFE	**			
Swing Span Pivot Pier								
Concrete	100%			LIFE	**			

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Intercom								
Generic	100%			2031	\$17,100			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
145TH STREET BRIDGE 145TH ST BRIDGE/HARLEM RIVER
Asset # : 2468

Bridge Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Communication Electrical								
Telephone								
Desk Top	100%			2031				
Control System Electrical								
Computer								
PLC	100%	Now	\$8,800	2031	\$29,400			
		<i>Other Observation, Extent : Severe, Area Affected : 50%</i>						
		<i>Location : Machinery Room</i>						
		<i>Explanation : Uninterruptible Power Source For Programmable Logic Controller Power Has Failed And Is Bypassed.</i>						
		<i>Plc #2 Has Failed</i>						
Control Console								
Stainless Steel	100%			LIFE	**			
Control Devices								
Relay	100%			2049	**			
Disconnect Switch								
Non Fused	100%			2049	**	1	\$35,900	
Limit Switch								
Generic	100%			2049	**			
Local Starter								
Magnetic	100%			2049	**			
Drive								
Machinery Brake								
Thruster	100%			2058	**	1	\$600	
Motor Brake								
Thruster	100%			2058	**	1	\$1,100	
Electrical Power								
MCC								
Generic	100%			2049	**			
Panelboard								
Circuit Breaker	100%			2049	**	1	\$6,700	
Transfer Switch								
Auto	100%			2049	**			
Transformer								
Dry	100%			2049	**			
Ground/Lightning Protection								
Ground Bus								
Copper	100%			2036	**			
Ground Rod								
Not Accessible	100%							
Ground Wire								
Green	100%			2036	**			
Lightning Terminals								
Copper	100%			2031	\$1,600			
Raceway								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
145TH STREET BRIDGE 145TH ST BRIDGE/HARLEM RIVER
Asset # : 2468

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Raceway								
Box								
Terminal	95%			2042	**	1	\$4,500	
Terminal	5%	Now	\$100	2040	**	1	\$4,000	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Under Bronx Approach</i>								
<i>Explanation : Junction Box Containing Fuses Has Bent Cover And Does Not Close.</i>								
Collector Ring								
Metal	100%			2040	**			
Communications								
Twisted Shielded pair	100%			2031				
Conduit								
Metal	100%			2067	**			
Submarine Control Cables								
Control	100%			2036	**			
Submarine Power Cable								
Power	100%			2036	**			
Wires								
Thermoplastic	100%			2049	**			
Stand-by Power								
Transfer Switch								
Auto	100%			2049	**			
Lighting								
Lighting Devices								
Generic	17%	Now	\$400	2036	**			
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Center Pier</i>								
<i>Explanation : Incandescent Fender Lighting - 2 Lights Out</i>								
Generic	24%	Now	\$14,200	2036	**			
<i>Other Observation, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Various Throughout Bridge</i>								
<i>Explanation : Various Battery Backups For Emergency Lights Not Working Around Bridge</i>								
Generic	59%			2036	**			
Main Drive								
Motor Controller								
Thyristor Drive	100%			2040	**	1-5	\$15,900	

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Swing								
Center Latch								
Generic	100%	Now	\$197,200	2067	**	2	\$18,000	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Center Latches</i>								
<i>Explanation : No Operation Observed. West Lock Not Engaged. East Lock Not In All The Way. Adjustment And Repairs Are Required</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
145TH STREET BRIDGE 145TH ST BRIDGE/HARLEM RIVER
Asset # : 2468

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Swing								
Center Pivot Generic	100%	Now	\$94,100	2067	**	2	\$53,900	
<i>Corrosion, Extent : Light, Area Affected : 100%</i> <i>Location : Center Pivot Rim Bearing Assembly.</i> <i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Center Pivot Rim Bearing Assembly</i> <i>Explanation : Water Collecting In Two Of The Track Pockets. Pier Drains Clogged.</i>								
Emergency Drive Emergency Power	100%	2-4	\$9,800	2067	**	2	\$35,900	
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Hydraulic Power Unit</i> <i>Explanation : Could Not Test. Some Old Fluid At The Bottom Of The Containment</i>								
End Lift Generic	100%	Now	\$30,100	2067	**	2	\$35,900	
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : End Lift</i> <i>Explanation : No Operation Observed. Minor Oil Leakage. Some Covers Removed</i>								
Fuel Tanks Generic	100%	Now	\$900	2049	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Hydraulic Power Unit</i> <i>Explanation : One Tank Cap Appeared To Be Damaged, Repaired With Tape And Should Be Replaced.</i>								
Houses Control House	100%	Now	\$279,000	2067	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Control Room, Bathroom And Approach Houses</i> <i>Explanation : No Running Water. Floors And Walls Are Damaged. Some Window Covers Not Functioning. Some Door And Hatch Repair Required. Fire Alarm Maintenance Required.</i>								
Main Drive System Generic	50%	Now	\$42,400	2067	**	2	\$179,600	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i> <i>Location : Cover Bolts Missing At Drive Machinery</i> <i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Drive Machinery</i> <i>Explanation : Some Bolts Require Paint. Secondary Reducers Do Not Have Sight Gauge. No Operation Observed. Slight Leakage And Loose Protective Covers.</i>								
Generic	50%			2067	**	2	\$224,500	
Structural Bearings Generic	100%	Now	\$16,300	2045	**			
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : End Lift Roller Bearing Plates</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
145TH STREET BRIDGE 145TH ST BRIDGE/HARLEM RIVER

Asset # : 2468

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Swing								
Traffic Devices								
Barrier Gate	100%	Now	\$106,900	2045		* *		
<i>Other Observation, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Barrier Gates</i>								
<i>Explanation : No Operation Observed. One Door Damaged. Maintenance Required.</i>								
Warning Gate	100%	Now	\$115,700	2045		* *		
<i>Other Observation, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Warning Gates</i>								
<i>Explanation : No Operation Observed. Gate Arm Bent. Maintenance Required.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT PARKWAY EAST BOUND OVER PAERDEGAT BASIN
Address : BELT SHORE PARKWAY
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0023.020 / 14776 **Yr Built/Renovated** : 2011 /
Area Sq Ft : 81,644 **Project Type** : WATERWAY BRIDGES
Date of Survey : 06-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231482

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$7,249,600	\$7,249,600
Total	\$7,249,600	\$7,249,600
Importance Code A	\$6,847,400	\$6,847,400
Importance Code B	\$402,200	\$402,200
Total	\$7,249,600	\$7,249,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$2,327,100		\$734,600	
Total	\$2,327,100		\$734,600	
Importance Code A	\$2,253,900		\$684,300	
Importance Code B	\$73,200		\$40,300	
Importance Code C			\$9,900	
Total	\$2,327,100		\$734,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY EAST BOUND OVER PAERDEGAT BASIN

Asset # : 14776

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2063		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Debris Buildup</i>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Walls								
Concrete	100%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE		**		
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Earth And Geogrid On Earth</i>								
Mat (scour & erosion)								
Stream Bed	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY EAST BOUND OVER PAERDEGAT BASIN

Asset # : 14776

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Feature Crossed								
Pier Protection								
Wood	100%			2044	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Of Piers Are Not Protected. Note That The Actual Pier Protection Material Is Rubber.</i>								
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$19,800	
Embankment								
Earth	100%			LIFE	**			
Guide Railing								
Concrete	100%			2044	**	4	\$2,200	
Steel	100%			LIFE	**	2-8	\$3,500	
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : North Side</i>								
<i>Explanation : Concrete With Steel Railing</i>								
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
Pier,Columns								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2063	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Middle Piers</i>								
<i>Explanation : Piers In Water Are Not Accessible</i>								
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY EAST BOUND OVER PAERDEGAT BASIN

Asset # : 14776

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Guide Railing Concrete	100%			2048	**			
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Steel	100%			LIFE	**			
Railings/Parapets								
Concrete	100%			2044	**	4	\$18,800	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : North Side</i>						
		<i>Explanation : Concrete With Steel Railing</i>						
Steel	100%			LIFE	**	2-8	\$42,000	
Sidewalks								
Concrete	100%			2040	**	5	\$29,200	
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Wearing Surface								
Concrete	100%			2044	**	5		
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$287,800	
		<i>Corrosion, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout On Stay In Place Forms</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Stay In Place Forms</i>						
Primary Member								
Steel	100%			LIFE	**	2-8	\$21,460,600	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$1,104,700	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELT PARKWAY WEST BOUND OVER PAERDEGAT BASIN
Address : BELT SHORE PARKWAY
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0023.010 / 14775 **Yr Built/Renovated** : 2011 /
Area Sq Ft : 47,361 **Project Type** : WATERWAY BRIDGES
Date of Survey : 06-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231481

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$4,668,100	\$4,668,100
Total	\$4,668,100	\$4,668,100
Importance Code A	\$4,408,300	\$4,408,300
Importance Code B	\$259,800	\$259,800
Total	\$4,668,100	\$4,668,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$1,514,000		\$490,500	
Total	\$1,514,000		\$490,500	
Importance Code A	\$1,466,700		\$449,900	
Importance Code B	\$47,300		\$26,100	
Importance Code C			\$14,600	
Total	\$1,514,000		\$490,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY WEST BOUND OVER PAERDEGAT BASIN

Asset # : 14775

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2063		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	100%			LIFE		**		
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Walls								
Concrete	100%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Feature Crossed								
Bank Protection								
Generic	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Earth And Geogrid On Earth</i>					
Mat (scour & erosion)								
Stream Bed	100%			LIFE		**		
Pier Protection								
Wood	100%			2044		**		
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : The Actual Pier Protection Material Is Rubber</i>					
Approaches								
Pavement								
Concrete	100%			2044	**	4	\$29,100	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELT PARKWAY WEST BOUND OVER PAERDEGAT BASIN

Asset # : 14775

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Embankment								
Earth	100%			LIFE	**			
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$3,000	
Steel	100%			LIFE	**			
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
Pier,Columns								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2063	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2044	**	4	\$25,700	
			<i>Cracks, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
Steel	100%			LIFE	**	2-8	\$57,400	
Wearing Surface								
Concrete	100%			2044	**	5		
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$156,500	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Stay In Place Forms</i>					
Primary Member								
Steel	100%			LIFE	**	2-8	\$13,862,200	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$713,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BELTSHORE PARKWAY BELT SHORE PKWY/FRESH CREEK
Address : BELT SHORE PKWY AT FRESH CREEK
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0134.000 / 4214 **Yr Built/Renovated** : 1931 / 2013
Area Sq Ft : 23,021 **Project Type** : WATERWAY BRIDGES
Date of Survey : 06-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231509

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$479,700	\$479,700
Total	\$479,700	\$479,700
Importance Code A	\$209,000	\$209,000
Importance Code B	\$209,000	\$209,000
Importance Code C	\$61,700	\$61,700
Total	\$479,700	\$479,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$170,300		\$62,200	
Total	\$170,300		\$62,200	
Importance Code A	\$132,300		\$26,200	
Importance Code B	\$38,100		\$21,000	
Importance Code C			\$15,000	
Total	\$170,300		\$62,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BELTSORE PARKWAY BELT SHORE PKWY/FRESH CREEK

Asset # : 4214

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE	**			
Backwall Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads Elastomeric	100%			2055	**			
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE	**			
		<i>Missing/Damaged Seal, Extent : Light, Area Affected : 35%</i>						
		<i>Location : Random Locations Throughout</i>						
Mat (scour & erosion) Riprap	100%			LIFE	**			
Pedestals Concrete	100%			LIFE	**			
Stem (breastwall) Concrete	100%			LIFE	**			
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE	**			
Riprap	100%			LIFE	**			
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Feature Crossed								
Bank Protection Riprap	100%			LIFE	**			
Mat (scour & erosion) Stream Bed	100%			LIFE	**			
Pier Protection Timber	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Timber Fenders</i>						
Approaches								
Pavement Concrete	100%			2044	**	4	\$30,100	
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Along Center Line And Random Transverse</i>						
Embankment Earth	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELTSORE PARKWAY BELT SHORE PKWY/FRESH CREEK

Asset # : 4214

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Guide Railing								
Concrete	100%			2044	**	4	\$2,800	
Steel	100%			LIFE	**	2-8	\$8,400	
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE	**	5	\$2,200	
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044	**	4	\$1,500	
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Random Locations Throughout</i>						
Scupper								
Cast Iron	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 4 Scuppers</i>						
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Metal Catwalk On Each Side</i>						
Pier,Columns								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
		<i>Other Observation, Extent : N/A, Area Affected : 0%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Stream Bed</i>						
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BELTSORE PARKWAY BELT SHORE PKWY/FRESH CREEK

Asset # : 4214

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Guide Railing Concrete	100%			2048	**			
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Steel	100%			LIFE	**			
Median								
Concrete	100%			LIFE	**	5	\$7,200	
Railings/Parapets								
Concrete	100%			2044	**	4	\$4,900	
Steel	100%			LIFE	**	2-8	\$21,900	
Sidewalks								
Concrete	100%			2040	**	5	\$8,800	
	<i>Cracks, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Wearing Surface								
Concrete	100%			2044	**	5	\$123,300	
	<i>Cracks, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Scupper								
Cast Iron	100%			LIFE	**			
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Explanation : 4 Total</i>							
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$92,600	
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Stay In Place Forms</i>							
Primary Member								
Steel	100%			LIFE	**	2-8	\$669,200	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$574,200	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : **BROADWAY BRIDGE BROADWAY BRIDGE/HARLEM RIVER**
 Address : **HARLEM RIVER, B'WAY**
 Borough : **MANHATTAN** Agency's Number : **N/A**
 Program / Asset # : **DOT0044.070 / 2558** Yr Built/Renovated :
 Area Sq Ft : **38,100** Project Type : **WATERWAY BRIDGES**
 Date of Survey : **28-May-2014** Landmark Status : **NONE**
 Areas Surveyed :
 Block : Lot : BIN : **2240137**

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$4,304,100	\$2,957,800
Bridge Electrical	\$9,625,600	\$1,975,300
Bridge Mechanical	\$9,341,400	
Total	\$23,271,100	\$4,933,100
Importance Code A	\$4,058,600	\$753,500
Importance Code B	\$18,967,100	\$2,728,800
Importance Code C	\$245,500	\$1,450,900
Total	\$23,271,100	\$4,933,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$39,400		\$152,600	\$42,000
Bridge Electrical	\$144,300			
Bridge Mechanical	\$81,500			
Total	\$265,200		\$152,600	\$42,000
Importance Code A	\$200		\$77,000	
Importance Code B	\$233,100		\$75,600	
Importance Code C	\$31,900			\$42,000
Total	\$265,200		\$152,600	\$42,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BROADWAY BRIDGE BROADWAY BRIDGE/HARLEM RIVER
Asset # : 2558

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 100%</i> <i>Location : North Abutment - MTA Track. South Abutment - Fenced Off Area.</i> <i>Explanation : North Abutment - MTA Track. South Abutment - Fenced Off Area.</i>								
Backwall								
Granite	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : Begin Abutment</i> <i>Explanation : Begin Abutment</i>								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : North Abutment - Mta Track.</i> <i>Explanation : North Abutment - Mta Track.</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : North Abutment - MTA Track. South Abutment - Fenced Off Area.</i> <i>Explanation : North Abutment - MTA Track. South Abutment - Fenced Off Area.</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Steel	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : End Abutment</i> <i>Explanation : End Abutment</i>								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : Begin Abutment</i> <i>Explanation : Begin Abutment</i>								
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Pedestals								
Concrete	90%			LIFE			**	
Concrete	10%	2-4	\$200	LIFE			**	
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 20%</i> <i>Location : End Abutment Center Pedestal</i> <i>Spalling, Extent : Moderate, Area Affected : 2%</i> <i>Location : End Abutment Center Pedestal</i>								
Stem (breastwall)								
Concrete	100%			LIFE			**	
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BROADWAY BRIDGE BROADWAY BRIDGE/HARLEM RIVER
Asset # : 2558

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Walls								
Concrete	100%	2-4	\$167,300	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Begin And End Abutments</i>								
<i>Settlement, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Begin Abutment Left Side.</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Begin And End Abutments</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 20%</i>								
<i>Location : Begin Abutment</i>								
Feature Crossed								
Bank Protection								
Concrete	100%	4+	\$7,000	LIFE			**	
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : North Bank</i>								
Riprap	75%			LIFE			**	
Riprap	25%	0-2	\$8,000	LIFE			**	
<i>Erosion, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Missing Riprap Causing Erosion Of Earth Near Begin Abutment</i>								
Timber	100%			2030				
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	80%			LIFE			**	
Timber	20%	4+	\$7,300	LIFE			**	
<i>Rotted, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Piers 1 And 2 Top Of Dolphin Piles.</i>								
Approaches								
Pavement								
Asphalt	100%			2030	\$392,200	4	\$18,100	
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
Embankment								
Earth	100%			LIFE			**	
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Sidewalks								
Concrete	100%			LIFE			**	
Piers								
Footings								
Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location : Piers 1 And 2.</i>								
<i>Explanation : Piers 1 And 2.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BROADWAY BRIDGE BROADWAY BRIDGE/HARLEM RIVER
Asset # : 2558

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Piers 1 And 2.</i>								
<i>Explanation : Piers 1 And 2.</i>								
Deck Elements								
Curbs								
Steel	100%			LIFE		**		
Gratings								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 2</i>								
<i>Explanation : Grating On Sidewalk Between Truss Members</i>								
Median								
Steel	100%			LIFE		**	4-8	\$41,200
Mono Deck Surface								
Concrete	90%			2045		**	5	\$186,000
Concrete	10%	4+	\$7,700	2045		**	5	\$93,000
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Spans 1 And 3</i>								
Railings/Parapets								
Steel	33%			LIFE		**	2-8	\$20,700
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 2</i>								
<i>Explanation : Steel Railing And High Fence On Each Side.</i>								
Steel	67%			LIFE		**	2-8	\$20,700
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 1 And 3</i>								
<i>Explanation : Steel Railing On Each Side.</i>								
Sidewalks								
Grating w/ Concrete	100%			2045		**		
Wearing Surface								
Concrete	90%			2034	\$571,000		5	\$84,100
Concrete	10%	4+	\$3,200	2034	\$63,400		5	\$42,000
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Spans 1 And 3</i>								
Steel Grating	90%			LIFE		**	5	\$72,600
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 2</i>								
<i>Explanation : Span 2</i>								
Steel Grating	10%	Now	\$78,200	LIFE		**	5	\$72,600
<i>Broken, Missing Pave, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Pier 2</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BROADWAY BRIDGE BROADWAY BRIDGE/HARLEM RIVER
Asset # : 2558

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$15,300	
Joints								
Steel	100%			LIFE	**			
		<i>Other Observation, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Pier 2</i>						
		<i>Explanation : Pier 2</i>						
Steel Finger Joints	100%			2053	**			
		<i>Other Observation, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Pier 1</i>						
		<i>Explanation : Pier 1</i>						
Primary Member								
Steel	90%			LIFE	**	2-8	\$703,700	
Steel	10%	4+	\$186,000	LIFE	**	2-8	\$703,700	
		<i>Corrosion, Extent : Moderate, Area Affected : 20%</i>						
		<i>Location : Spans 1 And 3 Stringers Below The Joints At Abutments And Piers.</i>						
		<i>Loss of Section, Extent : Moderate, Area Affected : 50%</i>						
		<i>Location : Spans 1 And 3 Stringers Below The Joints At Abutments And Piers.</i>						
Secondary Member								
Steel	100%			LIFE	**	2-8	\$1,178,900	
Movable Bridges								
Vertical Lift Span								
Steel	85%			LIFE	**			
Steel	10%	2-4	\$1,288,700	LIFE	**			
		<i>Other Observation, Extent : Severe, Area Affected : 15%</i>						
		<i>Location : Span 2</i>						
		<i>Explanation : Random Areas Of Corrosion And Section Loss</i>						
Steel	5%	Now	\$1,288,700	LIFE	**			
		<i>Other Observation, Extent : Severe, Area Affected : 15%</i>						
		<i>Location : Span 2</i>						
		<i>Explanation : Span 2 Has 17 Flagged Locations.</i>						
Vertical Lift Tower								
Steel	100%			LIFE	**			
Vertical Lift Pier								
Concrete	80%			LIFE	**			
Concrete	20%	4+	\$1,295,100	LIFE	**			
		<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>						
		<i>Location : Piers 1 And 2 Cap Beams</i>						
		<i>Explanation : Cracks And Spalls</i>						
Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BROADWAY BRIDGE BROADWAY BRIDGE/HARLEM RIVER
Asset # : 2558

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Communications								
Generic	100%	Now	\$41,100	2026	\$41,100			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Entire Bridge</i>								
<i>Explanation : 100% System Obsolete And Inoperative.</i>								
<hr/>								
Control System Electrical								
Control Console								
Stainless Steel	100%	Now	\$21,800	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Bridge Override Switches</i>								
<i>Explanation : Key Covers To Override Switches Missing. Some Indication Lights Not Functioning</i>								
<hr/>								
Disconnect Switch								
Generic	100%			2026	\$81,900			
<hr/>								
Limit Switch								
Generic	100%			2026	\$151,300			
<hr/>								
Electrical Power								
Dist Equip & Motor Controll								
Generic	100%	Now	\$854,600	2026	\$4,272,900			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Motor Control Center</i>								
<i>Explanation : Bridge Not Operable Due To Control System Issues.</i>								
<hr/>								
Raceway								
Submarine Control Cables								
Generic	100%	2-4	\$1,975,300	2030	\$1,975,300			
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Submarine Cable Cabinets</i>								
<i>Explanation : No Spares Remaining. Conductors Fail Randomly.</i>								
<hr/>								
Wiring								
Generic	100%			2026	\$1,903,600			
<hr/>								
Traffic System Electrical								
Traffic Signal								
Generic	100%	Now	\$40,300	2026	\$201,700			
<i>Other Observation, Extent : Light, Area Affected : 75%</i>								
<i>Location : All</i>								
<i>Explanation : Underground Conduit Damaged Gongs Not Operational.</i>								
<hr/>								
Lighting								
Lighting Devices								
Generic	100%	Now	\$61,400	2029	\$122,800			
<i>Other Observation, Extent : Light, Area Affected : 30%</i>								
<i>Location : West Light Fixture</i>								
<i>Explanation : The Entire Span Lighting Fixture Is Missing.</i>								

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Vertical Lift

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BROADWAY BRIDGE BROADWAY BRIDGE/HARLEM RIVER
Asset # : 2558

Bridge Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Vertical Lift								
Buffers								
Generic	100%	Now	\$38,100	2028	\$381,000			
	<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Air Buffers</i>							
	<i>Explanation : Some Broken Fittings, One Upper Buffer Is Stuck In Up Position. Upper Buffers Appear To Have Not Worked In Some Time</i>							
Counter Weight Ropes & Gui								
Generic	100%	Now	\$98,900	2040		**		
	<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>							
	<i>Location : Ropes And Guides.</i>							
	<i>Explanation : No Operation Observed. North Span Guide Rails Bent. Pigeon Droppings And Accumulated Debris.</i>							
Counter Weight								
Auxiliary CTRWT	100%			2040		**		
Main CTRWT	100%	0-2	\$97,000	2040		**		
	<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>							
	<i>Location : Tops Of Counterweight</i>							
	<i>Explanation : North Tower Not Accessible. Top Of South Tower Has Some Coverage Of Pigeon Droppings And Debris.</i>							
Elevators								
Generic	100%	Now	\$334,600	2028	\$669,100			
	<i>Other Observation, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : North And South Elevators.</i>							
	<i>Explanation : Both Elevators Are Not Operational.</i>							
Emergency Drive								
Emergency Power	100%			2040		**		
	<i>Other Observation, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Emergency Power</i>							
	<i>Explanation : No Operation Observed.</i>							
End Locks								
With Motor	100%	Now	\$106,100	2040		**		
	<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>							
	<i>Location : Span Locks</i>							
	<i>Explanation : S E Motor Coupling Not Aligned, Damaged Seals, Missing Shaft End Covers, Corroded Bolts And Motor Feet, Adj Required</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
BROADWAY BRIDGE BROADWAY BRIDGE/HARLEM RIVER
Asset # : 2558

Bridge Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Vertical Lift								
Houses								
Access Ways	100%	Now	\$75,700	2028	\$756,800			
<i>Other Observation, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : All Areas</i>								
<i>Explanation : Access Ways Are Covered In Pigeon Droppings.</i>								
Control House	100%	Now	\$53,300	2028	\$1,065,800			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Control House</i>								
<i>Explanation : Plumbing Not Working. Broken Window.</i>								
Machinery Room	100%	Now	\$185,300	2040		**		
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : South Machine Room, North Machine Room Not Accessible</i>								
<i>Explanation : South Machine Room - Broken Window And Corner Room Covered In Pigeon Droppings. North Tower Not Accessible</i>								
Main Drive System								
Generic	100%	Now	\$918,000	2040		**		
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : South Machine Room, North Not Accessible</i>								
<i>Explanation : Not Operational. South Tower Sheave Rooms Covered In Pigeon Droppings And One Motor Brake Is Not Functioning.</i>								
Sheaves								
Generic	100%	4+	\$1,051,300	2040		**		
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : South Machine Room, North Not Accessible</i>								
<i>Explanation : Sheave Rooms Covered In Pigeon Droppings. No Operation Observed. Check During Operation</i>								
Structural Bearings								
Generic	100%	Now	\$43,400	2028	\$216,800			
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Southwest</i>								
<i>Explanation : Movement At Live Load Support Under Traffic Loading.</i>								
Traffic Devices								
Barrier Gate	100%	Now	\$965,800	2028	\$1,931,600			
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Barrier Gates</i>								
<i>Explanation : South Net Requires Adjustment. North Gate Net Missing. Repairs Required</i>								
Warning Gate	100%	Now	\$434,500	2040		**		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Warning Gates</i>								
<i>Explanation : All Gates Are Not Functioning, Crash Trucks Are Used Instead. Some Pedestrian Arm Missing.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BROADWAY BRIDGE NYCTA IRT/HARLEM RIVER
Address : HARLEM RIVER, B'WAY
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0044.080 / 2559 **Yr Built/Renovated** :
Area Sq Ft : 38,100 **Project Type** : WATERWAY BRIDGES
Date of Survey : 04-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240138

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$753,500
Total		\$753,500
Importance Code A		\$376,700
Importance Code B		\$376,700
Total		\$753,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure			\$76,300	
Total			\$76,300	
Importance Code A			\$38,500	
Importance Code B			\$37,800	
Total			\$76,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
BROADWAY BRIDGE NYCTA IRT/HARLEM RIVER**

Asset # : 2559

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Safety Fence</i>								
<hr/>								
Sidewalks Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Adjacent To Both Tracks Throughout</i>								
<i>Explanation : Component Is Actually Fiberglass Safety Walk</i>								
<hr/>								
Deck Elements								
Railings/Parapets Steel	100%			LIFE		**	2-8	\$21,200
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Safety Steel Fence</i>								
<hr/>								
Sidewalks Fiberglass	100%			2038		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides Of The Tracks</i>								
<i>Explanation : Catwalk</i>								
<hr/>								
Superstructure								
Deck, Structural Steel	100%			LIFE		**	2-8	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Subway Track</i>								
<hr/>								
Timber	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railroad Timber Ties</i>								
<hr/>								
Primary Member Steel	100%			LIFE		**	2-8	\$703,700
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
<hr/>								
Secondary Member Steel	100%			LIFE		**	2-8	\$589,500
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
BROADWAY BRIDGE NYCTA IRT/HARLEM RIVER**

Asset # : 2559

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost

Superstructure

Vertical Lift Tower

Steel

100%

LIFE

* *

Other Observation, Extent : N/A, Area Affected : 100%

Location : Throughout

Explanation : Sits On Moveable Bridge - Asset 2558

*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CITY ISLAND BRIDGE CITY ISLAND ROAD/EASTCHESTER BAY
Address : EASTCHESTER BAY, CITY ISL RD.
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0046.000 / 2470 **Yr Built/Renovated** : 2017 /
Area Sq Ft : 29,019 **Project Type** : WATERWAY BRIDGES
Date of Survey : 16-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240210

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$345,400
Total		\$345,400
Importance Code A		\$287,200
Importance Code C		\$58,100
Total		\$345,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$47,800		\$38,800	
Total	\$47,800		\$38,800	
Importance Code A			\$29,700	
Importance Code C	\$47,800		\$9,100	
Total	\$47,800		\$38,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
CITY ISLAND BRIDGE CITY ISLAND ROAD/EASTCHESTER BAY
Asset # : 2470

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Riprap	100%			LIFE		**		
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Riprap	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Masonry	100%			LIFE		**		
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE		**		
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pier Protection								
Timber	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%			2042		**	4	
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Embankment								
Processed Stone	100%			LIFE		**		
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CITY ISLAND BRIDGE CITY ISLAND ROAD/EASTCHESTER BAY

Asset # : 2470

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
Pier,Columns								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$24,200
Sidewalks								
Concrete	100%			2038		**	5	\$18,200
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Wearing Surface								
Concrete	100%	4+	\$47,800	2042		**	5	\$58,100
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East End</i>								
<i>Explanation : Two Scuppers</i>								
Superstructure								
Deck,Structural								
Not Accessible	100%							
Primary Member								
Steel	100%			LIFE		**	2-8	\$536,500
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EASTCHESTER BRIDGE BOSTON ROAD/HUTCHINSON RIVER
Address : BOSTON RD X-ING HUTCH RIVER
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0015.090 / 4317 **Yr Built/Renovated** : 1965 /
Area Sq Ft : 95,683 **Project Type** : WATERWAY BRIDGES
Date of Survey : 11-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2229579

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$11,333,000	\$4,019,900
Total	\$11,333,000	\$4,019,900
Importance Code A	\$9,061,300	\$2,125,800
Importance Code B	\$1,733,800	\$1,894,100
Importance Code C	\$537,900	
Total	\$11,333,000	\$4,019,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$749,600		\$434,000	\$23,000
Total	\$749,600		\$434,000	\$23,000
Importance Code A	\$438,300		\$193,100	
Importance Code B	\$221,200		\$190,000	
Importance Code C	\$90,000		\$51,000	\$23,000
Total	\$749,600		\$434,000	\$23,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTCHESTER BRIDGE BOSTON ROAD/HUTCHINSON RIVER

Asset # : 4317

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	93%			LIFE				**
Concrete	7%	4+	\$1,200	LIFE				**
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Northern Abutment</i>								
<i>Explanation : Debris On Seat</i>								
<hr/>								
Backwall								
Concrete	50%			LIFE				**
Concrete	50%	2-4	\$15,000	LIFE				**
<i>Cracks, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Brngs,Ancr Blts,Pads								
Steel	80%			LIFE				**
Steel	20%	4+	\$32,900	LIFE				**
<i>Corrosion, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout, Mostly At Ends</i>								
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Joint with Deck								
Generic	78%			LIFE				**
Generic	22%	4+	\$2,400	LIFE				**
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Joint Filler Depressed</i>								
<hr/>								
Mat (scour & erosion)								
Earth	100%			LIFE				**
<hr/>								
Pedestals								
Concrete	100%			LIFE				**
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout And North Abutment</i>								
<i>Rust Stains, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Stem (breastwall)								
Concrete	60%			LIFE				**
Concrete	40%	4+	\$35,300	LIFE				**
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Wingwalls								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTCHESTER BRIDGE BOSTON ROAD/HUTCHINSON RIVER

Asset # : 4317

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Piles								
Not Accessible	100%							
Walls								
Concrete	85%			LIFE			**	
Concrete	15%	4+	\$50,600	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 40%</i> <i>Location : Random Locations Throughout</i> <i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i> <i>Location : Southeast Wingwall</i> <i>Spalling, Extent : Light, Area Affected : 30%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Paint Peeling</i>								
Feature Crossed								
Bank Protection								
Sheet Piling	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Both Embankments</i> <i>Explanation : Timber Rub Rail Is On The Face Of The Sheet Piling</i>								
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Asphalt	80%			2036		**	4	\$21,800
Asphalt	20%	2-4	\$38,500	2036		**	4	\$21,800
<i>Cracks, Extent : Moderate, Area Affected : 50%</i> <i>Location : Random Locations Throughout</i>								
Concrete	85%			2044		**	4	\$80,200
Concrete	15%	2-4	\$111,800	2044		**	4	\$80,200
<i>Settlement, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 40%</i> <i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 25%</i> <i>Location : At Surface</i> <i>Rust Stains, Extent : Severe, Area Affected : 75%</i> <i>Location : At Surface</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTCHESTER BRIDGE BOSTON ROAD/HUTCHINSON RIVER

Asset # : 4317

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Roadway</i>								
<hr/>								
Median								
Concrete	90%			LIFE		**	\$11,900	
Concrete	10%	4+	\$3,900	LIFE		**	\$5,900	
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : At Surface</i>								
Steel	10%			LIFE		**		
Steel	90%	Now	\$680,500	LIFE		**		
<i>Loss of Section, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling And Rust Stains</i>								
<hr/>								
Pavement Base								
Not Accessible	100%							
<hr/>								
Railings/Parapets								
Steel	90%			LIFE		**		
Steel	10%	4+	\$4,000	LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 50%</i>								
<i>Location : At Surface</i>								
<hr/>								
Sidewalks								
Concrete	85%			LIFE		**		
Concrete	15%	4+	\$15,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 70%</i>								
<i>Location : At Surface</i>								
<i>Settlement, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 70%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTCHESTER BRIDGE BOSTON ROAD/HUTCHINSON RIVER

Asset # : 4317

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam								
Concrete	65%			LIFE				**
Concrete	35%	4+	\$1,495,100	LIFE				**
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : At Surface</i>								
<i>Other Observation, Extent : N/A, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Steel Wire Mesh Placed At Spalls Areas</i>								
<hr/>								
Pier, Columns								
Concrete	75%			LIFE				**
Concrete	25%	2-4	\$659,900	LIFE				**
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : At Surface</i>								
<i>Delaminations, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 1%</i>								
<i>Location : Northern Most Pier On East Side</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
<hr/>								
Brngs, Ancr Blts, Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Earth	100%			LIFE				**
<hr/>								
Pedestals								
Concrete	95%			LIFE				**
Concrete	5%	4+	\$11,100	LIFE				**
<i>Cracks, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTCHESTER BRIDGE BOSTON ROAD/HUTCHINSON RIVER

Asset # : 4317

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 75%</i>								
<i>Location : At Surface</i>								
Median								
Concrete	90%			LIFE		**	5	\$30,300
Concrete	10%	4+	\$9,900	LIFE		**	5	\$15,100
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : At Surface</i>								
Steel	10%			LIFE		**	4-8	\$195,900
Steel	90%	Now	\$1,733,700	LIFE		**	4-8	\$122,600
<i>Loss of Section, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling And Rust Stain</i>								
Railings/Parapets								
Steel	100%	4+	\$78,400	LIFE		**	2-8	\$86,700
<i>Corrosion, Extent : Light, Area Affected : 50%</i>								
<i>Location : At Surface</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Impact Damage</i>								
Sidewalks								
Concrete	100%	4+	\$279,900	2040		**	5	\$17,100
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : At Surface</i>								
Wearing Surface								
Concrete	78%			2044		**	5	\$46,000
Concrete	22%	4+	\$20,800	2044		**	5	\$23,000
<i>Cracks, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Drains Clogged, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 18 Scuppers</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTCHESTER BRIDGE BOSTON ROAD/HUTCHINSON RIVER

Asset # : 4317

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Concrete	1%	Now	\$147,700	LIFE	**	5	\$77,800	
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 100%</i> <i>Location : Underneath East Sidewalk Stay In Place Forms</i> <i>Spalling, Extent : Severe, Area Affected : 100%</i> <i>Location : Underneath East Sidewalk Stay In Place Forms</i> <i>Other Observation, Extent : Light, Area Affected : 100%</i> <i>Location : Underside Of Deck</i> <i>Explanation : Stay In Place Forms Throughout The Underside Of The Deck</i>								
Concrete	99%	4+	\$3,654,600	LIFE	**	5	\$77,800	
<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Corrosion, Extent : Light, Area Affected : 10%</i> <i>Location : Stay In Place Form Under Deck Primarily Along Sidewalk And Fascia Throughout</i> <i>Efflorescence, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Underside Of Deck</i> <i>Explanation : Stay In Place Forms Throughout The Underside Of The Deck</i>								
Joints								
Generic	8%	Now	\$44,500	LIFE	**			
<i>Misaligned/Bulging, Extent : Severe, Area Affected : 100%</i> <i>Location : Northern Most Joint On Northbound Side And Southwest Joint, 1st Pier From South End</i>								
Generic	92%	2-4	\$51,200	LIFE	**			
<i>Loose Elements, Extent : Moderate, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Joint Filler Depressed And Filled With Debris</i>								
Primary Member								
Steel	95%			LIFE	**	2-8	\$3,031,800	
<i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Bottom Flange</i> <i>Explanation : Fatigue Prone Detail, Partial Cover Plate</i>								
Steel	5%	4+	\$300,500	LIFE	**	2-8	\$1,768,900	
<i>Corrosion, Extent : Light, Area Affected : 15%</i> <i>Location : At Surface</i>								
Secondary Member								
Steel	95%			LIFE	**	2-8	\$2,601,200	
Steel	5%	4+	\$126,900	LIFE	**	2-8	\$1,481,800	
<i>Corrosion, Extent : Light, Area Affected : 20%</i> <i>Location : At Surface And Near Fascia Girders</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EASTERN BLVD. BRUCKNER EXPWY NORTH BOUND OVER BRONX RIVER
Address : BRUCKNER EXPWY N.B. BRONX RIVER
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0004.020 / 2916 **Yr Built/Renovated** : 1952 /
Area Sq Ft : 22,300 **Project Type** : WATERWAY BRIDGES
Date of Survey : 04-Dec-2019 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2066672

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$18,500		\$16,100	
Total	\$18,500		\$16,100	
Importance Code A			\$1,600	
Importance Code C	\$18,500		\$14,600	
Total	\$18,500		\$16,100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
EASTERN BLVD. BRUCKNER EXPWY NORTH BOUND OVER BRONX RIVER
Asset # : 2916

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			* *	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE			* *	
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	100%			LIFE			* *	
Approaches								
Pavement								
Concrete	100%			2040			* * 4 \$29,100	
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Patching</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE			* *	
			<i>Corrosion, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTERN BLVD. BRUCKNER EXPWY NORTH BOUND OVER BRONX RIVER
Asset # : 2916

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Approaches							
Embankment							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Median							
Concrete	100%			LIFE	**	5	
		<i>Spalling, Extent : Light, Area Affected : 2%</i>					
		<i>Location : Random Locations Throughout</i>					
Pavement Base							
Not Accessible	100%						
Railings/Parapets							
Concrete	100%			2040	**	4	
Steel	100%			LIFE	**		
Sidewalks							
Concrete	100%			LIFE	**		
		<i>Cracks, Extent : Light, Area Affected : 5%</i>					
		<i>Location : Random Locations Throughout</i>					
Scupper							
Cast Iron	100%			LIFE	**		
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
		<i>Location : Southwest Approach</i>					
		<i>Explanation : 4 Scuppers</i>					
Piers							
Cap Beam							
Not Accessible	100%						
Pier,Columns							
Not Accessible	100%						
Stem,Solid Pier							
Not Accessible	100%						
Brngs,Ancr Blts,Pads							
Not Accessible	100%						
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Not Accessible	100%						
Pedestals							
Not Accessible	100%						
Piles							
Not Accessible	100%						
Deck Elements							
Curbs							
Concrete w/ Steel Face	100%			LIFE	**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTERN BLVD. BRUCKNER EXPWY NORTH BOUND OVER BRONX RIVER
Asset # : 2916

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Median								
Concrete	100%			LIFE	**	5	\$3,600	
	<i>Corrosion, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i> <i>Spalling, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 30%</i> <i>Location : Throughout</i> <i>Explanation : Steel Facing</i>							
Railings/Parapets								
Concrete	100%			2040	**	4	\$2,400	
Masonry	100%			2040	**	5		
Steel	100%			LIFE	**	2-8	\$9,900	
Sidewalks								
Asphalt	100%			2029		4		
Concrete	100%			2036	**	5	\$3,900	
	<i>Cracks, Extent : Light, Area Affected : 10%</i> <i>Location : Random Locations Throughout</i>							
Wearing Surface								
Concrete	100%			2040	**	5	\$48,200	
Superstructure								
Deck, Structural								
Grating w/ Concrete	100%			LIFE	**			
Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Span 1, 2, 4</i> <i>Explanation : Concrete Deck</i>							
Joints								
Steel	100%	Now	\$16,500	LIFE	**			
	<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i> <i>Location : Armor At Southwest Grating - Concrete Joint</i>							
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EASTERN BLVD. BRUCKNER EXPWY SOUTH BOUND OVER BRONX RIVER
 Address : BRUCKNER EXPWY S.B. BRONX RIVER
 Borough : BRONX Agency's Number : N/A
 Program / Asset # : DOT0004.010 / 2915 Yr Built/Renovated : 1952 /
 Area Sq Ft : 12,400 Project Type : WATERWAY BRIDGES
 Date of Survey : 04-Dec-2019 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2066671

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$158,500
Total		\$158,500
Importance Code A		\$158,500
Total		\$158,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$35,900		\$15,200	
Total	\$35,900		\$15,200	
Importance Code A	\$500		\$700	
Importance Code C	\$35,400		\$14,600	
Total	\$35,900		\$15,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTERN BLVD. BRUCKNER EXPWY SOUTH BOUND OVER BRONX RIVER
Asset # : 2915

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	100%			LIFE		**		
Approaches								
Pavement								
Concrete	100%			2040		**	4	\$29,100
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTERN BLVD. BRUCKNER EXPWY SOUTH BOUND OVER BRONX RIVER
Asset # : 2915

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2040	**	4		
Steel	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Median								
Concrete	100%			LIFE	**	5	\$1,900	
			<i>Other Observation, Extent : Light, Area Affected : 100%</i>					
			<i>Location : Throughout</i>					
			<i>Explanation : Steel Facing</i>					
Railings/Parapets								
Concrete	100%			2040	**	4	\$1,100	
Masonry	100%			2040	**	5	\$1,700	
Steel	100%	Now	\$500	LIFE	**	2-8	\$3,700	
			<i>Other Observation, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Bottom Rail At Midspan, Span 2</i>					
			<i>Explanation : Broken Bolt</i>					
Sidewalks								
Asphalt	100%			2029		4		
Concrete	90%			2036	**	5	\$1,300	
Concrete	10%	4+	\$2,400	2036	**	5	\$700	
			<i>Cracks, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EASTERN BLVD. BRUCKNER EXPWY SOUTH BOUND OVER BRONX RIVER
Asset # : 2915

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Wearing Surface								
Concrete	100%	4+	\$3,400	2040	**	5	\$11,200	
	<i>Spalling, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$158,500	
	<i>Other Observation, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Spans 1 And 3</i>							
	<i>Explanation : Not Accessible On Spans 1 And 3</i>							
Grating w/ Concrete	100%			LIFE	**			
Joints								
Steel	7%	Now	\$28,900	LIFE	**			
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Southwest Grating - Concrete Joint</i>							
	<i>Explanation : Broken Armor</i>							
Steel	93%			LIFE	**			
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FLUSHING BRIDGE EAST BOUND NORTHERN BLVD/FLUSHING RIVER
Address : NORTHERN BLVD. X-ING FLUSH. RIV.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0001.020 / 2560 **Yr Built/Renovated** :
Area Sq Ft : 78,894 **Project Type** : WATERWAY BRIDGES
Date of Survey : 05-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2055802

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$668,400	\$3,573,800
Total	\$668,400	\$3,573,800
Importance Code A	\$166,200	\$1,299,500
Importance Code B	\$279,700	\$1,957,600
Importance Code C	\$222,500	\$316,700
Total	\$668,400	\$3,573,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$131,400		\$315,500	\$23,800
Total	\$131,400		\$315,500	\$23,800
Importance Code A	\$40,000		\$119,200	\$13,500
Importance Code B	\$70,900		\$196,300	
Importance Code C	\$20,400			\$10,300
Total	\$131,400		\$315,500	\$23,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE EAST BOUND NORTHERN BLVD/FLUSHING RIVER
Asset # : 2560

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	98%			LIFE		**		
Concrete	2%	4+	\$4,500	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Brngs, Ancr Blts, Pads Consists Of 50 Percent Steel, 50 Percent Not Accessible</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	95%			LIFE		**		
Concrete	5%	4+	\$6,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Both Abutments</i>								
<i>Efflorescence, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	90%			LIFE		**		
Concrete	10%	4+	\$1,700	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Feature Crossed								
Bank Protection								
Concrete	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE EAST BOUND NORTHERN BLVD/FLUSHING RIVER
Asset # : 2560

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 60%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 60 Percent Not Accessible.</i>								
Pier Protection								
Timber	85%	Now	\$110,500	LIFE		**		
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Both Fender Systems</i>								
<i>Rotted, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Both Fender Systems</i>								
Timber	15%			LIFE		**		
Approaches								
Pavement								
Concrete	100%			2041		**	4	\$20,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Generic	100%			LIFE		**		
Guide Railing								
Concrete	100%			2041		**	4	\$11,400
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041		**	4	
Piers								
Cap Beam								
Concrete	90%			LIFE		**		
Concrete	10%	2-4	\$40,000	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Scattered Throughout</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Scattered Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	90%			LIFE		**	2-8	\$520,900
Steel	10%	4+	\$111,700	LIFE		**	2-8	\$520,900
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Exfoliation Of Weathering Steel</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE EAST BOUND NORTHERN BLVD/FLUSHING RIVER
Asset # : 2560

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns								
Concrete	90%			LIFE		**		
Concrete	10%	4+	\$91,800	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	90%			LIFE		**	2-8	\$569,900
Steel	10%	4+	\$19,700	LIFE		**	2-8	\$569,900
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Exfoliation Of Weathering Steel</i>								
<hr/>								
Stem,Solid Pier								
Concrete	90%			LIFE		**		
Concrete	10%	4+	\$77,400	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pedestals								
Concrete	100%			LIFE		**		
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Guide Railing								
Concrete	100%			2045		**		
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Mono Deck Surface								
Concrete	90%			2052		**	5	\$316,700
Concrete	10%	4+	\$14,200	2052		**	5	\$158,300
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2041		**	4	\$15,600
Steel	100%			LIFE		**	2-8	\$9,600
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Fence</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE EAST BOUND NORTHERN BLVD/FLUSHING RIVER
Asset # : 2560

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Scupper								
Cast Iron	100%			LIFE		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 10 Scuppers Observed</i>							
<hr/>								
Superstructure								
Deck, Structural								
Concrete	95%			LIFE		**	5	\$57,400
Concrete	5%	4+	\$54,500	LIFE		**	5	\$57,400
	<i>Cracks, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Efflorescence, Extent : Light, Area Affected : 4%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 80%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Moderate, Area Affected : 80%</i>							
	<i>Location : Random Locations Throughout</i>							
<hr/>								
Joints								
Generic	20%	2-4	\$64,200	LIFE		**		
	<i>Broken/Missing Elements, Extent : Light, Area Affected : 50%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Misaligned/Bulging, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
Generic	80%			LIFE		**		
<hr/>								
Primary Member								
Steel	99%			LIFE		**	2-8	\$685,500
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 50 Percent Not Accessible.</i>							
Steel	1%			LIFE		**	2-8	\$685,500
	<i>Rust Stains, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Random Locations Throughout</i>							
<hr/>								
Secondary Member								
Steel	94%			LIFE		**	2-8	\$1,221,800
	<i>Other Observation, Extent : N/A, Area Affected : 50%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : 50 Percent Not Accessible.</i>							
Steel	6%	4+	\$44,500	LIFE		**	2-8	\$1,221,800
	<i>Rust Stains, Extent : Light, Area Affected : 15%</i>							
	<i>Location : Random Locations Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FLUSHING BRIDGE WEST BOUND NORTHERN BLVD/FLUSHING RIVER
Address : NORTHERN BLVD. X-ING FLUSH. RIV.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0001.010 / 2665 **Yr Built/Renovated** :
Area Sq Ft : 71,900 **Project Type** : WATERWAY BRIDGES
Date of Survey : 05-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2055801

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$644,600	\$3,253,000
Total	\$644,600	\$3,253,000
Importance Code A	\$158,500	\$1,165,500
Importance Code B	\$254,000	\$1,740,000
Importance Code C	\$232,100	\$347,500
Total	\$644,600	\$3,253,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$121,100	\$7,400	\$278,400	\$1,400
Total	\$121,100	\$7,400	\$278,400	\$1,400
Importance Code A	\$50,000		\$103,900	\$1,400
Importance Code B	\$27,500		\$174,500	
Importance Code C	\$43,600	\$7,400		
Total	\$121,100	\$7,400	\$278,400	\$1,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE WEST BOUND NORTHERN BLVD/FLUSHING RIVER
Asset # : 2665

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Steel	100%			LIFE		**		
Backwall								
Concrete	98%			LIFE		**		
Concrete	2%	4+	\$4,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Brngs, Ancr Blts, Pads Consists Of 50 Percent Steel, 50 Percent Not Accessible.</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	95%			LIFE		**		
Generic	5%	4+	\$2,600	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Begin Approach</i>								
<i>Explanation : Missing Cover Plate</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	95%			LIFE		**		
Concrete	5%	4+	\$9,100	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Efflorescence, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	10%	4+	\$1,300	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Northwest Face At Begin Abutment</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northwest Face At End Abutment</i>								
Concrete	90%			LIFE		**		
Feature Crossed								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE WEST BOUND NORTHERN BLVD/FLUSHING RIVER
Asset # : 2665

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Feature Crossed								
Bank Protection								
Concrete	100%			LIFE	**			
Mat (scour & erosion)								
Generic	100%			LIFE	**			
	<i>Other Observation, Extent : N/A, Area Affected : 60%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Mat (scour & Erosion) Consists Of 40 Percent Generic, 60 Percent Not Accessible</i>							
Pier Protection								
Timber	85%	Now	\$102,000	LIFE	**			
	<i>Broken/Missing Elements, Extent : Severe, Area Affected : 50%</i>							
	<i>Location : Both Fender Systems</i>							
	<i>Rotted, Extent : Severe, Area Affected : 50%</i>							
	<i>Location : Both Fender Systems</i>							
Timber	15%			LIFE	**			
Approaches								
Pavement								
Concrete	100%	4+	\$19,100	2041	**	4	\$10,300	
	<i>Cracks, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Spalling, Extent : Light, Area Affected : 2%</i>							
	<i>Location : Random Locations Throughout</i>							
Embankment								
Generic	100%			LIFE	**			
Guide Railing								
Concrete	100%			2041	**	4	\$2,900	
Steel	100%			LIFE	**	2-8		
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041	**	4		
Sidewalks								
Concrete	95%			LIFE	**			
Concrete	5%	4+	\$3,500	LIFE	**			
	<i>Cracks, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							

Piers

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE WEST BOUND NORTHERN BLVD/FLUSHING RIVER
Asset # : 2665

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam								
Concrete	90%			LIFE		**		
Concrete	10%	2-4	\$50,000	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	90%			LIFE		**	2-8	\$427,900
Steel	10%	4+	\$91,700	LIFE		**	2-8	\$427,900
<i>Rust Stains, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Exfoliation Of Weathering Steel</i>								
Pier,Columns								
Concrete	10%	4+	\$95,800	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	90%			LIFE		**		
Steel	90%			LIFE		**	2-8	\$455,900
Steel	10%	4+	\$15,800	LIFE		**	2-8	\$455,900
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Exfoliation Of Weathering Steel</i>								
Stem,Solid Pier								
Concrete	90%			LIFE		**		
Concrete	10%	4+	\$56,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
Piles								
Not Accessible	100%							

Deck Elements

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE WEST BOUND NORTHERN BLVD/FLUSHING RIVER
Asset # : 2665

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Guide Railing Concrete	100%			2045		**		
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Mono Deck Surface Concrete	90%			2052		**	5	\$347,500
Concrete	10%	4+	\$15,600	2052		**	5	\$173,700
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Railings/Parapets Concrete	100%			2041		**	4	
Steel	100%			LIFE		**	2-8	\$31,000
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Railing And Fence</i>								
<hr/>								
Sidewalks Concrete	100%			2037		**	5	\$14,900
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Settlement, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Scupper Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 9 Scuppers Observed</i>								
<hr/>								
Superstructure								
Deck,Structural Concrete	5%	4+	\$66,800	LIFE		**	5	\$70,300
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	95%			LIFE		**	5	\$70,300

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FLUSHING BRIDGE WEST BOUND NORTHERN BLVD/FLUSHING RIVER
Asset # : 2665

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Joints								
Generic	80%			LIFE		**		
Generic	20%	Now	\$58,300	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Misaligned/Bulging, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Primary Member								
Steel	99%			LIFE		**	2-8	\$611,400
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Not Accessible</i>								
Steel	1%			LIFE		**	2-8	\$611,400
<i>Rust Stains, Extent : Light, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	94%			LIFE		**	2-8	\$1,113,500
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 50 Percent Not Accessible</i>								
Steel	6%			LIFE		**	2-8	\$1,113,500
<i>Rust Stains, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GERRITSEN INLET BRIDGE BELT SHORE PKWY/GERRITSEN INLET
Address : BELT SHORE PKWAY(BSP)
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0021.000 / 2452 **Yr Built/Renovated** : 1939 /
Area Sq Ft : 59,532 **Project Type** : WATERWAY BRIDGES
Date of Survey : 19-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2231450

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$134,600	\$1,317,000
Total	\$134,600	\$1,317,000
Importance Code A		\$1,115,400
Importance Code B		\$66,900
Importance Code C	\$134,600	\$134,600
Total	\$134,600	\$1,317,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure			\$121,900	\$17,700
Total			\$121,900	\$17,700
Importance Code A			\$112,300	\$5,600
Importance Code B			\$6,700	
Importance Code C			\$2,800	\$12,200
Total			\$121,900	\$17,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
GERRITSEN INLET BRIDGE BELT SHORE PKWY/GERRITSEN INLET
Asset # : 2452

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
Backwall Concrete	100%			LIFE		**		
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
Brngs,Ancr Blts,Pads Multi-Rotational Bearing	100%			2067		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Recent Replace Evident</i>						
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Recent Replace Evident</i>						
Mat (scour & erosion)								
Generic	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Asphalt Paved Over. Recent Replace Evident</i>						
Pedestals								
Concrete	100%			LIFE		**		
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
Stem (breastwall)								
Concrete	100%			LIFE		**		
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						

Feature Crossed

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GERRITSEN INLET BRIDGE BELT SHORE PKWY/GERRITSEN INLET
Asset # : 2452

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Recent Replace Evident</i>								
Mat (scour & erosion)								
Stream Bed	100%			LIFE	**			
Pier Protection								
Timber	100%			LIFE	**			
Approaches								
Pavement								
Concrete	100%			2045	**	4	\$24,300	
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Embankment								
Earth	100%			LIFE	**			
Guide Railing								
Concrete	100%			2045	**	4	\$2,300	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout On Southeast Side</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout On Southeast Side</i>								
Steel	100%			LIFE	**	2-8	\$2,300	
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout On Southeast Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout On Southeast Side</i>								
<i>Explanation : Steel Railing On Top Of Concrete Railing</i>								
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Median								
Concrete	100%			LIFE	**	5	\$400	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Pavement Base								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GERRITSEN INLET BRIDGE BELT SHORE PKWY/GERRITSEN INLET
Asset # : 2452

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Railings/Parapets Concrete	100%			2045	**	4	\$1,200	
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout On Northwest Side</i>						
Steel	100%			LIFE	**			
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout On Southeast Side</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout On Southeast Side</i>						
		<i>Explanation : Steel Mesh Behind Railing</i>						
Sidewalks								
Asphalt	100%			2036	**	4	\$5,700	
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout On Southeast Side</i>						
Piers								
Cap Beam Concrete	100%			LIFE	**			
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
Pier,Columns Concrete	100%			LIFE	**			
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
Stem,Solid Pier Concrete	100%			LIFE	**			
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 70%</i>						
		<i>Location : Submerged Under Water</i>						
		<i>Explanation : Stem, Solid Pier Consists Of 30 Percent Concrete, 70 Percent Not Accessible</i>						
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2067	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Recent Replace Evident</i>						
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE	**			
		<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
Piles								
Not Accessible	100%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GERRITSEN INLET BRIDGE BELT SHORE PKWY/GERRITSEN INLET
Asset # : 2452

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Guide Railing Concrete	100%			2049	**			
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout On Southeast Side</i> <i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout On Southeast Side</i>							
Steel	100%			LIFE	**			
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout On Southeast Side</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout On Southeast Side</i> <i>Explanation : Steel Railing On Top Of Concrete Railing</i>							
Median Concrete	100%			LIFE	**	5	\$5,600	
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i>							
Mono Deck Surface Concrete	100%			2058	**	5	\$269,300	
	<i>Cracks, Extent : Light, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i>							
Railings/Parapets Concrete	100%			2045	**	4	\$7,600	
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout On Northwest Side</i>							
Steel	100%			LIFE	**	2-8	\$10,500	
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout On Southeast Side</i>							
Sidewalks Concrete	100%			2040	**	5	\$11,800	
	<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout</i> <i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout On Southeast Side</i>							
Scupper Cast Iron	100%			LIFE	**			
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : 6 Scuppers Observed</i>							

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GERRITSEN INLET BRIDGE BELT SHORE PKWY/GERRITSEN INLET
Asset # : 2452

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Deck, Structural								
Not Accessible	100%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Throughout</i>							
	<i>Explanation : Light Corrosion On 2 Percent Of Area. Deck Is Covered With Stay In Place Forms.</i>							
Primary Member								
Steel	100%			LIFE	* *	2-8	\$2,083,400	
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							
Secondary Member								
Steel	100%			LIFE	* *	2-8	\$104,700	
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GRAND STREET BRIDGE GRAND ST BRIDGE/NEWTOWN CREEK
Address : GARDNER AVENUE BROOKLYN 47TH STREET QUEENS
Borough : BROOKLYN:QNS. Agency's Number : N/A
Program / Asset # : DOT0150.000 / 13513 Yr Built/Renovated : 1903 /
Area Sq Ft : 5,100 Project Type : WATERWAY BRIDGES
Date of Survey : 26-Apr-2021 Landmark Status : NONE
Areas Surveyed :
Block : Lot : BIN : 2240390

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,263,400	
Bridge Electrical	\$34,500	\$705,800
Bridge Mechanical	\$560,100	\$2,365,100
Total	\$1,858,000	\$3,070,900
Importance Code A	\$804,500	
Importance Code B	\$657,800	\$3,070,900
Importance Code C	\$395,600	
Total	\$1,858,000	\$3,070,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$77,800		\$900	
Bridge Electrical	\$34,300	\$1,500	\$1,500	\$1,500
Bridge Mechanical	\$151,600			
Total	\$263,700	\$1,500	\$2,400	\$1,500
Importance Code A	\$31,100		\$900	
Importance Code B	\$194,700	\$1,500	\$1,500	\$1,500
Importance Code C	\$38,000			
Total	\$263,700	\$1,500	\$2,400	\$1,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND STREET BRIDGE GRAND ST BRIDGE/NEWTOWN CREEK
Asset # : 13513

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Granite	5%	4+	\$100	LIFE		**		
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Begin Abutment Between Stringers S6 & S7</i>								
Granite	95%			LIFE		**		
Backwall								
Concrete	5%	4+	\$2,800	LIFE		**		
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Begin And End Abutment (1 Location Each)</i>								
Concrete	95%			LIFE		**		
Brngs,Ancr Blts,Pads								
Steel	100%	Now	\$30,200	LIFE		**		
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Begin Abutment, North Side Bearing Missing 3 Of 4 Anchor Bolts.</i>								
<i>Loose Fastenings, Extent : Severe, Area Affected : 100%</i>								
<i>Location : All 4 Bearings Have Loose Anchor Bolt Nuts.</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : End Abutment Bearings</i>								
<i>Explanation : Both Bearings Are Not Fully Seated</i>								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : End Abutment South Side</i>								
<i>Explanation : Both Abutment Joints Exhibit 0.75 Inch Vertical Differentials</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Masonry: Granite	10%	4+	\$8,800	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Beginning And End Abutments</i>								
<i>Explanation : Masonry Pointing Needed</i>								
Masonry: Granite	90%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Beginning And End Abutments</i>								
<i>Explanation : Masonry Pointing Needed</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND STREET BRIDGE GRAND ST BRIDGE/NEWTOWN CREEK
Asset # : 13513

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Bank Protection								
Concrete	100%			LIFE			**	
Riprap	100%	4+	\$56,000	LIFE			**	
<i>Erosion, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Begin North Side</i>								
Timber	100%			2027				
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	80%			LIFE			**	
Timber	20%	Now	\$63,300	LIFE			**	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Swing Span Pivot Pier</i>								
<i>Split/Dry/Cracked, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Swing Span Pivot Pier</i>								
Approaches								
Pavement								
Asphalt	75%			2026	\$254,700	4	\$15,700	
Asphalt	25%	Now	\$8,500	2026	\$84,900	4	\$10,500	
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Begin Approach Pavement</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Begin Approach Pavement Adjacent To Joint</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	
Granite	100%			LIFE			**	
Guide Railing								
Steel	100%			LIFE		2-8	\$7,500	
Sidewalks								
Concrete	80%			LIFE			**	
Concrete	20%	Now	\$21,400	LIFE			**	
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Begin Right Sidewalk</i>								
<i>Settlement, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Begin Right Approach Sidewalk</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Begin Right Sidewalk</i>								
<i>Other Observation, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Begin-right And End Left Approach Sidewalks</i>								
<i>Explanation : Approach Warning Light Pole Base Exhibits Large Holes W/ Wires Easily Accessible By</i>								
<i>Pedestrians And Light Pole At End Approach Has Been Removed, But Exposed Wires Remain.</i>								
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND STREET BRIDGE GRAND ST BRIDGE/NEWTOWN CREEK
Asset # : 13513

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Steel	95%			LIFE		**		
Steel	5%	Now	\$400	LIFE		**		
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Span 2 Left And Right Curbs</i>								
<i>Explanation : Broken Welds Between Curb Posts And Deck Grating</i>								
Railings/Parapets								
Steel	85%			LIFE		**	2-8	\$9,600
Steel	15%	0-2	\$500	LIFE		**	2-8	\$9,600
<i>Damaged Railing, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Span 1, Connection With Floorbeams 1 Thru 6, Left Side</i>								
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Span 2, Left Railing Near End Abutment</i>								
<i>Explanation : The Last Post Is Bent Outward Up To 7 Inches.</i>								
Sidewalks								
Asphalt	100%			2026			4	
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : Left Sidewalk</i>								
<i>Explanation : Left Sidewalk Is Covered With Timber</i>								
Movable Bridges								
Swing Span Truss								
Steel	25%	4+	\$699,600	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Swing Spans 1 And 2</i>								
<i>Explanation : Structural Steel Exhibits Minor To Moderate Section Losses And Corrosion In Localized Areas.</i>								
Steel	5%	Now	\$70,000	LIFE		**		
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Span 1 And 2 Stringers</i>								
<i>Explanation : Eight Curblines Stringers In Spans 1 And 2 And Right Main Truss Lower Chord Near End Abutment Exhibits Severe Section Losses And Holes.</i>								
Steel	65%			LIFE		**		
Steel	5%	0-2	\$35,000	LIFE		**		
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Span 1, Floorbeams 1 Thru 5 (Left Side)</i>								
<i>Explanation : Floorbeams Exhibit Impact Damage And Are Out Of Plane For Up To 4 Inches.</i>								
Swing Span Pivot Pier								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Swing Span Pivot Pier</i>								
<i>Explanation : Masonry Pointing Missing</i>								

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Communication Electrical

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND STREET BRIDGE GRAND ST BRIDGE/NEWTOWN CREEK
Asset # : 13513

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Air Horn								
Generic	100%			2031	\$2,500			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 100%</i>								
<i>Location : Control Room</i>								
Control System Electrical								
Control Console								
Stainless Steel	100%	Now	\$3,600	LIFE		**		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Control Booth</i>								
<i>Explanation : Open Holes, Unlabeled Buttons, Debris</i>								
Control Devices								
Relay	50%			2030	\$14,600			
Relay	50%	Now	\$4,400	2030	\$14,600			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Control Booth</i>								
<i>Explanation : Per Discussions With Nycdot Personnel, Bridge Must Be Operated In Bypass Mode.</i>								
Disconnect Switch								
Generic	100%	Now	\$12,600	2052		**		
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : East Rest Pier</i>								
<i>Explanation : East Wedge Disconnect Interior Corrosion</i>								
Limit Switch								
Rotary	100%			2026				
Generic	100%			2049		**		
Electrical Power								
Dist Equip & Motor Controll								
Generic	50%			2045		**		
Generic	50%	Now	\$5,600	2030	\$112,600			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : East And West Sides</i>								
<i>Explanation : East And West Service Cabinets Are Not Locked And Accessible To The Public.</i>								
Raceway								
Wiring								
Generic	100%			2033	\$593,200			
Lighting								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND STREET BRIDGE GRAND ST BRIDGE/NEWTOWN CREEK
Asset # : 13513

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Lighting								
Lighting Devices								
Generic	5%	Now	\$500	2026	\$4,800			
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Roadway Lighting</i>								
<i>Explanation : One Fixture Inoperative</i>								
Generic	64%			2037	**			
Generic	6%	Now	\$1,200	2026	\$5,800			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : West Pier</i>								
<i>Explanation : West Pier Light Not Operational.</i>								
Generic	25%	Now	\$4,800	2026	\$24,000			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout Span</i>								
<i>Explanation : Span Navigation Lighting Inoperable.</i>								

Main Drive

Motor Controller

Drum Controller

100%			2047	**	1	\$15,300
------	--	--	------	----	---	----------

*Other Observation, Extent : Light, Area Affected : 100%**Location : Control Room**Explanation : No Operations Observed*

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Swing								
Center Latch								
Generic	100%	Now	\$12,700	2035	\$127,300			
<i>Corrosion, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Center Latch</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Center Latch</i>								
<i>Explanation : No Operation Was Observed.</i>								
Center Pivot	100%			2035	\$1,292,300			
Generic								
End Lift								
Generic	100%	Now	\$83,700	2035	\$279,100			
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 100%</i>								
<i>Location : End Lifts</i>								
<i>Corrosion, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Open Gearing At End Lifts</i>								
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : End Lifts</i>								
<i>Explanation : Roller Assemblies And Cranks Are In Differing Positions. Reducer Oil Dark Color. One Crank Cotter Pin Damaged.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GRAND STREET BRIDGE GRAND ST BRIDGE/NEWTOWN CREEK
Asset # : 13513

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Swing								
Houses								
Access Ways	100%	Now	\$34,100	2047			**	
<i>Other Observation, Extent : Severe, Area Affected : 10%</i> <i>Location : Center Pivot Pier And End Lift Accessways</i> <i>Explanation : Some Center Pivot Deck Boards Need To Be Repaired. Grating At End Lifts Is Severely Corroded. Vertical Ladder To Pivot Is Corroded And Bent. Hatch To Center Pivot Corroded.</i>								
Control House	100%	Now	\$93,000	2072			**	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i> <i>Location : Control And Bridge House</i> <i>Explanation : The Bridge House Is At The End Of Its Useful Life. No Heat. No Bathroom.</i>								
Main Drive System								
Generic	100%	Now	\$51,500	2035	\$515,400			
<i>Other Observation, Extent : Light, Area Affected : 50%</i> <i>Location : Operating Machinery</i> <i>Explanation : Some Oil Leakage. Machinery Covers Replaced With Plywood. One Bearing Missing Cap Nuts. No Observation Observed.</i>								
Rack								
Generic	100%			LIFE			**	
Structural Bearings								
Generic	100%	Now	\$61,700	2028	\$123,300			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 75%</i> <i>Location : Anchor Bolts At Raceways, Roller Nest And Bases</i> <i>Other Observation, Extent : Moderate, Area Affected : 75%</i> <i>Location : Raceways, Roller Nest And Bases</i> <i>Explanation : Components Are Nearing The End Of Their Useful Life.</i>								
Traffic Devices								
Barrier Gate	100%	Now	\$29,400	2028	\$146,800			
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 100%</i> <i>Location : Barrier Gates</i> <i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Barrier Gates</i> <i>Explanation : No Observations Observed.</i>								
Signals	100%	Now	\$26,400	2035	\$52,800			
<i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Flashers Mounted On Structure; West Approach</i> <i>Explanation : Gongs Inoperative On Vehicular Gates.</i> <i>Traffic Signal Visor Missing</i>								
Warning Gate	100%	Now	\$49,100	2035	\$98,100			
<i>Other Observation, Extent : Severe, Area Affected : 50%</i> <i>Location : Warning Gates</i> <i>Explanation : Some Missing Gate Arms. Gates Are Nearing The End Of Their Useful Life.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GREENPOINT AVE. BRIDGE GREENPOINT AVE/NEWTOWN CREEK
 Address : NEWTOWN CREEK, LIRR
 Borough : BROOKLYN:QNS. Agency's Number : N/A
 Program / Asset # : DOT0047.000 / 2500 Yr Built/Renovated : 1987 / 2015
 Area Sq Ft : 76,106 Project Type : WATERWAY BRIDGES
 Date of Survey : 07-Apr-2021 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2240370

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$297,200	\$2,128,600
Bridge Electrical	\$85,000	\$1,425,900
Bridge Mechanical	\$3,866,400	\$1,361,700
Total	\$4,248,600	\$4,916,200
Importance Code A		\$904,600
Importance Code B	\$4,002,300	\$3,607,100
Importance Code C	\$246,300	\$404,500
Total	\$4,248,600	\$4,916,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$18,900	\$19,300	\$166,500	\$13,000
Bridge Electrical	\$109,200	\$6,900	\$6,900	\$6,900
Bridge Mechanical	\$47,800		\$71,800	
Total	\$175,800	\$26,200	\$245,200	\$19,900
Importance Code A	\$1,900		\$84,300	
Importance Code B	\$159,900	\$6,900	\$160,900	\$6,900
Importance Code C	\$14,100	\$19,300		\$13,000
Total	\$175,800	\$26,200	\$245,200	\$19,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GREENPOINT AVE. BRIDGE GREENPOINT AVE/NEWTOWN CREEK
Asset # : 2500

Bridge Structure	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	100%	Now	\$11,800	2033	\$235,300	4	\$7,100	
<i>Settlement, Extent : Light, Area Affected : 2%</i>								
<i>Location : Beginning And End Approaches</i>								
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : End Approach Right Side.</i>								
<i>Explanation : Asphalt Heaving And Uneven</i>								
Concrete	100%			2041	**	4	\$26,100	
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 30%</i>								
<i>Location : Both Sides Of The Beginning And End Approaches</i>								
Guide Railing								
Steel	100%			LIFE	**	2-8		
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE	**			
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Various Locations Throughout</i>								
<i>Explanation : 14 Scuppers Observed.</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
<i>Delaminations, Extent : Light, Area Affected : 3%</i>								
<i>Location : Pier 3</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Pier 10</i>								
Steel	100%			LIFE	**	2-8		
Pier,Columns								
Concrete	100%			LIFE	**			
Stem,Solid Pier								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Multi-Rotational Bearing	100%			2060	**			
<i>Loose Fastenings, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Piers 2 (6 Loc), 4 (1 Loc), 9 (1 Loc) 10 (3 Loc)</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GREENPOINT AVE. BRIDGE GREENPOINT AVE/NEWTOWN CREEK
Asset # : 2500

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pedestals								
Concrete	100%	2-4	\$50,900	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Pier 3 At Stringer 1 And Stringer 10</i>								
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Pier 3 At Stringer 11</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 30%</i>								
<i>Location : Spans 1 Through 5 And 7 Through 12</i>								
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$58,600
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Spans 1 Through 5 And 7 Through 12</i>								
<i>Explanation : Spans With Railings And Pedestrian Fencing</i>								
<hr/>								
Sidewalks								
Concrete	1%	Now	\$2,300	2037		**	5	\$19,300
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 3 At Pier 3, Left Sidewalk.</i>								
<i>Explanation : 2 Inches W x 15 Inches L Hole Adjacent To Deck Joint Armor Plate.</i>								
Concrete	99%			2037		**	5	\$38,600
<hr/>								
Wearing Surface								
Concrete	100%			2041		**	5	\$338,400
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Span 1 Adjacent To Begin Abutment Joint.</i>								
<hr/>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1,2,3,4 On The Left Side And 8,9,10,11&12 On Both Sides.</i>								
<i>Explanation : 48 Scuppers</i>								
<hr/>								
Superstructure								
Deck,Structural								
Concrete	100%			LIFE		**	5	\$85,100
<i>Cracks, Extent : Light, Area Affected : 15%</i>								
<i>Location : Spans 11</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Isolated Within Spans 1,2,3,7,8, 9 And 10.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GREENPOINT AVE. BRIDGE GREENPOINT AVE/NEWTOWN CREEK
Asset # : 2500

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Generic	100%	Now	\$77,100	LIFE		**		
<i>Leakage, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Piers 3, 4, 7 And 10</i>								
<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Piers 3, 4, 7 And 10 Armored Joint At Right (south) Sidewalk</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Spans 3, 4, 7 And 10</i>								
<i>Explanation : Joints Filled With Dirt And Leaking.</i>								
Primary Member Steel	100%			LIFE		**	2-8	\$1,530,700
Secondary Member Steel	100%			LIFE		**	2-8	\$1,282,300
Movable Bridges								
Bascule Span Steel	100%			LIFE		**		
Bascule Span Pier Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Bascule Span Piers 5 And 6</i>								
<i>Explanation : Previously Noted Base Of Trunnion Tower Columns Exhibiting Corrosion Not Verified Due To Inaccessibility. Pit Has Water In It.</i>								
Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Air Horn								
Generic	100%	Now	\$2,500	2034	\$2,500			
<i>Malfunctioning, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Entire Bridge</i>								
Intercom								
Generic	100%	Now	\$17,100	2032	\$17,100			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Entire Bridge</i>								
<i>Explanation : Intercom Not Functioning</i>								
Telephone								
Desk Top	100%			2031				
Control System Electrical								
Control Console								
Stainless Steel	100%	Now	\$65,400	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Knob On Power Feeder Selector Broken</i>								
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Control Desk</i>								
<i>Explanation : Position Indicator Not Working, Various Pilots Not Operational, Current Dial Fluctuating.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GREENPOINT AVE. BRIDGE GREENPOINT AVE/NEWTOWN CREEK
Asset # : 2500

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Control System Electrical								
Control Devices								
Relay	100%	Now	\$17,600	2037		**		
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Motor Drives And Barrier Gates.</i>								
<i>Explanation : Meters Show Current Surge During Operation Of Drives Multiple Bypasses Used During Operation</i>								
Disconnect Switch Non Fused	100%			2045		**	1	\$35,900
Limit Switch								
Generic	100%	Now	\$5,700	2045		**		
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : All Span Locks</i>								
<i>Explanation : Handcrank Switches Failed On Span Locks.</i>								
Local Starter								
Magnetic	100%			2045		**		
Drive								
Machinery Brake								
Thruster	100%			2058		**	1	\$1,100
Motor Brake								
Thruster	100%			2052		**	1	\$1,100
Span Lock Motor								
Generic	100%			2052		**	1	\$1,100
Electrical Power								
MCC								
Contactors	100%			2045		**		
Panelboard								
Circuit Breaker	100%			2049		**	1	\$6,700
Service Equipment								
Circuit Breaker	100%			2037		**		
Transfer Switch								
Auto	100%	Now	\$30,100	2052		**		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Service Room</i>								
<i>Explanation : The Existing Transfer Switch Has Failed. The Bridge Cannot Transfer Between Utility Feeds.</i>								
Transformer								
Dry	100%			2045		**		
Liquid Type	100%			2037		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Service Room</i>								
<i>Explanation : Con Ed Service Transformers.</i>								
Ground/Lightning Protection								
Ground Rod								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GREENPOINT AVE. BRIDGE GREENPOINT AVE/NEWTOWN CREEK
Asset # : 2500

Bridge Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Ground/Lightning Protection								
Ground Wire								
Green	100%	Now	\$1,500	2036		**		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Northwestern Corner In Control House</i>								
<i>Explanation : Ground Connection Loose In Corner Of Boiler Room</i>								
Raceway								
Box								
Pull Junction	100%			2032			1	\$6,700
Terminal	100%			2037		**	1	\$2,300
Communications								
Twisted Shielded pair	100%			2031				
Conduit								
Metal	100%			2060		**		
Submarine Control Cables								
Generic	100%			2030	\$1,328,800			
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : Far Side Submarine Cable Termination Cabinet</i>								
<i>Explanation : Far Side Submarine Termination Cabinet Has Corrosion On The Interior.</i>								
Submarine Power Cable								
Generic	100%			2033				
Trough								
Metal	100%			2047		**	1	\$1,100
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : West Side</i>								
<i>Explanation : Far Side Wire Way Has Corrosion.</i>								
Wires								
Thermoplastic	100%			2037		**		
Span Lock								
Motor								
Squirrel Cage	100%			2035				
Stand-by Power								
Transfer Switch								
Not Accessible	100%							
Lighting								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GREENPOINT AVE. BRIDGE GREENPOINT AVE/NEWTOWN CREEK
Asset # : 2500

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Lighting								
Lighting Devices								
Generic	29%	Now	\$17,800	2033	\$35,600			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Bascule Span East And West</i>								
<i>Explanation : 3 Of 4 Span Nav Lights Out</i>								
Generic	16%	0-2	\$2,000	2026	\$19,700			
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Northeast And Southeast Roadway HID Lights Inoperative</i>								
<i>Explanation : Broken/Missing Elements</i>								
Generic	16%	Now	\$2,000	2033	\$19,700			
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Spot Lighting At Areaways</i>								
<i>Explanation : Broken/Missing Elements</i>								
Generic	5%	Now	\$6,100	2037		**		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Various Throughout Bridge And Control House</i>								
<i>Explanation : All Emergency Lights Battery Backups Have Failed</i>								
Generic	34%			2033	\$41,800			
Main Drive								
Motor Controller								
Thyristor Drive	100%			2040		**	1-5	\$15,900

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Bascule								
Counter Weight								
Generic	100%			2060		**	2	\$89,800
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : East And West Counterweight Pits</i>								
<i>Explanation : Water Observed In Counterweight Pits. Maintenance Cleaning Required.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GREENPOINT AVE. BRIDGE GREENPOINT AVE/NEWTOWN CREEK
Asset # : 2500

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Houses								
Access Ways	100%	Now	\$58,900	2035	\$294,500			
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout All Areas</i>								
<i>Explanation : Some Grating, Door, And Hatch Repair Necessary. Platform Missing At Northwest And Northeast Pocket Access. Locks Needed.</i>								
Control House	100%	Now	\$132,800	2047	* *			
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Control House</i>								
<i>Explanation : Loose Railing, Roof, Some Doors, Windows Need Repair. Some Floor, Ceiling Panels Need Repair. Water & Heater Leaks. Heat, Some Leaks Need Repair. Sump Pumps & CO Detector Not Working</i>								
Machinery Room	100%	Now	\$122,400	2060	* *			
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Machinery Rooms</i>								
<i>Explanation : Machinery Rooms Are Corroded. Some Panels, Doors, Hatches And Locks Need Repair.</i>								
Lock Bars								
With Motor	100%	Now	\$379,700	2041	* *			
<i>Corrosion, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Lock Bars</i>								
<i>Lubrication Issue, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Lock Bars</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Lock Bars</i>								
<i>Explanation : Clearances Need To Be Reduced. Maintenance Needed.</i>								
Main Drive System								
Generic	100%	Now	\$1,694,800	2060	* *	2	\$215,500	
<i>Corrosion, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Operating Machinery</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Operating Machinery</i>								
<i>Explanation : Lube Leakage, Coupling Gaskets Deteriorating. Noise From Reducers Should Be Monitored. One Coupling Missing Bolt. Oil Levels Low Or Dark Color.</i>								
Rack								
Generic	100%	Now	\$85,400	2060	* *			
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Racks</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Racks</i>								
<i>Explanation : Some Build Up Of Debris On Supports And Fasteners.</i>								
Structural Bearings								
Generic	100%	Now	\$29,800	2035	\$298,100			
<i>Corrosion, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Live Load Bearings</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Live Load Bearings</i>								
<i>Explanation : Bearings Need To Be Adjusted In Conjunction With Locks.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
GREENPOINT AVE. BRIDGE GREENPOINT AVE/NEWTOWN CREEK
Asset # : 2500

Bridge Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Traffic Devices								
Barrier Gate	50%	Now	\$71,200	2035	\$237,300			
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : West And East Barrier Gates</i>								
<i>Explanation : Incandescent Traffic Gate Lights Broken/Missing</i>								
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : West Side</i>								
<i>Explanation : Not Interlocking Properly. Maintenance Required.</i>								
Barrier Gate	50%	Now	\$71,200	2035	\$237,300			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : East Side</i>								
<i>Explanation : Malfunctioning. Maintenance Required.</i>								
Warning Gate	50%	Now	\$58,900	2035	\$147,200			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : West Side</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : West Side</i>								
<i>Explanation : Disconnected Guy Wire On One Gate. Bent Plunger On One Side Of Gate. One Gate Not Vertical When Raised. Maintenance Required.</i>								
Warning Gate	50%	Now	\$58,900	2035	\$147,200			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : East Side</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : East Side</i>								
<i>Explanation : One Arm Broken At Tip, Maintenance And Repairs Required. East Gongs Do Not Work.</i>								
Trunnion								
Generic	100%	Now	\$1,132,200	2060			**	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Trunnion Assemblies</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Trunnion Assemblies</i>								
<i>Lubrication Issue, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Trunnion Assemblies</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Trunnion Assemblies</i>								
<i>Explanation : Slight Noise During Few Degrees Of Operation.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HAMILTON AVENUE BRIDGE NORTHBOUND LEAF
 Address : HAMILTON AVE./GOWANUS CANAL
 Borough : BROOKLYN Agency's Number : N/A
 Program / Asset # : DOT0138.010 / 13434 Yr Built/Renovated : 1931 / 2007
 Area Sq Ft : 7,300 Project Type : WATERWAY BRIDGES
 Date of Survey : 24-Apr-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2240232

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$462,500	\$3,265,700
Bridge Electrical	\$209,200	\$61,600
Bridge Mechanical	\$56,800	
Total	\$728,500	\$3,327,300
Importance Code A		\$72,300
Importance Code B	\$650,000	\$61,600
Importance Code C	\$78,500	\$3,193,400
Total	\$728,500	\$3,327,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$15,100	\$140,000	\$8,200	\$4,800
Bridge Electrical	\$39,700	\$500	\$500	\$500
Bridge Mechanical	\$130,700	\$9,000	\$62,900	\$9,000
Total	\$185,500	\$149,500	\$71,600	\$14,300
Importance Code A			\$7,800	
Importance Code B	\$170,400	\$9,500	\$63,800	\$9,500
Importance Code C	\$15,100	\$140,000		\$4,800
Total	\$185,500	\$149,500	\$71,600	\$14,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE NORTHBOUND LEAF
Asset # : 13434

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
Backwall Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : End Abutment Only</i>						
		<i>Explanation : Location Noted</i>						
Brngs,Ancr Blts,Pads Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : End Abutment Only</i>						
		<i>Explanation : Bearings Not Accessible</i>						
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Concrete	10%	4+	\$61,800	LIFE		**		
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : End Abutment</i>						
Concrete	90%			LIFE		**		
Masonry: Granite	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Begin Abutment</i>						
		<i>Explanation : Location Noted</i>						
Walls								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Span 3</i>						
		<i>Explanation : Walls Enclose Span 3</i>						
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
Feature Crossed								
Bank Protection								
Concrete	100%			LIFE		**		
Timber	100%			2039		**		
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE NORTHBOUND LEAF
Asset # : 13434

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Timber	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 1 And 2.</i>								
<i>Explanation : Location Noted</i>								
Approaches								
Pavement								
Asphalt	100%			2035	\$1,882,300	4	\$87,000	
Concrete	90%			2043	**	4	\$333,000	
Concrete	10%	4+	\$15,100	2043	**	4	\$222,000	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$11,100
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Pier 2</i>								
<i>Explanation : Steel Columns Support Bascule Girders.</i>								
Stem,Solid Pier								
Concrete	100%	4+	\$322,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 50%</i>								
<i>Location : Concrete Pier Wall, Cracking Surrounding The Windows And Girder Openings.</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**	2-8	\$6,900
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE NORTHBOUND LEAF
Asset # : 13434

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Median								
Cobblestone	100%			2054	**			
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$8,500	
Sidewalks								
Concrete	100%			2039	**	5	\$9,600	
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Wearing Surface								
Asphalt	100%			2035	\$1,093,400	5	\$139,200	
Concrete	100%			2043	**	5	\$156,900	
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$39,600	
Steel Grating	100%			LIFE	**	5	\$40,400	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Span 2</i>						
		<i>Explanation : Steel Grating In Bascule Span.</i>						
Joints								
Steel	100%			LIFE	**			
Primary Member								
Concrete	100%			LIFE	**	5		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Span 1</i>						
		<i>Explanation : Concrete Ribbed Arches.</i>						
Steel	100%			LIFE	**	2-8	\$135,000	
Secondary Member								
Concrete	100%			LIFE	**	5		
Movable Bridges								
Bascule Span								
Steel	100%			LIFE	**			
Bascule Span Pier								
Concrete	100%			LIFE	**			

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Communications								
Generic	100%	Now	\$61,600	2033	\$61,600			
		<i>Other Observation, Extent : Severe, Area Affected : 50%</i>						
		<i>Location : All</i>						
		<i>Explanation : Intercom System Has Failed</i>						
Control System Electrical								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE NORTHBOUND LEAF
Asset # : 13434

Bridge Electrical		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Control System Electrical								
Control Console Stainless Steel	100%	Now	\$2,200	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Desk</i>								
<i>Explanation : Some Pilot Lights Burnt Out.</i>								
Disconnect Switch Generic	100%			2051		**		
Limit Switch Generic	100%			2051		**		
Raceway								
Submarine Control Cables Generic	100%			2038		**		
Wiring Generic	100%	Now	\$57,400	2038		**		
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Various Locations Throughout</i>								
<i>Explanation : Miscellaneous Corroded Conduits, Exposed Conductors, Missing Covers On Conduit Bodies</i>								
Stand-by Power Generator								
Diesel	100%	Now	\$90,100	2054		**	1	\$4,000
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Generator</i>								
<i>Explanation : Generator Is Not Functional</i>								
Traffic System Electrical								
Traffic Signal Generic	100%	Now	\$600	2033	\$3,200	1		\$500
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Northbound Traffic Signal</i>								
<i>Explanation : Northbound Traffic Signal Had 2 Green Lights Not Operational.</i>								
Lighting								
Lighting Devices Generic	100%	Now	\$36,900	2038		**		
<i>Other Observation, Extent : Light, Area Affected : 35%</i>								
<i>Location : Various Locations</i>								
<i>Explanation : Exit Lighting Did Not Function When Tested With Button On Unit; Northeast Fender Pier Light Out; Green Lights Not Working On Span</i>								

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Counter Weight Generic	100%	Now	\$12,700	2069		**	2	\$35,900
<i>Other Observation, Extent : Severe, Area Affected : 1%</i>								
<i>Location : Counterweight</i>								
<i>Explanation : Extra Material On Top Of Counterweight.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE NORTHBOUND LEAF
Asset # : 13434

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Emergency Drive Emergency Power	100%	Now	\$8,300	2069	**	2	\$71,800	
<i>Other Observation, Extent : Severe, Area Affected : 5%</i> <i>Location : Hydraulic Power Unit And Control Rooms</i> <i>Explanation : Operation Was Not Observed. Check Operation And For The Presence Of Exhaust Gas In Control Tower. Missing Handle Locks.</i>								
Fuel Tanks								
Generic	100%			2051	**			
Houses								
Access Ways	100%	Now	\$2,500	2047	**			
<i>Other Observation, Extent : Moderate, Area Affected : 3%</i> <i>Location : Access Ways, Sump Pump Room And Counterweight Pits</i> <i>Explanation : Loose Hardware And Chains. Missing Grates.</i>								
Control House	100%	Now	\$29,800	2069	**			
<i>Other Observation, Extent : Severe, Area Affected : 2%</i> <i>Location : Control House</i> <i>Explanation : Leaky Windows And Doors, Permanent Shades Required. Alarms Require Repairs.</i>								
Machinery Room	100%	Now	\$5,200	2069	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Machine Room</i> <i>Explanation : Some Water Leakage Into Room.</i>								
Lock Bars								
With Motor	60%	Now	\$25,300	2047	**	2	\$35,900	
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i> <i>Location : East Lock Bars</i> <i>Explanation : Some Coverage Of Debris And Corrosion. Missing Single And/or Double Nuts. Brake Release Pulled. Minor Adjustments Required.</i>								
With Motor	40%			2047	**	2	\$44,900	
Main Drive System								
Generic	100%	Now	\$56,800	2069	**	2	\$107,800	
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i> <i>Location : East Machine Room</i> <i>Explanation : Breathers Will Need To Be Changed Soon. Some Minor Leaks And Machinery Covers Removed. Monitor Noise. Brakes May Require Adjustment.</i>								
Rack								
Generic	100%	0-2	\$8,300	2069	**			
<i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Racks And Pinion Assemblies.</i> <i>Explanation : Some Surface Corrosion And Debris Buildup On Interior Of Rack And Support.</i>								
Structural Bearings								
Generic	100%	Now	\$6,400	2047	**			
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i> <i>Location : Counter Weight Pit</i> <i>Explanation : Bumper Block Wood Is Splitting. Some Live Load And Center Guide Bolts Covered In Debris.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE NORTHBOUND LEAF**

Asset # : 13434

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Traffic Devices								
Barrier Gate	100%	Now	\$21,300	2047		* *		
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Barrier Gates</i>								
<i>Explanation : Some Doors And Hardware Damaged. Some Repairs Required; Miscellaneous Failed Bulbs Flashing Incorrectly</i>								
Warning Gate	100%	Now	\$5,400	2047		* *		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Warning Gates</i>								
<i>Explanation : Some Minor Repairs Required; Southeast Flashing Light Out</i>								
Trunnion								
Generic	15%	Now	\$5,700	2069		* *		
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Trunnions</i>								
<i>Explanation : Some Debris And Moderate Corrosion.</i>								
Generic	85%			2069		* *		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HAMILTON AVENUE BRIDGE SOUTHBOUND LEAF
Address : HAMILTON AVE./GOWANUS CANAL
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0138.000 / 4217 **Yr Built/Renovated** : 1931 / 2008
Area Sq Ft : 7,300 **Project Type** : WATERWAY BRIDGES
Date of Survey : 24-Apr-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240231

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$632,700	\$3,561,000
Bridge Electrical	\$147,600	\$163,000
Bridge Mechanical	\$648,200	
Total	\$1,428,500	\$3,724,000
Importance Code A	\$138,000	\$506,800
Importance Code B	\$1,117,900	\$163,000
Importance Code C	\$172,600	\$3,054,200
Total	\$1,428,500	\$3,724,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure			\$43,900	\$4,800
Bridge Electrical	\$54,000	\$500	\$500	\$500
Bridge Mechanical	\$163,600	\$35,900	\$62,900	\$35,900
Total	\$217,500	\$36,400	\$107,200	\$41,200
Importance Code A			\$43,500	
Importance Code B	\$217,500	\$36,400	\$63,800	\$36,400
Importance Code C				\$4,800
Total	\$217,500	\$36,400	\$107,200	\$41,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE SOUTHBOUND LEAF
Asset # : 4217

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : End Abutment</i>								
<i>Explanation : Concrete Bridge Seat.</i>								
Backwall Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : End Abutment</i>								
<i>Explanation : End Abutment</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location : End Abutment Only.</i>								
<i>Explanation : Bearings Not Accessible</i>								
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE		**		
Mat (scour & erosion) Not Accessible	100%							
Stem (breastwall) Concrete	100%			LIFE		**		
Masonry: Granite	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Begin Abutment</i>								
<i>Explanation : Begin Abutment</i>								
Walls Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span 3</i>								
<i>Explanation : Walls Enclose Span 3</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
Feature Crossed								
Bank Protection Riprap	100%			LIFE		**		
Sheet Piling	100%			LIFE		**		
Timber	100%			2039		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE SOUTHBOUND LEAF
Asset # : 4217

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 1 And 2.</i>								
<i>Explanation : Piers 1 And 2.</i>								
Approaches								
Pavement								
Asphalt	100%	Now	\$94,100	2035	\$1,882,300	4	\$58,000	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	100%			2043		**	4	
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Steel	100%			LIFE		**	2-8	
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$11,100
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Pier 2</i>								
<i>Explanation : Steel Columns For Bascule Span.</i>								
Stem,Solid Pier								
Concrete	100%	4+	\$322,200	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 50%</i>								
<i>Location : Pier Wall End Face Cracking Surrounding Windows And Girder Openings.</i>								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**	2-8	\$6,900
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE SOUTHBOUND LEAF
Asset # : 4217

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pedestals								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 1 And 2.</i>								
<i>Explanation : Concrete Pedestals For Span 2 At Pier 1 Bearings And For Span 3 At Pier 2 Bearings.</i>								
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Median								
Cobblestone	100%			2054	**			
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$8,500	
Sidewalks								
Concrete	100%			2039	**	5	\$9,600	
Wearing Surface								
Asphalt	100%			2035	\$1,093,400	5	\$15,500	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Concrete	100%			2043	**	5	\$156,900	
Superstructure								
Deck, Structural								
Concrete	1%	4+	\$138,000	LIFE	**	5	\$39,600	
<i>Spalling, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Span 1 Bay 6, Up To 1.5 Inches Deep W/ Ecr.</i>								
Concrete	99%			LIFE	**	5	\$39,600	
Steel Grating	100%			LIFE	**	5	\$40,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span 2</i>								
<i>Explanation : Steel Grating In Bascule Span.</i>								
Joints								
Steel	100%			LIFE	**			
Primary Member								
Concrete	100%			LIFE	**	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span 1</i>								
<i>Explanation : Concrete Ribbed Arch.</i>								
Steel	100%			LIFE	**	2-8	\$798,600	
Secondary Member								
Concrete	100%			LIFE	**	5		
Movable Bridges								
Bascule Span								
Steel	100%			LIFE	**			
Bascule Span Pier								
Concrete	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE SOUTHBOUND LEAF
Asset # : 4217

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Communications								
Generic	100%			2033	\$41,100			
Control System Electrical								
Control Console								
Stainless Steel	100%	Now	\$10,900	LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 25%</i>								
<i>Location : Control Desk</i>								
<i>Explanation : Some Pilot Lights Burnt Out; West Brakes Indicate That They Are Constantly Released. System Runs Without Incident Though</i>								
Disconnect Switch								
Generic	100%			2051	**			
Limit Switch								
Generic	100%			2051	**			
Raceway								
Submarine Control Cables								
Generic	100%			2038	**			
Wiring								
Generic	100%	Now	\$57,400	2038	**			
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Various Locations</i>								
<i>Explanation : Miscellaneous Corroded Conduits. Exposed Conductors. Missing Covers On Conduit Bodies.</i>								
Stand-by Power								
Generator								
Diesel	100%	Now	\$90,100	2054	**	1	\$4,000	
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Generator</i>								
<i>Explanation : Generator Is Not Functional</i>								
Traffic System Electrical								
Traffic Signal								
Generic	100%			2033	\$163,000	1	\$600	
Lighting								
Lighting Devices								
Generic	50%	Now	\$30,700	2038	**			
<i>Other Observation, Extent : Light, Area Affected : 35%</i>								
<i>Location : Various Locations</i>								
<i>Explanation : Bridge Service Lighting Has Some Fixtures That Are Not Working; Northeast Fender Pier Light Out; East And West Bascule Green Lights Are Not Working</i>								
Generic	50%	Now	\$12,300	2038	**			
<i>Other Observation, Extent : N/A, Area Affected : 40%</i>								
<i>Location : Various Locations</i>								
<i>Explanation : Some Emergency Exit Lights Do Not Work When Tested Using The Test Function On Unit.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE SOUTHBOUND LEAF
Asset # : 4217

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Counter Weight Generic	100%	Now	\$50,300	2069	**	2	\$35,900	
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i> <i>Location : Counterweight</i> <i>Explanation : Debris Accumulating On Counterweight. Pit Sump Pump Needs Repair.</i>								
Emergency Drive Emergency Power	100%	Now	\$23,700	2069	**	2	\$71,800	
<i>Other Observation, Extent : Severe, Area Affected : 5%</i> <i>Location : Hydraulic Power Unit And Control Rooms</i> <i>Explanation : Operation Was Not Observed. Check Operation And For The Presence Of Exhaust Gas In Control Tower. Missing Handle Locks.</i>								
Fuel Tanks Generic	100%			2051	**			
Houses								
Access Ways	100%	Now	\$12,700	2047	**			
<i>Other Observation, Extent : Moderate, Area Affected : 3%</i> <i>Location : Access Ways, Sump Pump Room And Counter Weight Pits</i> <i>Explanation : Loose Hardware And Chains. Missing Grates.</i>								
Control House	100%	Now	\$32,200	2069	**			
<i>Other Observation, Extent : Severe, Area Affected : 2%</i> <i>Location : Control House</i> <i>Explanation : Leaky Windows And Doors. Permanent Shades Required. Alarms Require Repairs.</i>								
Machinery Room	100%	Now	\$10,200	2069	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Machine Room</i> <i>Explanation : Some Water Leakage Into Room.</i>								
Lock Bars								
With Motor	65%	Now	\$19,400	2047	**	2	\$35,900	
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i> <i>Location : West Locks</i> <i>Explanation : Some Coverage Of Debris And Corrosion. Missing Single And/or Double Nuts. Minor Adjustment Required.</i>								
With Motor	35%			2047	**	2	\$44,900	
Main Drive System								
Generic	30%	Now	\$356,300	2069	**	2	\$107,800	
<i>Other Observation, Extent : Severe, Area Affected : 30%</i> <i>Location : West Machine Room</i> <i>Explanation : Breathers Will Need To Be Changed Soon. Some Minor Leaks And Machinery Covers Removed. Monitor Noise. Brakes Do Not Work.</i>								
Generic	70%			2069	**	2	\$134,700	
Rack								
Generic	100%	0-2	\$12,500	2069	**			
<i>Other Observation, Extent : Light, Area Affected : 10%</i> <i>Location : Rack And Pinion Assemblies</i> <i>Explanation : Some Surface Corrosion And Debris Buildup On Interior Of Rack And Support.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HAMILTON AVENUE BRIDGE SOUTHBOUND LEAF
Asset # : 4217

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Structural Bearings								
Generic	75%	Now	\$5,100	2047			* *	
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Counter weight Pit And Bascule Span</i>								
<i>Explanation : Bumper Block Wood Is Splitting. Some Live Load Bearings And Centering Guide Bolts Covered In Debris.</i>								
Generic	25%			2047			* *	
Traffic Devices								
Barrier Gate								
	60%	Now	\$241,600	2047			* *	
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Barrier Gates</i>								
<i>Explanation : Oncoming Gate Has Crack In Arm Weld. Off Going Gate Has Damaged Gate Housing And Guy Wires Need Repair; Miscellaneous Failed Bulbs Flashing Incorrectly</i>								
Barrier Gate	40%			2047			* *	
Warning Gate	100%	Now	\$5,900	2047			* *	
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Warning Gates</i>								
<i>Explanation : Some Repairs Required.</i>								
Trunnion								
Generic	35%	Now	\$41,900	2069			* *	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : West Trunnions</i>								
<i>Explanation : Missing Or Broken Grease Fittings. Some Coverage Of Debris And Minor Corrosion.</i>								
Generic	65%			2069			* *	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HUNTERS POINT AVE. BRIDGE HUNTERS POINT AVE BR/DUTCH KILLS
 Address : HUNTERS POINT AVE.
 Borough : QUEENS Agency's Number : N/A
 Program / Asset # : DOT0178.000 / 13712 Yr Built/Renovated :
 Area Sq Ft : 11,544 Project Type : WATERWAY BRIDGES
 Date of Survey : 06-Apr-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2240450

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$158,200	\$353,700
Bridge Electrical	\$348,700	\$201,700
Bridge Mechanical	\$1,403,100	
Total	\$1,910,000	\$555,400
Importance Code A		\$239,500
Importance Code B	\$1,910,000	\$315,900
Total	\$1,910,000	\$555,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$92,700		\$56,400	\$3,200
Bridge Electrical	\$31,800			
Bridge Mechanical	\$91,500			
Total	\$216,000		\$56,400	\$3,200
Importance Code A	\$29,700		\$11,900	
Importance Code B	\$160,600		\$11,500	
Importance Code C	\$25,700		\$33,100	\$3,200
Total	\$216,000		\$56,400	\$3,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTERS POINT AVE. BRIDGE HUNTERS POINT AVE BR/DUTCH KILLS
Asset # : 13712

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Steel	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : Begin And End Abutment</i>								
<i>Explanation : Debris On Bridge Seat.</i>								
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Steel	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : Begin And End Abutment.</i>								
<i>Explanation : Debris On Bearings.</i>								
Footings Not Accessible	100%							
Joint with Deck Generic	100%	Now	\$23,000	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Joint Armor At Middle Of End Abutment</i>								
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Begin And End Abutment</i>								
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Begin And End Abutment</i>								
<i>Explanation : Joint Sealer Cracked And Allows Water And Debris On Bridge Seat.</i>								
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%			LIFE		**		
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Riprap	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Masonry: Stone	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : All 4 Wingwalls</i>								
<i>Explanation : Efflorescence Located On The Wingwalls</i>								
Feature Crossed								
Bank Protection Riprap	100%	4+	\$1,300	LIFE		**		
<i>Erosion, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Begin Abut. Left Side Embankment.</i>								
Mat (scour & erosion) Stream Bed	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTERS POINT AVE. BRIDGE HUNTERS POINT AVE BR/DUTCH KILLS
Asset # : 13712

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Timber	100%	4+	\$158,200	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i>								
<i>Location : Pier 1 And Bascule Pier 2</i>								
<i>Rotted, Extent : Light, Area Affected : 20%</i>								
<i>Location : Both Piers</i>								
Approaches								
Pavement								
Concrete	100%	4+	\$4,400	2043		**	4	\$600
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : End Approach</i>								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Sidewalks								
Concrete	100%	4+	\$5,200	LIFE		**		
<i>Settlement, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Both Approaches</i>								
Piers								
Stem,Solid Pier								
Masonry	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Steel	5%	Now	\$1,200	LIFE		**	2-8	\$900
<i>Other Observation, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Pier 1 Span 2 Side Right Bearing</i>								
<i>Explanation : Right Bearing At Pier 1 Is Bouncing Under Live Load.</i>								
Steel	95%			LIFE		**	2-8	\$900
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Misaligned/Bulging, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 3, Left (North) Curb At Pier 3.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTERS POINT AVE. BRIDGE HUNTERS POINT AVE BR/DUTCH KILLS
Asset # : 13712

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Gratings								
Grating w/ Concrete	100%	4+	\$27,200	2054	**			
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Spans 2 And 3</i>								
<i>Explanation : Concrete Fill Missing At Scattered Locations. Scattered Areas Of Section Loss To Grating.</i>								
Railings/Parapets								
Steel	100%	4+	\$1,300	LIFE	**	2-8	\$9,600	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 2 And 3, Left (North) Railing, Missing 6 Bolts At Splice Locations And 1 Bolt At Pier 3</i>								
Sidewalks								
Concrete	100%			2039	**	5	\$6,400	
<i>Cracking/Crumbling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Both Sidewalks</i>								
Wearing Surface								
Concrete	100%			2043	**	5	\$66,200	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Spans 1, 3 And 4</i>								
<i>Explanation : Concrete Wearing Surface In Spans 1, 3 And 4.</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$125,200	
<i>Exposed Reinforcement, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 3</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 3</i>								
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Spans 1, 3 And 4</i>								
<i>Explanation : Located In Spans 1, 3, And 4</i>								
Joints								
Generic	100%	Now	\$14,800	LIFE	**			
<i>Joints Missing, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : All Spans</i>								
<i>Leakage, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : All Spans</i>								
<i>Loose Joint Plates, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Span 1 Right Sidewalk</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$213,400	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Spans 1, 3 And 4</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout; Worst Case Bottom Flanges</i>								
<i>Explanation : Paint Peeling</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTERS POINT AVE. BRIDGE HUNTERS POINT AVE BR/DUTCH KILLS
Asset # : 13712

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure Secondary Member Steel	100%	4+	\$14,200	LIFE	**	2-8	\$178,800	
<i>Corrosion, Extent : Light, Area Affected : 5%</i> <i>Location : Spans 1, 3 And 4</i> <i>Other Observation, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout; Worst Case Bottom Flanges</i> <i>Explanation : Paint Peeling</i>								
Movable Bridges Bascule Span Steel	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Spans 1, 3 And 4</i> <i>Explanation : Minor Corrosion.</i>								
Bascule Span Pier Concrete	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Piers 2 And 3</i> <i>Explanation : Fine Vertical Cracks</i>								
Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical Communications Generic	100%	Now	\$800	2033	\$41,100			
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Telephone</i> <i>Explanation : Telephone In Control Room Needs Repair.</i>								
Control System Electrical Control Console Stainless Steel	100%	Now	\$2,200	LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i> <i>Location : Indication Lights D Meters</i> <i>Explanation : The Indication Lights Need Replacement/ Relamping.</i>								
Disconnect Switch Generic	100%			2051	**			
Limit Switch Generic	100%			2051	**			
Electrical Power Transfer Switch Auto	100%	4+	\$2,200	2047	**			
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i> <i>Location : Circuit Breaker Transfer</i> <i>Explanation : Circuit Breaker Transfer Switch Making Noise When Turned Off</i>								
Transformer Dry	100%			2051	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTERS POINT AVE. BRIDGE HUNTERS POINT AVE BR/DUTCH KILLS
Asset # : 13712

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Electrical Power								
Heating								
Generic	100%			2051		**		
Dist Equip & Motor Controll								
Generic	100%	Now	\$266,100	2047		**		
			<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Electrical Room Drive Cabinet</i>					
			<i>Explanation : Secondary Motor Drive System Not Functioning.</i>					
Raceway								
Submarine Control Cables								
Generic	100%			2038		**		
Wiring								
Generic	100%			2038		**		
Stand-by Power								
Generator								
Natural Gas	100%	Now	\$82,600	2054		**		
			<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location :</i>					
			<i>Explanation : Generator Is Inoperable</i>					
Traffic System Electrical								
Traffic Signal								
Generic	100%	Now	\$4,000	2033	\$201,700			
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>					
			<i>Location : East Side</i>					
Lighting								
Lighting Devices								
Generic	100%	Now	\$22,700	2038		**		
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Navigation Lighting</i>					
			<i>Explanation : All Navigational Lights Need Relamping. Majority Of Lights In Control House Need Relamping.</i>					
Bridge Mechanical								
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Counter Weight								
Generic	100%	Now	\$91,400	2062		**		
			<i>Other Observation, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Counter Weight.</i>					
			<i>Explanation : Paint Failure. Some Bounce, Balance May Need Adjustment.</i>					
Emergency Drive								
Emergency Power	100%	Now	\$41,800	2049		**		
			<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location : Control House And Machine Room</i>					
			<i>Explanation : Emergency Operation Not Tested. Reported Not Run In Many Years. System Should Be Tested Periodically.</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTERS POINT AVE. BRIDGE HUNTERS POINT AVE BR/DUTCH KILLS
Asset # : 13712

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Houses								
Access Ways	100%	Now	\$10,400	2043		**		
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Access Hatches</i>								
<i>Explanation : Some Hatches Can Not Be Opened.</i>								
Control House	100%	Now	\$243,000	2062		**		
<i>Other Observation, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Control House</i>								
<i>Explanation : House Plumbing Needs Repair. Walls And Ceiling Removed.</i>								
Machinery Room	100%	Now	\$21,200	2069		**		
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Machine Room</i>								
<i>Explanation : Minor Leakage From Ceiling</i>								
Lock Bars								
With Motor	50%	Now	\$89,500	2043		**		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Toe Locks</i>								
<i>Explanation : Some Corrosion. Some Movement Observed May Require Adjustment With Live Load Bearings. Some Areas Dry Of Lubricant.</i>								
With Motor	50%	Now	\$149,200	2043		**		
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Tail Locks</i>								
<i>Explanation : Full Functional Operation Not Observed. Heavy Corrosion. Note Part Of Assembly Is Under Water When Pit Fills With Water.</i>								
Main Drive System								
Generic	100%	Now	\$289,100	2069		**		
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Machinery Room</i>								
<i>Explanation : Currently Not Operational. Adjustment May Be Required For Firm Bridge Seating.</i>								
Rack								
Generic	100%	Now	\$125,100	2069		**		
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Racks</i>								
<i>Explanation : No Operation Observed. Moderate Corrosion On Some Teeth And Fasteners. Some Lube In Poor Condition.</i>								
Structural Bearings								
Generic	100%	Now	\$18,200	2047		**		
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Live Load Bearings At Toe</i>								
<i>Explanation : Corrosion And Substantial Movement Under Traffic Loading.</i>								
Track								
Generic	100%	Now	\$68,600	2069		**		
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Track Supports</i>								
<i>Explanation : No Operation Observed. Minor To Moderate Corrosion Observed On Track Supports. Paint Failure.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUNTERS POINT AVE. BRIDGE HUNTERS POINT AVE BR/DUTCH KILLS
Asset # : 13712

Bridge Mechanical	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Traffic Devices								
Barrier Gate	100%	Now	\$200,000	2043			* *	
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Barrier Gates</i>								
<i>Explanation : The Barrier Gates Are Currently Not In Service. Some Corrosion Observed.</i>								
<i>Repairs Required. Loose Covers And Platforms. Missing Rope.</i>								
Warning Gate	100%	Now	\$147,200	2037			* *	
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Warning Gates</i>								
<i>Explanation : No Observation Observed. Missing Hardware. Damaged Arm. Grout Pad Cracking. Repairs Required.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HUTCHINSON RIVER PARKWAY BRIDGE HUTCHNS RIV PKY/HUTCHINSON RIVER
 Address : BARTOW AVE X-ING HUTCH RIVER
 Borough : BRONX Agency's Number : N/A
 Program / Asset # : DOT0007.090 / 4269 Yr Built/Renovated : 1935 / 1995
 Area Sq Ft : 60,456 Project Type : WATERWAY BRIDGES
 Date of Survey : 21-Mar-2023 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 2075859

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$688,900	\$1,299,500
Bridge Electrical	\$1,181,200	\$2,885,600
Bridge Mechanical	\$2,510,900	
Total	\$4,381,000	\$4,185,200
Importance Code A	\$543,000	\$523,300
Importance Code B	\$3,692,100	\$3,516,000
Importance Code C	\$145,800	\$145,800
Total	\$4,381,000	\$4,185,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$56,100	\$5,700	\$114,300	
Bridge Electrical	\$3,100			
Bridge Mechanical	\$20,400			
Total	\$79,600	\$5,700	\$114,300	
Importance Code A			\$51,100	
Importance Code B	\$50,900		\$63,200	
Importance Code C	\$28,700	\$5,700		
Total	\$79,600	\$5,700	\$114,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE HUTCHNS RIV PKY/HUTCHINSON RIVER
Asset # : 4269

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Begin Abutment</i>					
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$17,100	LIFE		**		
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 25%</i>					
			<i>Location : Begin Joint Between G3 And G4.</i>					
			<i>Leakage, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Begin And End Joint</i>					
			<i>Missing/Damaged Seal, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Begin And End Joint</i>					
			<i>Rust Stains, Extent : Light, Area Affected : 50%</i>					
			<i>Location : Begin Abutment</i>					
			<i>Spalling, Extent : Light, Area Affected : 1%</i>					
			<i>Location : End Joint Header</i>					
Mat (scour & erosion)								
Earth	100%	4+	\$10,200	LIFE		**		
			<i>Erosion, Extent : Light, Area Affected : 15%</i>					
			<i>Location : End Abutment Drainage</i>					
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Brick Veneer	10%	4+	\$2,900	LIFE		**		
			<i>Other Observation, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Areas Of Wingwalls</i>					
			<i>Explanation : Efflorescence</i>					
Brick Veneer	90%			LIFE		**		
Concrete	100%			LIFE		**		
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE HUTCHNS RIV PKY/HUTCHINSON RIVER
Asset # : 4269

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 4 And 5.</i>								
<i>Explanation : Granite Block Facade</i>								
Timber	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 2 And 3.</i>								
<i>Explanation : Piers 2 And 3.</i>								
Approaches								
Pavement								
Concrete	100%	Now	\$24,900	2047	**	4	\$36,500	
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : End Approach</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : End Approach</i>								
Curbs								
Concrete	100%			LIFE	**			
Embankment								
Earth	100%			LIFE	**			
Guide Railing								
Steel	100%			LIFE	**	2-8	\$5,500	
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Sidewalks								
Asphalt	100%			2038	**	4	\$2,700	
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 - 7.</i>								
<i>Explanation : Sidewalk On West Side Only</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : South Approach</i>								
<i>Explanation : Two Scuppers Total</i>								
Piers								
Cap Beam								
Steel	100%			LIFE	**	2-8	\$36,600	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE HUTCHNS RIV PKY/HUTCHINSON RIVER
Asset # : 4269

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns								
Brick Veneer	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Pier 2, Column 3; Pier 3, Column 3; Pier 4, Column 3; Pier 5, Column 1</i>								
<i>Explanation : Cracked Or Deteriorated Bricks</i>								
Concrete	100%			LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Pier 2, Column 1</i>								
Granite	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 4, 5, 6</i>								
<i>Explanation : Granite At Base.</i>								
Steel	100%			LIFE		**	2-8	\$92,200
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 2 And 3</i>								
<i>Explanation : Steel Columns Encased In Concrete.</i>								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 2 And 3</i>								
<i>Explanation : Solid Concrete Stem.</i>								
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2060		**		
Steel	100%	4+	\$55,100	LIFE		**	2-8	\$8,200
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Piers 2 And 3</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Pier 2 Pedestal 1</i>								
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
Guide Railing								
Steel	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE HUTCHNS RIV PKY/HUTCHINSON RIVER
Asset # : 4269

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Median								
Concrete	100%			LIFE	**	5	\$10,200	
<i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : Spans 1 And 6 Median</i> <i>Explanation : Broken Electrical Box Covers</i>								
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$65,700	
<i>Corrosion, Extent : Light, Area Affected : 1%</i> <i>Location : Span 7 West Railing</i>								
Sidewalks								
Concrete	100%			2042	**	5	\$11,400	
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Spans 1, 2, 4 - 7</i> <i>Spalling, Extent : Light, Area Affected : 1%</i> <i>Location : Span 6</i>								
Wearing Surface								
Concrete	100%			2047	**	5	\$291,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Spans 1, 2, 4 - 7</i> <i>Explanation : Concrete Wearing Surface.</i>								
Steel Grating	100%			LIFE	**	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Span 3</i> <i>Explanation : Bascule Span Steel Grating.</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Throughout</i> <i>Explanation : Twenty Scuppers Total</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$47,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Spans 1, 2, 4 - 7</i> <i>Explanation : Concrete Deck.</i>								
Grating w/ Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Span 2 And 4</i> <i>Explanation : Half The Spans Have Grating With Concrete.</i>								
Steel Grating	100%			LIFE	**	5	\$58,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Span 3</i> <i>Explanation : Steel Grating Deck.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE HUTCHNS RIV PKY/HUTCHINSON RIVER
Asset # : 4269

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Generic	100%			LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 1%</i>								
<i>Location : Joint Between Bascule Spans</i>								
<i>Leakage, Extent : Light, Area Affected : 1%</i>								
<i>Location : All Spans</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$868,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1, 2, 4 - 7</i>								
<i>Explanation : Structural Steel</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$936,200	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1, 2, 4 - 7</i>								
<i>Explanation : Structural Steel</i>								
Movable Bridges								
Bascule Span								
Steel	90%			LIFE	**			
Steel	10%	Now	\$437,600	LIFE	**			
<i>Other Observation, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Span 3</i>								
<i>Explanation : Based On Biennial Inspection Flags, Holes In Stringer And Purlins. Not Accessible</i>								
Bascule Span Pier								
Concrete	95%			LIFE	**			
Concrete	5%	4+	\$50,300	LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : North Leaf At Pier 3</i>								
<i>Explanation : Cracking Of Concrete And Exposed Reinforcement At Trunnion Bearing Pedestal.</i>								

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Communications								
Generic	100%			2032	\$41,100			
Control System Electrical								
Control Console								
Generic	100%	Now	\$900	2047	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Control Room</i>								
<i>Explanation : Some Pilot Lights Were Burnt Out</i>								
Disconnect Switch								
Generic	100%			2047	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE HUTCHNS RIV PKY/HUTCHINSON RIVER
Asset # : 4269

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Control System Electrical

Limit Switch

Generic

100% Now \$2,300 2054 **

*Other Observation, Extent : Light, Area Affected : 25%**Location : Southwest Machinery Area**Explanation : Southwest Fully Seated Proximity Limit Switch Was In Contact With Its Target.***Electrical Power**

Transformer

Dry

100% 2039 **

Heating

Generic

100% 2039 **

Dist Equip & Motor Controll

Generic

100% 2-4 \$582,500 2047 **

*Other Observation, Extent : Moderate, Area Affected : 100%**Location : Transfer Switch**Explanation : Only One Power Source Available; Transfer Switch Cannot Be Used Because Only One Source Of Power Is Available***Raceway**

Submarine Control Cables

Generic

100% 2032 \$971,800

Wiring

Generic

100% Now \$537,300 2035 \$1,791,000

*Other Observation, Extent : Moderate, Area Affected : 30%**Location : Below Machine Rooms And At Back Wall**Explanation : Conduits Corroding***Lighting**

Lighting Devices

Generic

100% Now \$61,400 2032 \$122,800

*Other Observation, Extent : Light, Area Affected : 50%**Location : Outside**Explanation : All Machinery Room Area Lights Have Failed; Several Of The Span Navigation Lights Were Damaged, Turned The Wrong Way, Or Out.*

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Bascule

Counter Weight

Generic

100% Now \$128,600 2049 **

*Other Observation, Extent : Moderate, Area Affected : 10%**Location : Counterweights**Explanation : Bridge Bounces. Some Balancing May Be Needed.*

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE HUTCHNS RIV PKY/HUTCHINSON RIVER
Asset # : 4269

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Emergency Drive Emergency Power	100%	Now	\$114,500	2049		**		
<i>Other Observation, Extent : Severe, Area Affected : 50%</i> <i>Location : All Machine Rooms</i> <i>Explanation : Emergency Drive Was Reported Not Be Working. Should Be Repaired And Tested.</i>								
Houses								
Access Ways	100%	Now	\$56,100	2037		**		
<i>Other Observation, Extent : Severe, Area Affected : 50%</i> <i>Location : Access Ways</i> <i>Explanation : Some Doors Do Not Close Properly. Open Pier Area Behind South Inboard Trunnions. Corroded Grating In Some Areas.</i>								
Auxiliary	100%	Now	\$65,800	2037		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i> <i>Location : South Auxiliary House</i> <i>Explanation : Leaky Door And Windows.</i>								
Control House	100%	Now	\$60,700	2049		**		
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i> <i>Location : Control House</i> <i>Explanation : Leaky Door. Exhaust Fan Non-functioning Bathroom Not Functioning. Air Conditioning Does Not Work.</i>								
Machinery Room	100%	Now	\$20,400	2049		**		
<i>Other Observation, Extent : Moderate, Area Affected : 60%</i> <i>Location : Machine Rooms</i> <i>Explanation : Some Doors Do Not Close Properly.</i>								
Lock Bars								
With Motor	100%	Now	\$643,200	2037		**		
<i>Other Observation, Extent : Severe, Area Affected : 60%</i> <i>Location : Span Lock Bars</i> <i>Explanation : Movement Of Spans Observed From Sidewalk, Locks And Live Load Bearings Require Adjustments. One Lock Does Not Work.</i>								
Main Drive System								
Generic	100%	0-2	\$583,200	2049		**		
<i>Other Observation, Extent : Moderate, Area Affected : 60%</i> <i>Location : Machine Rooms</i> <i>Explanation : Lubricant Leakage. Brake Adjustments May Be Required. Some Limit Switch Repairs Needed.</i>								
Rack								
Generic	100%	Now	\$122,800	2049		**		
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i> <i>Location : Racks</i>								
Structural Bearings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HUTCHINSON RIVER PARKWAY BRIDGE HUTCHNS RIV PKY/HUTCHINSON RIVER
Asset # : 4269

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Traffic Devices								
Barrier Gate	100%	Now	\$457,900	2043			* *	
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Barrier Gates</i>								
<i>Explanation : Some Paint Failure. Open Areas. Some Adjustments Needed. Last Condition Report Lists As Near Time To Replace; Misc Gates Have Missing Or Burnt Out Arm Lights; Lights Do Not Flash</i>								
Warning Gate	100%	Now	\$203,700	2043			* *	
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Warning Gates</i>								
<i>Explanation : Some Repairs And Adjustments Needed. Some Guy Wire May Need Adjustment. Last Condition Report Lists As Near Time To Replace; Warning Gongs Were Not Effectively Sounding</i>								
Trunnion								
Generic	100%	Now	\$74,400	2049			* *	
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Trunnion Bearings</i>								
<i>Explanation : Bearing Debris Covers May Rub.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : **MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER**
 Address : **E.155 ST. AND HARLEM RIVER**
 Borough : **MANHATTAN:BX.** Agency's Number : **N/A**
 Program / Asset # : **DOT0137.000 / 4180** Yr Built/Renovated : **1931 / 2004**
 Area Sq Ft : **275,000** Project Type : **WATERWAY BRIDGES**
 Date of Survey : **27-Apr-2021** Landmark Status : **EXTERIOR LANDMARK**
 Areas Surveyed :
 Block : Lot : BIN : **1240090**

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$10,379,000	\$7,687,800
Bridge Mechanical	\$396,000	
Total	\$10,775,000	\$7,687,800
Importance Code A	\$9,713,000	\$3,184,700
Importance Code B	\$566,100	\$3,185,100
Importance Code C	\$495,900	\$1,318,000
Total	\$10,775,000	\$7,687,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$119,600		\$623,200	
Bridge Electrical	\$109,600	\$6,700	\$6,700	\$6,700
Bridge Mechanical	\$183,900		\$80,800	
Total	\$413,000	\$6,700	\$710,700	\$6,700
Importance Code A	\$19,900		\$303,800	
Importance Code B	\$329,100	\$6,700	\$406,900	\$6,700
Importance Code C	\$64,000			
Total	\$413,000	\$6,700	\$710,700	\$6,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER
Asset # : 4180

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Granite	100%			LIFE		**		
Backwall								
Masonry	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE		**		
			<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Begin Abutment Girder Bearings</i>					
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	Now	\$6,500	LIFE		**		
			<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 75%</i>					
			<i>Location : Beginning Abutment Joint Sealer Damaged. End Abutment Joint Missing For 3 Ft. Begin Abutment Joint Was Noted To Be Replaced During Previous Biennial Inspection.</i>					
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Masonry: Granite	100%			LIFE		**		
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
Masonry: Granite	100%	4+	\$26,500	LIFE		**		
			<i>Broken/Missing Elements, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Beginning Right Wingwall Has Voids And Displacement 4 Inches.</i>					
Feature Crossed								
Bank Protection								
Concrete	100%			LIFE		**		
Riprap	100%			LIFE		**		
			<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Pier 35 Rip Rap At Northwest Corner Missing Stones</i>					
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER
Asset # : 4180

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Feature Crossed								
Pier Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Pier 36</i>								
<i>Explanation : Concrete With Rubber Bumpers.</i>								
Approaches								
Pavement								
Asphalt	100%	0-2	\$21,100	2033	\$1,054,400	4	\$29,500	
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Begin And End Approach Relief Joints</i>								
Concrete	100%			2041		**	4	
Curbs								
Steel	100%			LIFE		**		
Guide Railing								
Steel	100%			LIFE		**	2-8	\$18,100
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE		**		
Piers								
Cap Beam								
Steel	100%	4+	\$282,100	LIFE		**	2-8	\$1,633,900
<i>Corrosion, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Pier 34 Steel Cap Beam</i>								
<i>Recent Repair Evident, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Spans 1 Through 30</i>								
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$2,821,200
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Piers 1 To 30</i>								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
Masonry	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER
Asset # : 4180

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Brngs,Ancr Blts,Pads Elastomeric	100%	4+	\$77,900	2052		**		
<i>Corrosion, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Pier 32 Girder 5</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Pier 35, Girder 5; Pier 45 Girder 1</i>								
<i>Explanation : Pier 35 Bearing Is In Extreme Expansion Overhanging Pedestal At Begin Left Corner. Pier 45 Bearing Elastomer Is Torn.</i>								
Steel	25%	Now	\$89,800	LIFE		**	2-8	\$49,000
<i>Bearings Frozen, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Pier 6 Expansion Bearings Are Frozen.</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Piers 1 To 35</i>								
Steel	70%			LIFE		**	2-8	\$49,000
Steel	5%	Now	\$35,900	LIFE		**	2-8	\$49,000
<i>Loose Fastenings, Extent : Light, Area Affected : 5%</i>								
<i>Location : Pier 38 End Bearings At Truss 2 And 5 And Begin Bearing At Truss 1</i>								
<i>Missing Fastenings, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Pier 38 Begin And End Bearings At Truss 1 - 2 Of 3 Missing Anchor Bolts Each.</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%	4+	\$14,900	LIFE		**		
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Pier 40</i>								
Steel	100%	4+	\$14,300	LIFE		**		
<i>Loss of Section, Extent : Light, Area Affected : 2%</i>								
<i>Location : Piers 6, 10, 27</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Piers 1 To 30</i>								
Deck Elements								
Curbs								
Steel	100%			LIFE		**		
Guide Railing								
Concrete	100%			2045		**		
Steel	100%			LIFE		**		
Mono Deck Surface								
Concrete	100%			2052		**	5	
Railings/Parapets								
Steel	100%	Now	\$19,900	LIFE		**	2-8	\$136,600
<i>Damaged Railing, Extent : Severe, Area Affected : 1%</i>								
<i>Location : Span 52 Right Pedestrian Fence</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER
Asset # : 4180

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	1%	Now	\$1,400	2037	**	5	\$53,600	
<i>Spalling, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Span 35, Left Sidewalk At Pier 35</i>								
Concrete	99%			2037	**	5	\$107,100	
Wearing Surface								
Concrete	100%	0-2	\$259,100	2041	**	5	\$156,400	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Scattered Locations Throughout The Bridge</i>								
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Spans 4, 5, 6, 7, 11, 15, 18, 36, 37, 39, And 40</i>								
Scupper								
Cast Iron	10%	Now	\$15,000	LIFE	**			
<i>Drains Clogged, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Span 37 (1st Left Scupper), 40 (2nd Left Scupper), 51 (3rd Left Scupper), 52 (1st And 2nd Left Scuppers)</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Spans 47 To 52</i>								
<i>Explanation : Left And Right Scuppers Are Filled Up To 50 Percent.</i>								
Cast Iron	90%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 To 52</i>								
<i>Explanation : Each Span Typically Exhibits At Least 2 Scuppers. Total Number Of Scuppers = 207.</i>								
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$1,257,000	LIFE	**	5	\$164,400	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Stay In Place Corrosion In Spans 42, 43, 44, 45</i>								
Joints								
Steel	100%			LIFE	**			
Generic	100%	Now	\$183,200	LIFE	**			
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Piers 8, 20, And 29 - Missing Joint Plates</i>								
<i>Joints Missing, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Piers 45 And 50 (3 LF Each)</i>								
<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Piers 14 (50 Pct Length), 17 (60 Pct Length), 39 (50 Pct Length), 48 (30 Pct Length), 50 (10 Pct Length)</i>								
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout Bridge</i>								
<i>Explanation : Bridge Cannot Operate Clockwise Or Will Get Jammed Due To Thermal Expansion.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER
Asset # : 4180

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Primary Member								
Steel	95%			LIFE	**	2-8	\$2,059,400	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 10%</i>								
<i>Location : Spans 1 To 30</i>								
Steel	5%	4+	\$301,200	LIFE	**	2-8	\$2,059,400	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Span 40 Bottom Chord Eyebars. Floorbeams And Steel Trusses In Spans 38-40 & 48-52.</i>								
<i>Missing Fastenings, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Steel Trusses In Spans 39 And 40. Girder In Span 41.</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Span 16 And Span 40, North Side At East End Of Through Truss.</i>								
<i>Explanation : Truss Girders Exhibit Pack Rust. Drawbridge Signal Conduit Is Missing A Cover Exposing A Wire Easily Accessible By Pedestrians.</i>								
Secondary Member								
Steel	90%			LIFE	**	2-8	\$1,725,200	
Steel	10%	4+	\$170,200	LIFE	**	2-8	\$1,725,200	
<i>Corrosion, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Spans 23, 26, 30, 37, And 40 At Cross Frame Diaphragms.</i>								
Movable Bridges								
Swing Span Truss								
Steel	100%	4+	\$7,669,100	LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Spans 36 And 37</i>								
<i>Explanation : Minor Corrosion And Minor Section Losses To Primary And Secondary Members</i>								
Swing Span Pivot Pier								
Concrete	100%			LIFE	**			

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Air Horn								
Generic	100%			2031	\$2,700			
Communications								
Generic	90%	Now	\$16,200	2031	\$40,600			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout Bridge</i>								
<i>Explanation : Intercom Is Not Functioning Due To Hardware And Cable Issues.</i>								
Generic	5%	Now	\$1,100	2031	\$2,300			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Manhattan Side Of Bridge Has The Phone Line Feed.</i>								
<i>Explanation : Wall Mounted Phone Not Working</i>								
Generic	5%			2031	\$2,300			
Control System Electrical								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER
Asset # : 4180

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Control System Electrical								
Computer PLC	100%	Now	\$12,900	2031	\$32,300			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Programmable Logic Controller Cabinet</i>								
<i>Explanation : Programmable Logic Controller Has Issues With Program Retention.</i>								
Control Console								
Stainless Steel	100%	Now	\$47,800	LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Control Room</i>								
<i>Explanation : Many Pilot Lights Are Foggy, Operator Cannot See Light</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Control Desk</i>								
<i>Explanation : To Turn Traffic Signals Green, Bypass Is Needed To Be Operated On Control Desks.</i>								
Disconnect Switch Non Fused	100%			2049	**	1	\$35,900	
Limit Switch Generic	100%	Now	\$600	2049	**			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Control Room</i>								
<i>Explanation : Remount/remove Tape Located On North East. Fully Closed Limit Switch.</i>								
<i>Limit Switch Covers Missing Fasteners.</i>								
Local Starter Magnetic	100%			2049	**			
Drive								
Machinery Brake Thruster	100%			2058	**	1	\$600	
Motor Brake Thruster	100%			2058	**	1	\$1,100	
Electrical Power								
MCC								
Generic	10%	Now	\$1,900	2049	**			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Machine Room Motor Control Center</i>								
<i>Explanation : Northwest Endlift Not Operating</i>								
Generic	90%			2049	**			
Panelboard								
Circuit Breaker	100%			2049	**	1	\$6,700	
Transfer Switch								
Auto	100%			2049	**			
Ground/Lightning Protection								
Ground Bus								
Copper	100%			2037	**			
Ground Rod								
Not Accessible	100%							
Ground Wire								
Green	100%			2036	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER
Asset # : 4180

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Raceway								
Box								
Pull Junction	100%			2040	**	1	\$3,900	
Terminal	100%			2040	**	1	\$4,500	
Collector Ring								
Metal	100%			2040	**			
Submarine Control Cables								
Control	100%			2036	**			
Submarine Power Cable								
Power	100%			2036	**			
Trough								
Metal	100%			2067	**	1	\$1,100	
Wires								
Thermoplastic	100%			2045	**			
Wiring								
Generic	99%			2036	**			
Generic	1%	Now	\$400	2036	**			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Span 40</i>								
<i>Explanation : Drawbridge Ahead Sign Conduit Damage</i>								
Span Lock								
Motor								
Squirrel Cage	100%			2045	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : West Rest Pier</i>								
<i>Explanation : Span Lock Description Used For Endlifts Motors: Northwest End Lift Not Operational</i>								
Stand-by Power								
Transfer Switch								
Auto	100%			2052	**			
Lighting								
Lighting Devices								
Generic	40%			2036	**			
Generic	10%	Now	\$700	2036	**			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Outside Control Room On Access Platform</i>								
<i>Explanation : Exterior Access Light Fixtures Failed.</i>								
Generic	50%	Now	\$21,200	2036	**			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Collector Area</i>								
<i>Explanation : Lighting In Collector Area Not Operational</i>								
Main Drive								
Motor Controller								
Thyristor Drive	100%			2040	**	1-5	\$15,900	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Control Room</i>								
<i>Explanation : No Operation Observed</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER
Asset # : 4180

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Swing								
Center Latch Generic	100%	Now	\$43,300	2060	**	2	\$18,000	
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : East And West</i>								
<i>Explanation : Could Not Be Tested. Operation Reported To Be Problematic.</i>								
Center Pivot Generic	100%			2060	**	2	\$67,400	
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Rim Bearing At Center Pivot Pier</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Center Pivot Pier</i>								
<i>Explanation : Could Not Be Tested.</i>								
Emergency Drive Emergency Power	100%	Now	\$10,800	2060	**	2	\$35,900	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Swing Span Machinery Room</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Swing Span Machinery Room</i>								
<i>Explanation : Operation Was Not Observed. Battery Charger Was Not Working. Cut Out Coupling Has Painters Tape.</i>								
End Lift Generic	100%	Now	\$25,700	2060	**	2	\$35,900	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : East And West Rest Piers</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : East And West Rest Piers</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : East And West Rest Piers</i>								
<i>Explanation : Could Not Be Tested.</i>								
Fuel Tanks Generic	100%			2045	**			
Houses								
Access Ways	100%	Now	\$28,000	2060	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Swing Span Access Hatches</i>								
<i>Explanation : Hatches Need Maintenance. Step Ladders At End Lift Machinery Level Corroded. Bilco Hatch Has Failed Hydraulic Piston.</i>								
Control House	100%	Now	\$6,100	2060	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Control House</i>								
<i>Explanation : Door Lock Operation Problematic. Windows Do Not Open And Are Foggy.</i>								
Machinery Room	100%	Now	\$11,200	2060	**			
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Machinery Room</i>								
<i>Explanation : Door Handles Need Repair. Heat Does Not Work.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
MACOMBS DAM BRIDGE E.155 ST./HARLEM RIVER**

Asset # : 4180

Bridge Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Swing Main Drive System Generic	100%	Now	\$343,900	2060		**	2	\$179,600
<i>Corrosion, Extent : Severe, Area Affected : 10%</i> <i>Location : Operating Machinery</i> <i>Lubrication Issue, Extent : Severe, Area Affected : 10%</i> <i>Location : Operating Machinery</i> <i>Other Observation, Extent : Severe, Area Affected : 10%</i> <i>Location : Operating Machinery</i> <i>Explanation : No Testing Was Observed. Loose Brake Covers. Coupling Cover Missing Fastener. Some Bearings Leaking Oil. Reducer Oil Levels Low. Animal Droppings Observed On Oil Absorbing Material.</i>								
Structural Bearings Generic	100%			2041		**		
<i>Corrosion, Extent : Light, Area Affected : 2%</i> <i>Location : East And West Rest Piers</i> <i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : East And West Rest Piers</i> <i>Explanation : Debris Observed.</i>								
Traffic Devices Barrier Gate	100%	Now	\$52,100	2041		**		
<i>Other Observation, Extent : Severe, Area Affected : 5%</i> <i>Location : East And West Approaches</i> <i>Explanation : Could Not Be Tested.</i>								
Warning Gate	36%	Now	\$34,900	2041		**		
<i>Other Observation, Extent : Severe, Area Affected : 5%</i> <i>Location : Pedestrian Gates</i> <i>Explanation : Pedestrian Gate Arms Removed. Access Gates Bent. Could Not Be Tested.</i>								
Warning Gate	64%	Now	\$10,300	2041		**		
<i>Other Observation, Extent : Severe, Area Affected : 5%</i> <i>Location : Warning Gates</i> <i>Explanation : Could Not Be Tested. Northwest Warning Gate Is Not Fully Horizontal When Lowered</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : MADISON AVE. BRIDGE MADISON AVE. BRIDGE/HARLEM RIVER
Address : HARLEM RIVER, HARLEM RIV DR.
Borough : MANHATTAN:BX. **Agency's Number** : N/A
Program / Asset # : DOT0042.090 / 4209 **Yr Built/Renovated** : 1907 / 2004
Area Sq Ft : 69,800 **Project Type** : WATERWAY BRIDGES
Date of Survey : 29-May-2014 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240079

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,023,800	\$2,650,000
Bridge Electrical	\$277,100	\$210,600
Bridge Mechanical	\$2,699,700	
Total	\$4,000,600	\$2,860,600
Importance Code A		\$466,100
Importance Code B	\$2,976,900	\$530,200
Importance Code C	\$1,023,800	\$1,864,400
Total	\$4,000,600	\$2,860,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$11,000		\$96,000	\$45,000
Bridge Electrical	\$188,000	\$3,900	\$3,900	\$82,700
Bridge Mechanical	\$62,200		\$71,800	
Total	\$261,200	\$3,900	\$171,800	\$127,700
Importance Code A	\$1,100		\$35,900	
Importance Code B	\$254,600	\$3,900	\$107,800	\$82,700
Importance Code C	\$5,600		\$28,100	\$45,000
Total	\$261,200	\$3,900	\$171,800	\$127,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MADISON AVE. BRIDGE MADISON AVE. BRIDGE/HARLEM RIVER
Asset # : 4209

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE	**			
Backwall								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2051	**			
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	90%			LIFE	**			
Generic	10%	0-2	\$100	LIFE	**			
<i>Leakage, Extent : Light, Area Affected : 20%</i>								
<i>Location : Begin And End Abutment</i>								
<i>Missing/Damaged Seal, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Begin Abutment Joint</i>								
Pedestals								
Concrete	100%			LIFE	**			
Stem (breastwall)								
Concrete	100%			LIFE	**			
Walls								
Concrete	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Wingwalls</i>								
<i>Explanation : Beginning Wingwall Only. End Approach Has No Wingwall</i>								
Feature Crossed								
Bank Protection								
Concrete	100%			LIFE	**			
Riprap	100%			LIFE	**			
Timber	100%			2030				
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	100%			LIFE	**			
Approaches								
Pavement								
Asphalt	100%			2029	\$174,100	4	\$5,400	
Concrete	100%			2038	**	4		
Curbs								
Concrete	100%			LIFE	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MADISON AVE. BRIDGE MADISON AVE. BRIDGE/HARLEM RIVER
Asset # : 4209

Bridge Structure		Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost		
Approaches									
Guide Railing									
Steel	100%	Now	\$1,100	LIFE	**	2-8	\$11,700		
<i>Damaged Railing, Extent : Moderate, Area Affected : 5%</i>									
<i>Location : End Approach Left (North) Side.</i>									
Sidewalks									
Concrete	100%			LIFE	**				
Piers									
Cap Beam									
Steel	100%			LIFE	**	2-8	\$252,300		
Pier,Columns									
Steel	100%			LIFE	**	2-8	\$301,600		
Stem,Solid Pier									
Concrete	100%			LIFE	**				
Masonry	99%			LIFE	**				
Masonry	1%	2-4	\$100	LIFE	**				
<i>Other Observation, Extent : Moderate, Area Affected : 1%</i>									
<i>Location : Pier 12</i>									
<i>Explanation : Masonry Stone Displaced.</i>									
Brngs,Ancr Blts,Pads									
Elastomeric	100%			2051	**				
Steel	100%			LIFE	**	2-8	\$6,200		
Footings									
Not Accessible	100%								
Mat (scour & erosion)									
Not Accessible	100%								
Pedestals									
Concrete	100%	0-2	\$4,100	LIFE	**				
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>									
<i>Location : Piers 12 And 14.</i>									
Deck Elements									
Gratings									
Steel	100%			LIFE	**				
<i>Other Observation, Extent : Light, Area Affected : 1%</i>									
<i>Location : Spans 13 And 14</i>									
<i>Explanation : Spans 13 And 14</i>									
Guide Railing									
Concrete	100%			2045	**				
<i>Other Observation, Extent : Light, Area Affected : 1%</i>									
<i>Location : Spans 1 - 12 And 15 - 21.</i>									
<i>Explanation : Concrete Guide Railings Both Sides.</i>									
Steel	100%			LIFE	**				
<i>Other Observation, Extent : Light, Area Affected : 1%</i>									
<i>Location : Spans 13 And 14.</i>									
<i>Explanation : Swing Span.</i>									

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MADISON AVE. BRIDGE MADISON AVE. BRIDGE/HARLEM RIVER
Asset # : 4209

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Median								
Concrete	100%			LIFE	**	5	\$5,600	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 8 - 12 And 15 - 21.</i>								
<i>Explanation : Concrete Median.</i>								
Steel	100%			LIFE	**	4-8	\$27,500	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 13 And 14</i>								
<i>Explanation : Swing Spans</i>								
Railings/Parapets								
Steel	78%			LIFE	**	2-8	\$40,300	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 8 - 21</i>								
<i>Explanation : Pipe Railing And Chain-link Fence On Both Sides</i>								
Steel	22%			LIFE	**	2-8	\$40,300	
<i>Other Observation, Extent : Severe, Area Affected : 1%</i>								
<i>Location : Spans 1 - 7.</i>								
<i>Explanation : Pipe Railing And Chain-link Fence On One Side Only.</i>								
Sidewalks								
Concrete	78%			2033	\$1,310,500	5	\$28,100	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 8 - 21</i>								
<i>Explanation : Concrete Sidewalk On Both Sides.</i>								
Concrete	22%			2033	\$369,600	5	\$28,100	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 1 - 7.</i>								
<i>Explanation : Concrete Sidewalk On One Side Only.</i>								
Grating w/ Concrete	100%			2051	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 13 And 14.</i>								
<i>Explanation : Swing Span</i>								
Wearing Surface								
Asphalt	100%			2029	\$665,400	5	\$84,700	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 1 - 12 (Both Sides) And 15 - 21 (Left Side)</i>								
<i>Explanation : Asphalt Wearing Surface.</i>								
Concrete	100%			2038	**	5	\$368,400	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 15 - 21 (Right Side Only)</i>								
<i>Explanation : Concrete Wearing Surface.</i>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$115,700	
Grating w/ Concrete	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 13 And 14.</i>								
<i>Explanation : Swing Span.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MADISON AVE. BRIDGE MADISON AVE. BRIDGE/HARLEM RIVER
Asset # : 4209

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Piers 12 And 14.</i>								
<i>Explanation : Steel Joint.</i>								
Generic	80%			LIFE	**			
Generic	20%	0-2	\$5,600	LIFE	**			
<i>Leakage, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Piers 3, 9, 11 And 18.</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$401,200	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$336,100	
Movable Bridges								
Swing Span Truss								
Steel	100%			LIFE	**			
Swing Span Pivot Pier								
Concrete	100%			LIFE	**			

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Intercom								
Generic	100%	Now	\$12,900	2026	\$21,500			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Entire Bridge</i>								
<i>Explanation : Intercom System Is Not Functioning</i>								
Control System Electrical								
Computer								
PLC	50%			2026	\$14,700			
PLC	50%			2026	\$14,700			
Control Console								
Stainless Steel	50%			LIFE	**			
Stainless Steel	50%			LIFE	**			
Control Devices								
Relay	100%			2042	**			
Disconnect Switch								
Generic	100%			2042	**			
Limit Switch								
Generic	100%	0-2	\$1,800	2038	**			
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : East Center End Lift</i>								
<i>Explanation : Rotary Limit Switch Missing Cover Allow Severe Corrosion.</i>								
Local Starter								
Magnetic	100%			2042	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MADISON AVE. BRIDGE MADISON AVE. BRIDGE/HARLEM RIVER
Asset # : 4209

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Drive								
Machinery Brake Thruster	100%			2045	**	1	\$600	
Motor Brake Thruster	100%			2045	**	1	\$1,100	
Span Lock Motor Generic	100%			2051	**			
Wedge Motor Generic	100%			2051	**	1	\$1,100	
Electrical Power								
MCC								
Generic	100%	Now	\$6,500	2042	**			
<i>Other Observation, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Center Pier Mcc</i>								
<i>Explanation : End Lifts Do Not Disengage. Due To This The Bridge Will Not Open.</i>								
Panelboard								
Circuit Breaker	100%			2042	**	1	\$6,700	
Service Equipment Circuit Breaker	100%			2042	**			
Transfer Switch Auto	100%			2042	**			
Transformer Dry	100%			2042	**			
Exterior Lighting								
Lighting Contactor Generic	100%			2042	**	1	\$5,600	
Lighting Fixture HID	100%			2026			\$29,600	
Pole								
Aluminum	100%			2029			\$36,000	
Interior Lighting								
Lighting Fixture Fluorescent	100%	Now	\$200	2029	\$3,900	1	\$5,000	
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Various</i>								
<i>Explanation : Service Lighting Needs Relamping Or Ballast Replacement.</i>								
Wiring Device Generic	100%			2033			\$2,900	
Navigation Lighting								
Fender Lighting Incandescent	100%	Now	\$500	2026	\$10,500	1	\$3,000	
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Center Pier</i>								
<i>Explanation : North Tip And Center East Navigation Lights Out.</i>								
Pier Lighting Incandescent	100%			2026		1	\$4,500	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MADISON AVE. BRIDGE MADISON AVE. BRIDGE/HARLEM RIVER
Asset # : 4209

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Navigation Lighting								
Span Lighting								
Incandescent	100%	Now	\$4,200	2026	\$8,300	1	\$2,000	
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Various</i>								
<i>Explanation : Various Service Lighting Fixtures Are Out. Need Relamping.</i>								
Raceway								
Box								
Pull Junction	100%	Now	\$200	2030	\$4,200	1	\$3,500	
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Machine Room</i>								
<i>Explanation : Pull Box For Grounding Transformers Is Corroded And Latches Do Not Close.</i>								
Collector Ring								
Metal	100%			2033	\$210,600			
Conduit								
Metal	100%			2060	**			
Submarine Control Cables								
Generic	100%			2029				
Submarine Power Cable								
Power	100%			2029	\$38,900			
Trough								
Metal	100%			2060	**	1	\$1,100	
Wires								
Thermoplastic	100%			2042	**			
Span Lock								
Motor								
Squirrel Cage	100%			2038	**			
Traffic System Electrical								
Barrier Gate Lighting								
Incandescent	100%			2026	\$17,200	1	\$1,100	
Traffic Gate Lighting								
Incandescent	100%	Now	\$900	2026	\$17,200	1	\$1,000	
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Sw Warning Gate</i>								
<i>Explanation : 3 Arm Lights Broken</i>								
Traffic Gong								
Generic	100%			2026	\$18,100	1	\$600	
Traffic Signal								
Generic	100%			2026	\$277,100	1	\$600	

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Swing

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
MADISON AVE. BRIDGE MADISON AVE. BRIDGE/HARLEM RIVER
Asset # : 4209

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Swing								
Center Latch Generic	100%	Now	\$31,700	2028	\$158,400	2	\$18,000	
<i>Other Observation, Extent : Severe, Area Affected : 30%</i>								
<i>Location : Center Latches</i>								
<i>Explanation : No Operation Observed. Cracks In Bar Housing.</i>								
Center Pivot Generic	100%	0-2	\$206,900	2040	**	2	\$53,900	
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Center Pivot Pier</i>								
<i>Explanation : No Operation Observed. Some Corrosion. Difficult To Access Interior.</i>								
End Lift Generic	100%	Now	\$266,000	2040	**	2	\$35,900	
<i>Other Observation, Extent : Severe, Area Affected : 30%</i>								
<i>Location : End Lifts</i>								
<i>Explanation : End Lifts Do Not Function Properly. Limit Switches And Couplings Are In Poor Condition.</i>								
Houses								
Access Ways	100%	Now	\$79,400	2040	**			
<i>Other Observation, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Accessways And Fender Decking</i>								
<i>Explanation : Corroded Grating And Supports. Some Nails Are Popping Out Of Boards Around The Pier. Missing Pinion Platform</i>								
Control House	100%	Now	\$19,800	2040	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Control House</i>								
<i>Explanation : No Heat Or Ac</i>								
Main Drive System Generic	100%	Now	\$60,800	2028	\$1,216,300	2	\$179,600	
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Drive Machinery</i>								
<i>Explanation : Bridge Could Not Be Operated. Some Corrosion. Some Rack Nuts Not Seated.</i>								
Structural Bearings Generic	100%	0-2	\$50,800	2028	\$127,100			
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Rest Piers</i>								
<i>Explanation : Grout Pads Are Deteriorating</i>								
Traffic Devices								
Barrier Gate	100%	Now	\$8,500	2028	\$426,400			
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Barrier Gates</i>								
<i>Explanation : One Missing Gate Arm Buffer Stand. Some Corrosion</i>								
Warning Gate	100%	Now	\$2,200	2028	\$107,700			
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Warning Gates</i>								
<i>Explanation : One Missing Gate Arm Buffer Stand. Some Corrosion</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : NINTH STREET BRIDGE NINTH ST. BRIDGE/GOWANUS CANAL
Address : SMITH STREET AND 2ND. AVENUE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0149.000 / 13512 **Yr Built/Renovated** : 1999 /
Area Sq Ft : 4,800 **Project Type** : WATERWAY BRIDGES
Date of Survey : 20-Mar-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240240

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Electrical	\$239,800	
Bridge Mechanical	\$1,132,400	
Total	\$1,372,200	
Importance Code B	\$1,372,200	
Total	\$1,372,200	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$7,400	\$6,800	\$100	
Bridge Electrical	\$85,000			
Bridge Mechanical	\$26,700			
Total	\$119,100	\$6,800	\$100	
Importance Code A	\$500		\$100	
Importance Code B	\$111,700			
Importance Code C	\$6,900	\$6,800		
Total	\$119,100	\$6,800	\$100	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NINTH STREET BRIDGE NINTH ST. BRIDGE/GOWANUS CANAL
Asset # : 13512

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Stem (breastwall)								
Concrete	100%			LIFE	**			
Feature Crossed								
Bank Protection								
Sheet Piling	100%			LIFE	**			
Timber	100%			2042	**			
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	100%			LIFE	**			
		<i>Split/Dry/Cracked, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Timber Protection At Begin Vertical Lift Pier</i>						
Approaches								
Pavement								
Concrete	100%			2047	**	4	\$20,300	
		<i>Cracks, Extent : Moderate, Area Affected : 2%</i>						
		<i>Location : Beginning And End Approaches</i>						
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
		<i>Corrosion, Extent : Light, Area Affected : 40%</i>						
		<i>Location : Random Locations Throughout</i>						
Embankment								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE	**			
		<i>Cracks, Extent : Light, Area Affected : 1%</i>						
		<i>Location : Random Locations Throughout</i>						
Piers								
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**	2-8		
		<i>Corrosion, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Random Locations Throughout</i>						
Pedestals								
Concrete	100%			LIFE	**			
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
		<i>Corrosion, Extent : Light, Area Affected : 40%</i>						
		<i>Location : Random Locations Throughout</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NINTH STREET BRIDGE NINTH ST. BRIDGE/GOWANUS CANAL

Asset # : 13512

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railings/Parapets Steel	100%	4+	\$500	LIFE	**	2-8	\$3,500	
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Missing Fastenings, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 2, North Railing, 2nd Railing From The Bottom At The Northwest Corner - Missing Bolt.</i>								
<hr/>								
Sidewalks Concrete	100%			2042	**	5		
<hr/>								
Wearing Surface Concrete	100%			2047	**	5		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<hr/>								
Superstructure								
Joints								
Steel	100%	Now	\$6,900	LIFE	**			
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Pier 1 Joint At Right Sidewalk</i>								
<hr/>								
Primary Member Concrete	100%			LIFE	**	5		
<hr/>								
Movable Bridges								
Vertical Lift Span Steel	100%			LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Paint Peeling</i>								
<hr/>								
Vertical Lift Tower Steel	5%			LIFE	**			
Steel	95%			LIFE	**			
<hr/>								
Vertical Lift Pier Concrete	100%			LIFE	**			
<hr/>								

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Communication Electrical								
Communications Generic	100%	Now	\$24,600	2032	\$41,100			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Entire Bridge</i>								
<i>Explanation : CCTV, Fire Alarm, Security System, Public Address Not Functioning</i>								
<hr/>								
Control System Electrical								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NINTH STREET BRIDGE NINTH ST. BRIDGE/GOWANUS CANAL

Asset # : 13512

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Control System Electrical								
Control Console								
Stainless Steel	100%	Now	\$109,000	LIFE		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i>								
<i>Location : Alarm Printer Not Functioning; Various Meters Are Not Functioning At PLC User Console</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : Bridge Operates Under Half Speed - Otherwise, It Goes Out Of Skew. East Height Indicator Broken. Skew Meter Does Not Work. Bridge Goes Out Of Skew Even In 50 Pct Speed.</i>								
Disconnect Switch								
Generic	100%			2051		**		
Limit Switch								
Generic	100%			2051		**		
Electrical Power								
Transfer Switch								
Auto	100%	Now	\$4,700	2051		**		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : Transfer Switch Not Working, Only Stays On Primary Power.</i>								
Heating								
Generic	100%			2051		**		
Dist Equip & Motor Controll								
Generic	10%	Now	\$130,800	2054		**		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Bridge Control System/ Motor Controllers</i>								
<i>Explanation : Bridge Operators Are Told To Run Bridge In Reduced Speed To Avoid Skew And Not To Fully Open To Avoid Skew</i>								
Generic	90%			2051		**		
Raceway								
Submarine Control Cables								
Not Accessible	100%							
Wiring								
Generic	100%			2038		**		
Stand-by Power								
Generator								
Diesel	100%	Now	\$33,000	2051		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Generator House</i>								
<i>Explanation : Generator Is Not Operational, Warning Lights Are Present On Annunciator</i>								
Lighting								
Lighting Devices								
Generic	100%	Now	\$22,700	2038		**		
<i>Other Observation, Extent : Light, Area Affected : 75%</i>								
<i>Location : Random Light Fixtures Throughout Bridge</i>								
<i>Explanation : Light Bulbs Out; Southwest Pier Light Not Operational; Span Navigation Lights Do Not Turn Green At Fully Open</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NINTH STREET BRIDGE NINTH ST. BRIDGE/GOWANUS CANAL

Asset # : 13512

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Vertical Lift								
Counter Weight Ropes & Gui Generic	100%	Now	\$50,300	2069			**	
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Counter Weight Ropes And Guides</i>								
<i>Explanation : Live Load Noted In One Of The Corners. Live Load Bearings May Require Adjustment.</i>								
Counter Weight Main CTRWT	100%			2069			**	
Emergency Drive Emergency Power	100%	Now	\$51,400	2062			**	
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : Machine Rooms And At Roadway Level</i>								
<i>Explanation : Last Condition Inspection Reported Not Operational. System Not Tested. Should Be Repaired And Tested Periodically.</i>								
End Locks With Motor	100%	Now	\$138,400	2062			**	
<i>Other Observation, Extent : Severe, Area Affected : 40%</i>								
<i>Location : Lock Machinery</i>								
<i>Explanation : Some Reducers Low On Oil. Some Adjustments May Be Required. Minor Corrosion.</i>								
Houses Access Ways	100%	Now	\$15,000	2047			**	
<i>Other Observation, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Span Lock Access</i>								
<i>Explanation : Some Hatches Reported To Be Difficult To Open And Need Repair. Some Corrosion.</i>								
Control House	100%	Now	\$81,000	2069			**	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Control House</i>								
<i>Explanation : Signs Of Leaks. Some Doors Do Not Seal When Closed. Some Windows Need Repair.</i>								
HVAC	100%	Now	\$2,000	2062			**	
<i>Other Observation, Extent : Light, Area Affected : 30%</i>								
<i>Location : Control Tower</i>								
<i>Explanation : Air Condition And Heat Unit Reported Not Working Efficiently</i>								
Machinery Room	100%	Now	\$301,000	2069			**	
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Machine Rooms</i>								
<i>Explanation : Signs Of Leaking Ceiling. Insulation Coming Down.</i>								
Main Drive System Generic	100%	Now	\$334,000	2069			**	
<i>Other Observation, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Machine Rooms</i>								
<i>Explanation : Minor Lubricant Leakage. Brake Covers Removed. Skew Control Needs Repair. Limit Switch Drive Needs Repair.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
NINTH STREET BRIDGE NINTH ST. BRIDGE/GOWANUS CANAL
Asset # : 13512

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Vertical Lift								
Sheaves								
Generic	5%	Now	\$9,600	2069		* *		
	<i>Other Observation, Extent : Light, Area Affected : 3%</i>							
	<i>Location : Sheave Rooms</i>							
	<i>Explanation : Missing Purge Plug Noted At One Location. Movement At One Location Under Live Load.</i>							
Generic	95%			2069		* *		
Traffic Devices								
Barrier Gate	100%	Now	\$94,900	2043		* *		
	<i>Other Observation, Extent : Severe, Area Affected : 5%</i>							
	<i>Location : Barrier Gates</i>							
	<i>Explanation : Guy Wires Hardware Needs Repair. Crash Wire System Needs Repair. Lock Disk Missing On One Gate.</i>							
Warning Gate	100%	Now	\$81,500	2043		* *		
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Warning Gates</i>							
	<i>Explanation : Arms And Gates Need Adjustment And Repair. North West Gates Does Not Work. South West Pedestrian Gate Arm Missing.</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PELHAM BRIDGE SHORE ROAD/HUTCHINSON RIVER
Address : EASTCHESTER BAY,BX, PELHAM PKY
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0045.000 / 2469 **Yr Built/Renovated** : 1906 / 1981
Area Sq Ft : 42,640 **Project Type** : WATERWAY BRIDGES
Date of Survey : 20-Apr-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240200

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$9,951,900	\$3,396,500
Bridge Electrical	\$2,079,200	\$1,436,900
Bridge Mechanical	\$1,679,100	\$2,183,200
Total	\$13,710,200	\$7,016,600
Importance Code A	\$9,444,100	\$1,802,000
Importance Code B	\$4,266,100	\$3,620,100
Importance Code C		\$1,594,500
Total	\$13,710,200	\$7,016,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$65,000	\$9,800	\$8,600	
Bridge Electrical	\$148,100	\$2,800	\$1,300	\$1,300
Bridge Mechanical	\$73,500			
Total	\$286,600	\$12,700	\$9,900	\$1,300
Importance Code A	\$19,500		\$8,600	
Importance Code B	\$233,700	\$2,800	\$1,300	\$1,300
Importance Code C	\$33,500	\$9,800		
Total	\$286,600	\$12,700	\$9,900	\$1,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
PELHAM BRIDGE SHORE ROAD/HUTCHINSON RIVER
Asset # : 2469

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : End Abutment</i>					
			<i>Explanation : Earth In Front Of Abutment At Low Tide.</i>					
Riprap	100%			LIFE			**	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Both Abutments</i>					
			<i>Explanation : Rip Rap At Begin Abutment And At Corners Of The End Abutment.</i>					
Stem (breastwall)								
Masonry: Granite	100%			LIFE			**	
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Riprap	100%			LIFE			**	
			<i>Settlement, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Beginning Right Wingwall</i>					
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE			**	
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	100%	4+	\$9,200	LIFE			**	
			<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Pier 3</i>					
			<i>Explanation : Missing And Loose Timber Planks</i>					
Approaches								
Pavement								
Asphalt	100%	2-4	\$3,500	2030	\$174,100	4	\$5,400	
			<i>Cracks, Extent : Moderate, Area Affected : 5%</i>					
			<i>Location : Both Beginning And End Approaches</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Begin Approach - Northbound Lanes</i>					
Curbs								
Concrete w/ Steel Face	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PELHAM BRIDGE SHORE ROAD/HUTCHINSON RIVER
Asset # : 2469

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Earth	100%			LIFE		**		
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Begin-right, End-left And End-right Approaches</i>								
<i>Explanation : Light Pole Bases Exhibit Open Or Missing Covers With Exposed Wires At The Base At Three Locations Accessible To Pedestrians.</i>								
Stone Rough Work	100%			LIFE		**		
Guide Railing								
Steel	100%	Now	\$8,100	LIFE		**	2-8	\$5,800
<i>Damaged Railing, Extent : Severe, Area Affected : 5%</i>								
<i>Location : End Left Approach 100' From Bridge</i>								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Riprap	100%			LIFE		**		
Sidewalks								
Concrete	100%	Now	\$6,100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Begin And End Approaches</i>								
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Begin Right Approach Sidewalk 100' From Bridge</i>								
<i>Explanation : Approach Sidewalk Is Undermined For 3 Feet L x 2 Feet H x Up To 4 Feet Deep And Adjacent Guiderail Post Base Is Exposed.</i>								
Piers								
Stem,Solid Pier								
Concrete	100%	4+	\$105,400	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Piers 1, 2, 3, 4, 5 And 6</i>								
<i>Delaminations, Extent : Light, Area Affected : 25%</i>								
<i>Location : Piers 1, 2, 3, 4, 5 And 6</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Piers 1, 2, 3, 4, 5 And 6</i>								
Granite	100%	4+	\$402,500	LIFE		**		
<i>Joints Missing, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Piers 1, 2, 3, 4, 5, And 6</i>								
Footings								
Concrete	100%	4+	\$2,900	LIFE		**		
<i>Spalling, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Piers 1, 2, 3, 4</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%	4+	\$11,000	LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Span 4 Right Curb</i>								
<i>Explanation : Right Curb Steel Face Is Misaligned At Pier 4 For 10 Feet</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PELHAM BRIDGE SHORE ROAD/HUTCHINSON RIVER

Asset # : 2469

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Guide Railing								
Concrete	95%			2037		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 Through 3 And 5 Through 7</i>								
<i>Explanation : Concrete Barrier On The Bridge, Left Side Only</i>								
Concrete	5%	4+	\$400	2037		**		
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Spans 2, 5, And 6</i>								
Railings/Parapets								
Concrete	90%	4+	\$69,400	2035	\$1,387,900	4	\$25,400	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Spans 1 Through 3 And 5 Through 7.</i>								
<i>Explanation : Right Side Of Bridge.</i>								
Concrete	10%	4+	\$15,400	2035	\$154,200	4	\$25,400	
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Spans 1 Through 3, And 5 Through 7</i>								
<i>Other Observation, Extent : Severe, Area Affected : 1%</i>								
<i>Location : Right Parapet</i>								
<i>Explanation : Light Pole Installed At Right Parapet Exhibits An Open Access Cover Accessible By Pedestrians.</i>								
Sidewalks								
Concrete	90%			2032	\$1,060,600	5	\$19,700	
Concrete	10%	0-2	\$11,800	2032	\$117,800	5	\$9,800	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Spans 1 Through 3 And 5 Through 7 Fascias</i>								
<i>Other Observation, Extent : Light, Area Affected : 25%</i>								
<i>Location : Span 4- South Sidewalk</i>								
<i>Explanation : 6 Inch Gap Between Sidewalk And Southwest Bridge Operator House Can Pose As A Potential Tripping Hazard.</i>								
Wearing Surface								
Asphalt	100%	Now	\$12,100	2030	\$242,000	5	\$15,400	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Transverse Cracks At Spans 1 Through 3 And 5 Through 7</i>								
<i>Spalling, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Spans 2, 3, 6</i>								
<i>Other Observation, Extent : Severe, Area Affected : 4%</i>								
<i>Location : Piers 2 And 3, Left Side And Span 7</i>								
<i>Explanation : Pavement Settlement Around Drainage Scupper At Piers 2 And 3. Uneven Riding Surface And Upheaving In Span 7.</i>								
Steel Grating	100%			LIFE		**	\$11,500	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span 4</i>								
<i>Explanation : Steel Grating In Bascule Span 4.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PELHAM BRIDGE SHORE ROAD/HUTCHINSON RIVER

Asset # : 2469

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Spans 2, 3, 5 & 6 (Both Sides)</i> <i>Explanation : 8 Scuppers</i>								
Superstructure								
Joints								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Piers 3 And 4</i> <i>Explanation : Open Expansion Joints</i>								
Primary Member								
Concrete	100%	2-4	\$1,680,300	LIFE		**	5	\$175,500
<i>Cracks, Extent : Moderate, Area Affected : 35%</i> <i>Location : Spans 1, 2, 3, 5, 6, And 7</i> <i>Delaminations, Extent : Severe, Area Affected : 50%</i> <i>Location : Spans 1, 2, 3, 5, 6, And 7</i> <i>Spalling, Extent : Severe, Area Affected : 10%</i> <i>Location : Spans 1, 2, 3, 5, 6, And 7</i>								
Steel	100%	4+	\$415,700	LIFE		**	2-8	\$157,700
<i>Corrosion, Extent : Severe, Area Affected : 25%</i> <i>Location : Exposed Steel Truss In Random Spans.</i>								
Movable Bridges								
Bascule Span								
Steel	100%	Now	\$5,198,700	LIFE		**		
<i>Other Observation, Extent : Severe, Area Affected : 25%</i> <i>Location : Span 4</i> <i>Explanation : Corrosion Holes, Section Losses At Several Members Of The Primary And Secondary Members. 1-1/2 Inch Differential At Sidewalk Bascule Span Joint At Midspan Poses As A Tripping Haza</i>								
Bascule Span Pier								
Concrete	100%	0-2	\$2,064,600	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i> <i>Location : Piers 3 And 4</i> <i>Explanation : Pier Wall Supporting Truss Members Is Cracking And Spalling With Exposed Rebars.</i>								

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Air Horn								
Generic	100%	Now	\$2,500	2034	\$2,500			
<i>Malfunctioning, Extent : Severe, Area Affected : 100%</i> <i>Location : Control Room</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PELHAM BRIDGE SHORE ROAD/HUTCHINSON RIVER

Asset # : 2469

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Communications								
Generic	100%	Now	\$41,100	2032	\$41,100			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : System Wide</i>								
<i>Explanation : The Circuits In The Submarine Cable Utilized By This Equipment Have Been Utilized For Another System.</i>								
Control System Electrical								
Control Console								
Stainless Steel	100%	Now	\$43,600	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Control Desk</i>								
<i>Explanation : Automatic Seating Is Not Functioning. Must Be Manually Controlled. Several Pilot Lights Not Operational. Position Meter Not Operational.</i>								
Disconnect Switch								
Generic	100%			2037		**		
Limit Switch								
Generic	100%	Now	\$21,300	2045		**		
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Southeast Tail Lock; Northeast Tail Lock</i>								
<i>Explanation : Tail Lock Limit Switches Not Functioning Hand Crank Safety Switch Disabled</i>								
Electrical Power								
Transformer								
Dry	100%			2049		**		
Dist Equip & Motor Controll								
Generic	100%	2-4	\$204,700	2045		**		
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Control House</i>								
<i>Explanation : Panelboards Reaching Useful Life</i>								
Ground/Lightning Protection								
Ground Bus								
Copper	100%			2036		**		
Raceway								
Submarine Control Cables								
Generic	100%	Now	\$971,800	2037		**		
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Submarine Cable</i>								
<i>Explanation : Submarine Cable Conductors Are Nearing The End Of Their Useful Life.</i>								
Wiring								
Generic	100%	Now	\$482,100	2030	\$1,205,300			
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Counterweight Pits</i>								
<i>Explanation : Conduit And Conduit Supports Are Corroded. Junction Boxes And Pull Boxes Are Missing Covers.</i>								
Stand-by Power								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PELHAM BRIDGE SHORE ROAD/HUTCHINSON RIVER

Asset # : 2469

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Stand-by Power
Generator
Diesel

100% Now \$420,500 2052 * *
Other Observation, Extent : Severe, Area Affected : 100%
Location : Southwest Machinery Room Area
Explanation : Generator Has Failed

Lighting
Lighting Devices
Generic

100% Now \$38,400 2030 \$95,900
Other Observation, Extent : Moderate, Area Affected : 25%
Location : Toe Of Both Spans, Various Locations Throughout.
Explanation : Southeast Navigation Light Broken. Service Lighting Needs Relamping At Various Locations. Some Fixtures Not Operational.

Main Drive
Motor Controller
Thyristor Drive

100% 2032 \$135,800 1-5 \$15,900

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Bascule
Counter Weight
Generic

100% 0-2 \$246,500 2047 * *
Corrosion, Extent : Severe, Area Affected : 30%
Location : Steel At North And South Counterweights.

Emergency Drive
Emergency Power

100% Now \$55,400 2047 * *
Other Observation, Extent : Moderate, Area Affected : 100%
Location : Emergency Generator
Explanation : No Operation On Emergency Power Observed. Possible Exhaust Leak.

Fuel Tanks
Generic

100% 2-4 \$3,400 2037 * *
Other Observation, Extent : Moderate, Area Affected : 50%
Location : Southwest Corner
Explanation : Generator Fuel Tank Shows Moderate Surface Rusting. Tank Is Empty

Houses
Control House

100% Now \$32,200 2047 * *
Broken/Missing Elements, Extent : Light, Area Affected : 5%
Location : Throughout Control And Tenders House
Other Observation, Extent : Light, Area Affected : 5%
Location : Throughout Control And Tenders House
Explanation : There Are Some Window And Roof Leaks. Water Main Needs Repair. Exposed Electrical Throughout

HVAC
Machinery Room

100% 2035 \$48,700
 100% Now \$17,600 2047 * *
Other Observation, Extent : Moderate, Area Affected : 10%
Location : Machinery Room
Explanation : Corroded Grating. Ladders To Rack And Pinion Corroded.

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PELHAM BRIDGE SHORE ROAD/HUTCHINSON RIVER

Asset # : 2469

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Lock Bars								
With Motor	100%	Now	\$52,500	2035	\$524,900			
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Lock Bars On Pier</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Lock Bars On Pier</i>								
<i>Explanation : Torn Protective Covers. Receiver Grout Pads Are Deteriorating. Span Lock Assemblies Are Wrapped In Plastic.</i>								
Without Motor	100%	Now	\$52,500	2035	\$524,900			
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Throughout Jaw And Pin Locks.</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Jaw And Pin Locks</i>								
<i>Explanation : Automatic Engagement Not Functioning. Needs To Be Manually Engaged.</i>								
Main Drive System								
Generic	100%	Now	\$645,200	2047			**	
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout South And North Machine Rooms</i>								
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout South And North Machine Rooms</i>								
<i>Lubrication Issue, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Throughout South And North Machine Rooms</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : South And North Machine Rooms</i>								
<i>Explanation : Misaligned Couplings. Limit Switch Has Fallen Off Support.</i>								
Rack								
Generic	100%	Now	\$20,300	2047			**	
<i>Broken/Missing Elements, Extent : Light, Area Affected : 1%</i>								
<i>Location : Mounting Bolt At Southeast Rack</i>								
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : Debris Shields At Southeast Rack</i>								
Structural Bearings								
Generic	100%	Now	\$65,000	2035	\$162,600			
<i>Corrosion, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Forward Live Load Bearings</i>								
<i>Improper Bearing, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Forward Live Load Bearings</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Forward Live Load Bearings</i>								
<i>Explanation : Some Movement And Adjustment May Be Necessary Of Anchor Bolts.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PELHAM BRIDGE SHORE ROAD/HUTCHINSON RIVER

Asset # : 2469

Bridge Mechanical	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule Track Generic	100%	4+	\$135,500	2047				**
	<i>Corrosion, Extent : Light, Area Affected : 20%</i>							
	<i>Location : Bolts On Tracks</i>							
	<i>Lubrication Issue, Extent : Light, Area Affected : 20%</i>							
	<i>Location : Pintles And Tracks</i>							
	<i>Other Observation, Extent : Light, Area Affected : 20%</i>							
	<i>Location : Tracks</i>							
	<i>Explanation : Paint Failure On Some Bolts.</i>							
Traffic Devices Barrier Gate	100%	Now	\$237,300	2035	\$474,600			
	<i>Broken/Missing Elements, Extent : Light, Area Affected : 30%</i>							
	<i>Location : Barrier Gates</i>							
	<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>							
	<i>Location : Northeast Gate</i>							
	<i>Explanation : Northeast Barrier Gate Lights Do Not Work.</i>							
	<i>Other Observation, Extent : Severe, Area Affected : 30%</i>							
	<i>Location : Barrier Gates</i>							
	<i>Explanation : Adjustments Required. Some Latches Do Not Function, Crack In Arms.</i>							
Signals	100%	Now	\$100,800	2035	\$201,700			
	<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>							
	<i>Location : South Approach</i>							
	<i>Explanation : Traffic Signals Do Not Operate On Green.</i>							
Warning Gate	100%	Now	\$88,300	2035	\$294,400			
	<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Warning Gates</i>							
	<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Warning Gates</i>							
	<i>Explanation : Some Gate Heights Need Adjustment. Some Open Holes. One Gate Not Working.</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK
Address : NEWTOWN CREEK
Borough : BROOKLYN:QNS. **Agency's Number** : N/A
Program / Asset # : DOT0050.000 / 2476 **Yr Built/Renovated** : 1954 / 1995
Area Sq Ft : 214,183 **Project Type** : WATERWAY BRIDGES
Date of Survey : 29-Apr-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240639

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$3,360,200	\$2,807,600
Bridge Electrical	\$157,700	\$396,500
Bridge Mechanical	\$3,535,500	\$10,767,900
Total	\$7,053,400	\$13,972,000
Importance Code A	\$1,970,900	\$1,214,800
Importance Code B	\$4,609,800	\$12,384,700
Importance Code C	\$472,800	\$372,500
Total	\$7,053,400	\$13,972,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$75,900	\$23,600	\$231,100	\$2,300
Bridge Electrical	\$66,500	\$10,700	\$10,700	\$10,700
Bridge Mechanical	\$73,800		\$116,700	
Total	\$216,200	\$34,300	\$358,600	\$13,000
Importance Code A			\$108,700	\$2,300
Importance Code B	\$176,300	\$10,700	\$249,900	\$10,700
Importance Code C	\$39,900	\$23,600		
Total	\$216,200	\$34,300	\$358,600	\$13,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK

Asset # : 2476

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location : Beginning And End Abutments</i>							
	<i>Explanation : Enclosed Cell And Access Door Is Locked.</i>							
<hr/>								
Backwall Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location : Beginning And End Abutments</i>							
	<i>Explanation : Enclosed Cell And Access Door Is Locked.</i>							
<hr/>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location : Beginning And End Abutments</i>							
	<i>Explanation : Enclosed Cell And Access Door Is Locked.</i>							
<hr/>								
Footings								
Not Accessible	100%							
<hr/>								
Joint with Deck								
Composite	50%	2-4	\$10,300	LIFE			**	
	<i>Leakage, Extent : Moderate, Area Affected : 20%</i>							
	<i>Location : Beginning And End Abutment Joints</i>							
Composite	50%	Now	\$25,700	LIFE			**	
	<i>Cracks, Extent : Severe, Area Affected : 50%</i>							
	<i>Location : Beginning And End Abutments</i>							
	<i>Leakage, Extent : Moderate, Area Affected : 50%</i>							
	<i>Location : Beginning And End Abutments</i>							
<hr/>								
Mat (scour & erosion)								
Not Accessible	100%							
<hr/>								
Pedestals								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location : Beginning And End Abutments</i>							
	<i>Explanation : Enclosed Cell And Access Door Is Locked.</i>							
<hr/>								
Stem (breastwall)								
Not Accessible	100%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location : Beginning And End Abutments</i>							
	<i>Explanation : Enclosed Cell And Access Door Is Locked.</i>							
<hr/>								
Wingwalls								
Footings								
Not Accessible	100%							
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK
Asset # : 2476

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Wingwalls								
Walls								
Concrete	95%			LIFE		**		
Concrete	5%	4+	\$133,800	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : End Abutment</i>								
Feature Crossed								
Bank Protection								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Under Span 27</i>								
<i>Explanation : Not Accessible</i>								
Timber	100%			2037		**		
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Bank Protection Under Spans 25 And 27.</i>								
<i>Explanation : Minor Cracking</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	25%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 25%</i>								
<i>Location : Bascule Piers 25 And 26</i>								
<i>Explanation : East Side 2 Of 4 Dolphin Clusters Are New</i>								
Timber	75%			LIFE		**		
<i>Split/Dry/Cracked, Extent : Light, Area Affected : 2%</i>								
<i>Location : Bascule Piers 26 And 27</i>								
Approaches								
Pavement								
Asphalt	100%	0-2	\$37,300	2033	\$372,500	4	\$11,500	
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : End Approach</i>								
<i>Explanation : Pavement Shoving And Rutting</i>								
Concrete	100%			2041		**	4	
Guide Railing								
Concrete	100%			2041		**	4	\$4,600
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%	4+	\$2,400	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : End Approach</i>								
Scupper								
Ductile Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Beginning Approach Has 6 Scuppers And The End Approach Has 1 Scupper</i>								
<i>Explanation : Total Of 7 Scuppers</i>								
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK
Asset # : 2476

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Cap Beam								
Concrete	100%	4+	\$314,500	LIFE		**		
	<i>Spalling, Extent : Light, Area Affected : 10%</i> <i>Location : Piers 1,4,6,7,16,34,35,36,37,42 And 43.</i>							
Steel	100%			LIFE		**	2-8	
Pier,Columns								
Concrete	50%			LIFE		**		
Concrete	50%	2-4	\$328,700	LIFE		**		
	<i>Cracks, Extent : Moderate, Area Affected : 20%</i> <i>Location : Piers 19 Through 24 And 27 Through 30 And 33</i> <i>Delaminations, Extent : Moderate, Area Affected : 25%</i> <i>Location : Piers 19 - 24 And 27-30</i> <i>Efflorescence, Extent : Moderate, Area Affected : 10%</i> <i>Location : Piers 19 - 24 And 27-30</i>							
Steel	100%			LIFE		**	2-8	\$461,600
Stem,Solid Pier								
Concrete	80%			LIFE		**		
Concrete	20%	4+	\$160,000	LIFE		**		
	<i>Cracks, Extent : Moderate, Area Affected : 25%</i> <i>Location : Piers 1, 9, 18, 25, 36, And 40.</i> <i>Spalling, Extent : Moderate, Area Affected : 10%</i> <i>Location : Piers 1, 9, 18, 25, 36, And 40.</i>							
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2052		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Piers 1-18, 33-36 And 39-43.</i> <i>Explanation : Elastomeric Bearings</i>							
Steel	100%			LIFE		**	2-8	\$49,400
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Piers 31 And 32.</i> <i>Explanation : Fixed Steel Bearings</i>							
Multi-Rotational Bearing	100%			2060		**		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Piers 19-24, 27-30 And 33.</i> <i>Explanation : Pot Bearings</i>							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK
Asset # : 2476

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pedestals								
Concrete	100%	2-4	\$58,800	LIFE		**		
<i>Cracks, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Piers 8, 25, 39 And 40.</i>								
<i>Delaminations, Extent : Light, Area Affected : 2%</i>								
<i>Location : Piers 8, 25, 39 And 40.</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Piers 25, 39 And 40.</i>								
<hr/>								
Piles								
Not Accessible	100%							
<hr/>								
Deck Elements								
Guide Railing								
Concrete	100%			2045		**		
<hr/>								
Median								
Concrete	100%			LIFE		**	5	\$75,600
<hr/>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$8,000
<hr/>								
Sidewalks								
Concrete	100%			2037		**	5	\$41,100
<hr/>								
Wearing Surface								
Concrete	5%	Now	\$100	2041		**	5	\$3,000
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Spans 32 And 40 Southbound Roadway</i>								
Concrete	5%	2-4	\$100	2041		**	5	\$3,000
<i>Cracks, Extent : Moderate, Area Affected : 3%</i>								
<i>Location : Spans 19 Northbound And 21, 23, 31 Southbound Roadway</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Spans 19 Northbound And 21, 23 Southbound Roadway</i>								
Concrete	90%			2047		**	5	\$6,000
<hr/>								
Scupper								
Ductile Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 9, 19 To 24, 26 To 28 And 33, 40.</i>								
<i>Explanation : 24 Scuppers Located Between Piers 8 To 40.</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$1,379,900	LIFE		**	5	\$79,200
<i>Cracks, Extent : Moderate, Area Affected : 75%</i>								
<i>Location : Spans 25 And 27</i>								
Grating w/ Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 2%</i>								
<i>Location : Span 26</i>								
<i>Explanation : Worn Wearing Surface</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK
Asset # : 2476

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Joints								
Composite	85%	0-2	\$180,100	LIFE	**	4	\$841,100	
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Piers 8, 12, 15, 18, 19, 20, 27 And 36</i>								
<i>Explanation : Water Leakage Noted Below Joints</i>								
Composite	15%	Now	\$158,900	LIFE	**	4	\$841,100	
<i>Leakage, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Piers 2, 5, 9, 33, 39, 40 And 43</i>								
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Piers 2, 5, 9, 33, 39, 40 And 43</i>								
<i>Explanation : Torn And Cracked Sealer</i>								
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			
Steel	100%			LIFE	**	2-8	\$1,979,800	
Secondary Member								
Steel	100%	Now	\$369,000	LIFE	**	2-8	\$1,658,400	
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Span 30</i>								
<i>Explanation : Cross Bracing Missing 4 Of 4 Connection Rivets.</i>								
Movable Bridges								
Bascule Span								
Steel	90%			LIFE	**			
Steel	10%	4+	\$189,700	LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Piers 25 And 26</i>								
<i>Explanation : Steel Towers Exhibit Corrosion.</i>								
Bascule Span Pier								
Concrete	90%			LIFE	**			
Concrete	10%	0-2	\$86,800	LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Bascule Piers 25 And 26</i>								
<i>Explanation : Median Stringers 6 And 7 Pedestal Exhibit Spalls With Exposed Anchor Bolts.</i>								

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Air Horn								
Generic	100%	Now	\$2,500	2034	\$2,500			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Control Room</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK
Asset # : 2476

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Communication Electrical								
Intercom								
Generic	100%	Now	\$63,000	2032	\$63,000			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Random Throughout Bridge</i>								
<i>Explanation : Intercom System Not Functioning</i>								
Telephone								
Desk Top	100%			2030				
Jack								
Telephone	100%			2030				
Control System Electrical								
Control Console								
Stainless Steel	100%	Now	\$94,700	LIFE		**		
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Control Desk Span Position Meters Not Functioning</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Control Room</i>								
<i>Explanation : Select Pilot Lights Not Operating. Master Switch Labeling Reversed.</i>								
Control Devices								
Relay	80%			2037		**		
Relay	20%			2045		**		
Disconnect Switch								
Non Fused	100%			2030		1	\$49,400	
Limit Switch								
Generic	70%	Now	\$14,700	2045		**		
<i>Other Observation, Extent : Light, Area Affected : 25%</i>								
<i>Location : Southwest Seated Switch</i>								
<i>Explanation : Southwest Fully Seated Switch Is Failed</i>								
<i>Rotary Cam Limit Switches Decoupled</i>								
Generic	30%			2045		**		
Drive								
Machinery Brake								
Thruster	100%			2042		**	1	\$2,300
Motor Brake								
Thruster	100%			2042		**	1	\$2,300
Span Lock Motor								
Generic	100%			2042		**	1	\$2,300
Electrical Power								
MCC								
Starter	100%			2030				
Contactors	75%			2030				
Contactors	25%			2045		**		
Motor Circuit Protector	100%			2030	\$21,600	1	\$4,500	
Panelboard								
Circuit Breaker	100%			2037		**	1	\$13,500
Service Equipment								
Fused Disc Switch	100%			2030				

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK
Asset # : 2476

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Electrical Power								
Transfer Switch								
Auto	100%	Now	\$30,100	2045		**		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Bridge House</i>								
<i>Explanation : Transfer Switch Not Functioning</i>								
Ground/Lightning Protection								
Ground Bus								
Not Accessible	100%							
Ground Rod								
Not Accessible	100%							
Ground Wire								
Green	100%			2033				
Not Accessible	100%							
Raceway								
Box								
Pull Junction	100%			2032		1	\$13,500	
Terminal	100%			2032		1	\$4,500	
Conduit								
Metal	50%			2047		**		
Metal	50%			2047		**		
Submarine Control Cables								
Control	100%			2030				
Submarine Power Cable								
Power	100%			2030				
Wires								
Cloth	100%			2031	\$210,600			
Thermoplastic	100%			2045		**		
Span Lock								
Motor								
Squirrel Cage	100%			2035				
Lighting								
Lighting Devices								
Generic	85%			2033	\$104,400			
Generic	5%	4+	\$3,100	2033	\$6,100			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout Bridge</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout Bridge</i>								
<i>Explanation : HID Service Lighting Fixtures Not Working</i>								
Generic	5%	4+	\$3,100	2033	\$6,100			
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Incandescent Service Lighting Fixtures Not Working</i>								
Generic	5%	Now	\$1,200	2033	\$6,100			
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Various Locations Throughout Bridge</i>								
<i>Explanation : Switches Broken Or Wiring Devices Hanging Out Of Box.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK

Asset # : 2476

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Main Drive

Motor Controller

Drum Controller

100% Now \$2,800 2047 * * 1 \$13,800

Other Observation, Extent : Light, Area Affected : 100%

Location : Control Room

Explanation : Labels For Raise/lower Are Reversed

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Bascule

Counter Weight

Generic

100% Now \$128,600 2047 * * 2 \$71,800

Other Observation, Extent : Light, Area Affected : 5%

Location : Counterweights

Explanation : Some Open Pockets, One Bumper Block Is Damaged

Emergency Drive

Emergency Power

100% Now \$135,400 2047 * * 2 \$143,700

Corrosion, Extent : Severe, Area Affected : 100%

Location : Throughout Machine Rooms

Other Observation, Extent : Severe, Area Affected : 100%

Location : Machine Rooms

Explanation : Operation Of System Could Not Be Performed.

Fuel Tanks

Generic

100% Now \$200 2037 * *

Other Observation, Extent : Light, Area Affected : 2%

Location : Control House

Explanation : Reported No Longer Used

Houses

Access Ways

100% Now \$30,200 2035 \$302,400

Other Observation, Extent : Severe, Area Affected : 5%

Location : Accessways

Explanation : Some Grating, Hatches, Safety Chains, And Doors Loose, Missing Or Need Repair.

Control House

100% Now \$118,400 2047 * *

Broken/Missing Elements, Extent : Moderate, Area Affected : 20%

Location : Doors And Windows Throughout Control House

Other Observation, Extent : Moderate, Area Affected : 20%

Location : Control House

Explanation : Heating System And Plumbing Needs Work. Co Detectors Missing Or Not Working. Exposed Electrical Throughout

Machinery Room

100% Now \$81,600 2047 * *

Broken/Missing Elements, Extent : Light, Area Affected : 20%

Location : Doors And Enclosure Panels Throughout Machine Rooms

Other Observation, Extent : Light, Area Affected : 20%

Location : Machine Rooms

Explanation : Some Water And Oil On Floor. Bowed Down Step.

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK

Asset # : 2476

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Lock Bars								
With Motor	100%	Now	\$329,900	2035	\$1,099,800	2	\$35,900	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 35%</i>								
<i>Location : Lock Bars</i>								
<i>Corrosion, Extent : Severe, Area Affected : 35%</i>								
<i>Location : Lock Bars</i>								
<i>Other Observation, Extent : Severe, Area Affected : 35%</i>								
<i>Location : Lock Bars</i>								
<i>Explanation : Lockbar Clearances Need To Be Reduced. Leakage, One Span Lock Limit Switch Missing Cover.</i>								
Main Drive System								
Generic	100%	Now	\$529,600	2035	\$5,296,500	2	\$215,500	
<i>Corrosion, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Machine Rooms</i>								
<i>Other Observation, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Machine Rooms</i>								
<i>Explanation : Minor Leaks. Disconnected Limit Switch Coupling. Gearbox Oil Dark Color.</i>								
Rack								
Generic	100%	Now	\$211,900	2047			**	
<i>Corrosion, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Supports And Fasteners On Racks</i>								
Structural Bearings								
Generic	100%	Now	\$43,400	2035	\$108,400			
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Rear Live Load Bearings</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Rear Live Load Bearings</i>								
<i>Explanation : Adjustments May Be Required With Lock Adjustment.</i>								
Traffic Devices								
Barrier Gate	100%	Now	\$1,466,500	2035	\$3,666,400			
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : South Approach</i>								
<i>Explanation : Incandescent Traffic Gate Lights Broken/Missing</i>								
<i>Other Observation, Extent : Severe, Area Affected : 40%</i>								
<i>Location : North And South Approaches</i>								
<i>Explanation : All Barrier Gates Not Functioning. Southeast Net Missing.</i>								
Warning Gate	100%	Now	\$58,900	2035	\$294,400			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Warning Gates</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Warning Gates</i>								
<i>Explanation : Guy Wire Damage, No Locks On Some Doors, Missing Fasteners.</i>								
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : North And South Approaches</i>								
<i>Explanation : Traffic Warning Gongs Have Failed</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PULASKI BRIDGE PULASKI BRIDGE/NEWTOWN CREEK

Asset # : 2476

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Bascule

Trunnion

Generic

100% Now \$474,600 2047 * *

Corrosion, Extent : Moderate, Area Affected : 10%

Location : Trunnion Assemblies

Lubrication Issue, Extent : Severe, Area Affected : 10%

Location : Leaves On Trunnion Assemblies.

Other Observation, Extent : Severe, Area Affected : 10%

Location : Trunnion Assemblies

Explanation : Debris Observed On Exteriors Of Trunnion Assemblies. Noise From Leaves When Opening And Closing.

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RAMP FROM FDR DR. TO WILLIS AVE. HARLEM RIVER DRIVE NB
 Address : FDR AT 125 STREET
 Borough : MANHATTAN Agency's Number : N/A
 Program / Asset # : DOT0040.0A0 / 4240 Yr Built/Renovated : 1901 / 2008
 Area Sq Ft : 29,900 Project Type : WATERWAY BRIDGES
 Date of Survey : 08-Mar-2022 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 224005A

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$622,200
Total		\$622,200
Importance Code A		\$345,700
Importance Code B		\$276,400
Total		\$622,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$14,200		\$69,800	
Total	\$14,200		\$69,800	
Importance Code A	\$14,200		\$34,700	
Importance Code B			\$27,700	
Importance Code C			\$7,400	
Total	\$14,200		\$69,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP FROM FDR DR. TO WILLIS AVE. HARLEM RIVER DRIVE NB
Asset # : 4240

Bridge Structure System Component Type	Current Repair		Future Replacement		Maintenance		Priority
	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	
Piers							
Stem,Solid Pier Masonry	100%			LIFE	**		
		<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
		<i>Location : Throughout</i>					
		<i>Explanation : Graffiti On Fascia</i>					
Brngs,Ancr Blts,Pads Elastomeric	100%			2059	**		
Multi-Rotational Bearing	100%			2068	**		
Footings							
Not Accessible	100%						
Mat (scour & erosion)							
Generic	100%			LIFE	**		
Pedestals							
Concrete	100%			LIFE	**		
Piles							
Not Accessible	100%						
Deck Elements							
Mono Deck Surface Concrete	100%			2053	**	5	\$14,800
Railings/Parapets Concrete	100%			2042	**	4	\$42,500
Scupper							
Cast Iron	100%			LIFE	**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
		<i>Location : Throughout</i>					
		<i>Explanation : Total Of 8 Scuppers</i>					
Superstructure							
Deck,Structural Concrete	100%			LIFE	**	5	\$26,500
Joints							
Generic	100%			LIFE	**		
Primary Member							
Steel	100%			LIFE	**	2-8	\$516,300
Secondary Member							
Steel	100%			LIFE	**	2-8	\$432,500

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RAMP TO MADISON AVE. BRIDGE OVER E 138TH STREET
Address : HARLEM RIVER, HARLEM RIV DR.
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0042.0A0 / 4210 **Yr Built/Renovated** : 1907 / 2008
Area Sq Ft : 22,600 **Project Type** : WATERWAY BRIDGES
Date of Survey : 13-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224007A

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,656,700	\$699,700
Total	\$1,656,700	\$699,700
Importance Code A	\$1,441,900	\$370,700
Importance Code B	\$214,800	\$265,700
Importance Code C		\$63,300
Total	\$1,656,700	\$699,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$415,400		\$75,400	
Total	\$415,400		\$75,400	
Importance Code A	\$213,000		\$48,800	
Importance Code B	\$102,400		\$26,600	
Importance Code C	\$100,100			
Total	\$415,400		\$75,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO MADISON AVE. BRIDGE OVER E 138TH STREET

Asset # : 4210

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Walls								
Concrete	100%	4+	\$103,600	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Spall With Exposed Rebar At Southwest Wall At Pier</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Fascias Span 1</i>								
<i>Explanation : Under Cellular Abutment Wall</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Wingwalls</i>								
<i>Explanation : Concrete Sidewalk On West Side. Asphalt Parking Lot On Other</i>								
Piles								
Not Accessible	100%							
Walls								
Concrete	8%	Now	\$13,500	LIFE			**	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Spalls With Exposed Rebar At Southeast Wingwall At Pier Joint, Along Southwest Wingwall, Along Top Of Southeast Wingwall Adjacent To Sidewalk</i>								
Concrete	92%			LIFE			**	
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO MADISON AVE. BRIDGE OVER E 138TH STREET

Asset # : 4210

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Pier Protection								
Concrete	100%	4+	\$2,400	LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Cracks</i>								
Approaches								
Pavement								
Concrete	100%			2044		**	4	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Middle Of Southeast Approach</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At End Of Concrete Approach Slabs</i>								
<i>Explanation : Asphalt Expansion Joint Between Rigid Pavement And Approach Slab</i>								
Guide Railing								
Concrete	100%			2044		**	4	\$4,600
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**	2-8	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Top Of Concrete Barrier</i>								
<i>Explanation : Steel Railing</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%			LIFE		**	5	
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2044		**	4	\$17,600
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout West Parapet</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : On The East Side Of The Bridge Only</i>								
<i>Explanation : Railing</i>								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Sidewalk Observed On East Side Only</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO MADISON AVE. BRIDGE OVER E 138TH STREET

Asset # : 4210

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East Approach</i>								
<i>Explanation : One Scupper</i>								
Piers								
Cap Beam								
Steel	80%	4+	\$42,700	LIFE		**	2-8	\$180,200
<i>Rust Stains, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout And Under Deck Joint</i>								
Steel	20%			LIFE		**	2-8	\$301,500
<i>Other Observation, Extent : N/A, Area Affected : 5%</i>								
<i>Location : In Between Pier 5 And Abutments</i>								
<i>Explanation : Not Accessible</i>								
Pier,Columns								
Steel	20%			LIFE		**	2-8	\$120,200
<i>Other Observation, Extent : N/A, Area Affected : 20%</i>								
<i>Location : Between Piers 5 And Abutment</i>								
<i>Explanation : Not Accessible</i>								
Steel	80%	4+	\$14,100	LIFE		**	2-8	\$73,300
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Corrosion To Steel Protective Angles And Delamination/spall Of Concrete Cover</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Pier 2</i>								
<i>Explanation : Joint Leaking And Water Stains</i>								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
<i>Leakage, Extent : Light, Area Affected : 10%</i>								
<i>Location : Both Ends At Pier 5.</i>								
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Epoxy Coating Peeling.</i>								
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055		**		
<i>Other Observation, Extent : N/A, Area Affected : 30%</i>								
<i>Location : Piers 2 And 5 Only.</i>								
<i>Explanation : Bearing Present At Select Piers.</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 15%</i>								
<i>Location : Pier 5</i>								
<i>Explanation : Pedestals At Pier Only</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO MADISON AVE. BRIDGE OVER E 138TH STREET
Asset # : 4210

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing								
Concrete	100%	4+	\$13,300	2048		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Top Of Concrete Barrier</i>								
<i>Explanation : Steel Railing</i>								
Median								
Concrete	100%			LIFE		**	5	\$7,000
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : On East Face Within Middle Portion</i>								
Railings/Parapets								
Concrete	100%	4+	\$30,200	2044		**	4	\$13,200
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout West Parapet</i>								
Steel	100%			LIFE		**	2-8	\$21,500
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Railings Are On East Side Of Bridge</i>								
Sidewalks								
Concrete	100%			2040		**	5	\$5,600
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout Southbound Lanes</i>								
Wearing Surface								
Asphalt	100%	4+	\$43,100	2036		**	5	\$14,600
<i>Cracks, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Southbound Lane</i>								
<i>Explanation : Asphalt Wearing Surface On One Side Of The Lane Only</i>								
Concrete	100%	4+	\$36,000	2044		**	5	\$63,300
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 4 Scuppers</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RAMP TO MADISON AVE. BRIDGE OVER E 138TH STREET

Asset # : 4210

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%	Now	\$1,045,600	LIFE	**	5	\$31,900	
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Underside In Middle Bay</i> <i>Corrosion, Extent : Severe, Area Affected : 10%</i> <i>Location : Stay In Place Forms In East And West Fascia Bays</i>								
Joints								
Generic	100%	4+	\$7,400	LIFE	**			
<i>Leakage, Extent : Light, Area Affected : 20%</i> <i>Location : Random Locations Throughout</i> <i>Other Observation, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Explanation : Joint Filler Is Depressed.</i>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$687,600	
<i>Corrosion, Extent : Light, Area Affected : 1%</i> <i>Location : Random Locations Throughout</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$589,900	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RICHMOND AVENUE BRIDGE RICHMOND AVE./RICHMOND CREEK
Address : OVER RICHMOND CREEK
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0154.000 / 13517 **Yr Built/Renovated** : 1931 /
Area Sq Ft : 32,589 **Project Type** : WATERWAY BRIDGES
Date of Survey : 24-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240350

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$93,200	\$128,200
Total	\$93,200	\$128,200
Importance Code A		\$35,000
Importance Code C	\$93,200	\$93,200
Total	\$93,200	\$128,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$165,200		\$4,300	
Total	\$165,200		\$4,300	
Importance Code A	\$20,600		\$4,300	
Importance Code B	\$3,500			
Importance Code C	\$141,100			
Total	\$165,200		\$4,300	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
RICHMOND AVENUE BRIDGE RICHMOND AVE./RICHMOND CREEK
Asset # : 13517

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	63%	Now	\$3,500	LIFE			**	
		<i>Missing/Damaged Seal, Extent : Light, Area Affected : 80%</i>						
		<i>Location : Both Abutments</i>						
Generic	37%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%	4+	\$27,300	LIFE			**	
		<i>Erosion, Extent : Moderate, Area Affected : 100%</i>						
		<i>Location : Begin Abutment West Side</i>						
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE			**	
		<i>Other Observation, Extent : N/A, Area Affected : 75%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : Walls Consist Of 25 Percent Concrete, 75 Percent Not Accessible.</i>						
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE			**	
Mat (scour & erosion)								
Generic	100%			LIFE			**	
Approaches								
Pavement								
Concrete	100%	4+	\$31,600	2041		**	4	\$32,100
		<i>Cracks, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Both End Approaches</i>						
		<i>Spalling, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Both End Approaches</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RICHMOND AVENUE BRIDGE RICHMOND AVE./RICHMOND CREEK
Asset # : 13517

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Curbs								
Concrete w/ Steel Face	9%	4+	\$8,700	LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Both Approaches</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : West Side</i>								
<i>Explanation : Curbs Consist Of 50 Percent Concrete With Steel Face, 50 Percent Not Accessible Due To Construction.</i>								
Concrete w/ Steel Face	91%			LIFE		**		
Embankment								
Earth	100%			LIFE		**		
Guide Railing								
Steel	100%			LIFE		**	2-8	\$146,200
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Median								
Concrete	100%			LIFE		**	5	
<i>Vegetation Growth, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2041		**	4	
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Railing On Concrete</i>								
Sidewalks								
Concrete	11%	4+	\$18,600	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : West Side</i>								
<i>Explanation : Sidewalks Consist Of 50 Percent Concrete, 50 Percent Not Accessible Due To Construction.</i>								
Concrete	89%			LIFE		**		
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RICHMOND AVENUE BRIDGE RICHMOND AVE./RICHMOND CREEK
Asset # : 13517

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Curbs								
Under Construction	100%							
Guide Railing								
Concrete	100%			2045		**		
Median								
Concrete	100%	4+	\$4,800	LIFE		**	5	\$3,400
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
Railings/Parapets								
Concrete	100%	4+	\$7,100	2041		**	4	\$800
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : West Side</i>					
			<i>Explanation : Not Accessible Due To Construction</i>					
Steel	100%			LIFE		**	2-8	\$12,900
			<i>Other Observation, Extent : N/A, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : Steel Railing On Top Of Parapet; 50 Percent Not Accessible Due To Construction</i>					
Sidewalks								
Concrete	100%	4+	\$23,000	2037		**	5	\$6,700
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : West Side</i>					
			<i>Explanation : Sidewalks Consist Of 50 Percent Concrete, 50 Percent Not Accessible Due To Construction.</i>					
Wearing Surface								
Concrete	100%			2041		**	5	\$186,300
			<i>Cracks, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Spalling, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RICHMOND AVENUE BRIDGE RICHMOND AVE./RICHMOND CREEK
Asset # : 13517

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Scupper								
Cast Iron	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 4 Scuppers Observed On East Side, Not Accessible On West Side.</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	15%	Now	\$40,800	LIFE		**		
<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 80%</i>								
<i>Location : Throughout</i>								
Generic	85%			LIFE		**		
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RIKERS ISLAND BRIDGE RIKERS ISL BR/RIKERS ISL CHANNEL
Address : RIKERS ISL CHANNEL
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0052.000 / 2478 **Yr Built/Renovated** : 1966 /
Area Sq Ft : 183,419 **Project Type** : WATERWAY BRIDGES
Date of Survey : 29-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240660

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$3,456,700	\$3,037,800
Total	\$3,456,700	\$3,037,800
Importance Code A	\$2,316,300	\$2,088,000
Importance Code B	\$178,800	\$108,900
Importance Code C	\$961,500	\$840,900
Total	\$3,456,700	\$3,037,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$720,100		\$209,400	
Total	\$720,100		\$209,400	
Importance Code A	\$672,500		\$196,200	
Importance Code B	\$28,900		\$10,900	
Importance Code C	\$18,600		\$2,300	
Total	\$720,100		\$209,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
RIKERS ISLAND BRIDGE RIKERS ISL BR/RIKERS ISL CHANNEL
Asset # : 2478

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Concrete	100%	4+	\$3,500	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Backwall								
Concrete	89%			LIFE		**		
Concrete	11%	4+	\$10,500	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	50%	Now	\$9,100	LIFE		**		
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Island Side</i>								
Generic	50%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%	4+	\$1,900	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Stem (breastwall)								
Concrete	100%	4+	\$69,900	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Repair Evident, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Walls								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIKERS ISLAND BRIDGE RIKERS ISL BR/RIKERS ISL CHANNEL
Asset # : 2478

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Feature Crossed								
Mat (scour & erosion)								
Stream Bed	100%			LIFE		**		
Pier Protection								
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	70%			2036		**	4	\$4,600
Asphalt	30%	4+	\$6,100	2036		**	4	\$4,600
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Curbs								
Concrete w/ Steel Face	95%			LIFE		**		
Concrete w/ Steel Face	5%	4+	\$1,800	LIFE		**		
<i>Corrosion, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
Embankment								
Earth	100%			LIFE		**		
Guide Railing								
Concrete	100%			2044		**	4	\$2,500
Steel	75%			LIFE		**	2-8	\$9,300
Steel	25%			LIFE		**	2-8	\$9,300
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE		**		
Sidewalks								
Concrete	90%			LIFE		**		
Concrete	10%	4+	\$2,100	LIFE		**		
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : At Top Surface</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : South Entrance</i>								
<i>Other Observation, Extent : N/A, Area Affected : 2%</i>								
<i>Location : East Sidewalk</i>								
<i>Explanation : Water Main Utility</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Pier,Columns								
Concrete	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIKERS ISLAND BRIDGE RIKERS ISL BR/RIKERS ISL CHANNEL
Asset # : 2478

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing								
Steel	80%			LIFE				**
Steel	20%			LIFE				**
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets								
Steel	70%			LIFE		**	2-8	\$286,500
Steel	30%	4+	\$286,100	LIFE		**	2-8	\$175,900
<i>Corrosion, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Rust Stains, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	90%			2040		**	5	\$81,200
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East Sidewalk</i>								
<i>Explanation : Water Main Utility</i>								
Concrete	10%	4+	\$265,000	2040		**	5	\$40,600
<i>Spalling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Various Locations</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : East Sidewalk</i>								
<i>Explanation : Water Main Utility</i>								
Wearing Surface								
Concrete	90%			2044		**	5	\$840,900
Concrete	10%	4+	\$173,000	2044		**	5	\$420,500
<i>Cracks, Extent : Light, Area Affected : 100%</i>								
<i>Location : Transverse And Map Cracking Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 20%</i>								
<i>Location : Random Locations Throughout, At Deck Joints, Around Manhole Covers</i>								
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Temporary Repair At North End Of The Bridge</i>								
<i>Explanation : Steel Plate</i>								

Superstructure

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
RIKERS ISLAND BRIDGE RIKERS ISL BR/RIKERS ISL CHANNEL

Asset # : 2478

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Superstructure								
Deck, Structural Concrete	100%			LIFE	**	5	\$313,900	
	<i>Cracks, Extent : Light, Area Affected : 1%</i>							
	<i>Location : Random Locations Throughout</i>							
Joints								
Generic	100%	4+	\$103,100	LIFE	**			
	<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 10%</i>							
	<i>Location : Random Locations Throughout</i>							
	<i>Other Observation, Extent : N/A, Area Affected : 10%</i>							
	<i>Location : Near The Center Of The Bridge</i>							
	<i>Explanation : Metal Finger Joints</i>							
Primary Member								
Steel	100%			LIFE	**	2-8	\$5,811,900	
	<i>Corrosion, Extent : Light, Area Affected : 3%</i>							
	<i>Location : Random Locations Throughout</i>							
Secondary Member								
Steel	100%			LIFE	**	2-8	\$299,200	
	<i>Corrosion, Extent : Light, Area Affected : 3%</i>							
	<i>Location : Random Locations Throughout</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ROOSEVELT AVE. BRIDGE / VAN WYCK EXPY, FLUSHING RIVER
Address : VAN WYCK EXPY, FLUSHING RIV.
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0049.070 / 2573 **Yr Built/Renovated** : 1924 /
Area Sq Ft : 84,425 **Project Type** : WATERWAY BRIDGES
Date of Survey : 15-Apr-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240507

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$1,953,600
Total		\$1,953,600
Importance Code C		\$1,953,600
Total		\$1,953,600

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$21,400		\$24,200	\$40,200
Total	\$21,400		\$24,200	\$40,200
Importance Code A	\$1,000		\$600	
Importance Code B	\$2,100			
Importance Code C	\$18,300		\$23,500	\$40,200
Total	\$21,400		\$24,200	\$40,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT AVE. BRIDGE / VAN WYCK EXPY, FLUSHING RIVER

Asset # : 2573

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Not Accessible	100%							
Backwall								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	4+	\$2,100	LIFE			**	
			<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 30%</i>					
			<i>Location : Both Abutments On North Side</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 50%</i>					
			<i>Location : Throughout South Side</i>					
			<i>Explanation : Under Construction</i>					
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Stem (breastwall)								
Not Accessible	100%							
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Not Accessible	100%							
Feature Crossed								
Bank Protection								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT AVE. BRIDGE / VAN WYCK EXPY, FLUSHING RIVER

Asset # : 2573

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	100%			2034	\$449,000	4	\$8,700	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Northwest Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout Southwest Side</i>								
<i>Explanation : Under Construction</i>								
Concrete	100%			2042	**	4	\$8,100	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On Northeast Side</i>								
<i>Recent Repair Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Northeast Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout Southeast Side</i>								
<i>Explanation : Under Construction</i>								
Embankment								
Not Accessible	100%							
Guide Railing								
Concrete	100%			2042	**	4	\$3,000	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout North Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout South Side</i>								
<i>Explanation : Under Construction</i>								
Steel	100%			LIFE	**	2-8	\$4,100	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Steel Railing On Top Of Concrete Guide Rail On North Side</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout North Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout South Side</i>								
<i>Explanation : Under Construction</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT AVE. BRIDGE / VAN WYCK EXPY, FLUSHING RIVER

Asset # : 2573

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On North Side</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout North Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout South Side</i>								
<i>Explanation : Under Construction</i>								
Piers								
Cap Beam								
Not Accessible	100%							
Pier,Columns								
Not Accessible	100%							
Stem,Solid Pier								
Not Accessible	100%							
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Deck Elements								
Guide Railing								
Concrete	100%			2046		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations On North Side</i>								
<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout North Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout South Side</i>								
<i>Explanation : Under Construction</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout North Side</i>								
<i>Explanation : Steel Railing On Top Of Concrete Guide Rail</i>								
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$14,700
<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout North Side</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout South Side</i>								
<i>Explanation : Under Construction</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT AVE. BRIDGE / VAN WYCK EXPY, FLUSHING RIVER

Asset # : 2573

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Sidewalks								
Concrete	100%			2038	**	5	\$47,000	
<i>Cracks, Extent : Light, Area Affected : 2%</i> <i>Location : Random Locations Throughout On North Side</i> <i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout North Side</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout South Side</i> <i>Explanation : Under Construction</i>								
Wearing Surface								
Asphalt	100%			2034	\$1,504,500	5	\$80,500	
<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout North Side</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout South Side</i> <i>Explanation : Under Construction</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout North Side</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout South Side</i> <i>Explanation : Under Construction</i>								
Superstructure								
Deck, Structural								
Not Accessible	100%							
Joints								
Generic	100%	4+	\$12,700	LIFE	**			
<i>Misaligned/Bulging, Extent : Moderate, Area Affected : 5%</i> <i>Location : Random Locations Throughout</i> <i>Missing/Damaged Seal, Extent : Severe, Area Affected : 30%</i> <i>Location : Random Locations Throughout</i> <i>Recent Replace Evident, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout North Side</i> <i>Other Observation, Extent : N/A, Area Affected : 50%</i> <i>Location : Throughout South Side</i> <i>Explanation : Under Construction</i>								
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ROOSEVELT ISLAND BRIDGE E RIVER EAST CHAN/ROOSEVELT ISLD
Address : E RIVER, EAST CHANNEL,36 AVE
Borough : MANHATTAN:QNS. **Agency's Number** : N/A
Program / Asset # : DOT0051.000 / 2477 **Yr Built/Renovated** : 1955 / 2011
Area Sq Ft : 36,543 **Project Type** : WATERWAY BRIDGES
Date of Survey : 22-Apr-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240640

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$216,100	\$814,100
Bridge Electrical	\$57,200	\$24,400
Bridge Mechanical	\$506,700	
Total	\$780,000	\$838,500
Importance Code A		\$361,700
Importance Code B	\$563,900	\$417,200
Importance Code C	\$216,100	\$59,600
Total	\$780,000	\$838,500

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$51,300		\$80,100	
Bridge Electrical	\$23,500	\$1,500	\$1,500	\$1,500
Bridge Mechanical	\$154,800			
Total	\$229,600	\$1,500	\$81,600	\$1,500
Importance Code A			\$40,700	
Importance Code B	\$213,800	\$1,500	\$40,900	\$1,500
Importance Code C	\$15,800			
Total	\$229,600	\$1,500	\$81,600	\$1,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT ISLAND BRIDGE E RIVER EAST CHAN/ROOSEVELT ISLD
Asset # : 2477

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : End Abutment Only.</i>						
		<i>Explanation : Backwall Only.</i>						
Brngs,Ancr Blts,Pads								
Not Accessible	100%							
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	2-4	\$400	LIFE		**		
		<i>Missing/Damaged Seal, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : End Abutment Deck Joint</i>						
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
		<i>Other Observation, Extent : Light, Area Affected : 0%</i>						
		<i>Location : End Abutment Only</i>						
		<i>Explanation : End Abutment Only</i>						
Walls								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : End Approach Only.</i>						
		<i>Explanation : Wingwall Exists.</i>						
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE		**		
Sheet Piling	100%			LIFE		**		
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	6%	4+	\$26,400	LIFE		**		
		<i>Broken/Missing Elements, Extent : Light, Area Affected : 6%</i>						
		<i>Location : Piers 2, 3 & 4</i>						
Timber	94%			LIFE		**		
Approaches								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT ISLAND BRIDGE E RIVER EAST CHAN/ROOSEVELT ISLD
Asset # : 2477

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Pavement								
Asphalt	100%	2-4	\$71,800	2036	**	4	\$22,100	
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : End Approach</i>								
Concrete	100%	2-4	\$144,300	2045	**	4	\$84,600	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : End Approach Slab</i>								
<i>Spalling, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : End Approach Slab</i>								
Curbs								
Steel	100%			LIFE	**			
Guide Railing								
Concrete	100%			2045	**	4		
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Begin Pier</i>								
<i>Explanation : Hollow Sounding Concrete Patches</i>								
Steel	100%			LIFE	**	2-8	\$59,000	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 6 And 7 Only.</i>								
<i>Explanation : Steel Capbeam.</i>								
Pier,Columns								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Pier 5 Only.</i>								
<i>Explanation : Concrete Columns</i>								
Steel	100%			LIFE	**	2-8	\$89,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 6 And 7 Only.</i>								
<i>Explanation : Steel Columns.</i>								
Stem,Solid Pier								
Concrete	1%	Now	\$8,700	LIFE	**			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Piers 1 Through 4</i>								
<i>Explanation : Access Catwalk At Top Of Pier Exhibits Holed Through Or Missing Platform Longitudinal Bars. The Pier 2 Access Platform Adjacent To Right Bearing Exhibits Broken And Missing Rails.</i>								
Concrete	99%			LIFE	**			
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**	2-8	\$9,600	
Footings								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT ISLAND BRIDGE E RIVER EAST CHAN/ROOSEVELT ISLD
Asset # : 2477

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Piers 1, 2, 3, 4 And 5.</i>						
		<i>Explanation : Concrete Pedestal</i>						
Steel	100%			LIFE		**		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Piers 6 And 7.</i>						
		<i>Explanation : Steel Pedestal.</i>						
Deck Elements								
Curbs								
Steel	100%			LIFE		**		
Gratings								
Steel	100%			LIFE		**		
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Spans 2, 3 And 4.</i>						
		<i>Explanation : Steel Grating On Sidewalk.</i>						
Guide Railing								
Steel	100%			LIFE		**		
Railings/Parapets								
Steel	100%			LIFE		**	2-8	\$39,800
Sidewalks								
Concrete	100%			2040		**	5	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Spans 1, 2, 4 Through 8.</i>						
		<i>Explanation : Concrete Sidewalk.</i>						
Steel	100%			2058		**	2-8	
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Span 3</i>						
		<i>Explanation : Steel Plate On Top Of Concrete Filled Grating</i>						
Wearing Surface								
Asphalt	100%	Now	\$15,800	2036		**	5	\$10,100
		<i>Broken, Missing Pave, Extent : Severe, Area Affected : 10%</i>						
		<i>Location : Spans 1, 2, 4 Through 8</i>						
		<i>Other Observation, Extent : Light, Area Affected : 100%</i>						
		<i>Location : Spans 1, 2, 4 Through 8.</i>						
		<i>Explanation : Asphalt Wearing Surface.</i>						
Steel Grating	100%			LIFE		**	5	\$59,600
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Span 3.</i>						
		<i>Explanation : Steel Grating</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT ISLAND BRIDGE E RIVER EAST CHAN/ROOSEVELT ISLD
Asset # : 2477

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Scupper								
Stainless Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span 7, North Side.</i>								
<i>Explanation : 1 Scupper</i>								
Superstructure								
Deck, Structural								
Grating w/ Concrete	100%			LIFE		**		
<i>Corrosion, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Spans 5, 6 & 7</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1, 2, 4 Through 8</i>								
<i>Explanation : Concrete Filled Grating</i>								
Steel Grating	100%			LIFE		**	5	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span 3.</i>								
<i>Explanation : Steel Grating Deck.</i>								
Joints								
Steel Finger Joints	100%			2067		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span 3</i>								
<i>Explanation : Steel Finger Joint</i>								
Generic	100%			LIFE		**		
Primary Member								
Steel	100%			LIFE		**	2-8	\$675,600
<i>Loss of Section, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Primary And Secondary Steel Members In Spans 5, 6, And 8</i>								
Secondary Member								
Steel	100%			LIFE		**	2-8	\$565,900
<i>Loss of Section, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Spans 5, 6, And 8</i>								
Movable Bridges								
Vertical Lift Span								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Span 3 Primary And Secondary Members</i>								
<i>Explanation : Arrested Section Losses To Steel Members</i>								
Vertical Lift Tower								
Steel	100%			LIFE		**		
Vertical Lift Pier								
Concrete	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Piers 2 And 3</i>								
<i>Explanation : Concrete Piers Exhibit Fine Cracks And Small Spalls At Top Of Pier 2 And 3.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT ISLAND BRIDGE E RIVER EAST CHAN/ROOSEVELT ISLD
Asset # : 2477

Bridge Electrical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Communication Electrical								
Air Horn								
Generic	100%			2033	\$2,500			
Communications								
Generic	100%			2031	\$39,100			
Control System Electrical								
Control Console								
Stainless Steel	100%	Now	\$7,200	LIFE		* *		
		<i>Other Observation, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Control Room</i>						
		<i>Explanation : 2 Pilot Lights For The Fully Seated Limit Switches Remain On During Lift.</i>						
Disconnect Switch								
Non Fused	100%			2049		* *		
Limit Switch								
Lever	100%	Now	\$10,300	2031	\$20,600			
		<i>Other Observation, Extent : Light, Area Affected : 75%</i>						
		<i>Location : All Corners</i>						
		<i>Explanation : Several Fully Seated Limit Switches Are Malfunctioning And In Poor Condition.</i>						
Local Starter								
Magnetic	100%			2049		* *		
Ground/Lightning Protection								
Ground Bus								
Copper	100%			2036		* *		
Ground Rod								
Not Accessible	100%							
Ground Wire								
Green	100%			2036		* *		
Lightning Terminals								
Not Accessible	100%							
Raceway								
Wiring								
Generic	100%			2036		* *		
Stand-by Power								
Generator								
Diesel	100%	Now	\$4,500	2049		* *		
		<i>Other Observation, Extent : Light, Area Affected : 25%</i>						
		<i>Location : Back Up Generator House In Queens</i>						
		<i>Explanation : The Annunciator Does Not Show When The Generator Is Supplying Load. Unable To Confirm All Indicators Are Operating Correctly From Visual Survey.</i>						
Transfer Switch								
Auto	100%			2049		* *		
Lighting								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT ISLAND BRIDGE E RIVER EAST CHAN/ROOSEVELT ISLD
Asset # : 2477

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Lighting								
Lighting Devices								
Generic	38%	Now	\$44,100	2037		**		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Span 3</i>								
<i>Explanation : Incandescent Exterior Light Fixture Filled With Water.</i>								
Generic	5%	Now	\$5,800	2037		**		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout Bridge Areas</i>								
<i>Explanation : Majority Of Emergency Lights Have Failed.</i>								
Generic	21%	Now	\$7,300	2033	\$24,400			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Northeast And Southeast</i>								
<i>Explanation : Pier Light Not In Operation.</i>								
Generic	36%			2036		**		
Main Drive								
Motor Controller								
Drum Controller	100%			2067		**	1	\$15,300

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Vertical Lift								
Buffers								
Generic	100%			2045		**		
Counter Weight Ropes & Gui								
Generic	100%	Now	\$49,400	2067		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Upper Span Guide Rails</i>								
<i>Lubrication Issue, Extent : Light, Area Affected : 5%</i>								
<i>Location : Ropes And Guide Rails</i>								
Counter Weight								
Auxiliary CTRWT	100%	Now	\$8,400	2067		**		
<i>Lubrication Issue, Extent : Light, Area Affected : 2%</i>								
<i>Location : Counterweights</i>								
Main CTRWT	100%	0-2	\$69,500	2067		**		
<i>Broken/Missing Elements, Extent : Light, Area Affected : 5%</i>								
<i>Location : Pocket Covers Missing Fasteners At Top.</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Top</i>								
<i>Explanation : Pigeon Droppings On And Around Top. Beam Clamp Installed Above Counterweight At East Counterweight.</i>								
Elevators								
Generic	100%	Now	\$267,700	2045		**		
<i>Other Observation, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : East And West Towers</i>								
<i>Explanation : No Operation Was Observed. Elevators Reported Not To Work.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT ISLAND BRIDGE E RIVER EAST CHAN/ROOSEVELT ISLD
Asset # : 2477

Bridge Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Vertical Lift								
Emergency Drive Emergency Power	100%	Now	\$24,300	2067			**	
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Machinery And Generator Rooms</i>								
<i>Explanation : No Operation Observed. Actuator Mount May Require Adjustment. Generator Reported Not To Be Working</i>								
End Locks								
With Motor	100%	Now	\$53,100	2067			**	
<i>Corrosion, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Heavy Corrosion On Supports At Tower Piers</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Tower Piers</i>								
<i>Explanation : Reducer Sight Glasses Are Cloudy, Low Oil Level. Reducers Do Not Have Breathers.</i>								
Fuel Tanks								
Generic	100%	Now	\$400	2049			**	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Fuel Tank/ Generator Room</i>								
<i>Explanation : Wire Harness Is Loose At Top Of Fitting. Some Areas Of Tank And Frame Do Not Bear On Concrete</i>								
Houses								
Access Ways	20%	Now	\$31,700	2045			**	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Access To Locks</i>								
<i>Explanation : Accessway Hatch To Lock Platforms Problematic. Machinery Room Contactless Card Readers Not Working. Overhead Crane Chain Close To Rotating Machinery.</i>								
Access Ways	80%	Now	\$31,700	2045			**	
<i>Other Observation, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Tower Accessways</i>								
<i>Explanation : Tops Of Tower Accessways Covered In Pigeon Droppings. Corroded Grating And Missing Safety Chains At Some Access Points.</i>								
Control House	100%	Now	\$17,100	2067			**	
<i>Other Observation, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Control House</i>								
<i>Explanation : Fire Alarm, Key Pad Door Entry And Security Cameras Not Working.</i>								
Main Drive System								
Generic	30%	Now	\$53,000	2067			**	
<i>Lubrication Issue, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Machinery Rooms</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Machinery Rooms</i>								
<i>Explanation : Loose Inspection Cover Bolts. Brakes May Require Adjustment. Slight Rubbing Of Covers.</i>								
Generic	70%			2067			**	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ROOSEVELT ISLAND BRIDGE E RIVER EAST CHAN/ROOSEVELT ISLD
Asset # : 2477

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Vertical Lift								
Sheaves								
Generic	100%			2067		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Northeast And Northwest Sheaves</i>								
<i>Explanation : Noisy During Operation.</i>								
Structural Bearings								
Generic	100%	Now	\$13,600	2045		**		
<i>Improper Bearing, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Expansion Live Load Bearings</i>								
Traffic Devices								
Barrier Gate								
	100%	Now	\$38,600	2045		**		
<i>Other Observation, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Barrier Gates</i>								
<i>Explanation : Missing Gate Arm Locking Latches On Housings. Some Adjustments Required.</i>								
Signals								
	100%	Now	\$3,200	2045		**		
<i>Other Observation, Extent : Light, Area Affected : 20%</i>								
<i>Location : Queens Approach</i>								
<i>Explanation : Traffic Signal Is Skewed. Similarly For Stop Line Signal.</i>								
Warning Gate								
	100%			2045		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : THIRD AVE. BRIDGE RAMP TO BRUCKNER BLVD/RELIEF
Address : HARLEM RIVER, HARLEM RIV DR.
Borough : MANHATTAN:BX. **Agency's Number** : N/A
Program / Asset # : DOT0041.0A0 / 4320 **Yr Built/Renovated** : 2006 /
Area Sq Ft : 11,100 **Project Type** : WATERWAY BRIDGES
Date of Survey : 08-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224006A

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$338,000
Total		\$338,000
Importance Code A		\$109,900
Importance Code B		\$109,900
Importance Code C		\$118,300
Total		\$338,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$10,600		\$53,700	
Total	\$10,600		\$53,700	
Importance Code A	\$6,700		\$11,000	
Importance Code B			\$11,000	
Importance Code C	\$3,900		\$31,600	
Total	\$10,600		\$53,700	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE RAMP TO BRUCKNER BLVD/RELIEF
Asset # : 4320

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Backwall								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2053		**		
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE		**		
Pedestals								
Concrete	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%			LIFE		**		
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Southeast Wing Wall Not Accessible</i>								
Feature Crossed								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
Approaches								
Pavement								
Asphalt	100%			2034	\$118,300	4	\$2,900	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2042		**	4	\$5,300
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
Pier,Columns								
Concrete	100%			LIFE		**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE RAMP TO BRUCKNER BLVD/RELIEF
Asset # : 4320

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier								
Concrete	100%			LIFE			**	
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2053			**	
Multi-Rotational Bearing	100%			2061			**	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 3rd Pier From East End</i>								
<i>Explanation : High- Load Multi- Rotational Bearing</i>								
Footings								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE			**	
Piles								
Not Accessible	100%							
Deck Elements								
Mono Deck Surface								
Concrete	100%			2053		**	5	\$63,200
Railings/Parapets								
Concrete	100%			2042		**	4	\$14,700
Scupper								
Cast Iron	100%	Now	\$3,000	LIFE		**		
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 20%</i>								
<i>Location : At Span 3</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Total Of 5 Scuppers</i>								
Superstructure								
Deck,Structural								
Concrete	100%			LIFE		**	5	\$14,600
<i>Corrosion, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout Stay-in-place Forms</i>								
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : All Spans, Except At Deck Overhangs</i>								
<i>Explanation : Stay-in-place Forms Used With Concrete Deck</i>								
Joints								
Generic	100%			LIFE		**		
Primary Member								
Steel	100%			LIFE		**	2-8	\$205,200
Secondary Member								
Steel	100%			LIFE		**	2-8	\$171,900

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : THIRD AVE. BRIDGE THIRD AVE BRIDGE/HARLEM RIVER
Address : HARLEM RIVER, HARLEM RIV DR.
Borough : MANHATTAN:BX. **Agency's Number** : N/A
Program / Asset # : DOT0041.090 / 4319 **Yr Built/Renovated** : 2005 /
Area Sq Ft : 79,900 **Project Type** : WATERWAY BRIDGES
Date of Survey : 21-Apr-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240069

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$3,664,300	\$1,937,700
Bridge Electrical	\$131,000	\$105,100
Bridge Mechanical	\$119,400	
Total	\$3,914,600	\$2,042,800
Importance Code A	\$3,128,800	\$905,100
Importance Code B	\$250,300	\$895,900
Importance Code C	\$535,400	\$241,800
Total	\$3,914,600	\$2,042,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$84,200		\$162,500	
Bridge Electrical	\$50,900	\$2,000	\$2,000	\$2,000
Bridge Mechanical	\$197,700	\$9,000		\$9,000
Total	\$332,900	\$10,900	\$164,400	\$10,900
Importance Code A	\$70,300		\$83,200	
Importance Code B	\$250,000	\$10,900	\$81,300	\$10,900
Importance Code C	\$12,500			
Total	\$332,900	\$10,900	\$164,400	\$10,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE THIRD AVE BRIDGE/HARLEM RIVER
Asset # : 4319

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE		**		
Backwall Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads Elastomeric	100%			2058		**		
Footings Not Accessible	100%							
Joint with Deck Generic	100%	4+	\$1,400	LIFE		**		
			<i>Leakage, Extent : Severe, Area Affected : 5%</i>					
			<i>Location : Begin Abutment Joint</i>					
			<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>					
			<i>Location : Begin & End Abutment Joints</i>					
			<i>Explanation : Begin And End Abutment Concrete Header Exhibits Cracks</i>					
Mat (scour & erosion) Generic	100%			LIFE		**		
Pedestals Concrete	100%			LIFE		**		
Stem (breastwall) Concrete	100%			LIFE		**		
Walls Concrete	100%			LIFE		**		
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
Generic	100%			LIFE		**		
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE		**		
Feature Crossed								
Bank Protection Concrete	100%			LIFE		**		
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Timber	100%			LIFE		**		
Approaches								
Pavement Concrete	100%	4+	\$231,800	2045		**	4	\$46,100
			<i>Cracks, Extent : Severe, Area Affected : 5%</i>					
			<i>Location : Begin Approach Slab</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE THIRD AVE BRIDGE/HARLEM RIVER
Asset # : 4319

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Embankment								
Earth	100%			LIFE	**			
Generic	100%			LIFE	**			
Guide Railing								
Concrete	100%	Now	\$49,600	2045	**	4	\$6,900	
<i>Spalling, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Begin Right Approach Guide Rail</i>								
<i>Other Observation, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Begin Left Approach Guide Rail, 100 Feet From Bridge.</i>								
<i>Explanation : Severe Spalling Exposing Two Of Four Anchor Bolts Of Metal Railing 100 Feet From Start Of Bridge.</i>								
Steel	100%	Now	\$4,400	LIFE	**	2-8	\$18,700	
<i>Other Observation, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Begin Right Approach Rail</i>								
<i>Explanation : 2 Of 4 Exposed Anchor Bolts At Railing Post Due To Spalled Concrete</i>								
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pavement Base								
Not Accessible	100%							
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
Pier,Columns								
Concrete	100%			LIFE	**			
Stem,Solid Pier								
Concrete	100%			LIFE	**			
Piles								
Steel	75%	Now	\$356,800	LIFE	**			
<i>Loss of Section, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Pier 8 Steel Piles</i>								
Steel	25%			LIFE	**			
Deck Elements								
Guide Railing								
Concrete	100%	Now	\$16,400	2049	**			
<i>Spalling, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Span 10, Left Guiderail & Span 11, Right Guiderail</i>								
Steel	100%			LIFE	**			
Mono Deck Surface								
Concrete	100%			2058	**	5	\$220,800	
Railings/Parapets								
Steel	100%			LIFE	**	2-8	\$94,600	
Sidewalks								
Concrete	100%	4+	\$94,100	2040	**	5	\$15,700	
<i>Cracks, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Spans 1, 2, 3, 4, 10 And 11</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE THIRD AVE BRIDGE/HARLEM RIVER
Asset # : 4319

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Wearing Surface Concrete	100%	Now	\$99,100	2045	**	5	\$131,400	
<i>Spalling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Spans 5 And 6</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Spans 5 And 6</i>								
<i>Explanation : Uneven Riding Surface Due To Numerous Asphalt Patched Potholes</i>								
<hr/>								
Scupper Cast Iron	100%	Now	\$12,500	LIFE	**			
<i>Drains Clogged, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Span 12, Right Scupper</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 Through 4 & 9 Through 14</i>								
<i>Explanation : One Scupper In Spans 12, 13 And 14 (Left Side); Two Scuppers Each In Spans 1, 2, 3, 4, 9, 10; Three Scuppers In Span 11 (2 On Right Side, 1 On Left Side).</i>								
<i>Other Observation, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Piers 1 And 11</i>								
<i>Explanation : Drainage Pipes Are Disconnected At Elbow Connections Due To Fully Cracked Welds.</i>								
<hr/>								
Superstructure								
Deck, Structural Concrete	100%	4+	\$1,448,900	LIFE	**	5	\$83,200	
<i>Corrosion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Spans 1 Through 4, 7, 8, And 10 Through 14</i>								
<hr/>								
Joints								
Steel Generic	100%			LIFE	**			
<hr/>								
Primary Member								
Prestressed Concrete Box Beam	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Span 8 Only</i>								
<i>Explanation : Location Noted.</i>								
<hr/>								
Steel	100%			LIFE	**	2-8	\$1,477,100	
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$1,237,400	
<hr/>								
Movable Bridges								
Swing Span Truss								
Steel	100%			LIFE	**			
<hr/>								
Swing Span Pivot Pier								
Concrete	100%	4+	\$1,323,200	LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Pier 5</i>								
<i>Explanation : Longitudinal Crack Up To 1 Inch Wide</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE THIRD AVE BRIDGE/HARLEM RIVER

Asset # : 4319

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Air Horn								
Generic	100%			2031	\$2,500			
Intercom								
Generic	100%	Now	\$63,100	2031	\$105,100			
<i>Other Observation, Extent : Severe, Area Affected : 60%</i>								
<i>Location : End Rest Piers</i>								
<i>Explanation : Several Intercom Stations Have Failed Or Have Severe Corrosion.</i>								
Telephone								
Desk Top	100%			2031				
Jack								
Telephone	100%			2031				
Control System Electrical								
Computer								
PLC	100%			2031	\$29,400			
Control Console								
Stainless Steel	100%			LIFE	**			
<i>Broken/Missing Elements, Extent : Light, Area Affected : 10%</i>								
<i>Location : Control Desk</i>								
Control Devices								
Relay	100%	Now	\$14,600	2049	**			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Control House</i>								
<i>Explanation : Bridge Trips Out At Near Full Open And Near Full Closed. Drive 2 Pulsates. Drive 1 Trips Out System Everytime.</i>								
Disconnect Switch								
Non Fused	100%			2049	**			
Limit Switch								
Generic	100%	Now	\$8,400	2049	**			
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Bronx And Manhattan Rest Piers</i>								
<i>Explanation : End Lift Rotary Cam Limit Switches Failed To Provide Indication.</i>								
Local Starter								
Magnetic	100%			2049	**			
Drive								
Grating Motor								
Generic	100%			2058	**			
Machinery Brake								
Thruster	100%			2058	**			
Motor Brake								
Thruster	100%			2058	**			
Span Lock Motor								
Generic	100%			2058	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Span Locks</i>								
<i>Explanation : Span Locks Used For End Lifts Description</i>								
Wedge Motor								
Generic	100%			2058	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE THIRD AVE BRIDGE/HARLEM RIVER

Asset # : 4319

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Electrical Power								
MCC								
	Generic	100%			2049	**		
Panelboard								
	Circuit Breaker	100%			2049	**	1	\$6,700
Transfer Switch								
	Auto	100%	Now	\$2,800	2049	**		
			<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Control Room</i>					
			<i>Explanation : Manhattan Power Source Failed To Operate Bridge.</i>					
Transformer								
	Dry	100%			2049	**		
Ground/Lightning Protection								
Ground Bus								
	Copper	100%			2036	**		
Ground Rod								
	Not Accessible	100%						
Raceway								
Box								
	Pull Junction	100%			2040	**		
	Terminal	100%			2040	**		
Conduit								
	Metal	100%			2067	**		
Submarine Control Cables								
	Control	100%			2036	**		
Submarine Power Cable								
	Power	100%			2036	**		
Trough								
	Metal	100%			2067	**		
Wires								
	Thermoplastic	100%			2049	**		
Span Lock								
Motor								
	Squirrel Cage	100%			2045	**		
Stand-by Power								
Transfer Switch								
	Auto	100%			2049	**		
Lighting								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE THIRD AVE BRIDGE/HARLEM RIVER
Asset # : 4319

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Lighting								
Lighting Devices								
Generic	5%	Now	\$11,900	2037	**			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : East And West Rest Piers</i>								
<i>Explanation : Ground Electrode Conductor Severed.</i>								
Generic	5%	Now	\$11,900	2037	**			
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Throughout Bridge Areas.</i>								
<i>Explanation : All Emergency Exit Lights Have Failed.</i>								
Generic	5%	Now	\$600	2036	**			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Control Room</i>								
<i>Explanation : Fluorescent Lights Out.</i>								
Generic	85%			2037	**			

Main Drive

Motor Controller

Thyristor Drive

100%	Now	\$67,900	2040	**	1-5	\$13,100		
<i>Erratic Operation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Control Room</i>								

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Swing								
Center Latch								
Generic	100%	Now	\$4,100	2067	**			
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Center Latches</i>								
<i>Explanation : One Loose Limit Switch Arm. Proximity Switch Target Has Deteriorated.</i>								
Center Lift								
Generic	100%	Now	\$67,600	2067	**			
<i>Corrosion, Extent : Severe, Area Affected : 5%</i>								
<i>Location : North And South Center Wedges</i>								
<i>Lubrication Issue, Extent : Severe, Area Affected : 5%</i>								
<i>Location : North And South Center Wedges</i>								
Center Pivot								
Generic	20%	Now	\$51,800	2067	**			
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Center Pivot</i>								
<i>Explanation : Low Oil Level. Filter Requires Replacement.</i>								
Generic	80%			2067	**			
Emergency Drive								
Emergency Power								
100%				2067	**	2	\$44,900	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Emergency Drive</i>								
<i>Explanation : Not Tested. Failure.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE THIRD AVE BRIDGE/HARLEM RIVER
Asset # : 4319

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Swing								
End Lift								
Generic	100%	Now	\$44,300	2067				**
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Machinery Cover Supports At East And West Piers</i>								
<i>Not Functioning, Extent : Light, Area Affected : 5%</i>								
<i>Location : Hydraulic Jacks At East And West Rest Piers</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : East And West Rest Piers</i>								
<i>Explanation : Some Coverage Of Debris. Lubrication Charts Covered In Graffiti. Span Locks Used For End Lifts Description. West End Lift Motor Junction Box Broken.</i>								
Fuel Tanks								
Generic	100%			2049				**
Houses								
Access Ways	100%	Now	\$27,300	2067				**
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : East And West Rest Piers</i>								
<i>Explanation : Hatches At Rest Pier End Lift Need To Be Repaired</i>								
Control House	100%	Now	\$39,700	2067				**
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Bathroom</i>								
<i>Explanation : Bathroom Damaged, Not Functioning. Floors Need Repair. Exposed Electrical Throughout. Heat And Ac Not Working.</i>								
Machinery Room	100%			2067				**
Main Drive System								
Generic	100%			2067				**
<i>Broken/Missing Elements, Extent : Light, Area Affected : 1%</i>								
<i>Location : Lubrication Charts At Center Of Swing Span</i>								
<i>Lubrication Issue, Extent : Light, Area Affected : 1%</i>								
<i>Location : Center Of Swing Span</i>								
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Center Of Swing Span</i>								
<i>Explanation : Breathers Will Need To Be Changed Soon. Loose Covers, Reducer Oil Levels Hard To Read. Standing Water In Rack Support Pockets. Turning Machinery Float Shaft Cover Missing.</i>								
Structural Bearings								
Generic	100%			2047				**

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
THIRD AVE. BRIDGE THIRD AVE BRIDGE/HARLEM RIVER

Asset # : 4319

Bridge Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Swing								
Traffic Devices								
Barrier Gate	100%	Now	\$31,500	2045				* *
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 2%</i>								
<i>Location : East And West Barrier Gates</i>								
<i>Other Observation, Extent : Severe, Area Affected : 2%</i>								
<i>Location : East And West Barrier Gates</i>								
<i>Explanation : Loose Crash Gate Wire Anchor Base Nuts. Exposed Electrical. Damaged Angle. Missing Plunger Rods.</i>								
Signals	100%	Now	\$24,800	2047				* *
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : East Approach North Side</i>								
<i>Explanation : Green Light Flickering</i>								
Warning Gate	65%			2045				* *
Warning Gate	35%	Now	\$26,000	2045				* *
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northwest Gate</i>								
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : East Approach</i>								
<i>Explanation : Lens Broken On Advance Warning Sign</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Northwest Gate</i>								
<i>Explanation : Bent Guy Wire Frame.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : UNIONPORT BRIDGE BRUCKNER EXPRESSWAY SERVICE ROAD
 Address : WESTCHESTER CREEK
 Borough : BRONX Agency's Number : N/A
 Program / Asset # : DOT0140.000 / 4244 Yr Built/Renovated :
 Area Sq Ft : 4,900 Project Type : WATERWAY BRIDGES
 Date of Survey : 23-May-2014 Landmark Status : NONE
 Areas Surveyed :
 Block : Lot : BIN : 1066510

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$4,225,000	\$270,100
Bridge Electrical	\$2,060,600	\$1,148,900
Bridge Mechanical	\$7,513,100	
Total	\$13,798,700	\$1,419,000
Importance Code A	\$3,723,300	\$51,400
Importance Code B	\$9,835,800	\$1,148,900
Importance Code C	\$239,600	\$218,700
Total	\$13,798,700	\$1,419,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$175,300		\$800	
Bridge Electrical	\$220,300			
Bridge Mechanical	\$111,700			
Total	\$507,300		\$800	
Importance Code A	\$13,600		\$800	
Importance Code B	\$378,200			
Importance Code C	\$115,500			
Total	\$507,300		\$800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNIONPORT BRIDGE BRUCKNER EXPRESSWAY SERVICE ROAD
Asset # : 4244

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%	0-2	\$2,800	LIFE			**	
<i>Joints Missing, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Begin Abutment</i>								
<i>Leakage, Extent : Severe, Area Affected : 20%</i>								
<i>Location : At Begin Abutment Stem</i>								
Mat (scour & erosion)								
Earth	100%			LIFE			**	
Stem (breastwall)								
Concrete	100%	4+	\$167,300	LIFE			**	
<i>Cracking/Crumbling, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Begin Abutment</i>								
<i>Delaminations, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Begin Abutment</i>								
<i>Spalling, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Begin Abutment</i>								
Walls								
Concrete	100%			LIFE			**	
Feature Crossed								
Bank Protection								
Riprap	100%			LIFE			**	
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	100%	Now	\$36,700	LIFE			**	
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 70%</i>								
<i>Location : Piers 8 And 9.</i>								
<i>Rotted, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Piers 8 And 9.</i>								
Approaches								
Pavement								
Asphalt	100%			2026	\$239,600	4	\$11,100	
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : End Approach Only.</i>								
<i>Explanation : End Approach Only.</i>								
Curbs								
Concrete	100%			LIFE			**	
Concrete w/ Steel Face	100%			LIFE			**	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Left Side End Approach</i>								
<i>Explanation : Left Side End Approach</i>								
Embankment								
Earth	100%			LIFE			**	
Guide Railing								
Steel	100%			LIFE		**	2-8	\$5,800

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNIONPORT BRIDGE BRUCKNER EXPRESSWAY SERVICE ROAD
Asset # : 4244

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Sidewalks								
Concrete	100%			LIFE	**			
Piers								
Cap Beam								
Concrete	65%			LIFE	**			
Concrete	35%	0-2	\$175,700	LIFE	**			
<i>Leakage, Extent : Severe, Area Affected : 50%</i>								
<i>Location : At Cap Beam 1, 3, 5, 7, 10, 12, 14, 16</i>								
<i>Spalling, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Cap Beams 12, 14, 16 Right Side</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Piers 1, 3, 5, 7, 10, 12, 14, 16.</i>								
<i>Explanation : Cap Beams Spalling And Cracking</i>								
Pier,Columns								
Concrete	70%			LIFE	**			
Concrete	30%	0-2	\$94,800	LIFE	**			
<i>Cracks, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Piers 1, 3, 7, 13, 14, And 16</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Piers 1, 3, 7, 13, 14, And 16</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Piers 1, 3, 7, 13, 14, And 16</i>								
Stem,Solid Pier								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**	2-8	\$8,000	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 7, 8, 9, 10 And 15.</i>								
<i>Explanation : Spans 7, 8, 9, 10 And 15.</i>								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%	0-2	\$12,100	LIFE	**			
<i>Erosion, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Under Spans 10, 11, 12 And 14</i>								
Pedestals								
Concrete	100%	0-2	\$6,800	LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Pier 9</i>								
<i>Explanation : Pier 8 And 9</i>								
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNIONPORT BRIDGE BRUCKNER EXPRESSWAY SERVICE ROAD
Asset # : 4244

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Curbs								
Concrete	100%			2045		**		
Concrete w/ Steel Face	100%	Now	\$1,300	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Span 17 Left Side</i>								
<i>Explanation : Steel Plate Loose At End Abutment.</i>								
<hr/>								
Median								
Concrete	100%			LIFE		**	5	\$1,100
<hr/>								
Mono Deck Surface								
Concrete	90%			2035	\$196,800		5	\$26,600
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 6 - 8 And 10 - 12.</i>								
<i>Explanation : Spans 6 - 8 And 10 - 12.</i>								
Concrete	10%	2-4	\$4,400	2035	\$21,900		5	\$13,300
<i>Cracks, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Spans 6, 7, 8, 10 Through 12</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Spans 6, 7, 8, 10 Through 12</i>								
<i>Explanation : Numerous Patched Potholes,</i>								
<hr/>								
Railings/Parapets								
Concrete	100%			2040		**	4	
Steel	95%			LIFE		**	2-8	\$4,300
Steel	5%	4+	\$100	LIFE		**	2-8	\$4,300
<i>Corrosion, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Spans 8 And 10</i>								
<hr/>								
Sidewalks								
Asphalt	100%	Now	\$2,900	2026	\$14,300		4	\$2,200
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Span 9</i>								
<i>Explanation : Missing Asphalt Pavers.</i>								
Concrete	90%			2030	\$32,300		5	\$600
Concrete	10%	4+	\$400	2030	\$3,600		5	\$300
<i>Cracks, Extent : Light, Area Affected : 40%</i>								
<i>Location : Spans 8, 13, 14, And 16.</i>								
<hr/>								
Wearing Surface								
Asphalt	90%			2026	\$42,700		5	\$6,000
Asphalt	10%	0-2	\$500	2030	\$4,700		5	\$3,000
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Spans 5 Left Side, Westbound.</i>								
<i>Explanation : Potholes And Uneven Asphalt Patches</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%	4+	\$703,700	LIFE		**	5	\$6,700
<i>Spalling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Spans 8, 10,</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNIONPORT BRIDGE BRUCKNER EXPRESSWAY SERVICE ROAD

Asset # : 4244

Bridge Structure		Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority	

Superstructure

Joints

Steel	60%			LIFE		**		
Steel	40%	Now	\$43,700	LIFE		**		
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 60%</i>								
<i>Location : Spans 1, 3, 5, 7, 10, 12, 14 And 16</i>								
<i>Leakage, Extent : Moderate, Area Affected : 75%</i>								
<i>Location : Spans 1, 3, 5, 7, 10, 12, 14 And 16</i>								

Primary Member

Concrete	70%			LIFE		**	5	\$25,700
Concrete	30%	2-4	\$244,700	LIFE		**	5	\$25,700
<i>Cracks, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Spans 1 Through 7 And 11 Through 17</i>								
<i>Exposed Reinforcement, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Spans 1 Through 7 And 11 Through 17</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Spans 1 Through 7 And 11 Through 17</i>								

Secondary Member

Not Accessible	100%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : Spans 8 And 10.</i>								

Movable Bridges

Bascule Span

Steel	50%			LIFE		**		
Steel	50%	2-4	\$2,050,100	LIFE		**		
<i>Other Observation, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Span 9</i>								
<i>Explanation : Steel Section Loss And Corrosion Holes. Cracked Steel Grating Panel. Poor Condition Of Right Sidewalk.</i>								

Bascule Span Pier

Concrete	100%	2-4	\$549,100	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Bascule Span Piers</i>								
<i>Explanation : Spalls And Cracks</i>								

Bridge Electrical		Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority	

Communication Electrical

Communications

Generic	100%	Now	\$41,100	2026	\$41,100			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Numerous Locations</i>								
<i>Explanation : System Not Operational</i>								

Control System Electrical

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNIONPORT BRIDGE BRUCKNER EXPRESSWAY SERVICE ROAD
Asset # : 4244

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Control System Electrical								
Control Console								
Stainless Steel	100%	Now	\$65,400	LIFE		**		
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : On Console</i>								
<i>Explanation : Bridge Fully Open Indications Do Not Illuminate, Nameplates Barely Legible</i>								
Disconnect Switch								
Generic	100%	4+	\$44,700	2045		**		
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Various</i>								
<i>Explanation : Disconnect Switches Are Not All Operable</i>								
Limit Switch								
Generic	100%	0-2	\$45,300	2045		**		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : East And West Leaves</i>								
<i>Explanation : Limit Switch Housing Severely Corroded</i>								
Electrical Power								
Dist Equip & Motor Controll								
Generic	100%	0-2	\$532,100	2045		**		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Electrical Room</i>								
<i>Explanation : Not Osha Compliant, No Replacement Parts Available</i>								
Raceway								
Submarine Control Cables								
Not Accessible	100%							
Wiring								
Generic	100%	0-2	\$1,148,900	2030	\$1,148,900			
<i>Other Observation, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Various</i>								
<i>Explanation : Conduit Is Corroded. Wiring Is Damaged.</i>								
Traffic System Electrical								
Traffic Signal								
Generic	100%	Now	\$48,200	2026	\$160,700			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Approaches</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Approaches</i>								
<i>Explanation : Some Bulbs Need Replacement</i>								
Lighting								
Lighting Devices								
Generic	100%	Now	\$57,500	2026	\$95,900			
<i>Other Observation, Extent : Moderate, Area Affected : 60%</i>								
<i>Location : Various</i>								
<i>Explanation : Various Service Lighting Fixtures Are Broken/ Missing</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNIONPORT BRIDGE BRUCKNER EXPRESSWAY SERVICE ROAD

Asset # : 4244

Bridge Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Bascule								
Counter Weight Generic	100%	Now	\$30,500	2040			**	
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i> <i>Location : Counter Weights</i> <i>Explanation : Blocks On Top Of West Counter Weight Are Not Secured</i>								
Emergency Drive								
Emergency Power	100%	Now	\$6,100	2028	\$122,000			
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i> <i>Location : Auxiliary Drives</i> <i>Explanation : No Operation Observed. Need To Perform Maintenance, Repairs And Test Auxiliary Drive.</i>								
Manual	100%	Now	\$33,400	2028	\$167,000			
<i>Other Observation, Extent : Moderate, Area Affected : 75%</i> <i>Location : Manual Drive Components</i> <i>Explanation : No Operation Observed. Covered In Pigeon Droppings And Appears To Be Frozen</i>								
Fuel Tanks								
Generic	100%	Now	\$700	2030	\$6,800			
<i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Operators House</i> <i>Explanation : Slight Leakage Noted On Top Fittings, Bottom Not Accessible</i>								
Houses								
Access Ways	80%	4+	\$33,600	2028	\$167,800			
<i>Other Observation, Extent : Light, Area Affected : 75%</i> <i>Location : Span Drive Machinery</i> <i>Explanation : Mild Corrosion.</i>								
Access Ways	20%	Now	\$21,000	2028	\$42,000			
<i>Other Observation, Extent : Severe, Area Affected : 40%</i> <i>Location : Center Locks</i> <i>Explanation : Corrosion Of Access Platforms And Covered In Pigeon Droppings.</i>								
Control House	100%	Now	\$32,200	2040			**	
<i>Other Observation, Extent : Light, Area Affected : 5%</i> <i>Location : Control And Tender Houses</i> <i>Explanation : Some Window Leak. Reported That Air Conditioning Unit Does Not Cool Room.</i>								
Machinery Room	100%	Now	\$8,800	2040			**	
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Machinery Rooms</i> <i>Explanation : Some Broken Locks. Some Small Floor Panels Replaced With Plywood. Some Pigeon Droppings.</i>								
Lock Bars								
With Motor	100%	Now	\$269,000	2028	\$538,000			
<i>Other Observation, Extent : Severe, Area Affected : 50%</i> <i>Location : Lock Bar Machinery</i> <i>Explanation : Not Accessible From Platform. Machinery Is Covered In Debris, Corroded And Is In Poor Condition. Some Binding</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
UNIONPORT BRIDGE BRUCKNER EXPRESSWAY SERVICE ROAD

Asset # : 4244

Bridge Mechanical	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Bascule								
Main Drive System Generic	100%	Now	\$402,400	2028	\$4,024,000			
<i>Other Observation, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Machinery Room</i>								
<i>Explanation : One Brake Not Functioning. Lubricant Leakage. Some Corrosion. Some Bolts Have Heavy Corrosion/ Loss</i>								
<hr/>								
Rack Generic	100%	2-4	\$54,900	2040			**	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Racks</i>								
<i>Explanation : Some Corrosion</i>								
<hr/>								
Structural Bearings Not Accessible	100%							
<hr/>								
Traffic Devices								
Barrier Gate	100%	Now	\$189,900	2028	\$474,600			
<i>Other Observation, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Barrier Gates</i>								
<i>Explanation : Some Latches Missing Or Not Functioning. Some Cracks On Gate Arm. Paint Required. One Bent Housing</i>								
Warning Gate	100%	Now	\$58,900	2028	\$294,400			
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Warning Gates</i>								
<i>Explanation : Some Broken/missing Hardware. Missing Covers On Open Holes. Painting Required</i>								
<hr/>								
Trunnion Generic	100%	Now	\$653,700	2040			**	
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Trunnions</i>								
<i>Explanation : Machinery Covered In Debris/ Corrosion. Reported That It Is Difficult To Grease. Missing Limit Switch Gear Bolt</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : W 207 ST / UNIVERSITY HEIGHTS BR
Address : W 207 ST/W FORDHAM ROAD
Borough : MANHATTAN:BX. **Agency's Number** : N/A
Program / Asset # : DOT0139.000 / 4243 **Yr Built/Renovated** :
Area Sq Ft : 19,700 **Project Type** : WATERWAY BRIDGES
Date of Survey : 04-May-2010 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240120

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$2,182,100	\$1,675,600
Bridge Electrical	\$2,828,300	\$69,800
Bridge Mechanical	\$160,100	\$734,800
Total	\$5,170,500	\$2,480,200
Importance Code A		\$155,000
Importance Code B	\$2,988,400	\$959,600
Importance Code C	\$2,182,100	\$1,365,600
Total	\$5,170,500	\$2,480,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$24,900	\$33,700	\$35,200	\$40,100
Bridge Electrical	\$116,500			
Bridge Mechanical	\$72,800	\$9,000		\$9,000
Total	\$214,200	\$42,700	\$35,200	\$49,100
Importance Code A	\$4,600		\$18,700	
Importance Code B	\$196,700	\$9,000	\$16,500	\$9,000
Importance Code C	\$12,900	\$33,700		\$40,100
Total	\$214,200	\$42,700	\$35,200	\$49,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 207 ST / UNIVERSITY HEIGHTS BR
Asset # : 4243

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals								
Masonry	100%			LIFE	**			
Backwall								
Masonry	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Steel	100%			LIFE	**			
Footings								
Not Accessible	100%							
Joint with Deck								
Generic	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Stem (breastwall)								
Masonry: Granite	100%			LIFE	**			
Wingwalls								
Footings								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE	**			
Feature Crossed								
Bank Protection								
Concrete	100%			LIFE	**			
Riprap	100%			LIFE	**			
Timber	100%			2029	\$1,687,300			
Mat (scour & erosion)								
Not Accessible	100%							
Pier Protection								
Timber	85%			LIFE	**			
Timber	15%	0-2	\$7,400	LIFE	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Pier 3</i>								
<i>Rotted, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Pier 3</i>								
<i>Split/Dry/Cracked, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Pier 3</i>								
Approaches								
Pavement								
Concrete	100%			2034	\$806,200	4	\$35,500	
Curbs								
Concrete w/ Steel Face	100%			LIFE	**			
Guide Railing								
Steel	95%			LIFE	**	2-8	\$5,800	
Steel	5%	0-2	\$300	LIFE	**	2-8	\$5,800	
<i>Damaged Railing, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Begin Right Approach</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 207 ST / UNIVERSITY HEIGHTS BR
Asset # : 4243

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Sidewalks								
Concrete	95%			LIFE		**		
Concrete	5%	4+	\$100	LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 20%</i>								
<i>Location : Underside Of Sidewalk. Overhang And At Top.</i>								
<i>Efflorescence, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Underside Of Sidewalk. Overhang.</i>								
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
Steel	100%			LIFE		**	2-8	
Pier,Columns								
Steel	100%			LIFE		**	2-8	\$28,500
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Pier 1</i>								
Stem,Solid Pier								
Concrete	100%			LIFE		**		
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2047		**		
Steel	100%			LIFE		**	2-8	\$65,200
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Pedestals								
Concrete	100%			LIFE		**		
Steel	100%			LIFE		**		
Deck Elements								
Curbs								
Concrete w/ Steel Face	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Spans 1, 2, And 5.</i>								
<i>Explanation : Spans 1, 2, And 5.</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Spans 2 And 3</i>								
<i>Explanation : Spans 2 And 3</i>								
Guide Railing								
Steel	95%			LIFE		**		
Steel	5%	4+	\$1,300	LIFE		**		
<i>Damaged Railing, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Span 4 Left Side</i>								
Mono Deck Surface								
Concrete	100%			2047		**	5	\$67,500

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 207 ST / UNIVERSITY HEIGHTS BR
Asset # : 4243

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Railings/Parapets								
Cast Iron	90%			LIFE	**			
Cast Iron	5%	4+	\$2,200	LIFE	**			
<i>Corrosion, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Right Pedestrian Railing Spans 1- 5.</i>								
Cast Iron	5%	Now	\$900	LIFE	**			
<i>Broken/Missing Elements, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Spans 2 And 5.</i>								
Sidewalks								
Concrete	100%			2029	\$360,900	5	\$6,000	
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Spans 1 And 5</i>								
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Spans 1 And 5.</i>								
Grating w/ Concrete	100%			2047	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Spans 3 And 4.</i>								
<i>Explanation : Spans 3 And 4.</i>								
Wearing Surface								
Asphalt	100%			2026	\$133,800	5	\$1,900	
Concrete	100%			2034	\$559,400	5	\$74,100	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 10%</i>								
<i>Location : Spans 3 And 4.</i>								
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$15,800	
Grating w/ Concrete	100%			LIFE	**			
Joints								
Steel	100%			LIFE	**			
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$289,500	
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Spans 1, 2 And 5</i>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$242,500	
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Spans 1, 2 And 5.</i>								
Movable Bridges								
Swing Span Truss								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Spans 3 And 4.</i>								
<i>Explanation : Localized Corrosion With Section Loss In Primary And Secondary Members.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 207 ST / UNIVERSITY HEIGHTS BR
Asset # : 4243

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Movable Bridges

Swing Span Pivot Pier
Concrete

100% LIFE * *
Other Observation, Extent : Light, Area Affected : 100%
Location : Pier 3
Explanation : Has Masonry Facade.

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Communication Electrical

Communications
Generic

100% Now \$12,300 2026 \$41,100
Other Observation, Extent : Light, Area Affected : 100%
Location : Entire System
Explanation : Not Functional.

Control System Electrical

Control Console
Stainless Steel

100% LIFE * *

Disconnect Switch

Generic

100% 2034 \$37,900

Limit Switch

Generic

100% 2034 \$69,800

Electrical Power

Dist Equip & Motor Controll
Generic

100% Now \$33,800 2026 \$675,600
Other Observation, Extent : Light, Area Affected : 50%
Location : Motors 1 And 3
Explanation : Motors 1 And 3 Not Operational.

Raceway

Collector Ring
Metal

100% 2-4 \$19,000 2029 \$95,000
Other Observation, Extent : Light, Area Affected : 20%
Location : Rim Bearing Lower Level
Explanation : Colletor Shoes Are Slightly Corroded

Submarine Control Cables

Control

100% 2026

Wiring

Generic

100% 2026 \$1,779,700

Traffic System Electrical

Traffic Signal
Generic

100% Now \$7,900 2026 \$158,500
Other Observation, Extent : Moderate, Area Affected : 100%
Location : All Gongs
Explanation : Gongs Are Not Operational.

Lighting

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
W 207 ST / UNIVERSITY HEIGHTS BR
Asset # : 4243

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Lighting

Lighting Devices

Generic

100% Now \$2,400 2026 \$119,500

Other Observation, Extent : Light, Area Affected : 50%

Location : Entire System.

Explanation : Several Lamps Missing Or Inoperative.

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Swing

Center Latch

Generic

100% Now \$76,400 2049 **

Other Observation, Extent : Moderate, Area Affected : 100%

Location : East Latch

Explanation : East Latch Is Not Driven. Latch Is Failed.

Center Pivot

Generic

100% 2049 **

Emergency Drive

Emergency Power

100% 2049 ** 2 \$44,900

Other Observation, Extent : Light, Area Affected : 100%

Location : Emergency Power

Explanation : No Operation Observed.

End Lift

Generic

100% 4+ \$83,700 2049 **

Other Observation, Extent : Moderate, Area Affected : 20%

Location : End Lift Machinery

Explanation : Machinery Exhibits Corrosion

Houses

Access Ways

90% 2049 **

Access Ways

10% Now \$5,100 2049 **

Other Observation, Extent : Light, Area Affected : 100%

Location : Hatch To Center Machinery

Explanation : Hatch Exhibits Moderate Corrosion

Machinery Room

100% 2049 **

Main Drive System

Generic

100% 4+ \$30,900 2049 **

Other Observation, Extent : Light, Area Affected : 10%

Location : Span Drive

Explanation : Accumulated Pigeon Debris On Secondary Reducer Machinery

Structural Bearings

Generic

100% 2030 \$13,600

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
W 207 ST / UNIVERSITY HEIGHTS BR
Asset # : 4243

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Swing								
Traffic Devices								
Barrier Gate	50%			2030	\$220,200			
Barrier Gate	50%	Now	\$22,000	2030	\$220,200			
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : East Approach</i>								
<i>Explanation : Gate Arms Needed To Be Manually Interlocked At Center</i>								
Warning Gate	50%	Now	\$14,700	2030	\$147,200			
<i>Other Observation, Extent : Severe, Area Affected : 40%</i>								
<i>Location : Southeast And Southwest</i>								
<i>Explanation : Gates Are Not Lowering Fully. Concrete Missing Around Edge Of Base.</i>								
Warning Gate	50%			2030	\$147,200			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WARDS ISLAND PEDESTRIAN BRIDGE OVER HARLEM RIVER
Address : FOOT OF E. 103 ST. TO SOUTH END OF RANDALLS ISLAND
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0188.000 / 13872 **Yr Built/Renovated** :
Area Sq Ft : 12,600 **Project Type** : WATERWAY BRIDGES
Date of Survey : 25-Apr-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240620

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure		\$124,700
Bridge Electrical	\$86,100	
Bridge Mechanical	\$1,408,800	
Total	\$1,494,900	\$124,700
Importance Code A		\$124,700
Importance Code B	\$1,494,900	
Total	\$1,494,900	\$124,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$28,200	\$1,500	\$13,000	
Bridge Mechanical	\$38,000			
Total	\$66,200	\$1,500	\$13,000	
Importance Code A		\$1,500	\$13,000	
Importance Code B	\$56,700			
Importance Code C	\$9,500			
Total	\$66,200	\$1,500	\$13,000	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WARDS ISLAND PEDESTRIAN BRIDGE OVER HARLEM RIVER
Asset # : 13872

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Abutments								
Bridge Seat&pedestals								
Concrete	100%			LIFE		**		
Joint with Deck								
Generic	100%			LIFE		**		
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Stem (breastwall)								
Concrete	100%	4+	\$18,700	LIFE		**		
			<i>Exposed Reinforcement, Extent : Light, Area Affected : 2%</i>					
			<i>Location : East Abutment</i>					
Steel	100%			LIFE		**		
Wingwalls								
Mat (scour & erosion)								
Earth	100%			LIFE		**		
Walls								
Concrete	100%			LIFE		**		
			<i>Vegetation Growth, Extent : Light, Area Affected : 1%</i>					
			<i>Location : Random Locations Throughout East Side</i>					
Feature Crossed								
Bank Protection								
Masonry	100%	4+	\$9,500	LIFE		**		
			<i>Cracks, Extent : Light, Area Affected : 1%</i>					
			<i>Location : East Side Of Bank</i>					
Pier Protection								
Timber	100%			LIFE		**		
			<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i>					
			<i>Location : South Pier 6</i>					
			<i>Other Observation, Extent : N/A, Area Affected : 25%</i>					
			<i>Location : North Pier 6</i>					
			<i>Explanation : Under Construction</i>					
Not Accessible	100%							
Approaches								
Pavement								
Asphalt	100%			2035			4	
Piers								
Cap Beam								
Concrete	100%			LIFE		**		
			<i>Other Observation, Extent : N/A, Area Affected : 1%</i>					
			<i>Location : Pier 8</i>					
			<i>Explanation : Concrete Capbeam.</i>					
Steel	100%			LIFE		**	2-8	
			<i>Other Observation, Extent : N/A, Area Affected : 1%</i>					
			<i>Location : Piers 1, 3, 4, And 6 Through 8.</i>					
			<i>Explanation : Steel Capbeam</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WARDS ISLAND PEDESTRIAN BRIDGE OVER HARLEM RIVER
Asset # : 13872

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Pier,Columns Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Pier 8</i>								
<i>Explanation : Concrete Columns.</i>								
Steel	100%			LIFE	**	2-8		
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Piers 1, 3 And 6 Through 8.</i>								
<i>Explanation : Steel Columns.</i>								
Stem,Solid Pier Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Piers 5 And 9.</i>								
<i>Explanation : Concrete Stem</i>								
Brngs,Ancr Blts,Pads Steel	100%			LIFE	**	2-8	\$5,300	
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Piers 1, 3 Through 8</i>								
<i>Explanation : Steel Bearings</i>								
Mat (scour & erosion) Not Accessible	100%							
Pedestals Concrete	100%			LIFE	**			
Steel	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets Concrete	100%			2043	**	4	\$4,500	
Steel	100%			LIFE	**	2-8	\$8,200	
<i>Other Observation, Extent : N/A, Area Affected : 1%</i>								
<i>Location : Spans 1 Through 9.</i>								
<i>Explanation : Steel Rail And Fencing.</i>								
Wearing Surface Concrete	100%			2043	**	5		
Superstructure								
Deck,Structural Concrete	100%			LIFE	**	5	\$7,400	
Joints								
Steel	100%			LIFE	**			
<i>Corrosion, Extent : Light, Area Affected : 1%</i>								
<i>Location : All Spans</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WARDS ISLAND PEDESTRIAN BRIDGE OVER HARLEM RIVER
Asset # : 13872

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Superstructure								
Primary Member								
Steel	100%			LIFE	**	2-8	\$232,900	
<i>Cracks, Extent : Light, Area Affected : 1%</i> <i>Location : Spans 1-5 Concrete Within Girders.</i> <i>Corrosion, Extent : Light, Area Affected : 1%</i> <i>Location : Scattered Locations To Spans 1-8 Girders.</i> <i>Delaminations, Extent : Light, Area Affected : 1%</i> <i>Location : Span 5, Girder 1, At Pier 5.</i>								
Movable Bridges								
Vertical Lift Span								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : Girders And Floor beams.</i> <i>Explanation : Minor Corrosion, Rust Staining And Painted Over Pitting.</i>								
Vertical Lift Tower								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 1%</i> <i>Location : Steel Towers</i> <i>Explanation : Minor Corrosion, Rust Staining And Painted Over Pitting.</i>								
Vertical Lift Pier								
Concrete	100%			LIFE	**			
Bridge Electrical								
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Communication Electrical								
Communications								
Not Accessible	100%							
Control System Electrical								
Control Console								
Metal	100%	Now	\$86,100	2051	**			
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i> <i>Location : Bridge Controls</i> <i>Explanation : East Seating Problematic. Requires Adjustment. Some Pilot Lights Are Out.</i>								
Disconnect Switch								
Not Accessible	100%							
Limit Switch								
Generic	100%			2051	**			
Electrical Power								
Dist Equip & Motor Controll								
Not Accessible	100%							
Raceway								
Submarine Power Cable								
Not Accessible	100%							
Wiring								
Generic	100%			2038	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WARDS ISLAND PEDESTRIAN BRIDGE OVER HARLEM RIVER
Asset # : 13872

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Lighting

Lighting Devices

Generic

100%

2038

* *

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Vertical Lift

Counter Weight Ropes & Gui

Generic

20%

Now

\$235,200

2037

* *

*Other Observation, Extent : Moderate, Area Affected : 5%**Location : Observed From Span And West Lower Level**Explanation : Some Splay Shims Missing. One Cap Nut And Keeper Bolt Missing. Some Minor Corrosion And Paint Failure.*

Generic

80%

2037

* *

*Other Observation, Extent : Light, Area Affected : 10%**Location : Counter Weight Ropes And Guides**Explanation : Only Observed From Span Level.*

Counter Weight

Main CTRWT

100%

2062

* *

*Other Observation, Extent : Light, Area Affected : 10%**Location : Counter Weights**Explanation : Only Observed From Span Level.*

Houses

Access Ways

100%

Now

\$60,100

2037

* *

*Other Observation, Extent : Severe, Area Affected : 90%**Location : Accessways**Explanation : Most Of The Accessways Were Not Accessible For Observations. Need To Establish Acceptable Method Of Access.*

Control House

100%

Now

\$162,000

2049

* *

*Other Observation, Extent : Severe, Area Affected : 20%**Location : Assistant Bridge Operator House**Explanation : Door To Assistant Bridge Operator House Does Not Work. No Access Or Observations Made.*

Main Drive System

Generic

100%

Now

\$334,000

2049

* *

*Other Observation, Extent : Severe, Area Affected : 100%**Location : Machinery Rooms**Explanation : No Access To Tower. Operation Of Span Is Problematic And Needs Maintenance And Repair.*

Sheaves

Generic

100%

Now

\$617,500

2037

* *

*Other Observation, Extent : Severe, Area Affected : 100%**Location : Machinery Rooms And Towers**Explanation : No Access To Tower. Sheaves Need Maintenance.*

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
WARDS ISLAND PEDESTRIAN BRIDGE OVER HARLEM RIVER**

Asset # : 13872

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Vertical Lift

Traffic Devices

Barrier Gate

100% Now \$38,000 2037 * *

Other Observation, Extent : Severe, Area Affected : 5%

Location : Barrier Gates

Explanation : Gate Latches Do Not Fully Engage When Closed. Gates Do Not Lock In The Open Position. Repairs Required.

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WASHINGTON BRIDGE WASHINGTON BRIDGE/HARLEM RIVER
Address : W. 181ST,X-ING HARLEM RIVER
Borough : MANHATTAN:BX. **Agency's Number** : N/A
Program / Asset # : DOT0006.090 / 2441 **Yr Built/Renovated** : 1888 /
Area Sq Ft : 133,600 **Project Type** : WATERWAY BRIDGES
Date of Survey : 04-Mar-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2066919

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$1,056,600	\$4,392,000
Total	\$1,056,600	\$4,392,000
Importance Code A	\$529,700	\$88,600
Importance Code C	\$527,000	\$4,303,400
Total	\$1,056,600	\$4,392,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$152,000		\$1,700	
Total	\$152,000		\$1,700	
Importance Code A	\$36,300		\$1,700	
Importance Code C	\$115,700			
Total	\$152,000		\$1,700	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WASHINGTON BRIDGE WASHINGTON BRIDGE/HARLEM RIVER
Asset # : 2441

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Stem (breastwall)								
Granite	100%			LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Leakage, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Stem. Bridge Component And Defects Identified From Biennial.</i>								
Wingwalls								
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Not Accessible	100%							
Piles								
Not Accessible	100%							
Walls								
Granite	100%			LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Leakage, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Wingwall. Bridge Component And Defects Identified From Biennial.</i>								
Feature Crossed								
Bank Protection								
Masonry	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Bank Protection. Bridge Component Identified From The Biennial.</i>								
Riprap	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Bank Protection. Bridge Component Identified From The Biennial.</i>								
Mat (scour & erosion)								
Generic	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Mat (Scour & Erosion). Bridge Component Identified From The Biennial.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WASHINGTON BRIDGE WASHINGTON BRIDGE/HARLEM RIVER
Asset # : 2441

Bridge Structure	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Approaches								
Pavement								
Asphalt	100%	4+	\$32,100	2034	\$1,603,300	4	\$18,100	
<i>Cracks, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Embankment								
Not Accessible	100%							
Guide Railing								
Concrete	100%	4+	\$13,500	2042	**	4	\$4,600	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 5%</i>								
<i>Location : Throughout</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Median								
Concrete	100%	4+	\$5,900	LIFE	**	5	\$900	
<i>Cracks, Extent : Light, Area Affected : 30%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Pavement Base								
Not Accessible	100%							
Railings/Parapets								
Steel	100%			LIFE	**			
<i>Rust Stains, Extent : Light, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks								
Concrete	100%	4+	\$5,200	LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
Piers								
Cap Beam								
Masonry	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Substructure. Bridge Components Identified From Biennial.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WASHINGTON BRIDGE WASHINGTON BRIDGE/HARLEM RIVER
Asset # : 2441

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Granite	100%			LIFE		**		
<i>Efflorescence, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Leakage, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Vegetation Growth, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Substructure. Bridge Components And Defects Identified From Biennial.</i>								
Brngs,Ancr Blts,Pads Not Accessible	100%							
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Substructure. Bridge Components Identified From Biennial.</i>								
Pedestals Not Accessible	100%							
Piles Not Accessible	100%							
Deck Elements								
Guide Railing Concrete	100%	4+	\$200,300	2046		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								
Median Concrete	100%	4+	\$124,700	LIFE		**	5	\$9,500
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
Railings/Parapets Masonry	100%	4+	\$204,700	2042		**	5	\$11,800
<i>Spalling, Extent : Light, Area Affected : 15%</i>								
<i>Location : Random Locations Throughout</i>								
Steel	100%	4+	\$16,900	LIFE		**	2-8	\$46,700
<i>Corrosion, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Random Locations Throughout</i>								
Sidewalks Concrete	100%	4+	\$33,900	2038		**	5	\$5,200
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Random Locations Throughout</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WASHINGTON BRIDGE WASHINGTON BRIDGE/HARLEM RIVER
Asset # : 2441

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Wearing Surface Asphalt	100%	4+	\$44,500	2034	\$2,224,800	5	\$52,000	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Explanation : Rutting</i>								
Concrete	100%	0-2	\$348,300	2042	**	5	\$423,300	
<i>Spalling, Extent : Moderate, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Limited Access To Scuppers. Total Of 80 Scuppers</i>								
Superstructure								
Deck,Structural Concrete	100%			LIFE	**	5	\$88,600	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : No Access To Superstructure. Bridge Component Identified From Biennial.</i>								
Joints								
Steel	100%	0-2	\$178,700	LIFE	**			
<i>Broken/Missing Elements, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Loose Joint Plates, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Span 5 Westbound</i>								
Primary Member								
Not Accessible	100%							
Secondary Member								
Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WILLIS AVE. BRIDGE MOVABLE SPAN WILLIS AVE/HARLEM RIVER
Address : HARLEM RIVER, WILLIS AVE.
Borough : MANHATTAN:BX. **Agency's Number** : N/A
Program / Asset # : DOT0040.090 / 4239 **Yr Built/Renovated** : 2008 /
Area Sq Ft : 89,289 **Project Type** : WATERWAY BRIDGES
Date of Survey : 05-Apr-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 2240059

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$180,500	\$2,248,900
Bridge Electrical	\$107,300	\$87,300
Bridge Mechanical	\$414,100	
Total	\$701,800	\$2,336,100
Importance Code A		\$1,184,600
Importance Code B	\$521,300	\$971,000
Importance Code C	\$180,500	\$180,500
Total	\$701,800	\$2,336,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$38,400	\$41,900	\$190,300	
Bridge Electrical	\$56,400			
Bridge Mechanical	\$317,900	\$9,000	\$86,200	\$9,000
Total	\$412,700	\$50,800	\$276,500	\$9,000
Importance Code A		\$15,000	\$101,700	
Importance Code B	\$374,200	\$9,000	\$174,800	\$9,000
Importance Code C	\$38,400	\$26,800		
Total	\$412,700	\$50,800	\$276,500	\$9,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WILLIS AVE. BRIDGE MOVABLE SPAN WILLIS AVE/HARLEM RIVER
Asset # : 4239

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE	**			
Backwall Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads Elastomeric	100%			2060	**			
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE	**			
Mat (scour & erosion) Concrete	100%			LIFE	**			
Stem (breastwall) Concrete	100%			LIFE	**			
Granite	100%			LIFE	**			
<i>Efflorescence, Extent : Light, Area Affected : 1% Location : Random Locations Throughout</i>								
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Not Accessible	100%							
Piles Not Accessible	100%							
Walls Concrete	100%			LIFE	**			
Granite	100%			LIFE	**			
Feature Crossed								
Bank Protection Concrete	100%			LIFE	**			
Riprap	100%			LIFE	**			
Mat (scour & erosion) Not Accessible	100%							
Pier Protection Concrete	100%			LIFE	**			
Approaches								
Pavement Concrete	100%			2047	**	4	\$80,500	
Curbs Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100% Location : Both Approaches. Explanation : Curbs Are Incorporated Into The Barrier.</i>								
Embankment Not Accessible	100%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WILLIS AVE. BRIDGE MOVABLE SPAN WILLIS AVE/HARLEM RIVER
Asset # : 4239

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Approaches								
Guide Railing Concrete	100%			2047	**	4	\$19,700	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Approaches.</i>								
<i>Explanation : Guide Railing Is Located On Both Sides Of The Roadway.</i>								
Steel	100%			LIFE	**	2-8	\$13,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Approaches.</i>								
<i>Explanation : Guide Railing Is Located On Both Sides Of The Roadway.</i>								
Mat (scour & erosion)								
Not Accessible	100%							
Railings/Parapets								
Concrete	100%			2047	**	4		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Approaches.</i>								
<i>Explanation : Pedestrian Railing Along North Side.</i>								
Steel	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Approaches.</i>								
<i>Explanation : Pedestrian Railing Along North Side.</i>								
Sidewalks								
Concrete	100%			LIFE	**			
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Approaches.</i>								
<i>Explanation : Sidewalk On North Side Only.</i>								
Piers								
Cap Beam Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 1 - 5, 7 - 12.</i>								
<i>Explanation : Concrete Capbeams</i>								
Steel	100%			LIFE	**	2-8	\$261,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 6, 13, 14.</i>								
<i>Explanation : Steel Capbeams</i>								
Pier,Columns								
Concrete	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 2, 3, 12 - 14.</i>								
<i>Explanation : Concrete Pier Columns.</i>								
Granite	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 1, 4 - 12.</i>								
<i>Explanation : Granite Pier Columns.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WILLIS AVE. BRIDGE MOVABLE SPAN WILLIS AVE/HARLEM RIVER
Asset # : 4239

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Piers								
Stem,Solid Pier Granite	100%			LIFE		**		
<i>Joints Missing, Extent : Light, Area Affected : 1%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Pier 6</i>								
<i>Explanation : Granite Solid Stem.</i>								
Brngs,Ancr Blts,Pads Generic	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 10%</i>								
<i>Location : Span 6 Center Pier, Center Bearing Pad</i>								
Footings Not Accessible	100%							
Mat (scour & erosion) Earth	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 9 - 13.</i>								
<i>Explanation : Earth Mat.</i>								
Pedestals Concrete	100%			LIFE		**		
<i>Cracks, Extent : Light, Area Affected : 1%</i>								
<i>Location : Spans 5 And 7</i>								
Deck Elements								
Curbs Concrete	100%			2060		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 - 15.</i>								
<i>Explanation : Curb Is Integral With Traffic Barrier.</i>								
Guide Railing Concrete	100%			2051		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 - 15.</i>								
<i>Explanation : Guide Railing Is Located On Both Sides Of The Roadway.</i>								
Steel	100%			LIFE		**		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1-15</i>								
<i>Explanation : Guide Railing Is Located On Both Sides Of The Roadway.</i>								
Railings/Parapets Concrete	100%			2047	**	4	\$25,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 - 15.</i>								
<i>Explanation : Pedestrian Railing Along North Side Only.</i>								
Steel	100%			LIFE	**	2-8	\$38,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 - 15.</i>								
<i>Explanation : Pedestrian Railing On North Side Only.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WILLIS AVE. BRIDGE MOVABLE SPAN WILLIS AVE/HARLEM RIVER
Asset # : 4239

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Deck Elements								
Sidewalks								
Concrete	100%	4+	\$38,400	2042	**	5	\$16,000	
<i>Cracks, Extent : Light, Area Affected : 5%</i>								
<i>Location : Spans 8 - 11.</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 - 15.</i>								
<i>Explanation : Sidewalk On North Side Only.</i>								
<hr/>								
Wearing Surface								
Concrete	100%			2047	**	5	\$361,000	
<i>Cracks, Extent : Light, Area Affected : 2%</i>								
<i>Location : Random Locations Throughout</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Span 6, Left Lane</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 - 5, And 8 - 15.</i>								
<i>Explanation : Concrete Wearing Surface.</i>								
Steel Grating	100%			LIFE	**	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 6 And 7.</i>								
<i>Explanation : Steel Grating Wearing Surface</i>								
<hr/>								
Scupper								
Cast Iron	100%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Twenty Four Scuppers Total</i>								
<hr/>								
Superstructure								
Deck, Structural								
Concrete	100%			LIFE	**	5	\$121,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 1 - 5, And 8 - 15.</i>								
<i>Explanation : Concrete Deck.</i>								
Steel Grating	100%			LIFE	**	5	\$66,400	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Spans 6 And 7.</i>								
<i>Explanation : Steel Grating In Swing Spans</i>								
<hr/>								
Joints								
Generic	100%			LIFE	**			
<i>Leakage, Extent : Light, Area Affected : 50%</i>								
<i>Location : Piers 2, 4, 5, 7, 8, 10, 11, 13, And 14</i>								
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Piers 2, 4, 5, 7, 8, 10, 11, 13, And 14</i>								
<i>Explanation : Joints.</i>								
<hr/>								
Primary Member								
Steel	100%			LIFE	**	2-8	\$1,650,700	
<hr/>								
Secondary Member								
Steel	100%			LIFE	**	2-8	\$1,382,800	

Movable Bridges

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WILLIS AVE. BRIDGE MOVABLE SPAN WILLIS AVE/HARLEM RIVER
Asset # : 4239

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Movable Bridges

Swing Span Truss

Steel

100%

LIFE

* *

Swing Span Pivot Pier

Concrete

100%

LIFE

* *

Bridge Electrical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Communication Electrical

Communications

Generic

100%

Now

\$8,700

2034

\$87,300

*Other Observation, Extent : Light, Area Affected : 100%**Location : East Pier**Explanation : Intercom Severely Damaged*

Control System Electrical

Control Console

Stainless Steel

100%

Now

\$107,300

LIFE

* *

*Other Observation, Extent : Light, Area Affected : 100%**Location : Operator Room**Explanation : Position Indicator Was Pulsating And The Fault Light Was Illuminated; After Transformer Fire, PLC Lost Program And Has Not Operated The Same.*

Disconnect Switch

Generic

100%

2051

* *

Limit Switch

Generic

100%

2051

* *

Electrical Power

Transformer

Dry

100%

2051

* *

Dist Equip & Motor Controll

Generic

100%

2051

* *

Raceway

Submarine Control Cables

Generic

100%

2038

* *

Wiring

Generic

100%

2038

* *

Lighting

Lighting Devices

Generic

100%

Now

\$47,600

2038

* *

*Other Observation, Extent : Light, Area Affected : 100%**Location : Abo House And Rest Piers**Explanation : Lights In The Abo House Not Operational. Lights At The Rest Piers Not Operational.*

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WILLIS AVE. BRIDGE MOVABLE SPAN WILLIS AVE/HARLEM RIVER
Asset # : 4239

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Swing								
Center Latch Generic	100%	Now	\$39,400	2069	**	2	\$18,000	
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Centering Locks</i>								
<i>Explanation : Some Corrosion, Missing Covers, Minor Leakage And Adjustments May Be Necessary</i>								
Center Lift Generic	100%	Now	\$47,600	2069	**	2	\$21,600	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Center Lift</i>								
<i>Explanation : Minor Leakage, Loose Covers, Breathers May Be Becoming Saturated. Some Adjustments Repairs Required.</i>								
Center Pivot Generic	100%	Now	\$129,600	2069	**	2	\$53,900	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Center Pivot</i>								
<i>Explanation : Minor Leakage And Breather May Be Getting Close To Saturated. Some Cracks In Grout.</i>								
Emergency Drive Emergency Power	100%	Now	\$9,800	2069	**	2	\$35,900	
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : Emergency Drive Hydraulic Power Unit</i>								
<i>Explanation : Small Crack In Engine Belt Cover. Exhaust May Need To Be Sealed. Minor Leakage.</i>								
End Lift Generic	2%	Now	\$53,600	2069	**	2	\$35,900	
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : End Lifts</i>								
<i>Explanation : Minor Leakage, Corrosion, Some Missing Cover Bolts. Adjustments Required. Brakes May Need Adjustment.</i>								
Generic	98%			2069	**	2	\$44,900	
Fuel Tanks Generic	100%			2051	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WILLIS AVE. BRIDGE MOVABLE SPAN WILLIS AVE/HARLEM RIVER
Asset # : 4239

Bridge Mechanical		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Swing Houses								
Access Ways	100%	Now	\$36,900	2069		**		
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Machinery Access Hatch</i>								
<i>Explanation : Hatch Does Not Fully Seat</i>								
Control House	100%	Now	\$42,500	2069		**		
<i>Other Observation, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Control House And Assistant Bridge Operator House</i>								
<i>Explanation : Control Room Door Knob Broken. Water In Assistant House Does Not Get Hot. Alarm Needs To Be Repaired.</i>								
HVAC	100%	Now	\$15,400	2069		**		
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Control House</i>								
<i>Explanation : Air Conditioner Requires Repair.</i>								
Machinery Room	100%	Now	\$24,700	2069		**		
<i>Other Observation, Extent : Light, Area Affected : 1%</i>								
<i>Location : Machinery Room</i>								
<i>Explanation : May Have Minor Leakage In Ceiling Of Machinery Room.</i>								
Main Drive System								
Generic	100%	Now	\$230,800	2069		**	2	\$179,600
<i>Other Observation, Extent : Moderate, Area Affected : 2%</i>								
<i>Location : Operating Machinery</i>								
<i>Explanation : Minor Maintenance And Paint Repair Required. Not Running On Electrical Drive. Some Missing Cover Bolts. Hard To Read Oil Levels.</i>								
Rack								
Generic	100%	Now	\$37,500	LIFE		**		
<i>Corrosion, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Rack</i>								
Traffic Devices								
Barrier Gate	100%	Now	\$22,900	2047		**		
<i>Other Observation, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Barrier Gates, Observed From North Sidewalk Only</i>								
<i>Explanation : Some Guy Wire Need Repair And Or Adjustment; 2 Southeast And 2 Northeast Gate Arm Lights Out</i>								
Warning Gate	100%	Now	\$41,100	2047		**		
<i>Other Observation, Extent : Severe, Area Affected : 1%</i>								
<i>Location : Warning Gates, Observed From North Sidewalk Only</i>								
<i>Explanation : Some Adjustments And Repairs Required.</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WILLIS AVE. BRIDGE RAMP TO BRUCKNER BLVD.
Address : E 125TH STREET OVER HARLEM RIVER TO BRUCKNER BLVD
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0040.0B0 / 14727 **Yr Built/Renovated** :
Area Sq Ft : 18,778 **Project Type** : WATERWAY BRIDGES
Date of Survey : 19-Dec-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** : 224005B

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bridge Structure	\$347,900	\$347,900
Total	\$347,900	\$347,900
Importance Code A	\$231,100	\$231,100
Importance Code B	\$116,800	\$116,800
Total	\$347,900	\$347,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bridge Structure	\$129,100		\$60,200	\$5,900
Total	\$129,100		\$60,200	\$5,900
Importance Code A	\$107,900		\$34,500	
Importance Code B	\$21,300		\$11,700	
Importance Code C			\$14,000	\$5,900
Total	\$129,100		\$60,200	\$5,900



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WILLIS AVE. BRIDGE RAMP TO BRUCKNER BLVD.

Asset # : 14727

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Abutments								
Bridge Seat&pedestals Concrete	100%			LIFE	**			
Backwall Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads Elastomeric	100%			2055	**			
Footings Not Accessible	100%							
Joint with Deck Generic	100%			LIFE	**			
Mat (scour & erosion) Generic	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : In Front Of Stem Breast Wall</i>						
		<i>Explanation : A Drainage Structure</i>						
Pedestals Concrete	100%			LIFE	**			
Stem (breastwall) Concrete	100%			LIFE	**			
Walls Concrete	100%			LIFE	**			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout, Parallel To The Framing</i>						
		<i>Explanation : Masonry: Schist/ Gneiss</i>						
Wingwalls								
Footings Not Accessible	100%							
Mat (scour & erosion) Generic	100%			LIFE	**			
Piles Not Accessible	100%							
Walls Masonry: Schist/Gneiss	100%			LIFE	**			
Feature Crossed								
Mat (scour & erosion) Generic	100%			LIFE	**			
Approaches								
Pavement Concrete	100%			2044	**	4	\$28,000	
Mat (scour & erosion) Earth	100%			LIFE	**			
Pavement Base Not Accessible	100%							
Railings/Parapets Concrete	100%			2044	**	4	\$7,500	
Piers								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WILLIS AVE. BRIDGE RAMP TO BRUCKNER BLVD.

Asset # : 14727

Bridge Structure		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Piers								
Cap Beam								
Concrete	100%			LIFE	**			
Steel	100%			LIFE	**	2-8	\$140,900	
Pier,Columns								
Concrete	100%			LIFE	**			
Stem,Solid Pier								
Concrete	100%			LIFE	**			
Brngs,Ancr Blts,Pads								
Elastomeric	100%			2055	**			
Footings								
Not Accessible	100%							
Mat (scour & erosion)								
Earth	100%			LIFE	**			
Pedestals								
Concrete	100%			LIFE	**			
Piles								
Not Accessible	100%							
Deck Elements								
Railings/Parapets								
Concrete	100%			2044	**	4	\$15,200	
Wearing Surface								
Concrete	100%			2044	**	5	\$11,700	
Scupper								
Cast Iron	100%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Random Locations Throughout</i>					
			<i>Explanation : 3 Scuppers</i>					
Superstructure								
Deck,Structural								
Concrete	100%			LIFE	**	5	\$45,400	
			<i>Other Observation, Extent : N/A, Area Affected : 2%</i>					
			<i>Location : Random Locations Throughout Stay In Place Form</i>					
			<i>Explanation : Corrosion</i>					
Joints								
Generic	100%			LIFE	**			
Primary Member								
Steel	100%			LIFE	**	2-8	\$623,200	
Secondary Member								
Steel	100%			LIFE	**	2-8	\$320,800	

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : COAL DOCK -TIMBER PILE SUPPORTED CONCRETE PIER
Address : HART ISLAND
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0128.018 / 1790 **Yr Built/Renovated** :
Area Sq Ft : 7,760 **Project Type** : FERRIES
Date of Survey : 08-Dec-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 5649 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Piers	\$1,150,500	
Total	\$1,150,500	
Importance Code A	\$421,200	
Importance Code B	\$729,400	
Total	\$1,150,500	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers	\$2,400		\$31,400	
Total	\$2,400		\$31,400	
Importance Code A				
Importance Code B	\$2,400		\$31,400	
Total	\$2,400		\$31,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
COAL DOCK -TIMBER PILE SUPPORTED CONCRETE PIER

Asset # : 1790

Piers		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Structural Deck								
	Concrete	25%			LIFE	**	5	\$3,600
		<i>Cracking, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Isolated Locations</i>						
		<i>Spalling, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Isolated Locations</i>						
	Concrete	15%	4+	\$50,100	LIFE	**	5	\$2,200
		<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 50%</i>						
		<i>Location : At Construction Joints On North Side Of Pier And Approach</i>						
	Concrete	20%	0-2	\$89,100	LIFE	**	5	\$2,900
		<i>Spalling, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : At Loading Ramp And At Northwest Corner</i>						
	Not Accessible	40%						
Pile Caps								
	Timber	15%			LIFE	**	4	\$9,100
		<i>Rotting/Splitting, Extent : Light, Area Affected : 30%</i>						
		<i>Location : Isolated Locations</i>						
	Not Accessible	85%						
Piles and Bracing								
	Timber	30%	4+	\$282,000	LIFE	**	4-5	\$10,400
		<i>Rotting/Splitting, Extent : Moderate, Area Affected : 60%</i>						
		<i>Location : Approach And Pier Head</i>						
	Timber	10%			LIFE	**	4-5	\$3,500
		<i>Rotting/Splitting, Extent : Light, Area Affected : 40%</i>						
		<i>Location : Isolated Locations</i>						
	Not Accessible	60%						
Fender								
Wales and Chocks								
	Timber	55%	Now	\$228,800	2049	**	4	\$16,400
		<i>Missing Part, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Isolated Locations</i>						
	No Component	45%						
Piles								
	Timber	55%	Now	\$362,500	2049	**	4	\$7,600
		<i>Missing Part, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Offshore End</i>						
		<i>Rotting/Splitting, Extent : Severe, Area Affected : 75%</i>						
		<i>Location : At North Ends Of Approach And Pier Head</i>						
	No Component	45%						
Pile Cluster								
	Timber	30%			2038	**	4-10	\$38,500
	Timber	20%	2-4	\$83,700	2039	**	4	\$3,100
		<i>Rotting/Splitting, Extent : Moderate, Area Affected : 50%</i>						
		<i>Location : Both 3-pile Clusters Inshore Of Pier Head</i>						
	Not Accessible	50%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
COAL DOCK -TIMBER PILE SUPPORTED CONCRETE PIER**

Asset # : 1790

Piers		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Coping/Curb								
Timber	7%	Now	\$11,800	LIFE		* *		
	<i>Missing Part, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : Two Sections Totaling 35 Feet</i>							
Timber	63%	4+	\$42,600	LIFE		* *		
	<i>Rotting/Splitting, Extent : Moderate, Area Affected : 50%</i>							
	<i>Location : At Approach And Offshore Pier Head. Isolated Lengths Of Curb With Section Loss.</i>							
Timber	22%			LIFE		* *		
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Along Offshore Side Of Pier</i>							
	<i>Explanation : Recent Replace Evident</i>							
No Component	8%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 34TH STREET FERRY PIER
Address : E 35TH TO E 36TH STS EAST RIVER
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0199.020 / 14638 **Yr Built/Renovated** :
Area Sq Ft : 6,446 **Project Type** : FERRIES
Date of Survey : 21-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : 967 **Lot** : 50 **BIN** :

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers	\$62,300			\$6,600
Total	\$62,300			\$6,600
Importance Code A	\$58,400			
Importance Code B				\$6,600
Importance Code C	\$3,900			
Total	\$62,300			\$6,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
EAST 34TH STREET FERRY PIER
Asset # : 14638

Piers		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Deck								
Concrete	50%			LIFE	**	5	\$6,000	
Not Accessible	50%							
Deck Surface								
Asphalt Pavers	60%			2045	**			
Timber	30%			2041	**	5	\$7,800	
Not Accessible	10%							
Pile Caps								
Concrete	99%			LIFE	**	5	\$400	
Concrete	1%	4+	\$1,900	LIFE	**	5		
<i>Spalling, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : East Face Of Bent 1 And Bent 2 At West End Of Pier</i>								
Piles and Bracing								
Steel	5%	4+	\$43,400	LIFE	**	5	\$5,000	
<i>Corrosion, Extent : Light, Area Affected : 50%</i>								
<i>Location : In Tidal Zone On All H-piles</i>								
Steel	10%			LIFE	**	5	\$9,900	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : All Piles On North Section Of Pier Have Epoxy Encasements</i>								
<i>Explanation : Epoxy Encasements</i>								
Not Accessible	85%							
Fender								
Wales and Chocks								
Timber	60%			2041	**	4	\$12,300	
No Component	40%							
Piles								
Timber	10%			2041	**	4	\$900	
No Component	40%							
Not Accessible	50%							
Pile Cluster								
Timber	30%			2033		4-10		
<i>Loose Wrapping, Extent : Light, Area Affected : 10%</i>								
<i>Location : One Cluster On North Side</i>								
Not Accessible	70%							
Deck Elements								
Railing								
Steel	70%			2030				
No Component	30%							
Electrical								
Conduit								
Steel	100%			2030				
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Various Steel Conduits Along Pier Perimeter Totaling Approximately 1,950 Linear Feet In Length</i>								
<i>Explanation : Location</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 34TH STREET FERRY PIER
Asset # : 14638

Piers	Current Repair			Future Replacement		Maintenance		
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Electrical								
Lighting Fixture								
LED	70%			2030	\$30,500			
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Seven Light Poles On The Pier</i>							
	<i>Explanation : Light Poles</i>							
LED	30%	Now	\$13,100	2032	\$13,100			
	<i>Broken, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Three Sets Of Lights In Pier Canopy</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FERRY MAINTENANCE FACILITY PIER B1
Address : FORMER U. S. C. G. BASE NORTH SIDE OF MAINT BLDG
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0144.000 / 4521 **Yr Built/Renovated** :
Area Sq Ft : 24,350 **Project Type** : FERRIES
Date of Survey : 10-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : 1 **Lot** : 70 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Piers	\$276,600	\$1,965,800
Total	\$276,600	\$1,965,800
Importance Code A	\$52,400	
Importance Code B	\$224,100	\$1,965,800
Total	\$276,600	\$1,965,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers	\$117,400	\$29,200		\$53,600
Total	\$117,400	\$29,200		\$53,600
Importance Code A	\$56,200			\$49,800
Importance Code B	\$61,200	\$29,200		\$3,800
Total	\$117,400	\$29,200		\$53,600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FERRY MAINTENANCE FACILITY PIER B1
Asset # : 4521

Piers		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Deck								
Concrete	3%	4+	\$52,400	LIFE	**	5	\$1,400	
<i>Cracking, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Center Of Pier, 150 Feet From East End</i>								
<i>Spalling, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : South Side Of Expansion Joint 270 Feet From West End, And Center Of Offshore Section Of Pier</i>								
Concrete	72%			LIFE	**	5	\$32,700	
Not Accessible	25%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Inshore Half Of The Pier And Offshore 60 Feet</i>								
<i>Explanation : Steel Stay-in-place Formwork</i>								
Firewalls								
Concrete	70%			LIFE	**	5	\$1,900	
Not Accessible	30%							
Pile Caps								
Timber	96%			LIFE	**	4	\$183,700	
Timber	2%	2-4	\$24,700	LIFE	**	4	\$3,800	
<i>Rotting/Splitting, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Ends Of Offshore Pile Caps</i>								
Timber	2%			LIFE	**	4	\$3,800	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 50%</i>								
<i>Location : Sister Caps And Line Caps Installed At Pile Cap Ends At Offshore End Of Pier</i>								
Piles and Bracing								
Timber	2%	Now	\$29,500	LIFE	**	4-5	\$2,200	
<i>Broken, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Isolated Locations Primarily Within Offshore 220 Feet Of Pier</i>								
Timber	28%			LIFE	**	4-5	\$30,500	
Not Accessible	70%							
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 20 Percent With Encasements</i>								
Fender								
Buffer								
Rubber	100%			2041	**	4-5	\$26,800	
Wales and Chocks								
Timber	90%			2035	\$1,161,800	4	\$75,000	
Timber	10%	4+	\$25,800	2035	\$129,100	4	\$5,600	
<i>Loose Connections, Extent : Severe, Area Affected : 2%</i>								
<i>Location : Steel Connecting Hardware Between The Pier Deck And Fender System</i>								
<i>Rotting/Splitting, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Low Water Wale</i>								
<i>Worn, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Low Water Wale</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FERRY MAINTENANCE FACILITY PIER B1
Asset # : 4521

Piers		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Fender								
Piles								
Timber	2%	Now	\$16,400	2047	**	4	\$500	
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Isolated Piles Along Entire Fender System</i>								
Timber	33%			2035	\$674,900	4	\$12,700	
Not Accessible	65%							
Pile Cluster								
Timber	75%	Now	\$224,100	2037	**	4	\$8,400	
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Broken Piles In Tidal Zone</i>								
<i>Loose Wrapping, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : At Northwest End</i>								
Not Accessible	25%							
Deck Elements								
Coping/Curb								
Concrete	2%			LIFE	**			
<i>Spalling, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Northwest Corner Of Curb</i>								
Timber	93%			LIFE	**			
Timber	5%	Now	\$9,400	LIFE	**			
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Isolated Along Entire Curb</i>								
<i>Rotting/Splitting, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Isolated Along Entire Curb</i>								
Electrical								
Conduit								
Steel	30%	4+	\$2,000	2031	\$39,200			
<i>Broken, Extent : N/A, Area Affected : 15%</i>								
<i>Location : Splits In Conduit Couplers Leading To Junction Box Affecting 30 Feet, 230 Feet From West End</i>								
PVC	70%			2029	\$49,800			
<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Conduit For Light Fixtures Along Southern Side Of Pier</i>								
Lighting Fixture								
LED	100%			2031				
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 9 Light Fixtures</i>								
<i>Explanation : Other</i>								
Mechanical/ Plumbing								
Water Supply								
Galvanized Steel	100%			2030				
<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Fire Water Line Repainted Along Entire Length</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FERRY MAINTENANCE FACILITY PIER B2
Address : FORMER U. S. C. G. BASE LARGEST PIER INFRONT MAINT BLDG
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0145.000 / 4522 **Yr Built/Renovated** :
Area Sq Ft : 61,238 **Project Type** : FERRIES
Date of Survey : 10-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : 1 **Lot** : 70 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Piers	\$397,200	\$2,003,700
Total	\$397,200	\$2,003,700
Importance Code A	\$193,700	\$85,600
Importance Code B	\$203,500	\$1,918,100
Total	\$397,200	\$2,003,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers	\$37,300	\$26,100		\$6,400
Total	\$37,300	\$26,100		\$6,400
Importance Code A				
Importance Code B	\$37,300	\$26,100		\$6,400
Total	\$37,300	\$26,100		\$6,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FERRY MAINTENANCE FACILITY PIER B2
Asset # : 4522

Piers		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Structural Deck								
Concrete	75%			LIFE	**	5	\$85,600	
			<i>Cracking, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Entire Deck Surface</i>					
			<i>Spalling, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Isolated Locations, Primarily Offshore Half</i>					
Not Accessible	25%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : Soffit Of Inshore Half Of Pier</i>					
			<i>Explanation : Stay-in-place Formwork</i>					
Firewalls								
Concrete	70%			LIFE	**	5	\$4,800	
Not Accessible	30%							
Pile Caps								
Concrete	2%			LIFE	**	5	\$100	
Timber	98%			LIFE	**	4	\$471,600	
			<i>Recent Repair Evident, Extent : N/A, Area Affected : 10%</i>					
			<i>Location : Sister Caps Installed At Offshore Ends Of Pile Caps</i>					
Piles and Bracing								
Steel	2%	4+	\$82,500	LIFE	**	5	\$18,800	
			<i>Corrosion, Extent : Moderate, Area Affected : 30%</i>					
			<i>Location : Top 4 Feet</i>					
Timber	3%	4+	\$111,300	LIFE	**	4-5	\$8,200	
			<i>Rotting/Splitting, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Typically In The Tidal Zone</i>					
Timber	15%			LIFE	**	4-5	\$41,200	
			<i>Recent Repair Evident, Extent : N/A, Area Affected : 15%</i>					
			<i>Location : Bracing Replaced On Offshore End</i>					
Not Accessible	80%							
			<i>Other Observation, Extent : N/A, Area Affected : 0%</i>					
			<i>Location : Middle To Offshore End Of Pier</i>					
			<i>Explanation : 20 Percent Of Piles Are Encased</i>					
Fender Buffer								
Rubber	100%			2041	**	4-5	\$44,500	
Wales and Chocks								
Timber	45%			2035			\$62,200	
Timber	5%	4+	\$21,400	2035			\$4,600	
			<i>Worn, Extent : Moderate, Area Affected : 20%</i>					
			<i>Location : Isolated Across Entire Fender System</i>					
			<i>Other Observation, Extent : Severe, Area Affected : 2%</i>					
			<i>Location : At One Location Between Pier Deck And Fender System</i>					
			<i>Explanation : Steel Connecting Hardware Is Not Connected</i>					
Not Accessible	50%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FERRY MAINTENANCE FACILITY PIER B2
Asset # : 4522

Piers		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Fender								
Piles								
	Timber	5%	4+	\$67,800	2047	**	4	\$2,100
<i>Worn, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Above Mean Low Water Elevation</i>								
	Timber	5%	Now	\$67,800	2047	**	4	\$2,100
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Impact Damage At Isolated Piles Across Fender System</i>								
	Timber	25%			2035	\$847,800	4	\$16,000
	Timber	5%	Now	\$67,800	2047	**	4	\$2,100
<i>Marine Borer Infestation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Isolated Fender Piles Across Entire Fender System</i>								
	Not Accessible	60%						
Deck Elements								
Coping/Curb								
	Concrete	5%			LIFE	**		
	Timber	95%			LIFE	**		
<i>Rotting/Splitting, Extent : Light, Area Affected : 20%</i>								
<i>Location : Isolated Location Along Entire Timber Curb</i>								
Electrical								
Conduit								
	Not Accessible	100%						
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Steel Grating Covering Utilities On Both Sides Of The Pier</i>								
<i>Explanation : Covered</i>								
Lighting Fixture								
	LED	100%			2031			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 18 Light Fixtures</i>								
<i>Explanation : Other</i>								
Mechanical/ Plumbing								
Water Supply								
	Not Accessible	100%						
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Steel Grating Covering Utilities On Both Sides Of The Pier</i>								
<i>Explanation : Covered</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PIER 1 SOUTH OF FERRY MAINT FACILITY
Address : ST GEORGE
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0146.000 / 4523 **Yr Built/Renovated** :
Area Sq Ft : 49,870 **Project Type** : FERRIES
Date of Survey : 30-Nov-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 1 **Lot** : 70 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Piers	\$5,788,400	\$1,116,900
Total	\$5,788,400	\$1,116,900
Importance Code A	\$5,071,100	\$92,000
Importance Code B	\$717,300	\$1,024,900
Total	\$5,788,400	\$1,116,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers	\$200,900		\$2,800	\$46,100
Total	\$200,900		\$2,800	\$46,100
Importance Code A	\$143,000			\$46,100
Importance Code B	\$57,900		\$2,800	
Total	\$200,900		\$2,800	\$46,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PIER 1 SOUTH OF FERRY MAINT FACILITY
Asset # : 4523

Piers		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Structural Deck								
	Concrete	4%	Now	\$85,900	LIFE	**	5	\$3,700
<i>Cracking, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : At East End Of Pier</i>								
<i>Exposed Reinforcement, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Underdeck East Side At Edge And Throughout Soffit</i>								
	Concrete	90%			LIFE	**	5	\$167,300
<i>Cracking, Extent : Light, Area Affected : 5%</i>								
<i>Location : On The Topside Of The Deck Surface</i>								
<i>Spalling, Extent : Light, Area Affected : 1%</i>								
<i>Location : Intermittent 1 Square Foot Mechanical Spalls On Deck Surface</i>								
<i>Surface Wearing/Scaling, Extent : Light, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
	Concrete	5%	4+	\$357,800	LIFE	**	5	\$4,600
<i>Spalling, Extent : Moderate, Area Affected : 75%</i>								
<i>Location : Intermittent Along Edges Of Deck</i>								
	Not Accessible	1%						
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location : At South Side Of Pier</i>								
<i>Explanation : Under Building</i>								
Pile Caps								
	Concrete	25%	4+	\$750,900	LIFE	**	5	\$800
<i>Spalling, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Delamination And Spalling On Concrete Encased Steel Beams</i>								
	Timber	73%			LIFE	**	4	\$429,100
	Timber	2%	4+	\$84,300	LIFE	**	4	\$7,800
<i>Rotting/Splitting, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : At Ends Of Pile Caps</i>								
Piles and Bracing								
	Caissons	5%	4+	\$83,900	LIFE	**	5	\$3,100
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Mid-pier Stone Masonry Support Bent</i>								
<i>Explanation : Missing Joint Mortar At Stone Masonry Bent</i>								
	Timber	20%	Now	\$3,624,700	LIFE	**	4-5	\$44,700
<i>Rotting/Splitting, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Offshore 500 Feet Of Pier</i>								
	Not Accessible	75%						
<i>Other Observation, Extent : Light, Area Affected : 0%</i>								
<i>Location : Throughout Pier</i>								
<i>Explanation : 15 Percent Encased</i>								
Fender								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PIER 1 SOUTH OF FERRY MAINT FACILITY
Asset # : 4523

Piers		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Fender								
Pile Cluster								
Timber	80%	Now	\$717,300	2036	**	4	\$44,900	
	<i>Broken, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : In Tidal Zone</i>							
	<i>Loose Wrapping, Extent : Moderate, Area Affected : 25%</i>							
	<i>Location : Above Mean Low Water</i>							
Timber	10%			2036	**	4-10	\$43,000	
Not Accessible	10%							
Deck Elements								
Railing								
Steel	95%			2033			\$973,600	
Steel	5%	Now	\$20,500	2033			\$51,200	
	<i>Dents, Holes, Extent : Severe, Area Affected : 75%</i>							
	<i>Location : At 697 Feet And 759 Feet From Inshore, And At End Of Pier</i>							
Coping/Curb								
Timber	100%			LIFE	**			
Electrical								
Lighting Fixture								
Incandescent	100%			2029			\$46,100	
	<i>Other Observation, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Five Lights On The Approach And 16 Lights On The Pier</i>							
	<i>Explanation : Pier Lighting</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : PIER 11 WALL STREET FERRY PIER
Address : EAST RIVER AT GOUVERNEUR LANE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0001.000 / 4340 **Yr Built/Renovated** : 1906 / 2000
Area Sq Ft : 33,900 **Project Type** : FERRIES
Date of Survey : 14-Dec-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 36 **Lot** : 18 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Piers	\$151,000	\$730,000
Total	\$151,000	\$730,000
Importance Code B	\$151,000	\$730,000
Total	\$151,000	\$730,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers	\$111,200	\$28,900	\$8,800	
Total	\$111,200	\$28,900	\$8,800	
Importance Code A	\$48,600		\$8,800	
Importance Code B	\$62,600	\$28,900		
Total	\$111,200	\$28,900	\$8,800	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PIER 11 WALL STREET FERRY PIER
Asset # : 4340

Piers		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Structural								
Deck								
	Concrete	53%			LIFE	**	5	\$33,500
		<i>Cracking, Extent : Light, Area Affected : 2%</i> <i>Location : Deck Surface</i>						
		<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 10%</i> <i>Location : Light Wear In Painted Deck Surface, West End Of Pier</i>						
	Concrete	2%	4+	\$48,600	LIFE	**	5	\$1,300
		<i>Spalling, Extent : Moderate, Area Affected : 5%</i> <i>Location : Southwest Corner Of Pier And Offshore Structure South Face</i>						
	Not Accessible	45%						
Pile Caps								
	Concrete	2%			LIFE	**	5	
	Not Accessible	98%						
Piles and Bracing								
	Concrete Encased Timber	10%			LIFE	**	5	\$10,700
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i> <i>Location : Epoxy Encased Timber Piles</i> <i>Explanation : Epoxy Encasements</i>						
	Not Accessible	90%						
		<i>Other Observation, Extent : Light, Area Affected : 0%</i> <i>Location : All Piles</i> <i>Explanation : Epoxy Encasements</i>						
Fender								
Wales and Chocks								
	Timber	70%			2043	**	4	\$71,800
		<i>Rotting/Splitting, Extent : Light, Area Affected : 5%</i> <i>Location : Isolated Throughout</i>						
		<i>Other Observation, Extent : N/A, Area Affected : 20%</i> <i>Location : Recent Replacement Of Timber Wales On Perimeter Of Pier</i> <i>Explanation : Recent Repair Evident</i>						
	Timber	5%	Now	\$47,700	2049	**	4	\$3,400
		<i>Broken, Extent : Moderate, Area Affected : 100%</i> <i>Location : Inshore End Of Pier, North And South Sides, And Southwest Corner Of Island</i>						
	No Component	25%						
Piles								
	Timber	30%			2043	**	4	\$14,200
		<i>Other Observation, Extent : N/A, Area Affected : 20%</i> <i>Location : Replacement Of Single And Triple Timber Piles</i> <i>Explanation : Recent Replace Evident</i>						
	Timber	10%	Now	\$151,000	2049	**	4	\$3,200
		<i>Broken, Extent : Severe, Area Affected : 100%</i> <i>Location : Broken Piles At South End Of Pier And Between Pier And Island</i>						
	No Component	25%						
	Not Accessible	35%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
PIER 11 WALL STREET FERRY PIER
Asset # : 4340

Piers		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Fender								
	Pile Cluster							
	Timber	25%			2035	\$14,900	4-10	\$4,600
		<i>Other Observation, Extent : N/A, Area Affected : 25%</i>						
		<i>Location : Recent Replace Of Cluster On Northeast Corner Of Island</i>						
		<i>Explanation : Recent Replace Evident</i>						
	Timber	25%	Now	\$14,900	2039	**	4	\$600
		<i>Broken, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Southeast Corner Of Island</i>						
	Not Accessible	50%						
Deck Elements								
	Railing							
	Steel	100%			2032	\$730,000		
		<i>Corrosion, Extent : Light, Area Affected : 10%</i>						
		<i>Location : Perimeter Of Pier</i>						
Electrical								
	Conduit							
	Steel	100%			2032			
	Lighting Fixture							
	Incandescent	100%			2028	\$8,800		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 4 Lights On Pier</i>						
		<i>Explanation : Light Count</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ST. GEORGE FERRY TERMINAL FUEL PIER
Address : 1 BAY STREET
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0192.020 / 13895 **Yr Built/Renovated** :
Area Sq Ft : 8,400 **Project Type** : FERRIES
Date of Survey : 19-Apr-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 2 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Piers	\$169,200	\$801,800
Total	\$169,200	\$801,800
Importance Code A	\$169,200	\$602,800
Importance Code B		\$198,900
Total	\$169,200	\$801,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers	\$11,000	\$600	\$15,400	
Total	\$11,000	\$600	\$15,400	
Importance Code A	\$200		\$15,400	
Importance Code B	\$10,800	\$600		
Total	\$11,000	\$600	\$15,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

**DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL FUEL PIER**

Asset # : 13895

Piers		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Structural								
Deck								
	Concrete	30%			LIFE	**	5	\$4,700
	Steel	40%			2035	\$602,800	5	\$28,000
	Not Accessible	30%						
Pile Caps								
	Concrete	90%			LIFE	**	5	\$500
	Concrete	10%	4+	\$84,300	LIFE	**	5	\$100
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Isolated Throughout</i>								
Piles and Bracing								
	Concrete Encased Steel	60%			LIFE	**		
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : In The Tidal Zone</i>								
<i>Explanation : Erosion</i>								
	Concrete Encased Steel	10%	4+	\$84,800	LIFE	**		
<i>Spalling, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : At Tops Of Piles</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : In Tidal Zone</i>								
<i>Explanation : Erosion</i>								
	Not Accessible	30%						
Fender								
Piles								
	No Component	85%						
	Not Accessible	15%						
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : Barge Preventing Access To Piles</i>								
<i>Explanation : Obstruction</i>								
Pile Cluster								
	Timber	5%			2035	\$29,900	4-10	\$9,200
	No Component	85%						
	Not Accessible	10%						
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : Piles Behind Barge</i>								
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

*** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL FUEL PIER
Asset # : 13895

Piers System Component Type	Current Repair			Future Replacement		Maintenance		Priority
	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railing								
Steel	10%			2032	\$58,600			
Fiberglass	65%			2035	\$140,300			
Fiberglass	5%	Now	\$10,800	2039	**			
<i>Broken, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Toe boards</i>								
<i>Loose Connections, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Isolated Horizontal Elements</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Isolated Horizontal Elements</i>								
<i>Explanation : Cracking</i>								
No Component	20%							
Electrical								
Lighting Fixture								
Incandescent	70%			2028	\$10,800			
Incandescent	30%	4+	\$200	2028	\$4,600			
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : One Pole At South End Of Pier And One Pole At North End Of Catwalk, 7 Total</i>								
<i>Light Fixtures</i>								
<i>Explanation : Loose Hand Hole Cover</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ST. GEORGE FERRY TERMINAL NORTH WHARF
Address : NORTH SIDE OF TERMINAL BUILDING
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0195.000 / 13901 **Yr Built/Renovated** :
Area Sq Ft : 34,500 **Project Type** : FERRIES
Date of Survey : 25-May-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 2 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Piers	\$1,028,200	\$212,200
Total	\$1,028,200	\$212,200
Importance Code A	\$1,028,200	\$212,200
Total	\$1,028,200	\$212,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers				
Total				
Importance Code A				
Total				



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL NORTH WHARF

Asset # : 13901

Piers		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Structural								
Deck								
	Concrete	48%			LIFE	**	5	\$30,900
		<i>Cracking, Extent : Light, Area Affected : 10%</i>						
		<i>Location : In Deck Surface</i>						
	Concrete	2%	4+	\$99,000	LIFE	**	5	\$1,300
		<i>Spalling, Extent : Moderate, Area Affected : 10%</i>						
		<i>Location : Three Separate Spalls At The Northeast Corner</i>						
	Not Accessible	50%						
Piles and Bracing								
	Steel	40%	4+	\$929,100	LIFE	**	5	\$212,200
		<i>Corrosion, Extent : Moderate, Area Affected : 50%</i>						
		<i>Location : Above Mean Low Water</i>						
		<i>Missing Coating, Extent : Moderate, Area Affected : 50%</i>						
		<i>Location : Above Mean Low Water</i>						
	Not Accessible	60%						
Coping/Curb								
	Concrete	20%			LIFE	**		
		<i>Cracking, Extent : Light, Area Affected : 10%</i>						
		<i>Location : North End</i>						
	No Component	80%						
Deck Elements								
Railing								
	Fencing	90%			2035		3	
	No Component	10%						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ST. GEORGE FERRY TERMINAL SOUTH WHARF
Address : SOUTH SIDE OF TERMINAL BUILDING
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0194.000 / 13900 **Yr Built/Renovated** :
Area Sq Ft : 35,300 **Project Type** : FERRIES
Date of Survey : 19-Apr-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 1 **Lot** : 68 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Piers	\$2,909,400	\$352,800
Total	\$2,909,400	\$352,800
Importance Code A	\$1,894,600	\$352,800
Importance Code B	\$1,014,800	
Total	\$2,909,400	\$352,800

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers	\$24,600	\$21,200		\$1,700
Total	\$24,600	\$21,200		\$1,700
Importance Code A				
Importance Code B	\$24,600	\$7,200		\$1,700
Importance Code C		\$13,900		
Total	\$24,600	\$21,200		\$1,700



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL SOUTH WHARF
Asset # : 13900

Piers		Current Repair			Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural	Deck								
	Concrete	50%			LIFE	**	5	\$32,900	
				<i>Cracking, Extent : Moderate, Area Affected : 5%</i>					
				<i>Location : Pier Surface And Underdeck</i>					
				<i>Spalling, Extent : Moderate, Area Affected : 2%</i>					
				<i>Location : Isolated Locations In Underdeck</i>					
	Not Accessible	50%							
Deck Surface	Asphalt	25%			2037	**	5	\$9,700	
				<i>Cracking, Extent : Moderate, Area Affected : 5%</i>					
				<i>Location : Isolated Locations</i>					
	Concrete	75%			2047	**	5	\$18,100	
				<i>Cracking, Extent : Light, Area Affected : 5%</i>					
				<i>Location : Light Cracking On Concrete In Front Of Maintenance Facility</i>					
Pile Caps	Concrete	85%			LIFE	**	5	\$2,000	
				<i>Cracking, Extent : Light, Area Affected : 25%</i>					
				<i>Location : Hairline Cracks At Most Pile Locations</i>					
				<i>Spalling, Extent : Light, Area Affected : 15%</i>					
				<i>Location : Isolated Offshore Corners</i>					
	Concrete	5%	4+	\$53,200	LIFE	**	5	\$100	
				<i>Cracking, Extent : Moderate, Area Affected : 75%</i>					
				<i>Location : At Pile Caps Supporting Wharf Adjacent To Maintenance Building</i>					
	Timber	10%			LIFE	**	4	\$27,700	
				<i>Other Observation, Extent : Light, Area Affected : 10%</i>					
				<i>Location : Isolated Locations</i>					
				<i>Explanation : Checking</i>					
Piles and Bracing	Steel	50%	4+	\$594,200	LIFE	**	5	\$271,300	
				<i>Corrosion, Extent : Moderate, Area Affected : 100%</i>					
				<i>Location : Above Water</i>					
	Steel	15%	Now	\$178,300	LIFE	**	5	\$81,400	
				<i>Corrosion, Extent : Severe, Area Affected : 50%</i>					
				<i>Location : Tops Of Cross Bracing</i>					
	Timber	5%			LIFE	**	4-5	\$7,900	
				<i>Rotting/Splitting, Extent : Light, Area Affected : 20%</i>					
				<i>Location : Throughout</i>					
	Timber	5%	Now	\$1,069,000	LIFE	**	4-5	\$7,900	
				<i>Broken, Extent : Severe, Area Affected : 75%</i>					
				<i>Location : Broken Timber Piles At South End Of Facility</i>					
	Not Accessible	25%							
Fender									

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL SOUTH WHARF

Asset # : 13900

Piers		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Fender								
Wales and Chocks								
Timber	30%			2043	**	4	\$21,700	
Timber	35%	Now	\$392,700	2049	**	4	\$16,900	
<i>Rotting/Splitting, Extent : Severe, Area Affected : 75%</i>								
<i>Location : Tidal And Splash Zones</i>								
No Component	35%							
Piles								
Timber	35%	Now	\$622,100	2049	**	4	\$7,800	
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Inshore Section Adjacent To Maintenance Building</i>								
Timber	15%			2037	**	4	\$3,300	
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : On Face Of Fender Piles</i>								
<i>Explanation : Abrasion</i>								
No Component	35%							
Not Accessible	15%							
Deck Elements								
Railing								
Fencing	10%			2035		3		
<i>Corrosion, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout Fenced Area</i>								
No Component	90%							
Coping/Curb								
Timber	90%	2-4	\$24,600	LIFE	**			
<i>Rotting/Splitting, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : All Timber Curbs</i>								
No Component	10%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HARPER STREET ASPHALT PLANT WHARF
Address : FLUSHING CREEK WEST BANK BTWN WHITESTONE EXPWY & NORTHERN BLVD
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0217.020 / 15684 **Yr Built/Renovated** :
Area Sq Ft : 7,500 **Project Type** : HIGHWAYS
Date of Survey : 22-May-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 1791 **Lot** : 52 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Piers	\$1,199,900	
Total	\$1,199,900	
Importance Code A	\$1,199,900	
Total	\$1,199,900	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Piers	\$22,100			
Total	\$22,100			
Importance Code A				
Importance Code B	\$22,100			
Total	\$22,100			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HARPER STREET ASPHALT PLANT WHARF
Asset # : 15684

Piers		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Structural								
Deck								
	Concrete	10%	Now	\$107,600	LIFE	**	5	\$1,400
		<i>Mechanical Damage, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Northeast Corner Of Pier</i>						
	Concrete	25%			LIFE	**	5	\$3,500
	Not Accessible	65%						
Pile Caps								
	Concrete	15%	Now	\$112,900	LIFE	**	5	\$100
		<i>Mechanical Damage, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Impact Damage Along Offshore End Of Pier</i>						
	Concrete	25%			LIFE	**	5	\$100
	Not Accessible	60%						
Piles and Bracing								
	Steel	5%	Now	\$126,200	LIFE	**	5	\$5,800
		<i>Broken, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Northeast Corner Of Pier</i>						
	Steel	5%	2-4	\$126,200	LIFE	**	5	\$5,800
		<i>Corrosion, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : All Steel Piles</i>						
	Timber	10%	Now	\$454,300	LIFE	**	4-5	\$3,400
		<i>Broken, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Offshore End Of Pier And Northwest Corner</i>						
	Timber	10%	2-4	\$272,600	LIFE	**	4-5	\$3,400
		<i>Displaced Elements, Extent : Moderate, Area Affected : 100%</i>						
		<i>Location : Southwest Corner Of Pier</i>						
	Not Accessible	70%						
Deck Elements								
Coping/Curb								
	Concrete	50%	Now	\$18,400	LIFE	**		
		<i>Mechanical Damage, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Impact Damage Northeast Corner And Intermittent Locations Along Length Of Asset</i>						
	Concrete	50%	4+	\$3,700	LIFE	**		
		<i>Spalling, Extent : Moderate, Area Affected : 50%</i>						
		<i>Location : Offshore Face Of Pier</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BULKHEAD, PIER 26
Address : HUDSON RIVER N OF HUBERT TO S OF N MOORE ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0127.030 / 1809 **Yr Built/Renovated** :
Linear Ft : 580 **Project Type** : FERRIES
Date of Survey : 01-Feb-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 184 **Lot** : 8 **BIN** :

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
----------------	----------------	----------------	----------------	----------------

Bulkheads

Total

Importance Code A

Importance Code B

Total



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BULKHEAD, PIER 26
Asset # : 1809

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Structural								
	Gravity Wall Stone	40%			LIFE	**	5	\$19,700
			<i>Cracking, Extent : Light, Area Affected : 5%</i>					
			<i>Location : In Concrete Cap Element</i>					
			<i>Missing Block Seal, Extent : Light, Area Affected : 35%</i>					
			<i>Location : North And South Of Pier 26</i>					
	Not Accessible	60%						
Backfill								
	Fill							
	Not Accessible	100%						
	Surface							
	Stone	65%		2043		**	10	
	Under Construction	35%						
Deck Elements								
	Railing							
	Aluminum	25%		2032				\$36,900
			<i>Other Observation, Extent : Light, Area Affected : 60%</i>					
			<i>Location : Along Handrail North Of Pier 26</i>					
			<i>Explanation : Surface Staining</i>					
	No Component	75%						
Electrical								
	Lighting Fixture							
	LED	100%		2033				\$13,100
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Three Lights Along Handrail North Of Pier 26</i>					
			<i>Explanation : Light Count</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DOT HARPER ST. FLEET FACILITY BULKHEAD
Address : 32-11 HARPER STREET
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0129.000 / 1792 **Yr Built/Renovated** : 1950 /
Linear Ft : 1,615 **Project Type** : FERRIES
Date of Survey : 05-Dec-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 1790 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$478,600	
Total	\$478,600	
Importance Code B	\$478,600	
Total	\$478,600	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$31,500	\$6,500		
Total	\$31,500	\$6,500		
Importance Code A				
Importance Code B	\$11,100	\$6,500		
Importance Code C	\$20,400			
Total	\$31,500	\$6,500		



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
DOT HARPER ST. FLEET FACILITY BULKHEAD
Asset # : 1792

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Relieving Platform Top								
Concrete	27%			LIFE	**	5	\$1,600	
No Component	73%							
Coping/Curb								
Concrete	42%			LIFE	**	5	\$600	
			<i>Cracking, Extent : Light, Area Affected : 5%</i>					
			<i>Location : Full Length Of Curb From 931 Feet To 1,615 Feet From East</i>					
No Component	58%							
Piles and Bracing								
Not Accessible	100%							
Revetment								
Asphalt Remnants	7%			LIFE	**	5	\$100	
Stone	64%			LIFE	**	5	\$6,200	
Stone	2%	4+	\$20,400	LIFE	**	5	\$200	
			<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location : Beneath Whitestone Expressway</i>					
			<i>Explanation : Inadequate Stone</i>					
No Component	27%							
Backfill								
Fill								
Not Accessible	100%							
Surface								
Asphalt	70%			2037	**	5	\$12,900	
			<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location : Eastern 815 Feet, From 1,176 Feet To 1,292 Feet From East, And Western 215 Feet</i>					
Asphalt	5%	4+	\$11,100	2043	**	5	\$500	
			<i>Settlement, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : 1,103 To 1,176 Feet From East</i>					
Concrete	10%	4+	\$54,200	2043	**	5	\$900	
			<i>Settlement, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location : 931 To 1,103 Feet From East</i>					
Not Accessible	15%							
			<i>Other Observation, Extent : N/A, Area Affected : 0%</i>					
			<i>Location : 815 To 930 Feet And 1,290 To 1,400 Feet From East</i>					
			<i>Explanation : Container Boxes</i>					
Fender								
Piles								
Timber	100%	Now	\$322,500	2049	**	4	\$38,700	1
			<i>Broken, Extent : Severe, Area Affected : 50%</i>					
			<i>Location : Along Entire Length Of Bulkhead</i>					
			<i>Missing Part, Extent : Severe, Area Affected : 50%</i>					
			<i>Location : Along Entire Length Of Bulkhead</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

**DEPARTMENT OF TRANSPORTATION - 841
DOT HARPER ST. FLEET FACILITY BULKHEAD**

Asset # : 1792

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	

Fender

Wales and Chocks

Timber

100% Now \$101,800 2049 * * 4 \$87,600

Missing Part, Extent : Severe, Area Affected : 100%

Location : Along Entire Length Of Bulkhead

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : FERRY DOCKS TIMBER BULKHEAD
Address : HART ISLAND
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0128.017 / 1817 **Yr Built/Renovated** :
Linear Ft : 307 **Project Type** : FERRIES
Date of Survey : 08-Dec-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 5649 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$1,830,300	
Total	\$1,830,300	
Importance Code A	\$1,830,300	
Total	\$1,830,300	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$24,100			
Total	\$24,100			
Importance Code A				
Importance Code B	\$24,100			
Importance Code C				
Total	\$24,100			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
FERRY DOCKS TIMBER BULKHEAD
Asset # : 1817

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Piles and Bracing								
Timber	35%	2-4	\$165,900	2049	**	4	\$16,100	
<i>Rotting/Splitting, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Isolated Locations</i>								
Timber	65%	Now	\$308,100	2049	**	4	\$29,900	1
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Split And Broken Piles At Isolated Locations</i>								
<i>Excess Deflection, Extent : Severe, Area Affected : 80%</i>								
<i>Location : Piles Are Rotating At Center Of All Three Segments</i>								
Revetment								
Stone	70%			LIFE	**	5	\$1,300	
No Component	30%							
Sheet Piles								
Timber	100%	Now	\$1,124,000	LIFE	**	4	\$5,700	
<i>Interlock Damage, Extent : Severe, Area Affected : 15%</i>								
<i>Location : Isolated Locations</i>								
<i>Rotting/Splitting, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Tidal Zone</i>								
<i>Other Observation, Extent : Severe, Area Affected : 10%</i>								
<i>Location : At Interlock Damage</i>								
<i>Explanation : Loss Of Fill Through Gaps In Sheets</i>								
Wales								
Timber	60%	4+	\$139,300	LIFE	**	4	\$2,800	
<i>Rotting/Splitting, Extent : Light, Area Affected : 10%</i>								
<i>Location : Isolated Locations</i>								
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Isolated Locations</i>								
<i>Explanation : Cracking</i>								
Timber	40%	0-2	\$92,900	LIFE	**	4	\$1,800	
<i>Rotting/Splitting, Extent : Severe, Area Affected : 75%</i>								
<i>Location : In Tidal Zone At Southeast And Isolated Locations</i>								
Backfill								
Fill								
Topsoil	25%	Now	\$16,500	2074	**			
<i>Other Observation, Extent : Severe, Area Affected : 70%</i>								
<i>Location : Behind Bulkhead Up To 7 Feet Wide</i>								
<i>Explanation : Settlement</i>								
No Component	5%							
Not Accessible	70%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location : 105 Feet To 307 Feet From South End</i>								
<i>Explanation : Recent Repair Evident</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
FERRY DOCKS TIMBER BULKHEAD
Asset # : 1817

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Backfill								
Surface								
Stone	70%			2043		**	10	
		<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 105 Feet To 307 Feet From South End</i>						
Topsoil	25%	Now	\$7,500	2034	\$7,500	5	\$200	
		<i>Settlement, Extent : Severe, Area Affected : 70%</i>						
		<i>Location : Behind Bulkhead Up To 7 Feet Wide</i>						
No Component	5%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : **ST. GEORGE FERRY TERMINAL CONCRETE AND STEEL BULKHEAD**
 Address : **1 BAY STREET**
 Borough : **STATEN ISLAND** Agency's Number : **N/A**
 Program / Asset # : **DOT0131.020 / 1798** Yr Built/Renovated :
 Linear Ft : **2,940** Project Type : **FERRIES**
 Date of Survey : **25-May-2023** Landmark Status : **NONE**
 Areas Surveyed :
 Block : **2** Lot : **1** BIN :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$1,009,200	\$87,200
Total	\$1,009,200	\$87,200
Importance Code A	\$1,009,200	\$87,200
Total	\$1,009,200	\$87,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$89,700		\$12,600	
Total	\$89,700		\$12,600	
Importance Code A	\$17,700			
Importance Code B	\$72,000		\$12,600	
Importance Code C				
Total	\$89,700		\$12,600	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL CONCRETE AND STEEL BULKHEAD
Asset # : 1798

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Coping/Curb Timber	15%			LIFE	**	5	\$200	
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : West Of 69th Street Slip And Between Slips 3 And 4</i>								
<i>Explanation : Wear</i>								
No Component	85%							
Gravity Wall								
Concrete	25%			LIFE	**	5	\$3,000	
<i>Cracking, Extent : Moderate, Area Affected : 15%</i>								
<i>Location : Isolated Locations</i>								
<i>Erosion, Extent : Light, Area Affected : 30%</i>								
<i>Location : Tidal Zone</i>								
Stone	30%			LIFE	**	5	\$74,800	
Stone	5%	4+	\$293,100	LIFE	**	5	\$12,500	
<i>Displaced Elements, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Near Slip B-2 North At Ferry Maintenance Facility</i>								
No Component	30%							
Not Accessible	10%							
Revetment								
Stone	25%			LIFE	**	5	\$4,400	
<i>Erosion, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Underneath North Wharf</i>								
No Component	75%							
Sheet Piles								
Steel	5%	Now	\$716,200	LIFE	**			
<i>Corrosion, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Between Slips 3 And 4</i>								
No Component	65%							
Not Accessible	30%							
Pile Caps								
Concrete	2%	4+	\$17,700	LIFE	**	5	\$200	
<i>Spalling, Extent : Severe, Area Affected : 10%</i>								
<i>Location : Delaminations At Corner By 69th Street Slip</i>								
Concrete	33%			LIFE	**	5	\$2,900	
No Component	65%							
Backfill								
Fill								
Topsoil	5%	Now	\$31,700	2074	**			
<i>Sinkhole, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Near Slip 8, Between Slips 3 And 4, And At 69th Street Slip</i>								
Not Accessible	95%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL CONCRETE AND STEEL BULKHEAD
Asset # : 1798

Bulkheads	Current Repair			Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Backfill								
Surface								
Asphalt	45%			2043	**	5	\$15,100	
Asphalt	5%	Now	\$40,300	2049	**	5	\$800	
		<i>Sinkhole, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Near Slip 8 And Between Slips 3 And 4</i>						
Concrete	30%			2043	**	5	\$10,100	
Not Accessible	20%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WHITEHALL FERRY TERMINAL CONCRETE BULKHEAD
Address : 4 WHITEHALL STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0127.020 / 1808 **Yr Built/Renovated** :
Linear Ft : 390 **Project Type** : FERRIES
Date of Survey : 30-Nov-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 2 **Lot** : 1 **BIN** :


CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$38,000		\$2,200	
Total	\$38,000		\$2,200	
Importance Code A	\$34,400			
Importance Code B	\$3,600		\$2,200	
Importance Code C				
Total	\$38,000		\$2,200	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL CONCRETE BULKHEAD
Asset # : 1808

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Coping/Curb Concrete	10%			LIFE	**	5		
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Edge Of Asphalt Paver Walkway</i>							
	<i>Explanation : Coating Loss</i>							
No Component	90%							
Gravity Wall								
Concrete	30%	4+	\$34,400	LIFE	**	5	\$500	
	<i>Erosion, Extent : Moderate, Area Affected : 10%</i>							
	<i>Location : In Tidal Zone</i>							
	<i>Spalling, Extent : Light, Area Affected : 10%</i>							
	<i>Location : On Concrete Cap</i>							
Not Accessible	70%							
Revetment								
Stone	10%			LIFE	**	5	\$200	
	<i>Missing Part, Extent : Moderate, Area Affected : 100%</i>							
	<i>Location : Light Stone In Front Of Accessible Portion Of Gravity Wall</i>							
No Component	90%							
Backfill								
Fill								
Not Accessible	100%							
Surface								
Asphalt	60%			2043	**	5	\$2,700	
	<i>Cracking, Extent : Light, Area Affected : 5%</i>							
	<i>Location : Isolated</i>							
	<i>Sinkhole, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : 100 Feet From The West End Of Asset, At The Return Corner</i>							
	<i>Surface Wearing/Scaling, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Terminal Interior Roadway</i>							
Asphalt Pavers	20%			2043	**	5	\$900	
	<i>Settlement, Extent : Light, Area Affected : 10%</i>							
	<i>Location : Terminal Interior Walkway</i>							
Concrete	20%			2043	**	5	\$900	
Deck Elements								
Railing								
Fencing	20%	2-4	\$3,600	2035	\$6,000	3		
	<i>Corrosion, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Fencing From 0 To 100 Feet From The West End Of Asset</i>							
Steel	5%			2032	\$11,300			
No Component	75%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BULKHEAD / GRAVITY WALL
Address : E. RIVER, 71ST TO 78TH ST. COAST LINE OF 71 ST. TO CL 78 ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0025.055 / 4343 **Yr Built/Renovated** :
Linear Ft : 1,920 **Project Type** : HIGHWAYS
Date of Survey : 20-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 1483 **Lot** : 60 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$1,202,900	\$1,019,700
Total	\$1,202,900	\$1,019,700
Importance Code A	\$1,202,900	\$129,800
Importance Code B		\$889,900
Total	\$1,202,900	\$1,019,700

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$50,900			\$26,100
Total	\$50,900			\$26,100
Importance Code A	\$6,000			\$18,100
Importance Code B	\$44,800			\$8,000
Total	\$50,900			\$26,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BULKHEAD / GRAVITY WALL
Asset # : 4343

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Gravity Wall								
Conc w/Stone Face	12%	Now	\$534,500	LIFE	**	5	\$20,800	
<i>Erosion, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : At The Water Line, North Of E 76th Steet</i>								
<i>Missing Part, Extent : Severe, Area Affected : 25%</i>								
<i>Location : Missing Blocks North Of E 76th Street To 78th Street At Outfall</i>								
Conc w/Stone Face	43%			LIFE	**	5	\$148,800	
<i>Cracking, Extent : Light, Area Affected : 2%</i>								
<i>Location : Above The Waterline</i>								
Conc w/Stone Face	20%	4+	\$593,900	LIFE	**	5	\$34,600	
<i>Displaced Elements, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Displaced Blocks Around Outfall At 71st Street At Around Outfall At South End Of Asset</i>								
<i>Missing Block Seal, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout Length Of Asset</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Impact Damage On Granite Cap At 75th Street</i>								
<i>Explanation : Impact Damage</i>								
Not Accessible	25%							
Backfill								
Fill								
Not Accessible	100%							
Surface								
Asphalt Pavers	2%	Now	\$10,300	2044	**	5	\$200	
<i>Sinkhole, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Inshore Of Con Ed Building At 74th Street</i>								
Asphalt Pavers	5%	4+	\$34,500	2044	**	5	\$500	
<i>Settlement, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : North Of E 76th Street To 78th Street</i>								
Asphalt Pavers	73%			2044	**	5	\$16,000	
Not Accessible	20%							
Deck Elements								
Railing								
Steel	80%			2033	\$889,900			
<i>Missing Coating, Extent : Light, Area Affected : 20%</i>								
<i>Location : Full Length Of Railing</i>								
No Component	20%							
Electrical								
Lighting Fixture								
Incandescent	75%			2029	\$18,100			
Incandescent	25%	Now	\$6,000	2030	\$6,000			
<i>Broken, Extent : Light, Area Affected : 100%</i>								
<i>Location : 3 Of 11 Lights</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BULKHEAD AT PIER 79
Address : W 38TH ST TO SS OF PIER 81 HUDSON RIVER AT LINCOLN TUNNEL
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0025.021 / 4339 **Yr Built/Renovated** : 1900 /
Linear Ft : 772 **Project Type** : HIGHWAYS
Date of Survey : 29-Dec-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : 665 **Lot** : 999 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$338,500	\$178,900
Total	\$338,500	\$178,900
Importance Code A	\$338,500	
Importance Code B		\$178,900
Total	\$338,500	\$178,900

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$12,700			
Total	\$12,700			
Importance Code A	\$8,800			
Importance Code B	\$4,000			
Importance Code C				
Total	\$12,700			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BULKHEAD AT PIER 79
Asset # : 4339

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Relieving Platform Top								
No Component	40%							
Not Accessible	60%							
Coping/Curb								
Timber	30%			LIFE	**	5	\$100	
No Component	70%							
Sheet Piles								
Steel	10%			LIFE	**			
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Between Pier 78 And Ferry Terminal</i>					
			<i>Explanation : Steel Sheeting Under Platform</i>					
Steel w/Concrete	30%	4+	\$338,500	LIFE	**			
			<i>Corrosion, Extent : Light, Area Affected : 30%</i>					
			<i>Location : Top 3 Feet Of Sheeting Exposed Between Ferry Terminal And Pier 81</i>					
			<i>Spalling, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Located 25 Feet North Of Ferry Terminal Around Outfall And 60 Feet North Of Ferry Terminal</i>					
Not Accessible	60%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : Beneath Ferry Terminal</i>					
			<i>Explanation : Steel Sheet Pile Not Accessible Beneath Ferry Terminal</i>					
Backfill								
Fill								
Not Accessible	100%							
Surface								
Asphalt	43%			2041	**	5	\$3,800	
			<i>Settlement, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Settlement Up To 3 Inches From 0 Feet To 35 Feet North Of Pier 78</i>					
Concrete	45%			2041	**	5	\$4,000	
Gravel	12%			2041	**	2-5	\$300	
Deck Elements								
Railing								
Steel	40%			2030			\$178,900	
No Component	60%							
Electrical								
Lighting Fixture								
Incandescent	100%			2026			\$8,800	
			<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Between Ferry Terminal And Pier 81</i>					
			<i>Explanation : 4 Light Fixtures</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BULKHEAD NORTH OF UNIVERSITY HEIGHTS BRIDGE
Address : LANDING ROAD
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0209.000 / 14496 **Yr Built/Renovated** :
Linear Ft : 520 **Project Type** : HIGHWAYS
Date of Survey : 13-May-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : **Lot** : **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$2,690,000	
Total	\$2,690,000	
Importance Code A	\$2,690,000	
Total	\$2,690,000	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$39,400			
Total	\$39,400			
Importance Code A				
Importance Code B	\$39,400			
Total	\$39,400			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BULKHEAD NORTH OF UNIVERSITY HEIGHTS BRIDGE
Asset # : 14496

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Piles and Bracing No Component	45%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : From Northwest Corner To End Of Asset At The Northeast</i>							
	<i>Explanation : Steel Sheet Pile Bulkhead</i>							
Not Accessible	55%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Behind Steel Sheeting</i>							
	<i>Explanation : Timber Piles</i>							
Sheet Piles								
Steel	100%	Now	\$2,533,400	LIFE	**			1
	<i>Corrosion, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : Tidal Zone. Missing Section Due To Corrosion</i>							
Pile Caps								
Concrete	100%	4+	\$156,600	LIFE	**	5	\$1,600	
	<i>Cracking, Extent : Light, Area Affected : 15%</i>							
	<i>Location : Along Top And Offshore Faces Of The Pile Cap</i>							
	<i>Spalling, Extent : Moderate, Area Affected : 5%</i>							
	<i>Location : Along Offshore Edge With Areas Of Exposed Reinforcement</i>							
Backfill								
Fill								
Topsoil	10%	Now	\$11,200	2073	**			
	<i>Sinkhole, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : Intermittently Along North From The Northwest Corner To The End Of The Asset At The Northeast</i>							
Not Accessible	90%							
Surface								
Topsoil	35%			2031	\$17,900	5	\$900	
Topsoil	15%	Now	\$7,700	2033	\$7,700	5	\$200	
	<i>Sinkhole, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : Between 250 Feet And 315 Feet From South End Of Asset</i>							
Not Accessible	50%							
	<i>Other Observation, Extent : N/A, Area Affected : 0%</i>							
	<i>Location : Material Stored At Southern 90 Feet Of Asset And From Northwest Corner To End Of Asset At The Northeast</i>							
	<i>Explanation : Storage Yard</i>							
Deck Elements								
Railing								
Fencing	50%	Now	\$20,100	2038	**	3	\$100	
	<i>Broken, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : From Northwest Corner Of Asset To End Of Asset At The Northeast</i>							
No Component	50%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BULKHEAD, CONNER ST. YARD CONCRETE GRAVITY WALL
Address : 3200 CONNER STREET
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0128.020 / 1791 **Yr Built/Renovated** :
Linear Ft : 497 **Project Type** : HIGHWAYS
Date of Survey : 05-Dec-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 5256 **Lot** : 200 **BIN** :

CAPITAL

Total

Importance Code

Total

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads		\$100	\$6,500	
Total		\$100	\$6,500	
Importance Code A			\$4,500	
Importance Code B		\$100	\$2,000	
Total		\$100	\$6,500	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
BULKHEAD, CONNER ST. YARD CONCRETE GRAVITY WALL

Asset # : 1791

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Pile Supported Wall								
Concrete	45%			2043	**	5	\$8,900	
Not Accessible	35%							
Under Construction	20%							
Backfill								
Fill								
Not Accessible	80%							
Under Construction	20%							
Surface								
Asphalt	70%			2043	**	5	\$4,000	
Topsoil	10%			2032	\$4,900	5	\$200	
Under Construction	20%							
Deck Elements								
Railing								
Guard Rail	70%			LIFE	**			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Behind Guard Rail Along The Perimeter Of Asset</i>								
<i>Explanation : Gabion Wall</i>								
No Component	10%							
Under Construction	20%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CONNER STREET DOT YARD REVETMENT
Address : 3200 CONNER STREET
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0128.030 / 14768 **Yr Built/Renovated** :
Linear Ft : 495 **Project Type** : HIGHWAYS
Date of Survey : 05-Dec-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 5256 **Lot** : 200 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$356,700	
Total	\$356,700	
Importance Code C	\$356,700	
Total	\$356,700	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads			\$1,400	
Total			\$1,400	
Importance Code B			\$1,400	
Importance Code C				
Total			\$1,400	



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
CONNER STREET DOT YARD REVETMENT
Asset # : 14768

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Revetment								
Stone	95%	4+	\$356,700	LIFE	**	5	\$2,800	
	<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>							
	<i>Location : Non-engineered, Very Steep Slope With Areas Of Scour</i>							
	<i>Explanation : Inadequate Stone Protection</i>							
Stone	5%			LIFE	**	5	\$100	
	<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : Adjacent To Outfall</i>							
Backfill								
Fill								
Not Accessible	100%							
Surface								
Asphalt	50%			2043	**	5	\$2,800	
	<i>Erosion, Extent : Light, Area Affected : 100%</i>							
	<i>Location : Raveling Throughout Surface</i>							
Not Accessible	50%							
	<i>Other Observation, Extent : Light, Area Affected : 0%</i>							
	<i>Location : Inshore Of Revetment</i>							
	<i>Explanation : Under Stacked Concrete Block Wall And Dot Trucks</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DOT FACILITY REVETMENT
Address : 6080 FLATLANDS AVE.
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0130.020 / 1795 **Yr Built/Renovated** :
Linear Ft : 750 **Project Type** : HIGHWAYS
Date of Survey : 23-Mar-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 8012 **Lot** : 400 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$948,200	\$55,200
Total	\$948,200	\$55,200
Importance Code B		\$55,200
Importance Code C	\$948,200	
Total	\$948,200	\$55,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$69,900	\$600		
Total	\$69,900	\$600		
Importance Code B	\$69,900	\$600		
Importance Code C				
Total	\$69,900	\$600		



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
DOT FACILITY REVETMENT
Asset # : 1795

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Revetment								
Stone	97%	4+	\$919,700	LIFE	**	5	\$4,400	
<i>Erosion, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Entire Length Of Asset</i>								
Stone	3%	Now	\$28,400	LIFE	**	5	\$100	
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Western Most 20 Feet</i>								
<i>Explanation : Collapsed</i>								
Backfill								
Fill								
Topsoil	10%	Now	\$16,100	2074	**			
<i>Erosion, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Vertical Cut Banks Above Revetment</i>								
Not Accessible	90%							
Surface								
Asphalt	10%	Now	\$20,600	2049	**	5	\$400	
<i>Erosion, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Offshore Portion Of Non-engineered Asphalt Berm At Top Of Embankment</i>								
Asphalt	15%			2037	**	5	\$1,300	
<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Inshore Portion Of Non-engineered Asphalt Berm At Top Of Embankment</i>								
Topsoil	75%	2-4	\$33,100	2034	\$55,200	5	\$1,300	
<i>Erosion, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Entire Length Of Asset</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
<i>Explanation : Heavy Vegetation And Debris</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DOT FACILITY/STEEL BULKHEAD UNDER WILLIAMSBURG BRIDGE
Address : 352-372 KENT AVE. EAST RIVER, S 5TH TO S 6TH ST.
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0130.030 / 1796 **Yr Built/Renovated** :
Linear Ft : 430 **Project Type** : HIGHWAYS
Date of Survey : 05-Mar-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : 2453 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$106,300	
Total	\$106,300	
Importance Code A	\$106,300	
Total	\$106,300	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$29,400		\$10,500	\$1,500
Total	\$29,400		\$10,500	\$1,500
Importance Code A	\$700			
Importance Code B	\$28,700		\$10,500	\$1,500
Total	\$29,400		\$10,500	\$1,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
DOT FACILITY/STEEL BULKHEAD UNDER WILLIAMSBURG BRIDGE
Asset # : 1796

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Sheet Piles								
Steel	60%			LIFE		**	10	
			<i>Corrosion, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Above Mean Low Water</i>					
			<i>Missing Coating, Extent : Moderate, Area Affected : 50%</i>					
			<i>Location : Above Mean Low Water</i>					
No Component	5%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : At Two Bridge Piers</i>					
			<i>Explanation : No Component</i>					
Not Accessible	35%							
Wales								
Steel	45%	4+	\$106,300	LIFE		**	5	\$4,600
			<i>Corrosion, Extent : Moderate, Area Affected : 100%</i>					
			<i>Location : Entire Tie-back Wale</i>					
No Component	55%							
			<i>Other Observation, Extent : Light, Area Affected : 0%</i>					
			<i>Location : At Bridge Piers And On South Face</i>					
			<i>Explanation : No Component</i>					
Pile Caps								
Concrete	55%			LIFE		**	5	\$1,400
No Component	45%							
Backfill								
Fill								
Topsoil	5%	Now	\$4,600	2075		**		
			<i>Erosion, Extent : Severe, Area Affected : 100%</i>					
			<i>Location : Fill Loss At South End Of Sheet Pile Wall</i>					
Not Accessible	95%							
Surface								
Concrete	60%			2044		**	5	\$2,900
Concrete	5%	Now	\$24,100	2050		**	5	\$100
			<i>Other Observation, Extent : Severe, Area Affected : 100%</i>					
			<i>Location : Slab At South End Of Sheet Pile Wall</i>					
			<i>Explanation : Undermining</i>					
Stone	35%			2044		**	10	
Fender								
Wales and Chocks								
Timber	90%			2044		**	4	\$21,000
			<i>Recent Replace Evident, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : Throughout Asset Except At The Southern And Northern 20 Feet</i>					
No Component	10%							
Deck Elements								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT FACILITY/STEEL BULKHEAD UNDER WILLIAMSBURG BRIDGE
Asset # : 1796

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Deck Elements								
Railing								
Fencing	50%			2036		**	3	\$100
		<i>Corrosion, Extent : Moderate, Area Affected : 15%</i>						
		<i>Location : Base Of Posts At North End</i>						
No Component	50%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.
Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DOT HAMILTON AVE. ASPHALT PLANT RELIEVING PLATFORM
Address : 448 HAMILTON AVE. GOWANUS CANAL S OF BRIDGE
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0130.011 / 1793 **Yr Built/Renovated** :
Linear Ft : 520 **Project Type** : HIGHWAYS
Date of Survey : 07-Mar-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : 625 **Lot** : 2 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$209,500	
Total	\$209,500	
Importance Code A	\$53,700	
Importance Code B	\$155,800	
Total	\$209,500	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$20,300		\$100	\$500
Total	\$20,300		\$100	\$500
Importance Code A	\$10,100			
Importance Code B	\$10,000		\$100	\$500
Importance Code C	\$300			
Total	\$20,300		\$100	\$500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
DOT HAMILTON AVE. ASPHALT PLANT RELIEVING PLATFORM
Asset # : 1793

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Relieving Platform Top								
Concrete	10%	4+	\$53,700	LIFE	**	5	\$200	
<i>Erosion, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Low Level Platform In Tidal Zone</i>								
<i>Spalling, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Concrete	90%			LIFE	**	5-10	\$3,500	
Coping/Curb								
Timber	100%			LIFE	**	5	\$600	
Piles and Bracing								
Concrete	10%			LIFE	**	5	\$600	
Steel	10%			LIFE	**	5	\$16,100	
<i>Corrosion, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Splash Zone</i>								
Not Accessible	80%							
Pile Caps								
Not Accessible	100%							
Backfill								
Surface								
Gravel	100%			2044	**	2-5	\$1,600	
Fender								
Piles								
Timber	45%			2038	**	4	\$8,400	
<i>Worn, Extent : Light, Area Affected : 30%</i>								
<i>Location : Throughout</i>								
Timber	30%	Now	\$155,800	2044	**	4	\$3,700	
<i>Worn, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Throughout</i>								
Not Accessible	25%							
Wales and Chocks								
Timber	50%			2038	**	4	\$21,200	
<i>Worn, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Throughout</i>								
Not Accessible	50%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : DOT HAMILTON AVE. ASPHALT PLANT STEEL SHEET PILE BULKHEAD
Address : 448 HAMILTON AVE. GOWANUS CANAL N END OF PLANT
Borough : BROOKLYN **Agency's Number** : N/A
Program / Asset # : DOT0130.012 / 1794 **Yr Built/Renovated** :
Linear Ft : 31 **Project Type** : HIGHWAYS
Date of Survey : 07-Mar-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : 625 **Lot** : 2 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$151,000	
Total	\$151,000	
Importance Code A	\$151,000	
Total	\$151,000	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$9,200			
Total	\$9,200			
Importance Code B	\$9,200			
Total	\$9,200			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
DOT HAMILTON AVE. ASPHALT PLANT STEEL SHEET PILE BULKHEAD
Asset # : 1794

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Sheet Piles								
Steel	100%	Now	\$151,000	LIFE		**		1
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Full Length Of Asset</i>								
<hr/>								
Backfill								
Fill								
Stone	65%	Now	\$6,700	LIFE		**	5	
<i>Erosion, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Active Sloughing</i>								
<hr/>								
Not Accessible	35%							
<hr/>								
Surface								
Concrete	20%			2044		**	5	\$100
Topsoil	80%	Now	\$2,400	2035	\$2,400		5	\$100
<i>Erosion, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Active Sloughing</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : GRAVITY WALL AT HALLETS COVE
Address : 30TH DRIVE TO JUST SOUTH OF 31 AVENUE
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0196.000 / 14022 **Yr Built/Renovated** :
Linear Ft : 515 **Project Type** : HIGHWAYS
Date of Survey : 23-Feb-2024 **Landmark Status** : NONE
Areas Surveyed :
Block : 499 **Lot** : 51 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$60,600	\$131,100
Total	\$60,600	\$131,100
Importance Code A	\$60,600	
Importance Code B		\$131,100
Total	\$60,600	\$131,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$8,000		\$500	\$1,800
Total	\$8,000		\$500	\$1,800
Importance Code A	\$1,900			
Importance Code B	\$6,100		\$500	\$1,800
Total	\$8,000		\$500	\$1,800



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
GRAVITY WALL AT HALLETS COVE
Asset # : 14022

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Structural								
	Gravity Wall							
	Concrete	90%			LIFE	**	5-10	\$3,700
		<i>Spalling, Extent : Light, Area Affected : 2%</i>						
		<i>Location : Concrete Foundation In Tidal Zone</i>						
	Concrete	10%	4+	\$60,600	LIFE	**	5	\$200
		<i>Spalling, Extent : Moderate, Area Affected : 100%</i>						
		<i>Location : Isolated Areas Of Concrete Foundation, Primarily In Central 300 Feet</i>						
		<i>Other Observation, Extent : Moderate, Area Affected : 40%</i>						
		<i>Location : Adjacent To Steps At South End</i>						
		<i>Explanation : Undermining</i>						
Backfill								
	Fill							
	Sand	20%	Now	\$6,100	2065	**	5	\$100
		<i>Erosion, Extent : Moderate, Area Affected : 30%</i>						
		<i>Location : At South End, Undermining Steps And 6 Feet Of Gravity Wall</i>						
	Not Accessible	80%						
	Surface							
	Concrete	60%			2044	**	5	\$3,500
	Topsoil	40%			2033	\$20,200	5	\$1,000
Deck Elements								
	Railing							
	Aluminum	100%			2033	\$131,100		
	Parapet							
	Concrete	100%			2036	**		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HARPER STREET ASPHALT PLANT BULKHEAD & REVETMENT
Address : FLUSHING CREEK WEST BANK BTWN WHITESTONE EXPWY & NORTHERN BLVD
Borough : QUEENS **Agency's Number** : N/A
Program / Asset # : DOT0217.010 / 15679 **Yr Built/Renovated** :
Linear Ft : 845 **Project Type** : HIGHWAYS
Date of Survey : 22-May-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 1791 **Lot** : 52 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$51,600	
Total	\$51,600	
Importance Code A	\$51,600	
Total	\$51,600	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$41,200	\$100	\$300	\$100
Total	\$41,200	\$100	\$300	\$100
Importance Code A	\$41,200			
Importance Code B		\$100	\$300	\$100
Importance Code C				
Total	\$41,200	\$100	\$300	\$100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
HARPER STREET ASPHALT PLANT BULKHEAD & REVETMENT
Asset # : 15679

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Coping/Curb								
Concrete	55%			LIFE	**	5	\$400	
No Component	45%							
Revetment								
Stone	55%			LIFE	**	5	\$2,800	
No Component	45%							
Sheet Piles								
Steel	10%	4+	\$41,200	LIFE	**			
			<i>Corrosion, Extent : Moderate, Area Affected : 25%</i>					
			<i>Location : In Tidal Zone</i>					
Timber	1%	Now	\$51,600	LIFE	**	4	\$200	
			<i>Rotting/Splitting, Extent : Severe, Area Affected : 100%</i>					
			<i>Location : 310 To 315 Feet From The Northern End Of Asset</i>					
Timber	4%			LIFE	**	4	\$600	
			<i>Worn, Extent : Light, Area Affected : 5%</i>					
			<i>Location : 315 To 350 Feet From The Northern End Of Asset</i>					
No Component	55%							
Not Accessible	30%							
Backfill								
Fill								
Not Accessible	100%							
Surface								
Gravel	35%			2043	**	2-5	\$900	
Not Accessible	65%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RELIEVING PLATFORM
Address : E. RIVER, 59TH TO 63RD ST.
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0025.053 / 4341 **Yr Built/Renovated** :
Linear Ft : 1,223 **Project Type** : HIGHWAYS
Date of Survey : 22-Jan-2021 **Landmark Status** : NONE
Areas Surveyed :
Block : 1474 **Lot** : 60 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$399,100	\$177,100
Total	\$399,100	\$177,100
Importance Code A	\$399,100	
Importance Code B		\$177,100
Total	\$399,100	\$177,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$34,000	\$6,500		
Total	\$34,000	\$6,500		
Importance Code A	\$32,300	\$6,500		
Importance Code B	\$1,700			
Total	\$34,000	\$6,500		



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
RELIEVING PLATFORM
Asset # : 4341

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Pile Supported Wall								
Conc w/Stone Face	40%			LIFE	**	5	\$39,200	
			<i>Broken, Extent : Moderate, Area Affected : 10%</i>					
			<i>Location : Isolated Cracked Panels</i>					
			<i>Erosion, Extent : Moderate, Area Affected : 25%</i>					
			<i>Location : Above Granite Fascia Panels</i>					
			<i>Spalling, Extent : Moderate, Area Affected : 15%</i>					
			<i>Location : Isolated Concrete Spalls Along The Top Wall</i>					
Conc w/Stone Face	10%	4+	\$399,100	LIFE	**	5	\$9,800	
			<i>Missing Part, Extent : Severe, Area Affected : 50%</i>					
			<i>Location : Isolated Missing Panels Along Bottom Half Of Wall, Totaling 60 Feet</i>					
Under Construction	50%							
Piles and Bracing								
Not Accessible	100%							
Backfill								
Fill								
Not Accessible	100%							
Surface								
Asphalt Pavers	25%			2041	**	5	\$3,500	
			<i>Settlement, Extent : Light, Area Affected : 2%</i>					
			<i>Location : Primarily At Light Pole Foundations, Up To 3 Foot Radius</i>					
Under Construction	75%							
Deck Elements								
Railing								
Steel	25%			2030			\$177,100	
			<i>Missing Coating, Extent : Light, Area Affected : 10%</i>					
			<i>Location : Isolated Locations Along Handrail</i>					
Under Construction	75%							
Electrical								
Lighting Fixture								
Sodium	80%			2026			\$25,800	
Sodium	20%	Now	\$6,500	2027			\$6,500	
			<i>Broken, Extent : N/A, Area Affected : 100%</i>					
			<i>Location : 2 Out Of 10 Light Fixtures</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.


Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : RELIEVING PLATFORM
Address : EAST RIVER, 34TH ST TO 36TH ST
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0025.064 / 4342 **Yr Built/Renovated** :
Linear Ft : 582 **Project Type** : HIGHWAYS
Date of Survey : 11-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 966 **Lot** : 50 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$523,100	\$337,200
Total	\$523,100	\$337,200
Importance Code B	\$523,100	\$337,200
Total	\$523,100	\$337,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$76,300			\$3,300
Total	\$76,300			\$3,300
Importance Code A	\$69,000			
Importance Code B	\$6,700			\$3,300
Importance Code C	\$500			
Total	\$76,300			\$3,300



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
RELIEVING PLATFORM
Asset # : 4342

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Structural								
Relieving Platform Top								
Concrete/Stone	3%	4+	\$15,700	LIFE		**		
<i>Missing Block Seal, Extent : Light, Area Affected : 50%</i>								
<i>Location : Joints Between Masonry Panels</i>								
<i>Spalling, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Three Isolated Locations, South Side Of Ferry Landing</i>								
Concrete/Stone	95%			LIFE		**		
Stone	2%	Now	\$17,100	2075		**		
<i>Missing Part, Extent : Severe, Area Affected : 20%</i>								
<i>Location : Two Broken Masonry Panels With 10 Feet Total Missing</i>								
Coping/Curb	100%			LIFE		**	5-10	\$1,100
Concrete								
Piles and Bracing	100%							
Not Accessible								
Lowlevel Pile Caps								
Timber	5%	Now	\$36,200	LIFE		**		
<i>Rotting/Splitting, Extent : Severe, Area Affected : 80%</i>								
<i>Location : Line Cap Along Bulkhead Face</i>								
Not Accessible	95%							
Backfill								
Fill								
Not Accessible	100%							
Surface								
Asphalt Pavers	100%			2044		**	5	\$6,600
<i>Settlement, Extent : Light, Area Affected : 8%</i>								
<i>Location : 52 Feet Total At 175 To 200 Feet, 242 To 269 Feet From South End Of Asset</i>								
Fender								
Piles								
Timber	45%	Now	\$523,100	2050		**	4	\$6,300
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Entire Fender System</i>								
No Component	10%							
Not Accessible	45%							
Deck Elements								
Railing								
Steel	98%			2033	\$330,400			
<i>Missing Coating, Extent : Light, Area Affected : 20%</i>								
<i>Location : Primarily Top Rail And Posts Throughout</i>								
Steel	2%	4+	\$6,700	2035	\$6,700			
<i>Impact Damage, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : 140 To 160 Feet From South End Of Asset</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : REVTMENT - RIPRAP BULKHEAD
Address : W 205TH TO W 206TH ST HARLEM RIVER,SUB 2 OF ASSET TYPE
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0187.000 / 13798 **Yr Built/Renovated** :
Linear Ft : 296 **Project Type** : HIGHWAYS
Date of Survey : 23-Nov-2020 **Landmark Status** : NONE
Areas Surveyed :
Block : 2186 **Lot** : 9 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Bulkheads	\$145,900	
Total	\$145,900	
Importance Code C	\$145,900	
Total	\$145,900	

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Bulkheads	\$11,300			
Total	\$11,300			
Importance Code B	\$11,300			
Importance Code C				
Total	\$11,300			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
REVTMENT - RIPRAP BULKHEAD
Asset # : 13798

Bulkheads		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Structural	Revetment							
	Stone	65%	4+	\$145,900	LIFE	**	5	\$1,200
		<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>						
		<i>Location : Center Of Asset</i>						
		<i>Explanation : Steep, Unstable Slope</i>						
	Stone	35%			LIFE	**	5	\$600
Backfill	Fill							
	Not Accessible	100%						
	Surface							
	Topsoil	35%			2030	\$10,200	5	\$500
	Topsoil	65%	4+	\$11,300	2032	\$18,900	5	\$500
		<i>Erosion, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Center Of Asset</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : BATTERY MARITIME BUILDING SLIP 5 - FAST FERRY BARGE
Address : 10 SOUTH STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0192.000 / 13891 **Yr Built/Renovated** :
Area Sq Ft : 3,600 **Project Type** : FERRIES
Date of Survey : 30-Nov-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 2 **Lot** : 2 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks		\$561,400
Total		\$561,400
Importance Code A		\$561,400
Total		\$561,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$5,200	\$12,600	\$5,100	\$19,600
Total	\$5,200	\$12,600	\$5,100	\$19,600
Importance Code A	\$4,200		\$4,100	\$18,700
Importance Code B	\$500	\$12,300	\$500	\$500
Importance Code C	\$500	\$300	\$500	\$300
Total	\$5,200	\$12,600	\$5,100	\$19,600



*Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included. ** Replacement cost estimated to be beyond ten years is not included in this report.*

DEPARTMENT OF TRANSPORTATION - 841
BATTERY MARITIME BUILDING SLIP 5 - FAST FERRY BARGE

Asset # : 13891

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Access Walkways								
Gangways								
Aluminum	100%			2054	**	1-3	\$40,400	
Piles and Bracing								
Steel	100%			2054	**	5-10		
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Support Beam Flanges</i>								
Floating Docks								
Fenders								
Rubber	100%			2032	\$37,900	1-2	\$4,300	
<i>Worn, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Above Waterline</i>								
Floats/ Frames								
Steel	100%			2039	**	5-10	\$24,700	
Barge								
Steel	70%			2043	**	5	\$8,200	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Isolated Locations On Surface</i>								
<i>Other Observation, Extent : Light, Area Affected : 2%</i>								
<i>Location : At Gangway Landing</i>								
<i>Explanation : Abrasion</i>								
Not Accessible	30%							
Deck Elements								
Railing								
Steel	100%			2032	\$228,800			
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : Isolated Locations</i>								
Electrical								
Conduit								
PVC	100%			2030	\$123,400			
Lighting Fixture								
LED	98%			2032	\$204,900			
LED	2%	Now	\$4,200	2034	\$4,200			
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : One Light On Middle Walkway</i>								
Movable Ramps								
Deck and Railing								
Aluminum	100%			2043	**			

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : CITY ISLAND FERRY DOCK
Address : FORDHAM STREET
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0128.000 / 13923 **Yr Built/Renovated** :
Area Sq Ft : 1,620 **Project Type** : FERRIES
Date of Survey : 05-Jan-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 5644 **Lot** : 250 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$245,700	\$1,253,400
Total	\$245,700	\$1,253,400
Importance Code A	\$245,700	\$1,253,400
Total	\$245,700	\$1,253,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$5,300	\$800	\$22,500	\$600
Total	\$5,300	\$800	\$22,500	\$600
Importance Code A	\$4,000	\$800	\$22,500	
Importance Code B	\$1,300			\$600
Total	\$5,300	\$800	\$22,500	\$600



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
CITY ISLAND FERRY DOCK
Asset # : 13923

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Access Walkways								
Deck								
Timber	50%			2032	\$83,900	5	\$1,400	
<i>Surface Wearing/Scaling, Extent : Light, Area Affected : 50%</i>								
<i>Location : Isolated At Top Of Deck</i>								
Not Accessible	50%							
Gangways								
Aluminum	10%	4+	\$800	2064	**	1-3	\$200	
<i>Cracked Weld, Extent : Severe, Area Affected : 5%</i>								
<i>Location : Upland End Of Gangway</i>								
Aluminum	90%			2044	**	1-3	\$2,200	
Pile Caps								
Not Accessible	100%							
Piles and Bracing								
Not Accessible	100%							
Floating Docks								
Anchor Piles								
Timber	60%			2035	\$12,100	4-5	\$600	
<i>Abrasion, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : In Tidal Zone</i>								
Not Accessible	40%							
Floats/ Frames								
Timber	50%			2039	**			
<i>Wearing, Extent : Light, Area Affected : 100%</i>								
<i>Location : Surface Of Floating Dock</i>								
Not Accessible	50%							
Protective Structure								
Pile Cluster								
Timber	100%			2035		4-10		
<i>Worn, Extent : Light, Area Affected : 5%</i>								
<i>Location : Four 3-pile Clusters. Two Clusters At Southeast End Of South Fender Rack, Two Clusters At Floating Dock.</i>								
Deck Elements								
Railing								
Steel	79%			2032	\$315,800			
Steel	1%	4+	\$4,000	2034	\$4,000			
<i>Missing Connections, Extent : Light, Area Affected : 5%</i>								
<i>Location : Southeast Railing Along Access Walkway At Post Base Connection</i>								
Timber	20%			2028	\$22,500			
Fender								
Facing								
Timber	50%			2032	\$163,000			
<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Tidal Zone Of The South Rack</i>								
<i>Explanation : Abrasion</i>								
No Component	50%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
CITY ISLAND FERRY DOCK
Asset # : 13923

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Fender								
Piles								
Timber	30%	2-4	\$194,200	2039				**
<i>Other Observation, Extent : Moderate, Area Affected : 75%</i>								
<i>Location : South Fender Rack</i>								
<i>Explanation : Rotting, Splitting, Leaning/ Impact</i>								
Timber	20%			2035	\$129,500			
Not Accessible	50%							
Wales and Chocks								
Timber	10%	2-4	\$51,400	2039				**
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Primarily North Fender Rack</i>								
<i>Explanation : Rotting, Splitting</i>								
Timber	65%			2035	\$557,200			
Not Accessible	25%							
Gallows Frames								
Tower Frames								
Timber	90%			2043				**
<i>Recent Replace Evident, Extent : N/A, Area Affected : 10%</i>								
<i>Location : New Hardware And Localized Areas Of New Timber Members</i>								
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Isolated Areas On Timber Framework</i>								
<i>Explanation : Splitting</i>								
Not Accessible	10%							
Movable Ramps								
Bearings								
Steel	10%			2037				**
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : At All Steel Bearing Surfaces</i>								
<i>Explanation : Corrosion</i>								
Timber	40%			2037				**
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Timber Bearing Surfaces</i>								
<i>Explanation : Abrasion/ Wearing</i>								
Not Accessible	50%							
Deck and Railing								
Timber Deck on Steel	50%			2043				**
<i>Other Observation, Extent : Light, Area Affected : 50%</i>								
<i>Location : Steel Deck Framing And Isolated On Rail</i>								
<i>Explanation : Corrosion</i>								
Not Accessible	50%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : EAST 34TH ST FERRY LANDING BARGES
Address : EAST RIVER, E 34TH STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0199.000 / 14193 **Yr Built/Renovated** :
Area Sq Ft : 8,175 **Project Type** : FERRIES
Date of Survey : 11-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 967 **Lot** : 50 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$105,300	\$1,093,200
Total	\$105,300	\$1,093,200
Importance Code A	\$105,300	\$1,093,200
Total	\$105,300	\$1,093,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$18,700	\$700	\$11,000	\$22,500
Total	\$18,700	\$700	\$11,000	\$22,500
Importance Code A	\$10,200		\$4,900	\$21,800
Importance Code B	\$200	\$200	\$5,800	\$200
Importance Code C	\$8,200	\$400	\$400	\$400
Total	\$18,700	\$700	\$11,000	\$22,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
 Estimates are rounded to the nearest hundred dollars.
 Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
 ** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 34TH ST FERRY LANDING BARGES
Asset # : 14193

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Access Walkways								
Deck								
Aluminum	100%			2055	**			
Gangways								
Aluminum	100%			2055	**	1-3	\$19,000	
<i>Recent Repair Evident, Extent : N/A, Area Affected : 5%</i>								
<i>Location : Southwest Handrail Has Been Repaired</i>								
Floating Docks								
Anchor Piles								
Steel	50%			2055	**	3-5	\$15,400	
<i>Missing Coating, Extent : Light, Area Affected : 15%</i>								
<i>Location : In Tidal Zone</i>								
Steel	5%	4+	\$8,000	2065	**	3-5	\$1,500	
<i>Worn, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Pile Guide Pads</i>								
Not Accessible	45%							
Fenders								
Rubber	77%			2033	\$26,800	1-2	\$3,100	
<i>Worn, Extent : Light, Area Affected : 15%</i>								
<i>Location : At Slips S.1, S.2, S.3 And N.2</i>								
Rubber	18%	4+	\$6,300	2035	\$6,300	1-2	\$600	
<i>Worn, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Moderate Wear At Slip N.1 And N.3</i>								
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Bent Steel Bracket At Slip S.2</i>								
<i>Explanation : Impact Damage</i>								
Rubber	5%	Now	\$1,700	2035	\$1,700	1-2	\$200	
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : At Slip S.1 D Fender</i>								
Barge								
Steel	20%			2044	**	5	\$7,500	
<i>Corrosion, Extent : Light, Area Affected : 15%</i>								
<i>Location : All Surfaces</i>								
Steel	10%	4+	\$105,300	2044	**	5	\$1,900	
<i>Corrosion, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Intermittent Locations Throughout The Pedestrian Steel Access Walkway</i>								
Not Accessible	70%							
Protective Structure								
Donut Fender								
Steel/Rubber	40%			2033	\$99,600			
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Tidal Zone, Along The Height Of The Donut Fender</i>								
Not Accessible	60%							
Deck Elements								
Railing								
Steel	100%			2033	\$551,500			
Electrical								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
EAST 34TH ST FERRY LANDING BARGES
Asset # : 14193

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Electrical								
Conduit								
Steel	100%			2033	\$442,000			
Lighting Fixture								
Incandescent	89%			2029	\$17,600			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 6 Lights At Slip A, And 3 At Slip B</i>								
<i>Explanation : 9 Lights Total</i>								
Incandescent	11%	Now	\$2,200	2030	\$2,200			
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : One Broken Light</i>								
Movable Ramps								
Deck and Railing								
Steel	100%			2044		**		
<i>Recent Repair Evident, Extent : N/A, Area Affected : 2%</i>								
<i>Location : South Side Loader Ramp Repaired</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : HART ISLAND FERRY DOCK
Address : HART ISLAND
Borough : BRONX **Agency's Number** : N/A
Program / Asset # : DOT0193.000 / 13892 **Yr Built/Renovated** :
Area Sq Ft : 1,600 **Project Type** : FERRIES
Date of Survey : 08-Dec-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 5649 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$471,600	\$276,000
Total	\$471,600	\$276,000
Importance Code A	\$471,600	\$276,000
Total	\$471,600	\$276,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$107,100			\$9,000
Total	\$107,100			\$9,000
Importance Code A	\$107,100			\$9,000
Total	\$107,100			\$9,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
HART ISLAND FERRY DOCK
Asset # : 13892

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Access Walkways								
Deck								
Timber	100%			2029	\$217,900	5	\$3,600	
<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 40%</i>								
<i>Location : Top Of Deck</i>								
Pile Caps								
Timber	100%			2054	**	4	\$3,500	
<i>Splitting, Extent : Light, Area Affected : 5%</i>								
<i>Location : Isolated Locations</i>								
Piles and Bracing								
Timber	90%			2054	**	4-5	\$16,100	
<i>Splitting, Extent : Light, Area Affected : 20%</i>								
<i>Location : Isolated Locations</i>								
Timber	10%	4+	\$10,800	2054	**	4-5	\$900	
<i>Missing Connections, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Fishplate On South Side</i>								
<i>Splitting, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Northwest Corner</i>								
Deck Elements								
Railing								
Steel	25%			2032				
No Component	75%							
Fender								
Facing								
Timber	30%			2032	\$28,300			
<i>Other Observation, Extent : Light, Area Affected : 15%</i>								
<i>Location : Band Across Facing Due To Ferry Berthing</i>								
<i>Explanation : Abrasion</i>								
Timber	10%	Now	\$9,400	2034	\$9,400			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : At Waterline Throughout Fender Rack</i>								
<i>Explanation : Broken Fender Piles</i>								
No Component	50%							
Not Accessible	10%							
Piles								
Timber	35%			2035	\$276,000			
<i>Recent Repair Evident, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Both Sides Of Fender Rack</i>								
Timber	15%	Now	\$118,300	2039	**			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : At The Waterline Throughout Fender Rack</i>								
<i>Explanation : Broken Fender Piles</i>								
Not Accessible	50%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
HART ISLAND FERRY DOCK
Asset # : 13892

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Fender								
Wales and Chocks								
Timber	65%			2038		**		
Timber	10%	0-2	\$75,600	2039		**		
<i>Other Observation, Extent : Severe, Area Affected : 75%</i>								
<i>Location : Various Isolated Locations Along North And South Fender System</i>								
<i>Explanation : Rotting And Splitting</i>								
Not Accessible	25%							
Gallows Frames								
Tower Frames								
Steel	25%			2043		**		
<i>Other Observation, Extent : Light, Area Affected : 25%</i>								
<i>Location : Isolated Locations At Steel Framework</i>								
<i>Explanation : Corrosion And Coating Loss</i>								
Steel	25%	4+	\$59,800	2043		**		
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Above Mean Low Water</i>								
<i>Explanation : Corrosion</i>								
Timber	49%			2043		**		
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : At Southwest Corner And Isolated Locations</i>								
<i>Explanation : Cracking, Splitting</i>								
Timber	1%	Now	\$2,400	2049		**		
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : 13 Feet Of North Catwalk And 13 Feet Of South Catwalk</i>								
<i>Explanation : Two Missing Planks Of Timber Deck Catwalk</i>								
Movable Ramps								
Bearings								
Steel	50%	2-4	\$48,100	2043		**		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : At All Bearing Locations</i>								
<i>Explanation : Corrosion</i>								
Timber	50%	2-4	\$27,000	2043		**		
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Along All Timber Bearing Elements</i>								
<i>Explanation : Abrasion And Leaning</i>								
Deck and Railing								
Timber Deck on Steel	50%			2043		**		
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Timber Deck And Timber Stringers</i>								
<i>Explanation : Weathering</i>								
Timber Deck on Steel	5%	4+	\$7,700	2043		**		
<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>								
<i>Location : Steel Hardware At Timber Beams Beneath Timber Deck</i>								
<i>Explanation : Corrosion</i>								
Not Accessible	45%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ST. GEORGE FERRY TERMINAL FERRY SLIP 1
Address : 1 BAY STREET
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0192.010 / 13894 **Yr Built/Renovated** :
Area Sq Ft : 4,000 **Project Type** : FERRIES
Date of Survey : 19-Apr-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 2 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$62,300	\$13,659,100
Total	\$62,300	\$13,659,100
Importance Code A	\$62,300	\$13,659,100
Total	\$62,300	\$13,659,100

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$5,900	\$700	\$100	\$200
Total	\$5,900	\$700	\$100	\$200
Importance Code A	\$5,700			
Importance Code B	\$200	\$700	\$100	\$200
Total	\$5,900	\$700	\$100	\$200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL FERRY SLIP 1
Asset # : 13894

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Access Walkways								
Gangways								
Aluminum	50%			2054	**	1-3	\$2,300	
	<i>Other Observation, Extent : Light, Area Affected : 5%</i>							
	<i>Location : At Hinge</i>							
	<i>Explanation : Corrosion</i>							
Timber	50%			2032	\$8,300	1-3	\$1,000	
	<i>Other Observation, Extent : Light, Area Affected : 50%</i>							
	<i>Location : Throughout On The Walking Surface</i>							
	<i>Explanation : Wearing</i>							
Deck Elements								
Railing								
Timber	50%			2028				
No Component	50%							
Fender								
Facing								
Timber	97%			2032	\$183,300			
	<i>Other Observation, Extent : Light, Area Affected : 30%</i>							
	<i>Location : Above Tidal Zone Due To Ferry Berthing</i>							
	<i>Explanation : Abrasion</i>							
Timber	3%	Now	\$5,700	2034	\$5,700			
	<i>Other Observation, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : Both Sides Of Fender Rack</i>							
	<i>Explanation : Broken / Missing</i>							
Piles								
Timber	48%			2035	\$1,494,000			
Timber	2%	Now	\$62,300	2039	**			
	<i>Other Observation, Extent : Severe, Area Affected : 100%</i>							
	<i>Location : Both Sides Of Slip Fender Racks</i>							
	<i>Explanation : Broken</i>							
Not Accessible	50%							
Wales and Chocks								
Timber	100%			2035	\$11,976,200			
Gallows Frames								
Tower Frames								
Timber	60%			2043	**			
Not Accessible	40%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ST. GEORGE FERRY TERMINAL FERRY SLIPS 3 - 6
Address : 1 BAY STREET
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0192.030 / 13896 **Yr Built/Renovated** :
Area Sq Ft : 8,600 **Project Type** : FERRIES
Date of Survey : 19-Apr-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 2 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$4,737,200	\$8,379,300
Total	\$4,737,200	\$8,379,300
Importance Code A	\$4,737,200	\$8,379,300
Total	\$4,737,200	\$8,379,300

EXPENSE

Total

Importance Code

Total



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL FERRY SLIPS 3 - 6

Asset # : 13896

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Access Walkways								
Deck								
Timber	100%			2032		5		
<i>Aging, Extent : Light, Area Affected : 15%</i>								
<i>Location : Throughout Walkway Atop Ferry Slip Walls</i>								
Piles and Bracing								
Steel	70%			2054	**	5-10		
<i>Corrosion, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Cross Bracing</i>								
<i>Missing Coating, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout All Slips Upper And Lower</i>								
<i>Other Observation, Extent : Light, Area Affected : 100%</i>								
<i>Location : Concrete Encasements</i>								
<i>Explanation : Erosion</i>								
Not Accessible	30%							
Deck Elements								
Railing								
Timber	100%			2028				
<i>Aging, Extent : Light, Area Affected : 100%</i>								
<i>Location : Handrail And Walkway Along Perimeter Of Slips</i>								
Electrical								
Lighting Fixture								
Incandescent	100%			2028	\$74,600			
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : 24 Lights Total Inside Of Terminal And 10 Navigational Lights At The Ends Of Slips</i>								
<i>Explanation : Light Count</i>								
Fender								
Facing								
Timber	85%			2029	\$1,003,800			
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i>								
<i>Location : Above Tidal Zone Due To Ferry Berthing Along All Slips</i>								
<i>Explanation : Abrasion</i>								
Timber	5%	Now	\$59,000	2034	\$59,000			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Most Severe At Inshore Ends Of Slip And Offshore End Of Slip 3</i>								
<i>Explanation : Broken / Missing</i>								
Under Construction	10%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : Wests Side Of Slip 5</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL FERRY SLIPS 3 - 6

Asset # : 13896

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Fender								
Piles								
Timber	10%	0-2	\$1,867,500	2039				**
<i>Other Observation, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Offshore End Of Slip 3, Various Other Piles At All Slips</i>								
<i>Explanation : Broken</i>								
Timber	50%	4+	\$1,556,200	2039				**
<i>Other Observation, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : At Top Of Piles</i>								
<i>Explanation : Splitting</i>								
Not Accessible	30%							
Under Construction	10%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : Slip 5</i>								
Wales and Chocks								
Timber	55%			2035	\$8,320,300			
<i>Other Observation, Extent : Light, Area Affected : 25%</i>								
<i>Location : Isolated Locations</i>								
<i>Explanation : Rotting / Splitting</i>								
Not Accessible	35%							
Under Construction	10%							
<i>Other Observation, Extent : N/A, Area Affected : 0%</i>								
<i>Location :</i>								
<i>Explanation : Slip 5</i>								
Gallows Frames								
Tower Frames								
Steel	100%			2043				**
<i>Other Observation, Extent : Light, Area Affected : 5%</i>								
<i>Location : Isolated Locations At All Slips</i>								
<i>Explanation : Coating Loss And Corrosion</i>								
Movable Ramps								
Bearings								
Not Accessible	100%							
Deck and Railing								
Steel	70%	4+	\$176,000	2043				**
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Ramp Surfaces Which Are 50/50 Asphalt/Steel With Composite Surface Plates</i>								
<i>Explanation : Cracking / Coating Loss</i>								
Not Accessible	30%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ST. GEORGE FERRY TERMINAL SLIP 7
Address : 1 BAY STREET
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0192.040 / 13897 **Yr Built/Renovated** :
Area Sq Ft : 4,500 **Project Type** : FERRIES
Date of Survey : 25-May-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 2 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$252,600	\$1,716,300
Total	\$252,600	\$1,716,300
Importance Code A	\$252,600	\$1,447,200
Importance Code C		\$269,100
Total	\$252,600	\$1,716,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$17,500	\$7,500	\$12,700	\$26,200
Total	\$17,500	\$7,500	\$12,700	\$26,200
Importance Code A	\$17,500	\$3,400	\$12,700	\$26,200
Importance Code C		\$4,000		
Total	\$17,500	\$7,500	\$12,700	\$26,200



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL SLIP 7
Asset # : 13897

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Access Walkways								
Deck								
Concrete	35%			2037	**	5	\$5,900	
<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Walking Surface Of The Concrete Deck</i>								
Timber	5%			2032	\$54,700	5	\$900	
Not Accessible	60%							
Pile Caps								
Concrete	10%			2054	**	5	\$2,300	
<i>Cracking, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Shotcrete Coating At All Pile Caps</i>								
Not Accessible	90%							
Piles and Bracing								
Concrete Encased Timber	45%			2054	**			
<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 5%</i>								
<i>Location : Erosion In The Tidal Zone</i>								
Steel	5%	Now	\$84,200	2064	**	5	\$200	
<i>Corrosion, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Steel Bracing Mostly On North End</i>								
Steel	10%	4+	\$168,400	2064	**	5	\$300	
<i>Corrosion, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Steel Bracing</i>								
Not Accessible	40%							
Launch/Haulout								
Piles and Bracing								
Steel	60%			2054	**	5-10	\$985,500	
Not Accessible	40%							
Protective Structure								
Pile Cluster								
Timber	60%			2035	\$215,200	4-10	\$66,000	
Not Accessible	40%							
Deck Elements								
Railing								
Steel	80%			2032	\$220,600			
<i>Missing Coating, Extent : Light, Area Affected : 5%</i>								
<i>Location : Entire Length Of Handrail</i>								
Steel	5%	Now	\$13,800	2034	\$13,800			
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : At West Face Under Building With Missing Section</i>								
Timber	5%			2028	\$3,900			
Fencing	10%	2-4	\$3,700	2039	**	3		
<i>Corrosion, Extent : Severe, Area Affected : 10%</i>								
<i>Location : At Base Of Fence Posts</i>								
Electrical								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL SLIP 7
Asset # : 13897

Marinas/Docks	Current Repair		Future Replacement		Maintenance		Priority	
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Electrical								
Lighting Fixture								
Incandescent	100%			2028	\$8,800			
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : One Light Fixture At Asset</i>							
	<i>Explanation : Light Fixture</i>							
Fender								
Facing								
Timber	10%			2032	\$23,600			
	<i>Other Observation, Extent : Moderate, Area Affected : 25%</i>							
	<i>Location : In Tidal Zone At North Access Walkway</i>							
	<i>Explanation : Abrasion</i>							
No Component	90%							
Piles								
Timber	10%			2035	\$197,500			
No Component	85%							
Not Accessible	5%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ST. GEORGE FERRY TERMINAL SLIP 8 AND 69TH STREET SLIP
Address : 1 BAY STREET
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0192.050 / 13898 **Yr Built/Renovated** :
Area Sq Ft : 850 **Project Type** : FERRIES
Date of Survey : 19-Apr-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 2 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$1,201,200	\$10,377,200
Total	\$1,201,200	\$10,377,200
Importance Code A	\$1,086,500	\$9,946,800
Importance Code C	\$114,800	\$430,400
Total	\$1,201,200	\$10,377,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$27,200	\$1,800	\$13,400	\$3,000
Total	\$27,200	\$1,800	\$13,400	\$3,000
Importance Code A	\$27,200		\$10,600	\$2,900
Importance Code B	\$100	\$1,800	\$100	\$100
Importance Code C			\$2,700	
Total	\$27,200	\$1,800	\$13,400	\$3,000



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL SLIP 8 AND 69TH STREET SLIP
Asset # : 13898

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Access Walkways								
Deck								
Steel	20%	4+	\$8,700	2054	**			
<i>Corrosion, Extent : Light, Area Affected : 80%</i>								
<i>Location : Slip 8</i>								
<i>Missing Coating, Extent : Light, Area Affected : 80%</i>								
<i>Location : Slip 8</i>								
Timber	60%			2029	\$87,500	5	\$1,500	
<i>Surface Wearing/Scaling, Extent : Light, Area Affected : 100%</i>								
<i>Location : 69th Street Slip</i>								
Timber	20%	2-4	\$17,500	2032	\$29,200	5	\$200	
<i>Surface Wearing/Scaling, Extent : Severe, Area Affected : 80%</i>								
<i>Location : South End Of 69th Street Slip</i>								
Gangways								
Aluminum	100%			2054	**	1-3	\$5,900	
Piles and Bracing								
Timber	25%			2054	**	4-5	\$3,000	
<i>Rotting/Splitting, Extent : Light, Area Affected : 30%</i>								
<i>Location : 69th Street Slip In Tidal Zone</i>								
Timber	20%	4+	\$72,000	2064	**	4-5	\$1,200	
<i>Marine Borer Infestation, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Below Bracing At Mean Low Water</i>								
Timber	25%	Now	\$90,000	2064	**	4-5	\$1,500	
<i>Broken, Extent : Severe, Area Affected : 50%</i>								
<i>Location : Southwest Pile</i>								
Not Accessible	30%							
Protective Structure								
Pile Cluster								
Timber	20%			2032	\$143,500	4-10	\$41,300	
<i>Splitting, Extent : Light, Area Affected : 25%</i>								
<i>Location : Tops Of Piles At Isolated Locations</i>								
Timber	40%	Now	\$114,800	2035	\$286,900	4	\$10,800	
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Two Broken Clusters At Offshore End Of 69th Street Slip Fender Rack</i>								
Not Accessible	40%							
Deck Elements								
Railing								
Steel	30%			2032	\$17,400			
<i>Corrosion, Extent : Light, Area Affected : 20%</i>								
<i>Location : Throughout Railing</i>								
Timber	65%			2028	\$10,600			
Timber	5%	Now	\$800	2029	\$800			
<i>Missing Components, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Missing And Broken Railing At End Of Access Walkway</i>								
Fender								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL SLIP 8 AND 69TH STREET SLIP
Asset # : 13898

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Fender								
Piles								
Timber	50%	Now	\$415,000	2035	\$4,150,000			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout All Sections Of The Fender Rack</i>								
<i>Explanation : Broken</i>								
Timber	30%			2035	\$2,490,000			
<i>Other Observation, Extent : Light, Area Affected : 10%</i>								
<i>Location : Tops Of Piles At Isolated Locations</i>								
<i>Explanation : Splitting</i>								
Not Accessible	20%							
Wales and Chocks								
Timber	50%	Now	\$327,800	2035	\$1,638,800			
<i>Other Observation, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Throughout All Sections Of The Fender Rack</i>								
<i>Explanation : Broken</i>								
Timber	50%			2032	\$1,638,800			
Gallows Frames								
Tower Frames								
Timber	20%	2-4	\$94,100	2049		* *		
<i>Other Observation, Extent : Moderate, Area Affected : 50%</i>								
<i>Location : Isolated Elements At Both Slips</i>								
<i>Explanation : Splitting/ Rotting</i>								
Timber	80%			2043		* *		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : ST. GEORGE FERRY TERMINAL SLIPS B-1, B-2, AND PHANTOM
Address : 1 BAY STREET
Borough : STATEN ISLAND **Agency's Number** : N/A
Program / Asset # : DOT0192.060 / 13899 **Yr Built/Renovated** :
Area Sq Ft : 1,200 **Project Type** : FERRIES
Date of Survey : 19-Apr-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 1 **Lot** : 70 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$442,800	\$1,433,200
Total	\$442,800	\$1,433,200
Importance Code A	\$347,200	\$1,361,500
Importance Code C	\$95,600	\$71,700
Total	\$442,800	\$1,433,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$101,800	\$2,800	\$18,600	\$100
Total	\$101,800	\$2,800	\$18,600	\$100
Importance Code A	\$101,700		\$18,500	
Importance Code B	\$100	\$1,400	\$100	\$100
Importance Code C		\$1,300		
Total	\$101,800	\$2,800	\$18,600	\$100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL SLIPS B-1, B-2, AND PHANTOM
Asset # : 13899

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Access Walkways								
Deck								
Concrete	100%			2043	**	5	\$4,500	
<i>Cracking, Extent : Light, Area Affected : 10%</i>								
<i>Location : All Slips</i>								
<i>Spalling, Extent : Light, Area Affected : 2%</i>								
<i>Location : Phantom Slip</i>								
Gangways								
Aluminum	100%			2054	**	1-3	\$4,700	
Piles and Bracing								
Steel	25%	4+	\$22,500	2054	**	5	\$200	
<i>Corrosion, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : In Tidal Zone And Splash Zone At All Slips</i>								
<i>Missing Coating, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : In Tidal Zone And Splash Zone At All Slips</i>								
Not Accessible	75%							
Protective Structure								
Pile Cluster								
Timber	30%			2035	\$71,700	4-10	\$22,000	
Timber	40%	Now	\$95,600	2039	**	4	\$3,600	
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : 30 Broken Piles Across Four Pile Clusters</i>								
Not Accessible	30%							
Deck Elements								
Railing								
Timber	100%			2028	\$16,300			
<i>Wearing, Extent : Light, Area Affected : 40%</i>								
<i>Location : Phantom Slip</i>								
Fender								
Facing								
Timber	100%	2-4	\$47,200	2034	\$47,200			
<i>Other Observation, Extent : Moderate, Area Affected : 75%</i>								
<i>Location : Band Of Abrasion Due To Ferry Berthing</i>								
<i>Explanation : Abrasion</i>								
Piles								
Steel	50%	Now	\$347,200	2039	**			
<i>Broken, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Broken Piles Due To Corrosion At Hardware Holes At All Fender Panels</i>								
Timber	10%			2035	\$32,400			
Not Accessible	40%							
Wales and Chocks								
Timber	100%			2035	\$1,361,500			
<i>Other Observation, Extent : Light, Area Affected : 25%</i>								
<i>Location : All Slips</i>								
<i>Explanation : Splitting</i>								
Gallows Frames								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
ST. GEORGE FERRY TERMINAL SLIPS B-1, B-2, AND PHANTOM

Asset # : 13899

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Gallows Frames								
Tower Frames								
Steel	67%	4+	\$32,000	2043		* *		
	<i>Other Observation, Extent : Light, Area Affected : 30%</i>							
	<i>Location : Support Brackets At B2 North And B2 South</i>							
	<i>Explanation : Corrosion</i>							
Timber	33%			2043		* *		
Movable Ramps								
Bearings								
Steel	100%			2043		* *		
Deck and Railing								
Steel	100%			2043		* *		
	<i>Other Observation, Extent : Light, Area Affected : 30%</i>							
	<i>Location : B2 North And B2 South</i>							
	<i>Explanation : Coating Loss And Corrosion</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WALL STREET FERRY PIER SLIPS A AND C,NORTH SIDE PIER 11
Address : PIER 11, GOUVERNEUR LANE EAST RIVER
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0200.000 / 14194 **Yr Built/Renovated** :
Area Sq Ft : 10,700 **Project Type** : FERRIES
Date of Survey : 13-Sep-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 36 **Lot** : 18 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks		\$303,300
Total		\$303,300
Importance Code A		\$303,300
Total		\$303,300

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$41,800	\$500	\$8,600	\$32,500
Total	\$41,800	\$500	\$8,600	\$32,500
Importance Code A	\$37,400		\$2,800	\$31,700
Importance Code B	\$4,100	\$200	\$5,400	\$500
Importance Code C	\$400	\$200	\$400	\$200
Total	\$41,800	\$500	\$8,600	\$32,500



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WALL STREET FERRY PIER SLIPS A AND C, NORTH SIDE PIER 11
Asset # : 14194

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Access Walkways								
Deck								
Aluminum	10%			2055	**			
Steel	80%			2055	**			
<i>Corrosion, Extent : Light, Area Affected : 5%</i>								
<i>Location : On The Bottom Of Raised Platforms On Barge</i>								
Steel	10%	4+	\$32,800	2055	**			
<i>Corrosion, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : On Steel Structure Supporting Gangway North Side Of Pier 11 And On Steel Railings</i>								
Gangways								
Aluminum	95%			2055	**	1-3	\$17,800	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Throughout</i>								
<i>Explanation : 24 Built In Lights, 12 On Each Side</i>								
Aluminum	5%	4+	\$3,900	2065	**	1-3	\$900	
<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Non Slip Coating</i>								
Floating Docks								
Anchor Piles								
Steel	50%			2055	**	3-5	\$8,800	
<i>Corrosion, Extent : Severe, Area Affected : 5%</i>								
<i>Location : On Pile Caps, Southwest Pile Cap Has Corrosion Holes</i>								
<i>Missing Coating, Extent : Light, Area Affected : 10%</i>								
<i>Location : In Tidal Zone And Along Pile Guide Area</i>								
Not Accessible	50%							
Fenders								
Rubber	100%			2030		1-2	\$2,900	
<i>Worn, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : All Fenders</i>								
Barge								
Steel	40%			2044	**	5	\$10,800	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Isolated On All Barge Surfaces And Sides</i>								
Not Accessible	60%							
Protective Structure								
Donut Fender								
Steel/Rubber	50%			2033			\$31,100	
Not Accessible	50%							
Deck Elements								
Railing								
Aluminum	100%			2033			\$140,000	
Electrical								
Conduit								
Steel	100%			2033			\$163,300	
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : At Each Slip A And Slip C</i>								
<i>Explanation : 240 Feet Of Conduit</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WALL STREET FERRY PIER SLIPS A AND C,NORTH SIDE PIER 11
Asset # : 14194

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Electrical								
Lighting Fixture								
Incandescent	100%			2029	\$26,300			
	<i>Other Observation, Extent : N/A, Area Affected : 100%</i>							
	<i>Location : 6 Lights On Each Barge (12 Total)</i>							
	<i>Explanation : Light Count</i>							
Movable Ramps								
Deck and Railing								
Aluminum	95%			2044			**	
	<i>Corrosion, Extent : Light, Area Affected : 25%</i>							
	<i>Location : Mechanical Elements</i>							
Aluminum	5%	4+	\$4,600	2050			**	
	<i>Broken, Extent : Severe, Area Affected : 10%</i>							
	<i>Location : Broken Welds At Bow Loader Ramp, Landing A West Slip And Landing C East Slip</i>							
	<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 25%</i>							
	<i>Location : Non-slip Coating</i>							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WALL STREET FERRY PIER SLIPS B, D SOUTH SIDE PIER 11
Address : PIER 11, GOUVERNEUR LANE EAST RIVER
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0200.010 / 14265 **Yr Built/Renovated** :
Area Sq Ft : 7,560 **Project Type** : FERRIES
Date of Survey : 19-Sep-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 36 **Lot** : 18 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$75,600	\$241,000
Total	\$75,600	\$241,000
Importance Code A	\$75,600	\$241,000
Total	\$75,600	\$241,000

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$5,500	\$400	\$5,400	\$28,400
Total	\$5,500	\$400	\$5,400	\$28,400
Importance Code A	\$2,500		\$1,700	\$27,900
Importance Code B	\$2,600	\$100	\$3,400	\$300
Importance Code C	\$400	\$200	\$400	\$200
Total	\$5,500	\$400	\$5,400	\$28,400



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WALL STREET FERRY PIER SLIPS B, D SOUTH SIDE PIER 11
Asset # : 14265

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	
Access Walkways								
Deck								
Aluminum	5%			2055	**			
Concrete	5%			2044	**	5		
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Composite Deck On Slip B</i>								
<i>Explanation : Composite Deck</i>								
Steel	90%			2055	**			
Gangways								
Aluminum	95%			2055	**	1-3	\$11,200	
Aluminum	5%	4+	\$2,400	2065	**	1-3	\$600	
<i>Surface Wearing/Scaling, Extent : Moderate, Area Affected : 25%</i>								
<i>Location : Non-slip Coating</i>								
Floating Docks								
Anchor Piles								
Steel	40%			2055	**	3-5	\$5,300	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Above Mean Low Water Elevation And Along Pile Guides</i>								
<i>Missing Coating, Extent : Moderate, Area Affected : 10%</i>								
<i>Location : Above Mean Low Water Elevation</i>								
<i>Missing Components, Extent : Light, Area Affected : 40%</i>								
<i>Location : Missing Pile Caps On 4 Piles At Slip B</i>								
Not Accessible	60%							
Fenders								
Rubber	100%			2030		1-2	\$3,000	
<i>Worn, Extent : Moderate, Area Affected : 100%</i>								
<i>Location : Slip D Fenders</i>								
Barge								
Steel	44%			2044	**	5	\$11,900	
<i>Corrosion, Extent : Light, Area Affected : 10%</i>								
<i>Location : Isolated On Barge Surface At Slip D, And Along Sides Of Barges</i>								
Steel	1%	0-2	\$37,800	2050	**	5	\$100	
<i>Displaced Component, Extent : Severe, Area Affected : 100%</i>								
<i>Location : Broken Safety Ladder Connections, Both Slips</i>								
Steel	5%	4+	\$37,800	2044	**	5	\$700	
<i>Corrosion, Extent : Moderate, Area Affected : 75%</i>								
<i>Location : Isolated On Barge Surface At Slip D, And Along Sides Of Barges, Severe At South Side Of Slip D</i>								
Not Accessible	50%							
Protective Structure								
Fenders								
Steel/Rubber	100%			2034				
<i>Other Observation, Extent : N/A, Area Affected : 100%</i>								
<i>Location : Composite Fender Rack Between Slips B And D</i>								
<i>Explanation : Fender Rack</i>								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WALL STREET FERRY PIER SLIPS B, D SOUTH SIDE PIER 11
Asset # : 14265

Marinas/Docks		Current Repair		Future Replacement		Maintenance			
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Protective Structure									
Donut Fender									
	Steel/Rubber	40%			2033	\$49,800			
	Not Accessible	60%							
Deck Elements									
Railing									
	Aluminum	100%			2033	\$162,900			
Electrical									
Conduit									
	Steel	100%			2033	\$78,100			
Lighting Fixture									
	Incandescent	100%			2029	\$21,900			
				<i>Other Observation, Extent : N/A, Area Affected : 100%</i>					
				<i>Location : 5 Lights At Each Slip (10 Total)</i>					
				<i>Explanation : Light Count</i>					
Movable Ramps									
Deck and Railing									
	Aluminum	95%			2044				* *
	Aluminum	5%	4+	\$2,500	2050				* *
				<i>Cracked Weld, Extent : Moderate, Area Affected : 25%</i>					
				<i>Location : Broken Welds On Bow Loading Ramps</i>					

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WEST MIDTOWN FERRY TERMINAL PIER 79 NORTH RIVER
Address : WEST 39TH ST AND 12TH AVE @THE HUDSON RIVER
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0201.000 / 14195 **Yr Built/Renovated** : 2005 /
Area Sq Ft : 19,512 **Project Type** : FERRIES
Date of Survey : 23-Oct-2023 **Landmark Status** : NONE
Areas Surveyed :
Block : 665 **Lot** : 14 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$412,500	\$1,049,200
Total	\$412,500	\$1,049,200
Importance Code A	\$303,200	\$903,500
Importance Code C	\$109,300	\$145,700
Total	\$412,500	\$1,049,200

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$39,100	\$2,100	\$18,000	\$33,100
Total	\$39,100	\$2,100	\$18,000	\$33,100
Importance Code A	\$38,100		\$600	\$30,900
Importance Code B	\$700	\$700	\$15,500	\$700
Importance Code C	\$300	\$1,500	\$1,800	\$1,500
Total	\$39,100	\$2,100	\$18,000	\$33,100



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WEST MIDTOWN FERRY TERMINAL PIER 79 NORTH RIVER

Asset # : 14195

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Access Walkways								
Deck								
Steel	15%			2055	**			
No Component	85%							
Gangways								
Aluminum	100%			2055	**	1-3	\$51,100	
Piles and Bracing								
Steel	50%			2055	**	5-10	\$1,100	
		<i>Corrosion, Extent : Moderate, Area Affected : 30%</i>						
		<i>Location : Splash Zone</i>						
		<i>Missing Coating, Extent : Moderate, Area Affected : 30%</i>						
		<i>Location : Splash Zone</i>						
Not Accessible	50%							
Floating Docks								
Anchor Piles								
Composite	5%	0-2	\$700	2065	**			
		<i>Missing Components, Extent : Moderate, Area Affected : 5%</i>						
		<i>Location : Missing Hardware At North Pile Guide Buffer Pads</i>						
Steel	45%			2055	**	3-5	\$2,000	
		<i>Corrosion, Extent : Light, Area Affected : 15%</i>						
		<i>Location : Tidal Zone</i>						
		<i>Missing Coating, Extent : Light, Area Affected : 20%</i>						
		<i>Location : Tidal Zone</i>						
Not Accessible	50%							
Fenders								
Rubber	75%	4+	\$109,300	2035	\$109,300	1-2	\$11,000	
		<i>Worn, Extent : Severe, Area Affected : 50%</i>						
		<i>Location : Bow Loader</i>						
Rubber	25%			2033	\$36,400	1-2	\$4,200	
Railing								
Steel	100%			2033	\$521,400			
Barge								
Steel	43%			2044	**	5	\$61,800	
		<i>Corrosion, Extent : Light, Area Affected : 15%</i>						
		<i>Location : Sides Of Barges</i>						
Steel	5%	4+	\$100,600	2044	**	5	\$3,600	
		<i>Corrosion, Extent : Severe, Area Affected : 10%</i>						
		<i>Location : Access Hatches</i>						
Steel	2%	0-2	\$40,200	2044	**	5	\$1,400	
		<i>Worn, Extent : Moderate, Area Affected : 25%</i>						
		<i>Location : Torn Rubber Buffers At Reinforced Connection Between North And Center Barge</i>						
		<i>Other Observation, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Pin Connections At North And South Fingers</i>						
		<i>Explanation : Bent Connection Pins</i>						
Not Accessible	50%							
Protective Structure								

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WEST MIDTOWN FERRY TERMINAL PIER 79 NORTH RIVER

Asset # : 14195

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System	Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost
Protective Structure								
Donut Fender								
	Steel/Rubber	15%	4+	\$37,400	2035	\$37,400		
		<i>Other Observation, Extent : Moderate, Area Affected : 20%</i>						
		<i>Location : Northernmost Of Four Donut Fenders</i>						
		<i>Explanation : Impact Damage</i>						
	Steel/Rubber	45%			2033	\$112,100		
	Not Accessible	40%						
Electrical								
Conduit								
	Steel	100%			2033	\$232,700		
Lighting Fixture								
	Incandescent	100%			2029	\$162,400		
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Throughout</i>						
		<i>Explanation : 74 Canopy Light Fixtures</i>						
Movable Ramps								
Deck and Railing								
	Steel	100%			2044	* *		

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

Print Date : 07-Oct-2024

DEPARTMENT OF TRANSPORTATION - FY 2025

Asset Name : WHITEHALL FERRY TERMINAL FERRY SLIPS 1 - 3
Address : 4 WHITEHALL STREET
Borough : MANHATTAN **Agency's Number** : N/A
Program / Asset # : DOT0190.000 / 13889 **Yr Built/Renovated** :
Area Sq Ft : 7,650 **Project Type** : FERRIES
Date of Survey : 30-Nov-2022 **Landmark Status** : NONE
Areas Surveyed :
Block : 2 **Lot** : 1 **BIN** :

CAPITAL	FY 2026 - 2029	FY 2030 - 2035
Marinas/Docks	\$2,680,000	\$26,242,400
Total	\$2,680,000	\$26,242,400
Importance Code A	\$2,680,000	\$26,242,400
Total	\$2,680,000	\$26,242,400

EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Marinas/Docks	\$34,900			
Total	\$34,900			
Importance Code A	\$34,900			
Total	\$34,900			



Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars. Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.
**** Replacement cost estimated to be beyond ten years is not included in this report.**

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL FERRY SLIPS 1 - 3

Asset # : 13889

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Access Walkways								
Deck								
Concrete	45%			2043	**	5		
		<i>Cracking, Extent : Light, Area Affected : 5%</i>						
		<i>Location : Isolated Locations In Deck Surface</i>						
Timber	5%			2032		5		
Not Accessible	50%							
Piles and Bracing								
Steel	10%			2054	**	5-10		
		<i>Corrosion, Extent : Light, Area Affected : 30%</i>						
		<i>Location : Above Mean Low Water</i>						
Not Accessible	90%							
Electrical								
Lighting Fixture								
Sodium	9%	Now	\$8,500	2029	\$14,200			
		<i>Broken, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Three Lights Broken At Slip 2 And Two Lights Broken At Slip 3, 5 Total</i>						
Sodium	35%			2027	\$55,300			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : Eight Lights At Slip 1, Five Lights At Slip 2 And Six Lights At Slip 3, 19 Total</i>						
		<i>Explanation : Light Count</i>						
LED	56%			2032	\$119,500			
		<i>Other Observation, Extent : N/A, Area Affected : 100%</i>						
		<i>Location : 10 Lights At Each Slip, 30 Total</i>						
		<i>Explanation : Light Count</i>						
Fender								
Facing								
Timber	10%	2-4	\$118,100	2034	\$118,100			
		<i>Other Observation, Extent : Moderate, Area Affected : 40%</i>						
		<i>Location : Most Severe At North Ends Of Slips</i>						
		<i>Explanation : Abrasion</i>						
Timber	85%			2029	\$1,003,800			
		<i>Other Observation, Extent : Light, Area Affected : 30%</i>						
		<i>Location : Band Of Abrasion Due To Ferry Berthing</i>						
		<i>Explanation : Abrasion</i>						
Timber	5%	Now	\$59,000	2034	\$59,000			
		<i>Other Observation, Extent : Severe, Area Affected : 100%</i>						
		<i>Location : Predominantly At Slip 2</i>						
		<i>Explanation : Broken Elements</i>						

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841
WHITEHALL FERRY TERMINAL FERRY SLIPS 1 - 3

Asset # : 13889

Marinas/Docks		Current Repair		Future Replacement		Maintenance		Priority
System Component Type	% of Total	Fail Date (Years)	Estimated Cost	Year FY	Estimated Cost	Cycle (Yrs)	Estimated Cost	Priority
Fender								
Piles								
Timber	3%	Now	\$280,100	2039				**
<i>Recent Replace Evident, Extent : N/A, Area Affected : 25%</i> <i>Location : Pile Cluster Between Slip 2 And Slip 3 Replaced</i> <i>Other Observation, Extent : Severe, Area Affected : 40%</i> <i>Location : Clusters At Offshore Ends Of Slips 1 And 3</i> <i>Explanation : Broken</i>								
Timber	10%	4+	\$933,700	2039				**
<i>Other Observation, Extent : Moderate, Area Affected : 30%</i> <i>Location : At Isolated Locations, East Side Of Slip 1 Leaning</i> <i>Explanation : Impact Damage</i>								
Timber	47%			2035	\$4,388,600			
<i>Other Observation, Extent : Light, Area Affected : 15%</i> <i>Location : At Tops Of Piles</i> <i>Explanation : Splitting</i>								
Not Accessible	40%							
Wales and Chocks								
Timber	30%	2-4	\$215,600	2035	\$10,778,500			
<i>Other Observation, Extent : Moderate, Area Affected : 40%</i> <i>Location : Isolated Top 10 Feet</i> <i>Explanation : Rotting / Splitting</i>								
Timber	30%			2035	\$10,778,500			
Not Accessible	40%							
Gallows Frames								
Tower Frames								
Steel	100%			2043				**
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Areas Of Missing Coating</i> <i>Explanation : Coating Damage</i>								
Movable Ramps								
Bearings								
Not Accessible	100%							
Deck and Railing								
Steel	63%			2043				**
<i>Other Observation, Extent : Light, Area Affected : 2%</i> <i>Location : Railing</i> <i>Explanation : Coating Loss</i>								
Steel	7%	4+	\$26,400	2043				**
<i>Other Observation, Extent : Moderate, Area Affected : 100%</i> <i>Location : Slip 2 Bottom Ramp, Slip 3 Bottom Ramp Girders Bottom Flange. Corrosion On Handrail Connections With Ramp Girders</i> <i>Explanation : Wearing / Scaling</i>								
Not Accessible	30%							

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841

Project : HIGHWAYS

CAPITAL	FY 2026 - 2029		FY 2030 - 2035	
Miscellaneous Buildings	874,400		263,000	
EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Miscellaneous Buildings	71,600	12,600	17,200	12,300

ASSET #	NAME	SQFT	CAPITAL	EXPENSE
545	ARTERIAL AND FLEET SERVICES SHED 2	1,000	65,300	1,800
546	ARTERIAL AND FLEET SERVICES SHED 3	1,000	65,300	1,800
547	ARTERIAL AND FLEET SERVICES SHED 4	1,000	65,300	1,800
548	ARTERIAL AND FLEET SERVICES GUARD HOUSE 1	96	0	4,900
565	ARTERIAL AND FLEET SERVICES STORAGE 2	1,073	70,100	1,900
566	ARTERIAL AND FLEET SERVICES TRAILER 1	300	0	15,400
567	ARTERIAL AND FLEET SERVICES TRAILER 2	224	0	11,500
568	ARTERIAL AND FLEET SERVICES TRAILER 3	480	18,700	6,000
569	ARTERIAL AND FLEET SERVICES TRAILER 4	480	18,700	6,000
570	ARTERIAL AND FLEET SERVICES SHED 1	600	39,200	1,100
1014	GLENDALE YARD BLDG. 6	831	54,300	1,500
1015	GLENDALE YARD BLDG. 5	913	59,700	1,600
1016	GLENDALE YARD BLDG. 8	600	39,200	1,100
1017	GLENDALE YARD BLDG. 9	288	0	14,800
1025	HAMILTON AVE. ASPHALT PLANT STORAGE	1,472	96,200	2,700
1026	HAMILTON AVE. ASPHALT PLANT STORAGE	96	0	4,900
1027	FLATLANDS AVENUE YARD GARAGE 7	105	0	5,400
1037	FLATLANDS AVENUE YARD GARAGE 3	480	18,700	6,000
1038	FLATLANDS AVENUE YARD GARAGE 4	1,000	65,300	1,800
1039	FLATLANDS AVENUE YARD GARAGE 5	1,000	65,300	1,800
1040	FLATLANDS AVENUE YARD GARAGE 6	576	37,600	1,000
14124	BROOKLYN ARTERIAL HWYS GARAGE	4,425	289,100	8,000
14853	BROOKLYN ARTERIAL HIGHWAY GARAGE STORAGE SHED	1,062	69,400	1,900
15112	ARTERIAL AND FLEET SERVICES DIESEL STATION	179	0	9,200

Project : WATERWAY BRIDGES

CAPITAL	FY 2026 - 2029		FY 2030 - 2035	
Special Systems	1,163,438,000		0	
EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Special Systems	12,597,000	12,814,000	13,042,000	13,279,000

ASSET #	NAME	SQFT	CAPITAL	EXPENSE
2462	MANHATTAN BRIDGE MANHATTAN BRIDGE/EAST RIVER	1,203,814	577,550,000	12,384,000
2463	WILLIAMSBURG BRIDGE WILLIAMSBURG BR/EAST RIVER	741,020	6,888,000	13,203,000

Note : All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841

ASSET #	NAME	SQFT	CAPITAL	EXPENSE
2464	QUEENSBORO BRIDGE QUEENSBORO BR/EAST RIVER	1,287,107	573,500,000	15,018,000
2815	BROOKLYN BRIDGE BROOKLYN BRIDGE/I-278 BQE	633,015	5,500,000	11,127,000

Project: FERRIES

CAPITAL	FY 2026 - 2029		FY 2030 - 2035	
Special Systems	33,460,500		0	
EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Special Systems	7,175,000	10,766,000	14,306,400	11,413,100

ASSET #	NAME	SQFT	CAPITAL	EXPENSE
1022	FERRY-SAMUEL I. NEWHOUSE COAST GUARD #: 629315		3,350,000	3,350,000
4307	FERRY-ALICE AUSTEN COAST GUARD #: 696013		3,348,000	3,348,000
4308	FERRY-JOHN A. NOBLE COAST GUARD #: 696014		3,348,000	3,348,000
4538	FERRY-GUY V. MOLINARI COAST GUARD #: 1154854		3,350,000	3,350,000
4539	FERRY-JOHN J. MARCHI COAST GUARD #: 1163079		6,695,000	6,695,000
4540	FERRY-SPIRIT OF AMERICA COAST GUARD #: 1170221		6,510,000	6,510,000
4545	FERRY-MICHAEL OLLIS		2,811,800	5,517,000
4546	FERRY-SANDY GROUND		2,811,800	5,517,000
4547	FERRY-DOROTHY DAY		1,236,000	4,923,400
4548	FERRY-MICHAEL COSGROVE COAST GUARD #: 28762		0	1,102,100

Project: ELECTRIC CONTROL

CAPITAL	FY 2026 - 2029		FY 2030 - 2035	
Special Systems	3,020,000		0	
EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Special Systems	31,937,000	31,937,000	31,937,000	31,937,000

ASSET #	NAME	SQFT	CAPITAL	EXPENSE
2829	STREET LIGHTING SYSTEM		3,020,000	127,748,000

Project: HIGHWAY BRIDGES

CAPITAL	FY 2026 - 2029		FY 2030 - 2035	
Special Systems	206,796,000		0	
EXPENSE	FY 2026	FY 2027	FY 2028	FY 2029
Special Systems	0	0	0	0

ASSET #	NAME	SQFT	CAPITAL	EXPENSE
15833	ALL BRIDGES - BRIDGE COMPONENT REPAIRS / REPLACEMENTS HB-215		193,048,000	0
15834	ALL BRIDGES - BRIDGE PROTECTIVE COATING HB-1070		13,748,000	0

Note: All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation. Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.

DEPARTMENT OF TRANSPORTATION - 841

Project: HIGHWAYS

CAPITAL		FY 2026 - 2029		FY 2030 - 2035	
Special Systems		7,369,760,300		0	
EXPENSE		FY 2026	FY 2027	FY 2028	FY 2029
Special Systems		0	0	0	0
ASSET #	NAME	SQFT		CAPITAL	EXPENSE
2844	STREETS AND HIGHWAYS ARTERIAL			43,010,000	0
2845	STREETS AND HIGHWAYS STEP			77,592,000	0
15832	STREETS AND HIGHWAYS/ALL STREETS RECONSTRUCTION, RESURFACING			7,249,158,300	0

Project: TRAFFIC

CAPITAL		FY 2026 - 2029		FY 2030 - 2035	
Special Systems		28,731,000		0	
EXPENSE		FY 2026	FY 2027	FY 2028	FY 2029
Special Systems		45,638,000	45,638,000	45,638,000	45,638,000
ASSET #	NAME	SQFT		CAPITAL	EXPENSE
2830	TRAFFIC LIGHT SYSTEM			28,731,000	182,552,000

Note: All component repairs \$ estimates are in current dollars and are not escalated for potential future inflation.
Estimates are rounded to the nearest hundred dollars.

Maintenance \$ are aggregated over a ten-year period. Site specific cost escalations are not included.

** Replacement cost estimated to be beyond ten years is not included in this report.