

Local Law 78 Injury/Fatality Incident Report February 2021

Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury/Fatality Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Date of Employment	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number		
1000001406	AT CALL	2/26/21 17:15	1079102	15	BEEKMAN STREET	Manhattan	10038	Subcontractor	9172170459	Business	ALBA SERVICES INC		ALBA SERVICES INC	612373	SL GREEN	9	Non-Union	Y	On 2/26/21 laborer Luis Curillo Tappa while using an inspected sagged beam, was completing customary floor debris removals that were on the 54th floor, along with minimal floor debris removals that were on the beams. Mr. Curillo unfortunately lost his footing and suffered minor bruising. Thankfully, he was able to wally pull himself up and proceeded to walk down the stairs, changed his clothing, and walked to the field office to report what had occurred.	1	0	3/2/2021	8	2/10/2020	N	6	65,000	N	13	156					140897466-01-EW-OT, 140905732-01-EW-OT, 140908150-01-EW-OT, 123911286-01-DM, 123911286-01-EI-OT, 340294504-01-FI-CP, 902438703-10-OT, 900441706--01, 900441650-11-SI
1000001411	N/A	2/26/21 13:30	1077545	178	Avenue D	Manhattan	10009	General Contractor	9143648945	Business	WDF Inc.		WDF Inc.	GC-4331	NYCHA	1	Union	Y	An employee was dislodged from the platform of a power buggy during site utility installation. Specifically the employee was backing up into an open trench. During this time the power buggy fell forward causing the employee to become dislodged from the equipment.	1	0	3/3/2021	5	12/3/2019	Y	0	Ab. 10K	N	14	140					122136481-04-ew-01