

The details in this report are recorded by the property owner, contractor, etc. and the Department of Buildings does not edit the entries.

Reporting Permits	Active Permit Number
B00428858	
B00420325	
B01179336	
B01213010	
B01257392	
M01184871-I1	
M01184871-I1-SM	
M01184871-S2-PL	
M01184871-S3-EW-SP	
B00709512-II-GC	
B00709512-S1-FO	
B00709512-S3-ST	
B00709512-S4-PL	
B00709512-S5-EW-SD	
B00709512-S7-SE	
B00709512-S8-EW-SD	
B00738681-I1-FN	
M00744166-I1	
M00744166-I1	
M00744166-S2	
M00744166-S3	
M00744166-S4	
M0115510-I1	
M0115510-S1	
M0115510-S4	
Q00528973-II-GC	
M00556884-NB	
X00945722-II-PM	
X00949697-II-EL	
X00949706-II-EL	
X00984137-II-FN	
X00984137-II-FN	
X00984137-II-SP	
X00972956-II-EL	
X00984726-S1-EL	
M01172736-II-PM	
X00800823-IS-PL	
X00800823-I1-GC	
X00800823-S3-ST	
X00800823-S4-FO	
X00800823-S5-SE	
X00800823-S9-VT	
X00800823-Z1-VT	
X08011035-II-EW-SP	
X08012544-II-EW-SD	
X00909923-S8-SE	
210180873-01-AL	
B00655003-II-GC	
B00655003-S2-SM	
B00655003-S3-PL	
B00655003-S4-EW-SD	
B00655003-S4-EW-SP	
B00655003-S5-ST	
B00655003-S8-EW-SD	
B00655003-Z1-VT	
B00655003-Z2-SM	
B00655003-Z3-BE	
B00835483-II-EL	
B00876026-II-FN	
B00960047-S3-EL	
B01037483-II-SP	
M0057469-II-PM	
M0105974-II-PM	
M01087238-II-SP	
M0110317-II-FN	
M01136052-II-SC	
M01245188-II-EL	
M01245220-II-EL	
M01245220-S1-EL	
M01245220-S2-EL	
32142356-S1-AL	
M01012166-S2-ST	
M00947417-II-SM	
321954364-01-NB	
B00750123-II-FO	
B00750328-II-SE	
B00752281-II-FN	
M01068249-II-EW-SD	
B01235358-II-SP	
B01235358-II-SP	
B01237506-II-EL	
B01237794-II-PM	
B01237799-II-VT	
B01238062-II-EL	
M01095366-II-GC	
M01041788-II-GC	
Q00791713-II-GC	
Q00791713-S3-SE	
Q00791713-S1-FO	
Q00791713-S2-ST	
Q00985385-II-FN	
M00556884-NB	
M-01099276-II-GC	
M1250637	
M1250711	
M1250749	
M1251025	
M1261644	
B008566273-II-GC	
00763375	
M00707865-II-GC	
M00734766-II-SM	
M00807577-II-GC	
M008112479-PL	
M08034219-II-EW-SP	
Q01192715-II-GC	
Q01192715-II-GC	
Q01234687-II-SC	
Q01239193-II-SP	
Q01239388-II-EL	
X007506091	
X01243318/I1	

IncidentReporting																											IncidentReporting_Active Permits		
Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number
1000004824		8/22/2025 4:00:00 PM	2082192	1705	Bryant Avenue	Bronx	10460	General Contractor	7188506557	Business	Zoria Housing LLC		Zoria Housing LLC	GC-034719	NYCHA	5	Union	Y	Bradley Rzoma a asbestos handler injured during carrying construction debris. A small piece of metal fell down and hit his knee and he got small cut on his knee. Immediately 911 called , and took him to hospital with ambulance.	1	0	0	8000	N	6	60		X012446221 X012446431 X012461321	
1000004825		8/22/2025 10:45:00 PM	1087239	200	West Street	Manhattan	10282	General Contractor	2122296000	Business	Turner Construction Company		Nead Electric	2305	Goldman Sachs Properties	1	Union	Y	Worker was moving conduit off ladder when the ladder shifted causing the worker to injure their nose and wrist.	1	0	1	20,000	N	44	749		M01150193_11-GC	
1000004826		8/25/2025 8:10:00 PM	3141885	6315	14th Ave	Brooklyn	11219	General Contractor	3477281116	Individual			J&A Concrete	30951	SCA	10	Union	Y	A carpenter was on a work platform stripping forms off a shear wall and passing the forms down to another carpenter. One of the outriggers gave and the platform went down with the carpenter on it and landing on the other carpenter approx. 6-8' fall. Both carpenters left in the same ambulance and went to NYU Langone. Carpenter who was working on the platform had a sprained right knee. Carpenter who was on the ground level receiving the forms had a sprained shoulder.	2	0	8	62,000	Y		4	68	B00852836-I1-GC B00852836-S2-FO B00852836-S5-EA B00852836-S7-PL B00852836-Z5-VT B00994511-I1-FN B01231963-I1-SE B01235511-I1-SH B01259757-I1-EL CN0026325	
1000004827		8/22/2025 6:00:00 AM	1001162	199	Water Street	Manhattan	10038	General Contractor	7183472046	Business	Structural Preservation Systems		Structural Preservation Systems	GC-009832	Jonathan Resnick	1	Open Shop	Y	The individual was performing concrete chipping with an electric chipping hammer on a horizontal slab on grade slab when the individual struck a piece of steel reinforcement within the concrete slab. The chipping hammer kicked back causing an injury to his wrist.	1	0	0	20000	N	35	440		M0112618	
1000004828		8/27/2025 12:00:00 PM	1091731	200	east 75th street	Manhattan	10021	General Contractor	2123885700	Business	triton construction company, llc		Nolan Painting	GC- 35561	200		1	Open Shop	Y	worker was working off an a frame platform ladder cleaning the hinges on a door in apartment 7a on the 7th floor when she allegedly fell.	1	0	0	123,000	Y		18	154	M00723903-I1-gc
1000004829		8/29/2025 12:00:00 PM	4439038	45-40	Vernon Blvd	Queens	11101	Person in Control of Site	5168299400			Other	LIXiang Construction		ZDJ Vernon LLC	0	Non-Union	Y	Worker was set up on an A-frame ladder cutting a hole in the sheetrock above his work area which was around ten to eleven feet. Ladder was approximately 8 feet in height. Worker was descending on the ladder. When the worker had reached the third or fourth rung from the lowest step, he had slipped and fell to the floor. Worker had been sitting halfway upright leaning against the wall and then decided to lay down. I had arrived on the scene along with the eyewitness and the plumber foreman. Worker speaks minimal English and we were assessing the injuries and state of consciousness of the worker.	1	0	0	38,650	Y		22	271		
1000004830		8/28/2025 1:28:00 PM	2017421	2702	Creston Avenue	Bronx	10468	Person in Control of Site	9172974020			Other	Lifitech Elevators		SPAXEL CBRE 2702 CRESTON LLC	18	Non-Union	Y	Worker was placing metal plates on top of each other and accidentally injured his right index finger	1	0	0	64461	Y		13	114	Z20212543-I1-NB X00688893-I1-ST X00567886-I1-FN X00572534-I1-GC X00579813-I1-EW-SD X00579813-I1-EW-SP X00579813-I1-EW-SR X00579813-I1-PL X00661034-I1-MS X00712725-I1-EW-SD X01016579-I1-SH X01019129-I1-EL X01101824-I1-SF X01103650-I1-EL X01124707-I1-EL X01125386-I1-EL X01133221-I1-PMN X01136282-I1-VT X01256142-I1-VT	
1000004840		8/29/2025 12:00:00 PM	1005709	235	Bowery	Manhattan	10002	General Contractor	2122322200	Business	Sciame Construction		Nexx	606991	New Museum	1	Open Shop	Y	Worker reported feeling an accelerated heartbeat and felt ill.	1	0	0	50000	N	8	174		121205114-Q1-AL	
1000004842		8/26/2025 4:00:00 PM	2112853	480	East 176 Street	Bronx	10457	General Contractor	7182997000	Business	Procidia Construction Corp		Procidia Construction Corp	001863	The Lantern Organization	7	Non-Union	Y	Nitay Rivero Paxon was straightening a rebar when it snapped, and he fell back on the pipe riser clamp. The clamp pierced Nitay's back. The emergency services were alerted and Nitay was escorted to the ambulance. Nitay was taken to St. Barnabas Hospital.	1	0	2	254sf	N	8	92' 4"	X00432153-I1-SH X01026845-I1-EL X01165180-S1-MS X01165180-S2-PL X01165180-S3-EW-SP X01165180-S5-GC X01259777-I1-SC		