Incident	Smoke Det. Comments	Smoke Detector	Technology
12/16/201/		Unable to determine	Unable to determine
1 /0 /2010	·	Unable to determine	Unable to determine
1/9/2018	——————————————————————————————————————	Unable to determine	Unable to determine
1/12/2010	shoke detector presence and operation is unknown.	Not Procent	Unable to determine
			Unable to determine
	Hardwired Smoke detector, Working		Unable to determine
	· · · · · · · · · · · · · · · · · · ·	•	Unable to determine
	·	·	Unable to determine
			Unable to determine
	, - ,	•	Unable to determine
		·	Unable to determine
		Present Operational	Unable to determine
10/19/2018		Not Applicable	Unable to determine
9/22/2018		Present Unknown if operational	Unable to determine
	building maintenance.		
8/12/2018	U/I is not aware of smoke detector activating.	Present Unknown if operational	Unable to determine
1/30/2018		Present Operational	Unable to determine
1/16/2018	Smoke detector present, unknown if operational	Present Unknown if operational	Unable to determine
	·	·	Unable to determine
	smoke detector in apartment not found, witnesses stated they heard smoke		Unable to determine
7/2/2018	·	Not Present	Unable to determine
			Unable to determine
			Unable to determine
	Consider the standard but confidence if an austional	Present Unknown if operational	Unable to determine
	12/16/2017 1/9/2018 4/13/2018 3/18/2018 4/1/2018 4/1/2018 12/26/2018 12/24/2018 6/30/2018 2/8/2018 12/28/2017 10/19/2018 8/12/2018 1/30/2018 4/16/2018 4/16/2018 7/7/2018 6/5/2018 12/6/2018	12/16/2017 This case was not investigated by BFI at the time of the incident, therefore, smoke detector presence and operation is unknown.  1/9/2018 BFI was made aware of the case long after the incident date therefore smoke detector presence and operation is unknown.  4/13/2018 3/18/2018 4/12/2018 Hardwired Smoke detector, Working 4/25/2018 Occupants stated smoke detector on first floor none on 2nd floor.  12/26/2018 12/24/2018 Smoke detector was severely damaged by fire.  6/30/2018 Operational 2/8/2018 12/28/2017  10/19/2018  9/22/2018 As per building manager (Paul Reich 646-235-0309), due to size of apartment, only one smoke detector was installed and batteries check by building maintenance.  8/12/2018 U/I is not aware of smoke detector activating.  1/30/2018  4/16/2018 Smoke detector present, unknown if operational.  5/7/2018 Smoke detector present on 2nd floor, not operational 6/5/2018 smoke detector in apartment not found, witnesses stated they heard smoke detector in public hallway but not from the fire apartment 7/2/2018 Not present	12/16/2017 This case was not investigated by BFI at the time of the incident, therefore, smoke detector presence and operation is unknown.  1/9/2018 BFI was made aware of the case long after the incident date therefore smoke detector presence and operation is unknown.  4/13/2018 BFI was made aware of the case long after the incident date therefore smoke detector presence and operation is unknown.  Not Present  4/13/2018 Hardwired Smoke detector, Working Present Operational  4/25/2018 Occupants stated smoke detector on first floor none on 2nd floor.  12/26/2018 Smoke detector was severely damaged by fire.  6/30/2018 Operational  2/2/8/2018 Operational  1/2/28/2017 Present Operational  10/19/2018 As per building manager (Paul Reich 646-235-0309), due to size of apartment, only one smoke detector was installed and batteries check by building maintenance.  8/12/2018 U/I is not aware of smoke detector activating.  Present Unknown if operational  1/30/2018 Smoke detector present, unknown if operational.  1/30/2018 Smoke detector present on 2nd floor, not operational  8/16/2018 Smoke detector present on 2nd floor, not operational  1/30/2018 Smoke detector in apartment not found, witnesses stated they heard smoke detector in public hallway but not from the fire apartment  Not Present  Not Present  Not Present Not Operational  Present Not Operational

Cause Fire Description	Incident DateTime	Smoke Det. Comments	Smoke Detector	Technology
Electrical Wiring	2/9/2018	Smoke detectors were only on the first floor of the subject premises, none on second floor where fire occurred. FDNY reports smoke detector at base of the stairs to second floor sounding when they entered.	Present Operational	Unable to determine
Electrical Wiring	2/9/2018	Smoke detectors were only on the first floor of the subject premises, none on second floor where fire occurred. FDNY reports smoke detector at base of the stairs to second floor sounding when they entered.	Present Operational	Unable to determine
Electrical Wiring	2/10/2018	Smoke and Carbon Monoxide detectors rendered inoperable by homeowner due to them constantly going off when they cooked. This was done approximately 3-4 weeks prior to fire.	Present Not Operational	Unable to determine
Electrical Wiring	5/11/2018		Present Unknown if operational	Unable to determine
Electrical Wiring	9/25/2018	Capt. Brian Gill/ Officer L47 stated that there were no smoke detector alarms heard upon entering apartment.	Not Present	Unable to determine
Electrical Wiring	9/30/2018		Not Present	Unable to determine
Electrical Wiring	4/28/2018		Not Present	Unable to determine
Electrical Wiring	4/28/2018		Unable to determine	Unable to determine
Electrical Wiring	1/7/2018	Not present as per first due units that operated. None observed during investigation.	Not Present	Unable to determine
Electrical Wiring	1/31/2018		Not Present	Unable to determine
Electrical Wiring	4/7/2018		Not Present	Unable to determine
Electrical Wiring	8/17/2018		Present Not Operational	Unable to determine
Electrical Wiring	8/17/2018		Present Not Operational	Unable to determine
Extension Cord	6/18/2018		Not Present	
Extension Cord	11/16/2018		Present Operational	Unable to determine
Extension Cord	6/5/2018	Not present. Mounting ring found above front door. No detector found within vicinity.	Not Present	Unable to determine
Food on the Stove	4/19/2018		Present Operational	Unable to determine
Heat from Light Bulb	1/12/2018		Present Not Operational	Unable to determine
Heat from Light Bulb	1/12/2018		Not Present	Unable to determine
Ignitable Liquids/Gases - Gasoline	11/25/2018	3	Not Applicable	Unable to determine
Incendiary	3/5/2018	At this time unable to ascertain whether or not smoke detectors in the victims' apartment were functioning.	Unable to determine	Unable to determine

Cause Fire Description	Incident DateTime	Smoke Det. Comments	Smoke Detector	Technology
Incendiary	3/5/2018	At this time unable to ascertain whether or not smoke detectors in victims'	Unable to determine	Unable to determine
Incendiary	4/9/2018	apartment were functioning.  According to all statements taken, no smoke detector was heard or	Unable to determine	Unable to determine
incentially	4/9/2016	observed to be activated at the incident.	Offable to determine	onable to determine
Incendiary	8/18/2018		Not Applicable	Unable to determine
Incendiary - Combustible Material	12/23/2018		Present Not Operational	Photoelectric
Incendiary - Ignitable Liquid	6/12/2018	Smoke detector present, no battery	Present Not Operational	Unable to determine
Incendiary - Ignitable Liquid	6/9/2018		Present Operational	Unable to determine
Incendiary - Ignitable Liquid	6/9/2018		Present Operational	Unable to determine
Incendiary - Reckless Use of Open	3/19/2018		Not Present	Unable to determine
Flame				
Incendiary - Self Immolation	4/14/2018		Not Present	Unable to determine
Incendiary - Suicide	4/28/2018	N/A	Not Applicable	Unable to determine
Incense	1/28/2018	As per P.O. Hernandez (Shield #20592) PSA 6, he reported to FM Matthew	Present Not Operational	Unable to determine
		Lewis that he heard a smoke detector sounding while FDNY began to force		
		the door to the fire apartment (4H) but was unable to determine if it was		
		from the fire apartment or a neighboring apartment. He further reported		
		that neighbors had begun to open their doors and observed smoke entering		
		their apartments prior to him telling them to close their doors.		
Motors - Compressors	6/6/2018	Not present	Present Operational	Unable to determine
Motors - Compressors	6/6/2018		Present Operational	Unable to determine
Other	1/13/2018		Not Applicable	Unable to determine
Other - Electrical	6/2/2018	Present in common area of basement. No battery and battery door was in	Present Not Operational	Unable to determine
		the open position.		
Other - Hot Objects	1/14/2018		Present Unknown if operational	Unable to determine
Other - Hot Objects	1/14/2018		Present Unknown if operational	Unable to determine
Other - Open Flame	10/26/2018		Not Applicable	Unable to determine

Cause Fire Description	Incident DateTime	Smoke Det. Comments	Smoke Detector	Technology
Other - Open Flame		One smoke detector present and operational (kiddie 10 yr sealed battery).  One Carbon monoxide detector present and operational (kiddie 10 yr lithium power unit)  One 9v battery older model smoke detector present but not operational All three detectors located in close proximity in hall by north bedroom/bathroom doorways.	Present Operational	Unable to determine
Permanent Heater - Electric	2/28/2018	,	Present Operational	Unable to determine
Permanent Heater - Electric	2/28/2018		Present Operational	Unable to determine
Portable Heater - Electric	11/5/2018		Not Present	Unable to determine
Portable Heater - Electric	4/5/2018	Hard wired smoke detectors present throughout building. Upper floor detectors activated, basement detector present but not operational.	Present Not Operational	Unable to determine
Power Strip	12/8/2018	Present and operational as per occupant Vincent Gomez and located in the kitchen.	Present Operational	Unable to determine
Power Strip	12/8/2018	Present and operational as per occupant Vincent Gomez and was located in the kitchen.	Present Operational	Unable to determine
Smoking (Cigarette/Cigar)	11/1/2017		Present Operational	Unable to determine
Smoking (Cigarette/Cigar)	7/17/2018		Present Operational	Unable to determine
Smoking (Cigarette/Cigar)	6/5/2018	Not Present	Not Present	Unable to determine
Smoking (Cigarette/Cigar)	3/12/2018	Smoke detector found in room of fire origin burnt and melted. 2 Carbon Monoxide detectors found and operational.	Present Unknown if operational	Unable to determine
Smoking (Cigarette/Cigar)	12/15/2017		Unable to determine	Unable to determine
Smoking (Cigarette/Cigar)	1/26/2018	The U/I was informed by occupant that smoke detector was operational.  Occupant received smoke detector from NYCHA in December, and was tested in late January.	Present Operational	Unable to determine
Smoking (Cigarette/Cigar)	2/17/2018	Disabled due to cigarette smoking triggering alarms.	Present Not Operational	Unable to determine
Smoking (Cigarette/Cigar)	7/1/2018		Present Operational	Unable to determine
Smoking (Cigarette/Cigar)	12/13/2016		Present Not Operational	Unable to determine
Smoking (Cigarette/Cigar)	8/25/2018		Not Present	Unable to determine
Smoking (Cigarette/Cigar)	6/18/2018		Not Present	Unable to determine
Smoking (Cigarette/Cigar)	11/11/2018		Present Operational	Combo Smoke / CO
Smoking (Cigarette/Cigar)	4/26/2018	Two smoke detectors in apartment not operational. Smoke detector in hallway of 3rd floor was in working condition.	Present Not Operational	Unable to determine

Cause Fire Description	Incident Smoke Det. Comments	Smoke Detector	Technology
	DateTime		
Smoking (Cigarette/Cigar)	10/7/2018 unknown	Unable to determine	Unable to determine
Smoking (Cigarette/Cigar)	12/31/2017 present operational	Present Operational	Unable to determine
Smoking (Cigarette/Cigar)	5/28/2018 In hallway operational during the fire.	Present Operational	Unable to determine
Smoking (Cigarette/Cigar)	2/26/2018	Unable to determine	Unable to determine
Stove/Cooking - Other	12/11/2018 found in bathroom on floor, no battery	Present Unknown if operational	Combo Smoke / CO