Incident Incident Unique ID Number	ncident Date & Time BIN Hou	sie Number Street Name Borou	eh Zip Code Incident Reported By	Person Reporting Type of Person Phone Number Reporting Incide	n Organization of Person ent Reporting Person in Control of Si	te Name of Contractor	Person Repo	orting /	Number of Active Permits Issued Site Union	Construction Work	fker Incident Description Details	Injury Fat	stality Injury/	Injury/Fr Fatality Number ate Hours W	stality Injury/Fata er of Date of Forked Employme	ity Injury/Fatality F Worker Union	lumber of fiolations Site 1	otal Square Site New octage Building Fla	Site Existing Number of Site	Sin e Existing 7 Height	e Proposed Aumber of Site Stories	l Proposed Height Active Permit Number
								BOP 101 LINCOLN			Incident Description Details Concrete truck driver claims to have slipped on a piece of plastic sheeting used in concrete wishout area. Worker called 911 himself after refusing to talk with the onsite medic. A driver when an delicration affect for the original of the talkate, and											
1000001488	4/5/218:30 2000759	101 Lincoln Ave Bronx	10454 General Contractor	2123885700 Individual			NA	AVENUE. LLC	1 Open Shoo	Y	to talk with the onsite medic. A driver who was delivering places had the a frame slip off the tallgate, and	1	0 4	1/7/2021	3 7/1/2	316 Y	0	981.549 Y			25	262 220151948-01-NB
											A driver who was delivering glass had the a frame slip off the tailgate and it landed on his right foot. He went to the hospital and was released and drove back home to Maryland The driver or material was never inside of											
1000001490	4/6/21 13:30 1012253	29 11th avenue Manhatt	an 10001 General Contractor	6463437363 Individual			GC-002660	ROOR	4 Union	N	my project at Pier 57.	1	0 4	1/7/2021	0 1/0/1	000	0	360,000 N	5	14		123448661-03, 123681658-02, 123764499-01, m9021529
											AS per Statement From the Injured Party(Mr. Franklin Lopez) a Sharp pc of SS Metal was place or lying on the Scissor lift Platform, in an intent of											
											the injured party to climb back on to lift platform causing some movement trying to open an access door; a pc of SS Metal felt and											
1000001491 3.21E+08	4/6/21 12:25 3257037	38 Fleet Walk Brooklyn	11201 General Contractor	9146648444 Business	SN Builders Inc	SN Builders Inc	GC - 026674	NYCHA	6 Union	Y	moved striking Mr. Lopez betweenfinger 2 and 3 creating a small Laceration to his right hand palm. Steamfitter was installing and and welding saddles into hangars for	1	0 4	1/8/2021	3 10/1/2	220 Y	1	4.000 N	6 60+			321229862-01-EW-OT, 800325449-11-5H, 800330235-11- FN. 8003523-11-5F. 800352341-11-5F. 800352342-11-5F
											elevated steam pipes from a scissor lift on the 12th floor. Worker drove											
											the scissor lift onto the forks of a parked electric pallet jack. While preparing to weld the installed saddle into the hangar, scissor lift deck											
		Washington									@9.5 feet; the scissor lift became unstable and fell over. Worker was tended to by the medic and removed from site to Bellevue Hospital by											
1000001493	4/6/21 10:40 1010356	550 Street Manhatt	an 10014 Person in Control of Site	2014375150	Site Safety Manager	Adria Infrastructure LLC		1062 Oxford Properties	1 Union	Y	FDNY. White province on releasing stool from a flathed truck during one of the	1	0 4	1/9/2021	10 8/26/2	220 Y	4 1.15M	N	13	231.7		123156057-01-FO-EA
											load swings, the load/swing piece clipped one of the sitting pieces which accidentally nudged Jeffrey Perez causing him to lose his balance. He ended up on the street with the falling piece hitting him on his right hip											231101517.01.50. 231101517.01.50.50. 231101517.01.MB
	4/7/2113:15 3000000			7188757257 Business				14421 La Mirada-Schippers LLC	6 Non-Union	_	ended up on the street with the falling piece hitting him on his right hip		0 4	1/9/2021	4 3/3/2			4 ann 11				321191517-01-FG, 321191517-01-FG EA, 321191517-01-NB, 321956601-01-DM, 340725353-01-EW OT, 340744234-01- 105 ED OT
1000001494	4///2113:15 3000000	160 1/th Street Brooklyn	11215 Garranal Contractor	7188/5/25/ BUNNESS	SUS Leonard LLC	SUS LIFERIARD LLL		14421 La Minada-Schibbers LLC.	6 Non-Union		Juan Aragonez was making his way to the mechanical space from the	1		N7972021	4 3/3/2	121 N	3	6,000 4			,	100 1001
											and lac. Journ Aragonez was making his way to the mechanical space from the hoist. When he reached the bottom of the stair tower, he continued towards the entrance of the 10th foor mechanical space. A few feet away from the landing at the stair tower he was struck by a falling junior beam in the left thoudder.											
1000001495	4/9/2114:30 1036509	123 East 55th Street Manhatt	an 10022 Subcontractor	6462437833 Individual		Vivid Mechanical		2380 Central Synagogue	1 Non-Union	Y	away from the landing at the stair tower he was struck by a falling junior beam in the left shoulder.	1	0 4/	10/2021	7 2/23/2	321 N	3	46,204 N	10	106		123802938-01-EW-OT
		Parsons			Mega Contracting																	123802938-01-EW-OT 420664310-01-AL, 420664310-03-PL, 440541291-01-EW SD, 440548757-01-EW SD, 440548757-01-EW SP, 440550388-01-
1000001497	4/8/2112:00 4442434	8241 Boulevard Oueens	11432 General Contractor	7184891716 Business	Group. LLC	Apollo Concrete	6	03805 Durn Development	7 Open Shop	Y	The worker was cuttine pipe when debris ept into his eve. This morning at 10A on 4/13/21 Edgar Bocel was helping to bring drywall	1	0 4/	13/2021	6 4/9/2	220 N	0	238.000 N	10	120		EW BL 440557639-01-EO OT
											The worker was cuttine close when debris and into his eve. This moming at 10A on 4/13/21 digite Book was helping to bring drywell into the site from a delivery truck from Malginia. Carring with another worker the 2 boards they were carrying tipped over opposite way and lost their balance. Edger hust his thumb trying to regain balance and control of the sheets.											
1000001499	4/13/21 10:00 3064558	120 Java Street Brooklyn	11222 Person in Control of Site	9173303882	Construction Superintendent	Greenport Construction		27633 120 Java LLC	5 Non-Union	Y	lost their balance. Edgar hurt his thumb trying to regain balance and control of the sheets.	1	0 4/	13/2021	3 7/6/2	320 N	0	22,000 N	5	50		321288129-01-AL, 321288129-01-EQ-FN, 340621134-01-EW SP, B00061101-11-EL, B00391049-11-VT
											Spring scaffold was using a kuckle boom to boost material onto the Haier building for the building of roof protection. 1 worker was on top of the bed of the knuckle boom when the operator asked him to take over for											
											one of the workers doing the flagging. Because nobody witnessed the actual fall it is thought that he tripped on the material that was on the											
											bed of the knuckle boom and he lost his balance and fell off the side of the truck. An ambulance was called and the incident was reported to											
1000001500 2514	4/13/21 21:40 1015244	1370 Broadway Manhatti	an 10018 General Contractor	5169217100 Business	E.W. Howell LLC	E.W. Howell LLC		19416 Invesco	1 Open Shop		DOB dispatch #2514. Calls were not returned as of 930 4/14/21 as to the workers health.	, ,	0 4/		4 3/9/2			100 N	7	91		123815835-01-rwot
1000001500 2514	4/13/21/21/40 1015/244	145 West 47th Street Marrhatt		5169217100 Business	TRUSA LIC	BNC Industries	00.615037	NY Tower Development LLC	1 Open Shop		workers reason. While using the chipping gun the worker lost control of the gun and hurt his finger, which was left slightly swollen.		0 4/		6 1/1/2			311 727 V	,	91	48	
1000001503	4/14/21 14:20 1090823	145 West 47th Street Manhatt	an 1–36 General Contractor	6466926803 Business	TB USA, LLC	RNC Industries	GC-615037	шс	1 Open Shop	*	his finger, which was left slightly swollen	1	0 4/	15/2021	6 1/1/2	316 N	0	311,727 Y			48	520 NB 121187802 213191995-01-EQ FM, 121191995-01-FQ, 121191995-01-FQ EA, 121191995-01-RM, 121191995-04-FE, 140504489-01-EW SO, 140504489-01-EW SP, 140770590-01-EW SD, 140877200-01-EQ CT, 14088858-01EEQ CT, 140988169-01- EQ CT, 140983946-01-EQ CT, MODOSS8679, MODORS316,
																						EA, 121191995-01-NB, 121191995-04-PL, 140504489-01-EW SD, 140504489-01-EW SP, 140770690-01-EW SD,
											As stated by Walter Torres; Mr. Torres was installing formwork for stainwell A on the 22nd floor while on top of an A-Frame ladder when he fell off the Jadder. Mr. Torres was Sound at the bottom of the mid-stair landing between the 2nd floor and the 22nd floor in stainwell A.											140877200-01-EQ OT, 140889634-01EQ OT, 140946109-01- EQ OT, 140963946-01-EQ OT, M00053679, M00085316,
1000001505 1569056	4/14/217:15 1000801	50 Trinity Place Manhatt	an 11385 General Contractor	2129837150 Business	Cauldwell Winzate Co LLC	MOOREGROUP CORPORATION		26044 Trinity NYC Hotel, LLC	21 Non-Union	Y	fell off the ladder. Mr. Torres was found at the bottom of the mid-stair landing between the 2nd floor and the 23rd floor in stainwell A.	1	0 4/	16/2021	1 9/30/2	220 N	6	72.351 Y			31	M00085317, M00158965, M00263152, M00316859, 341.9 M00437820. M00469707. M00470128
											Workers were unloading materials from their truck onto A-frames, to											
		Washington									Workers were unloading materials from their truck onto A-frames, to take onto the hots, for a work platform to be constructed on the 2nd floor. While unloading a teste beam the worker pinched his right middle finger between 2 beams severing the fingertip.											
1000001506	4/14/21 7:45 1010356	550 Street Manhatt	an 10014 Person in Control of Site	2014375150	Site Safety Manager	Safway Atlantic, LLC		1062 Oxford Properties	1 Union	Y	finger between 2 beams severing the fingertip. Moving construction equipment located on roof. Fell over onto one of	1	0 4/	16/2021	1 8/21/2	319 Y	2 1.2M	N	12	237		123156057-01-AL
1000001508	4/19/21 9:25 1016224	920 Broadway Manhatti	an 10010 General Contractor	7189375353 Business	Skyline Restoration Inc	Magella Construction Co	orp	3365 Walnut Point Realty LLC	2 Non-Union	Y	the workers	1	0 4/	19/2021	2 4/16/2	321 N	0	5,500 N	17	170		140995680-01-EW OT, 140996402-01-EQ OT
											On 4/15/2021 at approximately 1:15pm, Pedro Coreas was bending #11											
											rebar using a mobile, hydraulic bending machine in the center of the site (cellar slab level, -13ft down from sidewalk). At the time of incident it was approximately 55 degrees Fahrenheit with heavy rain. During the											
											approximately 3.5 degrees remember with nearly rain. During the bending process, the rebar snapped and the remaining piece bit his right think causine him to fall down. He stated he could not move his lee and											1002626, 1002868, 121205597-01-FO, 121205597-01-FO EA. 121205597-01-MB. 121205597-04-FL. 140897778-01-EO
1000001509	4/15/21 13:15 1052673	1998 2nd Avenue Manhatt	an 10029 General Contractor	2126200500 Business	Bolivar Builders LLC	KNR Construction LLC	6	18745 Boliver Builders	8 Non-Union	Y	911 was called.	1	0 4/	19/2021	6 2/17/2	321 N	3	17,500 Y			12	EA, 121205397-01-NB, 121205397-04-PL, 140897778-01-EQ 125 OT, 140906615-01-EQ OT
											Worker was in the process of cutting a piece of wood flooring on a table saw when his left thumb made contact with the saw blade causing a											
1000001512 3793500	4/15/21 7:35 3428828	662 Pacific Street Brooklyn	11217 General Contractor	2123996000 Business	Tishman Construction Corp	Workroom 81	GC002540	Pacific Park Development	1 Union	Y	laceration at 7:35am on the 12th floor.	1	0 4/	20/2021	1 8/5/2	220 Y	4	370.789 Y			26	272 32090433-01-NB
1000001513	4/20/2111:00 1090786	1241 Broadway Manhatti	an 10001 General Contractor	2123885700 Individual			NA	1241 BROADWAY LLC	1 Open Shop	Y	Worker using single section of baker scaffold when it tipped and worker fell. Worker sent to hospital for additional medical evaluation.	1	0 4/	20/2021	12 4/7/2	321 N	0	178.884 Y			22	318 121188749-01-NB
1000001514	4/17/2113:00 5171652	2636 Hylan Boulevard Staten to		5162325827 Individual		Torc Inc		Hylan Plaza 1339 LLC	1 Non-Union		Owner of the GC tripped and fell on pipe sub-ups in floor.	1	0 4/	20/2021	0 1/0/1	000 0	0	200,000 Y			2	40 500468260-11-GC
																						321383007-01-FO-EA, 321383007-01-NB, 340634941-01-EW- SD, 800368001-11-EL, 800375397-11-SF, 800401209-11-SH.
1000001516	4/20/21 8:35 3394734	640 Columbia St Brooklyn	11213 General Contractor	6468807309 Individual				2834 640 Columbia LLC	8 Open Shop	Y	Jim Jaramillo was working on an A frame ladder in side of an elevator shaft installing a pour stop, when the ladder broke and he fell.	1	0 4/	21/2021	1.5 4/20/2	321 N	3	173,000 Y			3	 50066820611-07. 23138307-07-07-04, 323183007-03-NR, 340634981-03-0W-50, 800186001-04-10, 80037-38971-39, 800641208-1-34, 50060482611-348 500675-07-1, 22228670-06-7-N, 122228679-03-NR, 22228679-04-PR, 122242513, 123307418, 123232427, 22228679-04-PR, 12262510, 123520143, 123232427, 2228679-04-10-10-10-10-10-10-10-10-10-10-10-10-10-
																						122128679-04-Pt, 122842335, 123292418, 123292427,
1000001517 1569265	4/16/21 7:58 1090479	15 E30 Manhatti	an 10016 Person in Control of Site	2126890639		iden Elicc		15370 Madison 30-31 Owner LLC	19 Open Shoo	_	Youba Sylvanus climbing over parapet wall to adjacent building roof fell	1	0 4/	22/2021	2 11/12/2			325.243 Y			56	140254329, 140254356, 140388239, 140855313, 800 140864866, 140912083, 140940891, 141000556
1000001517 1509205	4/20/21 12:30 1012843	460 west 34th street Manhatt	an 10001 General Contractor	2124011220 Business	Archstone Builders	Acon .	Gc-608319	SL Green	2 Non-Union		coasiar back insur. Work was measurine for endantion form cassiar back insur. Work was measurine for endantion form other to to balance and felf while pushing a wheelburnow for concrete operation. Worker hit his cheek on wheelburnow. Worker was cutting a wertical section of rober with an angle grinder on the 2nd floor working deck. The grinder got bound in the robber and	1		22/2021	5/6/2			583,000 N	19	200	50	123845679-01-EW 0T, 123845679-02-EW 0T
100001318	4/20/21 22:30 2022043	400 WELL STOLLERS MINISTER	an 2002 Onnea Constitu	2124011220 0001140	Piccinocine administra	ALUII	0000323	J. Green	1 Horonon		Worker was cutting a vertical section of rebar with an angle grinder on	•		22/2021 48+	444	20 14		383,000 N	1,5	200		121205150-01-FO, 121205150-01-FO EA, 121205150-01-NB, 121205150-03-PL, 123823559-01-EW SD, 123823559-01-EW
1000001520	4/15/21 11:15 1033121	2330 Broadway Manhatt	an 10024 General Contractor	2123216800 Business	Hunter Roberts Construction Group	Pinnacle Industries II		32144 Hines	7 Open Shoo	Y		1	0 4/	22/2021	4 4/8/2	321 Y	1	10.000 Y			19	121205150-03-PL, 123823559-01-EW 50, 123823559-01-EW 230 SP. 140962947-01-EO OT
1000001524	4/22/21 12:30 1090823	145 West 47th Street Manhatt	an 10036 General Contractor	6466926803 Business	TB USA. LLC	Spectrum Painting	GC-615037	NY Tower Development LLC	1 Coan Shoo	Y	Worker tripped on Masonite and fell on his hands under his left breast (Ribs)	1	0 4/	23/2021	5 1/28/2	319 N	0	311.727 Y			48	520 NB 121187802
											The worker was working on a baker scaffold, the scaffold work platform was set at less than 5 feet from the floor. The person possibly tried to move the scaffold while on it causing the baker scaffold to tip over. The											
1000001525	4/23/2110:00 1084771	301 Park Ave Manhatt	an 10022 General Contractor	9179998811 Business	Aecom Tishman	Trident General Contracting, LLC	GC-2540	AB Stable LLC	1 Open Shop	Y	move the scaffold while on it causing the baker scaffold to tip over. The worker fell on the floor.	1	0 4/	24/2021	3 2/1/2	321 N	1	1,760,000 N	44	625		121191245-01-AL
1000001528	4/25/21 12:00 2000999	276 Grand Concourse Bronx	10451 Person in Control of Site	6466001866	Site Safety Coordinator	Gold Edge		2604 GC Capital Group LLC	1 Non-Union	Y	Worker pinched finger between wall and a-frame, injuring his finger.	1	0 4/	27/2021	7 4/12/2	321 N	0	196,982 Y			12 124	"3" 220689921-01-NB
											Erica Ortiz was transporting empty mini's throughout the 9th floor server											
											Erica Ortiz was transporting empty mint's throughout the 9th floor sector. A for the next days use. While pulling the mins through the comidor it accidently field to her. It works in the area care and encomed the mint from on top of hir. She was cared and in pain in the time the medic arrived. The medic did not was to move her so immediately called for a smith darked, and of the section of the section.											
											from on top of her. She was scared and in pain at the time the medic											
	4/26/2117:00 3425091		11202 Person in Control of Site	2127366900				85 Jay street(Brooklyn), 1712 LLC	1 Open Shoo		ambulance to take her and get her checked by a doctor. Erica complained		0 4/		10 1/20/2			878.003 Y				210 3211884515
1000001529	4/26/2117:00 3425091	85 Jay Street Brooklyn	11202 Person in Control of Site	2127366900	Site Safety Manager	PRC		1712 LLC	1 Clown Shoo	*	about lee pain and numbness, hip pain, and mid section.	1	0 4/	27/2021	10 1/20/2	321 N	0	878.003 Y			21	210 3211884515
											Bedrock employees were installing a no-hub stack in the shaft by the single passenger elevator from basement to use cellar. The witness was cutting the pips from the basement, which the injuried infoldual was below in the subcellar holding the pips. When the cut was complete, the pips field not the injuried person's Obst. At first, the worker off unit feel the pais, and continued working for about 15 minuses before determinion be presided to see a received at benefits.											
											cuturing the pipe from the basement, while the injured individual was below in the subcellar holding the pipe. When the cut was complete, the											
						Bedrock Plumbing &		Montague Terrace			pspe tell onto the injured person's foot. At first, the worker did not feel the pain, and continued working for about 15 minutes before											321194391-01-AL, 321194891-01-EQ FN, 321194391-02-PL, 321697053-01-EW SD, 321697053-01-EW SP, 340752750-01- EQ OT, 340761722-01-EQ OT, 340783352-01-EQ OT
1000001530	4/26/21 11:30 3001482	124 Columbia Heights Brooklyn	11201 General Contractor	2036193334 Individual		Heating Inc.		26301 Development, LLC	8 Open Shop	Y		1	0 4/	27/2021	4 10/16/2	220 N	0	148,803 N	9	90		EQ OT, 340761722-01-EQ OT, 340783352-01-EQ OT
											Craftsman while working inside of the elevator shaft from inside elevator car was prepping to install a rail clip by cutting out a piece of sheetrock.											
											while performing this task he over extended his body causing his back to spasm. worker was treated by onsite medic but insisted to be transported											
1000001532	4/27/218:15 1090263	181 Mercer Street Manhatt	an 10012 General Contractor	9145733941 Individual		Shindler Elevator		2529 New York University	1 Union	Y	to hospital by Ambulance for further evaluation.	1	0 4/	27/2021	1 2/23/2	321 Y	0	745.000 Y			24	334 121191174-01-NB
											On 4/26/21 at approximately 6:30pm, Adams European employee Angel											
											On 4/26/21 at approximately 6:30pm, Adams European employee Angel Aviila was working with other employees to remove a window when a section of metal flashing at corner of the window struck him near the											
											right eye. Mr. Avila requested an ambulance which arrived shortly and											
											transported him to Mt. Sinai hospital in Queens. On 4/27/21 Mr. Avila reported that the hospital had treated him for a contusion to the eye and											
1000001533	4/26/21 18:30 3066698	50 Bedford Avenue Brooklyn	11237 General Contractor	7184179000 Business	Adams European Contracting Inc	Adams European Contracting Inc.		16217 NYC Dept. of Education	1 Union	Y	transported him to Mrt. Simil hospital in Queren. On 4(27/21 Mr. Avalla reported that the hospital had breated him for a controlucion to the eye and released him with instructions to see his own doctor for a follow-up in a week. Mr. Avalla said he would be out of work for 3-2 days. Business owening (c) tripped backwards from standing height ortoo sanitary pipe stubbed up from the floor. Work- measuring partition	1	0 4/	27/2021	3.5 3/25/2	321 Y	0	90.000 N	6	90		302586672-01-EW-0T
											Business owner (gc) tripped backwards from standing height onto sanitary pipe stubbed up from the floor. Work-measuring partition											500468260-11-GC, 500468298-11-M5, 500468301-11-PL,
1000001538	4/17/2112:05 5171652	2636 HYLAN BLVD Staten to	and 10470 General Contractor	9148862944 Business	Torc, Inc		6	09982 Kimco	4 Non-Union	N	layout Injured party fell off a gang ladder approximately 8"-0" above the floor as	1	0 4/	29/2021	0 1/0/1	000 0	0	5,600 N	3	40		500489311-I1-EL
1000001540	4/28/21 16:28 3426503	60 Front Street Brenklus	11201 General Contractor	6468926230 Business	Urban Atelier Group, LLC	Manhattan Concrete LLC	: 4	Fortis Dumbo Acquisition, i15447 LLC	2 Open Shop	Y	injured party fell off a gang ladder approximately \$'-0" above the floor as they were removing a handrall vertical post, they lost their balance and fell to the around.	1	0 4/	29/2021	7 3/1/2	321 N	5	405,000 Y			26	410 321384364.321384462
													-		2.414		-					

Local Law 78 Injury/Fatality Incident Report April 2021

Incident Unique I			BIN H	ouse Number St	reet Name	Borough Zi	ip Code Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number		Number of Active Permits Issued	s Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury I	Fatality Injur Count	e/Fatality Nur	sber of	Date of			e Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Proposed Number of Stories	Active Permit Number
10000015	142	4/29/219:50	3005992	350 Bera	en St Br	trooklyn	11217 General Contractor	3477763798		345 Management Group Inc		Werleen	62148	350 BERGEN STREET OF 1 NEW YORK LLC	1	0 Non-Union		Joiann Alms Da Shu , the fatality who was employed by MMS Construction in c, subcontractor of vivinor, was reported by her co-overless more subcontractor of vivinor, was reported by her co-overless more subcontractor of vivinor from Shu		1 .	1/29/2021	1.5	4/29/2021	•	1	7.483	r Y		6	320012955-01-F0, 320012955-01-F0 EA, 320012955-01-FMB, 320012955-01-FMB, 32001295-01-FMB, 3
10000015	143	4/28/21 9:30	3058246	Will 141 Stree	oughby it Br	trookhvn	11201 General Contractor	7186793778	tndividual			Meiric Svitems Corp.	256	141 Willoughby Properl 3 Investors, LLC		5 Cosin Shoo	Y	Worker was installing in their waterprofiting for this on grade foundation, which is neath grade to the and are disselled quited for their case arisons. We want lead on his back and medical attention was given to the right desired in the case of their case of their disselled in the case of their disselled in their case of their disselled in case of their disselled in their their disselled	1	ā ·	1/30/2021	2	1/28/2021	,	3	354.000	Y		24	21159316-61-FQ, 211593116-61-FQ-K, 321593116-61-FM, 321593116-61-FM, 321593116-64-FK, 346007646-61-60-07
10000015		4/27/21 10:00 4/27/21 10:00		4 Nostrand Nost	rand Avenue Br		11205 Subcontractor 11205 General Contractor	9292285181 7184088842				International Concrete	2830 Dont have it	4 Preferred GC Group, Inc. BAIS YAAKOV DKHAL ADAS YEREIM		1 Non-Union 5 Non-Union	Y	Laborer was struck in chest and clavicle region, causing laborer to get injured. A worker got hit in the chest by a rebar that got stuck in the excivator showl while digging. Work performed at the time, Legging and working on the devator etc.	1		5/5/2021 5/5/2021		12/7/2020		4	23,800			3	3 320416867-01-FO-EA 320416867-01-FO, 320416867-01-FO EA, 320416867-01-NB, 3 320415867-01-FL 800138470-11-FN