

Local Law 78 Injury/Fatality Incident Report November 2023

Incident Unique ID	Incident Number	Incident Date & Time	BSN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Status Info	Construction Worker Involved Flag	Injury/Fatality Incident Description Details	Injury Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Date of Equipment	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number
1000003789	n/a	11/16/2023 15:30	3429595	180	Ashland Pl	Brooklyn	11217	Subcontractor	2016972055	Individual		Person in Control of Site	Melbury Concrete Inc	L55M #2324	Rockrose LLC	15	Open Shop	Y	A laborer employed by Highbury Concrete was working on the 7th floor landing rebar. Employee was bent over working with rebar when a V-Doka shoring post, recently installed adjacent to the employees work area, fell over striking the employee in the back. Employee sustained an unknown back injury requiring 911 to be called with EMS and FONY responding to the scene. EMS & FONY removed the employee and administered aid. 1:30pm incident time. 3:40pm called 911. 3:50pm EMS on scene. 4:00pm employee removed by EMS. 4:05pm FONY Engine#219 on scene. 4:25pm employee removed by EMS.	1	0	11/17/2023	8	8/8/2022	N	1	447,000 Y		51	580	80044144-15P 121208248-01-70, 121208248-16-FO-A, 121208248-17-1P	32150113-01-NB, 800427648-01-5T, 800427674-01-1N, 800389919-01-5P, 800390091-01-0N, 800361282-01-3P-A, 800780120-01-1N, 800300091-01-2P-A, 800300410-01-0N-A, 800300200-01-1P-A, 800304500-01-0N, 800312480-01-1N, 800320210-01-1P-A, 800320500-01-1P-A, 800320500-01-2P-A, 800320500-01-3P-A, 800320500-01-4P-A, 800320500-01-5P-A, 800320500-01-6P-A, 800320500-01-7P-A, 800320500-01-8P-A, 800320500-01-9P-A, 800320500-01-10P-A, 800320500-01-11P-A, 800320500-01-12P-A, 800320500-01-13P-A, 800320500-01-14P-A, 800320500-01-15P-A, 800320500-01-16P-A, 800320500-01-17P-A, 800320500-01-18P-A, 800320500-01-19P-A, 800320500-01-20P-A, 800320500-01-21P-A, 800320500-01-22P-A, 800320500-01-23P-A, 800320500-01-24P-A, 800320500-01-25P-A, 800320500-01-26P-A, 800320500-01-27P-A, 800320500-01-28P-A, 800320500-01-29P-A, 800320500-01-30P-A, 800320500-01-31P-A, 800320500-01-32P-A, 800320500-01-33P-A, 800320500-01-34P-A, 800320500-01-35P-A, 800320500-01-36P-A, 800320500-01-37P-A, 800320500-01-38P-A, 800320500-01-39P-A, 800320500-01-40P-A, 800320500-01-41P-A, 800320500-01-42P-A, 800320500-01-43P-A, 800320500-01-44P-A, 800320500-01-45P-A, 800320500-01-46P-A, 800320500-01-47P-A, 800320500-01-48P-A, 800320500-01-49P-A, 800320500-01-50P-A, 800320500-01-51P-A, 800320500-01-52P-A, 800320500-01-53P-A, 800320500-01-54P-A, 800320500-01-55P-A, 800320500-01-56P-A, 800320500-01-57P-A, 800320500-01-58P-A, 800320500-01-59P-A, 800320500-01-60P-A, 800320500-01-61P-A, 800320500-01-62P-A, 800320500-01-63P-A, 800320500-01-64P-A, 800320500-01-65P-A, 800320500-01-66P-A, 800320500-01-67P-A, 800320500-01-68P-A, 800320500-01-69P-A, 800320500-01-70P-A, 800320500-01-71P-A, 800320500-01-72P-A, 800320500-01-73P-A, 800320500-01-74P-A, 800320500-01-75P-A, 800320500-01-76P-A, 800320500-01-77P-A, 800320500-01-78P-A, 800320500-01-79P-A, 800320500-01-80P-A, 800320500-01-81P-A, 800320500-01-82P-A, 800320500-01-83P-A, 800320500-01-84P-A, 800320500-01-85P-A, 800320500-01-86P-A, 800320500-01-87P-A, 800320500-01-88P-A, 800320500-01-89P-A, 800320500-01-90P-A, 800320500-01-91P-A, 800320500-01-92P-A, 800320500-01-93P-A, 800320500-01-94P-A, 800320500-01-95P-A, 800320500-01-96P-A, 800320500-01-97P-A, 800320500-01-98P-A, 800320500-01-99P-A, 800320500-01-100P-A
1000003790	42459	11/17/2023 11:15	1024730	264	West 46th Street	Manhattan	10011	Person in Control of Site	646430349		Construction Superintendent	Person in Control of Site	Tolent General Contracting	221	Estel Development	3	Open Shop	Y	While stacking formwork for the right side linear	1	0	11/21/2023	4	11/16/2023	N	0	830,000 Y		58	1104	80082748-11-1P 80037402-10-0C, 80037402-11-0C, 80037402-12-0C, 80037402-13-0C, 80037402-14-0C, 80037402-15-0C, 80037402-16-0C, 80037402-17-0C, 80037402-18-0C, 80037402-19-0C, 80037402-20-0C, 80037402-21-0C, 80037402-22-0C, 80037402-23-0C, 80037402-24-0C, 80037402-25-0C, 80037402-26-0C, 80037402-27-0C, 80037402-28-0C, 80037402-29-0C, 80037402-30-0C, 80037402-31-0C, 80037402-32-0C, 80037402-33-0C, 80037402-34-0C, 80037402-35-0C, 80037402-36-0C, 80037402-37-0C, 80037402-38-0C, 80037402-39-0C, 80037402-40-0C, 80037402-41-0C, 80037402-42-0C, 80037402-43-0C, 80037402-44-0C, 80037402-45-0C, 80037402-46-0C, 80037402-47-0C, 80037402-48-0C, 80037402-49-0C, 80037402-50-0C, 80037402-51-0C, 80037402-52-0C, 80037402-53-0C, 80037402-54-0C, 80037402-55-0C, 80037402-56-0C, 80037402-57-0C, 80037402-58-0C, 80037402-59-0C, 80037402-60-0C, 80037402-61-0C, 80037402-62-0C, 80037402-63-0C, 80037402-64-0C, 80037402-65-0C, 80037402-66-0C, 80037402-67-0C, 80037402-68-0C, 80037402-69-0C, 80037402-70-0C, 80037402-71-0C, 80037402-72-0C, 80037402-73-0C, 80037402-74-0C, 80037402-75-0C, 80037402-76-0C, 80037402-77-0C, 80037402-78-0C, 80037402-79-0C, 80037402-80-0C, 80037402-81-0C, 80037402-82-0C, 80037402-83-0C, 80037402-84-0C, 80037402-85-0C, 80037402-86-0C, 80037402-87-0C, 80037402-88-0C, 80037402-89-0C, 80037402-90-0C, 80037402-91-0C, 80037402-92-0C, 80037402-93-0C, 80037402-94-0C, 80037402-95-0C, 80037402-96-0C, 80037402-97-0C, 80037402-98-0C, 80037402-99-0C, 80037402-100-0C	
1000003792		11/17/2023 14:18	1089322	2033	5 Avenue	Manhattan	10035	General Contractor	9142468292	Business	Chatsworth Builders	Person in Control of Site	Agri Electrical Ltd d/b/a Peninsula Electric	603849F	2013 National Back Theatre Way	16	Open Shop	Y	Worker was installing telecom boxes and stated that he was standing on the ground lifting the ladder and fell backwards. Worker was carrying formwork on the 48th floor. He was using a prybar as a club and accidentally hit a rebar. The prybar bounced back and hit him in the face causing injury to his mouth.	1	0	11/21/2023	7	9/9/2023	N	0	16,543 Y		22	259	80038101-01-NB, 80038101-02-NB, 80038101-03-NB, 80038101-04-NB, 80038101-05-NB, 80038101-06-NB, 80038101-07-NB, 80038101-08-NB, 80038101-09-NB, 80038101-10-NB, 80038101-11-NB, 80038101-12-NB, 80038101-13-NB, 80038101-14-NB, 80038101-15-NB, 80038101-16-NB, 80038101-17-NB, 80038101-18-NB, 80038101-19-NB, 80038101-20-NB, 80038101-21-NB, 80038101-22-NB, 80038101-23-NB, 80038101-24-NB, 80038101-25-NB, 80038101-26-NB, 80038101-27-NB, 80038101-28-NB, 80038101-29-NB, 80038101-30-NB, 80038101-31-NB, 80038101-32-NB, 80038101-33-NB, 80038101-34-NB, 80038101-35-NB, 80038101-36-NB, 80038101-37-NB, 80038101-38-NB, 80038101-39-NB, 80038101-40-NB, 80038101-41-NB, 80038101-42-NB, 80038101-43-NB, 80038101-44-NB, 80038101-45-NB, 80038101-46-NB, 80038101-47-NB, 80038101-48-NB, 80038101-49-NB, 80038101-50-NB, 80038101-51-NB, 80038101-52-NB, 80038101-53-NB, 80038101-54-NB, 80038101-55-NB, 80038101-56-NB, 80038101-57-NB, 80038101-58-NB, 80038101-59-NB, 80038101-60-NB, 80038101-61-NB, 80038101-62-NB, 80038101-63-NB, 80038101-64-NB, 80038101-65-NB, 80038101-66-NB, 80038101-67-NB, 80038101-68-NB, 80038101-69-NB, 80038101-70-NB, 80038101-71-NB, 80038101-72-NB, 80038101-73-NB, 80038101-74-NB, 80038101-75-NB, 80038101-76-NB, 80038101-77-NB, 80038101-78-NB, 80038101-79-NB, 80038101-80-NB, 80038101-81-NB, 80038101-82-NB, 80038101-83-NB, 80038101-84-NB, 80038101-85-NB, 80038101-86-NB, 80038101-87-NB, 80038101-88-NB, 80038101-89-NB, 80038101-90-NB, 80038101-91-NB, 80038101-92-NB, 80038101-93-NB, 80038101-94-NB, 80038101-95-NB, 80038101-96-NB, 80038101-97-NB, 80038101-98-NB, 80038101-99-NB, 80038101-100-NB	
1000003793	4843651	11/21/2023 8:30	4003053	26-38	Jackson Ave	Queens	11101	General Contractor	6462053128	Individual		Person in Control of Site	Cross Country Construction	29618	Rakic Realty LLC	1	Open Shop	Y		1	0	11/21/2023	2	6/5/2023	Y	0	10,000 Y		53	556	000008144 00056476, 00059713, 00064897, 00070029, 00070430, 00071764, 00077710, 00079480, 00079487, 00079806, 00080542, 00080548, 00080748, 00081208, 00083047, 00084796, 00084721, 00084745, 00084767, 00084867	
1000003795		11/17/2023 14:50	4436573	47150	50 Aw	Queens	11101	General Contractor	9142468292	Business	Congress Builders LLC	Person in Control of Site	Gotham Drywall Inc.	600734	50th & 5th LLC	21	Open Shop	Y	N/A	1	0	11/21/2023	7	9/17/2020	N	0	76,000 Y		12	125	00081677, 00081687	
1000003796	DOB	11/21/2023 10:30	1038892	126	East 57th Street	Manhattan	10022	General Contractor	2128494800	Business	Phase Construction	Person in Control of Site	Trident Construction	0651630	MWR 1326, LLC	1	Open Shop	Y	Per witness statements, Mr. Armando Ferris Medina (concrete carpenter), while shoulder carrying the panel, slipped/lost his footing and fell forward onto the 3rd floor concrete slab with the Doka panel which he was carrying striking him in the injured. SSM called and notified NY DOB as well and a Safety Stand Down was performed with the whole project involved to prevent this type of incident.	1	0	11/21/2023	2	11/2/2023	N	1	230,000 Y		29	345	00055684 00099447-11-0C, 00099447-13-0T, 00099447-14-0N, 00099447-15-0P, 00099447-16-0V, 00099447-17-0C, 00099447-18-0V, 00099447-19-0V, 00099447-20-0V, 00099447-21-0V, 00099447-22-0V, 00099447-23-0V, 00099447-24-0V, 00099447-25-0V, 00099447-26-0V, 00099447-27-0V, 00099447-28-0V, 00099447-29-0V, 00099447-30-0V, 00099447-31-0V, 00099447-32-0V, 00099447-33-0V, 00099447-34-0V, 00099447-35-0V, 00099447-36-0V, 00099447-37-0V, 00099447-38-0V, 00099447-39-0V, 00099447-40-0V, 00099447-41-0V, 00099447-42-0V, 00099447-43-0V, 00099447-44-0V, 00099447-45-0V, 00099447-46-0V, 00099447-47-0V, 00099447-48-0V, 00099447-49-0V, 00099447-50-0V, 00099447-51-0V, 00099447-52-0V, 00099447-53-0V, 00099447-54-0V, 00099447-55-0V, 00099447-56-0V, 00099447-57-0V, 00099447-58-0V, 00099447-59-0V, 00099447-60-0V, 00099447-61-0V, 00099447-62-0V, 00099447-63-0V, 00099447-64-0V, 00099447-65-0V, 00099447-66-0V, 00099447-67-0V, 00099447-68-0V, 00099447-69-0V, 00099447-70-0V, 00099447-71-0V, 00099447-72-0V, 00099447-73-0V, 00099447-74-0V, 00099447-75-0V, 00099447-76-0V, 00099447-77-0V, 00099447-78-0V, 00099447-79-0V, 00099447-80-0V, 00099447-81-0V, 00099447-82-0V, 00099447-83-0V, 00099447-84-0V, 00099447-85-0V, 00099447-86-0V, 00099447-87-0V, 00099447-88-0V, 00099447-89-0V, 00099447-90-0V, 00099447-91-0V, 00099447-92-0V, 00099447-93-0V, 00099447-94-0V, 00099447-95-0V, 00099447-96-0V, 00099447-97-0V, 00099447-98-0V, 00099447-99-0V, 00099447-100-0V	
1000003797		11/9/2023 14:55	4000000	4401	Northern Blvd	Queens	11101	General Contractor	7182608940	Business	NY Developers & Management LLC	Person in Control of Site	Sandstone Structures LLC	GC-617977	Silverstein Properties LLC	22	Open Shop	Y	The worker was taking a 5 gallon bucket of waterproofing material up the stairs and claimed to have fallen. Worker allegedly was walking down from 5th floor to 4th floor when he claims to have missed a step, lost his balance, and fell to the ground. Unknown injuries but ambulance was called.	1	0	11/22/2023	7	10/16/2023	N	0	430,000 Y		13	175	00082807-11-0C, 00082807-12-0C, 00082807-13-0C, 00082807-14-0C, 00082807-15-0C, 00082807-16-0C, 00082807-17-0C, 00082807-18-0C, 00082807-19-0C, 00082807-20-0C, 00082807-21-0C, 00082807-22-0C, 00082807-23-0C, 00082807-24-0C, 00082807-25-0C, 00082807-26-0C, 00082807-27-0C, 00082807-28-0C, 00082807-29-0C, 00082807-30-0C, 00082807-31-0C, 00082807-32-0C, 00082807-33-0C, 00082807-34-0C, 00082807-35-0C, 00082807-36-0C, 00082807-37-0C, 00082807-38-0C, 00082807-39-0C, 00082807-40-0C, 00082807-41-0C, 00082807-42-0C, 00082807-43-0C, 00082807-44-0C, 00082807-45-0C, 00082807-46-0C, 00082807-47-0C, 00082807-48-0C, 00082807-49-0C, 00082807-50-0C, 00082807-51-0C, 00082807-52-0C, 00082807-53-0C, 00082807-54-0C, 00082807-55-0C, 00082807-56-0C, 00082807-57-0C, 00082807-58-0C, 00082807-59-0C, 00082807-60-0C, 00082807-61-0C, 00082807-62-0C, 00082807-63-0C, 00082807-64-0C, 00082807-65-0C, 00082807-66-0C, 00082807-67-0C, 00082807-68-0C, 00082807-69-0C, 00082807-70-0C, 00082807-71-0C, 00082807-72-0C, 00082807-73-0C, 00082807-74-0C, 00082807-75-0C, 00082807-76-0C, 00082807-77-0C, 00082807-78-0C, 00082807-79-0C, 00082807-80-0C, 00082807-81-0C, 00082807-82-0C, 00082807-83-0C, 00082807-84-0C, 00082807-85-0C, 00082807-86-0C, 00082807-87-0C, 00082807-88-0C, 00082807-89-0C, 00082807-90-0C, 00082807-91-0C, 00082807-92-0C, 00082807-93-0C, 00082807-94-0C, 00082807-95-0C, 00082807-96-0C, 00082807-97-0C, 00082807-98-0C, 00082807-99-0C, 00082807-100-0C	
1000003802		11/27/2023 14:30	4634423	42-06	Oakland Street	Queens	11101	General Contractor	2123885700	Individual		Person in Control of Site	NA	BLOG	1	Open Shop	Y		1	0	11/27/2023	7	6/7/2023	N	0	980,000 Y		80	850	00052873-11-0C, 00052873-12-0C, 00052873-13-0C, 00052873-14-0C, 00052873-15-0C, 00052873-16-0C, 00052873-17-0C, 00052873-18-0C, 00052873-19-0C, 00052873-20-0C, 00052873-21-0C, 00052873-22-0C, 00052873-23-0C, 00052873-24-0C, 00052873-25-0C, 00052873-26-0C, 00052873-27-0C, 00052873-28-0C, 00052873-29-0C, 00052873-30-0C, 00052873-31-0C, 00052873-32-0C, 00052873-33-0C, 00052873-34-0C, 00052873-35-0C, 00052873-36-0C, 00052873-37-0C, 00052873-38-0C, 00052873-39-0C, 00052873-40-0C, 00052873-41-0C, 00052873-42-0C, 00052873-43-0C, 00052873-44-0C, 00052873-45-0C, 00052873-46-0C, 00052873-47-0C, 00052873-48-0C, 00052873-49-0C, 00052873-50-0C, 00052873-51-0C, 00052873-52-0C, 00052873-53-0C, 00052873-54-0C, 00052873-55-0C, 00052873-56-0C, 00052873-57-0C, 0005287		