Incident Incident Person Reporting Type of Person Or Unique ID Number Incident Date & Time BIN House Number Street Name Borough Zip Code Incident Reported By Phone Number Reporting Incident	Organization of Person Person Reporting Reporting Reporting Person in Control of Site Name of Contractor Number			Injury Fatality Injury/Fatality Injury/Fatality Number Injury/Fa Count Count Date of Hours Worked of Em	, , , , , , , , , , , , , , , , , , , ,	Site Proposed  Height  Active Permit Number  M0022023123-A54, M0202023123-A42, M02023123-A29, M022023123-A27, M022023123-A30, M022023123-A43, M022023123-A44, M022023123-A47,
1000003168 1638340 6/1/23 12:00 1015729 250 5th Avenue Manhattan 8873 Person in Control of Site 5167871226	Site Safety Manager All Glaas Metal	1478 Cosmic Realty Partners 19 Open Shop Y	During the unloading of a delivery two of the company mentioned of above worker got in a fist fight which lead to both of them being sent to the hospital by Ambulance.	zer 2 0 6/1/2023 1.5	5/15/2023 N 0 55,000 Y 24	M022023123-A30, M022023123-A43, M022023123-A44, M022023123-A47, M022023123-A50, M022023123-A51, M022023123-A52, M022023123-A53, M022023123-A44, M0022023123-49, M0022023123-A48, M02023123-A55, 106 M022023123-A28, M022023123-A38, M022023123-A41
			On Thursday, June 1st, 2023 at 2:20pm construction worker Jaime Pedraza Tenorio was moving material on the 13th floor when he suddenly collapsed and fell on his back. Ambulance was called and the worker was transported to Jamaica Hospital.	is		
Beach Channel 1000003170 6/1/23 14:20 4623356 5123 Drive Queens 11691 General Contractor 5162779300 Business Chatea	eau GC LLC Martin Feld of Sovereign	604027 EC A1 LP 1 Open Shop Y	Site safety manager Vitaly Nikitski called DOB immediately and spoke to DOB inspector Shivangi Vakil regarding the incident.  Starr Industries is building the scaffold as a subcontractor for the mentioned address. The worker was turning the scaffold system handle to lower the assembly. While turning the handle he accidentally released the lock and the	1 0 6/2/2023 7	6/1/2023 N 0 182,764 Y 17	185 421133339-01-NB
1000003171 6/1/23 12:30 1002364 124 White street Manhattan 10013 Subcontractor 6467564648 Business Starr In	Industries LLC Starr Industries LLC GC-615108	DDC 20 Union Y	handle kicked back on his face. The employee was send to UC with no major injuries, a couple of stiches on the cracked skin The crank unit (handle /Brake stop) were reviewed and deemed to be in good condition. No signs of damage, deterioration or blockages. The incident is reported via phone call to DOB from Site Safety.  On Monday, June 5th, 2023 at 8:10am, Edison Fajardo was walking down Stair A	1 0 6/2/2023 5	5/5/2023 Y 0 16,870 N 14 170	123916487, 72516, 72652, M00672650-P2, M00701334-I1-EW-SD, M00760639-S1, M00760704-I1, M00817189-I1, M00821216-I1, M00824202-I1-EL, M00824722-I1-EL, M00844139-I1-VT, M00854450-I1, M07994239-I1, M08004404-P3, M08004411-P1, M08004418-I1, M08008639-I1, M08008782-P1, M08045061-I1-LA
Beach Channel			between 3rd & 2nd Floors and fell down. Mr. Fajardo claimed he was in pain and could not move. Ambulance was called immediately. PER LEVEL 5 OWNER and foreman John Turza, Mr. Fajardo was let go from the Level 5 company last Wednesday (5/31/2023) but came to the job site to pick up his tools. Site Safety Manager Vitaly Nikitski contacted DOB and notified DOB inspector Jose Collazo of	d y of		
1000003174 6/5/23 8:10 4623356 5123 Drive Queens 11691 General Contractor 5162779300 Business Chatea	eau GC LLC Level 5 Carpentry Corp.	604027 EC A1 LP 1 Open Shop Y	the incident.  On Thursday, June 1 at approximately 12:30 pm, construction worker Elias Saracho fell from a 4th story window to grade level during lunchtime. It was	1 0 6/5/2023 0	1/0/1900 0 0 182,764 Y 17	185 421133339-01-NB
Carpenter 1000003175 6/1/23 12:30 2802508 4180 Avenue Bronx 10466 General Contractor 9148795750 Business BE Bron	ronx Builders, LLC Brophy Brothers	Carpenter Avenue Corner 34377 Associates, LLC 14 Non-Union Y	reported that Mr. Saracho tried to boost himself onto the lower guard rail with his feet to sit on the upper guard rail with his back to the outside, causing him to fall. He did this on his own negligence (worker error). The police were immediately called, and DOB was notified of the accident by construction superintendent.		5/30/2023 N 3 111,793 Y 5	X00599800-I1-GC, X00599800-S1-VT, X00618292-I1-ST, X00677973-I1-PL, X00678060-I1-EW-SD, X00678060-I1-EW-SP, X00700538-I1-FN, X00815475-I1-EL, X00877429-I1-EL, X00882058-I1-EL, X08003387-I1-EL, X08037838-I1-SH, X08037838-S1-SF, X08037910-I1-53 EL  121205524-01-F0-EA, 121205524-01-FO, 121205524-01-NB, 121205524-03-PL, 140857035-01-EW-SD, 140857035-01-EW-SP, M00274900-I1-BE, M00274900-S1-BE,
1000003176 1638460 6/2/23 7:35 1091567 88 East 127th Street Manhattan 10035 General Contractor 2129965100 Business Artimus	nus Construction Inc. Defalco Construction Inc.	3684 126th Street Equities LLC 23 Non-Union Y	The worker was preparing for a concrete pour on the 1st floor when a metal disk like piece fell from above and hit him on the shoulder.		6/13/2022 N 2 175,147 Y 19	M00622031-I1-FN, M00671018-I1-EL, M00724146-I1-PM, M00725480-I1-SH, M00725483-I1-PM, M00728835-I1-EL, M00729763-I1-EW-SD, M00737582-I1-VT, M00744139-I1-EL, M00755793-I1-SF, M00833438-I1-EL, M00840839-I1-EL, M00864854-215 I1-EL, M07996305-I1-VT, M07997587-I1-EL
			Victor Chango and 5 other workers from Sandstone were mobilizing a pallet of cement bags using a pallet jack. Victor was in front of the pallet jack pulling with Bryan Lopez and 3 other workers were pushing the pallet jack loaded with cement mix. Bryan claims someone from another trade cut in front of them unaware of them pulling/pushing the pallet jack up the ramp, giving them no time to stop or break. The pallet jack ran over Victor Chango's right ankle injuring him,	nt		
1000003178 6/6/23 9:00 3428896 85 Commercial St Brooklyn 11722 General Contractor 7329619801 Business Ray Bu	Builders Inc Sandstone Structures LLC	37185 Waterview Developer 1 Open Shop Y	Supervision was notified and the ambulance arrived shortly after.  At 10:30AM a mason worker was struck in the head by a 4ft level from the floor above 8ft away. The worker was wearing a hard hat and glasses when struck. The level was being used by an iron worker to spot check the level of the railings. No visible marks or injuries could be found but the worker wanted an ambulance	ne	2/22/2023 Y 1 256,552 Y 9	101 320627103
1000003179 039517493M 6/6/23 10:30 1091687 521 W 134th St Manhattan 10031 General Contractor 9177083700 Business Promet	ethean Builders Maspeth Welding GC-623350	Dan Smilow 5 Open Shop Y	which was called for immediately. EMT came to the site and brought the worker to Mount Sinai for a check up.  06/07/23, 12:05 pm, at time of visual inspection it was noted that the foreman of Commodore Construction reported a worker injured his right ankle during delivery of rebar ops to the 2nd floor. The On-Site Medic from Amphibious examined and	1 0 6/7/2023 3 of ry	1/1/2021 N 1 65 Y 8	M00551052-I1-GC, M00551052-S1-SE, M00551052-S2-FO, M00551052-S3-MS, 81 M00551052-S6-ST
No# Pr DOB West 137Th		NYC Economic Development	treated the worker. The worker was taken off-site by ambulance for further evaluation. 12:09 pm, I notified DOB at 212-602-0431. NYC DOB Construction Safety Enforcement Division Inspector J. Guirgis, Badge # 3339 was here in response to my notification reported to The Department. Partial Stop Work Order			
1000003181 Phone Rep 6/7/23 12:05 1091739 40 Street Manhattan 10037 General Contractor 7325471232 Business Skansk	Ska Commodore Construction Co.  Innovation Contracting Group	25623 Corp. (EDC) 1 Union Y	and (2) violations were issued.  A construction worker fell in permanent concrete stairwell and was found laying down in stairwell landing at 10th floor. No witnesses. No other stuff was found in stairwell besides him. Called and waited for ambulance to take him to the	1 0 6/8/2023 5	6/1/2023 Y 2 246,840 Y 10	175 121207648-01-FO 421747097-01-FO, 421747097-01-NB, Q00207425-I1-ST, Q00217625-I1-PL, Q00217739- I1-EW-SP, Q00217739-S1-EW-SD, Q00721266-I1-FN, Q00785441-I1-SF, Q00785441-I1- SH, Q00789438-I1-EL, Q00790899-I1-EL, Q00878181-I1-EL, Q08005090-I1-EL,
1000003182 N/A 6/7/23 11:00 4619563 98-10 63rd Road Queens 11374 General Contractor 6469984206 Business EFIN M		619584 Chuang Heng Rego Park LLC 14 Non-Union Y	hospital.  Telio Junior Silva Machado a worker of A&E was installing hard wood flooring on the 2nd floor. When installing the hardwood flooring, using a hand held circular		4/17/2023 N 0 28,841 Y 22	220 Q08027211-I1-VT
1000003183 N/A 6/8/23 11:00 3065237 82 Calyer St Brooklyn 11222 Person in Control of Site 7189631128 1000003187 6/7/23 8:00 4518258 244-04 N Conduit Ave Queens 11422 General Contractor 6315631110 Business Citnalta	Other A&E  Ilta Construction Corp Citnalta Construction Corp	Franklin 33 LLC 1 Non-Union Y Department of Design and 25848 Construction 5 Union Y	saw, Telio was cutting the hard wood using his leg as leverage, the saw slipped and cut his thigh. He left the site to see medical treatment.  While team lifting steel angle, one worker complained of lower back pain.	1       0       6/8/2023       4         1       0       6/9/2023       1	6/8/2023 N 0 15,000 Y 7 2/15/2023 Y 0 50,000 Y 2	70 321592308-01NB 420665211-01-FO, 420665211-01-NB, Q00342597-I1-FN, Q00585843-I1-PL, Q00605197- 36 I1-EL
			An incident occurred involving one of the workers on site named Camilo Sanchez during the delivery of wood doors. While in the process of delivering the wood doors on the second floor, the worker allegedly tripped onto the floor. immediate action was taken to ensure the worker's safety and well-being. The designated	e		
1000003188 3908717 6/8/23 12:00 3429049 2177 60 st Brooklyn 11204 General Contractor 7184088842 Individual	74:	41899946 SUW 4 LLC 6 Non-Union Y	emergency protocol was followed, and an ambulance was immediately called to the scene. The worker was then transported to Maimonides Hospital for further medical evaluation and treatment.		2/10/2023 N 0 62,923 Y 8	B00517601-I1-GC, B00517601-S3-MS, B00517601-S5-ST, B00517601-S6-FO-EA, 115 B00517601-S7-SE, B00546629-I1-FN
			Angel Vasquez, a worker for Industry Drywall, was performing carpentry work from a ladder and says he fell. Upon discovery, Angel was holding his left arm in discomfort and requested an ambulance. No witnesses to the fall could be found, and the only accord Angel would give was "I fell". 911 was called to dispatch EMS, but before they arrived, Angel changed his mind and did not want an	d,		
1000003193 6/9/23 15:30 1056547 2686 Broadway Manhattan 10533 Person in Control of Site 2012176626	Other Industry Drywall Corp	2686-2690 Broadway LLC 1 Open Shop Y	ambulance any more and walked off the job under his own free will.  At approximately 11:00 AM, Barr and Barr was notified by Bobby Hansen, Urban Foundations, that a laborer had cut his head while cleaning around the conveyer belt at the excavation. Upon investigation, we found that the injured party was cleaning soil from around the lower end of the conveyer belt when a rock bounced	•	5/1/2023 N 0 120,600 Y 13	144 121207354-01-NB
1000003200 6/9/23 12:00 3336293 4802 10th avenue Brooklyn 11219 General Contractor 6464172900 Individual	Urban Foundation	27925 Maimonides Medical Center 10 Union Y	off the conveyor belt, striking laborer Colin Brown above the right eyebrow resulting in a laceration. The injured party declined an ambulance and walked a block to the Maimonides ER, where he was treated and released. Employee of FWFREEDOM CONSTRUCTION CORP. was walking up the stairs and "lost feeling" in this feet while climbing past the 4th floor in the stairwell. The	1 0 6/12/2023 4	4/19/2023 Y 0 22,000 N 6 78	340761786-01-EW-OT, 340781194-01-EW-OT, 340787624-01-EW-OT, 340799782-01-EW-OT, B00429706-I1-EW-SP, B00429706-I1-PL, B00429708-I1-MS, B00435143-I1-FN, B00483315I1-ST, B0802563-I1-BE
MC GUINNESS 1000003201 6/10/23 11:00 3428943 173 BOULEVARD Brooklyn 11222 General Contractor 7183330924 Business BOSS A	S Associates Inc. FW Freedom Construction Corp GC5114	ARTLIFE 173-175 MCGUINNESS LLC 4 Non-Union Y	employee fell backwards off the 3rd step towards the landing. EMS and FDNY assisted the employee into an ambulance and transported him to Bellevue Hospital for observation. He complained of lower back pain and pain in the right knee. Employee was released from hospital around 4pm and is expected back to work tomorrow.		1/3/2023 N 0 20,086 Y 8	80 321595029-01-FO, 321595029-01-FO EA, 321595029-01-NB, B00231254-I1-ST
			the worker was carrying 2 2x4's, while walking, worker tripped and fell, when found near Sackett street the injured worker was expressing pain to the left side of the body. After the on site medic evaluated the worker it was decided their were no known deformities or injuries however the onsite medic determined the			
	n Atelier Group Manhattan Constructors GC-615447	Gowcan Owner LLC 9 Open Shop Y	worker needed further medical attention and was transported via ambulance to Methodist hospital for further evaluation.  Two workers got into an altercation and one worker kicked the other worker in the		5/15/2023 N 0 371,567 Y 21	B00612352-S3-SE, B00616358-I1-GC, B00612352-I1-GC, B00612352-S1-FO, B00612352- 261.4 S2-ST, B00612352-S4-MS, B00616358-S2-ST, B00616358-S3-SE, B00616358-S4-MS
1000003206 6/12/23 13:05 3426198 532 Neptune Avenue Brooklyn 11224 General Contractor 7187585333 Business Rybak I 1000003208 6/13/23 8:20 3429566 60 Wharf Drive Brooklyn 11222 Person in Control of Site 7182782080		624238 532 Neptune Residential LLC 1 Non-Union Y  2467 M & H realty LLC 4 Open Shop Y	leg causing some bruising. Injured worker went to the hospital and was released. Verizon interior worker "Diego Rumipamba" was carrying a bundle og insulation up the stairs. He stated that he fell. He complained about pain in his left leg knee and back hurting.		6/12/2023 N 0 100,000 Y 22 11/9/2022 N 1 636,457 Y 40	280 320622714-01-NB 452 320909996-01-FO, 320909996-01-NB, 320909996-01-OF EA, 320909996-04-PL
1000003210 6/9/23 8:50 3000462 15 Hanover Place Brooklyn 11201 General Contractor 2017701120 Business Noble 0	e Construction Group, LLC Elicc	605540 Hanover Place Owner, LLC 1 Open Shop Y	Worker entered a restricted area that was barricaded with signage and alleges to have struck back against insulation pins. No visible injury observed. Worker sent to ER as a precaution Released same day with no issues.		4/24/2023 N 1 294,000 Y 34	376 B100588594-I1-GC
WEST SERVICE 1000003211 5178136 6/12/23 12:00 5130986 1000 RD Staten Island 10312 General Contractor 9738821133 Business PRISMA	PRISMATIC DEVELOPMENT CORP	603725 NYC DSNY 6 Union Y	WATERPROOFER ON SITE, WHILE REACHING INTO HIS TOOLBAG FOR GLOVES, WORKER CUT HIS ARM WITH A NON RETRACTABLE CARPET KNIFE.  ON Wednesday JUNE 6TH, 2023 at approximately 6:00PM my HVAC subcontractor	1 0 6/14/2023 5 or	4/22/2022 Y 0 104,000 Y 2	31 510113315, S00313952, S00490341, S00768630, S00792835, S07999592
			by the name Salvatore Simone was on the pier of the property we are working on after work hours. This was the day the fire was raging in Canada, and the air quality was very bad. Salvatore ask one of the neighbors for a glass of water because he was thirsty. A few hours later at m the neighbor called 911 to report			
1000003213 41698 6/7/23 12:00 2081596 2806 Schurz av Bronx 10465 General Contractor 9144694860 Business Dewalt	alt Contracting LLC Construction	623597 JENNY BUI 3 Non-Union N	someone laid out on the floor of the pier. Mr. Salvatore Simone was diseased. The preliminary coroners report states that he died of a heart attack.  WORKER WAS WORKING ON TOP OFF A LADDER ON THE 5TH FL SECURING SOME REFRIGIRETION LINES AND A PIECE OF METAL FALLED IN TO HIS FACE HITTING HIS NOSE WHICH IT MAKE A CUT TO HIS NOSE, WE CALL AN	ne 1 1 6/14/2023 0	1/0/1900 0 1 3,000 N 2 28	2207831830-01-AL, X00416427-I1-PL, x00416427-s1-fn 122812527-03-EW-OT, 122812527-01-EW-OT, 122812527-02-EW-OT, 122812527-04- EW-OT, 122812536-01-EW-OT, 122812536-02-EW-MH, 123038033-01-AL, 123038033- 03-PL, 140786273-01-EQ-OT, 140812486-01-EQ-OT, 140825258-01-EQ-OT, 140951762-
1000003220 6/14/23 8:00 1006472 180 Second Ave Manhattan 10003 Person in Control of Site 9172614223  1000003222 6/14/23 8:53 3337065 245 Cozine Ave Brooklyn 11207 General Contractor 9142468292 Business SAP Co	Superintendent TRV Mechanical Contractors	26623 Robert Stern 12 Non-Union Y 623321 NYC Housing Authority 11 Open Shop Y	AMBULANCE AND WE REPORT THIS TO DOB.  Employee of Walsh Facade was operating lull machine to transport windows when a car in front of the lull machine stopped, causing lull to rear end the stopped car with forklift blade.	1 0 6/15/2023 1 1 0 6/15/2023 0	6/14/2023 N 1 1,530 N 7 96'11" 1/0/1900 0 1 61,664 N 8 68.5	300714822, 340064860, B00478616, B00517691, B00699164, B00711271, B00720993, B00721224, B00736146, B00751386, B00775629
	RIENT GROUP LLC MABE GROUP INC	18 ORIENT GROUP LLC 1 Non-Union Y	a worker tripped and fell at the property. There were no visible injuries however in the sake of caution 911 was called and the worker was taken to the hospital, where he was later released with an assessment that there was no injury.		3/1/2023 N 0 1,800 N 3 35	B00813055-I1-GC
1000003232 6/16/23 10:20 2120214 745 East 141st Street Bronx 10454 Person in Control of Site 9149651500	Construction Superintendent	30283 NYC DDC 1 Union N	Munoz Trucking dump truck collided with Yonkers Contracting Company, Inc.'s excavator's counterweight. Munoz truck driver had no visible injuries, but he called for an ambulance. Truck driver complained of back pain.	1 0 6/19/2023 0	1/0/1900 0 0 150,000 Y 9	110 X00731424-I1-SE
			Allegedly during a garbage dump in the process of adjusting the A frame that lifts the mini containers to accept a basket of derbies the driver moved the lever lifting the A frame which caused Mr. Gonzalez left thumb to be squeezed in between	ng		MO22323123-A-44, MO22323123-A-47, MO22323123-A-48, MO22323123-A-49, MO22323123-A-50, MO22323123-A-51, MO22323123-A-52, MO22323123-A-53, MO22323123-A27, MO22323123-A28, MO22323123-A29, MO22323123-A30, MO22323123-A31, MO22323123-A33, MO22323123-A34, MO22323123-A35, MO22323123-A37, MO22323123-A38, MO22323123-A39, MO22323123-A40, MO22323123-A41, MO22323123-A42, MO22323123-A43, MO22323123-A54,
1000003233 41745 6/16/23 12:00 1015729 250 5th Avenue Manhattan 1001 Person in Control of Site 5157871226	Site Safety Manager	1478 Cosmic 25 Open Shop Y	the A frame and the body of the truck.  DDS worker Lance Peters allegedly trip and fell at exposure #1 (Carroll Street) @ the adjacent property's sidewalk (417 Carroll street Brooklyn NY 11215) while receiving a delivery and bringing in materials. According to witness and coworker Elvis Bartley who was working with Lance Peters and helping bringing in		6/19/2023 Y 0 175,535 Y 25 2	248' MO22323123-A55
1000003234 6/15/23 7:00 3429585 424 Carroll street Brooklyn 11103 General Contractor 7189326342 Business Mega C	a Contracting Group LLC DDS	603805 The Domain Companies 4 Open Shop Y	Elvis Bartley who was working with Lance Peters and helping bringing in materials. Elvis in his statement said that he and Lance were taking a delivery. They had the pipe on the pipe rack pulling it inside the job. The pipe rack got stuck on a "Lip". The pipe fell off and push the pipe rack to Lances feet and Lance fell on the floor and hit his head.		3/23/2023 N 0 383,772 Y 21	130 B00614338-S4-FO, B00719668-I1-FO, B00614338-S6-SE, B00699836-I1-FN
1000003236 6/19/23 11:40 4624423 42-06 Orchard st Queens 11101 General Contractor 2123885700 Individual	N/A	BLDG orchard IIc 1 Open Shop Y	Klisman Perez claims he was working on the second floor with stripping crew, when he claim he was struck by a brace to hold back column formwork. Worker was evaluated by on site medic and PA. EMT was called and arrived 12:30PM. DOB was notified and arrived 2:00pm		5/3/2023 N 0 801,916 Y 69	794 Q00528973
1000003237 6/20/23 9:30 3429318 683 Court Street Brooklyn 11231 General Contractor 6467373143 Individual		26148 RXR 13 Open Shop Y	Worker was working on a scaffold system stripping the underside of the first floor deck. While walking across the plank the worker stated his retractable lanyard on his fall protection locked up, knocking him off balance causing him to trip. He swung back on the fall protection hitting his shoulder on the scaffold. Worker came down off scaffolding using an area lift and walked to the ambulance on his own.	or on	6/12/2023 N 2 252,000 Y 4	86 B00703468, B00796432, B00808021, B00816719, B00826613, B08051315, Boo824402
1000003237 6/20/23 9:30 3429318 683 Court Street Brooklyn 11231 General Contractor 6467373143 Individual 1000003238 1641226 6/20/23 10:00 1091643 310 Hudson Street Manhattan 10013 Person in Control of Site 6467730096	Site Safety Manager ASR	1757 Hudson Square Realty, LLC 3 Union Y	Worker was pulling electrical cable using a pair of linesman pliers. Worker was using 1 hand, pliers came off of wire snapping back into the worker's forehead.		10/11/2022 Y	320 121205864-01-FO, 121205864-01-FO-EA, 121205864-01-NB
			At 1215, Injured party stated he was working on the bicycle platform washing above the 3rd floor brick above windows at about elevation 12'. A coworker was working on the 4th floor level above injured party above 15' right when he felt a scaffold plank slip from under his feet and fell striking injured party on the left			321595449-01-FO-EA, 321595449-01-NB, B00238667-I1, B00238671-I1-EW-SD,
Hunter 1000003239 6/15/23 12:05 3827686 489 State Street Brooklyn 11217 General Contractor 2123216800 Business Group,	er Roberts Construction p, LLC Rad & D'Aprile Inc	32144 Alloy 11 Union Y	side of his back under his left shoulder. Injured party was brought by ambulance to Methodist Hospital and escorted by a coworker named Llio.  Work was being performed on roof level (installation of steel and welding) with overhead protection in place at roof level, fireguard in place and OSHA Barriers in	1 0 6/20/2023 4	3/8/2023 Y 2 173,000 Y 9	B00238671-I1-EW-SP, B00590787-I1-EW-SD, B00622684, B08030037-P1, B000789251- 164 I1-SH, B08002082-I1, B0802260-I1
reported, not 1000003243 given 6/20/23 7:30 1023462 140 W57th Street Manhattan 10019 General Contractor 2129521290 Business Univers	ersal Management Universal Management	140 W57th Street Building, 31856 LLC 14 Non-Union Y	place on all floors. subcontractor was informed to put overhead protection back on 3rd floor above work area before proceeding with any work in basement Worker entered work area in basement to shovel debris before protection was installed. A piece of concrete dislodged from the upper floor and fell hitting the worker in the hand.		10/1/2015 N 2 110,000 N 14 230	M00628979, M00419400, M00419407, M00419416, M00426213 - S-2, M00426213 - S-3, M00426213 L1, M00426213 S-1, M00426213 S-4, M00461800, M00658686, M00664271, M00664978, M00794934
1000003243 given 6/20/23 7:30 1023462 140 W57th Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University of Street Mannattan 10019 General Contractor 2129521290 Business University Office Street Mannattan 10019 General Contractor 2129521290 Business University Office Street Mannattan 10019 General Contractor 2129521290 Business University Office Street Man	Construction Superintendent Universal Management Construction	221 Extell 3 Open Shop N	While testing a footing rock anchor, the rock anchor extension bar separated from the coupler and landed on his top left foot causing a bone bruise.  John Conklin stepped over the railings at the roof level and the plywood gave way	om 1 0 6/21/2023 0	1/0/1900 0 0 800,010 Y 14 230 60	1067 121208326-01-FO, 121208326-01-NB, M00582748-I1-FN
	J&A Concrete Corp ing Builders Group, An	24673 School Construction Authority 1 Union Y	and he fell to the floor below hitting caps on the rebar  worker slipped off the second step of a job site ladder leading to the stripping floor above, worker is a form carpenter working on the deck, worker was taken to	1 0 6/22/2023 4.5 o	10/17/2016 Y 1 100,000 Y 3	46 201204268-01-NB
	OM Company Glenco Contracting Group, Inc	604029 204 4th Avenue. LLC 1 Non-Union Y	the ER via Ambulance, worker is returned to work the next day.  At about 4:10pm on June 20th the injured worker (Mr. Glenn Manno) was a Loc.580 iron worker conducting layout on an amenities roof of the 27th floor. It was reported that he had accessed the q-decking of the roof from a scissor lift and stepped on a unsecured piece of decking covering a hatchway opening (approximately 2ft X 3 ft.). The q-decking and Mr. Manno fell approx 15 feet to	1 0 6/22/2023 6.5	5/22/2023 N 0 500 Y 12	172 3429295
1000003248 6/20/23 16:10 1088749 1 Madison Ave. Manhattan 10010 Person in Control of Site 2129732999	Site Safety Manager Force Installations Inc.	1746 SL Green 1 Open Shop Y	approximately 2ft X 3 ft. ) . The q-decking and Mr. Manno fell approx 15 feet to the concrete deck below sustaining broken bones, internal injuries and head trauma.	1 0 6/23/2023 9	2/1/2016 Y 3 1.4 mil Y 27	402 123742101

000003249	6/21/23 13:30 3848334	1100 Myrtle Ave Brooklyn	11206 Subcontractor	9146544870 Business	Pro Safety Services, a Div. of Risk Strategies	Shannon Constr.	1629 SWDM MYRTLE LLC	4 Non-Union Y	Laborer was transporting sheetrock on an A-frame when he caught his hand between a frame and a guard rail injuring his right hand (minor laceration),	1	0 6/23/2023	6 6/21/2	023 N	2	298,000 Y		11	115 321592157-01-NB, 322092737-01-EQ-OT, 322092739-01-DM, B00607531-I1-FN
	, ,	,							Worker of B&V Contracting Enterprises Inc. was performing patching work and was instructed not to use a Baker's scaffold that a co-worker was constructing.		, ,				,			210179929, 210179929-01-FO, 210179929-01-FO EA, 210179929-01-NB, 220707661, 220716330, X00214433, X00341659, X00554825, X00579264, X00592810, X00639420,
00003250	6/22/23 10:48 2129393	575 Exterior Street Bronx	10451 General Contractor	9142468292 Business	Chatsworth Builders LLC	B&V Contracting Enterprises Inc. GC600849	Bronx Point Owner LLC	21 Open Shop Y	He was observed using both arms to pull himself up onto the platform of the Baker's scaffold. As he attempted to place a knee on the platform, it tilted to the right causing him to fall through the center of the scaffold.	1	0 6/23/2023	3 6/22/2	023 N	1	500,725 Y		23	220716330, X00214433, X00341659, X00554825, X00579264, X00592810, X00639420, X00648204, X00649158, X00787580, X00822724, X00824542, X07995167, X07995884, 235 X08019729, X08051554 121205926-01-fo-ea, 141023719-01-ew-ot, cn00112422, cn00112522, m00209825-L1-Pl, m00209885-L1-ms, m00222265-L1-st, m00247246-l1-ew-sd, m00247246-l1-EW-sp,
000003252 1641373	6/22/23 9:00 1090663	165 Broome Street Manhattan	10002 General Contractor	7188758160 Business	Monadnock Construction	Cosan	Attorney Street Associates, 3427 LLC	20 Non-Union Y	Worker was found to be trapped between our property line and the neighboring building. Emergency services was called to extract the worker. He was taken to local hospital for observation.	1	0 6/23/2023	2 5/16/2	023 N	2	274,188 Y		15	m00517163-L1-fn, m00782596-I1-el, m00810554-L1-sf, m00836865-I1-pmm, m08010060-II-el, m08010175-I1-el, m08015581-I1-vt, M08015601-L1-sh, m08015614-185 PM, m08038218-I1-EL
000003253	6/22/23 8:00 3339413	590 Clinton St. Brooklyn	11231 General Contractor	6467021812 Business	Adam's European Contracting Inc.	Arcadia Electrical	New York City Housing 16217 Authority	2 Union Y	Worker took the hole saw to drill a hole and there was a slug left inin the hole saw by someone else while removing the slug and worker slice his finger	1	0 6/23/2023	1 3/21/2	022 Y	0	4,000 Y		3	80 321726334-01-NB, B00415595-I1-EL
00003254	6/23/23 12:00 3429295	653 Union Street Brooklyn	11215 General Contractor	9172272636 Business	Leeding Builders Group	Glenco Contracting Group, Inc	604029 204 4th Avenue LLC	1 Non-Union Y	While moving a concrete form worker tripped and fell backwards bruising his left leg and left arm	1	0 6/25/2023	5 6/12/2	023 N	1	500 Y		12	172 342929
00003257	6/21/23 13:30 5013250	44 Victory Blvd Staten Island	10301 General Contractor	9142378244 Business	ECI Contracting, LLC	North Stucco	Freehold S.L. Limited 610806 Partnership	4 Open Shop Y	Worker claims they fell backwards on a scaffolding stair and injured their bacl. Local ambulance came and brought worker to the hospital via a stretcher.	1	0 6/26/2023	24 5/24/2	023 N	2	250,000 Y		6	65 520381097-01-FO, 520381097-01-NB, 520381097-02-PL, 520399621-01-AL
									The worker was moving a box fan with his partner from the 2nd floor up to the 3rd floor via staircase C in the commercial building. When they got to the 5th step of the riser from the mid landing to the 3rd floor Mr. Carriel while in front leading the way stepped up on to the 6th step and slipped, losing his balance. He tried to steady himself by grabbing the fan and cut himself on a part of the fan on his left forearm. Upon arriving on the scene, I was told that Mr. Carriel was complaining									121190308-01-EQ FN, 121190308-01-NB, 121190308-04-PL, 123842235-01-AL,
000003260	6/26/23 10:50 1089807	76 11th avenue Manhattan	10011 General Contractor	2012067220 Individual	Construction	Capstone Contracting	1924 76 Eleventh Partners LLC	9 Open Shop Y	of pain in his head, back and left arm. 911 was called and Mr. Carriel was taken to Bellevue Hospital  A worker was struck by a piece of rebar that fell and deflected off the foundation	1	0 6/27/2023	4 4/3/2	023 N	0	990 Y		36	140713887-01-EQ OT, 140733008-01-EQ OT, 140798082-01-EQ OT, 140830475-01-EC 373 OT, 141021720-01-EQ OT
00003262 41791	6/26/23 15:50 1000000	740 Eighth Avenue Manhattan	10036 Person in Control of Site	6464130349	Construction Superintendent	Trident	221 Extell Development	3 Open Shop Y	form work hitting the worker in the upper lip.	1	0 6/27/2023	7 1/2/2	023 N	2	810,000 Y		60	1067 121208326-01-FO, 121208326-01-FO-EA, M00582748-I1-FN
00002264	6/27/23 8:00 3426198	E22 Montuno Avonuo - Prooklyn	11224 General Contractor	7187585333 Business	Rybak Development	RC Structures	624238 532 Neptune Residential LLC	1 Non-Union Y	Worker was moving forms with another worker. The form got struck and fell, hitting his ankle. No bruising or swelling observed, just statement of some pain.	1	0 6/27/2023	1 3/1/2	022 N	0	100,000 Y		20	280 320622714-01-NB
00003264	6/27/23 8:00 3426198	532 Neptune Avenue Brooklyn	11224 General Contractor	/18/585333 Business	Rybak Development	RC Structures	Greenpoint Manufacturing	1 Non-Union Y	Worker refused medical care and just wanted to go home and ice it.	1	0 6/2//2023	1 3/1/2	U23 N	U	100,000 Y		20	321599212-01-EA, 321599212-01-FO, 321599212-01-NB, B00460527-I1-ST, B0062855-
00003265	6/24/23 17:00 3000000	203 Newport street Brooklyn	11212 General Contractor	7189326342 Business	Mega Contracting Group LLC  Construction	Mega Contracting	603805 and Design Center (GMDC)	5 Non-Union Y	Worker inexplicably felt "dizzy", while installing plywood panels  Worker was struck by piece of rebar while working below a foundation wall that	1	0 6/28/2023	8 11/1/2		0	215,213 Y		7	95 I1-FN
000003266 41791 000003268 41797	6/26/23 15:50 1000000 6/27/23 15:50 3429228	<ul><li>740 Eighth Avenue Manhattan</li><li>75 Dupont Street Brooklyn</li></ul>	10036 Person in Control of Site  11222 General Contractor	6464130349 2124191930 Business	Superintendent Omnibuild Construction	Tident  Moncon, Inc.	221 Extell Develpment 29604 Dupont Street Owner 2 LLC	3 Open Shop Y 5 Open Shop Y	was being constructed  A worker was cutting a piece of rigid styrofoam insulation w/ a knife, the knife slipped and cut the worker's forearm.	1	0 6/28/2023 0 6/28/2023	8 1/1/2 8 4/19/2		2 n	810,000 Y 50,000 Y		50 7	1070 121208326-01-FO, 121208326-01-FO-EA, M00582748-I1-FN 321805855-01-FO, 321805855-01-FO EA, 321805855-01-NB, 321805855-04-PL, 127 322100347-02-EQ OT
00003268 41797	6/27/23 15:50 3429228 6/27/23 16:00 3429227	65 Dupont Street Brooklyn	11222 General Contractor  11222 Subcontractor	3474950812 Individual	JZana Sonstituction	MONCON	2685 Peter serpico	1 Non-Union Y	Worker installing waterproofing (styrofoam and hydro duct) while using a box cutter cutting styrofoam blade slipped and cut his left forearm	1	0 6/28/2023	8 4/19/2		0	450,000 Y		10	
		<b>,</b>							Cesar Perez was in Stair A removing pieces of sheetrock down from the 25th floor to the 24th floor. According to the worker (Cesar Perez) he was walking backward down the stairs and lost his footing at the top step of the 24th floor causing him to lose his balance and fall backward down the flight of stairs. Upon crying for help, another worker (Sergio Jaime-Cardona) found Cesar lying on the floor and					-				5223030
0003270	6/27/23 8:45 3429566	ŕ	11222 Person in Control of Site	7182782080	Site Safety Manager		2639 Ninth Ave Construction BSD 685 New York Propco	3 Non-Union Y	called his supervisor.	1	0 6/29/2023	2 1/3/2		0	636,000 Y		40	400 320909996-01-FO, 320909996-01-FO EA, 320909996-01-NB
0003271	6/29/23 10:30 1035737	685 5th Ave Manhattan	10151 Subcontractor	7189375353 Business	Skyline Restoration Inc.	OLJ Services	3365 LLC, c/o SHVO	1 Non-Union Y	A worker fell down the scaffold stairs  Marco Isidro came to the CM and SSM to notify them that he had cut his hand using a hand tool to open a paint can when it slipped and struck his left wrist. He indicated there were no witnesses, then left on his own power to go to an urgent care center. SSM notified DOB, inspector Guirgis (badge #3339) arrived, walked	1	0 6/29/2023	2 6/12/2	023 N	0	100 N	14 178		M00652988-I1-GC
0003273	6/28/23 14:00 1056547	2686 Broadway Manhattan	10533 Person in Control of Site	2012176626	Other Leeding Builders Group, An	JEM Contracting Corp.	2686-2690 Broadway LLC	1 Open Shop Y	the site and left with no deficiencies to report and no violations issued.	1	0 6/29/2023	6 6/14/2		0	120,600 Y		13	144 121207354-01-NB
003274	6/28/23 12:35 3428521	29 Huron Street Brooklyn  Beach Channel	11222 General Contractor	9172272636 Business	AECOM Company	New York Renaissance	604024 QBDK Huron LLC	1 Non-Union Y	worker fell while climbing over a pallet of window located inside the hoist car.  On Thursday, June 29th, 2023 at 8:20am, Chateau GC LLC superintendent Alban Zaimi was inspecting apartment kitchen cabinets and was taking pictures with his phone. When he stepped back he accidentally tripped over a small stock of tiles that was stored on the floor. Mr. Zaimi fell on his back and injured his left ankle.	1	0 6/29/2023	6 4/3/2	023 N	1	300 Y		14	150 s321385700
003275	6/29/23 8:20 4623356		11691 Owner	5162779300 Business	Chateau GC LLC		EC A1 LP	1 Open Shop N	911/Ambulence was called and Mr. Zaimi was taken to St. John's hospital  At approximately 11:10 am General Contractor was notified of a worker related incident. Upon arriving on the second floor General Contractor met with the injured worker and his foreman and brought him back to the field office where he received first aid. Worker explained that while on the second floor west side	1	0 6/29/2023	0 1/0/1	900 0	0	182,764 Y		17	185 421133339-01-NB
003276	6/28/23 11:00 4624033 23-10	42nd Road Queens	11101 General Contractor	6467409345 Business	Suffolk Construction Company	Highrise safety Systems, Inc. d/b/a Park Avenue Concrete GC-611358	Albanese Development Corporation	13 Open Shop Y	passing material (rebar sticks) up to his partner on the 3rd floor link beam his partner lost grip of one of the pieces and the piece fell and struck him on the left side of his face causing a laceration.  At approximately 11:30AM, an individual sustained a personal injury. EMT was	1	0 6/29/2023	4 6/14/2	023 Y	1	236,000 Y		38 405'	CN00130322-FN, Q00548195-EW-SD, Q00548195-I1-GC, Q00548195-S2-ST, Q005481 S4-MS, Q00548195-S5-PL, Q00548195-S7-EW-SD, Q00842076-L1-SH, Q00842084-L1-I Q00842089-L1-SF, Q00842093-L1-PMM, Q00844202-I1-EI, Q00873606-L1-PMM
0003280 4929611	6/28/23 11:30 4206731 145-05	JAMAICA AVE Queens	11435 Owner	5165109858 Individual			KAREEM ATALLAH	1 Non-Union Y	promptly dispatched to the location. EMT assumed full responsibility for the individual's care. Despite the circumstances, the individual was conscious and independently mobile, able to walk towards the EMT unassisted. The individual appeared in good condition. The subsequent day, we received confirmation that the individual was OK. Please note, all necessary protocols were observed to ensure the safety and well-being and reported to DOB.	1	0 6/30/2023	0 1/0/1	900 0	2	2,000 N	2 25		Q00611153
1323011	, ,	<b>A</b>						1 Non Chian	Cleaning technician alleged tripping down two steps and was sent as a precaution to the hospital by ambulance and the technician was later released	-				_		2 23		220662735, 220662735-01-NB, 220662735-02-PL, 220662735-04-PL, 220676098-01-E
003281	6/28/23 9:15 2129114	2800 Goulden Ave Bronx	10468 General Contractor	6315631110 Business	Citnalta Construction Corp	GC-031743	DASNY	8 Union N	RNC lather carrying a bundle of rebar on his shoulder claims to have slipped and	1	0 6/30/2023	0 1/0/1		0	54,000 Y		4	60 SD, X00336532-I1-FN, X00753162-I1-SF, X08022049-I1-VT Q00564746-I1, Q00564746-S1, Q00564746-S2, Q00564746-S4, Q00564746-S7, Q00564746-S9, Q00564746-Z1, Q00564746-Z2, Q00564746-Z3, Q00564746-Z4, Q00564746-Z5, Q0056746-I1, Q00597123-I1, Q00664857-I1, Q00700079-I1, Q007277 I1, Q00727810-I1, Q00770986-I1, Q00805342-I1, Q00805348-I1, Q00807482-I1,
003282	6/30/23 13:00 4436573	47150 50 Ave Queens	11101 General Contractor	9142468292 Business	Congress Builders LLC	RNC Industries LLC	600734 50th & 5th LIC LLC  080 Boston Road Associates	25 Open Shop Y	fell and was transported to the hospital by EMS.  While attempted to lift a bucket with some compound, the worker felt a pain to	1	0 6/30/2023	6 6/30/2	023 N	1	562,607 Y		12	132 Q08021415-I1, Q08023672-I1, Q08024867-I1
003284	6/28/23 8:00 2013283	2080 Boston Rd Bronx	10460 General Contractor	7188758160 Business	Monadnock Construction	Giant Taping & Plastering, Inc.	3427 L.P., LLC c/o Phipps Houses	4 Open Shop Y	Two workers were on the sidewalk shed bringing some material/equipment from the street level to the sidewalk shed. At some point during this task the men took it upon themselves to remove one of the sidewalk shed panels for ease of the	1	0 6/30/2023	1 1/3/2	022 N	0	322,000 Y		16	176 210180864-01-FO, 210180864-01-FO EA, 210180864-01-NB, 240345006-01-EW OT
03285	6/29/23 16:00 1051470	EAST 98TH 50 STREET Manhattan	10029 General Contractor	9146685812 Business	Specialty Construction System,	REFIT CONSTRUCTION GC-614956	MSMC RESIDENTIAL REALTY	4 Non-Union Y	work without the GC's knowledge. When attempting to put the panel back at the end of the day, the two workers lost their balance and fell from the SWS and landed on the stored material on the street below.	2	0 7/3/2023	7 6/13/2	023 N	2	30,000 N	15 150		M00756507-I1-GC, M00847389-I1-EL, M00847918-I1-SH, SR23/0535
.323	5, 25, 25 10.00 10314/U	JJ JINEET IVIDIIIIDUUT	20020 General Contractor	2140003017 DRSHIE22		MELLI CONSTRUCTION GC-014930	RiseBoro Community	7 NOIT-OHIOH T	While working on disconnecting the condensate drain line from the VRF, Cristian had to allegedly remove tape from the pipe in which he pulled in an upwards	4	5 1/5/2023	, 0/13/2		2	50,000 N	15 150		321600736-01-FO, 321600736-01-FO-EA, 321600736-01-NB, B00554974-I1-ST,
293	6/29/23 12:55 3429305	88 Throop Ave Brooklyn	11206 General Contractor	7189326342 Business	Mega Contracting Group LLC	Admiral Air conditioning Corp	603805 Partnership	6 Open Shop Y	motion and cut his left hand.  2 workers got injured when they tripped and fell while carrying formworks for	1	0 7/6/2023	6 1/6/2		0	148,027 Y		8	95 B00555009-I1-FO-EA, B00634056-I1-FN
310 312	6/26/23 12:00 3076057 6/15/23 12:00 3321839	1333 Broadway Brooklyn 2936 West 23rd Street Brooklyn	11221 General Contractor 11224 General Contractor	2127364492 Business 9733179000 Business	E&T Skyline Construction LLC  Dobco Inc	E&T Skyline Construction LLC	616330 1333 Broadway LLC 613050 NYCHA	5 Non-Union Y  1 Union Y	columns on two separate floors.  worker was installing form work when the screw gun slipped and injured his finger.	2	0 7/11/2023 0 7/11/2023	5 6/22/2 4 5/1/2		1	154,115 Y 150,000 N	17 156	20	250 320912376, 340611920, B00385193-I1-EW-SD, B00833525-I1-EL, B08051082-I1 321187
312	0/13/23 12.00 3321639	2930 West 2310 Street Blooklyll	11224 General Contractor	9733179000 Busiliess	DODCO IIIC		013030 NTCHA	1 Onion 1	Worker walk down plywood ramp on stairwell at 40th floor and when he got to bottom of stairs he was holding on existing metal railing in stairwell he let go and fell at bottom of stairwell witness by other worker. Someone call ambulance, they took him to hospital No broken bones reported by hospital. There was other stairwell which all the workers were using to go up and down in the building. For	1	0 7/11/2023	4 3/1/2	019 1	1	130,000 N	17 130		32110
3315	6/30/23 13:30 1044935	330 East 75th street Manhattan	10021 General Contractor	6465328121 Business	Standard Waterproofing Corp.	Magnum Restoration Corp.	554 The Saratoga Condominum	1 Open Shop Y	some reason the worker Jose Ramirez decided go down the plywood ramp which was only to be used to get rid of debris and bringing up materials. No personnel allowed to walk on this plywood ramp.  The united port o san company was onsite today at 11:30 AM to service the sites port o potties. Service truck was parked in the work lane, the service man stretched hose across sidealk, the service man pulled hose up as old lady was	1	0 7/11/2023	37 5/15/2	023 N	1	190,000 N	40 400		140922802-01-EW-OT
3318	6/23/23 12:00 1047944	126 East 86th Street Manhattan	10028 General Contractor	7187585333 Business	Rybak Development Corp		126 East 86th Street 624238 Development LLC	1 Open Shop N	stepping over it causing her to trip and fall bruising her left hand. She did noit go to the hospital, nyc dob was notified.  This is a Interiors project, including, some plumbing and roof work. Worker was involved in a task that required him to provide metal studs for a carpenter.	1	0 7/11/2023	0 1/0/1	900 0	0	75,000 Y		20	230 121208
320	6/1/23 10:15 1012125	113 Jane Street Manhattan	10014 General Contractor	9734619034 Business	Elysium Construction Inc	Marcos Designs LLC	6128629 NYC Club Owner, LLC	1 Non-Union Y	Allegedely he slipped near the bottom of the steps as he was caring 2 light metal studs from the second floor to the 1st floor heading west.  However, while they were both demolishing the parapet wall simultaneously from opposite ends of each other, a piece of the Terracotta struck and cut Cristian in the left arm wrist area which resulted in bleeding. The other workers assisted Cristian from the scaffold to the roof. The Supervisor, Ismael was notified of the incident and he called for an Emergency Service(Ambulance) and informed PAL	1	0 7/11/2023	3.5 5/22/2	023 N	0	45,600 N	6 68'		M08044247
2220	6/20/22 0 25	F4CT CTDEET C	11377 Cararri Co	F4677FF6F0 F .	D.O. V. Combra - 11: - 2 · 2 · 2	DAL FAIL/IDONIA/FAITAL CODO	NIVOLIA	40 Hetse	management and the C. According to Ismael, First Aid was administered on Cristian while waiting for the Ambulance which subsequently arrived and took him	4	0 7/43/2222	2.5	022 V	-	14 0C7 N			Q00809645, Q00809808, Q00809863, Q08045187, Q08045189, Q08045192,
003330 003331	6/30/23 9:25 4430908 31-76 6/24/23 12:00 4213968	51ST STREET Queens 9075 Sutphin Blvd Queens	11377 General Contractor 11435 General Contractor	5167755659 Business 3475650888 Business	P & K Contracting inc  Front Wave Construction Inc.	PAL ENVIRONMENTAL CORP G018009  TDL Construction	NYCHA 616573 90-75 Sutphin Realty LLC	12 Union Y 6 Non-Union Y	to the Emergency Room.  Worker was tightening the fixture, then the bolt screw got loose and hit his forehead  Ruben was carrying comealongs up the gang ladder to bring to the 3rd floor deck	1	0 7/13/2023 0 7/14/2023	2.5 6/30/2 5 6/24/2		0	11,067 N 198,833 Y	6 54	19	Q08045220, Q08045221, Q08045222, Q08045281, Q08045286, Q08053965 4PL005378-03-EW, 4PL005377-03-EW S, 421171975-01-AL, 421171975-03-PL, 223 421171975-01-EQ FN, 440352413-01-EQ SH 340771613-01, B00115574-I1, B00522529-I1, B00522548-I1, B00573810-I1, B0063762
					Reliable Developers LLC				for concrete. As he made it abt halfway up(7ft) he slipped and fell to bottom of ladder. One witness Oscar Vargas. A 911 call was made, FDNY, NYPD and									11, B00649978-I1, B00649988-I1, B00653424-I1, B00775509-I1, B00780272-I1, B0080932