Incident Incident Unique ID Number In	cident Date & Time BIN House	Number Street Name Borough	Zip Code Incident Reported By	Person Reporting Type of Pers Phone Number Reporting Inci	on Organization of Person dent Reporting Person in Control of	ite Name of Contractor	Person Reporting License Number Name of Site Owner	Number of Active Permits Issued Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Fatali Count Cour	ty Injury/Fatality t Date	Injury/Fatality I Number of Hours Worked	njury/Fatality Inju Date of Wo Employment Me	ry/Fatality Numbe ker Union Violation mber Flaz Issue	r of ons Site To d Fo	tal Square Site Ne otage Building I	Site Existing w Number of Flag Stories	Site Existin	Site Prop ig Number Storie	osed r of Site Prop s Meist	oposed ight Active Permit Number
										During a concrete delivery with a truck a Gotham truck hit the rolling gate and dislodged the chain-link gate. After striking the gate, it tipped over and the chain link portion bumped into worker, Gerald G Poserio. Worker continued to work, and did not request any medical attention.												
1000001600	6/1/2117:15 3062567	74 North 1st Street Brooklyn	11249 Person in Control of Site	7187669189	Construction Superintendent	Bis Apple Testina	27633 HOLD BUSHWICK LLC	3 Non-Union	Y	owe and the chain link portion bumped into worker, Gerald G Poserio.  Worker continued to work, and did not request any medical attention.	1	0 6/2/2021	3	6/1/2021 N		0	15.985 Y				6	321140706-01-EQ-FN, 321599105-01-FO, 321599105-01-FO 70 EA
										At approximately 1 AM on Wednesday zure 2, 2021 a Turner laborer was using an aerial lift to access and begin removing a section of plaster ceiling mar the <sup>37</sup> staircase. A section came boose and fell, striking this worker on both feet. Please note: Inodified the DOB Accident too Line at	s											
1000001601	6/2/211:00 1014387	1 Penn Plaza Manhattan	10119 Person in Control of Site	2124875150	Site Safety Manager	Turner Construction	2546 Vomado realty	6 Union	Y	coming main the 13 stantows. A section came soons also fell, smooting mis- worker on both feet. Please note: I notified the DOB Accident Hot Line at 5:52 AM on Wednesday June 2, 2021 and spoke with Chris Garcia who took the this incidents information.	1	0 6/2/2021	6	1/6/2021 Y		0	127,000 N	5	57 7:	14		123661643, 123750814, 123750814-EW-OT, 123764480, 123821454, 123821454-01-AL
																						220569999-01-FO, 220569999-01-FO EA, 220569999-01-NB, 220569999-02-PL 240232654-01-EW SD, 240232654-01-EW
					Manielmek		Trinity Mid Bronx			Worker was pinning studs when one fell from the ceiling and cut his left												220569999-01-PL, 740232654-01-EW 50, 740232654-01-EW 5P, 240232672-01-EW 5D, 240274181-01-EQ 0T, 240276704 01-EQ 0T, 240276713-01-EQ 0T, 24027936-01-EQ 0T, 240278971-01-EW 0T, 240280263-01-EQ 0T, 240280897-01
000001604 2318196	6/1/2123:00 2129044	425 Grand Concourse Bronx	10451 General Contractor	7188758160 Business	Construction	Tempo Construction	3427 Residential L.P.	15 Non-Union	Y	wrist receiving stitches.  While cutting a piece of aluminum angle trim on a miter saw, the cut piece of angle kicked up and cut the workers middle finger on his left hand	1	0 6/2/2021	4	1/18/2017 N		1	278.555 Y				26	270 EO OT. 240289095-01-EO OT 121188598-01-AL, 123235739-02-EW-MH, 123655080-02-E1
000001611	6/3/2110:35 1016889	28 E 28th St Manhattan	10016 General Contractor	9175786671 Business	Schimenti Construction	Walsh Glass & Metal	GC005367 George Corrifort & Sons	6 Open Shop	Y		1	0 6/4/2021	3.5	8/17/2020 N		1	35,000 N	1	15 2:	16		MH, 123853437-01-EW-OT, 123853437-02-EW-MH, 123853437-03-EW-OT
100001612	6/2/2112:00 1080788	Park Avenue 470 South Manhattan	10016 General Contractor	7183021616 Individual		Upgrade Contracting Co., Inc.	GC#004015 Maria Morillo	1 Non-Union	Y	While sweeping on the sidewalk shed deck the worker did trip on a board failing forward onto the sidewalk shed deck. While failing forward his tonso did twist and he landed on his back. Worker was taken to NYU hosoital via ambulance for treatment of back pain.	1	0 6/4/2021	4	10/13/2020 N		2	108.000 N	1	17 16	60		1238624
00001614	6/4/218:20 3200867	Gravesend Neck 1711 Road Brooklyn	11229 General Contractor	7186767366 Business	MNC GeneraContractors	International Concrete Con	MNC General Contractor p 28630 Corp	ni, 4 Non-Union	¥	Worker was installing concrete forms and his finger pinched while performing the work. He went to the hospital for further evaluation.		0 6/4/2021	1	6/4/2021 N		0	8,815 Y				5	321800850-01-NB, 321800850-03-PL, 800470314-I1-EL, 69 8007414368-I1-FN
							Restoring Communities			Floor joists were being delivered through the 4th floor window with a boom. Six joists slipped from the boom while being loaded into the window, falling on top of the truck that was transporting them. The												210179661-01-AL, X00227390-11-MS, X00228818-11-EW-SP, X00228818-11-PL, X00443190-11-EL, X00445466-11-SH,
3001615	6/3/21 14:26 2004844	995 Union Avenue Bronx	10459 General Contractor	9146980700 Business	Avante Contractine Corp.		Restoring Communities Housing Development 35199 Fund Corporation	8 Non-Union 1	N	Worker was installing concrete forms and his finger pinched while performing the work. It we went to his hopstall for further evaluation. Pletor justs were selected evaluated to the property of the property	1	0 6/4/2021	0	1/0/1900	0	0	21.285 N		5 6	60		X00454455-11-FN. X00478112-11-EL
00001621	6/3/2111:45 1027125	660 12th Avenue Manhattan	10019 General Contractor	6468470100 Business	REDCOM DESIGN	APS Electric INC.	677 Eleventh Avenue 608235 Reality, LLC	5 Open Shop	Y	error towards the car lift, causing the worker's left hand that was holding on to the railing, to be caught in between scissor lift and the adjacent car lift.	1	0 6/7/2021	4	11/1/2018 N		1	420,198 N		7 16	62		121184501-01-AL, 121184501-01-EQ FN, 121184501-03-PL, 123070548-01-EQ-SH, M00391270-P1 220559999-01-FO, 220569999-01-FO EA, 220569999-01-NB
																						220569399-02-PL, 240232654-01-EW SD, 240232654-01-EV SP, 240232672-01-EW SD, 240274181-01-EQ OT, 24027670 01-EQ OT, 240276713-01-EQ OT, 240277936-01-EQ OT,
0001622 2318452	6/4/219:00 2129044	425 Grand Concourse Bronx	10451 General Contractor	7188758160 Business	Monadnock Construction	R&S United	Trinity Mid Bronx 3427 Residential L.P.	15 Open Shop	Y	Worker was movine a transformer and injured his back.	1	0 6/7/2021	2	3/21/2021 Y		3	278.555 Y				26	240278971-01-EW OT, 240280263-01-EQ OT, 240280897-0: 270 EO OT: 240289095-01-EQ OT
										During the installation of Pipe Scaffold /SWS Installation, Mr. Milla Cardona Francisco Alberto got injured on his right arm. While work Mr. Milla has Sharpe side of rench pointed toward the top and when he jumped from the rail on to the base of the platform then rench struck into his civil the man did an ambignor has hen railed. Si First till view for the control of the con												
										at the site. Mr. Milla has been taken to Mount Sinai Isreal hospital. Once we have further updates we will notify all parties. After preliminary investigation, we determined that Mr. Milla has placed the rench in the												140900327-01-EW-OT. M00326053-13-SH. M00326060-13-F
0001623	6/7/2114:00 1004688	89 Avenue C Manhattan	10009 General Contractor	7188506557 Business	Zoria Housina LLC	Zoria Housina LLC	GC 034719 NYCHA	5 Union	Y	wrone direction.  While stripping formwork from a concrete column, form came loose and struck worker in the head. Worker was conclous, however was taken in an ambridge.	1	0 6/7/2021	5.5	5/19/2021 Y		0	100 N		6 6			140903127-01-EW-07, M00326053-11-5H, M00326060-11-F M00326063-11-5F. M402083 121207782-01-ew-ot, 121207782-02-ew-ot, 123742101-01
001624	6/7/2113:45 1088749 One	Madison ave Manhattan	10010 General Contractor	6465334688 Individual		Standard Concrete	518 SL Green Realty	5 Open Shop	Y		1	0 6/8/2021	5	6/7/2021 N		1	800,000 N	1	10 13	20		AL, 140965588-01-EQ-CH, M00296570-11-ST 140918372, 140918381, 140921705, 140927870, 140958024, 140969325, 140970233, 140984273,
		Lincoln Center					Lincoln Center Perform	ng.		A Demolition worker carrying debris to load onto a dolley for removal from the building, caught his right boot on another piece of debris that was staged adjacent to the cert for loading, thereby causing worker to tris forward, landing his left knee on the floor.												121207782-01-ew-01, 121207782-02-ew-01, 123742101-01- AL, 14005588-01-12(-1), M0055870-13-37 140918172, 140918183, 140921705, 1409737870, 140918192, 140908193, 140918233, 140984273, 1409790-1, M00104123, M00104504, M001061410, M00040727, M00104102, M00104564, M00164145, M00442101, M00142100, M0015864, M00164150, M004442101, M0016812, M00145864, M00164150, M0044670, M00168121, M00145864, M00164150,
001626 1573375	6/7/216:50 1081023	10 Plaza Manhattan	10023 Person in Control of Site	6465996010	Construction Superints	nden Tri-State Dismantline	26162 Arts	25 Union	Y	trio forward. landing his left knee on the floor.  I was informed that the worker lost footing and slipped off a baker scaffold approx. 2-3ft high and landed on his back. He had shortness of	1	0 6/8/2021	3.5	6/1/2016 Y		3	245.000 N		5 1	87		M00511580
01627	6/8/2112:00 1024727	1535 Broadway Manhattan	10036 General Contractor	2124191930 Business	Omnituild	5th Ave Millwork	608390 Marriott Marquis	1 Open Shop	Y	breath and ambulance was called because of trouble breathing.  Approximately at 8;30AM, A laborer from Schear Construction was	1	0 6/9/2021	5	12/7/2020 N		0	40,000 N	4	46 60	00		123727645-01-EW-OT
										cleaning and moving materials in storage area at street level, when she picked up a piece of steel with another laborer she stepped backwards and she tripped her foot with another piece of steel and she fell. She said she felt pain in her left side arm and elbow. DOB Building Enforcement												
01628	6/4/218:30 1015729	250 5th Avenue Manhattan	10001 General Contractor	9147748379 Individual		Schear Construction	2212 Fred Ohebshalom	1 Open Shop	Y	Safety Team was called and notified the incident.	1	0 6/9/2021	1.5	1/20/2020 N		1	145.193 N	2	23 21	35		122414002-01-AL 210178939-01-FO, 210178939-01-FO EA, 210178939-01-N
01630	6/7/2114:00 2129384	740 Brook Avenue Bronx	10451 General Contractor	9147231200 Business	Mountco Construction	StructureTech	22340 Brook 156 Associates L	r. 12 Non-Union	Y	The worker was stripping forms at the cellar level. While climbing on the form, the worker moved sideways. Worker did not secure his hook and slipped and fell.	1	0 6/9/2021	7	4/23/2018 N		3	59,535 Y				9	210178939-01-F0, 210178939-01-F0 EA, 210178939-01-N0 210178939-03-FU, XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
										On 6/8/21 at approximately 9:15pm Adams European employee Mariusz Kazimierak was working in a roof bulkhead when his left arm scraped against a sharp object protruding from the bulkhead wall. Mr.												
1631	6/8/2121:00 1017828	40 Irving place Manhattan	10003 General Contractor	7184179000 Business	Adams European Contracting Inc.	Adams European Contracting Inc.	16217 NYC Dept. of Education	1 Union	Y	Kazimierak suffered a laceration to his left arm and a co-worker to drove him to seek medical attention. The wound required 10 sutures to close and he received instructions to follow-up with his doctor.	1	0 6/10/2021	6	12/10/2015 Y		0	80,000 N		7 1	90		103647706-02-EW-OT
										On 6,021 at graphers single \$7.50 m date. Expanse a residue of Marinum Confedence of an experiment of the American Ameri												
1632	6/9/2114:00 3332069	451 Columbia Street Brooklyn	11231 General Contractor	7184179000 Business	Adams European Contracting Inc.	Adams European Contracting Inc.	16217 NYCHA	1 Union	Y	might go to an urgent care facility after work. On 6/10/21 Ms. Gilyard arrived at work with a doctors note stating she should not work for 3 days.	1	0 6/10/2021	7	8/15/2018 Y		0	40,000 N		7 1	80		321969278-04-EW-OT
					Construction		BEDFORD REALTY			Oster Framers were framing the backyard of basement level, when a stud fell on 1 of their workers. Worker had hart hat at time of incident, started complaining for diziness, called 911, was checked out and trainported to	d											321588457-01-AL, 321588457-01-FO, 321588457-01-FO E 800358818-11-PL, 800384983-11-FN, 800389292-11-ST, 800430217-11-EL, 800527210-11-SF, 800527210-11-SH,
1633	6/10/2111:30 3048952	919 Bedford Ave. Brooklyn	11205 Person in Control of Site	3475988789	Construction Superintendent	Oster Framers	28422 HOLDINGS LLC	10 Non-Union	Y	Woodhul Hospital on Flushing Ave in Brooklyn  While off loading block saw one the legs of the machine became loose	1	0 6/10/2021	4	4/5/2021 Y		0	2,000 N		4	40		p800528009-I1-EL
1635	6/9/2114:45 4303321 71-15	BEACH CHANNEL DRIVE Queens	11692 Person in Control of Site	9174701524	Site Safety Manager	AWL INDUSTRIES	1727 NYCHA	5 Union	Y	and while attempting to brace himself to avoid falling and to keep the machine from falling to the ground AWL employee Victor Abrew sustained injury to his left aridle. (Incident Reported Next Day 6-10-21)	1	0 6/10/2021	6	5/4/2020 Y		0	159.000 N	1	11 14	40		
	6/11/21 14:30 1012472		10013 General Contractor	2122296000 Business	Turner Construction		2305 509 W 34th St LLC	1 Open Shop		Continues on sense single bendages only. The distinues are sense single bendages only. The distinues are sense single bendages only. The distinues are sense as a sense of the distinues of the ground order to be about the sense of the sense		0 6/14/2021		6/11/2021 Y			2,850,000 Y					1031 122885422-01-NB
31638	6/11/2114:30 1012472	509 W34th Street Manhattan 288 Water Street Brooklen	10013 General Contractor  11021 Person in Control of Site	2122290000 Business 9176153801	Company  Construction Superintendent	Lippolis	288 WATER STREET 288 WATER STREET 28317 OWNER, LLC	1 Open Shop 1	Y	had and was transported by ambulance to Bellevius Hospital WILSON SIGURENCIA REPORTED LEFT FOOT (NON-INJURED LEG) BEING CAUGHT, ONCE WILSON STEPPED WITH HIS RIGHT LEG HE FELT A PULL IN THE KNEE AREA.	1 N	0 6/14/2021		6/14/2021 V		0	2,850,000 Y				5	1031 1228E5422-01-NB 50 321588402-01-FO. 321588402-01-FO EA. 321588402-01-N
			10000 Consul Contractor	2126200500 Business			618745 Rollvar Brilders			Located on the 2nd floor, west elevation, 4 columns from the NW corner.  As per foreman: worker was checking plumb on steel. He slipped as he was coming down off the beam and fell approximately 8"-0" onto the 2nd	d d	0 6/14/2021		1/20/2020 N			17.500 Y					121205597-01-FQ, 121205597-01-FQ EA, 121205597-01-N 121205597-04-PL, 140897778-01-EQ 07, 140906615-01-EC
21640	6/9/21 10:00 1052673 6/14/21 10:00 1026982	1998 2nd Ave Manhattan 646 11 avenue Manhattan	10029 General Contractor  10458 Person in Control of Site	2126200500 Business 6465706184	Bolivar Builders, LLC Site Safety Manager	Newburgh Iron, LLC Pinnacle Electric	618745 Boliver Builders  2688 Iron State Developers	6 Non-Union	Y	floor deck.  Workers was cutting conduit pipe with saw, slipped of his hand and lacerated right index finger. Worker reported to Urgent care and received	1	0 6/14/2021	-	1/20/2020 N 6/8/2020 N		2	17,500 Y 150,000 Y				-	130 131304303 01 NB
1041	671472110300 1026982	646 II awnise Mannetan	20458 Person in Control of Site	0403/00184	Sittle Supprice Novamables	PINNACH ENCINC	2000 IFOR State Developers	1 Non-Union		Mr. Krzysztof Maiewski cut his left hand during installation of a plass		0 6/14/2021	,	6/8/2020 N			150,000 1					104875079, 122128679-01-N8, 122128679-04-PL, 122128679-EQ-FN, 122842335, 123292418, 123292427, 123292436, 123416561, 123520243, 1409998650.
11642 1573534	6/8/2114:05 1090479	15 E 30 Manhattan	10016 Person in Control of Site	2126890639	Construction Superintendent	Finest Window	615370 Madison 30-31 Owner	LC 19 Open Shop	Y	window in the 1st floor entrance storefront area when the glass window shattered from hitting something hard inside the glazing channel. Worker was walking behind an excivator while the operator was in rewerse. Worker was bump on his leg by the tracks. Worker Antonio	1	0 6/15/2021	6	10/5/2017 N		1	325,243 Y				56	140254329,140254356,140388239,140855313, 800 140864866,140912083,140940891,141000556
001643	6/16/21 12:00 3062178	153 benv st Brooklen	11249 Owner	6317417126 Individual		EBC	153 berry premium	4 Non-Union	Υ	Martinez did not request emergency medical attention and left site on his own accord.	is 1	0 6/16/2021	5	6/1/2021 N		0	3,000 Y				3	321592022-01-FO, 321592022-01-FO EA, 320954865-01-0 30 FN. 321592022-01-NB
0001644	6/15/21 11:30 1090823	145 West 47th Street Manhattan	10036 General Contractor	6466926803 Business	TB USA, LLC	Headquarters Mechanical Inc	NY Tower Development GC-615037 LLC	1 Open Shop	Y	Worker's right hand was shocked by a live 24 volt wire while she was installing a shower body in the bathroom of room 2216. Worker reported the incident to site safety and requested they call her an ambulance.	d 1	0 6/16/2021	4.5	6/3/2019 N		2	311,727 Y				48	520 1211878
										A worker, fields Ochoa, wanted to clean the top of the temporary protection of the physicol that is towering the top of AC units which his protection of the AC units of the protection of the AC units from Belling delices, not as a glation for walking. The supported scaffold was resting on top of the AC unit. While loading on the price of the AC unit. While cleaning on the price of the AC unit. While cleaning on the price of the scaffold on the silped on the physicol but had not not the form of the scaffolding platform and them let hermall got no the grown. DOS and Arbibitions called and their balan to be boost."	,											
		Saint Nicholas								walking. The suspended scaffold was resting on top of the AC unit. While cleaning on top, he then slipped on the plywood but held on to the frame of the scaffolding platform and then let himself go to the ground. DOB												121377321-01-EQ SH, 123759726-01-EW 0T, 123759735-0: EW 0T
.001645	6/4/2112:00 1059446	480 Avenue Manhattan	10030 General Contractor	7182822002 Business	Januar Contraction Inc.	Jaguar Contracting Inc	GC 604472 Dimitri Navlor	3 Non-Union	Y	and Ambulance called and then taken to hospital.	1	0 6/17/2021	2	4/28/2021 N		1	331.448 N	1	19 20	00		EW OT

## Local Law 78 Injury/Fatality Incident Report June 2021

Incident Incident	ncident Date & Time BIN House			Person Reporting Type of Person Person Reporting Inci	on Organization of Person		Person Reporting License Number		Number of Active Permits Issued Site Union Info	Construction Work	oer	Injury Fat	ality Injury/Fat	Injury/Fata lity Number Hours Wor	ality Injury/I	atality Injury/	Fatality Numb	ber of itions Site	Total Square Site N	Site Ex	xisting ber of Site Exis	Site F	roposed ober of Site Prop	ssed
Unique ID Number II	nobent bate & time on House	Number street name boroug	2p Cook Incident Reported by	Phone number Reporting Inci	sers: Reporting Person in Control or S	se Name of Contractor	Liceme Number	Name of Size Owner	issued Site Union into	involved Flag	incident Description Details	Count Co	unt Date	nours wor	гкео стрю	yment Mem	serring tas	Dec	rockage building	Flag Stor	cus neigr	11 31	ones neigh	
1000001646	6/14/2112:00 1026982	646 11th Avenue Manhattan	10458 General Contractor	9734940885 Business	CM & Associates (CMA)	Pinnacle Electric	60236	52 Iron State Developers	11 Non-Union	Y	Worker was cutting conduit pipe with a saw, slipped against the saw with his right hand and lacerated his right index finger. Worker went to a CityMD Urgent Care facility and received stitches.	1	0 6/17/	1021	3 6	%/2020 N		3	150,000 Y				12	22204302-01EQFN, 121204302-01NB, 121204302-02PL, 121204302-03PL, 121240448-01EWSD, 123240448-01EWSP, 123240493-01EQGF, 1232435-030-01EWSD, 12324093-01EQGF, 12324550-01EQGF, 123489553-130 01EWSD, 140820459-01EWBL, 140835782-01EWMH
1000001647	6/17/21 9:30 3424502	405 Dumont Avenue Brooklyn	11207 General Contractor	7184891716 Business	Mega Contracting Group. LLC	Sterline Floor Design	60380	25 Trinity Financial	8 Open Shop	Y	The worker was cutting porcelain tile when a piece of debris went into the worker's eve.	1	0 6/17/	1021	4 1	4/2021 N		0	206.140 Y				835	321186729-01-NR, 321186729-04-PL, 322011782-01-EW BL, 322019967-01-EW GT, 340536094-01-EW SD, 340536094-01- 15 EW SP, 34055085-01-EW SD, 340688973-01-EO GT 210138992-01-EO 210178919-01-EV SP, 210178919-01-BR
1000001648	6/16/21 7:30 2129384	740 Brook Avenue Bronx	10451 General Contractor	9147231200 Business	Mountco Construction	StructureTech	2234	IO Brook 156 Associates L.P.	12 Non-Union	Y	Worker was cirribing an extension ladder when the ladder slipped causing him to fall approx. 6°-0" Two workers were pushing a loaded A-frame cart. The cart tipped over.	1	0 6/17/	1021	1 5/1	0/2021 N		2	59,535 Y				9	210178939-013-PI, XXXX2216-91-EN, ZXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
1000001649	6/16/2113:40 1084771	301 Park Ave. Manhattar	10022 General Contractor	9179998811 Business	Aecom Tishman	Trident General Contractin Corp.	ng GC-2540	AB Stable . LLC	1 Open Shop	Y	Another worker quickly moved to avoid the tipping cart and twist his knee in the way.	1	0 6/18/	1021	5 6/3	6/2021 Y		1	1.750.000 N		44	625		121191245-01-AL
1000001650	6/16/21 13:45 1084771	301 Park Ave. Manhattas	10022 General Contractor	9179998811 Business	Aecom Tishman	Aecom Tishman	GC-2540	AB Stable: LLC	1 Coun Shoo	Y	The worker was pushing the container, he stepped on a floor hole cover, placed over a core drilled hole, cover moved, workers foot slipped in the hole and he cut his lear.	1	0 6/18/	1021	5 6/1	6/2021 Y		0	1.750.000 N		44	625		121191245-01-AL
											At the time of incident Driver of contractor Vehicle picking partially removed shed equipment climb on to ladder that leaned against shed to get access to shed. Driver then fell and hurt himself. Driver refused medical attention and did not go with ambulance,													
1000001651 NONE	6/16/218:00 1012125	113 Jane Street Manhatta	10014 General Contractor	2122475658 Business	Vema Group LLC		61296	39 Jame Hotel	2 Non-Union	N	On Friday, June 18, 2021, a worker from a carpentry subcontractor was working on a four (4) foot podium type platform ladder when the worker claims to have fallen from the third (3) rung of that ladder. He claims he was not climbing up or down just working from that rung when he lost	1	0 6/18/	1021	0 1	0/1900	0	a	100 N		6	70		123143179, M00398662
1000001652	6/18/21 9:40 3329438	11 Hoyt Street Brooklyn	11201 General Contractor	2123885700 Individual			N/A	11 HOYT PROPERTY OWNER, LP	1 Open Shop	Y	his balance and fell from the third rung. No witnesses. He was complaining of back pain so we called an ambulance so he could be taken to a local hospital for additional evaluation.	1	0 6/18/	1021	34 4	5/2021 N		2	613,389 Y				52	591 321197058-01-AL
									1 Ones Shop		Worker was insulating pipes in the sub cellar when he felt if. He was helped by a co worker outside to the main site entry. The GC called an armbulance. Daniel told parametrics he has a history of high blood cressions. He was taken to hosoital as a orecaution.													
1000001653	6/17/21 13:45 1090823	145 West 47th Street Manhattar	10036 General Contractor	6466926803 Business	TB USA. LLC	Forward Mechanical	GC-615037	Clarity 47 LLC	1 Open Shop	Y	orisizer. He was taken to hostiful as a encesidion.  WORKER WAS DRILLING A HOLE ON THE DRAIN STRANER ON BALCONY OF BUILDING 1. WORKER WAS SHICKING THE DRAIN IN HIS HAND AND DRILLED THROUGH THE SCREW HOLE AND KUNCTURED THE LEFT HAND BY HIS THURSE WORKER WAS TRANT TO THE HOSTIFLE OF THE STRE SHIP STRANG WORKER WAS TRANT TO THE HOSTIFLE OF THE STRE	1	0 6/18/	1021	6 6/3	7/2021 N		0	311.727 Y				48	520 NB 121187802
1000001654	6/18/21 12:40 1027059	520 wist 55th Manhattar	10019 General Contractor	7184398500 Business	PRO METAL CONSTRUCTION INC.	PRO-METAL CONSTRUCTION,INC	20.0	IS NYCHA	5 Union		BY HIS THUMB. WORKER WAS TAKEN TO THE HOSPITAL BY THE SITE SUPERVISOR, NO STRUCTURAL DAMAGED FOUND. HOSPITAL RELEASED HIM AFTER 3 HOURS.	,	0 6/18/	1031	4.5 6/1	e/1011 v		0	100 N		15	135		140864615-01-EU-OT, M00260538-L1-SH, M00260544-L1-FN, M00263897-11-EL, M00283637-L1-SF
100001034	6/21/2111:00 3394734	640 Columbia Street Brooklen	11231 General Contractor	6468807309 Individual	CONTROL INC.	CONTINUENDA, INC.		64 640 Columbia LLC	1 Open Shop		The incident occurred to a mason, the worker stated that the level line used in masonry was under tension and snapped causing a clip to come out and scratch his right forearm	1	0 6/21/		4 6/2				175.000 Y		.,	133		120 321383007-01-NB
100001655 100001657 N/A	6/21/21 11:00 3394734 6/21/21 7:45 1086559	640 Columbia Street Brooklyn Claremont 80 Avenue Manhattar	11231 General Contractor 10027 General Contractor	5463807309 Individual 2125926700 Business	Lendlease	Universal Builders Supply	283- 16836P	64 640 Columbia LLC Broadway Community Manager	1 Coan Shoo	Y	out and scratch his night forwarm  Worker while lifting a hoist gate up loading dock stairs, tweaked back	1	0 6/21/		1 11			2	330,000 Y					120 321383007-01-NB 480 121189436-01-NB
											At approximately 9:A5am on the 21nd floor area 2319 at 1540 Broadway. A Frame dolly containing Sheetrock for installation of room 2353. In transit, the A. Frame dolly containing Sheetrock begin to 16 once. During this time a subcontractor employee (Gary Dunne) attempted to stop the installation falling to the ground. During this course of action the employee injured this right vanit. The employee neclosed first aid on-site spin foreman sho placed to on his write. The injuried meloyee on his													
1000001659	6/22/21 9:45 1076844	1540 Broadway Manhattan	10036 General Contractor	6469950096 Individual		Rivco	267	73 Edge Funds	1 Union	Ψ.	own accord then took a cab with shop steward and taken to Mount Sinal Hospital. After checkine with	1	0 6/24/	1021	3 6	71/2021 Y		3	100 N		42 unknow			m00502668-11-GC 240169456-01-EW SD, 220546639-01-EQ FN, 220546639-01-
1000001661	6/23/21 9:25 2128910	225 E 179 st Bronx	10457 General Contractor	7182926400 Business	M.Melnick & Co., Inc.	CitiBrick & Tile	60224	11 Thomas Campbell	8 Non-Union	Y	Struck in the face by a co-workers hand trowel when turning around; all while installing brick on a scaffold.		0 6/24/	1021	2 7/1	7/2019 N		0	30,000 Y				12	FO, 220546639-01-NB, 220546639-04-PL, 220622761-01-EW 130 SD, 240169456-01-EW SP, 240249370-01-EQ OT
					Construction						At ages 15:30 on 6/21/21, worker named 2 skaria Mostil, who works for AMR TRAC, was waiting down bare located at the up 94 of the last. The was at the 2nd is located to the ground flow, which has last his facting was changloiser of any dates. Worker did not injure any other part of his was changloiser of any dates. Worker did not injure any other part of his body, the did not this hast. Also was indented at all times. Other co- workers were present at time of incident. Worker insidered on pains to the Rivis LSM. Hong proport states "paramet last in wide "A" Worker can Rivis LSM. Hong proport states" (paramet last in wide "A" Worker can													
1000001662	6/23/21 15:30 3241257	4121 Avenue T Brooklyn Parsons	11234 Person in Control of Site	9177481590	Superintendent  Mega Contracting	AMK Heating and Cooling		30 Michael Treff	2 Non-Union		return on 7/7/21*  Worker was working on an A-frame ladder when the worker lost his		0 6/24/		7.5 6/2			0	5,000 Y				3	45 321702662-01-AL, 321702662-01-PL 420664310-01-AL, 420664310-03-PL, 440541291-01-EW SD, 440548757-01-EW SD, 440548757-01-EW SP, 440550388-01-
1000001663	6/24/21 15:00 4442434 82-41	Boulevard Queens	11432 General Contractor	7184891716 Business	Group. LLC	Stuart Dean Company	60380	25 Dunn Development Corp.	7 Open Shop	Y	balance and fell.	1	0 6/25/	1021	8 6/3	0/2021 N		0	238.000 N		10	120		EW BL. 440557639-01-€0 OT
1000001664	6/24/2115:00 1035421	270 park ave Manhattar	10017 General Contractor	9177019156 Individual			161	19 JP Morgan Chase	1 Union	Y	The employee stated that he was using a circular saw to out a panel used for protection of an electrical service. When the employee completed the cut of the panel the saw blade bound up when the panel started to fold in half. The circular saw sicked back and the blade struck the employee in the right thigh.	1	0 6/25/	1021	2 6/2	4/2021 Y		2	80,000 Y				62 :	1425 140939992-01-EW-OT 210179689-01-AL X00231350-11-MS, X00231598-11-EW-SP,
1000001665 N/A	6/24/21 9:45 2004986	774 Union Avenue Brons	10455 General Contractor	9146980700 Business	Avante Contracting Corp.	M&B Renovations	3519	Restoring Communities Housing Development 29 Fund Corporation	8 Non-Union	Y	Worker fell between two beams while taking measurements for joist replacement. He took a step and fell through one floor.	1	0 6/25/	1021	2 3/1	5/2021 N		0	20.285 N		5	55		210179689-01-AL, X00231350-11-MS, X00231598-11-EW-SP, X00231598-11-PL, X00443181-11-EL, X00445218-11-SH, X00454469-11-FN, X00478161-11-EL
Complaint					Cross Management			JONES LANG LASALLE			THE WORKER SINGH WAS PERFORMING PAINTING OPERATION USING A FRAME LADDER HE FELL DOWN AND BROKE HIS RIGHT HAND													
1000001666 #:1574805	6/24/219:00 1035348	330 Madison Ave Manhattas	10017 General Contractor	2129221110 Business	Corp		2739	99 AMERICAS, INC	1 Union	Y	AMBULANCE CALLED. DOB#062421CE05SM01.ECB#35559539Z	1	0 6/25/	1021	2 6/2	4/2021 Y		1	100 N		44261	6		140949794 121205123-01-FO, 121205123-01-NB, 121205123-03-PL,
																								121205129-04-PJ, CN00085120, M00245110-11-EW-SD, M002451510-11-EW-SP, M0024514-02-11-EW-SP, M0024514-02-11-EW-SP, M0024514-02-11-EW, M0028575-11-EW, M0028523-11-EW, M00485502-11-FW, M0048502-11-FW, M
1000001667	6/25/2115:00 1091667	145 Bowery Manhattan	10002 Person in Control of Site	5162733006	Site Safety Manager		272	04 Liehtstone Group	21 Cown Shoo	N	S&E thridge and Scaffold LLC's driver lost his balance and fell off his thuck landsing on his liet students as inclinated by withensess. HVAC technician was sprayed with Freco as opened the valve to the refrigerator unit on the first floor The workers suffered a burn on the right forearm, but offsued medical attention	1	0 6/26/	1021	0 1	0/1900	0	0	22.500 Y				17 1	M00485622-I3-PM, M00487331-I1-SH, M00487667-I1-EL, 96.5 M00517211-I1-EL M00519900-I1-PM. M00527663-I1-PM
1000001668	6/23/21 12:00 1003795	9 Orchard Street Manhattan	10002 Person in Control of Site	9179634039	Site Safety Coordinator	Amercold	250	00 D & L Builders	1 Non-Union	Y		1	0 6/28/	1021	2 6/2	4/2021 N		1	90,000 N		14	80		121326010 1222222077-01-NB, 140527263-01-EW-SD, 140527623-01-
					Construction						2 WORKERS I WORKING AT ROOF AND BUILKHEAD WATER TANK AREA THEY WERE LOWERING FOAN AND 2X4S 5 FT LONG LABORER LOWERING BOARD WITH ROPE 2X4 SLIPED FROM ROPE HIT OTHER IN THE CHIN													EW-SP, 140616395-01-EW-RS, 140616395-01EW-MH, 140691428-01EQ-OT, 140831786-01EW-SD, 140850639-EQ OT, 140851843-01-WQ-OT, 140860763-EQ-OT, 140869754-
1000001670	6/28/215:15 1090683	120 water st Manhattar	10005 Person in Control of Site	3474161701	Superintendent	OFS LABORERS  LONG ISLAND CONCRETE,		56 RAI GURU SEAPORT MANAGEMENT	11 Non-Union	Y	MOUTH WAS BLOODY LOOKED LIKE HE CRACKED COUPLE OF TEETH  WHILE WALKING TO HELP REMOVE DEBRIS OFF TRUCK, HE STEPPED ON	1	0 6/29/	1021	8 6	3/2020 N		0	20 Y				26	300 EO-OT
1000001671	6/28/2112:00 1090738	96 SOUTH STREET Manhattan	10038 Subcontractor	7187844606 Business	LONG ISLAND CONGRETE, INC.	INC.	2582	DEVELOPMENT COMPANY 28 LLC	1 Union	Υ	A RAKE THAT WAS ON THE GROUND.	1	0 6/29/	1021	1 1	71/2018 Y		0	400 N		3	10		140937976-01-EW-OT
					Gilbane Residential			Midwood Investment &			On the morning of 60(2/2/2012, at 8.13.6 M. Mr. Digmo Fájardo was using a hand grinder to cut metal on the 1st floor when a piece of solid particle struck him in his right eye. According to Mr. Fájardo, he was wearing safety glasses at the time of the incident and was learing over while using the grinder when the piece of metal particle struck his eye in between the top part of the glasses and his face. Mr. Fájardo reported that he was in intermediate pain and respossted to be evoluted at the													M00019029-13-5H, M00019012-11-5H, M00069807-11-5F, M00069609-11-5F, M000196019-11-5F, M001271579-11-8H, M001271579-11-8H, M001271579-11-8H, M001271579-11-8H, M00127159-11-8H, M0017159-11-8H, M0017159-11-8H, M0017159-11-8H, M0017159-11-8H, M0017
1000001672	6/28/218:15 1091568	150 E 78th Street Manhattan	10075 General Contractor	6469601521 Business	Construction	StructureTech New York		38 Development NY Tower Development	21 Open Shop		local Urgent Care facility. There was no equipment malfunction reported.  Worker was moving a panel of the walk-in freezer on the 5th floor and his left index finger was pinched between the panel and duct work. He has a	1	0 6/29/			8/2017 N		1	100,000 Y					170 M00360933-11-EL, M00361288-11-EL, M00361288-P1-EL
1000001674	6/29/2111:20 1090823	145 West 47th Street Manhattas	10036 General Contractor	6466926803 Business	TB USA. LLC	Spacious Livine Group  AM Architectural Menal ar	GC-615037	LLC NY Tower Development	1 Cown Shoo	Y	local Utgent Care lacitity. There was no equipment mallsorction reported. Worker was moving a passe of the walk-in freezer on the 5th floor and shis left index finger was pinched between the panel and duct work. He has a cut on the uson left index fineer. Miggel was satisfied in mobilization of material which was a steel beam 8" x 5" with Pedro. He felt a pulling in back and could not move due to 	1	0 7/1/	1021	1 10	5/2020 N		0	311.727 Y				48	520 121187802
1000001675	6/29/2111:15 1090823	145 West 47th Street Manhattan Parsons	10036 General Contractor	6466926803 Business	TB USA LLC	Glass	GC-615037	rrc	1 Open Shop		pain.  Worker slipped and fell at or near a water cooler. Prior to incident worker		0 7/1/			72/2020 N		0	311.727 Y				48	520 121187802 440550388-01-EW B, 440557639-01-EQ O, 420664310-03- Pt, 440541291-01-EW SD, 440548757-01-EW SD,
1000001677	6/29/2113:35 4442434 82-41	Parsons Boulevard Queens	11432 General Contractor	7189326342 Business	Colette	Mega Contracting Group	60380	05 Dunn Development Corp	7 Open Shop	Y	was loading sheets of drywall into various apartments.  Worker was placing rebar on the sub-cellar deck in an open sunlit area.	1	0 7/1/	1021	4 5	9/2021 N		0	238,000 N		10	120		PL, 440541291-01-EW SD, 440548757-01-EW SD, 440548757-01-EW SP, 420664310-01-AL
none 100001678 provided	6/29/211:50 3428601	595 Dean Street Brooklyn	11238 General Contractor	2126721000 Business	TFC Pacific Park GC LLC	SBF Construction Inc.	GC 621137	595 Dean LLC	12 Open Shop	Y	He indicated to the formers that he defin't feel well used to take to get a comp. Formers had then it and conditated the monite medic right away. Mode indicated possible heat enhancing, but called an embalance cost of causinos. MS placed worker in embalance for med an assess his condition. After 5-20 minutes, EAFI eleformed cree the worker was much better, the table time of the decided in legal for an evaluation. Worker resistand from hopizal later the same day with return to work note.		0 7/1/	1021	7 6/1	6/2021 Y		0 116,	53 Y				29	321595403-01-FO, 321595403-01-RE, 321595403-FO-EA, 80212395-1-GE, 80223925-1-EA, 80233925-1-FA, 80233925-1-FA, 80233925-1-FA, 80233925-1-FA, 80233925-1-EA, 8023392-1-EA, 802392-1-EA, 802392-1-EA