

Local Law 78 Injury/Fatality Incident Report
October 2024

IncidentReporting																									IncidentReporting_Active Permits					
Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number	
1000004403		10/1/2024 9:15:00 AM	1009006	808	Broadway	Manhattan	10003	Subcontractor	9143535555	Business	Andamio Scaffolding LLC		Andamio Scaffolding LLC	623088	Broadway 11 owners inc. C/o First Service Residential Management		1	Non-Union	Y	Worker was on a rolling tower scaffold wearing a harness and hard hat. He was tied off to the rolling tower with his harness connected. As the workers were moving the tower, it got stuck in a crack on the sidewalk causing it to shift. When it shifted worker lost balance and the rolling tower came into contact with a truck parked along the sidewalk. Worker did not fall from the tower or onto the truck. Rather, he remained tied off to the tower. However, one of his ankles got caught on the braces of the tower causing him to twist his ankle.	1	0	1	60	N	7	77			M01116583
1000004404	43796	10/2/2024 12:00:00 PM	3861463	721	Clinton street	Brooklyn	11231	General Contractor	9146683366	Business	CELTIC SERVICES NYC INC			613080	MADISON REALTY		1	Non-Union	N	Hit an above ground gas line	1	0	0	14866	N	1	40			B00996763
1000004406		10/7/2024 9:00:00 AM	2130750	1600	Grand Ave	Bronx	10453	Person in Control of Site	7182945840			Site Safety Manager	Premier Flooring	SSM 2318	Star Hill Phase 1 Owners LP		11	Open Shop	Y	Randolf Baltra-Ayala, a worker for Premier flooring, who was not working on this site, showed up to see if there was work for him. The tile foreman explained that there was not work for him on this site. FDNY suddenly showed up on site at about 8:30am responding to a 911 call of an injured worker. This worker was found sitting on Stair A at the ground floor level. He explained in Spanish that he hurt his leg when he tripped on the stair. As of 11:30am this worker was treated and released from the hospital with a sprained ankle.	1	0	0	251,000	Y		14	155		ALT II 240357671 OT ALT III 240313095BP X00544682-11 MH X00544727 11 PL X00544768 11 ST X00643904 11 BL X00648896 11 SD SP X00648897 11 SD X00743727 11 EQ FN X00798337 11 EL X08028326 11 EL
1000004407		10/7/2024 1:47:00 PM	2092794	1730	Watson Avenue	Bronx	11416	General Contractor	7188450123	Business	J&N Construction Group, Corp.		J&N Construction Group, Corp.	GC-606780	New York City Housing Authority		4	Union	Y	There was an ongoing installation of side walk shed at Building 11, 1730 Watson Avenue ramp area. The injured person was tightening the bolts of the stud at side walk shed. He suddenly slipped and fell down.	1	0	0	6500	N	7	65			X01116822-11-FN X01116825-11-SH X01116826-11-SF X01120535-11-EL
1000004408	Chiu Badge 2617	10/3/2024 6:00:00 PM	1088394	125	White Street	Manhattan	10013	General Contractor	5168760020	Business	Gramercy Group, Inc.		Gramercy Group, Inc.	24918	New York City		11	Union	Y	Employee walking down stairs mis-stepped and injured knee	1	0	0	174700	N	14	247			123916478-01-DM CN001233-23 M00672697-11-FN M00701339-11-EW-SD M00760675-11-SH M00795604-11-SF M00947399-11-GC M01107483-11-SE M08040381-11-PMM M08088646-11-ST M08053650-11-EL
1000004409		10/7/2024 5:15:00 PM	3051540	432	Monroe Street	Brooklyn	11221	General Contractor	8455170711	Business	Nehal Contracting, Inc.		Nehal Contracting, Inc.	602060	NYC School Construction Authority		12	Union	Y	Mr. Orlando Rodriguez allegedly was doing demolition in Room #112 and got hurt by a nail on his left-hand wrist.	1	0	0	82,000	N	3	41' 7"			B00862411-11-SF B00851517-11-GC B00851527-S1-FO B00851527-S2-ST B00851527-S5-MS B00851527-S6-PL B00851527-S7-EW-SP B00962418-11-FN B00962435-11-SH B00962497-11-SE B01041308-11-EL B01043893-11-EL
1000004411	3979762	10/8/2024 6:45:00 AM	3426079	83	Gateway Drive	Brooklyn	11239	General Contractor	7188758160	Business	Monadnock Construction		Scott Landscape Design, Inc.	624455	Spring Creek 4C Owner LLC		3	Non-Union	Y	A worker got injured while cutting a 2x4 using a grinder. He was using the wrong blade for the tool.	1	0	1	7040	Y		4	38.5		321597278-01-FO 321597278-01-FO EA 321597278-01-NB
1000004412	N/A	10/9/2024 12:00:00 PM	1071418	31	West 52nd Street	Manhattan	10019	Person in Control of Site	5163060548			Other		N/A	Paramount		1	Open Shop	Y	Omar Alberto was taping a wall. After moving his ladder to a new spot, he climbed the ladder, and a pencil rod stuck him on his head (Front right side). This left him with a small cut. At this time, he left the floor and arrived at the Benchmark field office on the 10th floor and received first aid for the bleeding. After applying a bandage and stopping the bleeding, Omar Alberto decided to go to a local Emergency care facility (City MD at E-way and 49th Street). He arrived back at the job at 1:30 pm same day to return to work.	1	0	0	25000	N	29	348			M01040904
1000004413		10/7/2024 12:27:00 PM	2130757	1351	Jerome ave	Bronx	10452	General Contractor	9294282111	Business	On Star Management LLC		Windows NYC	GC-621905	Sam Rubin		1	Non-Union	Y	The worker was found, laying on the floor stating that he fell and was complaining of leg and back hurting.	1	0	0	37000	Y		14	140		X00729880-11-GC
1000004414		10/14/2024 2:45:00 PM	1009862	95	Bedford Street	Manhattan	10014	General Contractor	6465224266	Business	Spring Build, LLC		Sperrin Construction	626068	Bedford Estates		1	Open Shop	Y	Individual was working on ground floor emptying bucket of debris into container. His direct report was working on floor below out of line of site. No other workers were on the ground floor at the time. A few moments later another worker found individual lying on floor with no visible signs of injury. Individual was conscious but was not cooperating. Emergency services was contacted and arrived within 10 minutes and took individual to hospital. Technician mentioned to his supervisor that his vital signs were normal, area was clear and clean. No ladder or scaffolds in use.	1	0	0	9100	N	4	80			M00717108
1000004415	1679619	10/11/2024 9:15:00 AM	1083026	2	Pennsylvania Plaza	Manhattan	10121	General Contractor	3477281965	Individual			Vespa Stone	2421	Vornado		1	Open Shop	Y	Vespa Stone uses a fork lift to help set stone at the facade for the 2 Penn project. Fork lift operator and flagger were in process of getting the forklift into the fenced in yard. Flagger moved away to open fence. At that time pedestrian came out of NJ Transit gate and tripped over the forks.	1	0	2	1600000	N	32	412			121189356
1000004416		10/10/2024 6:35:00 AM	1009723	250	Hudson Street	Manhattan	10013	General Contractor	2124816100	Business	Structure Tone, LLC		Sirina Fire Protection Corp.	GC-002660	Edelman		2	Union	Y	Worker slipped on floor and lips came into contact with a ladder.	1	0	0	142000	N	14	170			M01068450-11-GC M01068466-11-EW-SP
1000004417	3	10/16/2024 7:40:00 AM	3816613	97	Glenmore Ave	Brooklyn	11212	General Contractor	3473327084	Individual			Bletas Plumbing & Heating Corp	25545	Glenmore Manor		1	Non-Union	Y	WORKER INJURED HIS LEG ON THE 9TH FLOOR	1	0	0	23630	Y		11	168		B00663906-11-GC
1000004418		10/16/2024 8:55:00 AM	2800856	2176	bathgate ave	Bronx	10457	Person in Control of Site	7183067778			Construction Superintendent	ACCURATE ELECTRIC	028831	Citywide		1	Non-Union	Y	At about 8:55 Am the worker name Henry Vazquez of accurate electric was working roughing BX Cables at a 6 feet A-Frame ladder fell during the process of roughing cables. 911 was called and he was evacuated by ambulance. The worker was conscious at the time of moving to ambulance. He signed the sign in sheet and was in pre shift meeting and was oriented on his 1st day on job-site.	1	0	0	9980	Y		8	74		X00700005-11
1000004419	1679616	10/11/2024 9:20:00 AM	1001004	60	Wall Street	Manhattan	10005	General Contractor	2124816100	Business	Structure Tone, LLC		United Structural Works	GC-002660	Paramount Group Inc.		2	Union	Y	Worker was on 2nd floor installing q-deck, when he fell to the ground level below.	1	0	1	50000	N	47	745			M00690568-11-GC M00891985-11-GC
1000004420		10/11/2024 10:30:00 AM	1071457	399	Park Avenue	Manhattan	10022	General Contractor	2124816100	Business	Structure Tone, LLC		Atlas-Acon Electric Service Corporation	GC-002660	Millennium Partners, LLP		2	Union	Y	Worker was lifting a raised floor access tile with a suction cup, when the suction cup gave way and the tile fell and came into contact with workers finger.	1	0	0	33000	N	41	524			M00945773-11-GC M01078621-11-EL
1000004422		10/15/2024 12:00:00 PM	3429585	424	Carroll Street	Brooklyn	11215	General Contractor	7189326342	Business	Mega Contracting Group LLC		Black Sheep Holding LLC	603805	The Vorea Group		3	Open Shop	Y	Rene Flores Hernandez experienced a seizure caused by pre-existing medical conditions while completing the final cleaning of a bathroom in one of the apartments.	1	0	0	386521	Y		16	130		B00614338-11-GC B00699836-11-FN
1000004423		10/18/2024 9:15:00 AM	1007174	174	Mott Street	Manhattan	10012	Person in Control of Site	9179920040			Construction Superintendent	Forge Enterprises, Inc.	25935	AlleyCorp		5	Non-Union	Y	Workers relocating a Roust-a-Bout Lift. Lift wheels turned and roust-a-bout fell over and made contact with worker shoulder before hitting the ground. Incident occurred on 6th floor North-East Elevation. Worker was hurt on right shoulder. No lacerations or major injuries identified. Worker left site voluntarily to visit a doctor. Doctor note obtained and provided to inspector. Worker Name: Luis Aleraldo Yasis	1	0	2	33,072	N	6	72			122778365-01-EQ FN 12244494-01-EW SD 123819305-01-AL 123819305-03-PL 140456895-01-EQ SF
1000004425		10/17/2024 8:20:00 PM	4623202	35-15	19th Avenue	Queens	11105	General Contractor	9172272636	Individual			Team Electrical	604024	Wildflower Studio IV LLC		1	Open Shop	Y	Worker was installing conduit when his right arm touched an exposed with and was shocked and fell off his ladder. Worker was taken to Elmhurst Hospital, discharged the same day.	1	0	0	50	Y		8	158		M00667549-01
1000004426		10/18/2024 10:00:00 AM	4437366	48-37	48th Street	Queens	11101	General Contractor	9172272636	Individual			Cetus	604024	SunnySide Studios Owner LLC		1	Open Shop	Y	Worker cut his left wrist with a Sheetrock knife while installing plastic tubing around electrical wires	1	0	0	50	Y		8	100		Q007040893
1000004429		10/16/2024 12:00:00 PM	4624033	23-10	42nd Road	Queens	11101	General Contractor	6469528000	Business	Suffolk		SKF Electric	GC-611358	Werwaiss		1	Open Shop	Y	Worker on 9th Floor Terrace using a hammer drill lost control of the tool and got his finger caught and lacerated.	1	0	0	236,872	Y		35	406		Q00648195-11-GC
1000004431	03933	10/18/2024 11:00:00 AM	1091738	280	East Houston Street	Manhattan	10002	General Contractor	7182909111	Business	KSK Construction Group		Doria Inc	GC-608693	280 East Houston Partners LLC		5	Non-Union	Y	He jumped from the truck while carrying a material.	1	0	1	150000	Y		12	120		M00647624-S4-PL M00647624-S7-EW-SD M00647624-S8-EW-SD M00950856-11-SF M00950856-11-SH
1000004432		10/17/2024 10:00:00 AM	1091738	280	East Houston Street	Manhattan	10002	General Contractor	7182909111	Business	KSK Construction Group		SKF Electric	GC-608693	280 East Houston Partners LLC		5	Non-Union	Y	He fell on the pile of sheetrock.	1	0	0	150000	Y		12	120		M00647624-S4-PL M00647624-S7-EW-SD M00647624-S8-EW-SD M00950856-11-SF M00950856-11-SH
1000004434		10/22/2024 12:00:00 PM	1047390	1133	5th Ave	Manhattan	10128	Subcontractor	2014375150	Individual				054013927711756	Blue House Trust		6	Open Shop	Y	While working on planks approximately 4' high installing structural deck support a plank gave way causing Miguel Diaz to fall injuring his left knee and his right rib cage.	1	0	2	11,221	N	16	190			M00520677-11-GC M00520726-11-MS M00520738-11-PL M00520762-11-ST M00794628-11-GC M00639869-11-GC
1000004435		10/23/2024 10:00:00 AM	3429452	548	Utica avenue	Brooklyn	11203	General Contractor	7188758160	Individual			B&V CONTRACTING ENTERPRISES INC.	GC-624455	YB Utica Crescent		7	Non-Union	Y	Worker was on his own using a hammer drill and the tool came into contact with his genitalia.	1	0	0	360,000	Y		12	140		B00648034-11-GC B00648034-S1-FO EA B00648034-S2-ST B00648034-S3-MS B00648034-S5-SE B00945125-11-FN B00969997-11-GC
1000004436	1680666	10/26/2024 1:15:00 AM	1077363	712	Fifth Avenue	Manhattan	10019	General Contractor	6467503634	Individual			Riteway Demo	037664	712 FIFTH AVENUE OWNER LP		5	Union	Y	Worker was working on the corridor side of the 1st floor of 712 Fifth Avenue (5th Street Entrance). Worker claims that metal mesh fell from a security wall being disassembled and struck them in the right arm.	1	0	1	1500	N	50	650			M01033846-11 M01033874-11 M08025950-11 M08025953-11 M08025955-11
1000004438		10/25/2024 10:20:00 AM	3385303	2926	W 25th Street	Brooklyn	11224	General Contractor	2017682213	Business	Neelam Construction Corp		Zovia Housing LLC	GC-015095	NYCHA		8	Union	Y	During Asbestos Abatement at 2923 W 25th St., Wing D, window line 41, handier was removing caulking & window sill when Mr. Juan Sepasay got hurt by debris of window sill. He was provided first aid at the GC trailer and he was sent to nearby hospital for check up by his supervisor	1	0	0	44,344	N	13	113			B00990075-11-GC B00605089-11-MS B01024514-11-SH B01024514-11-FN B01033563-11-SC B01033650-11-SF B01080603-11-EL B01093029-11-EL
1000004440		10/25/2024 7:45:00 AM	3429490	323	Bergen Street	Brooklyn	11217	Person in Control of Site	3477780565			Construction Superintendent	Lino CC	26915	Bergen Owner LLC		1	Non-Union	Y	On Friday morning at7:45 AM, one worker for Lino CC was working on the scaffolding on the 1st floor and fell. Based on what other crew members working for Lino CC told Andco, this individual that fell off from the scaffolding was on the 1st floor of the scaffolding to set the laser. The other crew members also mentioned that this worker did not tie-off and then ended up falling to the ground. This injured worker claimed to have pain on the left-side of his torso and also had a small cut with blood on his right eyebrow. We called an ambulance and this individual was taken to the hospital.	1	0	0	210000	Y		7	74		B007748231-GC
1000004441		10/28/2024 10:45:00 AM	4047330	9825	Horace Harding Expressway	Queens	11368	General Contractor	7187293685	Business	PRAT Enterprises Corp.		PRAT Enterprises Corp.	622810	Lefrak City		2	Open Shop	Y	During a recent job inspection and walkthrough, our supervisor, Artur Budzinski, unfortunately slipped and fell while on the sidewalk shed, resulting in an injury to his leg. He was promptly taken to the hospital for evaluation and treatment. We're relieved to report that he is now in good condition and is expected to return to work in a few days. In the meantime, we'll continue to maintain the momentum of our work while ensuring all safety protocols are thoroughly upheld to prevent similar incidents.	1	0	0	0000	N	16	144			Q00871573-11-GC Q00953392-11-SH
1000004444		10/28/2024 1:05:00 PM	4433860	104-20	Queens Boulevard	Queens	11375	Subcontractor	9293534595	Individual			San Pedro Contracting Corp	N/A	BPP Parker Tower Property Owner		1	Open Shop	Y	Worker was cleaning scaffold at the main entrance vestibule while wearing a personal fall arrest system and tied off to the safety line. Worker reported fall from 2'-3' high and claimed to have sustained a back/shoulder injury. Worker was released from hospital with no major injuries and will return to work in coming days. The worker was able to walk today without any assistance or support.	1	0	0	7000	N	20	175			Q00819824
1000004445		10/28/2024 11:15:00 AM	4004336	36-25	Vernon Boulevard	Queens	11106	General Contractor	7189375353	Business	Skyline Restoration		Skyline Restoration	003365	ROYAL CHARTER PROPERTIES, INC		2	Non-Union	Y	A roofer was tasked with removing a damaged section of roof. Once the section was cut he then stepped on the area he cut and fell through the roof landing one story down to the interior ground floor.	1	0	0	12,000	N	1	20			Q01104602-11-SH Q01104925-11-EL
1000004446	Not Available	10/29/2024 2:00:00 PM	3048468	122	Sandford	Brooklyn	11205	General Contractor	2122035577	Business	McGowan Builders Inc.		KDR Enterprises	21418	Myrtle Owner LLC		4	Open Shop	Y	During a special Operations Concrete Pour which required a lane closure on Myrtle Avenue between Sandford and Valworth, at approximately 2:10pm, a construction worker named Luis Sangurima who was a designated flagger for the operations was directing traffic when an oncoming vehicle ran a red light which hit the victim who suffered fatal injuries. The DOB were notified via cell Phone on 10.29.2024 and DOB Officer Powell#3188 arrived to the site.	1	1	0	90498	Y		10	125		321588705-01-FO B01060589-11-MS B01024514-11-SH B01024514-11-FN B01033563-11-SC B01033650-11-SF B01080603-11-EL B01093029-11-EL
1000004447		10/2/2024 12:00:00 PM	1000000	450	1st avenue	Manhattan	10016	General Contractor	3479771941	Individual			Corporate Electric Group	1689	NYULH		7	Union	Y	At about 2:10pm a Fire Alarm Electrician from Corporate Electric, Mr. Michael Begian fell off an A-Frame ladder on the 2nd floor north electrical closet. At about 2:20pm NYULH emergency medical staff arrived on site to attend to the worker. The worker was conscious when he was placed on a stretcher and was taken to the NYU emergency room.	1	0	1	140000	N	23	280			M00605085-11-GC B01060589-11-MS B0

IncidentReporting																											IncidentReporting_Active Permits		
Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number
1000004449		10/30/2024 8:00:00 AM	4003495	43-14	Queens Street	Queens	11101	Subcontractor	9175503840	Individual			KNS Building Restoration	1325	27-34 Jackson LLC	17	Open Shop	Y	Injured worker was laying 2'x2'x2" concrete pavers on the NW terrace of the 15th floor. While he was installing a paver on the floor 2 additional pavers on an A frame cart he was using tipped over and fell onto his left hand.	1	0	3	193,700	Y		20	250	Q00459818-IL-EW-SD Q00459828 Q00498278-IL-EW-SP Q00850660-IL-EL Q00870605-IL-PMM Q00677236-IL-SH Q008976534-IL-VT Q00890237-IL-EL Q00891424-IL-FN Q00913127-IL-PMM Q00913166-IL-PMM Q00945742-IL-EL Q01054804-IL-EA Q01068742-IL-SC Q01114717-IL-SC Q01154717-S1-BE	
1000004450		10/30/2024 10:00:00 AM	1089192	375	West 207th St	Manhattan	10034	General Contractor	2127669651	Business	Joy Construction Corp		County Electric LLC	01320	Sherman Creek LLC	4	Non-Union	Y	Worker was on a platform ladder in the closet working on the ceiling for Low Voltage wiring, when he was climbing down he missed the step and fell back and hit his knee and his head on his cart.A	1	0	0	600,000	Y		30	320	121189141 121205828 123899709	