

Local Law 78 Injury/Fatality Incident Report August 2024

[illegible]

Local Law 78 Injury/Fatality Incident Report August 2024

Incident Unique ID	Incident Date & Time	RIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Injured/Fatal	Incident Description Details	Injury Fatality Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Date of Employment	Injury/Fatality Worker Union Member	Number of Violations	Site Total Square Footage	Site New Building	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number
1000004343	8/27/24 9:30	3032113	755	Franklin Avenue	Brooklyn	11216	Subcontractor	9282837465	Business	NYC Special Contractors Inc.	NYC special contractors	NYC special contractors	623881	Tegern Capital	1	Non-Union	Y	At 9:30 it was notified that the worker - Wilson Ramirez collapsed on site not due to any activities he was doing. Last week the person told that he is not feeling well. Employee received a laceration to left forearm. Employee recalled location due to coming in contact with steel H-beam that fell while employee was tasked with removing H-beam [photo]. H-beam was being removed to facilitate excavation of area for new building foundation. H-section of H-beam column was protruding above grade level and the employee attempted to push it over. The H-beam moved in an unexpected manner and contacted employee's left forearm resulting in a laceration. Employee was sent to medical facility and EMT was contacted. Inspector 1 Leon Badge number 1386 responded.	1	0	8/27/2024	1	8/20/2023	N	0	65,000	Y	8	80	800840794-11-GC-CC		
1000004345	8/19/24 14:00	3000065	275	Atlantic Ave	Brooklyn	11201	General Contractor	9142810346	Individual	Yuri Perini Corporation	Yuri Perini Corporation	Department Design Construction LLC	2581	Department Design Construction LLC	4	Union	Y	148-18 Hillside Ave on 08/27/24 @9:00am Lifting comm. MSM Power LLC & S&S Enterprises NYP Corp. MSM Power LLC was operating the knuckle boom to transport lumber on the 3rd fl. The machine jerked before the lumber could be unstrapped on top which caused the formwork below to move and caused the accident. Luis Vivas & Alex Zhurav were injured in the accident and were rushed to the hospital. They both were discharged at 10:00pm 08/27/24 from the hospital with minor injury. Both person involved in the accident refused to report and claim insurance. They asked to cover their medical bills & pay for	1	0	8/27/2024	7	8/9/2024	Y	1	59,847	Y	22	339	800931842-11-MS, 800939363-05, 37, 8007701950-11-GC, 800151382-11-GC		
1000004347	8/27/24 9:50	4617668	148-18	HILLSIDE AVENUE	Queens	11435	General Contractor	3478870951	Business	360 PRESTIGE CONTRACTING	Enterprises NYP Corp	GC-421302	CHUNG LAM	10	Non-Union	Y	Carpenters were cutting plywood disks for edge forms. The # was cutting with the plywood nailed down to the table. Two hands on the silkwire, and cut level 4 grooves. While cutting, the saw ended up binding momentarily, while the #s weight continued forward. The # fell off with his left hand and brought it to the table to catch himself. At this point, with his right hand still firmly on the saw, the saw reengaged and cut through the top of his left index finger. The site was closed and no work was being done. Squatters set fire to some garage inside the site and FDNY came and took care of it. Third party delivery company drove from California to the site. Dropped off the trailer, the site contractor parked his load into the site and all went ok. Site contractor took the trailer back off site and returned to the driver who was outside the site waiting. Third party driver walked into the site to his left bags. While doing so on his knees, he passed out for a few seconds and fell on his side. Water was provided and ambulance was called for observation.	2	0	8/26/2024	3	8/6/2024	N	6	16,000	Y	9	95	020230047, Q20975618, Q20008064			
1000004348	8/26/24 10:40	1210065	2210	Manila Street	Bronx	10474	General Contractor	5163151792	Business	Skanska RI Industries	Skanska RI Industries	624170	NYC DEP	8	Union	Y	Carpenters were cutting plywood disks for edge forms. The # was cutting with the plywood nailed down to the table. Two hands on the silkwire, and cut level 4 grooves. While cutting, the saw ended up binding momentarily, while the #s weight continued forward. The # fell off with his left hand and brought it to the table to catch himself. At this point, with his right hand still firmly on the saw, the saw reengaged and cut through the top of his left index finger. The site was closed and no work was being done. Squatters set fire to some garage inside the site and FDNY came and took care of it. Third party delivery company drove from California to the site. Dropped off the trailer, the site contractor parked his load into the site and all went ok. Site contractor took the trailer back off site and returned to the driver who was outside the site waiting. Third party driver walked into the site to his left bags. While doing so on his knees, he passed out for a few seconds and fell on his side. Water was provided and ambulance was called for observation.	1	0	8/26/2024	3.5	6/9/2023	Y	0	8,133	Y	0	110	80041997-11-GC, 800430085-11-S1, 800430138-11-PL, 80044665-11-GC, 80077729-03-BM-GC, 42173840-11-MS, 80068420-11-FI, 49216112-02-4W-SF, 49216113-02-4W-SF			
1000004349	8/27/24 14:11	3831411	502	Wilson ave	Brooklyn	11221	General Contractor	6465295486	Individual			27838	505 Wilson ave LLC	1	Non-Union	N	The site was closed and no work was being done. Squatters set fire to some garage inside the site and FDNY came and took care of it. Third party delivery company drove from California to the site. Dropped off the trailer, the site contractor parked his load into the site and all went ok. Site contractor took the trailer back off site and returned to the driver who was outside the site waiting. Third party driver walked into the site to his left bags. While doing so on his knees, he passed out for a few seconds and fell on his side. Water was provided and ambulance was called for observation.	0	1/0/1900	0	1/0/1900	0	2,300	N	2	20	32118804-01-MB					
1000004351	8/29/24 14:30	3028368	36	W 66 street	Manhattan	10011	Person in Control of Site	2121026700			Site Safety Manager	2294	Esail	1	Open Shop	N	The site was closed and no work was being done. Squatters set fire to some garage inside the site and FDNY came and took care of it. Third party delivery company drove from California to the site. Dropped off the trailer, the site contractor parked his load into the site and all went ok. Site contractor took the trailer back off site and returned to the driver who was outside the site waiting. Third party driver walked into the site to his left bags. While doing so on his knees, he passed out for a few seconds and fell on his side. Water was provided and ambulance was called for observation.	1	0	8/29/2024	0	1/0/1900	0	0	718,000	Y	41	855.96	121130020			
1000004352	8/29/24 12:15	1027609	79	St Washington Sq	Manhattan	10003	General Contractor	2121216000	Business	Gilbane	DNA Construction, LLC	GC-094789	New York University	1	Union	Y	Luis Yankis was working on the roof level cutting a wood blocking in a bent over position, then when he stood up, he got dizzy and severe headache. Worker reported to his foreman about his condition, which the foreman took him to their charity vet him down and serve a water. After 15 min the condition did not go away, the foreman reported to Gilbane and the team made a decision of calling for ambulance. The worker was evaluated by EMS crew and taken to the hospital for the further examination. The worker was accompanied by his co-worker and a member of Gilbane team came to hospital. Worker was staying at Regency for a 3rd floor operator. Lost operator accidentally ran over worker's foot. Injured worker requested an ambulance. EMT determined nothing was broken and did not take worker	1	0	8/30/2024	5	10/0/2023	Y	0	40,000	N	7	70	M00814608-11-GC			
1000004353	8/29/24 15:00	4620885	26-38	Jackson Ave	Queens	11101	General Contractor	6462851128	Individual			Elise Mural & Glass	29618	Ratic LLC	1	Open Shop	Y	Worker was using a Regency for a 3rd floor operator. Lost operator accidentally ran over worker's foot. Injured worker requested an ambulance. EMT determined nothing was broken and did not take worker	1	0	8/30/2024	7	10/23/2023	N	0	300,000	Y	53	559	Q00028144		
1000004354	8/28/24 9:25	3043717	210	8 2nd Street	Manhattan	10009	General Contractor	2129966540	Business	Lettino Construction Corp.	Allied Enterprises	270 E 2nd Street Partners, 3001, LLC	8	Open Shop	Y	A worker allegedly fell from a working platform deck, falling approximately 6 feet before to a bench. The worker was transported to the hospital for evaluation. It appears the worker mis dropped while exiting Doka beams on the 5th floor deck. No unsafe conditions were found on-site, and all relevant documents were provided to DOB Inspector HANES RIGG & 2988. The worker did not sustain any serious injuries. The incident was closed as worker error was determined. No Conclusions were the hospital there were no broken bones or fractures. MR. Gonzalez was released from the hospital the same day.	1	0	8/30/2024	2.5	7/27/2024	N	40	65,213	Y	13	160	121208077-03-FO-SA, 121208077-01-MB, M003251283-S1, M003080486-11-GC, 800979413-11-PL, M00817750-11-PL, M0020979514-FI-PM, M002887217-11-PL, M002006624-11-GC, M004260120-S1-MS, M00426012				