Incident Incident Unique ID Number In	ncident Date & Time BIN House N	Number Street Name Borough	Zip Code Incident Reported By	Person Reporting Type of Perso Phone Number Reporting Incid	on Organization of Person lent Reporting Person in Control of Sit	ite Name of Contractor	Person Reporting License Number Name of Site	Number of Active Permits Owner Issued Site Union	Construction Work	er Incident Description Details	Injury Fatal	ality Injury/V	stality Numi	Fatality Injury, ber of Da Worked Emple	/Fatality Injury/ te of Works oyment Memi	Fatality Number of r Union Violation er Flag Issued	of ns Site Tot Foo	il Square Site New tage Building Flap	Site Existing Number of S Stories	Sin te Existing N Height	e Proposed Aumber of Site Stories	te Proposed Height Active Permit Number
1000001266	12/1/2020 7:30 1026318	COLUMBUS 10 CRCLE Manhattan	10019 General Contractor	2124816100 Business	STRUCTURETONE	ADCO ELECTRIC	2660 RELATED	1 Union	Y	NO WORK BEING PERFORMED, INDIVIDUAL WAS STANDING WHEN HIS LEFT KINE BUCKLED. THIS INCIDEND WS LINRELATED TO ANY WORK. Worker lost balance while descending and came off ladder. Worker made cortact with ground from approx. 2 or 3 feet. Worker requisited an	1	0 12	1/2020	1.5 8	8/8/2019 Y		0	75.000 N	54	750		M-00368435
1000001272	12/2/2020 8:10 1023395	106 West 56 Manhattan	10019 General Contractor	2016014065 Individual		MDB Development	1531 SAVANNA	1 Open Shop	Y	ambulance. Ladder remained in place and was secured on top and bottom (cleated and tied).	1	0 12/	3/2020	1 1	1/2/2020 N		2	87,692 Y			27	402 123057538-01
1000001274	12/4/2020 9:00 4077483 107-06	Queens Blvd Queens	11375 Person in Control of Site	9147607972	Site Safety Manager	Colgate Enterprise	2066 De Boulevard LL	C 4 Open Shop	Y	While material handling the workers hand was caught in between the hoist door opening	1	0 12/	4/2020	3 9/	/16/2020 N		0	142,615 Y			10	421535057-06-PL, 421535057-01-NB, 421535057-07-PL, 139 4PL005583-08-EW SP
							VC ATLANTIC PA	ATNERS,		Upon interviewing an eye witness, the witness stated - a worker was climbing down a job made ladder when he lost his footing and missed the last rung or two of the ladder hitting his hip and side on the wall												
1000001275	12/4/2020 7:40 3057522	545 Vanderbilt Ave Brooklyn	11238 General Contractor	2123885700 Individual	Construction		NA LLC.	1 Cown Shoo	Y	behind the ladder. Worker was taken to hospital for evaluation.	1	0 12			/16/2020 N		0	229.943 Y			29	312 321387478-01-NB
1000001276 N/A 1000001277	12/2/2020 0:20 2097311 12/2/2020 0:20 2097311	2830 Goulden Ave Bronx 2830 Goulden Ave Bronx	10468 Person in Control of Site 10468 General Contractor	6315631110 9142365455 Business	Superintendent Sezel	CCC AGA Enverironmental	25836 DASNY 620567 DASNY	1 Union 1 Union	Y	Employee fell through opening in roof.  Asbestos handler fell through hole from roof to ground.	1		4/2020 4/2020		/23/2020 Y /23/2020 Y		0	375.000 N 3.800 N	1	14 14		220668016-01-DM 220668016-01-DM
										Laborer Jean D. Bracho was working on roof floor using a wrench to unscrew scallfold equipment in high winds; a piece of screw broke of lift flow into fit wye due to winds. Leguny was not significant?. In the skie, Jean was driven to the doctor and returned to site the same day with a clean bill of health. He was placed as a security personnel and continued in the control of the control of the same day with a clean the control of the control of t												321583452, 321772710, 340705669, 340719066,
1000001278	12/3/2020 16:50 3427174	2201 Neptune Avenue Brooklyn	11224 General Contractor	7188519090 Individual			602821 2201 NEPTUNE	AVE LLC 7 Non-Union	Y	work from the next day onwards as well.  Worker felt chest pain while talking to his supervisor. Was transported		0 12/		7 1	2/3/2020 N		0	81,400 Y			7	88 800058863, 800203609, 800204165
1000001279 1559780	12/8/2020 10:41 1089972	401 9th avenue Manhattan	10001 General Contractor	2122296000 Business	Turner Construction		2305 Brookfield	1 Union	Y	for medical evaluation by ambulance.  During routing maintainance, maintenance before for CORE scaffold.		0 12/			2/8/2020 Y		0	30,000 N	69	690		123866502-01-EW-OT
1000001281	12/2/2020 10:00 1091631	200 East 34th Street Manhattan	10016 General Contractor	2017701120 Business	Noble Construction Group. LLC	Core scaffold Alistate 12 General	GC 605540 COA 200 East 3		Y	stuck head between mast structure and hoist.		0 12			2/2/2020 N		3	165.045 Y			31	390 12120v5221-01-NB
1000001283	12/9/2020 4:00 3426850	108 Downing Street Brooklyn	11238 General Contractor	5164824820 Individual		Contracting	27369 Fulton Star LLC	1 Non-Union	Y	Worker fell durine work	1	0 12/1	0/2020	24 12	2/7/2020 N		0	7.000 Y				85 321385880
1000001284	12/8/2020 12:00 3327047	NEW LOTS 96 AVENUE Brooklyn	11212 General Contractor	7182997000 Business	JEREMJAH		EBENEZER PLAZ 7863 PHASE 18 LLC	A.OWNER 20 Non-Union	N	A MAN WAS FOUND ON THE STH FLOOR EARLY MOINING ON 12/1/20, IN THE CLOSET OF APT SI, FOAM WAS COMING OUT OF HIS NOSE AND AND EXPORTED ON THE FLOORING HIS OCCUR. A CELL PROFILE AND MAID HAT WERE IN HIS LAP, OC CALLED 911, AND THE MAN WAS DECLARED DEAD ON THIS SCINE, OR REMOVED ALL PRECONTEL AND INFOCCIME REMOVED THE EDDY.	0	1 12/1	0/2020	0 :	1/0/1900	0	5	137,806 Y			,	218444-0-0-1-0-6, 21844-0-0-P-1, 0009111-0-EW MM; 1008759-01-14, 100875-70-0-0-0, 0009050-0-0-1-0-0; 12068878-0-1-0, 1206879-70-0-0, 12068880-0-1-0, 12068878-0-1-0-EW 07, 12184-10-0-1-0, 12184-10-0-1-0, 12168538-0-1-0-0, 2126538-0-1-0-1, 12184-10-0-1-0, 12168538-0-1-0-0, 2126538-0-1-0-1, 12184-10-0-1-0, 10, 14062602-0-1-0-1, 10052400-0-1-0-1-0-3, 14065-000-1-0-1 70-0-1-0, 14065538-0-1-0-0, 14066888-0-1-0-1-0-1, 140658-000-1-0-1
1000001286	12/9/2020 12:00 2129056	556 Beneen Ave Bronx	10455 General Contractor	9147231200 Business	Mountre Construction	Bietsas Plumbine	GC-022340 La Central Own	r LLC 6 Non-Union		Worker was trying to lift material from floor and felt pain in his back.		0 12/1			/23/2020 N			215.000 Y			12	220151859-01-EQ FN, 220151859-01-FQ, 220151859-01-FQ 142 EA. 220151859-01-NB. 240114835-01-EW, 240114933-01-EW
100001286	119912020 12500 1129056	336 BEFORE AWE BROTE	10405 General Connector	914/231200 Biolemas	Mounto Lonzaction	OMTIME PILITICITY	GC-022540 La Central Own	TILL 6 NON-UNION	•	worser was invest to set material from story and set pain in sits pair.  Worker was installing electrical books. Worker tricoed over a door forms	1	0 121	1/2020 48+	,,	23/2020 N			215,000 †			12	121 (St. 20013500-01-98. 200116855-01-07. 200116935-01-07. 21210961-01-14. 41710960-01-07. 20110237-01-07. 07. 417100960-01-144-07. 41100123-01-07. 01.2110237- 01-07. 04.1100086-01-07. 41100125-01-07. 04.1100237-01-07. 04.1100961-01-07. 41100125-01-07. 04.11001098-01-07. 04.1100961-01-07. 411001001-01-07. 04.11001860-01-07. 07. 00007376-03-14. 000161401-01-07. 000164037-1-07. 0004693-16-14. 0001693-01-14-07.
1000001287	12/14/2020 8:40 4617857 111-12	Astoria Boulevard Oueens	11369 Person in Control of Site	5169217100	Superintendent	Multi-Phase Electric	23799 NYCSCA	22 Union	Y	that was stared on the floor, fell, and injured his left shoulder.  One worker was reportedly moving a mini dumpster across the roof with the assistance of another worker. One of the dumpster wheels reportedly are now a depression in the concrete roof deck, topled over,	1	0 12/1	4/2020	2 4	/18/2019 Y		0	98.000 Y			5	72 000189678-11-VT. 000258118-11-VT
1000001288	12/14/2020 13:40 1014262	205 West 28th Street Manhattan	10001 General Contractor	2123885700 Individual		STNY	W28TH DEVELO	PMENT 1 Union	Y	and allegedly struck worker in leg. Second worker that was helping also alleges an injury to his foot/ankle. An ambulance was called.	2	0 12/1	4/2020	7 10	0/1/2020 N		0	72,696 Y			12	181 121205105-01-NB
1000001290 1560083	12/11/2020 9:15 1090952	185 BROADWAY Manhattan	10007 Subcontractor	5165389800 Business	CAPITAL INTERIORS	BUILDERS HO CORP	NA SL GREEN REAL		Y	SSM REPORTED THAT WHILE THE WORKER WAS WALKING DOWN THE STAIRS CARRYING METAL STUDS, TRIPPED AND FELL, AMBULANCE CALLED A worker name Ramon Sinhol was off loading windows from the back of a	1	0 12/1			/24/2020 N		0	13.726 Y			34	404 121188703
1000001292	12/11/2020 9:00 4623074 29-17	40th ave Queens	11101 General Contractor	7189371000 Business		Alumtec USA Corp.	621906 Lic Owner LLC	1 Non-Union		container with other Alumtec workers. At one point a window was shifted by the workers causing other windows to fall forward on to the injured worker. An ambulance was called and the injured worker was transported to the hospital.		0 12/1			/11/2020 N			109,925 Y				137 420666032-NB
100001292					SEC		Fortis Dumbo A	equisition,	,	Injured party was installing concrete panel forms when a form dislodged and fell down. Injured persons retractable lanyard was attached to form and when it fell it twisted employee as he was still attached in the front											10	
1000001294	12/15/2020 11:43 3426503	60 Front Street Brooklyn	11201 General Contractor	6468926230 Business	Urban Abelier Group, L.L.C.	Manhattan Concrete LLC		2 Cown Shoo	Y	to his ossitioning harness.  Pedestrian tripped over piece of sheet rock that was used to chock		0 12/1			/12/2020 N		3	405.000 Y			26	413 321384364-01-NB. 321384462-01-NB 121189597-01-AL, 140827041-01-EW-OT, 140827078-01-EW-
1000001295 2.12E+09	12/2/2020 12:00 1016004	424 Fifth Avenue Manhattan	10001 General Contractor	2124011220 Business	Archstone Builders. LLC		GC-608319 Amazon	4 Non-Union		conduit on sidewalk.		0 12/1		0 :		0	4	750,000 N 14,000 Y	12	163	12	OT.140829076-01-EW-OT
1000001300	12/22/2020 10:00 2000999	276 Grand Concourse Bronx	20451 Person in Control of Site	6466001866	Site Safety Coordinator				*	Worker fell over from standing position.  Worker was placing a piece of tile on a bathroom wall for tile installation, when in the process of setting the tile it broke and caused the worker to		0 12/2			/22/2020 N		0				12	124 220689921-01-NB
1000001304	12/22/2020 12:30 1085735	200 Park Avenue Manhattan	10017 General Contractor	2126821789 Business	Clune Construction	Coastal Tile & Marble	GC-606949 200 Park LP	1 Union	Y	sustain a laceration on his wrist  At 6:40am today, worker arrived and when to shanty. Worker began to	1	0 12/2	3/2020	6 1	2/7/2020 Y		0	40,000 N	59	808		140902316-01-EW-OT
1000001305	12/24/2020 7:00 1090786	1241 Broadway Manhattan	10001 General Contractor	2123885700 Individual		Roz-A-Lite	NA 1241 BROADWI	YLLC 1 Open Shop	Y	At 0-soam today, worser arrived and when to sharity. Worser began to complain he was not feeling well and passed out. This was not a work related incident. It was a personal medical issue. Ambulance called and worker taken to hospital. DOB notified.	1	0 12/2	4/2020	24 12/	/21/2020 N		0	178.884 Y			22	318 121188749-01-NB
1000001309	12/28/2020 8:15 1090163	450 West 126th Manhattan	10027 General Contractor	6464035708 Individual		Arete Construction	1799 Janus Propertie	12 Open Shop	*	Worker was cutting plywood in cellar level for wall blocking. Worker was using a circular saw to cut the wood when the saw bound and sicked out of the wood. The worker was holding the saw in his right hand when the blade struck the workers left hand causing laceration on all the fingers on their left hand except for his thumb.	1	0 12/2	8/2020	1.5 10)	/20/2020 N		2	300,000 Y			12	221643043-01-eq fn, 121643043-01-fn, 121643043-01-fn ea, 221643041-01-nh, 221643043-01-fn, 223395627-01-ew sf, 22339627-01-ew st, 223307363-01-ew sf, 223239342-01- ew fn, 140846235-01-eq ct, 140950789-01-eq ot, 140980972- 188 01-eq fn, 223598-01-eq ot, 240950789-01-eq ot, 240980972-
1000003312	12/28/2020 8:55 4443103 66-26	Metropolitan Averse Oseens	11379 Person in Control of Site	9142449100	Construction Superintered	ador Basin Francis	26968 Rentar	8 Open Shop	,	Adem Grygo (foremen) of Parinst Electric reported at 9:02am that while Ander Porce was installing conduct on a pipe rack busided on the 1st floor. Ander was lightening a coupler with a reventioner, the secredient slipped towards her and bit hisself on the face below his left eyeld. Ander them were this pipe site firm all claim spelled pressure to this key with a first and graze. While we wave questioning doubt he required on the first and graze. While we wave questioning doubt he required on the first and graze. While we wave questioning doubt he required on the first and graze to the contract of the contract of the state of the pipe shall be a shall be an extended as the collection of the forement Adam.		0 12/2	0/2020	2 4	/21/2020 Y			300,000 N		52		4117551 61-AL 42178551 61 EW 07, 42194552 61 EW 07, 42194386 61 W07, 0012598 61 AL, 0018477-61- E, 0001940 PLYT 0008517061
1000601312	12/20/2020 8:55 4443103 66-26	Avenue Queens	113/9 Person in Control of Site	9142449100	Construction Superinten	ratiot Electric		8 Open Shop	*		1	J 12/2	wy 2u/20	2 4/	/21/2020 Y		U	300,000 N	3	52		320912367-01-AL, 320912367-01-FO, 320912367-01-FO EA, 320912367-03-PL, 322040590-01-EW OT, 340669976-01-EW SD, 340669976-01-EW SP, 340670697-01-EQ OT, 340680506-
1000001314	44193.53125 3000556	50 Newins Street Brookhen	11217 General Contractor	7184891716 Business	Mega Contracting Groun. LLC	Laura Electric	Institute of Corr 603805 Living	13 Cost Shoo	Y	The worker was indocating a baker scaffold when he tried to lift up a portion of the scaffold and claims to have hart his back.  Worker Robert Huben was working on the 16th Boor sector B when he started experiencing chest pains. The worker went to site medic to get checked out, the immediately called \$11 to get an ambulance to site. The		0 12/2	9/2020	5 7/	/24/2019 N		0	118.576 Y			10	01-EW SP, 340600620-01-EQ OT, 340703732-01-EQ OT, 114 340717996-01-EQ CK. 3407806631-01-EQ OT
1000001315	44195.41667 3425091	85 Jay Street Brooklyn	11202 Person in Control of Site	2127366900	Site Safety Manager	ftael	85 Jay street(Br 1712 LLC	ooklyn), 1 Open Shop	Y	worker was picked up from site at 10:30em to go to Brooklyn Hospital. The worker was not lejured or exposed to any kind of chemicals that would have caused any chest pains.	1	0 12/3	0/2020	3 10)	/25/2018 Y		0	878,003 Y			21	210 121697455, 123697464, 123697473, 123697482, 123746535, 123746544, 123746553, 1237546562, 123755566, 123767548, 123792351, 123843733,
1000001320	44195.58333 1000855	7 Hanover Square Manhattan	10004 Owner	5088872352 Business	Ericson	Gotham Drywall Inc	7 Hanover Fee 0	remer LLC 22 Open Shop	¥	A subcontractor of Gotham Drywall was installing metal framing in one of the cellar bathrooms and tried to listen a piece of top track to a conduit. In doing so, the contractor drilled through a live electrical feeder.	1	0 1	5/2021	6 9/	/21/2020 N		1	980,000 N	27	350		MD0224965, MD0225313, MD0225839, MD0226018, MD0226428, MD0225880, MD0228560, MD0229412, MD0244321. MD0271326