

Local Law 78 Injury/Fatality Incident Report June 2018

Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Date of Employment	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number
1000000287		6/3/2019 9:00	3054173	369	Park Avenue	Brooklyn	11205	Person in Control of Site	3477785908			Construction Superintendent	GUB Maintenance Inc.	26691	Abe Scher	2	Non-Union	Y	The contractor was installing framing when he lost his balance on the ladder.	1	0	6/4/2019	1	5/31/2019	N	2	18172	N	4	45		321405957-01-EW-OT, 800095253-11-EL	
1000000291		6/10/2019 11:03	3329438	11	Hoyt Street	Brooklyn	11201	General Contractor	2123885700	Business	Triton Construction			35561	11 Hoyt Property Owner	1	Open Shop	N	Subcontractor worker was experiencing a personal medical condition - not work-related.	1	0	6/10/2019	40	9/27/2018	N	0	525,000	Y		53	545	321836162-01-EW-O	
1000000292	1512522	6/10/2019 9:30	1016004	424	5th ave	Manhattan	10018	Person in Control of Site	2127904200			Construction Superintendent	Alba Carting and Demolition Inc.	26278	WeWork	19	Non-Union	Y	Javier and three other workers were bringing minis to the street from the 1st floor of the building using a ramp to the street at the 39th street retail entrance. Javier was in the front of the mini as it was going down a ramp to the street, three other men were at the top side of the ramp controlling the mini. As the mini got to the bottom of the ramp Javier's hand/ finger got caught between the mini and the door frame causing the laceration to the finger. 1st aid was administered on site and Javier was transported to NYU Langone by Alba's safety director Carmine Pucci.	1	0	6/11/2019	2.5	8/15/2018	N	0	692812	N	14	162.67		123900528-01-EW-OT, 123900546-01-EW-OT, 140827014-01-PL, 140827041-01-EW-OT, 140827078-01-EW-OT, 140827096-01-EW-MH, 140829076-01-EW-OT, 140829156-01-EW-OT, 140829156-EW-OT, 140838958-01-EW-SD, 140839118-01-EW-SD, 140851870-01-EQ-OT, M00139223-11-VT, M00144050-11-VT, M00144086-11-VT, M00151579-11-VT, M00151580-11-VT	
1000000293	4777814	6/8/2019 11:00	4005166	23-15	44 Drive	Queens	11101	Person in Control of Site	2126837200			Site Safety Manager	HIGHBURY CONCRETE, INC	1950	PARK PLACE ESTATE, LLC	1	Open Shop	Y	WORKER USING A STEEL SAW CUTTING PLYWOOD CUT HIS FINGER AND WAS TAKEN TO NEAR CLINIC FOR STITCHES.	1	0	6/11/2019	4	6/1/2016	N	2	780,992	Y		67	722	420655954	
1000000294		6/10/2019 20:15	1001026	120	Broadway	Manhattan	10271	General Contractor	2125939700	Business	Theodore Williams Construction Company, LLC		Tri-State Dismantling Corp	21265	Silverstein Properties	3	Union	Y	An employee of one of our subcontractors, Segunda Santander of Tri-State Dismantling, was injured last night at approximately 8:15pm. While Mr. Segunda was cutting ductwork on a ladder, he cut the last hanger supporting the duct, which swung down and hit the podium ladder causing him to fall to the ground.	1	0	6/12/2019	2.5	10/13/2011	Y	0	33,000	N	41	542		123894544-01-EW-OT, 123894544-02-EW-MH, 123894544-02-PL	
1000000295		6/14/2019 12:15	3421880	911	Erskine Street	Brooklyn	112	Person in Control of Site	5162779300			Construction Superintendent	M C O Masonry	27047	Seaview Erskine Fountain A2 partner ship	1	Non-Union	Y	He was on the second floor setback operating the rope on a well wheel lowering scaffold framed. The rope jammed, he pulled on it and the wheel let go, it came down and hit him in the hard hat. The hat split open. The wheel then hit him in the back. Of the head. His name is Luis Ramon. The FDNY is transporting him. He did not lose consciousness, he has a deep wound in the back of his head. The FDNY took the damaged hard hat with them.	1	0	6/14/2019	5	6/14/2019	N	0	60000	Y		9	95	321195096-01-NB	
1000000296	Complaint #1512726	6/12/2019 12:30	1090777	53	west 53	Manhattan	10019	Person in Control of Site	3478802753			Site Safety Manager	Orange County Ironworks	2428	THE MUSEUM OF MODERN ART	1	Union	Y	Ironworker using magnetic drill, left thumb was caught in drill, treated by onsite medic who sent worker to hospital for further treatment.	1	0	6/14/2019	4	6/12/2019	Y	0	716000	Y		73	1050	121327224-01-NB	
1000000297	1512722	6/12/2019 11:25	1014526	531	6 AVENUE	Manhattan	10011	Person in Control of Site	6466267300			Site Safety Manager	STRUCTURETECH NEW YORK	2637	531-539 SIXTH AVENUE LLC	1	Open Shop	Y	WORKER PUTTING OXYGEN TANK IN THE CAGE, DROPPED THE BOTTOM EDGE ON HIS TOE. WORKER WENT TO URGENT CARE ON HIS OWN.	1	0	6/19/2019	4	6/1/2015	N	0	60,301	Y		13	102	123174803-01-FO	
1000000298	3707611	6/18/2019 12:40	3425091	85	JAY STREET	Brooklyn	11202	Person in Control of Site	2127366900			Site Safety Manager	CASINO DEVELOPMENT GROUP	1065	85 JAY STREET (BROOKLYN), LLC	1	Open Shop	Y	WORKER SLIPPED AND GOT SHOCKED WHEN HE GRABBED AN ELECTRICAL LINE. WILL BE TRANSPORTED TO HOSPITAL. NO AMBULANCE CALLED	1	0	6/19/2019	5	3/18/2019	N	3	878003	Y		22	210	321188415-01-NB	
1000000310	3707921	6/19/2019 9:45	3322044	3030	Surf Avenue	Brooklyn	11224	General Contractor	7184179000	Business	Adam's European Contracting Inc.			1222	NYCHA	5	Union	N	Resident of building claims to have slipped or tripped on a temporary ramp.	1	0	6/21/2019	0	1/0/1900	0	2	25000	N	14	140	321457892-01-EW OT, 321457892-02-EW OT, 340489929-01-EQ FN, 340490052-01-EQ SF, 340490141-01-EQ SH		
1000000312	3707902	6/20/2019 12:00	3000417	7	Boerum Place	Brooklyn	11201	General Contractor	2129378605	Business	Leeding Builders Group LLC		Aro Construction Group	604029	Avery Hall Investments	3	Open Shop	Y	While passing #11 rebar, finger was pinched between rebar and form work.	1	0	6/24/2019	1.5	1/2/2017	N	2	6000	Y		20	300	320912394-01-fo, 320912394-01-fo ea, 320912394-01-nb	
1000000314		6/24/2019 12:50	2093499	1216	Burke Avenue	Bronx	10469	General Contractor	7189373800	Business	Peter		Prograde Construction	602375	NYCHA	4	Union	Y	Roma is performing Roof Restoration for NYCHA and an employee of Prograde Construction (subcontractor) was throwing out debris in the container and slipped and fell injuring his right wrist.	1	0	6/27/2019	4	5/20/2019	Y	1	10	N	7	89		240247979-01-EW-OT, X00157658-11-EL, X00163474-11-SH, X00163632-11-FN	
1000000315		6/27/2019 8:30	1002816	28	Hubert Street	Manhattan	10013	General Contractor	7188036400	Business	Bulado General Contractors, Corp			886026	28 Hubert St Corp	4	Non-Union	N	Supervisor performing visual inspection and taking photographs of work in progress and fell 10 feet from pipe scaffold on to sidewalk bridge	1	0	6/28/2019	0	1/0/1900	0	1	250	N	6	60		123662349-01-EW-OT, M00159924-11-SF, M00159927-11-SH, M00159930-11-EL	
1000000316		6/28/2019 9:00	3400863	93	Linden Street	Brooklyn	11221	Person in Control of Site	9177478373			Construction Superintendent		27027	Moshe Braver	6	Non-Union	N	At approximately 8:43 am, a delivery of elevator rails was being delivered in the street, on the Grove Street side of the site. The flatbed of the truck was lowered and the banding wire holding the rails together, snapped and an elevator rail slid and struck driver of the truck on the top of his forearm. Driver sustained a laceration on the top of his arm. An ambulance was called to the Grove Street side of the site and the driver was taken to Wyckoff Heights Medical Center for stitches. Driver Dwayne S Proctor was alert and able to communicate with FDNY emergency personnel.	1	0	6/28/2019	0	1/0/1900	0	0	76,093	Y		5	65	321210202, 321272421, 340638475, 340666327	
1000000317	Complaint #2283423	6/19/2019 10:40	2127129	600	Bergen Avenue	Bronx	10455	General Contractor	9147231200	Individual		Structure Tech NY	22340	LA CENTRAL OWNERS LLC	10	Non-Union	Y	Worker #1 was mixing cement on the platform of the 2nd floor scaffold. Worker #2 was next to worker #1 moving OSHA planks to the 3rd floor. The plank slipped and struck worker #1 on the right shoulder and hardhat.	1	0	6/28/2019	3	5/28/2019	N	4	386,000	Y		13	153	240117137-01-EW SD, 220151868-01-EQ FN, 220151868-01-FO, 220151868-01-FO EA, 220151868-02-PL, 240108799-01-EW SD, 240108799-01-EW SP, 240242313-01-EQ OT, 240247327-01-EQ OT		
1000000318	4779142	6/20/2019 9:20	4615628	2807	Jackson Avenue	Queens	11101	General Contractor	2128871417	Business	Affinity Building Solution		Quality Sheet Metal	615978	LIC Site B1 Owner, LLC	9	Open Shop	Y	Worker an HVAC mechanic installing ductwork. While installing ductwork using an 8-FT stepladder, worker indicated as he stepped up on the ladder, ladder became unstable and he fell to the floor.	1	0	6/28/2019	2	6/3/2019	N	1	15500	Y		27	396	421739676-01-EW-OT, 421889807-01-EW-OT, 421889807-02-EW-OT, 421889807-02-PL, 421889816-EW-OT, 421889816-01-EW-OT, 421889816-02-PL, 421891652-01-EW-SP, 421891661-EW-SP	

Local Law 78 Injury/Fatality Incident Report June 2018

Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Date of Employment	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number			
1000000319	1006516	6/28/2019 8:50	1090122	66	Hudson Blvd	Manhattan	10001	General Contractor	2122296000	Individual			NYC Constructors	2505	509 W 34th street LLC	14	Open Shop	Y	Worker stated they were carrying a metal plate on the working deck, the worker tripped on guy cable and this caused the worker to injure their knee.	1	0	7/1/2019	2	6/7/2019	Y	0	2216567	Y		67	1031	122885422-01-EQ-FN, 122885422-01-FO, 122885422-01-FO EA, 122885422-01-NB, 122885422-05-PL, 123401112-01-EW SD, 123501433-01-PL, 123731836-01-EQ-OT, 123754268-01-EQ OT, 123808781-01-EQ OT, 123824512-01-EQ OT, 123892993-01-EQ OT, 140821065-01 EQ OT, 140854644-01 EQ OT				





Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Date of Employment	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number		





Local Law 78 Injury/Fatality Incident Report June 2018

Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Date of Employment	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number		



Local Law 78 Injury/Fatality Incident Report June 2018

Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Date of Employment	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number				



