## Local Law 78 Injury/Fatality Incident Report Febrary 2025

The details in this report are recorded by the property owner, contractor, etc. and the Department of Buildings does not edit the entries.

ncidentReporting																											IncidentReporting_Act Permits
	dent Incident Date & Time	BIN	Hou: Num		treet Name	Boroug		Incident Reported	By Person Reporting Phone Number	Type of Person Reportin Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owr	Number of Active Permits	Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Fatalit Count Count		Site Total Square Footage	New E Building N Flag		eight Num	osed Propose ber Height ories	Active Permit Number
000004566	2/1/2025 8:30:00 AM	10227	706 1251		venue Of ne Americas	Manhatt	an 10020	) Subcontra	ctor 212229600	0 Individua			Sherland And Farrington, Inc.	131401980	Mitsui Fudosan		Union	Y	Worker cut his index finger while using a saw and took a taxi to ER for treatment. Worker is expected to return to work at his next scheduled shift with no lost time.	1 0	0	2.1M		64 75	0		M01067026-I1-GC M01067041-I1-MS M01067052-I1-PL M01067062-I1 M01067083-I1-ST
000004567	2/3/2025 7:45:00	34293	27 625	F	ulton Street	Brooklyr	1120	1 Person in Control of	646499102	22		Site Safety Manager	QFS	1765	Galaxy Develope		Non-Union	n Y	Worker was cleaning a finished apartment when she claims the ladder she was standing on tipped over causing an injury to her left arm. Worker was transported by private	1 0	0	1000000	Y		40	470	M01084187-I1-EL 321583238-01-NB
000004568	AM 2/4/2025 8:00:00 AM	10281	68 36	W	V 66th street	Manhatt	an 10023	Site	212592680	00		Site Safety Manager	R&J	2294	Extell		Open Shop	Y	vehicle to the hospital for evaluation.  A flag person was hit by a pedestrian car while flagging at 65th street this morning	1 0	0	719000	Y		43	855	121190200-010-NB
000004569 2409	7 11 11	21307	30 671	Т	inton ave	Bronx	10455	5 General Contractor		i1 Individua			COSAN CONSTRUCTION	24693	Catholic Charities	1	Non-Union	n Y	Worker was supposed to be working in basement due to weather. He went to get his hammer on the scaffolding outside which was only 6 ft above the ground which he claims he went up to fetch the hammer and fell. Keep in mind that the worker was not supposed to be on the scaffolding and was wrapped with a tarp so nobody seen him fall. I was all	1 0	0	150,000	Y		12	160 ft	X00695344-L1-GC
000004570	2/5/2025 1:30:00 PM	10910	110 270	P	ark Avenue	Manhatt	an 10012	Person in Control of Site	347380276	68		Site Safety Manager		2657	JPMC	1	Union	N	set up as he himself cut the plank he said that failed  A technician was onsite for a field meeting when he became ill. The employee was seen by the onsite medic and was referred to a hospital. The employee was taken to NYU Langone by ambulance where he was treated for pneumonia and later released.	1 0	0	2.5 mil	Y		60	1388	121205604-01-
000004571	2/3/2025 3:00:00 PM	34293	625	F	ulton Street	Brooklyr	1120	1 General Contractor		32 Business	Galaxy Developers		QFS	613366	625 FULTON LLC		Non-Union	Y	Worker was cleaning a finished apartment when she claims the ladder she was standing on tipped over causing an injury to her left arm. Worker was transported by private vehicle to the hospital for evaluation.	1 0	0	1000000	Y		40	470	321583238-01-NB
000004572	2/5/2025 12:00:00 PM		48 42-1	4 0	rchard street	Queens	1110	1 General Contractor		0 Business	triton construction		AGIR Electrical LTD	n/a	BLDG Orchard		Open Shop	Y	Worker returned from lunch and reported to her supervisor that she did not feel well. She proceeded to faint at her work area and was brought to the medic for further evaluation when she fainted again and 911 was called. This was a medical issue, non work related.	1 0	0	190,000	Y		3	40	4440766887
00004573 2410	2/12/2025 12:00:00 PM		355	e	xterior street	Bronx	1045	General Contractor		Business	On Star Magement		EDC	GC 621905	Bryan Ra (REP)	mm 2	Non-Union	n Y	Support of excavation & earthwork phase. It was reported a worker was struck by object while material lifting operations occured. Worker was Taken to hospital and pronounced decease outside of construction site. A full incident report will be provided to construction safety enforcement with further details of the incident. There is no additional information to provide at this time, and its still pending further information on what exactly has occurred.	0 1	0	726,179	Y		43	400	210182069-01-FO 210182069-01-FO EA
00004574	2/11/2025 12:10:00 PM		525	S	ixth Avenue	Manhatt	an 1001	1 General Contractor		9 Individua			Industry Drywall Corp	30505	Izaki Gro Investme		Open Shop	Y	This event involved two individuals. They were moving metal studs on an A frame cart, when the A frame cart tipped over, landing on the injured parties' legs. Injured parties claimed to experience pain in legs. Authorities were contacted. Injured parties left the site in an ambulance assisted by FDNY. NYC DOB was notified of incident by phone, and they arrived onsite within an hour of incident.	2 0	2	121,000	Y		13	145	M08011197 I1 M08011197 S1 M08011197 S2
000004575	2/12/2025 12:00:00 PM		18 625	6	Avenue	Manhatt	an 1001	1 General Contractor		0 Business	Reidy Contracting Group		EC Framing, Inc.	GC-604484	625 Ownersh LLC		Open Shop	Y	Incident where worker fell off baker scaffold 7ft platform height while completing top track installation for drywall assembly.	1 0	1	28,000	N 5	10	0		M01153466-I1-GC
00004576	2/11/2025 11:30:00 AM			S	ast 15th treet	Brooklyr		General Contractor		Business	Structural Preservation System		Structural Preservation System	GC-009832	Property Centers	1	Non-Union		A piece of 4" x 20' long ductile pipe rolled off the truck while offloading it and struck the employee's right leg. The employee was positioned on the left side of the truck. The employee suffered an injury to his right leg which appeared to be a fracture.	1 0	0	200	N 4	50		70	Bo1019252-i1-st
00004577	2/14/2025 3:00:00 PM				edford ave	Brooklyr		Person in Control of Site	347243600			Construction Superintenden	fort scaffolding	27516	1730 Bedford realty llc		Non-Union	n Y	minor injury to construction workers foot while taking off side walk shed	1 0	0	30000	Y		6	70	
00004578	2/17/2025 8:00:00 AM	5 42096	32   166-	20 9	0th Ave	Queens	11432	2 General Contractor		7 Individua				2351	BRP	1	Open Shop	N	We walked into the construction site Monday morning February 17th, 2025 and noticed one of the fence panels on the back side of our site was blown loose and leaning against a car parked in the driveway of the home located directly behind the jobsite. There was a weather advisory issued for the weekend and no persons were injured, minor scratch observed to vehicle.	1 0	1	100,000	Y		12	150	421133151-01-NB
000004579 4	2/19/2025 8:50:00 AM	5 38166	97	-	Blenmore ve	Brooklyr	11212	2 General Contractor	1	84 Business	Lemle & Wolff		RL Mechanical	25545	Glenmor	) 1	Non-Union	Y	SLIPPED AND FELL ON THE 2ND FLOOR DURING HVAC DUCT INSTALLATION.	1 0	0	23630	Y		11	168	B00663906-L1-GC
000004580 1689	2/20/2025 10:25:00 AM		755 83	Т	hompson st	Manhatt	an 10012	General Contractor		4 Individua			ISG-Glaziers	602362	Spring st Owner, L		Open Shop	Y	Material handling(5 glass panel delivery) using drywall cart from 2 workers, worker pushing the dolly into the jobsite(Darwin Galvis) as they were entering the building on thompson st, the cart got stuck on the ramp, back tracked, caused the 5 glass panels to fall on the sidewalk, as Darwin tried to hold them, they trapped his right foot, injuring him. PM Anselmo and his coworker Tarcis, helped lift the glass off his foot. Worker claimed he was in pain, and requested an ambulance, was taken to langone hospital for treatment	1 0	1	4719	Y		7	75	M00553059
000004581	2/20/2025 1:00:00 PM	48019	09 4-34	2	6 Ave	Queens	11102	2 Person in Control of Site	718850175	54		Construction Superintenden	Framing C.M.G	030758	YNH Construc NY IIc		Non-Union	Y Y	2 Worker was pushing cart with sheet rocks on it. The work was being done on the first floor, moving materials. some sheet rocks fell down on 1 worker and hit his foot. Left foot got injured. Ambulance was called on site	1 0	1	134982	Y		7	85-5	Q00646746-S3-SE Q00646746-S6-MS Q00646746-S9-PL Q00646746-Z3-ST Q00938741-I1-EW-SI Q00941068-I1-EW-SI Q01151518-I1-SF Q01159962-I1-EL
00004582	2/24/2025 8:00:00 AM	5 46245	663 13-0	4 N	lameoke Ave	Queens	1169	General Contractor		Business	Mega Contracting Group LLC		Raikos Electric LLC	603805	Brisa Builders	4	Open Shop	Y	The employee was on the 5th floor in unit 501 cutting conduit pipes for the risers in the electrical shaft. He was allegedly placing the bandsaw on the pipe when he accidentally pulled the trigger and it dropped onto his pointer and middle fingers of his left hand. He was not on a ladder and did not slip or fall. He went down to Raikos' shanty, where his fingers were bandaged/wrapped by his foreman Michael E Santangelo. He left the site to seek medical attention for the injury, driven by his electrical super Lee Preece. No	1 0	1	55000	Y		9	115	Q00791713-I1-GC Q00791713-S3-SE Q00791713-S2-ST Q00985385-I1-FN
000004584	2/24/2025 10:25:00 AM		125 125	W	Vest End Ave	Manhatt	an 10038	General Contractor		00 Business	JRM Construction Mgmt. LLC		JSP Electric	37664	125 Wes End LLC		Open Shop	Y	Ambulance was called  JSP worker was completing the installation of pull cords in a security wiring pathway on top of a six foot type A platform style ladder. The worker fell off the ladder. Co workers found the worker on the floor holding his right shoulder. EMS was called. As EMS attended to the worker he stated he felt dizzy on top of the ladder and next thing he jnew he fell.	1 0	0	11,000	N 7	10	5		M01158585-I1-EL
000004585 1689	2/26/2025 12:45:00 PM		23 183		chrystie treet	Manhatt	an 10002	2 General Contractor		Business	Danya Cebus Construction		Best Mechanical Plumbing	GC-611702	Danya Cebus Construc		Non-Union	Y	Luis Felipe Molina, who is a worker for Best Mechanical Plumbing, was working in the cellar connecting a drain on the floor above ( ceiling work). Worker was by himself, and other workers found him laying on the ground in the working area unresponsive. No one on site witnessed what happened during the accident, everyone only was aware after they found the worker laying on the ground. EMT was called, and was taken to the hospital. No visible injuries were seen by the General Contractor, nor the EMT.	1 0	2	65,404	Y		17	214	M00674541-I1-GC
000004586	2/26/2025 3:30:00 PM	5 30005	285		chermerhorn treet	Brooklyr	11217	7 General Contractor		8 Individua			Manhattan Contractors	25513	3RE/Urb: Developr Partners	nent	Open Shop	Υ	A workers was cutting with a grinder when it kicked back and hit another worker in the hand	1 0	5	80,000	N E	75			320627416-01-EQ-FN 320627416-01-FO 320627416-01-FO-EA 320627416-01-NB 320627416-04-PL 34078432-01-EQ-OT B00406810-I1-SH B00718275-I1-VT B01006096-I1-EW-SE B01102330-I1-SF
000004588	2/27/2025 3:00:00 PM	5 48314	77 106-		OCKAWAY EACH BLVD		11694	4 Subcontract	ctor 718300822	Business	Tristar Developing Inc.			614827	106-02 Rockawa Beach, L	y	Non-Union	n Y	At the time, they were doing panel installation. The worker was wearing a hard hat. While on the ladder doing the panel installation, he turned his head around and bumped it against the sprinkler head which caused him to get a cut on the side of his head.	1 0	0	165844	Y		6	73.5	B01165378-I1-GC Q00608821-I1-GC Q00608821-S2-PL Q00608821-S3-EW-S Q00608821-S4-GC-C Q00737008-I1-FN Q00773868-I1-EL Q00963950-I1-SH