Local Law 78 Injury/Fatality Incident Report September 2023

Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Date of Employment	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number
1000003575	0	9/5/23 10:00	4624047	45219	Borden Avenue	Queens	11101	Person in Control of Site	6466916370			Construction Superintendent	The Vorea Construction	24839	The Vorea Construction	7	Non-Union	Y	At 10:00 AM one of workes from Skyline scaffolding as he was dismantling the scaffolding on east side of building felt approximately from 7' in height to thier overhead protection. FDNY and DOB where notified. Injured person Jose Romero was taken by FDNY to the hosoital	1	0	9/5/2023	3	9/6/2022	N	2	42.000	Y			4	67'	Q005160B8-I1-GC, Q005160B8-S5-PL, Q008000779-I1-PN, Q008046821-I1-EL, Q008533221-EL, Q008701681-SP, Q008048928-I1-SH
1000003578		9/5/23 10:40	1091692	407	West 206 Street	Manhattan	10034	General Contractor	9142468292	Business	Chatsworth Builders LLC		RNC Industries LLC	600849	West 207 Grocery Owners LLC	5	Open Shop	Y	RNC Industries employee claims to have felt dizzy and faint. In an abundance of precaution, worker was sent to a nearby hospital for evaluation.	1	0	9/6/2023	4	6/5/2023	N	0	616.809	Y	14		140		M005994905, M007480844, M007828825, M008028712, M008028714
1000003579		9/5/23 14:30	4624582	41-34	27th St.	Queens	11101	General Contractor	6466793500	Business	Consieli Construction Co. Inc		Casino Development Group Inc.	622919	Grubb Properties. LLC	21	Open Shop	Y	While working on the first floor deck laying rebar, the worker started to experience some signs of heat stress. He decided to take a break by going down to the cellar to sit in the shade. At that time he began experiencing more symptoms of heat stress (cold clammy skin, tingling in the back of the neck. no lonner sweating. cramsine.)	1	0	9/6/2023	7	8/24/2023	N	1	371.191	Y	27		336		CN00021822-FN, Q000557681-S1-SE, Q000557681-S2-FO-EA, Q000557681-S3-ST, Q000557681-S5-CC, Q000557681-S6-PL, Q000557681-S8-MS, Q000557681-S9-EW-SD, Q000557681-S9-EW-SP, Q000570601-I1-SH, Q000571846-I1-PM, Q000571996-I1-PM, Q000721301-PN, Q000602227-I1-ST, Q000607681-I1-GC, Q008174821-I1-EL, Q008276093-I1-PMBA, Q008307711-I1-EL, Q008368025-I1-EL, Q009116643-I1-EL, Q008303031-I1-EW-SD
1000003580	4936490	9/6/23 11:00	4000000	26-32	Jackson Ave	Queens	11101	General Contractor	6462853128	Individual			Capital Interiors	29618	American Lion LLC	1	Open Shop	Y	Worker felt dizzy and while coming down a ladder banged his hose in ladder and eat a bloody nose.	1	0	9/7/2023	4	8/30/2023	N	0	10.000	Y	53		547		Q00668144
1000003581	N/A	9/5/23 14:30	3336349	9216	7th Avenue	Brooklyn	11228	General Contractor	5163060548	Individual				39625	Polv Prep	1	Open Shop	Y	On 9/5/2023 around 2:30pm Inmer Yrigoin (Iconic Subcontractor) carpenter was accidently injured. The incident occurred in basement level, worker was lifting a piece of sheetrock by himself and tripped on a wood plank and fell on the ground. The worker hurt his back and knee and was transported to the ER via ambulance.	1	0	9/7/2023	7	6/1/2023	N	1	9.980	Y	2		30		B00619525
1000003582		9/7/23 8:30	3321839	2946	W. 23rd Street	Brooklyn	11224	Person in Control of Site	9173373362			Site Safety Manaxer	Dobco Inc.	1344	NYCHA	8	Union	Y	A laborer was assisting with installing lifelines on the Roof of the building. The laborer claims the wire rope slipped from his right hand striking his ankle finger.	1	0	9/7/2023	2	12/23/2019	Y	0	15.000	N	17	156			321187389-01-AL, 321187389-04-PL, 340750725-01-EQ-OT, B00539456-I1-SH, B00539467-I1-FN, B00450780-I1-SP, B00541230-I1-PN, B00766892-I1-EL
1000003583		9/1/23 14:15	4286188	182-22	150th Ave	Queens	11413	General Contractor	6466793500	Business	Consieli Construction Co.. Inc.		Meridian Restoration	GC-622919	Cushman & Wakefield, Inc.	9	Open Shop	Y	Worker on the ground floor was chipping brick and mortar with an electric chipping gun. A small 2x4 ledger piece became dislodged and when the worker backed up to avoid it from landing on him he mis-stepped and fell backwards to the ground. An ambulance was called and the worker was able to walk, talk and climb in under his own power	1	0	9/7/2023	7	7/14/2023	N	3	82.489	N	1	27			Q007235747-I1-GC, Q007267591-I1-GC, Q007270481-S1-SE, Q007270721-MS, Q007271001-I1-PL, Q007357657-I98-EW-SP, Q008053721-I1-PN, Q008379511-I1-EL, Q008693361-I1-VT
1000003584		9/7/23 11:00	3019905	1510	Broadway	Brooklyn	11221	General Contractor	9174187471	Individual			Sandstone	29293	Maouenten	11	Non-Union	Y	Informed by Sandstone foreman (Mario Escorbar that worker (Jorge De Jesus Campos was carrying a five gallon bucket filled with mortar at stair D from the second floor to the first floor, when he slipped and lost his balance from a possible plastic cup on the ground, causing him to fall and landing on the ground on the first floor, which he claims to have insured his back. which no witnesses observed the incident.	1	0	9/7/2023	4	9/7/2023	N	0	115.530	Y	8	72'7"			321593673-01-FO, 321593673-02-FO-EA, 321593673-01-NB, 321593673-05-PL, B00000847787-I1-VT, B00083163I-I1-PPM, B00745845-I1-PN, B00821737-I1-SH, B00846125-I1-EL, B00897597-I1-PMM, B00914789-I1-EL
1000003585		9/7/23 10:10	4000000	4401	northern blvd	Queens	11101	General Contractor	7182608940	Business	NY Developers & Manaeement LLC		Sandstone Structures LLC	GC-617977	Silverstien Properties LLC	20	Non-Union	Y	the worker was carrying material from one floor to the next on the scaffoldine and tripped on the stairs.	1	0	9/7/2023	3	8/28/2023	N	0	430.000	Y	13		175		Q009589457-I1-GC, Q009589457-S3-ST, Q009589457-S4-MS, Q009589457-S5-PL, Q00642992-I1-EW-SD, Q00642992-I1-EW-SP, Q00646830-I1-EW-SD, Q007357544-I1-PN, Q008338851-I1-SH, Q008357477-I1-EL, Q008365081-I1-PMM, Q008343149-I1-PMM, Q008472344-I1-EL, Q008598831-I1-SP, Q008679748-I1-PMM, Q008805466-I1-VT, Q008828071-I1-VT, Q009302779-I1-GC
1000003586	0	9/5/23 11:15	1059047	389	manhattan ave	Manhattan	10026	General Contractor	7186768059	Individual				622643	HHLA VENTURE I LLC	2	Non-Union	N	At the time of the incident, Leo Salazar a temp fill-in laborer by our subcontractor Method Maintenance to remove material from the roof. On the floor below, the joist that was bracing the header snapped & one (right side) dropped with the 4 joists attached. Leo S. was standing on the floor above & slid down along with the header & retained a cut on his inner right thigh. EMS was called immediately by Method General Contractors; Leo S. moved to a safe area, was conscious, aware & speaking clearly not showing any signs of paralysis or serious injury. Medics transported him to the ER	1	0	9/7/2023	0	1/0/1900	0	0	2.880	N	3	38			M00677925. M00305092
1000003587		9/7/23 14:30	3429566	60	Wharf Drive	Brooklyn	11222	Person in Control of Site	6315213333			Site Safety Manaxer	Master Roofing	2639	Ninth Avenue Construction	3	Open Shop	Y	Worker was laying pavers on the 37th Floor Balcony when suddenly he felt sick, weak, fatigue. A fellow co-worker brought him to the elevator down to the first floor and he sat down and waited for an ambulance. The worker was visibly uncomfortable but remained conscious the entire time. Medics arrived and assessed him for heat exhaustion and dehydration. He was taken to Brooklyn Hospital for further evaluation.	1	0	9/8/2023	7	9/7/2023	N	0	636.000	Y	40		400		320909996-01-NB, 320909996-01-FO, 320909996-01-FO-EA
1000003589	N/A	9/6/23 16:00	3034540	975	Nostrand Ave	Brooklyn	11225	Person in Control of Site	2122853023			Construction Superintende	Concrete Services & Maintenance Corp	26077	Nostrand Green, LLC	9	Open Shop	Y	Worker was moving cardboard boxes to the tash when he was poked himself in the right eye. worker was taken to the hospital	1	0	9/8/2023	48+	8/14/2023	N	0	58,792	Y	7		80		B00622668-L1-GC, B00622668-S2-ST, B00622688-S5-SE, B00622688-S6-FO-EA, B00688625-I1-PL, B00688630-I1-EW-SD, B00703059-I1-FN, B00752248-I1-EL, B00842546-I1-EL
1000003594		9/7/23 13:00	3428521	29	Huron Street	Brooklyn	11222	General Contractor	9172272636	Business	Leeding Builders Group, An AECOM Company		PGB Group	604024	QBDK Huron LLC	1	Open Shop	Y		1	0	9/11/2023	5	8/11/2023	N	0	500	Y	14		150		121185350
1000003595		9/8/23 12:00	1024730	264	West 46th street	Manhattan	10011	Person in Control of Site	6464130349			Construction Superintende	Trideny	221	Extell Development	3	Open Shop	Y	Worker while walking down stair tower slipped and hurt leg	1	0	9/11/2023	7	9/8/2023	N	0	810,000	Y	58		1194		121208326-01-PO, 121208326-02-FO-EA, M00582748-11-FN
1000003596		9/11/23 7:40	3426198	532	Neotune Avenue	Brooklyn	11224	General Contractor	7187585333	Business	Rvbak Develoonent		Rvbak Develoonent	624218	532 Neptune Residential LLC	1	Non-Union	Y	Had a worker fell on the 22nd floor tower 2 at approximately 8:40 AM. Worker was covering hole when one leg slipped into the hole and his other leg and body stayed on the slab. Worker was in pain in groin area. lower back and riaht lee. Ambulance was called and DOB notified.	1	0	9/11/2023	1.5	6/5/2023	N	2	100.000	Y	22		240		320627714-01-NB
1000003597	3926342	9/11/23 10:25	3429537	90	Flatbush Avenue	Brooklyn	11217	General Contractor	6468926280	Business	Urban Atelier Group		Ennish Construction Corp	615447	Allov	25	Open Shop	Y	A worker was applying finish caulicking where the wall and ceiling meet in an apartment. The worker was working off of a Platform ladder; The worker over extended which resulted in a fall off of the ladder. The worker was taken by ambulance to the hospital(Shoulder Dislocament).	1	0	9/11/2023	3	8/15/2023	N	1	400.000	Y	44		512		321595145-01-FO, 321595145-02-FO-EA, 321595145-01-NB, B00544999-I1-FN, B00577563-I1-EW-FP, B00577563-I1-EW-SD, B00598242-I1-PM, B00687629-I1-VT, B00697396-I1-EL, B00699274-I1-EL, B00699274-S1-EL, B00708026-I1-EL, B00709026-I1-PM, B00709042-I1-PM, B00718593I-PM, B00718749-I1-EL, B00725585-I1-VT, B00769291-I1-PM, B00783602-I1-EL, B00793693-I1-EL, B00794742-I1-VT, B00795134-I1-VT, B00802913-I1-BE, B00801527-I1-PM, B00846752-I1-BE
1000003598	3926433	9/11/23 14:45	3429328	450	GRAND AVE	Brooklyn	11238	Person in Control of Site	9174826032			Construction Superintendent	CITI BUILDERS NY LLC	26882	CHANA LEAH BAUKANY	12	Non-Union	Y	Worker Luis Miguel Ordonez, a laborer, was walking down the stairs from the 6th to the 5th floor when he slipped. Nobody saw the incident or was a witness to it. When he was found lying on the stairs, he requested an ambulance. Initially, he did not want to specify the injuries he had suffered but requested an ambulance. After numerous attempts by Leah Baikany, the Competent Person, Luis Miguel Ordonez said his arm was hurt. There were no visible broken bones or swelling. He remained conscious throughout and was taken to the local hospital.	1	0	9/12/2023	8	7/28/2023	N	0	41,385	Y	7		82		B00408724-I1-EL, B00408725-I1-SH, B00582010-I1-GC, B00582010-S3-PL, B00582010-S4-MS, B00582010-S6-ST, B00710350-I1-FN, B00750770-I1-SE, B00750770-I1-FO, B00756822-I1-EW-SD, B07996241-I1-SP, B08010968-I1-EL
1000003599	42159	9/12/23 8:30	2130750	1600	Grand Avenue	Bronx	10453	General Contractor	9172996797	Individual			Vava Restoration	2318	Starhill Phase 1 Owner LLC	8	Non-Union	Y	A laborer for the Mason Contractor was cleaning the 13th floor and dismantling the scaffold. He was discovered laying on the ground. He said he fell from the scaffold. He was complaing that he could not move. 911 was called and he left in an ambulance.	1	0	9/12/2023	1	9/12/2023	N	0	251.000	Y	14		155		210180828-01-NB, K00544727-I1-PL, K00648896-I1-EW\\-SD, K00648897-I1-EW-SD, K00788002-I1-SH, K00788011-I1-PM, K00788050-I1-PM, K00798337-I1-EL
1000003600	3926074	9/8/23 9:00	3344948	180	Staee WALK	Brooklyn	11206	General Contractor	6313641778	Business	MDG Desien & Construction LLC		Venia Contractine LLC	31838	Williamsburc PACT LLC	11	Non-Union	Y	OVERHEAD HOLE IN THE CEILING WAS COVERED BY A PIECE OF SHEETROCK. DEBRIS BROKE THROUGH THE SHEETROCK AND HIT WORKER IN THE BACK OF THE HEAD. IT CAUSED A GASH WOUND THAT WAS TREATED WITH A GAUZE PAD UNTIL HE GETS TO URGENT CARE. WORKER CLAIMS HE WAS WEARING A HARD HAT.	1	0	9/12/2023	9	11/20/2020	N	0	25	N	4	40			B00492025, B00492752, B00727255, B00764949, B00818123, B00818187, B00916770, B00925741, B00925865. B00925887. B00925914
1000003601	3926077	9/8/23 0:20	3344948	180	Staee Walk	Brooklyn	11206	General Contractor	6313641778	Business	MDG Desien & Construction LLC		Venia Contractine LLC	31838	Williamsburc PACT LLC	11	Non-Union	Y	WORKER'S KNEE PAD GOT STUCK IN LADDER CAUSING WORKER TO LOSE CONTROL AND FALL ON HIS BACK	1	0	9/12/2023	5	5/23/2022	N	1	88	N	4	40			B00492025, B00492752, B00727255, B00764949, B00818123, B00818187, B00916770, B00925741, B00925865. B00925887. B00925914
1000003602	1647937	9/12/23 8:00	1091643	310	Hudson Street	Manhattan	10013	Person in Control of Site	6467730096			Site Safety Manaxer	Core Installation	1757	Hudson Square Realty, LLC	3	Union	Y	CORE Glasiers were at the 17th floor East Tower opening a plywood crate that contained shadow box glass for the former hoist openings. As the glasiers opened the plywood box, three glass pieces within the crate began to shift and proceeded to fall out of the plywood crate and strike one elazier.	1	0	9/13/2023	1	9/29/2022	Y	1	1.300.000	Y	22		320		121205864-01-FO, 121205864-02-FO-EA, 121205864-01-NB
1000003603		9/13/23 9:00	3429031	2224	Crossev Avenue	Brooklyn	11214	Person in Control of Site	7182608940			Other	Hvbrid Improvements Inc		Crossey AIRS LLC and Crossey Airs Fee Holder LLC	13	Non-Union	Y	Worker was on a ladder on the 9th floor with his back towards the stairs. When stepping off the ladder he lost his balance and feel backwards down the stairs.	1	0	9/13/2023	3	8/14/2023	N	0	7.500	Y	11		148		321600362-01-NB, B00503572-I1-MS, B00503585-I1-PL, B00503606-I1-EW-SD, B00503744-I1-ST, B00637703-I1-PN, B00665163-I1-EL, B00890413-I1-PMM, B00893843- I1- EL, B00901977-I1-PMM, B00908758-I1-VT, B00914861-I1-SP, B00920303- I1- EL
1000003604		9/13/23 7:00	3000605	275	Atlantic Avenue	Brooklyn	11201	Person in Control of Site	7187529200			Site Safety Manaxer	IAR	2705	City of New York/DDC	16	Union	Y	Asbestos workers were spreading plastic on the roof to begin abatement of the parapet of ACM. The worker pulling the plastic was walking backward kicked a hole cover consisting of 2"planks. One of the planks fell and the worker fell through the opening the plank was in; approximately 9 1/2'. The worker fell approximately 18' to the concrete floor below.	1	0	9/14/2023	1	9/11/2023	Y	4	480.000	N	11	175			322105422-01-DM, B00665663-I1-EL, B00669477-I1-PM, B00670007-I1-GC, B00672424-I1-FN, B00672443-I1-SH, B00672771-I1-SP, B00675543-I1-ST, B00690164-I1-EN-SD, B00702476-I1-EL, B00719236-I1-PM, B00754557-I1-GC, B00754926-I1-PM, B00765827-I1-VT, B00795427-I1-EL, B00816691-I1-GC
1000003607		9/14/23 8:20	1084397	20	BATTERY PLACE	Manhattan	10280	General Contractor	6312491872	Business	POSILLICO CIVIL, INC.		POSILLICO CIVIL, INC	GC-602187	BATTERY PARK CITY AUTHORITY	5	Union	Y	Lowering a piece of granite into the Hudson River using a crane and the chock. Employee took laborer to NY Presbyterian Lower Manhattan Hospital. Employee was wearing gloves during this operation.	1	0	9/15/2023	1.33	1/19/2023	Y	0	304,920	Y	0		0		M00743423-I1-GC, M00743461-I1-ST, M00743461-S1-FO, M00764648-I1-EA, M00847014-I1-FN

Local Law 78 Injury/Fatality Incident Report September 2023

Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Date of Employment	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number
1000003608	na	9/12/23 8:50	4623739	44978	Malt Drive	Queens	11101	General Contractor	2129845000	Business	Bud North GC LLC		Sal-Vio Construction	GC 623328	Bud North LLC	1	Open Shop	Y	Worker went onto a suspended scaffold by the accessible ladder without donning a PFAS harness. He works for the mason subcontractor is unclear what he was doing on the scaffold. It seems he was setting up his work area. The scaffold platform was between two floors with an interior exposure of appx 5 ft to the 25th floor. The worker fell onto the 25th floor deck on his feet and then went down on his buttocks. Per the onsite medic, the worker was not injured and all his vitals were fine. Worker was transferred to Bellevue hospital, checked out and released the next day with no sustained injuries	1	0	9/15/2023	3	8/24/2023	Y		1	846.238	Y			39	400	000810431
1000003610		9/15/23 14:20	1033543	609	Columbus Ave	Manhattan	10024	Person in Control of Site	7184720830			Site Safety Manager	CEDO Services Inc	2395	Robert Irvine	1	Non-Union	Y	Employee accepting bucket from electric hoist lost control and bucket contacted his lee	1	0	9/15/2023	6	9/14/2023	N		0	1.000	N	19	200			123913541
1000003611		9/14/23 10:35	3027909	684	dean street	Brooklyn	11238	General Contractor	6469528634	Business	Pars Elite Construction Group		JCVC	618022	684 Dean Partners	1	Non-Union	Y	Labor was cleaning the site by front door and picked up a large piece of wood by himself and fell on the concrete edge 2 feet deep. 3	1	0	9/18/2023	3	9/14/2023	N		0	1.500	Y			0	0	B00423899-I1-PN
1000003612		9/13/23 14:15	3426198	532	Neptune Avenue	Brooklyn	11224	General Contractor	7187585333	Business	Rvbak Development		TRV Mechanical	624238	532 Neptune Residential LLC	1	Non-Union	Y	Worker was wrapping duct with insulation, facing wrong way on ladder, slipped and fell approximately 3 to 4 feet to ground. Worker complained of pain in her legs. Said she couldn't get up, it was too painful and an ambulance was called. Area was cautioned off and DOB notified	1	0	9/20/2023	6	8/1/2023	N		1	100.000	Y			22	240	320622714
1000003613		9/16/23 8:00	3256921	10502	Avenue D	Brooklyn	11236	General Contractor	7186474924	Business	LoSardo General Contractors Inc.		San Sebastian Enterprise Ltd.	GC-3810	DSNY	5	Union	Y	During roof removal, an unforeseen section of metal decking failed and worker fell to lower level.	1	0	9/20/2023	1	5/8/2023	Y		0	154,154	N	1	20			320085266-01-EW-OT, B00345572-I1-EW-SP, B00781355-I1-EL, B00883443-I1-EL, B08003284-I1-SP
1000003614		9/20/23 10:00	1083026	2	Penn Plaza	Manhattan	10121	General Contractor	9172399840	Individual			W&W	2868	Vernado	1	Union	Y	The employee was taking a delivery on the loadign dock. While taking the delivery he lost his footing and fell off the dock, he was taken to the hospital via ambulance	1	0	9/20/2023	4	2/16/2023	Y		0	1.000	N	32	340			121189356-01-el
1000003616		9/18/23 9:00	3427949	1100	Myrtle Ave	Brooklyn	11206	Subcontractor	9146544870	Individual			LIVE Constr.	1629	SWDM MYRTLE LLC	4	Non-Union	Y	Live employee was performing spot demo utilizing approx. 2 feet high working platform / baker scaffold when he allegedly lost balance and fell of the platform.	1	0	9/20/2023	1	9/18/2023	N		7	298.000	Y			11	115	321592157-01-NB, 320927739-01-DM, 320927739-01-EQ-OT, B00607531-I1-PN
1000003618		9/20/23 6:45	4456705	22-61	45th Street	Queens	11105	General Contractor	7189326342	Business	Mexa Contractine Group LLC		New Benchmark Contractine	603805	M045 Developers LLC	4	Open Shop	Y	Allegedly Miguel Gonza was attempting to install a piece of sheetrock (3'10" x 16.5") in apartment 2G, when he overreached , causing him to lose his balance and fall. Miguel had a cut on his head and was speaking out regarding his back.	1	0	9/20/2023	1	9/13/2023	N		0	162.510	Y			8	95	421130035-01-FO, 421133035-01-FO-EA, 421130035-01-NB. C005086675-I1-PN
1000003619		9/19/23 9:45	4004595	38-03	31st Street	Queens	11101	Person in Control of Site	5167901228			Construction Superintendent	Fast Service	23118	LIC 31 LLC	1	Non-Union	Y	On 9/19/23 at approximately 9:45am, worker Yomayra Vasquez claims to have slipped while walking down the stairs. She requested an ambulance, and she was removed from the site by FDNY ambulance. There were no witnesses to the incident, and no further information regarding her condition is known.	1	0	9/20/2023	2	9/1/2023	N		0	758	Y			5	48	421779285-01-NB
1000003620		9/19/23 21:20	1091643	310	Hudson Street	Manhattan	10013	General Contractor	2124816100	Business	Structure Tone. LLC		Wohl Diversified Services	GC-002660	Disney	2	Union	Y	Worker was on a single-tier frame baker scaffold removing plastic protection wrap from ductwork, when one wheel of the baker went into a small hole opening in the raised floor causing the baker to tip over.	1	0	9/21/2023	6	6/9/2023	Y		0	1,200.000	Y			22	338	M00787158-I1-GC. M08046294-I1-EL
1000003621		9/20/23 10:30	2817578	3095	Webster Ave	Bronx	10467	General Contractor	7186537766	Business	The J. PILLA GROUP		K&E Builders	601734	GEEL Community Services	12	Open Shop	Y	A worker fell down the stairs coming from the second to first floor. She lost her footing and fell halfway down. She was concious but in visible pain so we called 911 who dispatched an ambulance to take her to the hospital. We called DOB and they sent inspector Kalaba badge 2989 who determined the stairwell was clean and safe and that it was an accident. No violation given. Our building is a 11 story block and plank residential still in the superstructure phase on the 5th floor.	1	0	9/21/2023	48+	7/31/2023	N		0	76.387	Y			11	130	210181364, 210181364-01-FO, 210181364-01-FO-EA, 210181364-01-nb, CN000472223, M00356567-I1-ew-sd, M00356567-I1-ew-sp, M00677392-I1-fn, M00832124-I1-en, X00909901-I1-el, X00909934-I1-anm. M00910273-I1-el
1000003622		9/20/23 13:45	1024730	264	West 46th street	Manhattan	10011	Person in Control of Site	6464130349			Construction Superintendent	Trident General Contractine	221	Extell	3	Open Shop	Y	While setting a Rock Anchor worker was attempting to cut plastic sheathine off anchor and cut his right index finger	1	0	9/21/2023	7	5/29/2018	N		0	810.000	Y			58	1194	121208326-01-FO, 121208326-01-FO-EA, M00582768-I1-FN
1000003624	0.479166667	9/20/23 12:00	1091666	509	3 Avenue	Manhattan	10016	General Contractor	2122519600	Business	Charlton Development Group LLC		Royal Floorine 11 Corp	GC617769	Third and Thirty Four LLC	10	Open Shop	Y	Worker fell down stairs while carrvine a pail of floor primer	1	0	9/21/2023	4	9/18/2023	N		1	40	Y			35	400	121205640, M00614010-I1-PM, M00623809-I1-SH, M00624093-I1-PM, M00624733-I1-FN, M00625033-I1-PM, M00635968-I1-PM, M00637129-I1-PM, M00637137-I1-VT, M00675865-I1-EL
1000003629		9/22/23 11:49	3087764	2777	Atlantic ave	Brooklyn	11207	Person in Control of Site	3476237427			Construction Superintendent	MTW	28196	YC Atlantic LLC	1	Non-Union	Y	It was reported to me that a worker fell down a flight of stairs when I arrived EMT was on site removing the worker from site. No evidence of blood on site.location 2777 Atlantic ave staircase B between 4th and 3rd floor.work Description at the time of incident house keeping	1	0	9/22/2023	4	8/24/2023	N		0	80	Y			8	84	B00624645-I1-GC
1000003630		9/21/23 8:50	3330787	54	Crown Street	Brooklyn	11225	Subcontractor	2126062222	Business	Core Scaffold		OFS	123123	Carmel Construction East	7	Non-Union	Y	The flagger was inside the controlled access zone that she was supposed to be protecting from pedestrians walking into. She was told several times by site supervisor to move, instead she sat on the barrier where a fence was being installed. The fence was not attached yet and fell forward and bumped her as she sat between barrier and where work was being performed. She was supposed to be 15 yards away by pedestrian crosswalk. Instead she ignored directions from site suzer.	1	0	9/22/2023	2	3/15/2023	N		1	450.000	Y			17	175	321098389-01-DM, 321098389-01-EQ-FN, 321115100-01-EQ-FN, 321593986-01-FO, 321593986-01-FO-EA, 321593986-01-NB, 321593986-02-PL
1000003637		9/25/23 14:45	3429585	424	Carroll Street	Brooklyn	11215	General Contractor	7189326342	Business	Mexa Contractine Group LLC		Aerotek	603805	The Vorea Group	4	Open Shop	Y	William Mendez stated he was working from a ladder and while he was using a screw gun his hand slipped and the zippy screw went into his left wrist. He stated he did not fall off the ladder. He stated he is ok and was just nervous about pulline the screw out himself.	1	0	9/25/2023	7.5	5/2/2023	N		0	383.772	Y			21	95	B00614338-S4-FO, B00614338-S6-SE, B00699836-I1-PN. B00719568-I1-FO
1000003638		9/26/23 8:00	1000817	60	Broad St	Manhattan	10004	General Contractor	2128494800	Business	Plaza Construction LLC			612630	Piedmont Real Estate	4	Open Shop	N	While making a delivery Fred Astadillo sustained an ankle injury. Fred Astadillo is a delivery man for GER Millwork was injured inside the truck. The truck was located on New St outside of the building freight entrance. Incident occurred at 8am and ambulance was called and arrived at 8:09. Dob was contacted verbally by myself, Robert Murphy using the 2128020431 and the DOB representative noted that an incident number will not be provided since this was not a construction worker and did not occur onsite.	1	0	9/26/2023	0	1/0/1900		0	0	15.000	N	39	503			M00718438-I1, M00718815-I1-MS, M00718827-I1. M00718835-I1
1000003639		9/12/23 12:00	3000412	80	Willoughby Street	Brooklyn	11201	General Contractor	9732420515	Business	Rallv Restoration Corp.		Rallv Restoration Corp.	29178	80 Willoughby LLC	1	Non-Union	Y	working was cleaning debris from supported scaffold platform when he grabbed onto the guardrail and the guardrail dislodged and the worker fell approximately 35 feet onto sidewalk shed	1	0	9/26/2023	7	4/10/2023	N		0	n/a	N	10	110			B00752220-I1
1000003640		9/22/23 12:15	4000000	4401	northern blvd	Queens	11101	General Contractor	7182608940	Business	NY Developers & Management LLC		Best Mechanical Plumbing LLC	GC-617977	Silberstein Properties LLC	21	Non-Union	Y	One of the workers was passing a pipe through a floor penetration while installine a plumbine riser and lost control of it.	1	0	9/26/2023	5	1/23/2023	N		1	430.000	Y			13	175	Q00591457-I1-GC, Q00599457-S3-ST, Q00599457-S4-MS, Q00599457-S5-PL, Q00599457-S6-VT, Q00599457-S7-VT, Q00642992-I1-EW-SD, Q00642992-I1-EW-SP, Q00644830-I1-EW-SD, Q00730754-I1-PN, Q00833885-I1-SH, Q00835477-I1-EL, Q00836508-I1-PMM, Q00843149-I1-PMM, Q00847234-I1-EL, Q00859981-I1-SP, Q00879748-I1-PMM, Q00880546-I1-VT, Q00892807-I1-VT,
1000003643		9/19/23 14:00	2000003	138	Bruckner blvd	Bronx	10454	General Contractor	9294282111	Individual			Pelican Interiors	621905	138 Bruckner LLC	1	Non-Union	Y	Worker was carrvine material misstep and rolled ankle.	1	0	9/20/2023	7	8/29/2023	N		0	423.000	Y			12	125	X00647715-I1-GC
1000003648		9/21/23 11:00	1015624	212	5th Avenue	Manhattan	10010	General Contractor	7184967800	Business	Silverlinine Interiors		Mobility Elevator	3979	Jeffrev Poirot	21	Non-Union	Y	Mr. Barnett passed out, stopped breathing for around 3 minutes. In that time, 911 was called and CPR was performed and Mr. Barnett started breathine again.	1	0	9/27/2023	2	9/11/2023	N		0	18.000	N	24	299			140966943-01-AL, 141004437-01-EQ-OT, 141005187-01-EQ-OT, CNE-21-06049, M00411430-I1-PL, M00411534-I1-EW-SP, M00411584-I1-MS, M00415763-I1-ST, M00491273-I1-EW-SP, M00544609-I1-SH, M00562501-I1-EL, M00566019-I1-EL, M00595912-I1-ST, M00644152-I1-EL, M00648663-I1-VT, M00652861-I1-VT, M00667470-I1-EL, M00694724-I1-PM, M02-2023177-A28, M02-2023177-A29. M02-2023177-A30
1000003653		9/26/23 10:00	3429585	424	Carroll Street	Brooklyn	11215	General Contractor	7189326342	Business	Mexa Contractine Group LLC		European American Window Inc	603805	The Vorea Group	4	Open Shop	Y	Alfredo Bonilla claims while working on the 13th floor of the west building cutting SIGA tape for the windows, he cut the tip of his left thumb. Workers Bryan Campoverde injury was not a result of the work he was performing today and did not occur at 305 East 61st Street. He experienced lower back pain when he was on lunch which made it difficult to stand. He said he went to the doctor for existing issue EMS was called.	1	0	9/27/2023	3	7/14/2023	N		0	383.772	Y			21	130	B00614338-S4-FO, B00614338-S6-SE, B00699836-I1-PN. B00719568-I1-FO
1000003656		9/28/23 12:00	1044226	305	East 61st Street	Manhattan	10065	General Contractor	2122193800	Business	Fokosh Construction		Fokosh Construction	352	ASF 61 LLC	10	Non-Union	Y	The employee Fernando Acosta leaned a column form on the column. The column form fell and struck Fernando who was picking up a 2x4 at the time.	1	0	9/28/2023	1	7/5/2022	N		0	1.306	N	11	140			122839591-01-AL, EA 177-17, M00725350-I1-MS, M00725399-I1-PL, M00725419-I1-EW-SD, M00725419-I1-EW-SP, M00740390-I1-EL, M00741191-I1-EL, M00741291-S1-EL, M00741295-I1-EL
1000003658		9/26/23 13:00	1089192	375	West 207th Street	Manhattan	10034	General Contractor	2127669651	Business	Jov Construction Corp		Leading Builders Group, An	1320	Sherman Creek LLC	4	Non-Union	Y		1	0	9/29/2023	6	6/29/2023	N		0	600.000	Y			30	320	121189141. 121205828. 123899709
1000003659		9/28/23 10:20	4623202	3515	19th Avenue	Queens	11105	General Contractor	9172272636	Business	AECOM Company		KNS Roofine	604624	Wildflower Studio IV LLC	1	Open Shop	Y	worker alleedly fell while walkine up the stairs carine material	1	0	10/2/2023	3	8/4/2023	N		0	30	Y			8	158	420667549-01-NB
1000003663		9/29/23 8:15	2001876	629	Courtlandt Ave	Bronx	10451	Person in Control of Site	6464769228			Construction Superintendent	Five Hands Construction	30199	BM Courtlandt LLC	5	Non-Union	Y	At around 815am, Five Hands Construction was performing saw cutting along the concrete floor in the cellar in order to jack hammer and remove the concrete. When the worker completed his section of work he turned off his machine and unplugged it. However he was not cautious of the blade that was still spinning and placed it to close to his right leg. The blade then made contact with his leg and created a very large laceration to his thigh. Site Superintendent was notified right away and he then notified 911 and DOB right after.	1	0	10/3/2023	34	6/13/2023	N		1	21.183	N	3	36			X00825579-S2-PL, X00825579-S3-EW-SP, X00877118-S2-PMM, X00893026-I1-PN, X00919510-I1-ST
1000003674		9/29/23 12:00	1046687	7	East 81st Street	Manhattan	10028	General Contractor	3477716183	Business	CUBIC CONSTRUCTION		CUBIC CONSTRUCTION	622803	CMCHS	17	Non-Union	Y	The worker got hit in the face with a sledge hammer while he was removine plywood.	1	0	10/6/2023	35	7/17/2023	N		0	6.000	N	5	60			M00032038, M00334084, M00334975, M00335077, M00453715, M00458222, M00461346, M00466988, M00623635