



Local Law 78 Injury/Fatality Incident Report June 2020

Incident Unique ID	Incident Number	Incident Date & Time	BIN	House Number	Street Name	Borough	Zip Code	Incident Reported By	Person Reporting Phone Number	Type of Person Reporting Incident	Organization of Person Reporting	Person in Control of Site	Name of Contractor	Person Reporting License Number	Name of Site Owner	Number of Active Permits Issued	Site Union Info	Construction Worker Involved Flag	Incident Description Details	Injury Count	Fatality Count	Injury/Fatality Date	Injury/Fatality Number of Hours Worked	Injury/Fatality Worker Union Member Flag	Number of Violations Issued	Site Total Square Footage	Site New Building Flag	Site Existing Number of Stories	Site Existing Height	Site Proposed Number of Stories	Site Proposed Height	Active Permit Number
100000089		6/22/20 10:30	100518	141	East Houston Street	Manhattan	10002	General Contractor	9734940885	Business	CM and Associates	Trident General Contracting LLC	G-602382	East End Capital Partners LLC	23	Non-Union	Y	Worker from Trident General Contracting was in the process of cleaning the Northwest side of the project, picked up a small beam. The beam slipped causing a laceration to his left middle finger. Worker went to CityHD received stitches, a tetanus shot and returned to work the next day.	1	0	6/26/2020	3	9/12/2019	N	3	60,000	Y	9		123705501-01-FW, 100884876-01-AL, 102897111-01-AL, 123215939-01-AL, 100002951-01-EW-SF, 102887566-01-SL, 123215939-01-PL, 123770212-01-EW-OT, 140800347-01-EQ-OT, 100884876-01-EQ-FN, 100884876-01-FN, 100104645-01-EW-OT, 103058994-01-EW-NL, 123202087-01-EW-OT, 123202087-01-FW-OT, 123244605-01-DM, 123433056-01-FW-SF, 123424899-02-EW-SL, 123424861-01-EW-NL, 123428861-120-01-EW-OT, 123428861-01-PL, 140819794-01-EQ-DI		
100000090		6/24/20 1:00	1090733	159	West 48	Manhattan	10036	General Contractor	2127086800	Business	AECOM/Tubman	Pinnacle Industries	GC-2340	EXTLL	16	Open Shop	Y	Worker was installing Concrete Form for Column along with another Worker. Area was tight and worker had to position his hands while setting Column form during that time the injured party lost control of bottom of form forcing the Column form to land on top of left foot.	1	0	6/24/2020	6	11/01/2019	Y	0	2,500	Y	15		123131224-01-NL, 123181742-01-EW-DS, 140830996-01-EQ-OT, 140887021-01-EQ-OT, 140837076-01-EQ-OT, 140837080-01-EQ-OT, 140839274-01-EQ-OT, 140842328-01-EQ-OT, 140843346-01-EQ-OT, 140883303-01-EQ-OT, 140882427-01-OT-OT, M0014287-11-FN, M0014383-11-SM, M00021890-11-SD-VI, M00124446-11-VI, M00143370-11-VI		
100000091		6/26/20 15:38	1090811	142	West 29th	Manhattan	10011	General Contractor	2122395450	Individual				25114	142West29thLLC	2	Open Shop	N	An inspecting engineer showed up to the job site and was sick. He spent the majority of the day in the bathroom. His employer arranged for a coworker to come and pick him up and take him home.	1	0	6/26/2020	0	0	0	2,500	Y	8	74	121190549-01-140860959-01		
100000092	N/A	6/20/20 14:30	1062567	296	Wythe Ave	Brooklyn	11249	Person in Control of Site	9173303882		Construction Superintendent	QuickLufe		27633	Moshé Braver	7	Non-Union	Y	Worker from QuickLufe - Segundo D. Astimbay was working on removing an existing fence on N. 26 St. Mr. Astimbay was in the middle of chipping out the concrete holding the post for the fence. The post then fell out of the hole and hit Mr. Astimbay on his leg above his knee. The injured refused to have medical care on site. He then on his own accord left the site, and saw care at a local care facility. He was in condition. He returned to the site same day, and was back to work in the morning. Not reported initially as not escorted by an ambulance not an emergency.	1	0	7/2/2020	6	6/9/2020	N	0	12,000	0	0	32204884-01-EW-SF, 121140706-01-EQ-FN, 121140706-01-NL, 121424869-01-DM, 121424704-01-DM, 121423711-01-DM, 120246636-01-PL		
100000093		6/25/20 12:15	1090457	368	3rd Avenue	Manhattan	10016	General Contractor	9734940885	Business	CM and Associates	Westside Windows	G-602382	368 Third Avenue Owners LLC	3	Non-Union	Y	Westside Windows employee started walking down the 10th-floor stairs tripped on the second stair and fell two steps. The worker fell pain in her right ankle and lower back. The worker left the project went home then later went to the doctor with a diagnosis of a bruised ankle.	1	0	7/6/2020	5	6/9/2020	N	0	144,000	Y	36	405	121190745-01-NL, 121190745-06-PL, 140865632-01-EQ-OT		
100000094		6/20/20 12:00	1026982	646	11th Avenue	Manhattan	10036	General Contractor	9734940885	Business	CM and Associates	CM and Associates	G-602388	646 11th Owner LLC	9	Non-Union	Y	An employee of CMA was in the kneeling position repairing utility protection when standing he lost his balance falling back onto a curb landing on the right of the head. Worker went home then to the emergency room at St. Luke's diagnosed contusion of the right scalp. The worker returned to within three days.	1	0	7/9/2020	7	6/3/2016	N	0	270,000	Y	12	143	121204902-01-NL, 121204902-02-PL, 121204948-01-EW-SL, 121204948-01-EW-SF, 121204902-01-EQ-OT, 121485161-01-FW-SL, M00160595-11-SM, M00180609-01-SM, M00181328-01-		